
AN10030_1

Simultaneous DMA and PIO Access in the ISPII6Ix, ISPII8Ix and ISPI36x Device Controller



Application Note Rev. 1.1

Revision History:

Version	Date	Description	Author
1.1	Mar 2003	Added ISP1362	Rajaram Veerappan
1.0	Feb 2003	First version.	Rajaram Veerappan

Note: ISP1161x denotes any Philips USB single-chip Host Controller and Device Controller whose name starts with 'ISP1161'; this includes ISP1161A, ISP1161A1 and any future derivatives. ISP1181x denotes any Philips USB interface device whose name starts with 'ISP1181'; this includes ISP1181, ISP1181A, ISP1181B, and any future derivatives. ISP136x denotes any Philips single-chip USB OTG dual-role controller whose name starts with 'ISP136', this includes ISP1362, ISP1363 and. any future derivatives.

We welcome your feedback. Send it to <u>wired.support@philips.com</u>.

Philips Semiconductors - Asia Product Innovation Centre Visit <u>www.semiconductors.philips.com/buses/usb</u> or <u>www.flexiusb.com</u>



July 2003

This is a legal agreement between you (either an individual or an entity) and Philips Semiconductors. By accepting this product, you indicate your agreement to the disclaimer specified as follows:

DISCLAIMER

PRODUCT IS DEEMED ACCEPTED BY RECIPIENT. THE PRODUCT IS PROVIDED "AS IS" WITHOUT WARRANTY OF ANY KIND. TO THE MAXIMUM EXTENT PERMITTED BY APPLICABLE LAW, PHILIPS SEMICONDUCTORS FURTHER DISCLAIMS ALL WARRANTIES, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANT ABILITY, FITNESS FOR A PARTICULAR PURPOSE, AND NONINFRINGEMENT. THE ENTIRE RISK ARISING OUT OF THE USE OR PERFORMANCE OF THE PRODUCT AND DOCUMENTATION REMAINS WITH THE RECIPIENT. TO THE MAXIMUM EXTENT PERMITTED BY APPLICABLE LAW, IN NO EVENT SHALL PHILIPS SEMICONDUCTORS OR ITS SUPPLIERS BE LIABLE FOR ANY CONSEQUENTIAL, INCIDENTAL, DIRECT, INDIRECT, SPECIAL, PUNITIVE, OR OTHER DAMAGES WHATSOEVER (INCLUDING, WITHOUT LIMITATION, DAMAGES FOR LOSS OF BUSINESS PROFITS, BUSINESS INTERRUPTION, LOSS OF BUSINESS INFORMATION, OR OTHER PECUNIARY LOSS) ARISING OUT OF THIS AGREEMENT OR THE USE OF OR INABILITY TO USE THE PRODUCT, EVEN IF PHILIPS SEMICONDUCTORS HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

CONTENTS

Ι.		4
2.	TIMING CONSTRAINT	4
3.	COMMAND SETS	5

The names of actual companies and products mentioned herein may be the trademarks of their respective owners. All other names, products, and trademarks are the property of their respective owners. **Note**: ISP1161x denotes any Philips USB single-chip Host Controller and Device Controller whose name starts with 'ISP1161'; this includes ISP1161A, ISP1161A1 and any future derivatives. ISP1181x denotes any Philips USB interface device whose name starts with 'ISP1181'; this includes ISP1181, ISP1181A, ISP1181B, and any future derivatives. ISP136x denotes any Philips single-chip USB OTG dual-role controller whose name starts with 'ISP136', this includes ISP1362, ISP1363 and. any future derivatives.

I. Introduction


In some complex applications, such as multifunctional adapters, there may be a need to simultaneously perform direct memory access (DMA) and parallel I/O (PIO).

This document explains the points that must be covered while performing simultaneous DMA and PIO accesses in the device controller of the ISPI161x, the ISPI181x, or the ISPI36x.

2. Timing constraint

When the Device Controller is performing DMA transfer, it can also perform PIO access in between. You have to ensure, however, that the internal RAM is not disturbed because of this access.

For example, during the DMA transfer for an IN token: While the buffer (IN endpoint) is being filled up, once the packet boundary^[1] is reached, internally the DMA state machine updates the RAM status for 700 ns. After every 64 bytes, the state machine updates the status for 700 ns. It is during this time that access to the internal RAM is not recommended. The commands in Section 3 directly affect the RAM; when issued, they lock up the internal RAM. When these commands are issued during the critical period of 700 ns, the internal RAM gets corrupted, leading to data error.



There cannot be any PIO access during this time.

Therefore, during the 'x' period, there cannot be any PIO access to the ISPII61x, ISPII81x or ISPI36x Device Controller.


^[1] Packet boundary is the endpoint size. If the endpoint size is configured as 64 bytes, then packet boundary is 64 bytes.

3. Command sets

The following commands lock the internal RAM. If the following commands need to be executed during DMA access, then issue the commands 700 ns after the DACK deassertion.

- Stall control OUT/IN endpoint (0x40/0x41)
- Stall endpoint n (0x42 to 0x4F)
- Read control OUT/IN status (0x50/0x51)
- Read endpoint n status (0x52 to 0x5F)
- Validate control OUT/IN buffer (0x60/0x61)
- Validate endpoint n buffer (0x62 to 0x6F)
- Clear control OUT/IN buffer (0x70/0x71)
- Clear endpoint n buffer (0x72 to 0x7F)
- Unstall control OUT/IN endpoint (0x80/0x81)
- Unstall endpoint n (0x82 to 0x8F)
- Acknowledge setup (0xF4)

While issuing these commands, you must observe the timing constraint mentioned in Section 2. The following diagram shows the DMA and PIO accesses:



In the diagram, it is assumed that:

- DREQ is active HIGH,
- DACK is active LOW, and
- RD_N, CS_N and WR_N are active LOW.


If the specified timing constraints are not properly addressed, then the internal RAM could get corrupted, resulting in data error.

Philips Semiconductors

Philips Semiconductors is a worldwide company with over 100 sales offices in more than 50 countries. For a complete up-to-date list of our sales offices please e-mail

- sales. addresses @www.semiconductors.philips.com.
- A complete list will be sent to you automatically.

You can also visit our website http://www.semiconductors.philips.com/sales/



© Koninklijke Philips Electronics N.V. 2003

All rights reserved. Reproduction in whole or in part is prohibited without the prior written consent of the copyright owner. The information presented in this document does not form part of any quotation or contract, is believed to be accurate and reliable and may be changed without notice. No liability will be accepted by the publisher for any consequence of its use. Publication thereof does not convey or imply any license under patent – or other industrial or intellectual property rights.

