CHAPTER 555

STABILIZERS



CHAPTER 55 STABILIZERS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
EFFECTIVE PAG	GES	55-10-01 IDENTIF	FICATION 3 (cont)		ABLE DAMAGE 1
1 thru 13	Jul 10/2009	13	Mar 10/2004	(cont)	
14	BLANK	14	Nov 01/2003	105	Jul 10/2004
55-CONTENTS		15	Nov 01/2003	106	Nov 10/2005
1	Nov 10/2005	16	BLANK	107	Nov 01/2003
2	Nov 10/2005	55-10-01 IDENTIF	FICATION 4	108	Nov 01/2003
3	Nov 10/2005	1	Jul 10/2004	109	Nov 10/2006
4	Nov 10/2005	2	Mar 10/2004	110	Nov 01/2003
5	Nov 10/2005	3	Mar 10/2004	111	Nov 01/2003
6	Nov 10/2005	4	Mar 10/2004	112	Nov 01/2003
7	Nov 10/2004	55-10-01 IDENTIF	FICATION 5	113	Nov 01/2003
8	BLANK	1	Jul 10/2004	114	BLANK
55-10-00 IDENTI		2	Mar 10/2004	55-10-01 ALLOW	ABLE DAMAGE 2
1	Jul 10/2004	3	Mar 10/2004	101	Nov 10/2007
2	Mar 10/2004	4	Mar 10/2004	102	Nov 01/2003
3	Mar 10/2004 Mar 10/2004	5	Nov 01/2003	103	Nov 01/2003
4	BLANK	6	Mar 10/2004	104	Nov 10/2007
55-10-01 IDENTI		7	Mar 10/2004	105	Jul 10/2004
1	Jul 10/2004	8	Nov 01/2003	106	Nov 01/2003
2	Jul 10/2004	9	Mar 10/2004	107	Nov 01/2003
3	Mar 10/2004	10	Mar 10/2004	108	Nov 01/2003
4	Mar 10/2004 Mar 10/2004	11	Nov 01/2003	109	Nov 01/2003
		12	Mar 10/2004	110	Nov 10/2005
1	Jul 10/2004	13	Mar 10/2004	111	Nov 01/2003
2	Mar 10/2004	14	Nov 01/2003	112	Nov 01/2003
2	Mar 10/2004 Mar 10/2004	15	Nov 10/2006	55-10-01 ALLOW	ABLE DAMAGE 3
-		16	Mar 10/2004	101	Nov 10/2005
4	BLANK	17	Nov 01/2003	102	Nov 10/2005
55-10-01 IDENTI		18	Mar 10/2004	103	Nov 01/2003
1	Jul 10/2004	19	Mar 10/2004	104	Nov 10/2007
2	Jul 10/2004	20	Nov 01/2003	105	Nov 10/2007
3	Nov 01/2003	20		106	Nov 01/2003
4	Nov 01/2003		Mar 10/2004	107	Nov 01/2003
5	Nov 01/2003	22	Mar 10/2004	108	Nov 01/2003
6	Mar 10/2004	23	Nov 01/2003	109	Nov 01/2003
7	Mar 10/2004	24	Nov 01/2003	110	Nov 10/2007
8	Nov 01/2003		ABLE DAMAGE 1	111	Nov 10/2007
9	Mar 10/2004	101	Nov 01/2003	112	Nov 10/2007
10	Mar 10/2004	102	Nov 01/2003	113	Nov 10/2007
11	Nov 01/2003	103	Nov 01/2003	114	Nov 10/2005
12	Mar 10/2004	104	Nov 10/2007		

A = Added, R = Revised, O = Overflow, D = Deleted

55-EFFECTIVE PAGES

Page 1 Jul 10/2009



CHAPTER 55 STABILIZERS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
55-10-01 ALLOW	ABLE DAMAGE 3	55-10-01 REPAIR	4 (cont)	55-10-04 IDENTIF	FICATION 1 (cont)
(cont)		204	Jul 10/2004	4	BLANK
115	Nov 10/2005	205	Nov 01/2003	55-10-09 IDENTIF	FICATION 1
116	Nov 10/2005	206	Nov 10/2007	1	Mar 10/2004
117	Nov 10/2005	207	Nov 10/2007	2	Mar 10/2004
118	Nov 10/2005	208	Nov 01/2003	3	Mar 10/2004
	ABLE DAMAGE 4	209	Nov 01/2003	4	Mar 10/2004
101	Nov 01/2003	210	BLANK	5	Nov 01/2003
102	Jul 10/2004	55-10-01 REPAIR	7	6	Mar 10/2004
103	Jul 10/2004	201	Nov 01/2003	7	Mar 10/2004
104	Jul 10/2004	202	Nov 01/2003	8	Nov 01/2003
105	Jul 10/2004	203	Nov 01/2003	55-10-09 IDENTIF	FICATION 2
106	BLANK	204	Nov 01/2003	1	Mar 10/2004
55-10-01 REPAIR		205	Nov 01/2003	2	Mar 10/2004
201	Nov 01/2003	206	BLANK	3	Mar 10/2004
202	Nov 01/2003	55-10-01 REPAIR	8	4	Mar 10/2004
R 203	Jul 10/2009	201	Nov 01/2003	5	Mar 10/2004
O 204	Jul 10/2009	202	Nov 01/2003	6	Mar 10/2004
205	Nov 01/2003	203	Nov 01/2003	7	Mar 10/2004
206	Nov 01/2003	204	Nov 01/2003	8	Mar 10/2004
207	Nov 01/2003	205	Nov 01/2003	9	Mar 10/2004
208	BLANK	206	BLANK	10	Mar 10/2004
55-10-01 REPAIR	8.2	55-10-01 REPAIR	9	11	Mar 10/2004
201	Nov 01/2003	201	Nov 01/2003	12	Mar 10/2004
202	Nov 10/2007	202	Nov 01/2003	13	Mar 10/2004
203	Nov 10/2007	203	Nov 01/2003	14	Mar 10/2004
204	Nov 01/2003	204	Nov 01/2003	15	Mar 10/2004
205	Nov 01/2003	205	Nov 01/2003	16	Mar 10/2004
206	BLANK	206	Nov 01/2003	55-10-09 IDENTIF	FICATION 3
55-10-01 REPAIR	83	207	Nov 01/2003	1	Mar 10/2004
201	Nov 01/2003	208	BLANK	2	Mar 10/2004
202	Nov 01/2003	55-10-01 REPAIR	10	3	Mar 10/2004
203	Nov 01/2003	201	Nov 10/2005	4	Mar 10/2004
204	Nov 10/2007	202	Nov 10/2005	5	Nov 01/2003
205	Nov 10/2007	203	Nov 10/2005	6	Mar 10/2004
206	Nov 01/2003	204	BLANK	7	Mar 10/2004
55-10-01 REPAIR	R 4	55-10-04 IDENTIF		8	BLANK
201	Nov 01/2003	1	Jul 10/2004	55-10-10 IDENTIF	
202	Nov 01/2003	2	Mar 10/2004	1	Jul 10/2004
203	Nov 01/2003	3	Nov 01/2003	2	Mar 10/2004
		Ŭ	1101 01/2000	<u> </u>	

A = Added, R = Revised, O = Overflow, D = Deleted

55-EFFECTIVE PAGES

Page 2 Jul 10/2009



CHAPTER 55 STABILIZERS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
55-10-10 IDENTIF 3	FICATION 1 (cont) Mar 10/2004	55-10-10 ALLOW/ (cont)	ABLE DAMAGE 2	55-10-13 ALLOW. (cont)	ABLE DAMAGE 1
4	Mar 10/2004 Mar 10/2004	106	Nov 01/2003	104	Nov 01/2003
4 55-10-10 IDENTIF		107	Nov 01/2003	105	Jul 10/2004
1	Jul 10/2004	108	Nov 01/2003	106	Nov 01/2003
2	Mar 10/2004	109	Nov 01/2003	107	Nov 01/2003
3	Nov 01/2003	110	Nov 01/2003	108	Nov 01/2003
4	Nov 01/2003	111	Nov 01/2003	55-10-13 ALLOW	ABLE DAMAGE 2
5	Mar 10/2004	112	Nov 01/2003	101	Nov 01/2003
6	Mar 10/2004 Mar 10/2004	113	Nov 01/2003	102	Nov 01/2003
7	Mar 10/2004 Mar 10/2004	114	Nov 01/2003	103	Nov 01/2003
		115	Nov 01/2003	104	Jul 10/2005
8 55 10 10 IDENTIE		116	Nov 01/2003	105	Nov 01/2003
55-10-10 IDENTIF	Jul 10/2004	55-10-10 REPAIR	1	106	Nov 01/2003
	Mar 10/2004	201	Nov 10/2006	107	Nov 01/2003
2		202	Nov 01/2003	108	Nov 01/2003
3 4	Mar 10/2004	203	Nov 10/2007	109	Nov 01/2003
	Mar 10/2004	204	Nov 10/2007	110	Nov 01/2003
5	Nov 01/2003	205	Nov 01/2003	55-10-13 REPAIR	1
6	BLANK	206	Nov 01/2003	201	Nov 10/2006
	ABLE DAMAGE 1	207	Nov 01/2003	202	Nov 01/2003
101	Mar 10/2007	208	BLANK	203	Nov 01/2003
102	Nov 01/2003	55-10-13 IDENTIF	ICATION 1	204	BLANK
103	Mar 10/2007	1	Jul 10/2004	55-10-13 REPAIR	2
104	Jul 10/2004	2	Mar 10/2004	201	Nov 01/2003
105	Jul 10/2004	3	Nov 01/2003	202	Nov 01/2003
106	Nov 01/2003	4	BLANK	203	Nov 01/2003
107	Nov 01/2003	55-10-13 IDENTIF	ICATION 2	204	BLANK
108	Nov 01/2003	1	Mar 10/2004	55-10-30 IDENTIF	ICATION 1
109	Nov 01/2003	2	Mar 10/2004	1	Jul 10/2004
110	Nov 01/2003	3	Mar 10/2007	2	Mar 10/2004
111	Nov 01/2003	4	Mar 10/2004	3	Mar 10/2004
112	Nov 01/2003	5	Mar 10/2007	4	Mar 10/2004
113	Nov 01/2003	6	Mar 10/2004	5	Mar 10/2004
114	BLANK	7	Mar 10/2007	6	BLANK
	ABLE DAMAGE 2	8	Mar 10/2004	55-10-30 IDENTIF	
101	Mar 10/2007		ABLE DAMAGE 1	1	Jul 10/2004
102	Nov 01/2003	101	Jul 10/2004	2	Mar 10/2004
103	Nov 01/2003	102	Jul 10/2004	3	Mar 10/2004
104	Jul 10/2004	103	Nov 01/2003	4	Mar 10/2004
105	Nov 01/2003			-	

A = Added, R = Revised, O = Overflow, D = Deleted

55-EFFECTIVE PAGES

Page 3 Jul 10/2009



CHAPTER 55 STABILIZERS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
55-10-30 IDENTI	FICATION 2 (cont)	55-10-90 IDENTIF	FICATION 1 (cont)	55-20-01 IDENTIFICATION 2 (cont)	
5	Mar 10/2004	3	Mar 10/2004	4	Mar 10/2004
6	Mar 10/2004	4	Mar 10/2004	5	Mar 10/2004
7	Nov 01/2003	5	Mar 10/2004	6	Nov 01/2003
8	BLANK	6	Mar 10/2004	7	Nov 01/2003
55-10-30 ALLOW	ABLE DAMAGE 1	7	Mar 10/2004	8	BLANK
101	Jul 10/2005	8	Mar 10/2004	55-20-01 IDENTIF	FICATION 3
102	Nov 10/2007	9	Nov 01/2003	1	Jul 10/2004
103	Nov 01/2003	10	Mar 10/2004	2	Mar 10/2004
104	Nov 10/2007	11	Mar 10/2004	3	Nov 01/2003
105	Nov 10/2007	12	Nov 01/2003	4	Mar 10/2004
106	Nov 01/2003	55-10-90 IDENTIF	FICATION 2	5	Mar 10/2004
107	Nov 01/2003	1	Jul 10/2004	6	Nov 01/2003
108	Nov 01/2003	2	Mar 10/2004	7	Mar 10/2004
109	Nov 01/2003	3	Mar 10/2004	8	Mar 10/2004
110	BLANK	4	Mar 10/2004	9	Nov 01/2003
55-10-30 ALLOW	ABLE DAMAGE 2	5	Mar 10/2004	10	Mar 10/2004
101	Jul 10/2005	6	Mar 10/2004	11	Mar 10/2004
102	Nov 10/2007	7	Nov 01/2003	12	Mar 10/2004
103	Nov 10/2007	8	BLANK	13	Mar 10/2004
104	Nov 01/2003	55-10-90 REPAIR	1	14	Nov 01/2003
105	Nov 01/2003	201	Nov 10/2007	55-20-01 ALLOW	ABLE DAMAGE 1
106	BLANK	202	Nov 10/2006	101	Jul 10/2005
55-10-30 REPAIF	R 1	203	Nov 10/2007	102	Nov 10/2004
201	Nov 01/2003	204	Nov 10/2005	103	Nov 01/2003
202	Nov 01/2003	205	Nov 10/2005	104	Nov 01/2003
203	Jul 10/2005	206	Nov 10/2005	105	Mar 10/2004
204	Nov 01/2003	55-20-01 IDENTIF	FICATION 1	106	Mar 10/2004
205	Nov 01/2003	1	Jul 10/2004	107	Mar 10/2004
206	BLANK	2	Mar 10/2004	108	Mar 10/2004
55-10-30 REPAIF	8 2	3	Nov 01/2003	109	Mar 10/2007
201	Nov 01/2003	4	Mar 10/2004	110	Mar 10/2007
202	Jul 10/2004	5	Mar 10/2004	111	Mar 10/2007
203	Jul 10/2005	6	Nov 01/2003	112	Mar 10/2007
204	Jul 10/2004	7	Nov 01/2003	55-20-01 ALLOW	ABLE DAMAGE 2
205	Jul 10/2004	8	BLANK	101	Nov 01/2003
206	BLANK	55-20-01 IDENTIF	ICATION 2	102	Nov 01/2003
55-10-90 IDENTI	FICATION 1	1	Jul 10/2004	103	Nov 10/2007
1	Mar 10/2004	2	Mar 10/2004	104	Nov 10/2007
2	Mar 10/2004	3	Nov 01/2003	105	Nov 01/2003

A = Added, R = Revised, O = Overflow, D = Deleted

55-EFFECTIVE PAGES

Page 4 Jul 10/2009



CHAPTER 55 STABILIZERS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
	ABLE DAMAGE 2	55-20-01 REPAIR	R 3 (cont)	55-20-02 IDENTI	FICATION 2 (cont)
(cont)		202	Nov 01/2003	2	Mar 10/2004
106	Nov 01/2003	203	Nov 01/2003	3	Mar 10/2004
107	Nov 10/2007	204	Nov 10/2007	4	Mar 10/2004
108	Nov 01/2003	205	Nov 01/2003	5	Mar 10/2004
109	Nov 01/2003	206	Nov 01/2003	6	Mar 10/2004
110	Nov 01/2003	207	Nov 10/2007	7	Mar 10/2004
111	Nov 01/2003	208	Jul 10/2004	8	Mar 10/2004
112	Nov 01/2003	209	Jul 10/2004	9	Mar 10/2004
	ABLE DAMAGE 3	210	BLANK	10	Mar 10/2004
101	Nov 01/2003	55-20-01 REPAIR	R 4	11	Mar 10/2004
102	Nov 01/2003	201	Jul 10/2005	12	Mar 10/2004
103	Nov 01/2003	202	Nov 01/2003	13	Nov 01/2003
104	Nov 10/2007	203	Nov 01/2003	14	BLANK
105	Nov 01/2003	204	Nov 01/2003	55-20-02 IDENTI	FICATION 3
106	Nov 01/2003	205	Nov 01/2003	1	Mar 10/2004
107	Nov 10/2007	206	Jul 10/2005	2	Mar 10/2004
108	Nov 10/2007	207	Nov 01/2003	3	Nov 01/2003
109	Nov 10/2007	208	BLANK	4	Mar 10/2004
110	Nov 01/2003	55-20-02 IDENTI	FICATION 1	5	Mar 10/2004
55-20-01 REPAIR	R 1	1	Mar 10/2004	6	Mar 10/2004
201	Nov 10/2006	2	Mar 10/2004	7	Mar 10/2004
202	Nov 01/2003	3	Mar 10/2004	8	Mar 10/2004
203	Nov 01/2003	4	Mar 10/2004	9	Mar 10/2004
204	Nov 01/2003	5	Mar 10/2004	10	Nov 01/2003
205	Nov 01/2003	6	Mar 10/2004	55-20-02 ALLOW	VABLE DAMAGE 1
206	Jul 10/2005	7	Mar 10/2004	101	Nov 10/2004
207	Mar 10/2007	8	Mar 10/2004	102	Mar 10/2007
208	BLANK	9	Mar 10/2004	103	Nov 01/2003
55-20-01 REPAIR	R 2	10	Mar 10/2004	104	Nov 01/2003
201	Nov 01/2003	11	Mar 10/2004	105	Nov 01/2003
202	Nov 01/2003	12	Mar 10/2004	106	Nov 01/2003
203	Nov 10/2007	13	Mar 10/2004	107	Nov 01/2003
204	Nov 01/2003	14	Mar 10/2004	108	Nov 01/2003
205	Nov 10/2007	15	Mar 10/2004	109	Nov 01/2003
206	Mar 10/2007	16	Mar 10/2004	110	Nov 01/2003
207	Nov 01/2003	17	Mar 10/2004	111	Nov 01/2003
208	BLANK	18	BLANK	112	Nov 01/2003
55-20-01 REPAIR	R 3	55-20-02 IDENTI		113	Nov 01/2003
201	Nov 01/2003	1	Mar 10/2004	114	Nov 01/2003

A = Added, R = Revised, O = Overflow, D = Deleted

55-EFFECTIVE PAGES

Page 5 Jul 10/2009



CHAPTER 55 STABILIZERS

Date	Subject/Page	Date	Subject/Page	Date
55-20-02 ALLOWABLE DAMAGE 1 (cont)		55-20-02 REPAIR 2		ABLE DAMAGE 1
M 40/0007	201	Jul 10/2005	101	Nov 10/2007
	202	Nov 01/2003	102	Nov 01/2003
	203	Nov 01/2003	103	Nov 01/2003
	204	Jul 10/2005	104	Nov 01/2003
	205	Jul 10/2004	105	Nov 01/2003
	206	BLANK	106	Nov 10/2007
	55-20-02 REPAIR	3	55-20-70 REPAIR	11
	201	Jul 10/2005	201	Nov 01/2003
	202	Nov 01/2003	202	Mar 10/2007
	203	Nov 01/2003	203	Mar 10/2007
	204	Nov 01/2003	204	BLANK
ABLE DAMAGE 2	205	Jul 10/2005	55-20-90 IDENTIF	FICATION 1
	206	Nov 01/2003	1	Jul 10/2004
BLANK	55-20-30 IDENTIF	FICATION 1	2	Mar 10/2004
	1	Jul 10/2004	3	Mar 10/2004
	2	Mar 10/2004	4	Nov 01/2003
	3	Mar 10/2004	5	Nov 01/2003
Nov 01/2003	4	Nov 01/2003	6	BLANK
	55-20-30 ALLOW	ABLE DAMAGE 1	55-20-90 IDENTIF	FICATION 2
	101	Nov 01/2003	1	Jul 10/2004
	102	Nov 10/2007	2	Mar 10/2004
	103	Nov 01/2003	3	Nov 01/2003
BLANK	104	Nov 10/2007	4	Nov 01/2003
1	105	Nov 10/2006	55-20-90 IDENTIF	FICATION 3
Nov 01/2003	106	BLANK	1	Jul 10/2004
Nov 01/2003	55-20-30 REPAIR	1	2	Mar 10/2004
Nov 01/2003	201	Nov 01/2003	3	Nov 01/2003
	202	Nov 01/2003	4	BLANK
Nov 01/2003	203	Nov 01/2003	55-20-90 ALLOW	ABLE DAMAGE 1
Nov 01/2003	204	Jul 10/2005	101	Nov 01/2003
Nov 01/2003	205	Nov 10/2006	102	Nov 01/2003
Nov 01/2003	206	BLANK	103	Nov 01/2003
Nov 01/2003	55-20-70 IDENTIF	FICATION 1	104	Nov 01/2003
Nov 01/2003	1	Jul 10/2004	105	Nov 01/2003
Nov 01/2003	2	Mar 10/2004	106	Nov 01/2003
Jul 10/2005	3	Mar 10/2004	107	Nov 01/2003
Jul 10/2007	4	Mar 10/2004	108	Jul 10/2004
Mar 10/2007	5	Nov 01/2003	109	Nov 01/2003
	6	BLANK	110	Nov 01/2003
	Mar 10/2007 Mar 10/2007 Mar 10/2007 Mar 10/2007 Mar 10/2007 Mar 10/2007 Mar 10/2007 Mar 10/2007 Mar 10/2007 BLANK ABLE DAMAGE 2 Nov 01/2003 BLANK ABLE DAMAGE 3 Jul 10/2005 Nov 01/2003 Nov 01/2003 Nov 01/2003 Nov 01/2003 Jul 10/2004 BLANK 1 Nov 01/2003 Nov 01/2003	Mar 10/2007 201 Mar 10/2007 203 Mar 10/2007 204 Mar 10/2007 205 Mar 10/2007 206 Mar 10/2007 201 Mar 10/2007 201 Mar 10/2007 201 Mar 10/2007 201 Mar 10/2007 202 Mar 10/2007 203 BLANK 204 ABLE DAMAGE 2 205 Nov 01/2003 206 BLANK 55-20-30 IDENTIF ABLE DAMAGE 3 1 Jul 10/2005 2 Nov 01/2003 3 Nov 01/2003 4 Nov 01/2003 101 Jul 10/2005 102 Jul 10/2005 102 Jul 10/2004 103 BLANK 104 1 105 Nov 01/2003 201 Nov 01/2003 202 Nov 01/2003 203 Nov 01/2003 204 Nov 01/2003 205 Nov 01/2003 206 Nov 01/2003	201 Jul 10/2005 Mar 10/2007 202 Nov 01/2003 Mar 10/2007 203 Nov 01/2003 Mar 10/2007 204 Jul 10/2004 Mar 10/2007 206 BLANK Mar 10/2007 206 BLANK Mar 10/2007 201 Jul 10/2005 Mar 10/2007 201 Jul 10/2003 Mar 10/2007 203 Nov 01/2003 BLANK 204 Nov 01/2003 BLANK 204 Nov 01/2003 BLANK 204 Nov 01/2003 BLANK 204 Nov 01/2003 BLANK 205 Jul 10/2004 Jul 10/2003 206 Nov 01/2003 BLANK 55-20-30 IDENTIFICATION 1 ABLE DAMAGE 3 1 Jul 10/2004 Jul 10/2005 2 Mar 10/2004 Nov 01/2003 55-20-30 ALLOWABLE DAMAGE 1 Nov 01/2003 101 Nov 01/2003 Jul 10/2004 103 Nov 01/2003 Jul 10/2005 102 Nov 01	Mar 10/2007 201 Jul 10/2005 101 Mar 10/2007 202 Nov 01/2003 102 Mar 10/2007 203 Nov 01/2003 103 Mar 10/2007 204 Jul 10/2005 104 Mar 10/2007 205 Jul 10/2004 105 Mar 10/2007 206 BLANK 106 Mar 10/2007 201 Jul 10/2005 201 Mar 10/2007 201 Jul 10/2005 201 Mar 10/2007 202 Nov 01/2003 202 Mar 10/2007 203 Nov 01/2003 204 ABLE DAMAGE 2 205 Jul 10/2005 55-20-90 IDENTIFICATION 1 2 ABLE DAMAGE 3 1 Jul 10/2004 3 3 Jul 10/2005 2 Mar 10/2004 5 Nov 01/2003 3 Mar 10/2004 5 Nov 01/2003 101 Nov 01/2003 1 Jul 10/2005 102 Nov 10/2003 1 </td

A = Added, R = Revised, O = Overflow, D = Deleted

55-EFFECTIVE PAGES

Page 6 Jul 10/2009



CHAPTER 55 STABILIZERS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
55-20-90 ALLOW	ABLE DAMAGE 1	55-30-00 IDENTIF	FICATION 0 (cont)	55-30-01 IDENTI	FICATION 3 (cont)
(cont)		3	Nov 01/2003	15	Mar 10/2004
111	Nov 01/2003	4	BLANK	16	Mar 10/2004
112	BLANK	55-30-01 IDENTIF	FICATION 1	17	Nov 01/2003
	ABLE DAMAGE 2	1	Jul 10/2004	18	BLANK
101	Nov 01/2003	2	Mar 10/2004	55-30-01 IDENTI	FICATION 4
102	Nov 01/2003	3	Mar 10/2004	1	Jul 10/2004
103	Nov 01/2003	4	Mar 10/2004	2	Mar 10/2004
104	Nov 01/2003	5	Mar 10/2004	3	Mar 10/2004
105	Nov 01/2003	6	BLANK	4	Mar 10/2004
106	Nov 01/2003	55-30-01 IDENTIF	FICATION 2	5	Mar 10/2004
107	Jul 10/2004	1	Jul 10/2004	6	Mar 10/2004
108	Nov 01/2003	2	Mar 10/2004	7	Mar 10/2004
109	Nov 01/2003	3	Mar 10/2004	8	Mar 10/2004
110	Nov 01/2003	4	Mar 10/2004	9	Mar 10/2004
55-20-90 ALLOW	ABLE DAMAGE 3	5	Mar 10/2004	10	BLANK
101	Nov 01/2003	6	Mar 10/2004	55-30-01 IDENTI	FICATION 5
102	Nov 01/2003	7	Mar 10/2004	1	Jul 10/2004
103	Nov 01/2003	8	Mar 10/2004	2	Mar 10/2004
104	Nov 01/2003	9	Mar 10/2004	3	Nov 01/2003
105	Nov 01/2003	10	Mar 10/2004	4	Mar 10/2004
106	Nov 01/2003	11	Mar 10/2004	5	Mar 10/2004
107	Nov 01/2003	12	Mar 10/2004	6	Mar 10/2004
108	Nov 01/2003	13	Mar 10/2004	7	Mar 10/2004
55-20-90 REPAIF	R 1	14	BLANK	8	Mar 10/2004
201	Nov 10/2006	55-30-01 IDENTI		9	Mar 10/2004
202	Mar 10/2007	1	Jul 10/2004	10	Mar 10/2004
203	Mar 10/2007	2	Mar 10/2004	11	Mar 10/2004
204	BLANK	3	Nov 01/2003	12	Mar 10/2004
55-20-90 REPAIF	R 2	4	Mar 10/2004	13	Mar 10/2004
201	Nov 01/2003	5	Mar 10/2004	14	Mar 10/2004
202	Nov 01/2003	6	Mar 10/2004	15	Mar 10/2004
203	Mar 10/2007	7	Mar 10/2004	16	Mar 10/2004
204	Mar 10/2007	8	Mar 10/2004	17	Nov 01/2003
55-20-90 REPAIF	3	9	Mar 10/2004	18	BLANK
201	Mar 10/2007	10	Mar 10/2004	55-30-01 IDENTI	
202	Mar 10/2007	11	Mar 10/2004	1	Jul 10/2004
55-30-00 IDENTI	FICATION 0	12	Mar 10/2004	2	Jul 10/2004
1	Mar 10/2004	13	Mar 10/2004	3	Mar 10/2004
2	Mar 10/2004	14	Mar 10/2004	4	Nov 01/2003
				-	

A = Added, R = Revised, O = Overflow, D = Deleted

55-EFFECTIVE PAGES

Page 7 Jul 10/2009



CHAPTER 55 STABILIZERS

55-30-01 IDENTIFICATION 6 (cont) 55-30-01 ALLOWABLE DAMAGE 3 (cont) 55-30-01 ALLOWABLE 3 55-30-01 REPAIR 3 (cont) 5 Nov 01/2003 111 Nov 01/2003 202 Nov 01/2003 6 Jul 10/2004 112 BLANK 204 Nov 01/2003 101 Nov 10/2007 102 Jul 10/2004 205 Nov 01/2003 102 Nov 01/2003 101 Nov 01/2004 206 Nov 01/2003 105 Jul 10/2004 104 Jul 10/2004 208 Nov 01/2003 105 Jul 10/2004 104 Jul 10/2004 208 Nov 01/2003 106 Nov 01/2003 106 BLANK 211 Nov 01/2003 108 Nov 01/2003 101 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 5 212 Nov 01/2003 109 Nov 01/2003 101 Nov 01/2003 55-30-01 REPAIR 4 110 Nov 01/2003 111 Nov 01/2003 103 Nov 01/2003 53-0-01 REPAIR 4 400 112 Nov 01/2003 103	Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
S Nov 01/2003 111 Nov 01/2003 202 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 1 112 BLANK 204 Nov 01/2003 101 Nov 10/2007 55-30-01 ALLOWABLE DAMAGE 4 205 Nov 01/2003 102 Nov 01/2003 101 Nov 01/2003 206 Nov 10/2007 103 Jul 10/2004 207 Nov 10/2003 208 Nov 10/2003 105 Jul 10/2004 103 Jul 10/2004 208 Nov 01/2003 106 Nov 01/2003 105 Jul 10/2004 208 Nov 01/2003 106 Nov 01/2003 105 Jul 10/2004 208 Nov 01/2003 107 Nov 01/2003 106 BLANK 211 Nov 01/2003 108 Nov 01/2003 101 Nov 10/2006 214 BLANK 1111 Nov 01/2003 102 Mar 10/2006 214 BLANK 112 Nov 01/2003 104 Nov 01/2003 205 Nov 01/2003 102 Nov 01/20	55-30-01 IDENTIF	FICATION 6 (cont)		ABLE DAMAGE 3	55-30-01 REPAIR	3 (cont)
b Juli 10/2004 112 BLANK 203 Nev 01/2003 55-30-01 ALLOWABLE DAMAGE 1 112 BLANK 204 Nev 01/2003 101 Nev 01/2003 101 Nev 01/2003 206 Nev 01/2003 102 Nev 01/2007 102 Jul 10/2004 206 Nev 01/2003 105 Jul 10/2004 103 Jul 10/2004 208 Nev 01/2003 106 Nev 01/2003 105 Jul 10/2004 209 Nev 01/2003 106 Nev 01/2003 105 Jul 10/2004 209 Nev 01/2003 107 Nev 01/2003 106 BLANK 211 Nev 01/2003 108 Nev 01/2003 101 Nev 10/2007 213 Jul 10/2005 110 Nev 01/2003 102 Mar 10/2003 201 Nev 01/2003 111 Nev 01/2003 104 Nev 01/2003 201 Nev 01/2003 104 Nev 01/2003 106 Mar 10/2006 203 Nev 01/2003 102 <t< td=""><td>5</td><td>Nov 01/2003</td><td>、 ,</td><td></td><td>202</td><td>Nov 01/2003</td></t<>	5	Nov 01/2003	、 ,		202	Nov 01/2003
b3-50-01 ALLOWABLE DAMAGE 1 204 Nov 01/2003 101 Nov 01/2003 101 Nov 01/2003 206 Nov 01/2003 102 Nov 01/2003 101 Nov 01/2003 206 Nov 01/2003 103 Nov 10/2007 102 Jul 10/2004 208 Nov 01/2003 105 Jul 10/2004 104 Jul 10/2004 208 Nov 01/2003 106 Nov 01/2003 105 Jul 10/2004 208 Nov 01/2003 107 Nov 01/2003 105 Jul 10/2004 210 Nov 01/2003 108 Nov 01/2003 101 Nov 01/2003 213 Jul 10/2005 110 Nov 01/2003 102 Mar 10/2006 214 BLANK 111 Nov 01/2003 104 Nov 01/2003 201 Nov 01/2003 101 Nov 01/2003 104 Nov 01/2003 201 Nov 01/2003 102 Nov 01/2003 106 Mar 10/2006 203 Nov 01/2003 102 Nov 01/2003 107 <td>6</td> <td>Jul 10/2004</td> <td></td> <td></td> <td>203</td> <td>Nov 01/2003</td>	6	Jul 10/2004			203	Nov 01/2003
101 Nov 10/2003 101 Nov 01/2003 206 Nov 01/2003 102 Nov 10/2007 102 Jul 10/2004 207 Nov 10/2007 104 Jul 10/2004 103 Jul 10/2004 208 Nov 01/2003 105 Jul 10/2004 104 Jul 10/2004 208 Nov 01/2003 106 Nov 01/2003 106 BLANK 210 Nov 01/2003 107 Nov 01/2003 106 BLANK 211 Nov 01/2003 108 Nov 01/2003 101 Nov 10/2007 213 Jul 10/2005 110 Nov 01/2003 102 Mar 10/2006 214 BLANK 111 Nov 01/2003 104 Nov 01/2003 201 Nov 01/2003 101 Nov 01/2003 106 Mar 10/2006 204 Nov 01/2003 102 Nov 01/2003 107 Mar 10/2006 204 Nov 01/2003 102 Nov 01/2003 108 Nov 01/2003 205 Nov 01/2003 103	55-30-01 ALLOW	ABLE DAMAGE 1			204	Nov 01/2003
ID2 Nov 01/2003 Jul 10/2004 Jul 10/2004 ZOF Nov 10/2007 103 Nov 10/2007 103 Jul 10/2004 207 Nov 01/2003 105 Jul 10/2004 104 Jul 10/2004 209 Nov 01/2003 106 Nov 01/2003 105 Jul 10/2004 209 Nov 01/2003 107 Nov 01/2003 106 BLANK 211 Nov 01/2003 108 Nov 01/2003 101 Nov 10/2006 214 BLANK 110 Nov 01/2003 101 Nov 01/2003 253-0-01 REPAIR 4 112 111 Nov 01/2003 104 Nov 01/2003 201 Nov 01/2003 101 Nov 01/2003 106 Mar 10/2006 204 Nov 01/2003 101 Nov 01/2003 106 Nar 01/2006 204 Nov 01/2003 102 Nov 01/2003 107 Mar 10/2006 206 Nov 01/2003 102 Nov 01/2003 108 Nov 01/2003 207 Nov 01/2003	101	Nov 10/2007			205	Nov 01/2003
103 NoV 10/2007 103 Jul 10/2004 207 NoV 10/2007 104 Jul 10/2004 103 Jul 10/2004 208 Nov 01/2003 105 Jul 10/2004 105 Jul 10/2004 209 Nov 01/2003 106 Nov 01/2003 106 BLANK 210 Nov 01/2003 107 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 5 212 Nov 01/2003 109 Nov 01/2003 101 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 5 214 BLANK 111 Nov 01/2003 102 Mar 10/2006 214 BLANK 111 Nov 01/2003 105 Nov 10/2007 201 Nov 01/2003 101 Nov 01/2003 106 Mar 10/2006 203 Nov 01/2003 101 Nov 01/2003 107 Mar 10/2006 204 Nov 01/2003 102 Nov 01/2003 108 Nov 01/2003 205 Nov 01/2003 103 Nov 01/2003 201 Nov 01/2003 206 Nov 01/2003	102	Nov 01/2003	-		206	Nov 10/2007
104 Jul 10/2004 104 Jul 10/2004 208 Nov 01/2003 105 Jul 10/2004 105 Jul 10/2004 210 Nov 01/2003 107 Nov 01/2003 106 BLANK 211 Nov 01/2003 108 Nov 01/2003 15-30-01 ALLOWABLE DAMAGE 5 212 Nov 01/2003 109 Nov 01/2003 101 Nov 01/2003 213 Jul 10/2005 110 Nov 01/2003 102 Mar 10/2006 214 BLANK 111 Nov 01/2003 104 Nov 01/2003 201 Nov 01/2003 101 Nov 01/2003 104 Nov 01/2003 201 Nov 01/2003 101 Nov 01/2003 106 Mar 10/2006 203 Nov 01/2003 102 Nov 01/2003 106 Nov 01/2003 205 Nov 01/2003 102 Nov 01/2003 109 Nov 01/2003 206 Nov 01/2003 104 Nov 01/2003 201 Nov 01/2003 207 Nov 01/2003 105	103	Nov 10/2007	-		207	Nov 10/2007
105 Jul 10/2004 105 Jul 10/2004 209 Nov 01/2003 106 Nov 01/2003 106 BLANK 210 Nov 01/2003 108 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 5 212 Nov 01/2003 109 Nov 01/2003 101 Nov 01/2003 213 Jul 10/2006 110 Nov 01/2003 102 Mar 10/2006 214 BLANK 111 Nov 01/2003 103 Nov 01/2003 201 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 2 105 Nov 01/2003 201 Nov 01/2003 101 Nov 01/2003 106 Mar 10/2006 203 Nov 01/2003 102 Nov 01/2003 108 Nov 01/2003 205 Nov 01/2003 103 Nov 01/2003 109 Nov 01/2003 206 Nov 01/2003 104 Nov 01/2003 109 Nov 01/2003 207 Nov 01/2003 105 Nov 01/2003 201 Nov 01/2003 207 Nov 01/2003	104	Jul 10/2004			208	Nov 01/2003
106 Nov 01/2003 106 BLANK 210 Nov 01/2003 107 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 5 211 Nov 01/2003 109 Nov 01/2003 101 Nov 10/2007 213 Jul 10/2005 110 Nov 01/2003 102 Mar 10/2006 214 BLANK 111 Nov 01/2003 103 Nov 01/2003 201 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 2 105 Nov 01/2003 201 Nov 01/2003 101 Nov 01/2003 106 Mar 10/2006 203 Nov 01/2003 101 Nov 01/2003 106 Mar 10/2006 204 Nov 01/2003 102 Nov 01/2003 108 Nov 01/2003 205 Nov 01/2003 103 Nov 01/2003 109 Nov 01/2003 206 Nov 01/2007 105 Nov 01/2003 201 Nov 01/2003 206 Nov 01/2003 106 Nov 01/2003 201 Nov 01/2003 209 Nov 01/2003	105	Jul 10/2004			209	Nov 01/2003
107 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 5 211 Nov 01/2003 108 Nov 01/2003 101 Nov 10/2007 213 Jul 10/2005 110 Nov 01/2003 102 Mar 10/2006 214 BLANK 111 Nov 01/2003 103 Nov 01/2003 55-30-01 REPAIR 4 55-30-01 REPAIR 4 112 Nov 01/2003 104 Nov 01/2003 201 Nov 01/2003 101 Nov 01/2003 105 Nov 10/2007 202 Nov 01/2003 101 Nov 10/2007 106 Mar 10/2006 203 Nov 01/2003 102 Nov 01/2003 107 Mar 10/2006 204 Nov 01/2003 103 Nov 01/2003 108 Nov 01/2003 205 Nov 10/2007 105 Nov 01/2003 109 Nov 01/2003 207 Nov 10/2003 106 Nov 10/2007 55-30-01 REPAIR 1 208 Nov 01/2003 107 Nov 01/2003 201 Nov 01/2003 201 Nov 01/2003 1	106	Nov 01/2003			210	Nov 01/2003
108 Nov 01/2003 101 Nov 10/2007 212 Nov 01/2003 109 Nov 01/2003 101 Nov 10/2006 214 BLANK 111 Nov 01/2003 103 Nov 01/2003 55-30-01 REPAIR 4 1112 Nov 01/2003 104 Nov 01/2003 201 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 2 105 Nov 10/2007 202 Nov 01/2003 101 Nov 10/2007 106 Mar 10/2006 203 Nov 01/2003 102 Nov 01/2003 108 Nov 01/2003 205 Nov 01/2003 103 Nov 01/2003 109 Nov 10/2003 206 Nov 01/2003 104 Nov 01/2003 109 Nov 01/2003 207 Nov 01/2003 106 Nov 10/2007 55-30-01 REPAIR 1 208 Nov 01/2003 209 Nov 01/2003 107 Nov 01/2003 201 Nov 01/2003 210 Nov 01/2003 210 Nov 01/2003 106 Nov 01/2003 202 Nov 01/2003 210<	107	Nov 01/2003			211	Nov 01/2003
109 Nov 01/2003 102 Mar 10/2006 213 311 10/2003 110 Nov 01/2003 103 Nov 01/2003 214 BLANK 111 Nov 01/2003 104 Nov 01/2003 55-30-01 REPAIR 4 112 Nov 01/2003 104 Nov 01/2003 201 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 2 105 Nov 10/2006 203 Nov 01/2003 101 Nov 01/2003 107 Mar 10/2006 204 Nov 01/2003 102 Nov 01/2003 108 Nov 01/2003 205 Nov 01/2003 103 Nov 01/2003 109 Nov 01/2003 206 Nov 10/2007 105 Nov 01/2003 100 Nov 01/2003 207 Nov 10/2007 106 Nov 01/2003 201 Nov 01/2003 209 Nov 01/2003 107 Nov 01/2003 201 Nov 01/2003 210 Nov 01/2003 108 Nov 01/2003 205 Nov 01/2003 210 Nov 01/2003 111	108	Nov 01/2003			212	Nov 01/2003
110 Nov 01/2003 103 Nov 01/2003 214 BLANK 111 Nov 01/2003 103 Nov 01/2003 55-30-01 REPAIR 4 112 Nov 01/2003 104 Nov 01/2007 201 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 2 105 Nov 10/2007 202 Nov 01/2003 101 Nov 01/2003 107 Mar 10/2006 203 Nov 01/2003 102 Nov 01/2003 108 Nov 01/2003 205 Nov 01/2003 103 Nov 01/2003 109 Nov 01/2003 206 Nov 01/2003 104 Nov 01/2003 110 Nov 01/2003 207 Nov 10/2007 106 Nov 01/2003 201 Nov 01/2003 209 Nov 01/2003 107 Nov 01/2003 202 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 203 Nov 01/2003 210 Nov 01/2003 111 Nov 01/2003 206 Nov 01/2003 201 Nov 01/2003 112	109	Nov 01/2003			213	Jul 10/2005
111 Nov 01/2003 104 Nov 01/2003 201 Nov 01/2003 112 Nov 01/2003 105 Nov 10/2007 202 Nov 01/2003 101 Nov 01/2003 106 Mar 10/2006 203 Nov 01/2003 102 Nov 01/2003 107 Mar 10/2006 204 Nov 01/2003 103 Nov 01/2003 108 Nov 01/2003 205 Nov 01/2003 104 Nov 01/2003 109 Nov 10/2006 206 Nov 01/2003 104 Nov 01/2003 109 Nov 01/2003 207 Nov 10/2007 105 Nov 01/2003 201 Nov 01/2003 209 Nov 01/2003 107 Nov 01/2003 201 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 202 Nov 01/2003 210 Nov 01/2003 110 Nov 01/2003 204 Nov 01/2003 211 Nov 01/2003 108 Nov 01/2003 205 Nov 01/2003 201 Nov 01/2003	110	Nov 01/2003	-		214	BLANK
112 Nov 01/2003 201 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 2 105 Nov 10/2007 202 Nov 01/2003 101 Nov 10/2003 107 Mar 10/2006 203 Nov 01/2003 102 Nov 01/2003 107 Mar 10/2006 204 Nov 01/2003 103 Nov 01/2003 108 Nov 01/2003 205 Nov 01/2003 104 Nov 01/2003 109 Nov 10/2006 206 Nov 01/2007 105 Nov 01/2003 109 Nov 01/2003 207 Nov 10/2007 106 Nov 01/2003 201 Nov 01/2003 209 Nov 01/2003 107 Nov 01/2003 202 Nov 01/2003 210 Nov 01/2003 108 Nov 01/2003 203 Nov 10/2007 211 Nov 01/2003 110 Nov 01/2003 204 Nov 10/2007 212 Jul 10/2005 111 Nov 01/2003 206 Nov 01/2003 201 Nov 01/2003 103 Nov 01/2003	111	Nov 01/2003	103	Nov 01/2003	55-30-01 REPAIR	4
b3-30-01 ALLOWABLE DAMAGE 2 106 Mar 10/2006 202 Nov 01/2003 101 Nov 01/2003 107 Mar 10/2006 203 Nov 01/2003 102 Nov 01/2003 108 Nov 01/2003 205 Nov 01/2003 104 Nov 01/2003 109 Nov 01/2003 206 Nov 10/2007 105 Nov 01/2003 110 Nov 01/2003 207 Nov 10/2007 106 Nov 10/2007 55-30-01 REPAIR 1 208 Nov 01/2003 107 Nov 01/2003 201 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 203 Nov 10/2007 211 Nov 01/2003 110 Nov 01/2003 204 Nov 10/2007 212 Jul 10/2005 111 Nov 01/2003 205 Nov 01/2003 201 Nov 01/2003 104 Nov 01/2003 206 Nov 01/2003 201 Nov 01/2003 105 Nov 01/2003 206 Nov 01/2003 202 Nov 01/2003 101	112	Nov 01/2003	104	Nov 01/2003	201	Nov 01/2003
101 Nov 10/2007 107 Mar 10/2006 203 Nov 01/2003 102 Nov 01/2003 107 Mar 10/2006 204 Nov 01/2003 103 Nov 01/2003 108 Nov 01/2003 205 Nov 01/2003 104 Nov 01/2003 109 Nov 01/2003 206 Nov 01/2007 105 Nov 01/2003 110 Nov 01/2003 207 Nov 01/2003 106 Nov 01/2003 201 Nov 01/2003 209 Nov 01/2003 107 Nov 01/2003 202 Nov 01/2003 210 Nov 01/2003 108 Nov 01/2003 203 Nov 10/2007 212 Jul 10/2003 110 Nov 01/2003 205 Nov 01/2003 205 Nov 01/2003 111 Nov 01/2003 206 Nov 01/2003 201 Nov 01/2003 102 Nov 10/2007 201 Nov 01/2003 202 Nov 01/2003 102 Nov 10/2007 201 Nov 01/2003 205 Nov 01/2003	55-30-01 ALLOW	ABLE DAMAGE 2	105	Nov 10/2007	202	Nov 01/2003
102 Nov 01/2003 108 Nov 01/2003 204 Nov 01/2003 103 Nov 01/2003 109 Nov 10/2006 206 Nov 01/2003 104 Nov 01/2003 109 Nov 01/2003 207 Nov 10/2007 105 Nov 01/2003 55-30-01 REPAIR 1 208 Nov 01/2003 107 Nov 01/2003 201 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 202 Nov 01/2003 210 Nov 01/2003 109 Nov 01/2003 202 Nov 10/2007 211 Nov 01/2003 110 Nov 01/2003 204 Nov 10/2007 212 Jul 10/2003 110 Nov 01/2003 205 Nov 01/2003 55-30-01 REPAIR 5 111 110 Nov 01/2003 206 Nov 01/2003 201 Nov 01/2003 111 Nov 01/2003 206 Nov 01/2003 201 Nov 01/2003 112 Nov 01/2003 208 BLANK 203 Nov 01/2003	101	Nov 10/2007	106	Mar 10/2006	203	Nov 01/2003
103 Nov 01/2003 109 Nov 10/2006 205 Nov 01/2003 104 Nov 01/2003 109 Nov 10/2006 206 Nov 10/2007 105 Nov 01/2003 110 Nov 01/2003 207 Nov 10/2007 106 Nov 10/2007 55-30-01 REPAIR 1 208 Nov 01/2003 107 Nov 01/2003 201 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 202 Nov 01/2003 210 Nov 01/2003 109 Nov 01/2003 203 Nov 10/2007 211 Nov 01/2003 110 Nov 01/2003 205 Nov 01/2003 212 Jul 10/2005 1111 Nov 01/2003 206 Nov 01/2003 201 Nov 01/2003 112 Nov 01/2003 208 BLANK 203 Nov 01/2003 102 Nov 10/2007 55-30-01 REPAIR 2 204 Nov 01/2003 103 Nov 01/2003 201 Nov 01/2003 205 Nov 01/2003 104	102	Nov 01/2003	107	Mar 10/2006	204	Nov 01/2003
104 Nov 01/2003 110 Nov 01/2003 206 Nov 10/2007 105 Nov 01/2003 110 Nov 01/2003 207 Nov 10/2007 106 Nov 10/2007 55-30-01 REPAIR 1 208 Nov 01/2003 107 Nov 01/2003 201 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 202 Nov 01/2003 210 Nov 01/2003 109 Nov 01/2003 203 Nov 10/2007 211 Nov 01/2003 110 Nov 01/2003 204 Nov 10/2007 212 Jul 10/2005 111 Nov 01/2003 205 Nov 01/2003 201 Nov 01/2003 111 Nov 01/2003 206 Nov 01/2003 201 Nov 01/2003 112 Nov 01/2003 208 BLANK 203 Nov 01/2003 102 Nov 10/2007 25-30-01 REPAIR 2 204 Nov 01/2003 103 Nov 01/2003 201 Nov 01/2003 205 Nov 01/2003 <	103	Nov 01/2003	108	Nov 01/2003	205	Nov 01/2003
105 Nov 01/2003 55-30-01 REPAIR 1 207 Nov 01/2003 208 Nov 01/2003 209 Nov 01/2003 209 Nov 01/2003 201 Nov 01/2003 209 Nov 01/2003 209 Nov 01/2003 201 Nov 01/2003 210 Nov 01/2003 211 Nov 01/2003 212 Jul 10/2005 211 Nov 01/2003 205 Nov 01/2003 201 Nov 01/2003 202 Nov 01/2003 202 Nov 01/2003 201 Nov 01/2003 202 Nov 01/2003 202 Nov 01/2003 202 Nov 01/2003 202 Nov 01/2003 203 Nov 01/2003 204 Nov 01/2003 205 Nov 01/2003 204 Nov 01/2003 205 Nov 01/2003 205 Nov 01/2003	104	Nov 01/2003	109	Nov 10/2006	206	Nov 10/2007
106 Nov 10/2007 201 Nov 01/2003 209 Nov 01/2003 107 Nov 01/2003 202 Nov 01/2003 210 Nov 01/2003 109 Nov 01/2003 203 Nov 10/2007 211 Nov 01/2003 110 Nov 01/2003 204 Nov 10/2007 212 Jul 10/2005 111 Nov 01/2003 206 Nov 01/2003 55-30-01 REPAIR 5 112 Nov 01/2003 206 Nov 01/2003 202 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 3 207 Nov 01/2003 202 Nov 01/2003 101 Jul 10/2005 208 BLANK 203 Nov 01/2003 102 Nov 10/2007 55-30-01 REPAIR 2 204 Nov 01/2003 103 Nov 01/2003 201 Nov 01/2003 205 Nov 10/2007 105 Nov 01/2003 203 Nov 10/2007 207 Nov 10/2007 106 Nov 10/2007 204 Nov 01/2003 209 Nov 01/2003 107 <t< td=""><td>105</td><td>Nov 01/2003</td><td>-</td><td></td><td>207</td><td>Nov 10/2007</td></t<>	105	Nov 01/2003	-		207	Nov 10/2007
107 Nov 01/2003 202 Nov 01/2003 210 Nov 01/2003 108 Nov 01/2003 203 Nov 10/2007 211 Nov 01/2003 109 Nov 01/2003 204 Nov 10/2007 211 Nov 01/2003 110 Nov 01/2003 204 Nov 10/2007 212 Jul 10/2005 111 Nov 01/2003 205 Nov 01/2003 55-30-01 REPAIR 5 201 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 3 207 Nov 01/2003 202 Nov 01/2003 202 Nov 01/2003 101 Jul 10/2005 208 BLANK 203 Nov 01/2003 102 Nov 01/2003 201 Nov 01/2003 205 Nov 01/2003 103 Nov 01/2003 201 Nov 01/2003 205 Nov 10/2007 105 Nov 01/2003 203 Nov 10/2007 206 Nov 10/2007 106 Nov 10/2007 204 Nov 01/2003 209 Nov 01/2003 107 Nov 01/2003 205 Nov 01/2003	106	Nov 10/2007	55-30-01 REPAIR	1	208	Nov 01/2003
108 Nov 01/2003 203 Nov 10/2007 211 Nov 01/2003 109 Nov 01/2003 204 Nov 10/2007 212 Jul 10/2005 110 Nov 01/2003 205 Nov 01/2003 55-30-01 REPAIR 5 112 Nov 01/2003 206 Nov 01/2003 202 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 3 207 Nov 01/2003 202 Nov 01/2003 101 Jul 10/2005 208 BLANK 203 Nov 01/2003 102 Nov 10/2007 201 Nov 01/2003 205 Nov 01/2003 103 Nov 01/2003 202 Nov 01/2003 206 Nov 10/2007 105 Nov 01/2003 202 Nov 01/2003 206 Nov 10/2007 106 Nov 10/2007 204 Nov 01/2003 208 Nov 01/2003 107 Nov 01/2003 202 Nov 01/2003 206 Nov 01/2003 106 Nov 01/2003 203 Nov 01/2003 209 Nov 01/2003 107<	107	Nov 01/2003	201	Nov 01/2003	209	Nov 01/2003
109 Nov 01/2003 204 Nov 10/2007 212 Jul 10/2003 110 Nov 01/2003 205 Nov 01/2003 55-30-01 REPAIR 5 112 Nov 01/2003 206 Nov 01/2003 201 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 3 207 Nov 01/2003 202 Nov 01/2003 101 Jul 10/2005 208 BLANK 203 Nov 01/2003 102 Nov 01/2003 201 Nov 01/2003 205 Nov 01/2003 103 Nov 01/2003 201 Nov 01/2003 205 Nov 01/2003 104 Nov 01/2003 202 Nov 01/2003 206 Nov 10/2007 105 Nov 01/2003 203 Nov 10/2007 206 Nov 01/2003 106 Nov 10/2007 204 Nov 01/2003 209 Nov 01/2003 107 Nov 01/2003 205 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 206 Nov 01/2003 210 BLANK	108	Nov 01/2003	202	Nov 01/2003	210	Nov 01/2003
110 Nov 01/2003 205 Nov 01/2003 55-30-01 REPAIR 5 111 Nov 01/2003 206 Nov 01/2003 201 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 3 207 Nov 01/2003 202 Nov 01/2003 101 Jul 10/2005 208 BLANK 203 Nov 01/2003 102 Nov 01/2003 201 Nov 01/2003 205 Nov 01/2003 103 Nov 01/2003 202 Nov 01/2003 205 Nov 01/2003 104 Nov 01/2003 202 Nov 01/2003 206 Nov 10/2007 105 Nov 01/2003 203 Nov 10/2007 207 Nov 10/2007 106 Nov 10/2007 204 Nov 10/2007 208 Nov 01/2003 107 Nov 01/2003 205 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 206 Nov 01/2003 210 BLANK	109	Nov 01/2003	203	Nov 10/2007	211	Nov 01/2003
111 Nov 01/2003 206 Nov 01/2003 201 Nov 01/2003 112 Nov 01/2003 207 Nov 01/2003 201 Nov 01/2003 55-30-01 ALLOWABLE DAMAGE 3 207 Nov 01/2003 202 Nov 01/2003 101 Jul 10/2005 208 BLANK 203 Nov 01/2003 102 Nov 01/2003 201 Nov 01/2003 205 Nov 01/2003 103 Nov 01/2003 201 Nov 01/2003 205 Nov 01/2003 104 Nov 01/2003 203 Nov 10/2007 207 Nov 10/2007 105 Nov 01/2003 203 Nov 10/2007 207 Nov 01/2003 106 Nov 10/2007 204 Nov 01/2003 209 Nov 01/2003 107 Nov 01/2003 206 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 206 Nov 01/2003 210 BLANK	110	Nov 01/2003			212	Jul 10/2005
112 Nov 01/2003 207 Nov 01/2003 202 Nov 01/2003 203 Nov 01/2003 202 Nov 01/2003 203 Nov 01/2003 204 Nov 01/2003 205 Nov 01/2003 205 Nov 01/2003 205 Nov 01/2003 206 Nov 10/2007 203 Nov 01/2003 206 Nov 10/2007 207 Nov 01/2003 206 Nov 01/2003 206 Nov 01/2003 207 Nov 01/2003 206 Nov 01/2003 209 Nov 01/2003 209 Nov 01/2003 209 Nov 01/2003 209 Nov 01/2003 206 Nov 01/2003 206 Nov 01/2003 210 BLANK	111	Nov 01/2003		Nov 01/2003	55-30-01 REPAIR	5
S5-30-01 ALLOWABLE DAMAGE 3 208 BLANK 203 Nov 01/2003 101 Jul 10/2005 208 BLANK 203 Nov 01/2003 102 Nov 10/2007 55-30-01 REPAIR 2 204 Nov 01/2003 103 Nov 01/2003 201 Nov 01/2003 205 Nov 01/2003 104 Nov 01/2003 202 Nov 01/2003 206 Nov 10/2007 105 Nov 01/2003 203 Nov 10/2007 207 Nov 10/2007 106 Nov 10/2007 204 Nov 01/2003 209 Nov 01/2003 107 Nov 01/2003 206 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 206 Nov 01/2003 210 BLANK	112	Nov 01/2003			201	Nov 01/2003
101 Jul 10/2005 203 Nov 01/2003 102 Nov 10/2007 55-30-01 REPAIR 2 204 Nov 01/2003 103 Nov 01/2003 201 Nov 01/2003 205 Nov 01/2003 104 Nov 01/2003 202 Nov 01/2003 206 Nov 10/2007 105 Nov 01/2003 203 Nov 10/2007 207 Nov 10/2007 106 Nov 10/2007 204 Nov 01/2003 208 Nov 01/2003 107 Nov 01/2003 205 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 206 Nov 01/2003 210 BLANK	55-30-01 ALLOW	ABLE DAMAGE 3	207		202	Nov 01/2003
102 Nov 10/2007 201 Nov 01/2003 204 Nov 01/2003 103 Nov 01/2003 201 Nov 01/2003 205 Nov 01/2003 104 Nov 01/2003 202 Nov 01/2003 206 Nov 10/2007 105 Nov 01/2003 203 Nov 10/2007 207 Nov 10/2007 106 Nov 01/2003 205 Nov 01/2003 208 Nov 01/2003 107 Nov 01/2003 206 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 206 Nov 01/2003 210 BLANK	101	Jul 10/2005	208	BLANK	203	Nov 01/2003
103 Nov 01/2003 202 Nov 01/2003 206 Nov 01/2003 104 Nov 01/2003 202 Nov 01/2003 206 Nov 10/2007 105 Nov 01/2003 203 Nov 10/2007 207 Nov 10/2007 106 Nov 10/2007 204 Nov 10/2007 208 Nov 01/2003 107 Nov 01/2003 205 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 206 Nov 01/2003 210 BLANK	102	Nov 10/2007	55-30-01 REPAIR	2	204	Nov 01/2003
104 Nov 01/2003 203 Nov 10/2007 206 Nov 10/2007 105 Nov 01/2003 203 Nov 10/2007 207 Nov 10/2007 106 Nov 10/2007 204 Nov 10/2007 208 Nov 01/2003 107 Nov 01/2003 205 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 206 Nov 01/2003 210 BLANK	103	Nov 01/2003	201	Nov 01/2003	205	Nov 01/2003
105 Nov 01/2003 204 Nov 10/2007 208 Nov 01/2003 106 Nov 01/2007 204 Nov 10/2007 208 Nov 01/2003 107 Nov 01/2003 205 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 206 Nov 01/2003 210 BLANK	104	Nov 01/2003	202	Nov 01/2003	206	Nov 10/2007
106 Nov 10/2007 205 Nov 01/2003 209 Nov 01/2003 107 Nov 01/2003 206 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 206 Nov 01/2003 210 BLANK	105	Nov 01/2003	203	Nov 10/2007	207	Nov 10/2007
107 Nov 01/2003 209 Nov 01/2003 108 Nov 01/2003 206 Nov 01/2003 210 BLANK	106	Nov 10/2007	204		208	Nov 01/2003
108 Nov 01/2003 206 Nov 01/2003 210 BLANK	107	Nov 01/2003	205	Nov 01/2003	209	Nov 01/2003
	108		206	Nov 01/2003	210	
109 Nov 01/2003 55-30-01 REPAIR 5 55-30-01 REPAIR 6			55-30-01 REPAIR	3		
110 Nov 01/2003 201 Nov 01/2003 201 Nov 01/2003			201	Nov 01/2003		

A = Added, R = Revised, O = Overflow, D = Deleted

55-EFFECTIVE PAGES

Page 8 Jul 10/2009



CHAPTER 55 STABILIZERS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
55-30-01 REPAIR	R 6 (cont)	55-30-01 REPAIR	10	55-30-09 IDENTI	FICATION 2 (cont)
202	Nov 01/2003	201	Nov 01/2003	6	Mar 10/2004
203	Nov 01/2003	202	Nov 01/2003	7	Mar 10/2004
204	Nov 01/2003	203	Nov 01/2003	8	Mar 10/2004
205	Nov 01/2003	204	Nov 01/2003	9	Mar 10/2004
206	Nov 10/2007	205	Nov 01/2003	10	BLANK
207	Nov 10/2007	206	Nov 01/2003	55-30-09 IDENTI	FICATION 3
208	Nov 01/2003	207	Nov 10/2007	1	Mar 10/2004
209	Nov 01/2003	208	Nov 10/2007	2	Mar 10/2004
210	BLANK	209	Nov 01/2003	3	Mar 10/2004
55-30-01 REPAI	R 7	210	Nov 01/2003	4	Nov 01/2003
201	Nov 01/2003	55-30-01 REPAIR	R 11	55-30-09 IDENTI	FICATION 4
202	Nov 01/2003	201	Nov 01/2003	1	Jul 10/2004
203	Nov 01/2003	202	Nov 01/2003	2	Mar 10/2004
204	Nov 01/2003	203	Nov 01/2003	3	Nov 01/2003
205	Nov 01/2003	204	Nov 01/2003	4	BLANK
206	Nov 10/2007	205	Nov 01/2003	55-30-09 ALLOW	ABLE DAMAGE 2
207	Nov 10/2007	206	Nov 10/2007	101	Nov 01/2003
208	Nov 01/2003	207	Nov 10/2007	102	Nov 01/2003
209	Nov 01/2003	208	Nov 01/2003	103	Nov 01/2003
210	BLANK	209	Nov 01/2003	104	Nov 01/2003
55-30-01 REPAI	R 8	210	BLANK	105	Nov 01/2003
201	Nov 01/2003	55-30-01 REPAIR	12	106	Nov 01/2003
202	Nov 01/2003	201	Nov 01/2003	107	Nov 01/2003
203	Nov 01/2003	202	Nov 01/2003	108	Nov 01/2003
204	Nov 01/2003	203	Nov 01/2003	109	Nov 01/2003
205	Nov 01/2003	204	Mar 10/2006	110	Nov 01/2003
206	Nov 10/2007	205	Nov 10/2006	55-30-09 REPAIF	3 2
207	Nov 10/2007	206	BLANK	201	Nov 10/2006
208	Nov 01/2003	55-30-09 IDENTIF	FICATION 1	202	Nov 10/2006
209	Nov 01/2003	1	Jul 10/2004	55-30-10 IDENTI	FICATION 1
210	BLANK	2	Mar 10/2004	1	Jul 10/2004
55-30-01 REPAIR	R 9	3	Nov 01/2003	2	Mar 10/2004
201	Nov 01/2003	4	BLANK	3	Nov 01/2003
202	Nov 01/2003	55-30-09 IDENTIF	FICATION 2	4	Mar 10/2004
203	Nov 01/2003	1	Jul 10/2004	5	Mar 10/2004
204	Nov 01/2003	2	Mar 10/2004	6	Mar 10/2004
205	Nov 01/2003	3	Nov 01/2003	7	Mar 10/2004
206	Nov 01/2003	4	Mar 10/2004	8	BLANK
		5	Mar 10/2004		

A = Added, R = Revised, O = Overflow, D = Deleted

55-EFFECTIVE PAGES



CHAPTER 55 STABILIZERS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
55-30-10 IDENTI	FICATION 2	55-30-10 REPAIR	2 (cont)	55-30-13 IDENTIFICATION 1	
1	Jul 10/2004	202	Nov 01/2003	1	Jul 10/2004
2	Mar 10/2004	203	Nov 10/2007	2	Mar 10/2004
3	Nov 01/2003	204	Nov 10/2007	3	Nov 01/2003
4	Nov 01/2003	205	Nov 01/2003	4	BLANK
5	Mar 10/2004	206	Nov 01/2003	55-30-13 ALLOW	ABLE DAMAGE 1
6	Mar 10/2004	207	Nov 01/2003	101	Nov 01/2003
55-30-10 ALLOW	ABLE DAMAGE 1	208	BLANK	102	Jul 10/2004
101	Nov 01/2003	55-30-10 REPAIR	3	103	Jul 10/2004
102	Jul 10/2004	201	Nov 01/2003	104	Nov 01/2003
103	Jul 10/2004	202	Nov 01/2003	105	Nov 01/2003
104	Jul 10/2004	203	Nov 10/2007	106	BLANK
105	Nov 01/2003	204	Nov 10/2007	55-30-13 REPAIR	1
106	Nov 01/2003	205	Nov 01/2003	201	Nov 01/2003
107	Nov 01/2003	206	Nov 01/2003	202	Nov 01/2003
108	Nov 01/2003	207	Nov 01/2003	55-30-30 IDENTIF	FICATION 1
109	Nov 01/2003	208	Nov 01/2003	1	Jul 10/2004
110	Nov 01/2003	209	Nov 01/2003	2	Mar 10/2004
111	Nov 01/2003	210	BLANK	3	Nov 01/2003
112	BLANK	55-30-10 REPAIR	4	4	BLANK
55-30-10 ALLOW	ABLE DAMAGE 2	201	Nov 01/2003	55-30-30 IDENTIFICATION 2	
101	Nov 01/2003	202	Nov 01/2003	1	Jul 10/2004
102	Jul 10/2004	203	Nov 10/2007	2	Jul 10/2004
103	Jul 10/2004	204	Nov 10/2007	55-30-30 ALLOW	ABLE DAMAGE 1
104	Jul 10/2004	205	Nov 01/2003	101	Nov 10/2005
105	Nov 01/2003	206	Nov 01/2003	102	Nov 10/2005
106	Nov 01/2003	207	Nov 01/2003	103	Nov 10/2007
107	Nov 01/2003	208	Nov 01/2003	104	Nov 10/2007
108	Nov 01/2003	209	Nov 01/2003	105	Nov 10/2007
109	Nov 01/2003	210	Nov 01/2003	106	Nov 10/2005
110	BLANK	55-30-10 REPAIR	5	107	Nov 10/2005
55-30-10 REPAIF	R 1	201	Nov 01/2003	108	Nov 10/2005
201	Mar 10/2007	202	Nov 01/2003	109	Nov 10/2005
202	Nov 01/2003	203	Nov 10/2007	110	Nov 10/2005
203	Nov 01/2003	204	Nov 10/2007	55-30-30 ALLOW	ABLE DAMAGE 2
204	Nov 01/2003	205	Nov 01/2003	101	Jul 10/2005
205	Nov 01/2003	206	Nov 01/2003	102	Nov 10/2007
206	BLANK	207	Nov 01/2003	103	Nov 10/2007
55-30-10 REPAIF	3 2	208	BLANK	104	Nov 01/2003
201	Nov 01/2003			105	Nov 01/2003

A = Added, R = Revised, O = Overflow, D = Deleted

55-EFFECTIVE PAGES

Page 10 Jul 10/2009



CHAPTER 55 STABILIZERS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
	ABLE DAMAGE 2		ABLE DAMAGE 1	55-40-01 ALLOW	ABLE DAMAGE 1
(cont)		(cont)		101	Nov 01/2003
106	BLANK	116	Nov 01/2003	102	Nov 10/2005
55-30-30 REPAIF		117	Nov 01/2003	103	Nov 10/2005
201	Nov 10/2005	118	Nov 01/2003	104	Nov 10/2005
202	Nov 10/2005	119	Nov 01/2003	105	Nov 10/2005
203	Nov 10/2005	120	Nov 01/2003	106	Nov 10/2005
204	Nov 10/2005	121	Nov 01/2003	107	Nov 10/2005
205	Nov 10/2005	122	Nov 01/2003	108	Nov 10/2005
206	Nov 10/2005	123	Nov 01/2003	109	Nov 10/2005
207	Nov 10/2005	124	Nov 01/2003	110	Nov 01/2003
208	BLANK	55-30-90 REPAIR	R GENERAL	111	Nov 10/2005
55-30-30 REPAIF	R 2	201	Nov 10/2006	112	Nov 01/2003
201	Nov 01/2003	202	Nov 01/2003	113	Nov 10/2005
202	Jul 10/2004	55-40-01 IDENTIF	FICATION 1	114	BLANK
203	Jul 10/2004	1	Mar 10/2004	55-40-01 ALLOW	ABLE DAMAGE 2
204	Jul 10/2004	2	Mar 10/2004	101	Mar 10/2006
205	Jul 10/2004	3	Mar 10/2004	102	Mar 10/2006
206	BLANK	4	Nov 01/2003	103	Nov 01/2003
55-30-90 IDENTI	FICATION 1	5	Nov 01/2003	104	Mar 10/2006
1	Jul 10/2004	6	Mar 10/2004	55-40-01 REPAIF	
2	Mar 10/2004	7	Mar 10/2004	201	Nov 10/2005
3	Nov 01/2003	8	Nov 01/2003	202	Nov 01/2003
4	Nov 01/2003	9	Nov 01/2003	203	Nov 01/2003
55-30-90 ALLOW	ABLE DAMAGE 1	10	Jul 10/2005	204	Mar 10/2006
101	Nov 01/2003	11	Mar 10/2004	205	Mar 10/2006
102	Nov 01/2003	12	Mar 10/2004	206	BLANK
103	Nov 01/2003	13	Mar 10/2004	55-40-02 IDENTI	
104	Nov 01/2003	14	Mar 10/2004	1	Jul 10/2004
105	Nov 01/2003	15	Mar 10/2004	2	Mar 10/2004
106	Nov 01/2003	16	Mar 10/2004	3	Mar 10/2004
107	Nov 01/2003	17	Mar 10/2004	3	Mar 10/2004
108	Nov 01/2003	18	Mar 10/2004	5	
109	Nov 01/2003	19	Mar 10/2004	5	Nov 01/2003 Nov 01/2003
110	Nov 01/2003	20	Mar 10/2004	6 7	Nov 01/2003
111	Nov 01/2003	21	Mar 10/2004		Mar 10/2003
112	Mar 10/2007	22	Mar 10/2004	8	
113	Jul 10/2004	23	Nov 01/2003	9	Mar 10/2004
114	Nov 01/2003	24	BLANK	10	Nov 01/2003
115	Nov 01/2003			11	Mar 10/2004
	-			12	Mar 10/2004

A = Added, R = Revised, O = Overflow, D = Deleted

55-EFFECTIVE PAGES

Page 11 Jul 10/2009



CHAPTER 55 STABILIZERS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
55-40-02 IDENTI	FICATION 1 (cont)	55-40-02 IDENTIF	FICATION 2 (cont)	55-40-02 REPAIR	1
13	Nov 01/2003	25	Jul 10/2004	201	Jul 10/2005
14	Mar 10/2004	26	BLANK	202	Nov 01/2003
15	Mar 10/2004	55-40-02 IDENTIF	FICATION 3	203	Nov 01/2003
16	Nov 01/2003	1	Jul 10/2004	204	Nov 01/2003
17	Mar 10/2004	2	Mar 10/2004	205	Nov 01/2003
18	Mar 10/2004	3	Mar 10/2004	206	Nov 01/2003
19	Nov 01/2003	4	Mar 10/2004	207	Jul 10/2005
20	Mar 10/2004	5	Nov 01/2003	208	Jul 10/2005
21	Mar 10/2004	6	BLANK	209	Nov 10/2006
22	Nov 01/2003	55-40-02 ALLOW	ABLE DAMAGE 1	210	Nov 01/2003
23	Mar 10/2004	101	Jul 10/2005	55-40-30 IDENTIF	FICATION 1
24	Mar 10/2004	102	Nov 01/2003	1	Jul 10/2004
25	Nov 01/2003	103	Nov 01/2003	2	Jul 10/2004
26	BLANK	104	Nov 01/2003	3	Mar 10/2004
55-40-02 IDENTI	FICATION 2	105	Nov 01/2003	4	Nov 01/2003
1	Jul 10/2004	106	Nov 01/2003	5	Mar 10/2004
2	Mar 10/2004	107	Jul 10/2005	6	Mar 10/2004
3	Nov 01/2003	108	Nov 01/2003	7	Mar 10/2004
4	Jul 10/2004	109	Nov 01/2003	8	Mar 10/2004
5	Jul 10/2004	110	BLANK	9	Nov 01/2003
6	Jul 10/2004	55-40-02 ALLOW	ABLE DAMAGE 2	10	BLANK
7	Jul 10/2004	101	Nov 01/2003	55-40-30 ALLOW	ABLE DAMAGE 1
8	Jul 10/2004	102	Nov 01/2003	101	Nov 10/2006
9	Jul 10/2004	103	Nov 01/2003	102	Nov 10/2006
10	Jul 10/2004	104	Nov 01/2003	103	Nov 01/2003
11	Jul 10/2004	105	Nov 01/2003	104	Mar 10/2006
12	Jul 10/2004	106	Nov 01/2003	105	Mar 10/2006
13	Jul 10/2004	55-40-02 ALLOW	ABLE DAMAGE 3	106	BLANK
14	Jul 10/2004	101	Nov 01/2003	55-40-30 REPAIR	1
15	Jul 10/2004	102	Nov 01/2003	201	Nov 01/2003
16	Jul 10/2004	103	Nov 01/2003	202	Nov 01/2003
17	Jul 10/2004	104	Nov 01/2003	203	Nov 01/2003
18	Jul 10/2004	105	Jul 10/2004	204	Jul 10/2005
19	Jul 10/2004	106	Jul 10/2004	205	Mar 10/2006
20	Jul 10/2004	107	Nov 01/2003	206	BLANK
21	Jul 10/2004	108	Nov 01/2003	55-40-90 IDENTIF	FICATION 1
22	Jul 10/2004	109	Nov 01/2003	1	Jul 10/2004
23	Jul 10/2004	110	BLANK	2	Mar 10/2004
24	Jul 10/2004			3	Nov 01/2003

A = Added, R = Revised, O = Overflow, D = Deleted

55-EFFECTIVE PAGES

Page 12 Jul 10/2009



CHAPTER 55 STABILIZERS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
55-40-90 IDENTIF	FICATION 1 (cont)				
4	BLANK				
55-40-90 ALLOW	ABLE DAMAGE 1				
101	Nov 01/2003				
102	Nov 01/2003				
103	Nov 01/2003				
104	Nov 01/2003				
105	Nov 01/2003				
106	Nov 01/2003				
107	Nov 01/2003				
108	Nov 01/2003				
109	Nov 01/2003				
110	BLANK				
55-40-90 REPAIR	1				
201	Nov 01/2003				
202	Nov 10/2006				

A = Added, R = Revised, O = Overflow, D = Deleted

55-EFFECTIVE PAGES

Page 13 Jul 10/2009



CHAPTER 55 STABILIZERS

SUBJECT	CHAPTER SECTION SUBJECT
HORIZONTAL STABILIZER	55-10-00
IDENTIFICATION GENERAL - Horizontal Stabilizer Station Diagram	
HORIZONTAL STABILIZER SKIN	55-10-01
IDENTIFICATION 1-Horizontal Stabilizer Leading Edge Skin	
IDENTIFICATION 2-Horizontal Stabilizer Upper Inspar Skin	
IDENTIFICATION 3-Upper Panel Assembly - Horizontal Stabilizer Trailing Edge	
IDENTIFICATION 4-Horizontal Stabilizer Lower Inspar Skin	
IDENTIFICATION 5-Lower Panel Assembly - Horizontal Stabilizer Trailing Edge	
ALLOWABLE DAMAGE 1-Horizontal Stabilizer Leading Edge Skins	
ALLOWABLE DAMAGE 2-Horizontal Stabilizer Inspar Skins	
ALLOWABLE DAMAGE 3-Horizontal Stabilizer Trailing Edge Panels	
ALLOWABLE DAMAGE 4-Horizontal Stabilizer Leading Edge Skins, Erosion Damage	
REPAIR 1-Horizontal Stabilizer Leading Edge Skin External Repair	
REPAIR 2-Flush Repair of the Horizontal Stabilizer Leading Edge Skin	
REPAIR 3-Horizontal Stabilizer Inspar Skin External Repair	
REPAIR 4-Horizontal Stabilizer Inspar Skin Flush Repair	
REPAIR 7-Horizontal Stabilizer Access Panel Installation With a One-Piece Doubler	
REPAIR 8 - Horizontal Stabilizer Lower Skin and Access Panel Installation With a Two- Piece Doubler	
REPAIR 9-Horizontal Stabilizer Trailing Edge Panels	
REPAIR 10-Horizontal Stabilizer Trailing Edge Panel Conductive Strip	
HORIZONTAL STABILIZER INTERCOSTALS	55-10-04
IDENTIFICATION 1-Horizontal Stabilizer Inspar Intercostals	
HORIZONTAL STABILIZER RIBS	55-10-09
IDENTIFICATION 1-Horizontal Stabilizer Leading Edge Ribs	
IDENTIFICATION 2-Horizontal Stabilizer Inspar Ribs	
IDENTIFICATION 3-Horizontal Stabilizer Trailing Edge Ribs	

55-CONTENTS



CHAPTER 55 STABILIZERS

	CHAPTER SECTION
	SUBJECT
HORIZONTAL STABILIZER SPARS	55-10-10
IDENTIFICATION 1-Horizontal Stabilizer Front Spar Structure	
IDENTIFICATION 2-Horizontal Stabilizer Rear Spar Structure	
IDENTIFICATION 3-Horizontal Stabilizer Center Section Spar Structure	
ALLOWABLE DAMAGE 1-Horizontal Stabilizer Front Spar	
ALLOWABLE DAMAGE 2-Horizontal Stabilizer Rear Spar	
REPAIR 1-Horizontal Stabilizer Front Spar Web	
HORIZONTAL STABILIZER BEAMS	55-10-13
IDENTIFICATION 1-Horizontal Stabilizer Beam	
IDENTIFICATION 2-Horizontal Stabilizer Center Section Beams	
ALLOWABLE DAMAGE 1-Horizontal Stabilizer Trailing Edge Beams	
ALLOWABLE DAMAGE 2-Horizontal Stabilizer Center Section	
REPAIR 1-Horizontal Stabilizer Trailing Edge Beams	
REPAIR 2-Horizontal Stabilizer Center Section Beams	
HORIZONTAL STABILIZER AUXILIARY STRUCTURE	55-10-30
IDENTIFICATION 1-Horizontal Stabilizer Tip	
IDENTIFICATION 2-Horizontal Stabilizer Cove	
ALLOWABLE DAMAGE 1-Horizontal Stabilizer Tip	
ALLOWABLE DAMAGE 2-Horizontal Stabilizer Cove	
REPAIR 1-Horizontal Stabilizer Tip	
REPAIR 2-Horizontal Stabilizer Cove	
HORIZONTAL STABILIZER FITTINGS	55-10-90
IDENTIFICATION 1-Horizontal Stabilizer Fittings	
IDENTIFICATION 2-Horizontal Stabilizer Center Section Beam Fittings	
REPAIR 1-Horizontal Stabilizer Outboard Closure Rib Lightning Strike Repair	
ELEVATOR SKIN	55-20-01
IDENTIFICATION 1-Elevator Upper Skin	

55-CONTENTS

Page 2 Nov 10/2005



CHAPTER 55 STABILIZERS

SUBJECT

IDENTIFICATION 2-Elevator Lower Skin

IDENTIFICATION 3-Elevator Tab Skins

ALLOWABLE DAMAGE 1-Upper and Lower Elevator Skin Panels

ALLOWABLE DAMAGE 2-Elevator Tab Skins

ALLOWABLE DAMAGE 3 - Elevator Tab Skins For Airplane Line Numbers 1175 And On And Line Numbers 1 Through 1174 With Completion of Service Bulletins 737-55-1080 and 737-55-1082

REPAIR 1-Elevator Skins

REPAIR 2-Elevator Tab Skins

REPAIR 3-Elevator Tab Skins For Airplane Line Numbers 1175 And On And Line Numbers 1 Through 1174 With Completion of Service Bulletins 737-55-1080 and 737-55-1082

REPAIR 4-Elevator Hinge Cover Crack

ELEVATOR STRUCTURE

IDENTIFICATION 1-Elevator Leading Edge Structure

IDENTIFICATION 2-Elevator Rib Structure

IDENTIFICATION 3-Elevator Rear Spar Structure

ALLOWABLE DAMAGE 1-Elevator Structure

ALLOWABLE DAMAGE 2-Elevator Tab Spar

ALLOWABLE DAMAGE 3-Elevator Tab Spar For Airplane Line Numbers 1175 and On and Line Numbers 1 Through 1174 With Completion of Service Bulletins 737-55-1080 and 737-55-1082

REPAIR 1-Elevator Structure

REPAIR 2-Elevator Tab Spar

REPAIR 3-Elevator Tab Spar For Airplane Line Numbers 1175 And On And Line Numbers 1 Through 1174 With Completion of Service Bulletins 737-55-1080 and 737-55-1082

ELEVATOR BALANCE HORN

IDENTIFICATION 1-Elevator Balance Horn Fairing

ALLOWABLE DAMAGE 1-Elevator Balance Horn Fairing

55-CONTENTS

Page 3 Nov 10/2005

D634A210

CHAPTER SECTION SUBJECT

55-20-02

55-20-30



CHAPTER 55 STABILIZERS

SUBJECT	CHAPTER SECTION SUBJECT
REPAIR 1-Elevator Balance Horn Fairing	
ELEVATOR FAIRINGS	55-20-70
IDENTIFICATION 1-Elevator Fairing and Elevator Tab Fairing Skin	
ALLOWABLE DAMAGE 1-Elevator Fairing Skin and Elevator Tab Fairing Skin	
REPAIR 1-Elevator Fairing and Elevator Tab Fairing Skin	
ELEVATOR SPAR FITTINGS	55-20-90
IDENTIFICATION 1-Elevator Front Spar Hinge Fittings	
IDENTIFICATION 2-Elevator Rear Spar Hinge Fittings	
IDENTIFICATION 3-Elevator Tab Fittings	
ALLOWABLE DAMAGE 1-Elevator Front Spar Hinge Fittings	
ALLOWABLE DAMAGE 2-Elevator Rear Spar Hinge Fittings	
ALLOWABLE DAMAGE 3-Elevator Tab Fittings	
REPAIR 1-Elevator Front Spar Hinge Fittings	
REPAIR 2-Elevator Rear Spar Hinge Fittings	
REPAIR 3-Elevator Tab Fittings	
VERTICAL STABILIZER	55-30-00
IDENTIFICATION GENERAL - Vertical Stabilizer and Rudder Station Diagram	
VERTICAL STABILIZER SKIN	55-30-01
IDENTIFICATION 1-Vertical Stabilizer Leading Edge Skin	
IDENTIFICATION 2-Vertical Stabilizer Left Inspar Skin	
IDENTIFICATION 3-Vertical Stabilizer Left Trailing Edge Panels	
IDENTIFICATION 4-Vertical Stabilizer Right Inspar Skin	
IDENTIFICATION 5-Vertical Stabilizer Right Trailing Edge Panels	
IDENTIFICATION 6-Dorsal Fin Skin	
ALLOWABLE DAMAGE 1-Vertical Stabilizer Leading Edge Skins	
ALLOWABLE DAMAGE 2-Vertical Stabilizer Inspar Skins	
ALLOWABLE DAMAGE 3-Vertical Stabilizer Trailing Edge Panels	

55-CONTENTS



CHAPTER 55 STABILIZERS

SUBJECT

ALLOWABLE DAMAGE 4-Vertical Stabilizer Leading Edge Skins, Erosion Damage

ALLOWABLE DAMAGE 5-Dorsal Fin Skin

REPAIR 1-Vertical Stabilizer Leading Edge Skin External Repair

REPAIR 2-Flush Repair of the Vertical Stabilizer Leading Edge Skin

REPAIR 3 - Vertical Stabilizer Inspar Skin External Repair Between Ribs - Fin Stations 73.400 thru 196.663

REPAIR 4 - Vertical Stabilizer Inspar Skin External Repair Between Ribs - Fin Stations 196.663 thru 343.863

REPAIR 5-Vertical Stabilizer Inspar Skin Flush Repair Between Ribs - Fin Stations 73.400 thru 196.663

REPAIR 6-Vertical Stabilizer Inspar Skin Flush Repair with Spliced Doubler Between Ribs - Fin Stations 73.400 thru 196.663

REPAIR 7-Vertical Stabilizer Inspar Skin Flush Repair Between Ribs - Fin Stations 196.663 thru 343.863

REPAIR 8-Vertical Stabilizer Inspar Skin Flush Repair with Spliced Doubler Between Ribs - Fin Stations 196.663 thru 343.863

REPAIR 9-Vertical Stabilizer Trailing Edge and Closeout Panels

REPAIR 10-Vertical Stabilizer Access Panel Installation With a One-Piece Doubler

REPAIR 11-Vertical Stabilizer Access Panel Installation With a Two-Piece Doubler

REPAIR 12-Dorsal Fin Skin

VERTICAL STABILIZER RIBS

IDENTIFICATION 1-Vertical Stabilizer Leading Edge Ribs

IDENTIFICATION 2-Vertical Stabilizer Inspar Ribs

IDENTIFICATION 3-Vertical Stabilizer Trailing Edge Ribs

IDENTIFICATION 4-Dorsal Fin Structure

ALLOWABLE DAMAGE 2-Dorsal Fin Structure

REPAIR 2-Dorsal Fin Structure

VERTICAL STABILIZER SPARS

IDENTIFICATION 1-Vertical Stabilizer Front Spar Structure

IDENTIFICATION 2-Vertical Stabilizer Rear Spar Structure

55-30-10

55-30-09

55-CONTENTS

Page 5 Nov 10/2005



CHAPTER 55 STABILIZERS

<u>SUBJECT</u>	CHAPTER SECTION <u>SUBJECT</u>
ALLOWABLE DAMAGE 1-Vertical Stabilizer Front Spar	
ALLOWABLE DAMAGE 2-Vertical Stabilizer Rear Spar	
REPAIR 1-Vertical Stabilizer Spar	
REPAIR 2-Vertical Stabilizer Front Spar Web	
REPAIR 3-Vertical Stabilizer Rear Spar Web - Fin Stations 251.86 to 350.00	
REPAIR 4-Vertical Stabilizer Rear Spar Web Repair - Fin Stations 215.06 thru 251.86	
REPAIR 5-Vertical Stabilizer Rear Spar Web Repair - Fin Stations 88.44 thru 215.06	
VERTICAL STABILIZER BEAMS	55-30-13
IDENTIFICATION 1-Vertical Stabilizer Beam	
ALLOWABLE DAMAGE 1-Vertical Stabilizer Trailing Edge Beams	
REPAIR 1-Vertical Stabilizer Trailing Edge Beam	
VERTICAL STABILIZER AUXILIARY STRUCTURE	55-30-30
IDENTIFICATION 1-Vertical Stabilizer Tip	
IDENTIFICATION 2-Vertical Stabilizer Cove	
ALLOWABLE DAMAGE 1-Vertical Stabilizer Tip	
ALLOWABLE DAMAGE 2-Vertical Stabilizer Cove	
REPAIR 1-Vertical Stabilizer Tip	
REPAIR 2-Vertical Stabilizer Cove	
VERTICAL STABILIZER FITTINGS	55-30-90
IDENTIFICATION 1-Vertical Stabilizer Fittings	
ALLOWABLE DAMAGE 1-Vertical Stabilizer Fittings	
REPAIR GENERAL - Vertical Stabilizer Hinge Fittings	
RUDDER SKIN	55-40-01
IDENTIFICATION 1-Rudder Skin	
ALLOWABLE DAMAGE 1-Rudder Skin	
ALLOWABLE DAMAGE 2-Rudder Balance Arm Skin	
REPAIR 1-Rudder Skin	

55-CONTENTS

Page 6 Nov 10/2005



CHAPTER 55 STABILIZERS


SUBJECT	CHAPTER SECTION SUBJECT
RUDDER STRUCTURE	55-40-02
IDENTIFICATION 1-Rudder Rib Structure	
IDENTIFICATION 2-Rudder Spar Rib Structure	
IDENTIFICATION 3-Rudder Balance Arm Structure	
ALLOWABLE DAMAGE 1-Rudder Spar and Spar Ribs	
ALLOWABLE DAMAGE 2-Leading Edge Ribs of the Rudder Structure	
ALLOWABLE DAMAGE 3-Rudder Balance Arm Structure	
REPAIR 1-Rudder Structure	
RUDDER TIP	55-40-30
IDENTIFICATION 1-Rudder Tip Fairing Skins	
ALLOWABLE DAMAGE 1-Rudder Tip Fairing Skins	
REPAIR 1-Rudder Tip Fairing Skins	
RUDDER FITTINGS	55-40-90
IDENTIFICATION 1-Rudder Hinge Fittings	
ALLOWABLE DAMAGE 1-Rudder Hinge Fittings	
REPAIR 1-Rudder Hinge Fittings	



Page 7 Nov 10/2004



IDENTIFICATION GENERAL - HORIZONTAL STABILIZER STATION DIAGRAM



Horizontal Stabilizer Location Figure 1


Table 1:

	REFERENCE DRAWINGS		
DRAWING NUMBER	TITLE		
180A1540	Horizontal Tail Centerline Diagram		






737-800 STRUCTURAL REPAIR MANUAL








Horizontal Stabilizer Leading Edge Station Diagram Figure 3



D634A210



IDENTIFICATION 1 - HORIZONTAL STABILIZER LEADING EDGE SKIN



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

UPPER SURFACE IS SHOWN


Horizontal Stabilizer Leading Edge Skin Locations Figure 1

Table 1:		
REFERENCE DRAWINGS		
DRAWING NUMBER	TITI F	
186A1001	Leading Edge Assembly/Installation - REM, Horizontal Stabilizer	
186A1200	200 Skin Assembly - REM LE, Horizontal Stabilizer	
186A2001	LE Installation - Fixed, Horizontal Stabilizer	



ABDEING®

737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE UPPER SURFACE IS SHOWN

Horizontal Stabilizer Leading Edge Skin Identification Figure 2

Table 2:


	LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY	
[1]	Fixed LE Panel Skin	0.071 (1.80)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 3 for the different chem-mill thicknesses		
[2]	Removable LE Panel Skin	0.071 (1.80)	2024-T3 clad sheet as given in QQ-A-205/5. Refer to Figure 4 for the different chem-mill thicknesses		

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).



BOEING®

737-800 STRUCTURAL REPAIR MANUAL




Chem-Milled Areas of Figure 2, Item [1] Figure 3



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL




UPPER SURFACE IS SHOWN

Chem-Milled Areas of Figure 2, Item [2] Figure 4

> IDENTIFICATION 1 Page 4 Mar 10/2004



IDENTIFICATION 2 - HORIZONTAL STABILIZER UPPER INSPAR SKIN



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

UPPER SURFACE IS SHOWN

Horizontal Stabilizer Upper Inspar Skin Locations Figure 1

Table 1:


REFERENCE DRAWINGS		
DRAWING NUMBER	TITLE	
182A3001 Skin, Upper-Inspar, Horizontal Stabilizer Installation		



Page 1



737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE UPPER SURFACE IS SHOWN

Horizontal Stabilizer Upper Inspar Skin Identification Figure 2

Table 2:


	LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY	
[1]	Inspar Skin - Upper Panel	0.080 (2.03)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 3 for the different chem-mill thicknesses		

*[1] Note: T = Pre-manufactured thickness in inches.





737-800 STRUCTURAL REPAIR MANUAL



Chem-Milled Areas of Figure 2, Item [1] Figure 3



Page 3


BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details

D634A210



737-800 STRUCTURAL REPAIR MANUAL

IDENTIFICATION 3 - UPPER PANEL ASSEMBLY - HORIZONTAL STABILIZER TRAILING EDGE



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

UPPER SURFACE IS SHOWN

Horizontal Stabilizer Upper Trailing Edge Panel Locations Figure 1


Table 1:

	REFERENCE DRAWINGS		
DRAWING NUMBER			
185A1700	185A1700 Panel Installation - Trailing Edge, Horizontal Stabilizer		
185A1800	185A1800 Panel Installation - Outboard Trailing Edge, Horizontal Stabilizer		





737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

UPPER SURFACE IS SHOWN

Horizontal Stabilizer Upper Trailing Edge Panel Identification Figure 2

Table 2:

LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Upper Panel - Bonded Part		Glass Fiber Reinforced Plastic (GFRP) and Carbon Fiber Reinforced Plastic (CFRP) honeycomb sandwich	
	Skin		Refer to Figure 3.	
	Core	0.400 (1.02)	Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0	
[2]	Upper Panel - Bonded Part		GFRP and CFRP honeycomb sandwich	
	Skin		Refer to Figure 4.	
	Core	0.400 (1.02)	Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0	
[3]	Upper Panel - Bonded Part		GFRP and CFRP honeycomb sandwich	
	Skin		Refer to Figure 5.	
	Core	0.400 (1.02)	Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0	
[4]	Upper Panel - Bonded Assembly		(GFRP) and (CFRP) honeycomb sandwich.	
	Skin		Refer to Figure 6.	
	Core	0.400 (1.02)	Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0	


*[1] Note: T = Pre-manufactured thickness in inches (millimeters).

IDENTIFICATION 3 Page 2 Jul 10/2004

D634A210



737-800 STRUCTURAL REPAIR MANUAL



PLY LAYUP AND CORE RIBBON DIRECTION

NOTES


- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PANEL.
- REFER TO SECTIONS A-A, B-B, C-C, AND D-D FOR THE PLY SEQUENCE OVER EACH CORE.
- REFER TO THE ENGINEERING DRAWING FOR THE PLY LAYUP AT THE EDGES OF THE PANEL.
- REFER TO TABLE 3 FOR THE DIRECTION AND MATERIAL OF EACH PLY.

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [1] Figure 3 (Sheet 1 of 3)





737-800 STRUCTURAL REPAIR MANUAL





Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [1] Figure 3 (Sheet 2 of 3)

> IDENTIFICATION 3 Page 4 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL





Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [1] Figure 3 (Sheet 3 of 3)

> IDENTIFICATION 3 Page 5 Nov 01/2003

D634A210




Table 3:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [1]		
PLY	DIRECTION	MATERIAL
P1		Surfacing film as given in BMS 8-341, Type II (METALBOND 1515-3M film adhesive) (Optional: Surfacing film as given in BMS 8-341, Type III (SYNSKIN HC9837.1 composite surfacing film)) (Optional: Toolside surface treatment)
P2, P22	+ or - 45 degrees	GFRP as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781
P3, P4, P12, P13, P21	0 or 90 degrees	GFRP as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781
P5, P6, P19, P20	0 degrees	CFRP unidirectional tape as given in BMS 8-168, Type II, Class I, Grade 145
P7, P8, P9, P10, P11, P14, P15, P16, P17, P18	90 degrees	CFRP unidirectional tape as given in BMS 8-168, Type II, Class I, Grade 145
P23		0.001 inch (0.025 mm) thick white bondable Tedlar film







NOTES


- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PANEL.
- REFER TO SECTIONS A-A AND B-B FOR THE PLY SEQUENCE OVER EACH CORE.
- REFER TO THE ENGINEERING DRAWING FOR THE PLY LAYUP AT THE EDGES OF THE PANEL.
- REFER TO TABLE 4 FOR THE DIRECTION AND MATERIAL OF EACH PLY.


Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [2] Figure 4 (Sheet 1 of 2)

> IDENTIFICATION 3 Page 7 Mar 10/2004

A BOEING®

737-800 STRUCTURAL REPAIR MANUAL





Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [2] Figure 4 (Sheet 2 of 2)

> IDENTIFICATION 3 Page 8 Nov 01/2003




Table 4:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, Item [2]			
PLY	DIRECTION	MATERIAL	
P1		Surfacing film as given in BMS 8-341, Type II (METALBOND 1515-3M film adhesive) (Optional: Surfacing film as given in BMS 8-341, Type III (SYNSKIN HC9837.1 composite surfacing film)) (Optional: Toolside surface treatment)	
P2, P13	+ or - 45 degrees	GFRP as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781	
P3, P7, P8, P12	0 or 90 degrees	GFRP as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781	
P4, P5, P6, P9, P10, P11	90 degrees	CFRP unidirectional tape as given in BMS 8-168, Type II, Class I, Grade 145	
P14		0.001 inch (0.025 mm) thick white bondable Tedlar film	







NOTES


- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PANEL.
- REFER TO SECTIONS A-A AND B-B FOR THE PLY SEQUENCE OVER EACH CORE.
- REFER TO THE ENGINEERING DRAWING FOR THE PLY LAYUP AT THE EDGES OF THE PANEL.
- REFER TO TABLE 5 FOR THE DIRECTION AND MATERIAL OF EACH PLY.

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [3] Figure 5 (Sheet 1 of 2)


> IDENTIFICATION 3 55-10-01 Page 10 Mar 10/2004



737-800 STRUCTURAL REPAIR MANUAL



A-A



Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [3] Figure 5 (Sheet 2 of 2)






Table 5:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, Item [3]			
PLY	DIRECTION	MATERIAL	
P1		Surfacing film as given in BMS 8-341, Type II (METALBOND 1515-3M film adhesive) (Optional: Surfacing film as given in BMS 8-341, Type III (SYNSKIN HC9837.1 composite surfacing film)) (Optional: Toolside surface treatment)	
P2, P13	+ or - 45 degrees	GFRP as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781	
P3, P7, P8, P12	0 or 90 degrees	GFRP as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781	
P4, P5, P6, P9, P10, P11	90 degrees	CFRP unidirectional tape as given in BMS 8-168, Type II, Class I, Grade 145	
P14		0.001 inch (0.025 mm) thick white bondable Tedlar film	





737-800 STRUCTURAL REPAIR MANUAL




NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PANEL.
- REFER TO SECTIONS A-A FOR THE PLY SEQUENCE OVER EACH CORE.
- REFER TO THE ENGINEERING DRAWING FOR THE PLY LAYUP AT THE EDGES OF THE PANEL.
- REFER TO TABLE 6 FOR THE DIRECTION AND MATERIAL OF EACH PLY.

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [4] Figure 6 (Sheet 1 of 2)

> IDENTIFICATION 3 Page 13 Mar 10/2004





PLY LAYUP SEQUENCE A-A

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [4] Figure 6 (Sheet 2 of 2)






Table 6:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, Item [4]		
PLY	DIRECTION	MATERIAL
P1		Surfacing film as given in BMS 8-341, Type II (METALBOND 1515-3M film adhesive) (Optional: Surfacing film as given in BMS 8-341, Type III (SYNSKIN HC9837.1 composite surfacing film)) (Optional: Toolside surface treatment)
P2, P12	+ or - 45 degrees	GFRP as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781
P3, P4, P7, P8, P11	0 or 90 degrees	GFRP as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781
P5, P10	0 degrees	CFRP unidirectional tape as given in BMS 8-168, Type II, Class I, Grade 145
P6, P9	90 degrees	CFRP unidirectional tape as given in BMS 8-168, Type II, Class I, Grade 145
P13		0.001 inch (0.025 mm) thick white bondable Tedlar film





IDENTIFICATION 4 - HORIZONTAL STABILIZER LOWER INSPAR SKIN



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

LOWER SURFACE IS SHOWN

Horizontal Stabilizer Lower Inspar Skin Location Figure 1


Table 1:

	REFERENCE DRAWINGS				
	DRAWING NUMBER	TITLE			
ſ	182A4001	Skin, Lower - Inspar, Horizontal Stabilizer Installation			



Page 1

A BOEING



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

LOWER SURFACE IS SHOWN

Horizontal Stabilizer Lower Inspar Skin Identification Figure 2



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details




Table 2:

	LIST OF MATERIALS FOR FIGURE 2					
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY		
[1]	Lower Skin assembly Inspar Skin - Lower Panel	0.071 (1.80)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 3 for the different chem-mill thicknesses			
	Doubler	0.100 (2.54)	2024-T3 clad sheet as given in QQ-A-250/5			
	Doubler	0.080 (2.54)	2024-T3 clad sheet as given in QQ-A-250/5			
	Doubler (2)	0.071 (1.80)	2024-T3 clad sheet as given in QQ-A-250/5			
	Doubler (3)	0.180 (4.57)	2024-T3 clad sheet as given in QQ-A-250/5			
	Doubler	0.625 (15.87)	7075-T7351 plate as given in QQ-A-250/12			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).








LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE UPPER SURFACE IS SHOWN

> Chem-Milled Areas of Figure 2, Item [1] Figure 3





IDENTIFICATION 5 - LOWER PANEL ASSEMBLY - HORIZONTAL STABILIZER TRAILING EDGE



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

LOWER SURFACE IS SHOWN

Horizontal Stabilizer Lower Trailing Edge Panel Location Figure 1


Table 1:

REFERENCE DRAWINGS				
DRAWING NUMBER	TITI F			
185A1700	185A1700 Panel Installation - Trailing Edge, Horizontal Stabilizer			
185A1711	185A1711 Panel Installation - Trailing Edge, Horizontal Stabilizer Rework			
185A1800 Panel Installation - Outboard Trailing Edge, Horizontal Stabilizer				





737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE LOWER SURFACE IS SHOWN

Horizontal Stabilizer Lower Trailing Edge Panel Identification Figure 2





Table 2:


	LIST OF MATERIALS FOR FIGURE 2					
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY		
[1]	Lower Panel - Bonded Part		Glass Fiber Reinforced Plastic (GFRP) and Carbon Fiber Reinforced Plastic (CFRP) honeycomb sandwich			
	Skin		Refer to Figure 3			
	Core	0.400 (10.16)	Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			
[2]	Lower Panel - Bonded Part		GFRP and CFRP honeycomb sandwich			
	Skin		Refer to Figure 4			
	Core	0.400 (10.16)	Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			
[3]	Lower Panel - Bonded Part		GFRP and CFRP honeycomb sandwich			
	Skin		Refer to Figure 5			
	Core	0.400 (10.16)	Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			
[4]	Lower Panel - Bonded Part		GFRP and CFRP honeycomb sandwich			
	Skin		Refer to Figure 6			
	Core	0.400 (10.16)	Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			
[5]	Lower Panel - Bonded Part		GFRP and CFRP honeycomb sandwich			
	Skin		Refer to Figure 7			
	Core	0.400 (10.16)	Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			
[6]	Lower Panel - Bonded Part		GFRP and CFRP honeycomb sandwich			
	Skin		Refer to Figure 8			
	Core	0.400 (10.16)	Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			
[7]	Lower Outboard Trailing Edge Panel - Bonded Assembly		GFRP and CFRP honeycomb sandwich			
	Skin		Refer to Figure 9			
	Core	0.400 (10.16)	Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





737-800 STRUCTURAL REPAIR MANUAL





PLY LAYUP AND CORE RIBBON DIRECTION

А

NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PANEL.
- REFER TO SECTIONS A-A AND B-B FOR THE PLY SEQUENCE OVER EACH CORE.
- REFER TO THE ENGINEERING DRAWING FOR THE PLY LAYUP AT THE EDGES OF THE PANEL.
- REFER TO TABLE 3 FOR THE DIRECTION AND MATERIAL OF EACH PLY.

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [1] Figure 3 (Sheet 1 of 2)

55-10-01


IDENTIFICATION 5


Page 4


Mar 10/2004



737-800 STRUCTURAL REPAIR MANUAL







B-B

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [1] Figure 3 (Sheet 2 of 2)






Table 3:

PLY MATERIAL AND DIRECTION FOR FIGURE 3			
PLY	DIRECTION	MATERIAL	
P1		BMS 5-129, Type 2, Grade 5, is preferred. (Optional: BMS 8-341, Type II (METALBOND 1515-3M film adhesive) or Type III (SYNSKIN HC9837.1 composite surfacing film)). (Optional: Toolside surface treatment)	
P2, P14	+ or - 45 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781	
P3, P4, P8, P9, P13	0 or 90 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781	
P5, P12	0 degrees	CFRP unidirectional tape as given in BMS 8-168, Type II, Class I, Grade 145	
P6, P7, P10, P11	90 degrees	CFRP unidirectional tape as given in BMS 8-168, Type II, Class I, Grade 145	
P15, P16		0.001 inch (0.025 mm) thick white bondable Tedlar film	
P17		0.001 inch (0.025 mm) thick teflon film as given in BMS 10-86	





737-800 STRUCTURAL REPAIR MANUAL



PLY LAYUP AND CORE RIBBON DIRECTION

А

NOTES


- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PANEL.
- REFER TO SECTIONS A-A AND B-B FOR THE PLY SEQUENCE OVER EACH CORE.
- REFER TO THE ENGINEERING DRAWING FOR THE PLY LAYUP AT THE EDGES OF THE PANEL.
- REFER TO TABLE 4 FOR THE DIRECTION AND MATERIAL OF EACH PLY.

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Lower Trailing Edge Panel, Figure 2, Item [2] Figure 4 (Sheet 1 of 2)

> IDENTIFICATION 5 Page 7 Mar 10/2004



737-800 STRUCTURAL REPAIR MANUAL



Ply Direction, Core Ribbon Direction, and Ply Sequence for the Lower Trailing Edge Panel, Figure 2, Item [2] Figure 4 (Sheet 2 of 2)






Table 4:

PLY MATERIAL AND DIRECTION FOR FIGURE 4			
PLY	DIRECTION	MATERIAL	
P1		BMS 5-129, Type 2, Grade 5, is preferred. (Optional: BMS 8-341, Type II (METALBOND 1515-3M film adhesive) or Type III (SYNSKIN HC9837.1 composite surfacing film)). (Optional: Toolside surface treatment)	
P2, P23	+ or - 45 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Class III, Grade B, Style 120 or 1581	
P3, P5, P6, P9, P10, P15, P16, P19, P20, P22	90 degrees	Unidirectional graphite tape as given in BMS 8-168, Type II, Class 1, Grade 190	
P4, P7, P11, P14, P18, P21	0 or 90 degrees	Graphite fabric cloth as given in BMS 8-168, Type II, Class 2, Style 3K-70-PW	
P8, P12, P13, P17	+ or - 45 degrees	Graphite fabric cloth as given in BMS 8-168, Type II, Class 2, Style 3K-70-PW	
P24		0.001 inch (0.025 mm) thick teflon film as given in BMS 10-86	
P25		0.001 inch (0.025 mm) thick white bondable Tedlar film	





737-800 STRUCTURAL REPAIR MANUAL



NOTES


- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PANEL.
- REFER TO SECTIONS A-A AND B-B FOR THE PLY SEQUENCE OVER EACH CORE.
- REFER TO THE ENGINEERING DRAWING FOR THE PLY LAYUP AT THE EDGES OF THE PANEL.
- REFER TO TABLE 5 FOR THE DIRECTION AND MATERIAL OF EACH PLY.

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Lower Trailing Edge Panel, Figure 2, Item [3] Figure 5 (Sheet 1 of 2)

> IDENTIFICATION 5 55-10-01 Page 10 Mar 10/2004



737-800 STRUCTURAL REPAIR MANUAL



Ply Direction, Core Ribbon Direction, and Ply Sequence for the Lower Trailing Edge Panel, Figure 2, Item [3] Figure 5 (Sheet 2 of 2)

> IDENTIFICATION 5 **55-10-01** Page 11 Nov 01/2003




Table 5:

PLY MATERIAL AND DIRECTION FOR FIGURE 5			
PLY	DIRECTION	MATERIAL	
P1		BMS 5-129, Type 2, Grade 5, is preferred. (Optional: BMS 8-341, Type II (METALBOND 1515-3M film adhesive) or Type III (SYNSKIN HC9837.1 composite surfacing film)). (Optional: Toolside surface treatment)	
P2, P23	+ or - 45 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Class III, Grade B, Style 120 or 1581	
P3, P5, P6, P9, P10, P15, P16, P19, P20, P22	90 degrees	Unidirectional graphite tape as given in BMS 8-168, Type II, Class 1, Grade 190	
P4, P7, P11, P14, P18, P21	0 or 90 degrees	Graphite fabric cloth as given in BMS 8-168, Type II, Class 2, Style 3K-70-PW	
P8, P12, P13, P17	+ or - 45 degrees	Graphite fabric cloth as given in BMS 8-168, Type II, Class 2, Style 3K-70-PW	
P24		0.001 inch (0.025 mm) thick white bondable Tedlar film	
P25		0.001 inch (0.025 mm) thick teflon film as given in BMS 10-86	



BOEING®

737-800 STRUCTURAL REPAIR MANUAL



PLY LAYUP AND CORE RIBBON DIRECTION (A)

NOTES


- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PANEL.
- REFER TO SECTIONS A-A FOR THE PLY SEQUENCE OVER EACH CORE.
- REFER TO THE ENGINEERING DRAWING FOR THE PLY LAYUP AT THE EDGES OF THE PANEL.
- REFER TO TABLE 6 FOR THE DIRECTION AND MATERIAL OF EACH PLY.

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [4] Figure 6 (Sheet 1 of 2)

> IDENTIFICATION 5 55-10-01 Page 13 Mar 10/2004







PLY LAYUP SEQUENCE A-A

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [4] Figure 6 (Sheet 2 of 2)






Table 6:

PLY MATERIAL AND DIRECTION FOR FIGURE 6			
PLY	DIRECTION	MATERIAL	
P1		BMS 5-129, Type 2, Grade 5, is preferred. (Optional: BMS 8-341, Type II (METALBOND 1515-3M film adhesive) or Type III (SYNSKIN HC9837.1 composite surfacing film)). (Optional: Toolside surface treatment)	
P2, P9	+ or - 45 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781	
P3, P5, P6, P8	0 or 90 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781	
P4, P7	90 degrees	CFRP unidirectional tape as given in BMS 8-168, Type II, Class I, Grade 145	
P10		0.001 inch (0.025 mm) thick white bondable Tedlar film	
P11		0.001 inch (0.025 mm) thick teflon film as given in BMS 10-86	





737-800 STRUCTURAL REPAIR MANUAL




NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PANEL.
- REFER TO SECTIONS A-A FOR THE PLY SEQUENCE OVER EACH CORE.
- REFER TO THE ENGINEERING DRAWING FOR THE PLY LAYUP AT THE EDGES OF THE PANEL.
- REFER TO TABLE 7 FOR THE DIRECTION AND MATERIAL OF EACH PLY.

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [5] Figure 7 (Sheet 1 of 2)







PLY LAYUP SEQUENCE A-A

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [5] Figure 7 (Sheet 2 of 2)






Table 7:

PLY MATERIAL AND DIRECTION FOR FIGURE 7			
PLY	DIRECTION	MATERIAL	
P1		BMS 5-129, Type 2, Grade 5, is preferred. (Optional: BMS 8-341, Type II (METALBOND 1515-3M film adhesive) or Type III (SYNSKIN HC9837.1 composite surfacing film)). (Optional: Toolside surface treatment)	
P2, P9	+ or - 45 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781	
P3, P5, P6, P8	0 or 90 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781	
P4, P7	90 degrees	CFRP unidirectional tape as given in BMS 8-168, Type II, Class I, Grade 145	
P10		0.001 inch (0.025 mm) thick white bondable Tedlar film	
P11		0.001 inch (0.025 mm) thick teflon film as given in BMS 10-86	





737-800 STRUCTURAL REPAIR MANUAL





PLY LAYUP AND CORE RIBBON DIRECTION (A)

NOTES


- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PANEL.
- REFER TO SECTIONS A-A AND B-B FOR THE PLY SEQUENCE OVER EACH CORE.
- REFER TO THE ENGINEERING DRAWING FOR THE PLY LAYUP AT THE EDGES OF THE PANEL.
- REFER TO TABLE 8 FOR THE DIRECTION AND MATERIAL OF EACH PLY.


Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [6] Figure 8 (Sheet 1 of 2)

> IDENTIFICATION 5 55-10-01 Page 19 Mar 10/2004

BOEING®

737-800 STRUCTURAL REPAIR MANUAL





Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [6] Figure 8 (Sheet 2 of 2)

> IDENTIFICATION 5 55-10-01 Page 20 Nov 01/2003




Table 8:

PLY MATERIAL AND DIRECTION FOR FIGURE 8			
PLY	DIRECTION	MATERIAL	
P1		BMS 5-129, Type 2, Grade 5, is preferred. (Optional: BMS 8-341, Type II (METALBOND 1515-3M film adhesive) or Type III (SYNSKIN HC9837.1 composite surfacing film)). (Optional: Toolside surface treatment)	
P2, P13	+ or - 45 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781	
P3, P7, P8, P12	0 or 90 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781	
P4, P5, P6, P9, P10, P11	90 degrees	CFRP unidirectional tape as given in BMS 8-168, Type II, Class I, Grade 145	
P14, P15, P16		0.001 inch (0.025 mm) thick white bondable Tedlar film	
P17		0.001 inch (0.025 mm) thick teflon film as given in BMS 10-86	





737-800 STRUCTURAL REPAIR MANUAL



PLY LAYUP AND CORE RIBBON DIRECTION

NOTES


- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PANEL.
- REFER TO SECTIONS A-A FOR THE PLY SEQUENCE OVER EACH CORE.
- REFER TO THE ENGINEERING DRAWING FOR THE PLY LAYUP AT THE EDGES OF THE PANEL.
- REFER TO TABLE 9 FOR THE DIRECTION AND MATERIAL OF EACH PLY.

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [7] Figure 9 (Sheet 1 of 2)

> IDENTIFICATION 5 Page 22 Mar 10/2004



737-800 STRUCTURAL REPAIR MANUAL



PLY LAYUP SEQUENCE

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Trailing Edge Panel, Figure 2, Item [7] Figure 9 (Sheet 2 of 2)





Table 9:

PLY MATERIAL AND DIRECTION FOR FIGURE 9		
PLY	DIRECTION	MATERIAL
P1		BMS 5-129, Type 2, Grade 5, is preferred. (Optional: BMS 8-341, Type II (METALBOND 1515-3M film adhesive) or Type III (SYNSKIN HC9837.1 composite surfacing film)). (Optional: Toolside surface treatment)
P2, P12	+ or - 45 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781
P3, P4, P7, P8, P11	0 or 90 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781
P5, P10	0 degrees	CFRP unidirectional tape as given in BMS 8-168, Type II, Class I, Grade 145
P6, P9	90 degrees	CFRP unidirectional tape as given in BMS 8-168, Type II, Class I, Grade 145
P13		0.001 inch (0.025 mm) thick white bondable Tedlar film





ALLOWABLE DAMAGE 1 - HORIZONTAL STABILIZER LEADING EDGE SKINS


1. Applicability

A. This subject gives the allowable damage limits for the horizontal stabilizer leading edge skins shown in Horizontal Stabilizer Leading Edge Skin Locations, Figure 101/ALLOWABLE DAMAGE 1.










LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE UPPER SURFACE IS SHOWN

> Horizontal Stabilizer Leading Edge Skin Locations Figure 101 (Sheet 1 of 2)





737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE LOWER SURFACE IS SHOWN

Horizontal Stabilizer Leading Edge Skin Locations Figure 101 (Sheet 2 of 2)



D634A210

BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



2. General

- A. Remove the damaged material as necessary.
 - (1) Refer to 51-10-02 for the inspection and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (4) If countersink rivets are removed to clean up the damage, then do the steps that follow:
 - (a) Install new rivets that have the same material and diameter as the initial rivets.
 - 1) Use oversize rivets as necessary.
 - 2) It is optional to install NAS1399D blind rivets.
 - 3) If you install the NAS1399D blind rivets, make an inspection at each 400 flight hour interval.
 - 4) Replace the blind rivets with solid rivets after no more than 5000 flight hours.
 - (b) If the head is above the skin surface, remove the unwanted material with the microshave flush procedure as specified in 51-10-01.
 - 1) The maximum head height that is permitted above the skin is 0.006 inch.
- B. Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to 51-20-01.
- C. Apply two layers of BMS 10-79, Type II or III, primer to the reworked areas. Refer to SOPM 20-44-04.
- D. Apply the decorative finish to the reworked areas as given in AMM PAGEBLOCK 51-21-99/701.
- E. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.

3. References

Reference	Title
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-70-01	REPAIRS FOR MINOR DENTS IN METALLIC SHEET MATERIALS
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Allowable Damage Limits

A. Cracks:

- (1) Damage is permitted as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Detail A.
- B. Nicks, Gouges, Scratches, and Corrosion:





- (1) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A, D, and E.
 - (a) Only one area of damage removal, as shown in Detail D, is permitted for each 15.0 square inches of panel.
- C. Holes and Punctures are permitted if:
 - (1) They are a maximum of 0.25 inch in diameter
 - (2) There is not more than one hole or puncture for each 15.0 square inches of panel area
 - (3) The edge of the damage is a minimum of 1.00 inch away from the edge of a fastener hole, other damage, or the panel.
 - (4) They are filled with a 2117-T3 or 2117-T4 aluminum flush head rivet.
 - (a) If the head is above the skin, use the microshave flush procedure as specified in 51-10-01.
 - (b) It is optional to install a 2117-T3 or 2117-T4 aluminum protruding head rivet, or a NAS1399D blind rivet. Do the steps that follow when you install the blind rivets:
 - 1) Make an inspection of blind rivets at each 400 flight hour interval.
 - 2) Replace the blind rivets with solid rivets after no more than 5000 flight hours.
- D. Dents:
 - (1) Dents are permitted for the general conditions of Paragraph 4.D.(2)/ALLOWABLE DAMAGE 1 and for the specified conditions of Paragraph 4.D.(3)/ALLOWABLE DAMAGE 1
 - (a) Refer to Definition of Dent Dimensions, Figure 103/ALLOWABLE DAMAGE 1 for the definitions of the dimensions for a dent.
 - (b) Refer to Allowable Damage Limits for Leading Edge Skin Dents, Figure 104/ALLOWABLE DAMAGE 1 for the relation of dent dimensions.
 - (c) Refer to Damage Size and Spacing Limits for Adjacent Dents, Figure 105/ALLOWABLE DAMAGE 1 for the definition of the dimensions for adjacent dents.
 - (d) Refer to Equivalent Length of Dents When the Depth is Large, Figure 106/ALLOWABLE DAMAGE 1 for the definition of the length if there is more than one dent in a bay.
 - (2) General Conditions:
 - (a) The edge of the damage is a minimum of 1.0 inch away from a hole.
 - (b) There are no pulled or loose fasteners or missing fastener locations.
 - (c) There are no sharp creases, gouges, or cracks.
 - (d) There is no damage to the structure that is below the skin panels.
 - (e) There are no dents at the rib chord locations.
 - (f) The conditions of Table 101/ALLOWABLE DAMAGE 1 are kept.

CONDITIONS FOR THE LOCATIONS AND QUANTITY OF DENTS		
DEPTH OF DENT (Y), INCH	LIMITS FOR PERMITTED DENTS	
If (Y) is more than or equal to 0.50 but less than 1.0	There must be 5 bays that are not damaged on each side of the damaged bay. There must be no other damage in the damaged bay	
If (Y) is more than or equal to 0.40 but less than 0.50	There must be 3 bays that are not damaged on each side of the damaged bay. There must be no other damage in the damaged bay	
If (Y) is more than or equal to 0.30 but less than 0.40	There must be 2 bays that are not damaged on each side of the damaged bay	

Table 101:

ALLOWABLE DAMAGE 1

Page 105

Jul 10/2004





(Y) is more than o	r equal to 0.20 but less than 0.30 There must be 1 bay that is not damaged on each side of the damaged ba
	ecified Conditions:
(a)	Dents are permitted in Area 1 as shown in Allowable Damage Limits for Leading Ed Skin Dents, Figure 104/ALLOWABLE DAMAGE 1.
	 For dents that are more than the limits shown in Allowable Damage Limits, Figure 107/ALLOWABLE DAMAGE 1, fill the dents as given in 51-70-01.
(b)	Dents are permitted in Area 2 if you make an inspection of the damage after no more th 5000 flight hours. Refer to Allowable Damage Limits for Leading Edge Skin Dents, Figure 104/ALLOWABLE DAMAGE 1.
	NOTE : It is recommended that you remove or repair the damage after no more th 5000 flight hours or 18 months, that which occurs first.
	 For dents that are more than the limits shown in Allowable Damage Limits, Figu 107/ALLOWABLE DAMAGE 1, fill the dents as given in 51-70-01.
(C)	Dents are permitted in Area 3 as shown in Allowable Damage Limits for Leading Ed Skin Dents, Figure 104/ALLOWABLE DAMAGE 1 if you do the steps that follow:
	1) Fill the dent as given in 51-70-01.
	2) Seal the damage with 3M-436 aluminum foil tape (speed tape) or the equivalent.
	3) Make a detailed visual inspection of the damage at each 400 flight hour interval. If the are cracks or the damage has become larger, repair the damage immediately.
	 Install a permanent repair after no more than 5000 flight hours or 18 months, that wh occurs first.
(d)	Dents are permitted in Area 4 as shown in Allowable Damage Limits for Leading Ed Skin Dents, Figure 104/ALLOWABLE DAMAGE 1 if you do the steps that follow:
	1) For dents with a depth less than 0.50 inch, fill the dent as given in 51-70-01.
	2) For dents with a depth equal to or greater than 0.50 inch, do the steps that follow:
	a) Fill the dent as given in 51-70-01.
	b) Fill half of the depth of the dent with potting compound and permit it to fully cu
	c) Fill the remaining depth of the dent and permit the compound to fully cure.
	NOTE: BMS 5-92 adhesive is the better alternative to the potting compour given in 51-70-01.
	3) Seal the damage with 3M-436 aluminum foil tape (speed tape) or the equivalent.
	4) Make a general visual inspection of the potting compound each day after removal the aluminum foil tape (speed tape). If there are cracks or the damage has becom larger, repair the damage immediately.
	5) Install an external doubler repair with blind fasteners or a permanent flush repair in days. If you do a repair that has blind rivets, do the steps that follow:
	a) Make an inspection of blind fastener repairs at each 400 flight hour interval
	b) Replace the blind fastener repair with a permanent flush repair after no more th 5000 flight hours.

ALLOWABLE DAMAGE 1

55-10-01

Page 106 Nov 10/2005





D634A210


Page 107

Nov 01/2003

55-10-01




737-800 STRUCTURAL REPAIR MANUAL





737-800 STRUCTURAL REPAIR MANUAL




Definition of Dent Dimensions Figure 103



BOEING®

737-800 STRUCTURAL REPAIR MANUAL




FOR AREA NUMBER	REFER TO ALLOWABLE DAMAGE PARAGRAPH
1	4. D. (3) (a)
2	4. D. (3) (b)
3	4. D. (3) (c)
4	4. D. (3) (d)

TABLE A

Allowable Damage Limits for Leading Edge Skin Dents Figure 104







NOTE: D IS THE LARGEST LENGTH OF THE ADJACENT DENTS.

Damage Size and Spacing Limits for Adjacent Dents Figure 105




D634A210

BOEING PROPRIETARY - Copyright ${\rm (\sc)}$ Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL




- NOTE: IF THE DEPTH OF THE DENT IS 0.050 INCH OR MORE, THEN 1) ADD THE LENGTH OF EACH DENT TO GET THE EQUIVALENT LENGTH (L) OF THE DENTS. $L = L_1 + L_2 + L_3$
 - 2) AND APPLY THE ALLOWABLE DAMAGE LIMITS FOR ONE DENT.

Equivalent Length of Dents When the Depth is Large Figure 106



BOEING®

737-800 STRUCTURAL REPAIR MANUAL





Allowable Damage Limits Figure 107





ALLOWABLE DAMAGE 2 - HORIZONTAL STABILIZER INSPAR SKINS

1. Applicability

A. This subject gives the allowable damage limits for the horizontal stabilizer inspar skins shown in Horizontal Stabilizer Upper Inspar Skin Location, Figure 101/ALLOWABLE DAMAGE 2 and Horizontal Stabilizer Lower Inspar Skin Location, Figure 102/ALLOWABLE DAMAGE 2.


2. General

- A. Remove the damaged material as necessary.
 - (1) Refer to 51-10-02 for the inspection and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (4) If countersink rivets are removed to clean up the damage, then do the steps that follow:
 - (a) Install new rivets that have the same material and diameter as the initial rivets.
 - 1) Use oversize rivets as necessary.
 - 2) It is optional to install solid protruding head rivets with countersink washers.
 - (b) Make sure the countersink depth is not more than 80 percent of the skin thickness.
 - (c) If the head is above the skin surface, remove the unwanted material with the microshave flush procedure as specified in 51-10-01.
 - 1) The maximum head height that is permitted above the skin is 0.006 inch.
- B. Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to 51-20-01.
- C. Apply two layers of BMS 10-79, Type II or III, primer to the reworked areas. Refer to SOPM 20-44-04.
- D. Apply the decorative finish to the reworked areas as given in AMM PAGEBLOCK 51-21-99/701.
- E. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.





737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE UPPER SURFACE IS SHOWN

Horizontal Stabilizer Upper Inspar Skin Location Figure 101




D634A210

BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE LOWER SURFACE IS SHOWN

Horizontal Stabilizer Lower Inspar Skin Location Figure 102



D634A210

BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



3. References

Reference	Title
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Allowable Damage Limits

- A. Cracks:
 - (1) Damage is permitted as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Detail A.
- B. Nicks, Gouges, Scratches, and Corrosion:
 - (1) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Details A, D, F, G, H, and I.
 - (a) Only one area of damage removal, as shown in Detail D, is permitted for each 15.0 square inches of panel.
- C. Dents are permitted as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Detail E if:
 - (1) The edge of the dent is a minimum 4D from the edge of any other damage. D is the maximum dimension of the largest damage.

PERCENT OF CROSS-SECTIONAL AREA REMOVED FROM THE UPPER AND LOWER INSPAR SKINS	
ZONE NUMBER AND SKIN	MAXIMUM PERCENTAGE OF THE INITIAL CROSS-SECTIONAL AREA (AS MANUFACTURED BY BOEING) PERMITTED
1, UPPER	15
2, UPPER	10
3, UPPER	NO DAMAGE PERMITTED
4, UPPER	10
5, UPPER	NO DAMAGE PERMITTED
6, LOWER	15
7, LOWER	10
8, LOWER	5
9, LOWER	10
10, LOWER	5
11, LOWER	NO DAMAGE PERMITTE

Table 101:


D. Holes and Punctures are permitted if:


ALLOWABLE DAMAGE 2 55-10-01 Page 104 Nov 10/2007



- (1) They are a maximum of 0.25 inch in diameter
- (2) There is not more than one hole or puncture for each 15.0 square inches of panel area
- (3) They are not more than the limits shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Details G, H, and I.
- (4) The edge of the damage is a minimum of 1.00 inch away from the edge of a fastener hole, other damage, or the panel.
- (5) They are filled with a 2117-T3 or 2117-T4 aluminum flush head rivet.
 - (a) The countersink depth must not be more than 80 percent of the skin thickness.
 - (b) If the head is above the skin surface, remove the unwanted material with the microshave flush procedure as specified in 51-10-01.
 - (c) It is optional to install a 2117-T3 or 2117-T4 aluminum protruding head rivet.







D634A210


ALLOWABLE DAMAGE 2

55-10-01

Page 106


Nov 01/2003






BOEING

737-800 STRUCTURAL REPAIR MANUAL



Allowable Damage Limits Figure 103 (Sheet 3 of 7)






Allowable Damage Limits Figure 103 (Sheet 4 of 7)






737-800 STRUCTURAL REPAIR MANUAL







737-800 STRUCTURAL REPAIR MANUAL




Allowable Damage Limits Figure 103 (Sheet 6 of 7)





737-800 STRUCTURAL REPAIR MANUAL



 D_1 , D_4 = DIAMETERS OF THE INITIAL FASTENER HOLES D_2 , D_3 = DIAMETERS OF THE HOLES WHERE THERE IS DAMAGE W = WIDTH OF THE SKIN AT THE CROSS-SECTION BETWEEN POINTS A AND B T = THICKNESS OF THE SKIN AS GIVEN BY THE NOMINAL THICKNESS ON THE PRODUCTION DRAWING A₁ = INITIAL AREA OF THE SKIN = THE TOTAL CROSS-SECTIONAL AREA MINUS THE CROSS-SECTIONAL AREA OF THE INITIAL FASTENERS HOLES (AS MANUFACTURED BY BOEING) = WT - $D_1T - D_4T$ A₁ = CROSS-SECTIONAL AREA OF THE DAMAGE THAT IS REMOVED AT LOCATION 1 A₂ = CROSS-SECTIONAL AREA OF THE DAMAGE THAT IS REMOVED AT LOCATION 2 A₃ = CROSS-SECTIONAL AREA OF THE DAMAGE THAT IS REMOVED AT LOCATION 3 $\left(\frac{A_1 + A_2 + A_3}{A_1}\right)$ X 100 = PERCENT OF CROSS-SECTIONAL AREA REMOVED AS GIVEN IN TABLE 101

THE TOTAL CROSS-SECTIONAL AREA REMOVED IN ALL ZONES A-B (3.00 INCH (76.2 mm) ON EACH SIDE OF A LINE A-B) MUST NOT BE MORE THAN THE LIMITS GIVEN IN TABLE 101

C-C

Allowable Damage Limits Figure 103 (Sheet 7 of 7)






ALLOWABLE DAMAGE 3 - HORIZONTAL STABILIZER TRAILING EDGE PANELS

1. Applicability

- A. This subject gives the allowable damage limits for the parts that follow:
 - (1) Horizontal stabilizer trailing edge panels and the conductive strip shown in Horizontal Stabilizer Upper Trailing Edge Panel Locations, Figure 101/ALLOWABLE DAMAGE 3.

Horizontal stabilizer trailing edge panels shown in Horizontal Stabilizer Lower Trailing Edge Panel Locations, Figure 102/ALLOWABLE DAMAGE 3.






Horizontal Stabilizer Upper Trailing Edge Panel Locations Figure 101

> ALLOWABLE DAMAGE 3 Page 102 Nov 10/2005



737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO FIGURE 105 FOR THE DEFINITIONS OF THE ALLOWABLE DAMAGE ZONES.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE LOWER SURFACE IS SHOWN

Horizontal Stabilizer Lower Trailing Edge Panel Locations Figure 102





2. General

- A. Paragraphs 2.B, 2.C, 2.D, and 2.E are applicable to the trailing edge panels only. Paragraph 2.F is applicable to the conductive strip only.
- B. Use a Non-Destructive Test (NDT) to find the length, width, and depth of damage.
 - (1) For the honeycomb core areas that have damage on a facesheet with 3 or less plies, Boeing recommends that you use an instrumented NDT procedure. The tap test procedure is optional. Refer to 737 NDT Part 1, 51-01-02, 737 NDT Part 1, 51-01-03, and 737 NDT Part 1, 51-05-01 for the inspection procedures.
 - (2) For the honeycomb core areas that have damage on a facesheet with 4 or more plies, Boeing recommends that you use an instrumented NDT procedure. Refer to 737 NDT Part 1, 51-01-02 and 737 NDT Part 1, 51-01-03 for the inspection procedures.
 - **NOTE**: The tap test procedure as given in 737 NDT Part 1, 51-05-01 is optional only if it can be shown that the defects (that are less than or equal to the allowable damage limits) can be found.
 - (3) For damage in the solid laminate areas, Boeing recommends that you use an instrumented NDT procedure. Refer to 737 NDT Part 1, 51-01-02 and 737 NDT Part 1, 51-01-03 for the inspection procedures.
 - (4) Refer to Definitions of Damage Size, Figure 103/ALLOWABLE DAMAGE 3, Details A, B, and C for the definitions of the length, width, and depth of damage.
 - (5) Refer to Definitions of the Facesheets, Figure 104/ALLOWABLE DAMAGE 3 for the definitions of the facesheets of a honeycomb core area.
 - (6) Refer to Horizontal Stabilizer Trailing Edge Panels Allowable Damage Zones, Figure 105/ALLOWABLE DAMAGE 3 for the locations of the allowable damage zones.
- C. Remove all contamination and water from the structure.
 - (1) Refer to 51-30-05 for possible sources of equipment and tools you can use to remove the damage.
 - (2) Refer to 51-70-04 for the damage removal procedures.
- D. Seal all permitted damage areas that are not more than one ply deep. Refer to Paragraph 4./ALLOWABLE DAMAGE 3 for the allowable damage limits. Seal the damage with one of the two methods that follow:
 - (1) Make a temporary seal.
 - (a) Apply aluminum foil tape (speed tape).
 - (b) Keep a record of the location.
 - (c) Make sure that the tape is in satisfactory condition at each 400 flight hour interval.
 - (d) Repair the damage after no more than 5000 flight hours.
 - (2) Make a permanent seal.
 - (a) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given in 51-70-08.
 - (b) Apply one layer of BMS 10-79, Type 3 primer. Refer to SOPM 20-44-04.
 - (c) Apply one layer of BMS 10-60 enamel to the areas sealed with epoxy resin. Refer to AMM PAGEBLOCK 51-21-99/701.




- E. Seal all permitted damage areas that are more than one ply deep. Refer to Paragraph 4./ALLOWABLE DAMAGE 3 for the allowable damage limits. Seal the damage as follows:
 - (1) Use vacuum and heat to remove moisture from the solid laminate and/or honeycomb cells. Refer to 51-70-04.
 - (2) Make a temporary seal with aluminum foil tape (speed tape).
 - (3) Keep a record of the location.
 - (4) Repair the damage after no more than 400 flight hours.
- F. Aluminum material damage removal.
 - (1) Remove damage from the aluminum material as necessary.
 - (a) Refer to INSPECTION AND REMOVAL OF DAMAGE, 51-10-02 for the inspection and removal of damage.
 - Refer to NON-METALLIC MATERIALS, 51-30-03 for possible sources of the abrasive (b) and other materials you can use to remove the damage.
 - (c) Refer to EQUIPMENT AND TOOLS FOR REPAIRS, 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (2) Make sure there is a 125 micro inches Ra or smoother surface finish. Refer to 51-20-13, GENERAL.
 - (3) Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS. 51-20-01.
 - (4) Apply two layers of BMS 10-11, Type I primer to the reworked areas. Refer to SOPM 20-41-02.
 - (5) Apply BMS 5-95 sealant at the damage location to make sure all gaps are filled. Refer to 51-20-05, GENERAL.
 - (6) Apply the decorative finish to the reworked areas as given in AMM PAGEBLOCK 51-21-99/701.
 - (7) Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in AERODYNAMIC SMOOTHNESS, 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.
 - (8) After 30 days or less, make an initial visual inspection of the damaged Conductive Strip for signs of new damage or for loose or missing fasteners. Repeat the inspections at each 30 day interval. If any new damage is found to the conductive strip then replace the part.
 - **NOTE:** Replacement of the damaged part with a new part stops the repeat inspection intervals.
 - (9) Replace the damaged Conductive Strip with a new part in 24 months or less.



Page 105


BOEING

737-800 STRUCTURAL REPAIR MANUAL




SIZE DEFINITIONS FOR NICK, GOUGE, OR SCRATCH DAMAGE

А



SIZE DEFINITIONS FOR DENT DAMAGE

В



SIZE DEFINITIONS FOR EDGE DAMAGE

С

Definitions of Damage Size Figure 103




Page 106

D634A210 BOEING PROPRIETARY - Copyright ${\rm (\sc)}$ Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL




Definitions of the Facesheets Figure 104






BDEING®

737-800 STRUCTURAL REPAIR MANUAL



TYPICAL UPPER PANEL IS SHOWN, LOWER PANELS ARE THE SAME



A-A


ZONE 1: SOLID LAMINATE AREA WITH FASTENERS, EDGE BAND ZONE 2: HONEYCOMB CORE AREA ZONE 3: SOLID LAMINATE AREA WITHOUT FASTENERS

> Horizontal Stabilizer Trailing Edge Panels Allowable Damage Zones Figure 105 (Sheet 1 of 2)

> > ALLOWABLE DAMAGE 3 Page 108 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



В-В

ZONE 1: SOLID LAMINATE AREA WITH FASTENERS, EDGE BAND ZONE 2: HONEYCOMB CORE AREA

> Horizontal Stabilizer Trailing Edge Panels Allowable Damage Zones Figure 105 (Sheet 2 of 2)





3. References

Reference	Title	
51-10-01	AERODYNAMIC SMOOTHNESS	
51-10-02	INSPECTION AND REMOVAL OF DAMAGE	
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS	
51-20-05, GENERAL	Repair Sealing	
51-20-13, GENERAL	Surface Roughness Finish Requirements	
51-30-03	NON-METALLIC MATERIALS	
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS	
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS	
51-70-08	RESIN SWEEP-FAIR PROCEDURES	
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING	
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes	
SOPM 20-44-04	Application of Urethane Compatible Primers	
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage	
737 NDT Part 1, 51-01-03	NDT Assessment of Lightning Strike Damage to Graphite/Epoxy Composite Structure	
737 NDT Part 1, 51-05-01	Tap Test Inspection of Honeycomb Sandwich Structure	

4. Allowable Damage Limits

- A. Zone 1 Solid Laminate Areas With Fasteners
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted if:
 (a) They are sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
 - (2) Nicks, Gouges, and Scratches that cause damage to the glass fibers are permitted if:
 - (a) Not more than one fastener hole in six is damaged
 - (b) Not more than 10 percent of the edgeband for each side of panel is damaged
 - (c) They are sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
 - (3) Dents are permitted if:
 - (a) Not more than one fastener hole in six is damaged
 - (b) Not more than 10 percent of the edgeband for each side of panel is damaged
 - (c) They are sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
 - (4) Holes and Punctures are permitted if:
 - (a) They are a maximum 0.25 inch in diameter
 - (b) Not more than one fastener hole in six is damaged
 - (c) Not more than 10 percent of the edgeband for each side of panel is damaged
 - (d) They are sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
 - (5) Delaminations are permitted if:
 - (a) Not more than one fastener hole in six is damaged
 - (b) Not more than 10 percent of the edgeband for each side of panel is damaged
 - (c) They are sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3





- (6) Edge Erosion is permitted as shown in Edge Erosion Damage Removal, Figure 106/ALLOWABLE DAMAGE 3 if:
 - (a) Not more than 10 percent of the edgeband for each side of panel is damaged
 - (b) It is sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
- (7) Edge damage is permitted if:
 - (a) It is a maximum 0.10 inch in depth
 - (b) Not more than 10 percent of the edgeband for each side of panel is damaged
 - (c) It is removed as shown in Allowable Damage Limits, Figure 107/ALLOWABLE DAMAGE 3, Detail A
 - (d) It is sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
- B. Zone 2 Honeycomb Core Areas
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted if:
 - (a) They are sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
 - (2) Nicks, Gouges, and Scratches that cause damage to the glass fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum length of 1.50 inches
- (c) A maximum width of 1.50 inches
- (d) A minimum distance away from the edge of any hole, part edge, or other damage of 4D. Refer to Damage Size and Spacing Limits, Figure 108/ALLOWABLE DAMAGE 3 for damage and spacing limits and the value of D. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass ply, and
 - 2) Are sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
- (e) Sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
- (3) Dents are permitted if:
 - (a) They are a maximum of one facesheet
 - (b) They are a maximum diameter of 1.50 inches
 - (c) They are a minimum distance away from the edge of any hole, part edge, or other damage of 4D. Refer to Damage Size and Spacing Limits, Figure 108/ALLOWABLE DAMAGE 3 for damage and spacing limits and the value of D. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass ply, and
 - 2) Are sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
 - (d) There is no fiber damage or delamination
 - (e) The damage is sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
- (4) Holes and Punctures are permitted if they are:
 - (a) A maximum of one facesheet and the core in depth
 - (b) A maximum diameter of 1.50 inches



- (c) A minimum distance away from the edge of any hole, part edge, or other damage of 4D. Refer to Damage Size and Spacing Limits, Figure 108/ALLOWABLE DAMAGE 3 for damage and spacing limits and the value of D. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass ply, and
 - 2) Are sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
- (d) Sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3

NOTE: Do not remove the damage unless it is necessary to remove resin burrs that extend into the surface contour.

- (5) Delaminations are permitted if they are:
 - (a) On a maximum of one facesheet
 - (b) A maximum diameter of 1.50 inches
 - (c) A minimum distance away from the edge of any hole, part edge, or other damage of 4D. Refer to Damage Size and Spacing Limits, Figure 108/ALLOWABLE DAMAGE 3 for damage and spacing limits and the value of D. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass ply, and
 - 2) Are sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
 - (d) Sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
- C. Zone 3 Solid Laminate Areas Without Fasteners
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted if:
 - (a) They are sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
 - (2) Nicks, Gouges, and Scratches that cause damage to the glass fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.


- (b) A maximum length of 1.50 inches
- (c) A maximum width of 1.50 inches
- (d) A minimum distance away from the edge of any hole, part edge, or other damage of 4D. Refer to Damage Size and Spacing Limits, Figure 108/ALLOWABLE DAMAGE 3 for damage and spacing limits and the value of D. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass ply, and
 - 2) Are sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
- (e) Sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
- (3) Dents are permitted if:
 - (a) They are a maximum diameter of 0.75 inch
 - (b) They are a minimum distance away from the edge of any hole, part edge, or other damage of 4D. Refer to Damage Size and Spacing Limits, Figure 108/ALLOWABLE DAMAGE 3 for damage and spacing limits and the value of D. Other damage does not include nicks, gouges, and scratches that:

ALLOWABLE DAMAGE 3

55-10-01

Page 112

Nov 10/2007






- 1) Do not cause damage to the glass ply, and
- 2) Are sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
- (c) There is no fiber damage or delamination
- (d) The damage is sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
- (4) Holes and Punctures are not permitted.
- (5) Delaminations are permitted if they are:
 - (a) A maximum diameter of 0.75 inch
 - (b) A minimum distance away from the edge of any hole, part edge, or other damage of 4D. Refer to Damage Size and Spacing Limits, Figure 108/ALLOWABLE DAMAGE 3 for damage and spacing limits and the value of D. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass ply, and
 - 2) Are sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
 - (c) Sealed as given in Paragraph 2.D./ALLOWABLE DAMAGE 3
- D. Conductive Strip
 - **NOTE**: This allowable damage section is approved only for conductive strip damage where none of the initial fasteners are loose or damaged. If there are initial fasteners loose or damaged, refer to 55-10-01, Repair 10 CONDUCTIVE STRIP.
 - (1) Remove the damage. Refer to Figure 109 for the permitted damage limits. Find the area removed from the initial cross-sectional area. If the area removed is less than or equal to 20% of the initial cross-sectional area, continue with Paragraph 4.D.(2). If the area removed is more than 20% of the initial cross-sectional area, refer to 55-10-01, Repair 10 CONDUCTIVE STRIP.
 - (2) After 30 days or less, make an initial visual inspection of the damaged Conductive Strip for signs of new damage and for loose or missing fasteners. Repeat the inspections at each 30 day interval. If any new damage is found to the conductive strip then replace the part.

NOTE: Replacement of the damaged part with a new conductive strip stops the repeat inspection intervals.

(3) Replace the damaged Conductive Strip with a new part in 24 months or less.








Edge Erosion Damage Removal Figure 106





REMOVAL OF DAMAGED MATERIAL AT EDGES WHERE THE FASTENER EDGE MARGINS DO NOT HAVE AN OVERLAP


REMOVAL OF DAMAGED MATERIAL AT EDGES WHERE THE FASTENER EDGE MARGINS HAVE AN OVERLAP

Allowable Damage Limits Figure 107

> ALLOWABLE DAMAGE 3 Page 115 Nov 10/2005



737-800 STRUCTURAL REPAIR MANUAL



NOTE: TO FIND DELAMINATION YOU CAN USE NONDESTRUCTIVE INSPECTION PROCEDURES (REFER TO NDT PART 1, 51-01-02).

THE DIAMETER OF A DAMAGE AREA IS EITHER THE DIAMETER OF THE VISUAL DAMAGE OR THE DIAMETER OF THE DELAMINATION. USE THE DIAMETER OF THE LARGER DAMAGE.

A DAMAGE AREA DOES NOT INCLUDE NICKS, GOUGES, AND SCRATCHES THAT DO NOT CAUSE DAMAGE TO THE GLASS AND CARBON FIBER PLIES IF:

- YOU MAKE A TEMPORARY SEAL OF THE DAMAGE AS GIVEN IN PARAGRAPH 2 OR - YOU MAKE A PERMANENT SEAL OF THE DAMAGE AS GIVEN IN PARAGRAPH 2

(D) IS THE LARGER DIAMETER OF TWO ADJACENT DAMAGE AREAS AND IS A MAXIMUM OF 1.50 INCHES

(d) IS THE SMALLER DIAMETER OF TWO ADJACENT DAMAGE AREAS.

(a) IS THE DISTANCE BETWEEN TWO ADJACENT DAMAGE AREAS. THE MINIMUM (a) THAT IS PERMITTED IS (4D).

> **Damage Size and Spacing Limits** Figure 108




Page 116

D634A210 BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details

BOEING


737-800 STRUCTURAL REPAIR MANUAL







737-800 STRUCTURAL REPAIR MANUAL



- D_1 = DIAMETERS OF THE INITIAL FASTENER HOLES
- t = MATERIAL THICKNESS
- W = STRIP WIDTH
- A: = INITIAL AREA OF THE STRIP
 - = THE CROSS-SECTIONAL AREA MINUS THE CROSS-SECTIONAL AREA OF THE INITIAL HOLE (AS MANUFACTURED BY BOEING)
 - $= Wt D_1t$
- A_1 = CROSS-SECTIONAL AREA OF THE DAMAGE REMOVED AT LOCATION 1
- $\begin{pmatrix} A_1 \\ \overline{A_i} \end{pmatrix}$ X 100 = percent of cross-sectional area removed = a maximum of 20 percent

Conductive Strip Allowable Damage Limits Figure 109 (Sheet 2 of 2)





ALLOWABLE DAMAGE 4 - HORIZONTAL STABILIZER LEADING EDGE SKINS, EROSION DAMAGE


1. Applicability

A. This subject gives the allowable damage limits for the horizontal stabilizer leading edge skins that have erosion damage. These limits are for the removable skin panels shown in Horizontal Stabilizer Leading Edge Skin Locations, Figure 101/ALLOWABLE DAMAGE 4. Do not use the limits of this subject for the fixed leading edge skin or the outboard tip. Refer to Allowable Damage 1 for other types of damage limits permitted.



BOEING®

737-800 STRUCTURAL REPAIR MANUAL



Horizontal Stabilizer Leading Edge Skin Locations Figure 101

> ALLOWABLE DAMAGE 4 55-10-01 Page 102 Jul 10/2004



2. General

- A. Do what follows for the aluminum leading edge skins:
 - (1) Remove the damaged material as given in Paragraph 4./ALLOWABLE DAMAGE 4 The maximum depth of material that can be removed is equal to 25% of the initial thickness of the skin.
 - (a) Refer to 51-10-02 for the inspection and removal of damage.
 - (b) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (c) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (2) Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.

3. References

Reference	Title
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-08	EROSION PROTECTION
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
AMM 51-21-00 P/B 701	INTERIOR AND EXTERIOR FINISHES - CLEANING/PAINTING

4. Allowable Damage Limits

WARNING: MATERIALS THAT ARE USED TO CLEAN AND COAT ARE TOXIC AND FLAMMABLE. MAKE SURE THERE IS A GOOD FLOW OF AIR AND YOU OBEY ALL FIRE PRECAUTIONS.

- A. Light Erosion Damage to the Aluminum Skin:
 - (1) Make the metal contour smooth.
 - (a) Apply masking tape to the areas where there is no damage.
 - (b) Clean the surface with a moist cheesecloth. Use water to make the cheesecloth moist.
 - (c) Polish or sand the damaged area to make a smooth surface. The maximum depth of removal must not be more than 25% of the initial skin thickness.

NOTE: Use aluminum oxide abrasives or aluminum wool. Do not use silicon carbide abrasives or steel wool.

- (d) Where the skin has been pushed in, make the skin contour smooth with the adjacent skin.
 - 1) Use powdered household cleanser or 400 grit aluminum oxide paper.
 - Refer to Horizontal Stabilizer Leading Edge Skin Locations, Figure 101/ALLOWABLE DAMAGE 4, Section A-A, for the surface contour limits.
- (e) Clean the surface with a moist new cheesecloth. Use MIBK to make the cheesecloth moist.
- (f) Find the depth of material that has been removed.

ALLOWABLE DAMAGE 4 55-10-01 Page 103 Jul 10/2004



- 1) Use a Vidigage, Branson digital caliper, dial gage, or a straight edge with feeler gages to find the depth.
- 2) Repair the leading edge skin if the depth of material removed is more than 25% of the initial skin thickness.
- 3) Apply a chemical conversion coating if the depth of material removed is less than 25% of the initial skin thickness. Apply the conversion coating to the bare surfaces of the skin as given in 51-20-01.
- (g) For more protection of leading edge skins, apply a new layer of erosion tape or an erosion coating. Refer to 51-20-08.
 - 1) Replace the tape or erosion coating if there is too much wear.
 - 2) When the bare metal shows or the aerodynamic smoothness limits are not kept, there is too much wear. Refer to 51-10-01 for the aerodynamic smoothness limits.
- B. Moderately damaged to badly damaged areas of the aluminum skin:
 - (1) Prepare the metal areas.
 - (a) Apply masking tape to the areas where there is no damage.
 - (b) Close and seal all openings to keep all material out of the structure.
 - (c) Static ground the airplane and the abrasive blast equipment.
 - (d) Use a spray gun with water or toluene to clean the eroded area of the skin.

CAUTION: DO NOT USE A CLOTH OR OTHER FABRIC TO CLEAN THE ABRASIVE BLASTED AREA. UNWANTED LINT ON THE CLEANED AREA WILL DECREASE THE LIFE OF THE EROSION COATING.

- (e) Use an abrasive blast to remove the erosion damage as given in 51-10-02.
 - 1) Make sure all of the oxide and corrosion has been removed from the eroded areas.
 - 2) Refer to Horizontal Stabilizer Leading Edge Skin Locations, Figure 101/ALLOWABLE DAMAGE 4, Section A-A, for the limits of a good taper.
- (f) Find the depth of material that has been removed.
 - 1) Use a Vidigage, Branson digital caliper, dial gage, or a straight edge with feeler gages to find the depth.
 - 2) Repair the leading edge skin if the depth of material removed is more than 25% of the initial skin thickness.
 - 3) Apply a chemical conversion coating if the depth of material removed is less than 25% of the initial skin thickness. Apply the conversion coating to the bare surfaces of the skin as given in 51-20-01.
- (g) For more protection of leading edge skins, apply a new layer of erosion tape or an erosion coating. Refer to 51-20-08.
 - 1) Replace the tape or erosion coating if there is too much wear.
 - 2) When the bare metal shows or the aerodynamic smoothness limits are not kept, there is too much wear. Refer to 51-10-01 for the aerodynamic smoothness limits.
- C. Damage to the initial layer of erosion protection:
 - (1) Areas of bare metal or unsatisfactory aerodynamic smoothness are caused by damage to the erosion protection. Refer to 51-10-01 for the aerodynamic smoothness limits and do what follows for these areas:

ALLOWABLE DAMAGE 4



- (a) Remove the erosion coating with MIBK.
 - 1) Soak the coating with MIBK with the use of cheesecloth.
 - 2) Keep the cheesecloth on the coating until it is soft.
 - 3) Use a plastic scraper to remove the erosion coating.
- (b) Remove the erosion tape.
 - 1) Soak the tape edge sealer with MIBK with the use of cheesecloth.
 - 2) Keep the cheesecloth on the edge sealer until it is sufficiently soft to remove.
 - 3) Heat (150°F maximum temperature) can be used to make the tape soft.
 - 4) Use a plastic scraper, razor, or knife to start the removal of the tape at edges. Use your hand to pull the tape away from the metal skin.
- (c) For more protection of leading edge skins, apply a new layer of erosion tape or an erosion coating. Refer to 51-20-08.
 - 1) Replace the tape or erosion coating if there is too much wear.
 - 2) When the bare metal shows or the aerodynamic smoothness limits are not kept, there is too much wear. Refer to 51-10-01 for the aerodynamic smoothness limits.






REPAIR 1 - HORIZONTAL STABILIZER LEADING EDGE SKIN EXTERNAL REPAIR

1. Applicability

- A. Repair 1 is applicable to damage to the horizontal stabilizer leading edge skins shown in Horizontal Stabilizer Leading Edge Skin Locations, Figure 201/REPAIR 1 if:
 - (1) You do inspections of the repair as given in Paragraph 5./REPAIR 1
 - (2) You replace Repair 1 no more than 15,000 hours after installation with one of the repairs that follow:
 - (a) A permanent flush repair as shown in Repair 2
 - (b) A replacement of the blind rivets with solid flush rivets for a permanent external repair.







LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE UPPER SURFACE IS SHOWN

> Horizontal Stabilizer Leading Edge Skin Locations Figure 201



REPAIR 1 Page 202 Nov 01/2003



2. General

- A. Repair 1 gives instructions for a Category C repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.
- C. Make sure that all blind rivets are correctly seated on the internal side of the skin. Make sure that there is sufficient edge margin from the edge of all chem-milled pockets.

3. <u>References</u>

Reference	Title	
51-00-06	STRUCTURAL REPAIR DEFINITIONS	
51-10-01	AERODYNAMIC SMOOTHNESS	
51-10-02	INSPECTION AND REMOVAL OF DAMAGE	
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS	
51-20-05	REPAIR SEALING	
51-30-05, GENERAL	Equipment and Tools For Repairs	
51-40-00, GENERAL	Fasteners	
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING	
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES	

4. Repair Instructions

- A. Drill a stop hole at the ends of all skin cracks that do not end at fastener holes. Refer to Horizontal Stabilizer Leading Edge Skin External Repair, Figure 202/REPAIR 1 and SRM 51-10-02 for the procedures to drill a stop hole. For other damage, do what follows:
 - Cut and remove the damaged part of the skin as shown in Horizontal Stabilizer Leading Edge Skin External Repair, Figure 202/REPAIR 1. Refer to 51-10-02 for the procedures to remove the damage.
 - (a) Make the cut in the shape of a rectangle with the longest sides parallel to the leading edge ribs.
 - (b) Make the corner radii of the cut a minimum of 0.50 inch.
 - (c) Make sure there is a minimum of two rows of repair fasteners around the edges of the cut.
- B. Put the skin that is around the damage back to the initial contour. Refer to 51-10-01.
- C. Make the part [1] doubler as shown in Horizontal Stabilizer Leading Edge Skin External Repair, Figure 202/REPAIR 1. Refer to Table 201/REPAIR 1 for the repair material.
 - (1) Make the contour of the part [1] doubler the same as the initial contour of the skin.

	REPAIR MATERIAL		
ITEM	PART	QUANTITY	MATERIAL
[1]	Doubler	1	Use clad 2024-T3 that is 0.063 inch thick when the initial skin is 0.040 inch thick. Use clad 2024-T3 that is one gage thicker than the initial skin when the thickness is more than 0.040 inch.

Table 201:



55-10-01




- D. Assemble the part [1] doubler as shown in Horizontal Stabilizer Leading Edge Skin External Repair, Figure 202/REPAIR 1.
- E. Drill and countersink the fastener holes.
- F. Remove the part [1] doubler.
- G. Remove the nicks, scratches, gouges, burrs, and sharp edges from the doubler and the bare surfaces of the skin.
- H. Apply a chemical conversion coating to the part [1] doubler and bare surfaces of the skin. Refer to 51-20-01 for the chemical conversion coating procedures.
- I. Install the part [1] doubler with BMS 5-95 sealant between the mating surfaces. Refer to 51-20-05 for the procedures to apply the sealant.
- J. Install the fasteners dry.
- K. Apply BMS 5-95 sealant around the edges of the part [1] doubler as given in 51-20-05.
- L. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.



ABDEING®

737-800 STRUCTURAL REPAIR MANUAL



FLAT PATTERN OF THE REPAIR

NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENERS. USE (D) TO CALCULATE EDGE MARGINS.
- MAKE SURE THAT THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.


FASTENER SYMBOLS

➡ REPAIR FASTENER LOCATION. INSTALL A BACR15FP5E() OR A NAS 1739E5 BLIND RIVET. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.


> Horizontal Stabilizer Leading Edge Skin External Repair Figure 202 (Sheet 1 of 2)



REPAIR 1 Page 205 Nov 01/2003







55-10-01

REPAIR 1 Page 206 Nov 01/2003



5. Inspection Instructions

A. Do a detailed visual inspection of the repair at each 5000 flight hour interval or more frequently. Inspect the blind rivets carefully. Blind rivets that are loose, missing, or damaged must be replaced.




REPAIR 1 Page 207 Nov 01/2003



REPAIR 2 - FLUSH REPAIR OF THE HORIZONTAL STABILIZER LEADING EDGE SKIN

1. Applicability

A. Repair 2 is applicable to damage to the horizontal stabilizer leading edge skins shown in Horizontal Stabilizer Leading Edge Skin Locations, Figure 201/REPAIR 2. Repair 2 is also applicable as a replacement repair for Repair 1.



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE UPPER SURFACE IS SHOWN

Horizontal Stabilizer Leading Edge Skin Locations Figure 201

2. <u>General</u>

- A. Repair 2 gives instructions for a Category A repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Make sure the aerodynamic smoothness is satisfactory or there will be a decrease in the performance of the aircraft. Refer to 51-10-01.



REPAIR 2 Page 201 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05	REPAIR SEALING
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-40-05, GENERAL	Fastener Hole Sizes
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
51-70-09	BONDED METAL STRUCTURE REPAIR PROCEDURES
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Repair Instructions

- A. Remove the damaged leading edge section.
- B. If this repair replaces an external repair, remove the repair fasteners, repair doubler, and sealant of the external repair. Refer to 51-40-02 for the procedures to remove the repair fasteners.
- C. Cut and remove the damaged part of the skin as shown in Horizontal Stabilizer Leading Edge Skin Flush Repair, Figure 202/REPAIR 2. Refer to 51-10-02 for the procedures to remove the damage.
 - (1) Make the cut in the shape of a rectangle with the longest sides parallel to the leading edge ribs.
 - (2) Make the corner radii of the cut a minimum of 0.50 inch.
 - (3) Make the edges of the cut smooth to a surface finish of 125 microinches.
 - (4) Make sure there is a minimum of two rows of repair fasteners around the edges of the cut.
- D. Put the skin that is around the damage back to the initial contour.
- E. Make the repair parts as shown in Horizontal Stabilizer Leading Edge Skin Flush Repair, Figure 202/REPAIR 2. Refer to Table 201/REPAIR 2 for the repair material.
 - (1) Make the contour of the repair parts the same as the initial contour of the skin.

REPAIR MATERIAL			
ITEM	PART	QUANTITY	MATERIAL
[1]	Doubler	1	Use clad 2024-T3 that is 0.063 inch thick when the initial skin is 0.040 inch thick. Use clad 2024-T3 that is one gage thicker than the initial skin when the thickness is more than 0.040 inch
[2]	Filler	1	Use clad 2024-T3 that is the same thickness as the initial skin





55-10-01



- F. Assemble the repair parts as shown in Horizontal Stabilizer Leading Edge Skin Flush Repair, Figure 202/REPAIR 2.
- G. Drill and countersink the fastener holes.
 - (1) Align fastener holes in the part [1] doubler with holes in the skin made from an external repair.
- H. Remove the repair parts.
- I. Remove the nicks, scratches, gouges, burrs, and sharp edges from the repair parts and the bare surfaces of the skin.
- J. Bond the part [1] doubler to the leading edge skin with BMS 5-141 as shown in Horizontal Stabilizer Leading Edge Skin Flush Repair, Figure 202/REPAIR 2. Refer to 51-70-09 for the procedures to bond the doubler at room temperature.

NOTE: It is optional to make a mating surface seal with BMS 5-95 sealant when you install the part [1] doubler.


- K. Install the rivets dry in the part [1] doubler and skin.
- L. Bond the part [2] filler to the part [1] doubler with BMS 5-141 as given in 51-70-09.
- M. Install the rivets without sealant in the part [2] filler.
- N. Apply BMS 5-95 or BMS 5-26 sealant in the gap between the filler and the edge of the skin cut. Refer 51-20-05 for the procedures to apply the sealant.
- O. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.



REPAIR 2 Page 203 Nov 10/2007



737-800 STRUCTURAL REPAIR MANUAL



NOTES

- ALL DIMENSIONS ARE IN INCHES
- (D) IS THE DIAMETER OF THE REPAIR FASTENER. USE (D) TO CALCULATE EDGE MARGINS.

FASTENER SYMBOLS

REPAIR FASTENER LOCATION. INSTALL A BACR15GF5D() SOLID RIVET. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.


> Horizontal Stabilizer Leading Edge Skin Flush Repair Figure 202 (Sheet 1 of 2)



REPAIR 2 Page 204 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



SECTION THROUGH LEADING EDGE REPAIR

Horizontal Stabilizer Leading Edge Skin Flush Repair Figure 202 (Sheet 2 of 2)



REPAIR 2 Page 205 Nov 01/2003



REPAIR 3 - HORIZONTAL STABILIZER INSPAR SKIN EXTERNAL REPAIR

1. Applicability


- A. Repair 3 is applicable to damage to the horizontal stabilizer inspar skins shown in Horizontal Stabilizer Upper Inspar Skin Location, Figure 201/REPAIR 3 and Horizontal Stabilizer Lower Inspar Skin Location, Figure 202/REPAIR 3.
- B. Repair 3 is not applicable to damage to the lower inspar skin outboard of Stabilizer Station 258.28.



REPAIR 3 Page 201 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE UPPER SURFACE IS SHOWN


Horizontal Stabilizer Upper Inspar Skin Location Figure 201



REPAIR 3 Page 202 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE LOWER SURFACE IS SHOWN

Horizontal Stabilizer Lower Inspar Skin Location Figure 202



REPAIR 3 Page 203 Nov 01/2003



2. General

- A. Repair 3 gives instructions for a Category A repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Refer to Repair 4 for a flush repair to the horizontal stabilizer inspar skin.
- C. Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
- D. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.
- E. Repair 3 can be used only if you install the rivets flush against the internal structure.
- F. Get access to the inside of the stabilizer through openings in the front spar.
 - (1) Use these openings to make sure the repair fasteners are installed correctly.

3. <u>References</u>

Reference	Title
51-00-06 STRUCTURAL REPAIR DEFINITIONS	
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-40-00, GENERAL	Fasteners
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-40-05, GENERAL	Fastener Hole Sizes
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Repair Instructions

- A. Drill a stop hole at the ends of all skin cracks that do not end at fastener holes. Refer to Horizontal Stabilizer Inspar Skin External Repair, Figure 203/REPAIR 3 and SRM 51-10-02 for the procedures to drill a stop hole. For other damage, do what follows:
 - (1) Cut and remove the damaged part of the skin as shown in Horizontal Stabilizer Inspar Skin External Repair, Figure 203/REPAIR 3. Refer to 51-10-02 for the procedures to remove the damage.
 - (a) Make the cut in the shape of a rectangle with the longest sides parallel to the inspar ribs.
 - (b) Make the corner radii of the cut a minimum of 0.50 inch.
- B. Put the skin that is around the damage back to the initial contour.



REPAIR 3 Page 204 Nov 10/2007



- C. Make the part [1] doubler as shown in Horizontal Stabilizer Inspar Skin External Repair, Figure 203/REPAIR 3. Refer to Table 201/REPAIR 3 for the repair material.
 - (1) Make the contour of the part [1] doubler the same as the initial contour of the skin.

Table 201:

	REPAIR MATERIAL		
ITEM	PART	QUANTITY	MATERIAL
[1]	Doubler	1	Use clad or bare 2024-T3. Refer to Table 202 for the necessary thickness of the material. The use of clad material is recommended


Table 202

REPAIR PART THICKNESSES AND REPAIR FASTENER DIAMETERS FOR INITIAL SKIN THICKNESSES			
INITIAL SKIN THICKNESS (INCH) ITEM [1] DOUBLER THICKNESS (INCH) REPAIR FASTENE		REPAIR FASTENER DIAMETER (INCH)	
0.040	0.063	3/16	
0.050	0.063	3/16	
0.060	0.080	3/16	
0.071	0.090	3/16	
0.080	0.100	3/16	

- D. Assemble the part [1] doubler as shown in Horizontal Stabilizer Inspar Skin External Repair, Figure 203/REPAIR 3.
- E. Drill the fastener holes.
- F. Countersink the fastener holes in the part [1] doubler.
- G. Remove the part [1] doubler.
- H. Remove the nicks, scratches, gouges, burrs, and sharp edges from the doubler and the bare surfaces of the skin.
- I. Apply a chemical conversion coating to the part [1] doubler and bare surfaces of the skin. Refer to 51-20-01 for the chemical conversion coating procedures.
- J. Apply one layer of BMS 10-79, Type III, primer to the area of the repair. Refer to SOPM 20-44-04 for the procedures to apply the primer.
 - (1) Apply the primer to the part [1] doubler.
 - (2) Apply the primer to the bare surfaces of the skin.
- K. Install the part [1] doubler with BMS 5-95 sealant between the mating surfaces. Refer to 51-20-05 for the procedures to apply the sealant.
- L. Install the fasteners dry.
- M. Apply BMS 5-95 sealant around the edges of the part [1] doubler as given in 51-20-05.
- N. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.



REPAIR 3 Page 205 Nov 10/2007



NOTES

- MAKE SURE THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.
- MAKE SURE THERE IS A MINIMUM OF FOUR ROWS OF REPAIR FASTENERS AROUND THE DAMAGE.

FASTENER SYMBOLS

➡ REPAIR FASTENER LOCATION. INSTALL A BACR15CE6D SOLID RIVET. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.

> Horizontal Stabilizer Inspar Skin External Repair Figure 203



REPAIR 3 Page 206 Nov 01/2003



REPAIR 4 - HORIZONTAL STABILIZER INSPAR SKIN FLUSH REPAIR


1. Applicability

- A. Repair 4 is applicable to damage to the horizontal stabilizer inspar skins shown in Horizontal Stabilizer Upper Inspar Skin Location, Figure 201/REPAIR 4 and Horizontal Stabilizer Lower Inspar Skin Location, Figure 202/REPAIR 4.
 - (1) Repair 4 is also applicable as a replacement repair for Repair 3.





737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE UPPER SURFACE IS SHOWN


Horizontal Stabilizer Upper Inspar Skin Location Figure 201



REPAIR 4 Page 202 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE LOWER SURFACE IS SHOWN

Horizontal Stabilizer Lower Inspar Skin Location Figure 202



REPAIR 4 Page 203 Nov 01/2003




2. General

- A. Repair 4 gives instructions for a Category A repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.
- C. Repairs with protruding head fasteners are permitted as shown in Horizontal Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners, Figure 203/REPAIR 4 and as follows:
 - (1) For the area of each skin located in front of balance bays numbers 2, 3, and 4 (located between ELEV STA 66.54 and ELEV STA 149.12), repairs are permitted as follows:
 - (a) The total outboard width across all repairs can not be more than 15 percent of the width of the airstream for each skin. The width of this airstream is the distance across the airstream measured in the outboard direction.
 - (2) For the area of each skin not located in front of balance bays numbers 2, 3, and 4 repairs are permitted as follows:
 - (a) The total outboard width across all repairs can not be more than 25 percent of the width of the airstream for each skin. The width of this airstream is the distance across the airstream measured in the outboard direction. This width does not include the airstream in front of balance bays numbers 2, 3, and 4.
- D. Get access to the inside of the stabilizer through openings in the front spar.
 - (1) It is optional to make an access door in the inspar skin.
 - (2) Use these openings or doors to make sure the repair fasteners are installed correctly.
 - (3) Refer to Repair 7 and Repair 8 to make an access door.



REPAIR 4 Page 204 Jul 10/2004



NOT PERMITTED.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Horizontal Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 203

> REPAIR 4 Page 205 Nov 01/2003

55-10-01



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-00, GENERAL	Fasteners
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-40-05, GENERAL	Fastener Hole Sizes
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
51-70-09	BONDED METAL STRUCTURE REPAIR PROCEDURES
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Repair Instructions

- A. If this repair replaces an external repair, remove the repair fasteners, repair doubler, and sealant of the external repair. Refer to 51-40-02 for the procedures to remove the repair fasteners.
- B. Cut and remove the damaged part of the skin as shown in Horizontal Stabilizer Inspar Skin Flush Repair, Figure 204/REPAIR 4. Refer to 51-10-02 for the procedures to remove the damage.
 - (1) Make the cut in the shape of a rectangle with the longer sides parallel to the inspar ribs.
 - (2) Make the corner radii of the cut a minimum of 0.50 inch.
 - (3) Make sure there is a minimum of three rows of repair fasteners around the edges of the cut.
- C. Put the skin that is around the damage back to the initial contour.
- D. Make the repair parts as shown in Horizontal Stabilizer Inspar Skin Flush Repair, Figure 204/REPAIR 4. Refer to Table 201/REPAIR 4 for the repair material.
 - (1) Make the contour of the repair parts the same as the initial contour of the skin.

	REPAIR MATERIAL				
ITEM PART QUANTITY MATERIAL					
[1]	Doubler	1	Use clad or bare 2024-T3. Refer to Table 202 for the necessary thickness of the material. The use of clad material is recommended		
[2]	Filler	1	Use clad or bare 2024-T3 that is the same thickness as the initial skin. The use of clad material is recommended		

Table 201:



55-10-01



Table 202:

REPAIR PART THICKNESSES AND REPAIR FASTENER DIAMETERS FOR INITIAL SKIN THICKNESSES				
INITIAL SKIN THICKNESS (INCH)	REPAIR FASTENER DIAMETER (INCH)			
0.040	0.063	3/16		
0.050	0.063	3/16		
0.060	0.071	3/16		
0.071	0.090	3/16		
0.080	0.100	3/16		


- E. Assemble the repair parts as shown in Horizontal Stabilizer Inspar Skin Flush Repair, Figure 204/REPAIR 4.
- F. Drill the fastener holes.
 - (1) Align fastener holes in the part [1] doubler with holes in the skin made from an external repair.
- G. Remove the repair parts.
- H. Remove the nicks, scratches, gouges, burrs, and sharp edges from the repair parts and the bare surfaces of the skin.
- I. Apply a chemical conversion coating to the repair parts and bare surfaces of the skin. Refer to 51-20-01 for the chemical conversion coating procedures.
- J. Apply one layer of BMS 10-79, Type II or III, primer to the area of the repair. Refer to SOPM 20-44-04 for the procedures to apply the primer.
 - (1) Apply the primer to the repair parts.
 - (2) Apply the primer to the bare surfaces of the skin.
- K. Bond the part [1] doubler to the inspar skin with BMS 5-101 as shown in Horizontal Stabilizer Inspar Skin Flush Repair, Figure 204/REPAIR 4. Refer to 51-70-09 for the procedures to bond the doubler.

NOTE: It is optional to apply BMS 5-95 sealant to the mating surfaces when you install the repair parts.

- L. Install the rivets dry without sealant in the part [1] doubler and skin.
- M. Bond the part [2] filler to the part [1] doubler with BMS 5-101 as given in 51-70-09.
- N. Install the rivets dry without sealant in the part [2] filler.
- O. Apply BMS 5-95 or BMS 5-26 sealant in the gap between the filler and the edge of the skin cut. Refer 51-20-05 for the procedures to apply the sealant.
- P. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.



REPAIR 4 Page 207 Nov 10/2007



REPAIR FASTENER LOCATIONS - STABILIZER STATIONS 83.5 TO 92.7


NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENER. USE (D) TO CALCULATE EDGE MARGINS AND THE DISTANCE BETWEEN FASTENERS.
- MAKE SURE THAT THERE IS A MINIMUM OF THREE ROWS OF FASTENERS AROUND THE DAMAGE.
- MAKE SURE THAT THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.

FASTENER SYMBOLS

REPAIR FASTENER LOCATION. INSTALL A BACR15FT6D() SOLID RIVET. REFER TO SRM 51-40-00 THROUGH 51-40-06 FOR THE FASTENER DATA.


> Horizontal Stabilizer Inspar Skin Flush Repair Figure 204 (Sheet 1 of 2)



REPAIR 4 Page 208 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



Horizontal Stabilizer Inspar Skin Flush Repair Figure 204 (Sheet 2 of 2)



REPAIR 4 Page 209 Nov 01/2003



REPAIR 7 - HORIZONTAL STABILIZER ACCESS PANEL INSTALLATION WITH A ONE-PIECE DOUBLER

1. Applicability

- A. Repair 7 is applicable to damage to the horizontal stabilizer lower skin from Stab BL 83.5 to Stab BL 258.
- B. Repair 7 can be used to make an access hole in the lower skin of the horizontal stabilizer.
- C. Repair 7 is not applicable to damage on the upper skin of the horizontal stabilizer.
 - (1) Locations where there is sufficient clearance to install a one-piece part [2] doubler.

2. General

- A. Repair 7 is a Category A repair. Refer to 51-00-06 for the definitions of the different categories of repairs.
- B. An alternative to Repair 7 is Repair 8.

<u>NOTE</u>: Repair 8 is an access panel installation with a two-piece doubler for locations where there is not sufficient clearance to install a one-piece doubler.

3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-40-05	FASTENER HOLE SIZES
51-40-06, GENERAL	Fastener Edge Margins
AMM 51-21-99/701	Decorative Exterior Paint System - Cleaning and Painting
SOPM 20-44-01	Application of Special Purpose Coatings and Finishes
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Repair Instructions

- A. Cut the hole in the skin to the shape shown in Horizontal Stabilizer Access Panel Installation, Figure 201/REPAIR 7.
 - (1) Make sure you do not cover a drain hole with the repair parts.
 - (a) If you must do the repair in a drain hole area, then put the cutout in position so you can drill a hole through a repair part at the initial drain hole.
- B. Remove the fasteners from the rib chords as necessary.
 - (1) Refer to 51-40-02.
- C. Make the repair parts. Refer to Table 201/REPAIR 7.

-						
	REPAIR MATERIAL					
ITEM	ITEM PART QUANTITY MATERIAL					
[1]	[1] Cover Plate 1 Use bare or clad 2024-T3 that is 0.070 inch thick					
[2]	[2] Doubler 1 Use bare or clad 2024-T351 that is 0.250 inch thick					

Table 201:



55-10-01



REPAIR MATERIAL			
ITEM PART QUANTITY MATERIAL			
[3] Shim 1 Use bare or clad 2024-T3 that is 0.030 inch thick		Use bare or clad 2024-T3 that is 0.030 inch thick	

- D. Assemble the part [2] doubler and the part [3] shim as shown in Horizontal Stabilizer Access Panel Installation, Figure 201/REPAIR 7.
- E. Drill the fastener holes that go through the skin, rib chords, the part [2] doubler, and the part [3] shim.
 - (1) Refer to 51-40-05 for the fastener hole dimensions.
 - (2) If you installed the repair parts at a drain hole location, then drill a hole through the repair parts and through the initial drain hole.
 - (a) Make the hole you drill the same diameter as the initial drain hole.
- F. Disassemble the repair parts.
- G. Remove the nicks, scratches, gouges, and burrs from the initial parts and from the part [2] doubler and the part [3] shim.
- H. Apply a chemical conversion coating to the part [2] doubler and the part [3] shim and the bare surfaces of the skin. Refer to 51-20-01.
- I. Apply one layer of BMS 10-79, Type II primer to the part [2] doubler and the part [3] shim and the bare surfaces of the initial parts. Refer to SOPM 20-44-04.
- J. Install the part [2] doubler and the part [3] shim.
 - (1) Apply BMS 5-95 sealant to the mating surfaces. Refer to 51-20-05.
 - (2) Install the rivets without sealant.
 - (3) If you use hex drive bolts, install the fasteners wet with BMS 5-95 sealant.
- K. Put the part [1] cover plate in position as shown in Horizontal Stabilizer Access Panel Installation, Figure 201/REPAIR 7.
- L. Drill the 0.190 to 0.199 inch diameter holes for the nutplates as shown in Horizontal Stabilizer Access Panel Installation, Figure 201/REPAIR 7.
- M. Remove the part [1] cover plate.
- N. Put the nutplates in position on the part [2] doubler and drill the holes for the rivets.
- O. Remove all the nicks, scratches, gouges, and burrs from the part [1] cover plate, the part [2] doubler, and the part [3] shim.
- P. Apply a chemical conversion coating to the part [1] cover plate and the bare surfaces of the part [2] doubler and the part [3] shim. Refer to 51-20-01.
- Q. Apply one layer of BMS 10-79, Type II primer to the part [1] cover plate and the bare surfaces of the part [2] doubler and the part [3] shim. Refer to SOPM 20-44-04.
- R. Install the nutplates on the part [2] doubler.
 - (1) Install the rivets without sealant.
- S. Apply BMS 10-86, Type I white abrasion resistant coating to the mating surfaces of the part [1] cover plate and the part [2] doubler. Refer to SOPM 20-44-01.
- T. Install the part [1] cover plate.
 - (1) Apply BMS 5-95 sealant to the mating surfaces. Refer to 51-20-05.
 - (2) Install the fasteners wet with BMS 5-95 sealant.
 - (3) Put BMS 5-95 sealant into the space between the skin and the part [1] cover plate.



REPAIR 7 Page 202 Nov 01/2003




U. Apply the decorative finish to the repair area if necessary. Refer to AMM 51-21-99/701.



REPAIR 7 Page 203 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



NOTES

1 USE THE FASTENER SPACING AS FOLLOWS: - 0.65 INCH FOR STAB BL 83.5 TO STAB BL 258.0

> Horizontal Stabilizer Access Panel Installation Figure 201 (Sheet 1 of 2)




REPAIR 7 Page 204 Nov 01/2003

D634A210

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



A-A

FASTENER SYMBOLS

- + INITIAL FASTENER LOCATION. INSTALL A FASTENER THAT IS THE SAME TYPE AND DIAMETER AS THE INITIAL FASTENER. YOU CAN INSTALL A FASTENER THAT IS UP TO 1/32 INCH DIAMETER OVERSIZE.
- + REPAIR FASTENER LOCATION. INSTALL A BACB30MY6K HEX DRIVE BOLT.
- + REPAIR FASTENER LOCATION. INSTALL BACN10JR03CFM NUTPLATE WITH BACR15BA3D RIVETS. INSTALL A BACB30EL3-() BOLT TO ATTACH THE PART [1] COVER PLATE.

Horizontal Stabilizer Access Panel Installation Figure 201 (Sheet 2 of 2)



REPAIR 7 Page 205 Nov 01/2003

D634A210



REPAIR 8 - HORIZONTAL STABILIZER LOWER SKIN AND ACCESS PANEL INSTALLATION WITH A TWO-PIECE DOUBLER

1. Applicability

A. Repair 8 is applicable for damage to:

- (1) The horizontal stabilizer lower skin from Stab BL 83.5 to Stab BL 258
- (2) Locations where there is not sufficient clearance to install a one-piece part [2] doubler.
- B. Repair 8 can be used to make an access hole in the lower skin of the horizontal stabilizer.
- C. Repair 8 does not apply to the upper skin of the horizontal stabilizer.

2. General

- A. Repair 8 is a Category A repair. Refer to 51-00-06 for the definitions of the different categories of repairs.
- B. An alternative to Repair 8 is Repair 7.

NOTE: Repair 7 is an access panel installation for locations where there is sufficient clearance to install a one-piece doubler.

3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-40-05	FASTENER HOLE SIZES
51-40-06, GENERAL	Fastener Edge Margins
AMM 51-21-99/701	Decorative Exterior Paint System - Cleaning and Painting
SOPM 20-44-01	Application of Special Purpose Coatings and Finishes
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Repair Instructions

- A. Cut the hole in the skin to the shape shown in Horizontal Stabilizer Access Panel Installation, Figure 201/REPAIR 8.
 - (1) Make sure you do not cover a drain hole with the repair parts.
 - (a) If you must do the repair in a drain hole area, then put the cutout in position so you can drill through a repair part at the initial drain hole.
- B. Remove the fasteners from the rib chords as necessary.
 - (1) Refer to 51-40-02.
- C. Make the repair parts. Refer to Table 201/REPAIR 8.

Table 201:

	REPAIR MATERIAL					
ITEM	ITEM PART QUANTITY MATERIAL					
[1] Cover Plate 1 Use bare or clad 2024-T3 that is 0.070 inch thick						





737-800 STRUCTURAL REPAIR MANUAL

	REPAIR MATERIAL				
ITEM	ITEM PART QUANTITY MATERIAL				
[2]	[2] Doubler 2 Use bare or clad 2024-T351 that is 0.25 inch thick				
[3]	[3] Shim 2 Use bare or clad 2024-T3 that is 0.030 inch thick				
[4]	Splice Plate	2	Use bare or clad 2024-T351 that is 0.25 inch thick		

- D. Assemble the part [2] doublers and the part [3] shims as shown in Horizontal Stabilizer Access Panel Installation, Figure 201/REPAIR 8.
- E. Drill the fastener holes that go through the skin, the rib chords, the part [2] doublers, and the part [3] shims.
 - (1) Refer to 51-40-05 for the fastener hole dimensions.
 - (a) If you installed the repair parts at a drain hole location, then drill a hole through the repair parts and through the initial drain hole.
 - (b) Make the hole you drill the same diameter as the initial drain hole.
- F. Assemble the part [4] splice plates as shown in Horizontal Stabilizer Access Panel Installation, Figure 201/REPAIR 8.
- G. Drill the fastener holes that go through the skin, the part [4] splice plates, the part [2] doublers. Refer to 51-40-05 for the fastener hole dimensions.
- H. Disassemble the repair parts.
- I. Remove the nicks, scratches, gouges, and burrs from the initial parts and from the part [2] doublers, the part [3] shims, and the part [4] splice plates.
- J. Apply a chemical conversion coating to the bare surfaces of the initial parts and to the part [2] doublers, the part [3] shims, and the part [4] splice plates. Refer to 51-20-01.
- K. Apply one layer of BMS 10-79, Type II primer to the bare surfaces of the initial parts and to the part [2] doublers, the part [3] shims, and the part [4] splice plates. Refer to SOPM 20-44-04.
- L. Install the part [2] doublers, the part [3] shims, and the part [4] splice plates.
 - (1) Apply BMS 5-95 sealant to the mating surfaces. Refer to 51-20-05.
 - (2) Install the rivets without sealant.
 - (3) If you use hex drive bolts, install the fasteners wet with BMS 5-95 sealant.
- M. Put the part [1] cover plate in position as shown in Horizontal Stabilizer Access Panel Installation, Figure 201/REPAIR 8.
- N. Drill the 0.190 to 0.199 inch diameter holes for the nutplates as shown in Horizontal Stabilizer Access Panel Installation, Figure 201/REPAIR 8.
- O. Remove the part [1] cover plate.
- P. Put the nutplates in position on the part [2] doubler and drill the holes for the rivets.
- Q. Remove the nicks, scratches, gouges, and burrs from the repair parts.
- R. Apply a chemical conversion coating to the part [1] cover plate and the bare surfaces of the part [2] doublers, the part [3] shims, and the part [4] splice plates. Refer to 51-20-01.
- S. Apply one layer of BMS 10-79, Type II primer to the part [1] cover plate and the bare surfaces of the part [2] doublers, the part [3] shims, and the part [4] splice plates. Refer to SOPM 20-44-04.
- T. Install the nutplates on the part [2] doubler.
 - (1) Install the rivets without sealant.



REPAIR 8 Page 202 Nov 01/2003




- U. Apply BMS 10-86, Type I white abrasion resistant coating to the mating surfaces of the part [1] cover plate and the part [2] doublers. Refer to SOPM 20-44-01.
- V. Install the part [1] cover plate.
 - (1) Apply BMS 5-95 sealant to the mating surfaces. Refer to 51-20-05.
 - (2) Install the fasteners wet with BMS 5-95 sealant.
 - (3) Put BMS 5-95 sealant into the space between the skin and the part [1] cover plate.
- W. Apply the decorative finish to the repair area if necessary. Refer to AMM 51-21-99/701.



REPAIR 8 Page 203 Nov 01/2003

BDEING®

737-800 STRUCTURAL REPAIR MANUAL



NOTES

1 USE THE FASTENER SPACING AS FOLLOWS: - 0.65 INCH FOR STAB BL 83.5 TO STAB BL 258.0

> Horizontal Stabilizer Access Panel Installation Figure 201 (Sheet 1 of 2)




REPAIR 8 Page 204 Nov 01/2003


D634A210



737-800 STRUCTURAL REPAIR MANUAL



A-A



B-B

FASTENER SYMBOLS

- H INITIAL FASTENER LOCATION. INSTALL A FASTENER THAT IS THE SAME TYPE AND DIAMETER AS THE INITIAL FASTENER. YOU CAN INSTALL A FASTENER THAT IS UP TO 1/32 INCH DIAMETER OVERSIZE.
- + REPAIR FASTENER LOCATION. INSTALL A BACB30MYK HEX DRIVE BOLT.
- + REPAIR FASTENER LOCATION. INSTALL BACN10JR03CFM NUTPLATE WITH BACR15BA3D RIVETS. INSTALL A BACB30EL3-() BOLT TO ATTACH THE PART [1] COVER PLATE.

Horizontal Stabilizer Access Panel Installation Figure 201 (Sheet 2 of 2)



REPAIR 8 Page 205 Nov 01/2003





REPAIR 9 - HORIZONTAL STABILIZER TRAILING EDGE PANELS

1. Applicability

- A. Repair 9 is applicable to damage on the horizontal stabilizer trailing edge panels shown in Horizontal Stabilizer Upper Trailing Edge Panel Locations, Figure 201/REPAIR 9. The trailing edge panels are made of Glass Fiber Reinforced Plastic (GFRP) and Carbon Fiber Reinforced Plastic (CFRP).
- B. Repair 9 is applicable to damage that is more than the limits permitted in Allowable Damage 3. Refer to Allowable Damage 3 for the type and size of damage that is permitted.

2. General

- A. Repair 9 gives instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Get access to the damaged area.
 - (1) If necessary, remove the trailing edge panels.
 - (2) Refer to 51-40-02 for information on fastener removal.
- C. Refer to Damage Definitions, Figure 202/REPAIR 9, Details A, B, and C for the definitions of the length, width, and depth of damage.
- D. Refer to Definitions of the Facesheets, Figure 203/REPAIR 9 for the definitions of the facesheets of a honeycomb core area.
- E. Some trailing edge panels have a protective layer of Teflon film. If damage occurs, refer to AMM 51-21-81/701 for the procedures to repair the Teflon film.
- F. The conditions that follow must be true for panel areas other than the edgeband:
 - (1) The edges of the room-temperature Category B repairs must be 6 inches or more away from:
 - (a) The edge of other repairs
 - (b) The panel edge
 - (c) The edge of other damage. This does not include damage that is permitted and sealed as given in Allowable Damage 3.
 - (2) The edges of the 150°F (66°C) and 200°F (93°C) cure Category A repairs must be 3 inches or more away from:
 - (a) The edge of other repairs
 - (b) The panel edge
 - (c) The edge of other damage. This does not include damage that is permitted and sealed as given in Allowable Damage 3.
- G. Do the repair as given in Paragraph 4./REPAIR 9
- H. Put the trailing edge panels back to the initial condition, as applicable.
 - (1) Install the trailing edge panels, if they were removed.
 - (a) Refer to 51-40-02 for information on fastener installation.
 - (2) Make sure the aerodynamic smoothness is satisfactory or there will be a decrease in the performance of the airplane. Refer to 51-10-01.



REPAIR 9 Page 201 Nov 01/2003





Figure 201



REPAIR 9 Page 202 Nov 01/2003

BOEING

737-800 STRUCTURAL REPAIR MANUAL



D634A210


REPAIR 9 Page 203

Nov 01/2003

55-10-01



737-800 STRUCTURAL REPAIR MANUAL



Definitions of the Facesheets Figure 203

3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-05, GENERAL	Repair Sealing
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05, REPAIR GENERAL	Repair Procedures for Preimpregnated Materials
51-70-06	ROOM TEMPERATURE CURE REPAIRS
51-70-14, REPAIR GENERAL	Structures With Aluminum Coatings and Foils
55-10-01, ALLOWABLE DAMAGE 3	Horizontal Stabilizer Trailing Edge Panels
AMM 51-21-81 P/B 701	ABRASION-RESISTANT TEFLON FINISH - CLEANING/PAINTING
AMM 51-21-81/701	Abrasion-resistant Teflon Finish - Cleaning/Painting

4. Repair Instructions

- A. For dents that are a maximum of 2 inches in diameter and have no fiber damage and delamination, do the steps that follow:
 - (1) Fill the dent with BMS 5-28, Type 7 potting compound.
 - (2) Apply a fiberglass patch over the potted area as given in 51-70-04.
- B. For dents that are not permitted by Paragraph 4.A./REPAIR 9 and for other damage that is not permitted by Allowable Damage 3, refer to:
 - (1) Table 201/REPAIR 9 for panel areas with honeycomb core
 - (2) Table 202/REPAIR 9 for solid laminate panel areas, except edgebands
 - (3) Table 203/REPAIR 9 for panel areas with edgebands.



REPAIR 9 Page 204 Nov 01/2003



Table 201:

REPAIR DATA FOR	REPAIR DATA FOR THE 250°F (121°C) CURE TRAILING EDGE PANELS FOR PANEL AREAS WITH HONEY COMB CORE					
REPAIR TYPE	CATEGORY B WET LAYUP REPAIR AS GIVEN IN SRM 51-70-06	CATEGORY A WET LAYUP REPAIR AS GIVEN IN SRM 51-70-04	CATEGORY A WET LAYUP REPAIR AS GIVEN IN SRM 51-70-04	CATEGORY A PREIMPREGNATED LAYUP REPAIR AS GIVEN IN SRM 51-70-05		
REPAIR CURE TEMPERATURE	Room Temperature	150°F (66°C)	200°F (93°C)	250°F (121°C)		
REPAIR SIZE	Damage that is a maximum of: - 2.0 inches in diameter - 30 percent of the smallest dimension across the panel at the damage location - One facesheet and the honeycomb core in depth	Damage that is a maximum of: - 4.0 inches in diameter - 50 percent of the smallest dimension across the panel at the damage location	Damage that is a maximum of: - 6.0 inches in diameter - 50 percent of the smallest dimension across the panel at the damage location	There are no limits on the size of the repair		
REPAIR PROCEDURES	Refer to Paragraph 4.C	Refer to Paragraph 4.D	Refer to Paragraph 4.E	Refer to Paragraph 4.F		

Table 202:

REPAIR DATA FOR THE 250°F (121°C) CURE TRAILING EDGE PANELS FOR SOLID LAMINATE PANEL AREAS, EXCEPT EDGEBANDS					
REPAIR TYPE	CATEGORY B WET LAYUP REPAIR AS GIVEN IN SRM 51-70-06	CATEGORY A WET LAYUP REPAIR AS GIVEN IN SRM 51-70-04	CATEGORY A WET LAYUP REPAIR AS GIVEN IN SRM 51-70-04	CATEGORY A PREIMPREGNATED LAYUP REPAIR AS GIVEN IN SRM 51-70-05	
REPAIR CURE TEMPERATURE	Room Temperature	150°F (66°C)	200°F (93°C)	250°F (121°C)	
REPAIR SIZE	Damage that is a maximum of: - 1.0 inches in diameter - 15 percent of the smallest dimension across the panel at the damage location - One facesheet and the honeycomb core in depth	Damage that is a maximum of: - 2.0 inches in diameter - 25 percent of the smallest dimension across the panel at the damage location	Damage that is a maximum of: - 3.0 inches in diameter - 35 percent of the smallest dimension across the panel at the damage location	There are no limits on the size of the repair	
REPAIR PROCEDURES	Refer to Paragraph 4.C	Refer to Paragraph 4.D	Refer to Paragraph 4.E	Refer to Paragraph 4.F	



REPAIR 9 Page 205 Nov 01/2003

D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



Table 203:

REPAIR DATA FOR THE EDGEBANDS OF 250°F (121°C) CURE TRAILING EDGE PANELS					
REPAIR TYPE	CATEGORY B WET LAYUP REPAIR AS GIVEN IN SRM 51-70-06	CATEGORY A WET LAYUP REPAIR AS GIVEN IN SRM 51-70-04	CATEGORY B WET LAYUP REPAIR AS GIVEN IN SRM 51-70-04	CATEGORY A PREIMPREGNATED LAYUP REPAIR AS GIVEN IN SRM 51-70-05	
REPAIR CURE TEMPERATURE	Room Temperature	150°F (66°C)	200°F (93°C)	250°F (121°C)	
REPAIR SIZE	Damage that is a maximum of: - 15 percent of the cross- sectional area of the edge- band at the damage location - 10 percent of the length of the edgeband on the side of the damage	Damage that is a maximum of: - 15 percent of the cross- sectional area of the edgeband at the damage location - 10 percent of the length of the edgeband on the side of the damage	There are no size limits on the dimensions of the repair	There are no limits on the size of the repair	
REPAIR PROCEDURES	Refer to Paragraph 4.C	Refer to Paragraph 4.D	Refer to Paragraph 4.E	Refer to Paragraph 4.F	

- C. Use the instructions that follow to do a Category B repair with wet layup materials at room temperature cure.
 - (1) Repair the damage as given in 51-70-06, but for each facesheet or solid laminate area that is damaged, do the steps that follow:
 - (a) Use the same number of repair plies as the number of initial plies that were removed. Refer to Definitions of the Facesheets, Figure 203/REPAIR 9 for the definition of a facesheet.
 - (b) Add one ply (structural) of BMS 9-3, Type H-2, (or Type H-3) glass fabric that is ± 45 degrees.
 - (c) Add a second ply (structural) of BMS 9-3, Type H-2 (or Type H-3) glass fabric that is 0 or 90 degrees.
 - (d) You must do an inspection of the repair every 800 flight hours or sooner.
- D. Use the instructions that follow to do a Category A repair with wet layup materials at 150°F (66°C) cure.
 - (1) Repair the damage as given in 51-70-04, but for each facesheet or solid laminate area that is damaged, do the steps that follow:
 - (a) Use the same number of repair plies as the number of initial plies that were removed. Refer to Definitions of the Facesheets, Figure 203/REPAIR 9 for the definition of a facesheet.
 - (b) Add one ply (structural) of BMS 9-3, Type H-2, (or Type H-3) glass fabric that is ± 45 degrees.
 - (c) Add a second ply (structural) of BMS 9-3, Type H-2 (or Type H-3) glass fabric that is 0 or 90 degrees.
- E. Use the instructions that follow to do a Category A repair with wet layup materials at 200°F (93°C) cure.
 - (1) Repair the damage as given in 51-70-04, but for each facesheet or solid laminate area that is damaged, do the steps that follow:



REPAIR 9 Page 206 Nov 01/2003



- (a) Use the same number of repair plies as the number of initial plies that were removed. Refer to Definitions of the Facesheets, Figure 203/REPAIR 9 for the definition of a facesheet.
- (b) Add one ply (structural) of BMS 9-3, Type H-2, (or Type H-3) glass fabric that is ± 45 degrees.
- (c) Add a second ply (structural) of BMS 9-3, Type H-2 (or Type H-3) glass fabric that is 0 or 90 degrees.
- F. Use the instruction that follows to do a Category A repair with preimpregnated layup materials at 250°F (121°C) cure.
 - (1) Use the same number of repair plies as the number of initial plies that were removed.



REPAIR 9 Page 207 Nov 01/2003



REPAIR 10 - HORIZONTAL STABILIZER TRAILING EDGE PANEL CONDUCTIVE STRIP

1. Applicability

- A. Repair 10 is applicable to damage on the horizontal stabilizer trailing edge panel conductive strip.
- B. Repair 10 is applicable to damage to the conductive strip that is more than the limits permitted in SRM 55-10-01, Allowable Damage 3.

2. General

- A. Repair 10 gives instructions for a Category C repair. Refer to STRUCTURAL REPAIR DEFINITIONS, 51-00-06 for definitions of the different categories of repairs.
- B. Gain access to the damaged area.
 - (1) If necessary, remove the trailing edge panels.
 - (2) Refer to FASTENER INSTALLATION AND REMOVAL, 51-40-02 for information on fastener removal.

3. <u>References</u>

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-20-13	SURFACE ROUGHNESS FINISH REQUIREMENTS
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-08	COUNTERSINKING
51-70-14	STRUCTURES WITH ALUMINUM COATINGS AND FOILS
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes

4. Repair Instructions

- A. Remove fasteners as necessary to the conductive strip at the damaged location. Refer to the part [1] doubler given in Figure 201.
- B. Blend or completely remove the damaged area as shown in Figure 201. Maintain a minimum 125 micro inches Ra surface smoothness or smoother. Refer to SURFACE ROUGHNESS FINISH REQUIREMENTS, 51-20-13.
- C. Make the repair parts as shown in Figure 201/REPAIR 10. Refer to Table 201/REPAIR 10 for the repair material. Make the Part [1] Doubler to follow the skin panel contour. Make sure the Part [1] Doubler extends two fasteners minimum beyond damage in either direction. Make sure there is 1.5D minimum edge margin on all the fasteners. Make sure the corner radii are 0.5 inch minimum.

Table 201:					
	REPAIR MATERIAL				
ITEM	PART	QUANTITY	MATERIAL		
[1]	Doubler	1	0.04 inch (1.0 mm) 6061-T4. It is optional to use 2024-T3 sheet		





Table 201:

REPAIR MATERIAL					
[2]	Filler (if necessary)	1	Use 6061-T4 sheet with a thickness to limit all gaps to a maximum 0.01 inch (0.25 mm). It is optional to use 2024-T3 sheet.		


- D. Remove the finish from the initial conductive strip surface that is common to the part [1] doubler.
- E. Make the countersink washers for necessary initial fastener locations. Refer to COUNTERSINKING, 51-40-08.
- F. At necessary initial fastener locations, install countersink repair washers with BMS 5-95 sealant. Refer to COUNTERSINKING, 51-40-08. Perform a resistance check between the washers and the conductive strip as given in BAC 5117-6. The maximum resistance is to be 0.01 ohms.
- G. Assemble the repair parts as shown in Figure 201/REPAIR 10.
- H. Drill the fastener holes.
- I. Remove the repair parts.
- J. Remove all nicks, scratches, gouges, burrs, and sharp edges from the repair parts and the bare surfaces of the initial parts.
- K. Install the repair parts dry.
- L. Install the fasteners without sealant. Do a resistance check between the fastener head and the initial structure as given in BAC 5117.
- M. Apply a chemical conversion coating to the repair parts and bare surfaces. Refer to PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS, 51-20-01.
- N. Apply two layers of BMS 10-11, Type II primer to the bare surfaces except at areas common to the static wicks. Refer to SOPM 20-41-02.
- O. Fillet seal the repair parts and all gaps with BMS 5-95 sealant. Refer to REPAIR SEALING, 51-20-05.
- P. Do a resistance test between the Part [1] Doubler and conductive strip. Refer to STRUCTURES WITH ALUMINUM COATINGS AND FOILS, 51-70-14 for test procedures.
- Q. Apply all initial production drawing finishes as necessary.
- R. After 30 days or less, make an initial visual inspection of the repaired conductive strip for signs of new damage or for loose or missing fasteners. Repeat the inspections at each 30 day interval. If there is new damage found to the conductive strip then replace the conductive strip. Replacement of the damaged part with a new conductive strip stops the necessary inspection.
- S. Replace the damaged conductive strip with a new conductive strip in 24 months or less.



REPAIR 10 Page 202 Nov 10/2005

BOEING®

737-800 STRUCTURAL REPAIR MANUAL






55-10-01



IDENTIFICATION 1 - HORIZONTAL STABILIZER INSPAR INTERCOSTALS



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Horizontal Stabilizer Inspar Intercostal Location Figure 1


Table 1:

REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE			
001A8001	Section 82 Left Horizontal Stabilizer - Product Collector			
001A8002	Section 82 Right Horizontal Stabilizer - Product Collector			
182A0001	Torque Box Functional Collector - Left Horizontal Stabilizer			
182A0002	Torque Box Functional Collector - Right Horizontal Stabilizer			
182A5000	Intercostal Installation - Inboard Rib, Horizontal Stabilizer			





737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Horizontal Stabilizer Inspar Intercostal Identification Figure 2





Table 2:


	LIST OF MATERIALS FOR FIGURE 2					
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY		
[1]	Intercostal (2)		BAC1506-4354 7075-T73511 extrusion as given in QQ-A-200/11			
[2]	Intercostal (3)		BAC1506-4381 7075-T73511 extrusion as given in QQ-A-200/11			
[3]	Intercostal (3)		BAC1506-4384 7075-T73511 extrusion as given in QQ-A-200/11			
[4]	Intercostal (2)		BAC1506-4352 7075-T73511 extrusion as given in QQ-A-200/11			
[5]	Intercostal (2)		BAC1506-4353 7075-T73511 extrusion as given in QQ-A-200/11			
[6]	Gusset (2)	0.063 (1.60)	2024-T42 clad sheet as given in QQ-A-250/5			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





IDENTIFICATION 1 - HORIZONTAL STABILIZER LEADING EDGE RIBS



LEADING EDGE RIB LOCATION

NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Horizontal Stabilizer Leading Edge Rib Figure 1

Table 1:

	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
186A0001	Leading Edge and Miscellaneous Functional Collector - Left Horizontal Stabilizer				
186A0002	Leading Edge and Miscellaneous Functional Collector - Right Horizontal Stabilizer				
186A1001	Leading Edge Assembly/Installation-Removable, Horizontal Stabilizer				
186A1301	Rib Assembly - Leading Edge Station 78.29				
186A1302	Rib Assembly - Leading Edge Station 86.66				
186A1303	Rib Assembly - Leading Edge Station 95.96				






REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE			
186A1304	Rib Assembly - Leading Edge Station 105.26			
186A1305	Rib Assembly - Leading Edge Station 114.55			
186A1306	Rib Assembly - Leading Edge Station 123.85			
186A1307	Rib Assembly - Leading Edge Station 133.15			
186A1308	Rib Assembly - Leading Edge Station 142.45			
186A2001	Leading Edge Installation, Fixed - Horizontal Stabilizer			
186A2002	Rib Assembly - Leading Edge Station 56.01-61.81			
186A2003	Rib Assembly - Leading Edge Station 69.93			








Horizontal Stabilizer Leading Edge Rib Location Figure 2



D634A210



737-800 STRUCTURAL REPAIR MANUAL



Removable Horizontal Stabilizer Leading Edge Rib Identification Figure 3 (Sheet 1 of 2)





737-800 STRUCTURAL REPAIR MANUAL








Table 2:


	LIST OF MATERIALS FOR FIGURE 3					
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY		
[1]	Leading Edge Rib Assembly					
	Web	0.020 (0.51)	2024-T3 clad sheet as given in QQ-A-250/5 (Bonded 2 ply 0.010 + 0.010 (0.25 mm + 0.25 mm) as given in BAC5514-5101)			
	Chord		BAC1490-2655 2024-T42 clad rolled section as given in QQ-A-250/5			
	Stiffener		BAC1503-100235 2024-T3511 extrusion as given in QQ-A-200/3			
[2]	Rib, Removable Leading Edge	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 3 FOR THE LIST OF MATERIALS.

FIXED HORIZONTAL STABILIZER LEADING EDGE RIB

Fixed Horizontal Stabilizer Leading Edge Rib Identification Figure 4



D634A210



Table 3:


	LIST OF MATERIALS FOR FIGURE 4					
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY		
[1]	Leading Edge Rib Assembly					
	Rib		7075-T7351 plate as given in QQ-A-250/12. Grain direction controlled part			
	Stiffener		BAC1503-100026 7075-T73511 extrusion as given in QQ-A-200/11			
[2]	Leading Edge Rib Assembly					
	Web	0.020 (0.51)	2024-T3 clad sheet as given in QQ-A-250/5 (Bonded 2 ply 0.010 + 0.010 (0.25 mm + 0.25 mm) as given in BAC5514-5101)			
	Chord		BAC1505-100624 2024-T42 extrusion as given in QQ-A-200/3			
	Stiffener		BAC1503-100235 2024-T3511 extrusion as given in QQ-A-200/3			
[3]	Door	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





IDENTIFICATION 2 - HORIZONTAL STABILIZER INSPAR RIBS



REFER TO FIGURE 2 FOR THI HORIZONTAL STABILIZER INSPAR RIB LOCATION

NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Horizontal Stabilizer Inspar Rib Figure 1

Table 1:

	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
182A0001	Torque Box Functional Collector - Left Horizontal Stabilizer				
182A0002	Torque Box Functional Collector - Right Horizontal Stabilizer				
182A5001	Rib Assembly/Installation Inboard Closure, Horizontal Stabilizer				
182A5002	Rib Assembly/Installation Stabilizer Station 83.50, Horizontal Stabilizer				
182A5003	Rib Assembly/Installation Transverse No. 1, Horizontal Stabilizer				
182A5004	Rib Assembly/Installation Transverse No. 2, Horizontal Stabilizer				


IDENTIFICATION 2 Page 1 Mar 10/2004



	REFERENCE DRAWINGS					
DRAWING NUMBER TITLE						
182A5005	182A5005 Rib Assembly/Installation Transverse No. 3, Horizontal Stabilizer					
182A5006 Rib Assembly/Installation Transverse No. 4, Horizontal Stabilizer						







LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE


Horizontal Stabilizer Inspar Rib Location Figure 2



Page 3

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



IDENTIFICATION 2 Page 4 Mar 10/2004



Table 2:


	LIST OF MATERIALS FOR FIGURE 3			
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Rib, Inboard Closure			
	Stiffener		AND10134-1204 7075-T6511 extrusion as given in QQ-A-200/11	
	Channel	0.090 (2.23)	2024-T42 clad sheet as given in QQ-A-250/5 and BAC 5602	
	Rib Assembly			
	Stiffener (4)		BAC1514-1681 7075-T6511 extrusion as given in QQ-A-200/11	
	Stiffener (2)		BAC1503-100028 7075-T6511 extrusion as given in QQ-A-200/11	
	Web	0.056 (1.42)	2024-T3 clad sheet as given in QQ-A-250/5.	
	Angle (2)		BAC1514-1262 7075-T6511 extrusion as given in QQ-A-200/11	
	Stiffener		BAC1506-4442 7075-T6511 extrusion as given in QQ-A-200/11	
	Upper Chord		BAC1506-4359 7075-T62 extrusion as given in QQ- A-200/11	
	Lower Chord		BAC1506-4379 7075-T62 extrusion as given in QQ- A-200/11	


*[1] Note: T = Pre-manufactured thickness in inches (millimeters).






737-800 STRUCTURAL REPAIR MANUAL









Horizontal Stabilizer Rib Identification Figure 4





Table 3:


	LIST OF MATERIALS FOR FIGURE 4			
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Rib Assembly, Stabilizer Station 83.50			
	Web	0.050 (1.27)	2024-T3 clad sheet as given in QQ-A-250/5	
	Stiffener (4)		BAC1503-100397 7075-T6511 extrusion as given in QQ-A-200/11	
	Stiffener		BAC1509-100673 7075-T6511 extrusion as given in QQ-A-200/11	
	Upper Chord		BAC1505-101674 7075-T62 extrusion as given in QQ-A-200/11	
	Lower Chord		BAC1505-101674 7075-T62 extrusion as given in QQ-A-200/11	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).



BOEING®

737-800 STRUCTURAL REPAIR MANUAL




Horizontal Stabilizer, Transverse Rib Assembly Identification Figure 5 (Sheet 1 of 4)



Page 8



737-800 STRUCTURAL REPAIR MANUAL




Horizontal Stabilizer, Transverse Rib Assembly Identification Figure 5 (Sheet 2 of 4)



 $\label{eq:BOEING PROPRIETARY - Copyright @ Unpublished Work - See title page for details$



737-800 STRUCTURAL REPAIR MANUAL








BOEING"

737-800 STRUCTURAL REPAIR MANUAL










Table 4:

		LIST OF	MATERIALS FOR FIGURE 5	
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Rib Assembly, Transverse No. 1			
	Stiffener (2)		BAC1505-23760 7075-T6511 extrusion as given in QQ-A-200/11	
	Web	0.036 (0.91)	2024-T3 clad sheet as given in QQ-A-250/5	
	Stiffener		BAC1506-4358 7075-T6511 extrusion as given in QQ-A-200/11	
	Stiffener		BAC1506-4357 7075-T6511 extrusion as given in QQ-A-200/11	
	Upper Chord		BAC1506-4359 7075-T62 extrusion as given in QQ- A-200/11	
	Lower Chord		BAC1506-4359 7075-T62 extrusion as given in QQ- A-200/11	
[2]	Rib Assembly, Transverse No. 2			
	Stiffener		BAC1503-1430 7075-T6511 extrusion as given in QQ-A-200/11	
	Web	0.036 (0.91)	2024-T3 clad sheet as given in QQ-A-250/5.	
	Stiffener (2)		BAC1505-23760 7075-T6511 extrusion as given in QQ-A-200/11	
	Upper Chord		BAC1506-4359 7075-T62 extrusion as given in QQ- A-200/11	
	Lower Chord		BAC1506-4356 7075-T62 extrusion as given in QQ- A-200/11	
[3]	Rib Assembly, Transverse No. 3			
	Stiffener		BAC1503-1430 7075-T6511 extrusion as given in QQ-A-200/11	
	Web	0.036 (0.91)	2024-T3 clad sheet as given in QQ-A-250/5	
	Stiffener (2)		BAC1505-23760 7075-T6511 Extrusion as given in QQ-A-200/11	
	Upper Chord		BAC1506-4355 7075-T62 extrusion as given in QQ- A-200/11	
	Lower Chord		BAC1506-4356 7075-T62 extrusion as given in QQ- A-200/62	
[4]	Rib Assembly, Transverse No. 4			
	Stiffener		BAC1503-100277 7075-T6511 extrusion as given in QQ-A-200/11	
	Stiffener		BAC1503-1430 7075-T6511 extrusion as given in QQ-A-200/11	
	Doubler	0.050 (1.27)	2024-T3 clad sheet as given in QQ-A-250/5	
	Web	0.036 (0.91)	2024-T3 clad sheet as given in QQ-A-250/5	
	Upper Chord		BAC1505-101662 7075-T62 extrusion as given in QQ-A-200/11	

IDENTIFICATION 2 Page 12 Mar 10/2004




LIST OF MATERIALS FOR FIGURE 5				
ITEM	DESCRIPTION	T*[1]	MATERIAL	EFFECTIVITY
	Lower Chord		BAC1506-4355 7075-T62 extrusion as given in QQ- A-200/11	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 5 FOR THE LIST OF MATERIALS.

INSPAR RIB ASSEMBLIES

Horizontal Stabilizer Inspar Rib Identification Figure 6



D634A210

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details




Table 5:


	LIST OF MATERIALS FOR FIGURE 6			
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Rib Fitting		7075-T7351 plate as given in QQ-A-250/12. Refer to the production drawing for the machined thicknesses	
			(Optional: 7050-T7451 plate as given in AMS 4050)	YA001 to YA003
[1]	Rib Fitting		7075-T7351 plate as given in QQ-A-250/12. Refer to the production drawing for the machined thicknesses	
[2]	Rib Fitting		7050-T7451 plate as given in AMS 4050. Refer to the production drawing for machined thicknesses. Refer to Figure 6 for an example of a typical machined rib	
[3]	Rib Fitting		7050-T7451 plate as given in BMS 7-323, Type I. Refer to the production drawing for machined thicknesses	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).









Machined Thicknesses For Figure 6, Item [2] Figure 7




D634A210

BOEING PROPRIETARY - Copyright ${\rm (\sc)}$ Unpublished Work - See title page for details



IDENTIFICATION 3 - HORIZONTAL STABILIZER TRAILING EDGE RIBS



REFER TO FIGURE 2 FOR THE HORIZONTAL STABILIZER TRAILING EDGE RIB LOCATIONS

NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Horizontal Stabilizer Trailing Edge Rib Figure 1

Table 1:

	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
185A0001	Trailing Edge Functional Collector - Left, Horizontal Stabilizer				
185A0002	Trailing Edge Functional Collector - Right, Horizontal Stabilizer				
185A1200	Support Installation - Trim Tab Lock, Horizontal Stabilizer				
185A1310	Rib Installation - Trailing Edge, Elevator Station 23.04 - 24.90				
185A1320	Rib Installation - Trailing Edge, Elevator Station 39.02				
185A1330	Rib Installation - Trailing Edge, Elevator Station 66.54				


IDENTIFICATION 3 Page 1 Mar 10/2004



	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
185A1340	Rib Installation - Trailing Edge, Elevator Station 94.07				
185A1350	Rib Installation - Trailing Edge, Elevator Station 121.59				
185A1360	Rib Installation - Trailing Edge, Elevator Station 149.12				
185A1370	Rib Installation - Trailing Edge, Elevator Station 176.64				
185A1410	Rib Installation - Trailing Edge, Elevator Station 195.00				
185A1420	Rib Installation - Trailing Edge, Elevator Station 213.32				
185A1430	Rib Installation - Trailing Edge, Elevator Station 231.70				
185A1440	Rib Installation - Trailing Edge, Elevator Station 250.04				
185A1450	Rib Installation - Trailing Edge, Elevator Station 265.45				
185A1610	Chord Installation - Trailing Edge, Horizontal Stabilizer				







LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Horizontal Stabilizer Trailing Edge Rib Location Figure 2




Page 3

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details

BOEING®

737-800 STRUCTURAL REPAIR MANUAL





NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Horizontal Stabilizer Trailing Edge Rib Identification Figure 3





Table 2:

	1		MATERIALS FOR FIGURE 3	
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Support Chord, Trim Tab		BAC1506-4461 7075-T3511 extrusion as given in QQ-A-200/11	
[2]	Rib Assembly, Elevator Station 23.04			
	Access Door	0.063 (1.60)	2024-T3 clad sheet as given in QQ-A-250/5	
	Rib Fitting		7050-T7451 plate as given in BMS 7-323, Type I. Refer to the production drawing for the machined thicknesses. Refer to Figure 3 for an example of a typical machined rib	
[3]	Rib Fitting, Elevator Stations 39.02 and 66.54		7050-T7451 plate as given in BMS 7-323, Type I. (Grain direction controlled part) Refer to the production drawing for machined thicknesses	
[4]	Rib Fitting, Elevator Stations 195.00, 231.70 and 265.45		7050-T7451 plate as given in AMS 4050. (Grain direction controlled part) Refer to the production drawing for machined thicknesses	
[5]	Rib Assembly, Elevator Stations 94.07 and 149.12			
	Web Assembly			
	Core	0.200 (5.08)	Aluminum honeycomb core as given in BMS 4-4, Type 3-10ND, Grade 1, Form B	
	Pan	0.020 (0.51)	2024-T42 clad sheet as given in QQ-A-250/5	
	Doubler	0.012 (3.05)	2024-T3 clad sheet as given in QQ-A-250/5	
	Face Panel	0.020 (0.51)	2024-T3 clad sheet as given in QQ-A-250/5	
	Rib Fitting		7050-T7451 plate as given in AMS 4050. (Grain direction direction controlled part) Refer to the production drawing for machined thicknesses	
[6]	Rib Assembly, Elevator Station 121.59			
	Web Assembly			
	Core	0.200 (5.08)	Aluminum honeycomb core as given in BMS 4-4, Type 3-10ND, Grade 1, Form B	
	Pan	0.020 (0.51)	2024-T42 clad sheet as given in QQ-A-250/5	
	Doubler	0.012 (3.05)	2024-T3 clad sheet as given in QQ-A-250/5	
	Face Panel	0.020 (0.51)	2024-T3 clad sheet as given in QQ-A-250/5	
	Rib Fitting		7050-T7451 plate as given in BMS 7-323, Type I. (Grain direction controlled part) Refer to the production drawing for machined thicknesses	
[7]	Rib Assembly, Elevator Stations 176.64 and 250.04			
	Rib Fitting		7050-T7451 plate as given in BMS 7-323, Type I. (Grain direction controlled part) Refer to the production drawing for machined thicknesses	
	Clevis Fitting		BAC1507-48859 7075-T73511 extrusion as given in QQ-A-200/11	
[8]	Rib Assembly, Elevator Station 213.32			


IDENTIFICATION 3 Page 5 Nov 01/2003



	LIST OF MATERIALS FOR FIGURE 3			
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
	Rib Fitting		7050-T7451 plate as given in AMS 4050. (Grain direction controlled part) Refer to the production drawing for machined thicknesses	
	Clevis Fitting		BAC1507-48859 7075-T73511 extrusion as given in QQ-A-200/11	
[9]	Upper Chord		BAC1505-101654 7075-T73511 extrusion as given in QQ-A-200/11	
[10]	Lower Chord		BAC1505-101654 7075-T73511 extrusion as given in QQ-A-200/11	

*[1] T = Pre-manufactured thickness in inches (millimeters).












IDENTIFICATION 1 - HORIZONTAL STABILIZER FRONT SPAR STRUCTURE



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Horizontal Stabilizer Front Spar Structure Location Figure 1


	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
182A0001	Torque Box Functional Collector - Left Horizontal Stabilizer				
182A0002	Torque Box Functional Collector - Right Horizontal Stabilizer				
182A2401	Front Spar Assembly/Installation-Horizontal Stabilizer				
001A8001	Section 82 Left Horizontal Stabilizer - Product Collector				
001A8002	Section 82 Right Horizontal Stabilizer - Product Collector				







737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Horizontal Stabilizer Front Spar Structure Identification Figure 2






Table 2:

	LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T*[1]	MATERIAL	EFFECTIVITY	
[1]	Web		7075-T7351 plate as given in QQ-A-250/12. Refer to Figure 3 for the machined thicknesses		
[2]	Web	0.080 (2.03)	7075-T62 clad sheet as given in QQ-A-250/13		
[3]	Web	0.063 (1.60)	7075-T6 clad sheet as given in QQ-A-250/13		
[4]	Web	0.056 (1.42)	7075-T6 clad sheet as given in QQ-A-250/13		
[5]	Web	0.050 (1.27)	7075-T6 clad sheet as given in QQ-A-250/13		
[6]	Web	0.032 (0.81)	7075-T6 clad sheet as given in QQ-A-250/13		
[7]	Stiffener		BAC1506-4367 7075-T73511 extrusion as given in QQ-A-200/11		
[8]	Stiffener		BAC1506-4343 7075-T73511 extrusion as given in QQ-A-200/11		
[9]	Stiffener		BAC1506-4342 7075-T73511 extrusion as given in QQ-A-200/11		
[10]	Stiffener		BAC1506-4351 7075-T73511 extrusion as given in QQ-A-200/11		
[11]	Stiffener		BAC1506-4380 7075-T73511 extrusion as given in QQ-A-200/11		
[12]	Stiffener		BAC1506-4328 7075-T73511 extrusion as given in QQ-A-200/11		
[13]	Stiffener		BAC1506-4329 7075-T73511 extrusion as given in QQ-A-200/11		
[14]	Stiffener		BAC1506-4327 7075-T73511 extrusion as given in QQ-A-200/11		
[15]	Fitting		7050-T7451 plate as given in AMS 4050		
[16]	Upper Spar Chord		BAC1506-4432 7150-T77511 ex- trusion as given in BMS 7-306		
[17]	Lower Spar Chord		BAC1506-4431 7150-T77511 ex- trusion as given in BMS 7-306		


*[1] Note: T = Pre-manufactured thickness in inches (millimeters).












Machined Areas of Figure 2, Item [1] Figure 3





IDENTIFICATION 2 - HORIZONTAL STABILIZER REAR SPAR STRUCTURE



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Horizontal Stabilizer Rear Spar Structure Location Figure 1


Table 1:

	REFERENCE DRAWINGS			
DRAWING NUMBER	TITLE			
001A8001	Section 82 Left Horizontal Stabilizer - Product Collector			
001A8002	Section 82 Right Horizontal Stabilizer - Product Collector			
182A1500	Rear Spar Assembly/Installation - Horizontal Stabilizer			
185A0001	Trailing Edge Functional Collector - Left, Horizontal Stabilizer			
185A0002	Trailing Edge Functional Collector - Right, Horizontal Stabilizer			





737-800 STRUCTURAL REPAIR MANUAL



VIEW LOOKING FORWARD

NOTES


• REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Horizontal Stabilizer Rear Spar Structure Identification Figure 2 (Sheet 1 of 2)





737-800 STRUCTURAL REPAIR MANUAL



Horizontal Stabilizer Rear Spar Structure Identification Figure 2 (Sheet 2 of 2)





Table 2:

	LIST OF MATERIALS FOR FIGURE 2					
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY		
[1]	Web - Inboard	0.125 (3.18)	7075-T6 sheet as given in QQ-A-250/12. Refer to Figure 3 for chem-mill thicknesses			
[2]	Web - Outboard	0.040 (1.02)	7075-T6 sheet as given in QQ-A-250/12. Refer to Figure 4 for chem-mill thicknesses			
[3]	Chord - Upper		BAC1506-4318 2024-T3511 extrusion as given in QQ-A-200/3			
[4]	Chord - Lower		BAC1506-4341 7150-T77511 extrusion as given in BMS7-306			
[5]	Chord - Failsafe		BAC1520-2787 7150-T77511 extrusion as given in BMS7-306			
[6]	Stiffener (2)		BAC1505-100416 7075-T6511 extrusion as given in QQ-A-200/11			
[7]	Stiffener (2)		BAC1506-4418 7075-T6511 extrusion as given in QQ-A-200/11			
[8]	Stiffener (2)		BAC1506-4415 7075-T6511 extrusion as given in QQ-A-200/11			
[9]	Stiffener (2)		BAC1506-4419 7075-T6511 extrusion as given in QQ-A-200/11			
[10]	Stiffener		BAC1506-4420 7075-T6511 extrusion as given in QQ-A-200/11			
[11]	Stiffener (3)		BAC1506-4421 7075-T6511 extrusion as given in QQ-A-200/11			
[12]	Stiffener (2)		BAC1506-4422 7075-T6511 extrusion as given in QQ-A-200/11			
[13]	Stiffener		BAC1506-4423 7075-T6511 extrusion as given in QQ-A-200/11			
[14]	Stiffener		BAC1506-4424 7075-T6511 extrusion as given in QQ-A-200/11			
[15]	Stiffener		BAC1506-4425 7075-T6511 extrusion as given in QQ-A-200/11			
[16]	Stiffener (4)		BAC1505-101672 7075-T6511 extrusion as given in QQ-A-200/11			
[17]	Stiffener (2)		BAC1503-101038 7075-T6511 extrusion as given in QQ-A-200/11			
[18]	Stiffener (2)		BAC1503-101039 7075-T6511 extrusion as given in QQ-A-200/11			
[19]	Stiffener		BAC1506-4426 7075-T6511 extrusion as given in QQ-A-200/11			
[20]	Stiffener		BAC1505-101673 7075-T6511 extrusion as given in QQ-A-200/11			
[21]	Stiffener		BAC1514-3284 7075-T6511 extrusion as given in QQ-A-200/11			
[22]	Stiffener (6)		BAC1506-4427 7075-T6511 extrusion as given in QQ-A-200/11			

IDENTIFICATION 2 Page 4 Nov 01/2003




	LIST OF MATERIALS FOR FIGURE 2					
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY		
[23]	Stiffener (4)		BAC1506-4428 7075-T6511 extrusion as given in QQ-A-200/11			
[24]	Stiffener		BAC1506-4429 7075-T6511 extrusion as given in QQ-A-200/11			
[25]	Stiffener		BAC1506-4417 7075-T6511 extrusion as given in QQ-A-200/11			
[26]	Stiffener		BAC1506-4430 7075-T6511 extrusion as given in QQ-A-200/11			
[27]	Fitting (2)		7075-T7351 plate as given in QQ-A-250/12			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).








Chem-Milled Areas of Figure 2, Item [1] Figure 3



BOEING®



INBD 🧲

Chem-Milled Areas of Figure 2, Item [2] Figure 4




D634A210

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



IDENTIFICATION 3 - HORIZONTAL STABILIZER CENTER SECTION SPAR STRUCTURE



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Horizontal Stabilizer Center Section Spar Structure Locations Figure 1


Table 1:

	REFERENCE DRAWINGS		
DRAWING NUMBER	TITLE		
001A4001	Fuselage Product Collector		
140A0810	Center Section Functional Collector Horizontal Tail		
181A1000	Rear Spar Installation, Center Section, Horizontal Stabilizer		
181A1110	81A1110 Rear Spar Fitting - Upper, Center Section Horizontal Tail		
181A1120	Rear Spar Fitting - Center Section Horizontal Tail		
181A2000	Front Spar Installation - Center Section Horizontal Tail		





737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Horizontal Stabilizer Forward Center Section Spar Structure Identification Figure 2



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details




Table 2:

LIST OF MATERIALS FOR FIGURE 2					
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY	
[1]	Front Spar Fitting		7050-T74 die forging as given in BMS 7-214		

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).







NOTE: REFER TO TABLE 3 FOR THE LIST OF MATERIALS.

Horizontal Stabilizer Aft Center Section Spar Structure Identification Figure 3





Table 3:

LIST OF MATERIALS FOR FIGURE 3				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Rear Spar Fitting - Upper		Ti-6AI-4V titanium forging as given in BMS 7-247	
[2]	Rear Spar Fitting - Lower		7050-T74 forging as given in BMS 7-214	
[3]	Web-Splice	0.125 (3.18)	Ti-6AI-4V titanium sheet as given in MIL-T-9046, Code AB-1, in the annealed condition	
[4]	Upper and Lower Brace Fitting (LH and RH)		7050-T7451 plate as given in BMS 7-323, Type I	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).






ALLOWABLE DAMAGE 1 - HORIZONTAL STABILIZER FRONT SPAR

1. Applicability

A. This subject gives the allowable damage limits for the horizontal stabilizer front spar shown in Horizontal Stabilizer Front Spar Location, Figure 101/ALLOWABLE DAMAGE 1 and Horizontal Stabilizer Front Spar Structure and Allowable Damage Zones, Figure 102/ALLOWABLE DAMAGE 1.




Horizontal Stabilizer Front Spar Location Figure 101





737-800 STRUCTURAL REPAIR MANUAL



NOTE: ALL PARTS IDENTIFIED ARE MADE OF ALUMINUM.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Horizontal Stabilizer Front Spar Structure and Allowable Damage Zones Figure 102

> ALLOWABLE DAMAGE 1 Page 102 55-10-10 Nov 01/2003



2. General

A. Refer to Table 101/ALLOWABLE DAMAGE 1 for the references of the allowable damage limits.

Table 101:					
PARAGE	APH REFEREN	CES FOR THE ALLOWABLE DAMAGE LIMITS			
TYPE OF STRUCTURE ZONE STABILIZER STATION PARAGRAPH					
Upper Chord	1	258.28 and inboard	4.A		
	2	258.28 and outboard	4.		
Lower Chord	3	92.70 and inboard 258.28 and outboard	4.C		
	4	258.28 to 166.30	4.D		
	5	166.30 to 92.70	4.E		
Webs		All	4.F		
Stiffeners		All	4.G		

- B. Remove the damage as necessary.
 - (1) Refer to 51-10-02 for the inspection and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
- C. After you remove the damage, do the procedures that follow.

WARNING: MAKE SURE THAT YOU WEAR EYE PROTECTION WHEN YOU USE THE FLAP PEEN WHEEL. IF YOU DO NOT OBEY, AN INJURY CAN OCCUR.

- (1) Flap peen or shot peen the surfaces of the upper and lower chords if you remove the damage.
 - (a) Refer to 51-20-06 for shot peen intensity and shot number.
 - (b) Refer to SOPM 20-10-03 for flap peen and shot peen procedures.
- (2) Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to 51-20-01.
- (3) Apply two layers of BMS 10-79, Type III, primer to the reworked areas of the upper and lower chords. Refer to SOPM 20-44-04.
- (4) Apply one layer of BMS 10-11, Type I, primer to the reworked areas of the stiffeners and the webs. Refer to SOPM 20-41-02.

3. References

Reference	Title
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05, GENERAL	Repair Sealing
51-20-06	SHOT PEENING
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS





(Continued)

Reference	Title
AMM 51-21-00 P/B 701	INTERIOR AND EXTERIOR FINISHES - CLEANING/PAINTING
SOPM 20-10-03	General - Shot Peening Procedures
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Allowable Damage Limits

- A. Upper Chord Zone 1
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A, B, C, D, E, and F.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- B. Upper Chord Zone 2
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A, B, C, D, E, and F.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- C. Lower Chord Zone 3
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A, B, C, D, E, and F.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- D. Lower Chord Zone 4
 - (1) Cracks are not permitted.
 - (2) Nicks, Gouges, Scratches and Corrosion are not permitted.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- E. Lower Chord Zone 5





- (1) Cracks are not permitted.
- (2) Nicks, Gouges, Scratches and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details D, E, and F.
- (3) Dents are not permitted.
- (4) Holes and Punctures are not permitted.


F. Webs

- (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A, B, and G.
- (2) Nicks, Gouges, Scratches and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A, B, D, F, G, and I.
- (3) Dents are permitted as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Detail H.
- (4) Holes and Punctures are permitted if:
 - (a) They are a maximum of 0.25 inch (6.4 mm) in diameter
 - (b) They are a minimum of 4D (D = the diameter of the damage) away from a hole, a part edge, or other damage
 - (c) They are filled with a 2117-T3 or 2117-T4 aluminum protruding head rivet.
 - 1) Install the rivet without sealant.
 - (d) There is not more than two holes or punctures in each bay between two stiffeners.
- G. Stiffeners
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A, B, C, D, E, and F.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.



BOEING


737-800 STRUCTURAL REPAIR MANUAL





737-800 STRUCTURAL REPAIR MANUAL


THE REMOVAL OF MATERIAL AROUND THREE FASTENERS IN ALL GROUPS OF TEN IS PERMITTED TO A MAXIMUM DEPTH OF X



REMOVE THE FASTENERS BEFORE THE DAMAGE IS REMOVED. INSTALL THE FASTENERS AFTER THE DAMAGE IS REMOVED

REMOVAL OF DAMAGE AROUND THE FASTENERS ON AN EDGE OR A SURFACE






A-A

Allowable Damage Limits Figure 103 (Sheet 2 of 8)






Allowable Damage Limits Figure 103 (Sheet 3 of 8)





737-800 STRUCTURAL REPAIR MANUAL




DEPTH OF THE REMOVED MATERIAL				
TYPE OF STRUCTURE ZONE MAXIMUM PERCENT OF THE INITIAL THICK				
UPPER CHORD	1	10		
UPPER CHURD	2	10		
	3	10		
LOWER CHORD	4	NO DAMAGE PERMITTED		
	5	5		
WEB	-	15		
STIFFENERS	-	10		

TABLE 102

Allowable Damage Limits Figure 103 (Sheet 4 of 8)






ALLOWABLE DAMAGE 1 55-10-10 Page 110 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



H = HEIGHT OF THE WEB

ОUTBD

ZONE A: NO HOLE DAMAGE PERMITTED


REMOVAL OF DAMAGED MATERIAL FROM A WEB

Allowable Damage Limits Figure 103 (Sheet 6 of 8)





737-800 STRUCTURAL REPAIR MANUAL



 $D_1 = DIAMETER OF THE INITIAL FASTENER HOLE$ J = HEIGHT OF THE WEB IN SECTION D-DT = THICKNESS OF THE WEB $<math>A_1 = INITIAL AREA OF THE WEB$ = THE TOTAL CROSS-SECTIONAL AREA MINUS THE CROSS-SECTIONAL AREA OF THE INITIALHOLES (AS MANUFACTURED BY BOEING) $<math>= JT - D_1T$ $A_1 = CROSS-SECTIONAL AREA OF THE DAMAGE THAT IS REMOVED AT LOCATION 1$ (A_1)

$$\left(\frac{1}{A_{i}}\right)$$
 X 100 = PERCENT OF CROSS-SECTIONAL AREA REMOVED
= A MAXIMUM OF 10 PERCENT

THE TOTAL CROSS-SECTIONAL AREA REMOVED IN ALL ZONES A-B (1.00 INCH (25.4 mm) ON EACH SIDE OF A LINE A-B) MUST NOT BE MORE THAN 10 PERCENT OF THE INITIAL AREA OF THE WEB.


D-D

Allowable Damage Limits Figure 103 (Sheet 7 of 8)





737-800 STRUCTURAL REPAIR MANUAL



Allowable Damage Limits Figure 103 (Sheet 8 of 8)






ALLOWABLE DAMAGE 2 - HORIZONTAL STABILIZER REAR SPAR

1. Applicability

A. This subject gives the allowable damage limits for the horizontal stabilizer rear spar shown in Horizontal Stabilizer Rear Spar Location, Figure 101/ALLOWABLE DAMAGE 2 and Horizontal Stabilizer Rear Spar Structure and Allowable Damage Zones, Figure 102/ALLOWABLE DAMAGE 2.




Horizontal Stabilizer Rear Spar Location Figure 101





737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

NOTES

- ALL PARTS IDENTIFIED ARE MADE OF ALUMINUM.
- ZONES 1, 2, 3, 4 AND 5 ARE APPLICABLE TO THE UPPER CHORD.
- ZONES 6,7,8,9, and 10 ARE APPLICABLE TO THE LOWER CHORD.
- ZONES 11 AND 12 ARE APPLICABLE TO THE FAILSAFE CHORD.

Horizontal Stabilizer Rear Spar Structure and Allowable Damage Zones Figure 102 (Sheet 1 of 2)





737-800 STRUCTURAL REPAIR MANUAL




Figure 102 (Sheet 2 of 2)

ALLOWABLE DAMAGE 2 **55-10-10**Page 103 Nov 01/2003



2. General

A. Refer to Table 101/ALLOWABLE DAMAGE 2 for the references of the allowable damage limits.

PARAGRAPH REFERENCES FOR THE ALLOWABLE DAMAGE LIMITS				
TYPE OF STRUCTURE	ZONE	STABILIZER STATION	PARAGRAPH	
Upper Chord	1	68.87 thru 83.50	4.A	
	2	83.50 thru 157.10	4.A	
	3	157.10 thru 193.90	4.A	
	4	193.90 thru 285.90	4.A	
	5	285.90 and outboard	4.A	
Lower Chord	6	68.87 thru 221.50	4.B	
	7	221.50 thru 230.70	4.B	
	8	230.70 thru 258.28	4.B	
	9	258.28 thru 285.90	4.B	
	10	285.90 and outboard	4.B	
Failsafe Chord	11	68.87 thru 111.10	4.C	
	12	111.10 thru 204.11	4.C	
Webs		All	4.D	
Stiffeners, Fitting		All	4.E	

- B. Remove the damage as necessary.
 - (1) Refer to 51-10-02 for the inspection and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
- C. After you remove the damage, do the procedures that follow.

WARNING: MAKE SURE THAT YOU WEAR EYE PROTECTION WHEN YOU USE THE FLAP PEEN WHEEL. IF YOU DO NOT OBEY, AN INJURY CAN OCCUR.

- (1) Flap peen or shot peen the surfaces of the upper and lower chords if you remove the damage.
 - (a) Refer to 51-20-06 for shot peen intensity and shot number.
 - (b) Refer to SOPM 20-10-03 for flap peen and shot peen procedures.
- (2) Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to 51-20-01.
- (3) Apply two layers of BMS 10-79, Type III, primer to the reworked areas of the upper and lower chords. Refer to SOPM 20-44-04.
- (4) Apply one layer of BMS 10-11, Type I, primer to the reworked areas of the stiffeners, fitting, and the webs. Refer to SOPM 20-41-02.





3. References

Reference	Title
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05, GENERAL	Repair Sealing
51-20-06	SHOT PEENING
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
AMM 51-21-00 P/B 701	INTERIOR AND EXTERIOR FINISHES - CLEANING/PAINTING
SOPM 20-10-03	General - Shot Peening Procedures
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Allowable Damage Limits

- A. Upper Chord Zones 1 thru 5
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Details A, B, C, D, E, and F.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- B. Lower Chord Zones 6 thru 10
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Details A, B, C, D, E, and F.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- C. Failsafe Chord Zones 11 and 12
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Details A, B, C, D, E, and F.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.






D. Webs

- (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Details A, B, and G.
- (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Details A, B, D, F, G d I.
- (3) Dents are permitted as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Detail H.
- (4) Holes and Punctures are permitted if:
 - (a) They are a maximum of 0.25 inch (6.4 mm) in diameter
 - (b) They are a minimum of 4D (D = the diameter of the damage) away from a hole, a part edge, or other damage
 - (c) They are filled with a 2117-T3 or 2117-T4 aluminum protruding head rivet
 - 1) Install the rivet without sealant.
 - (d) There is not more than two holes or punctures in each bay between two stiffeners.
- E. Stiffeners and Fittings
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Details A, B, C, D, E, and F.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are permitted as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Detail J.



BOEING


737-800 STRUCTURAL REPAIR MANUAL





737-800 STRUCTURAL REPAIR MANUAL


THE REMOVAL OF MATERIAL AROUND THREE FASTENERS IN ALL GROUPS OF TEN IS PERMITTED TO A MAXIMUM DEPTH OF X



REMOVE THE FASTENERS BEFORE THE DAMAGE IS REMOVED. INSTALL THE FASTENERS AFTER THE DAMAGE IS REMOVED

REMOVAL OF DAMAGE AROUND THE FASTENERS ON AN EDGE OR A SURFACE


D



A-A


Allowable Damage Limits Figure 103 (Sheet 2 of 10)





BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details

737-800 STRUCTURAL REPAIR MANUAL



Allowable Damage Limits Figure 103 (Sheet 4 of 10)





DEPTH OF THE REMOVED MATERIAL				
TYPE OF STRUCTURE ZONE		MAXIMUM PERCENT OF THE INITIAL THICKNESS AS GIVEN BY THE NOMINAL THICKNESS ON THE PRODUCTION DRAWING		
	1	DAMAGE THAT CAN NOT BE MEASURED		
	2	3		
UPPER CHORD	3	5		
	4	10		
	5	20		
	6	10		
	7	5		
LOWER CHORD	8	DAMAGE THAT CAN NOT BE MEASURED		
	9	5		
	10	20		
	11	20		
FAILSAFE CHORD	12	5		
	BAYS 1 THRU 6	20		
	BAY 7	2		
INBOARD WEB 1	BAY 8	4		
	BAYS 9 THRU 21	20		
OUTBOARD WEB	-	20		
STIFFENERS	-	20		
FITTING	-	10		


TABLE 102

NOTES

1 WEB BAYS 1 THRU 6 ARE BETWEEN STAB STAS 68.87 AND 111.10 WEB BAY 7 IS BETWEEN STAB STAS 111.10 AND 120.30 WEB BAY 8 IS BETWEEN STAB STAS 120.30 AND 129.50 WEB BAYS 9 THRU 21 ARE BETWEEN STAB STAS 129.50 AND 249.10

> Allowable Damage Limits Figure 103 (Sheet 5 of 10)









737-800 STRUCTURAL REPAIR MANUAL





Figure 103 (Sheet 7 of 10)





737-800 STRUCTURAL REPAIR MANUAL



 D_1 , D_3 = DIAMETERS OF THE INITIAL FASTENER HOLES D_2 = DIAMETER OF THE HOLE WHERE THERE IS DAMAGE H = HEIGHT OF THE WEB AT THE CROSS-SECTION T = THICKNESS OF THE WEB AS GIVEN BY THE NOMINAL THICKNESS ON THE PRODUCTION DRAWING A_1 = INITIAL AREA OF THE WEB = THE TOTAL CROSS-SECTIONAL AREA MINUS THE CROSS-SECTIONAL AREA OF THE INITIAL FASTENERS HOLES (AS MANUFACTURED BY BOEING) = HT - D_1 T - D_3 T A_1 = CROSS-SECTIONAL AREA OF THE DAMAGE THAT IS REMOVED AT LOCATION 1 A_2 = CROSS-SECTIONAL AREA OF THE DAMAGE THAT IS REMOVED AT LOCATION 2

 $\begin{pmatrix} \frac{n_1 \cdot n_2}{A_1} \end{pmatrix}$ X 100 = PERCENT OF CROSS-SECTIONAL AREA REMOVED = A MAXIMUM OF 20 PERCENT

THE TOTAL CROSS-SECTIONAL AREA REMOVED IN ALL ZONES A-B (1.00 INCH (25.4 mm) ON EACH SIDE OF A LINE A-B) MUST NOT BE MORE THAN 20 PERCENT OF THE INITIAL AREA OF THE WEB


D-D

Allowable Damage Limits Figure 103 (Sheet 8 of 10)





737-800 STRUCTURAL REPAIR MANUAL



 D_1 , D_4 = DIAMETERS OF THE INITIAL FASTENER HOLES D_2 , D_3 = DIAMETERS OF THE HOLES WHERE THERE IS DAMAGE L = LENGTH OF THE WEB AT THE CROSS-SECTION BETWEEN POINTS C AND D T = THICKNESS OF THE WEB AS GIVEN BY THE NOMINAL THICKNESS ON THE PRODUCTION DRAWING A_1 = INITIAL AREA OF THE WEB = THE TOTAL CROSS-SECTIONAL AREA MINUS THE CROSS-SECTIONAL AREA OF THE INITIAL FASTENERS HOLES (AS MANUFACTURED BY BOEING) = HT - D_1 T - D_4 T A_1 = CROSS-SECTIONAL AREA OF THE DAMAGE THAT IS REMOVED AT LOCATION 1 A_2 = CROSS-SECTIONAL AREA OF THE DAMAGE THAT IS REMOVED AT LOCATION 2 A_3 = CROSS-SECTIONAL AREA OF THE DAMAGE THAT IS REMOVED AT LOCATION 3 $\left(\frac{A_1 + A_2 + A_3}{A_1}\right) \times 100$ = PERCENT OF CROSS-SECTIONAL AREA REMOVED = A MAXIMUM OF 20 PERCENT THE TOTAL CROSS-SECTIONAL AREA REMOVED IN ALL ZONES C-D (1.00 INCH (25.4 mm) ON

EACH SIDE OF A LINE C-D) MUST NOT BE MORE THAN 20 PERCENT OF THE INITIAL AREA OF THE WEB


E-E

Allowable Damage Limits Figure 103 (Sheet 9 of 10)





737-800 STRUCTURAL REPAIR MANUAL



W = THE WIDTH OF THE STIFFENER FLANGE

HOLES THAT ARE PERMITTED TO REMOVE DAMAGED MATERIAL IN WEB STIFFENERS

> Allowable Damage Limits Figure 103 (Sheet 10 of 10)







REPAIR 1 - HORIZONTAL STABILIZER FRONT SPAR WEB

1. Applicability

- A. Repair 1 is applicable to damage to the web of the horizontal stabilizer front spar shown in Horizontal Stabilizer Front Spar Location, Figure 201/REPAIR 1 if:
 - (1) The damage is between Stabilizer Stations 111.10 and 175.50.





LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Horizontal Stabilizer Front Spar Location Figure 201



REPAIR 1 Page 202 Nov 01/2003



2. General

- A. Repair 1 gives instructions for a Category A repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.

3. <u>References</u>

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-40-00, GENERAL	Fasteners
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-40-05	FASTENER HOLE SIZES
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
51-70-09	BONDED METAL STRUCTURE REPAIR PROCEDURES
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes

4. Repair Instructions

- A. Remove initial fasteners from skin assemblies as necessary to get access to the damaged area of the web. Refer to 51-40-02.
- B. Drill a stop hole at the ends of all web cracks that do not end at fastener holes. Refer to Horizontal Stabilizer Front Spar Web Repair, Figure 202/REPAIR 1 and SRM 51-10-02 for the procedures to drill a stop hole. For other damage, do what follows:
 - Cut and remove the damaged part of the web as shown in Horizontal Stabilizer Front Spar Web Repair, Figure 202/REPAIR 1. Refer to 51-10-02 for the procedures to remove the damage.
- C. Remove the initial web fasteners and stiffeners as necessary for the repair.
- D. Make the repair part as shown in Horizontal Stabilizer Front Spar Web Repair, Figure 202/REPAIR
 1. Refer to Table 201/REPAIR 1 for the repair material.

REPAIR MATERIAL			
ITEM	PART	QUANTITY	MATERIAL
[1]	Doubler	1	Use clad or bare 7075-T6 that is 0.100 inch thick. The use of clad material is recommended. It is permitted to make the repair part from 7075-T6 plate

Table 201:

E. Assemble the repair part as shown in Horizontal Stabilizer Front Spar Web Repair, Figure 202/REPAIR 1.








- F. Drill the fastener holes. Refer to 51-40-05 for the fastener hole dimensions.
- G. Remove the repair part.
- H. Remove the nicks, scratches, gouges, burrs, and sharp edges from the repair part and the bare surfaces of the web.
- I. Apply a chemical conversion coating to the repair part and bare surfaces of the web. Refer to 51-20-01 for the chemical conversion coating procedures.
- J. Apply one layer of BMS 10-11, Type I, primer to the area of the repair. Refer to SOPM 20-41-02 for the procedures to apply the primer.
 - (1) Apply the primer to the repair part.
 - (2) Apply the primer to the bare surfaces of the web.
- K. Install the repair part with BMS 5-95 sealant between the mating surfaces. Refer to 51-20-05 for the procedures to apply the sealant.
 - (1) It is optional to bond the repair part to the initial web as given in 51-70-09. This option will increase the fatigue life of the repair.
- L. Install the initial web stiffeners.
- M. Install the fasteners.
 - (1) Install the hex drive fasteners wet with BMS 5-95 sealant in transition fit holes.
 - (2) Install the rivets at the initial locations without sealant.
- N. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.
- O. Install the skin assemblies if they were removed.



REPAIR 1 Page 204 Nov 10/2007



737-800 STRUCTURAL REPAIR MANUAL



NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENER.
- 1 MAKE SURE THAT THERE IS A MINIMUM OF THREE FULL VERTICAL ROWS OF FASTENERS ON EACH SIDE OF THE DAMAGED AREA.
- 2 PUT THE LAST ROW OF FASTENERS AWAY FROM A STIFFENER.

FASTENER SYMBOLS


- ➡ REPAIR FASTENER LOCATION. INSTALL A BACB30VT8K() OR BACB30FM8A() HEX DRIVE BOLT. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.

Horizontal Stabilizer Front Spar Web Repair Figure 202 (Sheet 1 of 3)



REPAIR 1 Page 205 Nov 01/2003





REPAIR SHOWN WITH THE BEST FLANGE FOR THE DOUBLER $\ensuremath{\mathsf{A-A}}$


Horizontal Stabilizer Front Spar Web Repair Figure 202 (Sheet 2 of 3)



REPAIR 1 Page 206 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



REPAIR SHOWN WITH OPTIONAL MACHINED DOUBLER


Horizontal Stabilizer Front Spar Web Repair Figure 202 (Sheet 3 of 3)



REPAIR 1 Page 207 Nov 01/2003



IDENTIFICATION 1 - HORIZONTAL STABILIZER BEAM



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Horizontal Stabilizer Beam Location Figure 1


Table 1:

REFERENCE DRAWINGS		
DRAWING NUMBER	TITLE	
185A0001	Trailing Edge Functional Collector - Left, Horizontal Stabilizer	
185A0002	Trailing Edge Functional Collector - Right, Horizontal Stabilizer	
185A1600	Beam Installation - Trailing Edge, Horizontal Stabilizer	



BOEING

737-800 STRUCTURAL REPAIR MANUAL



THE LEFT HORIZONTAL STABILIZER BEAM IS SHOWN, THE RIGHT HORIZONTAL STABILIZER BEAM IS OPPOSITE

NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Horizontal Stabilizer Beam Identification Figure 2



Page 2



Table 2:


	LIST OF MATERIALS FOR FIGURE 2			
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Upper Beam Assembly			
	Upper Beam		BAC1506-4398 7075-T73511 extrusion as given in QQ-A-200/11	Cum Line numbers 1 thru 215
	Upper Beam (Angle)		7050-T7451 plate as given in AMS 4050	
	Upper Beam Assembly Upper Beam		BAC1506-4398 7075-T73511 extrusion as given in QQ-A-200/11	Cum Line numbers 216 and on
	Upper Beam (Angle)		7050-T7451 plate as given in AMS 4050	
[2]	Lower Beam Assembly			
	Lower Beam		BAC1506-4398 7075-T73511 extrusion as given in QQ-A-200/11	Cum Line numbers 1 thru 215
	Lower Beam (Angle)		7050-T7451 plate as given in AMS 4050	
	Lower Beam		7050-T7451 plate as given in BMS 7-323	Cum Line numbers 216 and on

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





IDENTIFICATION 2 - HORIZONTAL STABILIZER CENTER SECTION BEAMS



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Horizontal Stabilizer Center Section Beam Locations Figure 1

Та	h	lo.	-1	•
ıa	υ	IC.		

REFERENCE DRAWINGS		
DRAWING NUMBER	TITLE	
181A3000	Beam Installation - Center Section Horizontal Tail	
181A3101	Sheet Metal Details - Primary Beam, Center Section Horizontal Tail	
181A3102	Extruded Details - Primary Beam, Center Section Horizontal Tail	
181A3103	Upper Chord - Primary Beam, Center Section Horizontal Tail	
181A3104	Lower Chord - Primary Beam, Center Section Horizontal Tail	
181A3201	Sheet Metal Details - Thrust Beam Center Section Horizontal Tail	






REFERENCE DRAWINGS			
DRAWING NUMBER	TITLE		
181A3202	Extruded Details - Thrust Beam, Center Section Horizontal Tail		
181A3203	Chords - Thrust Beam, Center Section Horizontal Tail		





737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Horizontal Stabilizer Center Section Primary Beams Identification Figure 2





Table 2:


LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T*[1]	MATERIAL	EFFECTIVITY
[1]	Upper Gusset (2)	0.312 (7.92)	7075-T7351 machined plate as given in QQ-Q- 250/12. Refer to the production drawing for the machined thicknesses	
[2]	Splice Angle (16)		BAC1514-3163 7075-T73511 extrusion, as given in QQ-A-200/11. Refer to the production drawing for machined thicknesses	
[3]	Splice Plate (4)	0.160 (4.64)	7075-T6 sheet as given in QQ-A-250/13	
[4]	Lower Gusset (2)	0.160 (4.64)	7075-T6 sheet as given in QQ-A-250/12	
[5]	Stiffener (2)		BAC1505-101411 7075-T6511 extrusion as given in QQ-A-200/11. Refer to the production drawing for the machined thicknesses	
[6]	Stiffener (2)		BAC1505-100101 7075-T6511 extrusion as given in QQ-A-200/11. Refer to the production drawing for machined thicknesses	
[7]	Stiffener (2)		BAC1505-101579 7075-T6511 extrusion as given in QQ-A-200/11. Refer to the production drawing for the machined thicknesses	
[8]	Lower Chord (2)		BAC1505-101216 7075-T73511 extrusion as given in QQ-A-200/11. Refer to the production drawing for the machined thicknesses	
[9]	Stiffener (4)		BAC1505-1011184 7075-T6511 extrusion as given in QQ-A-200/11. Refer to the production drawing for the machined thicknesses	
[10]	Attach Angle (2)	0.080 (2.03)	7075-T62 clad sheet as given in QQ-A-250/12	
[11]	Web (2)	0.090 (2.29)	7075-T6 sheet as given in QQ-A-250/12. Refer to the production drawing for the chem-milled thicknesses	
[12]	Upper Chord (2)		BAC1505-101216 7075-T73511 extrusion as given in QQ-A-200/11. Refer to the production drawing for the machined thicknesses	
[13]	Splice Chord		7075-T73511 bar as given in QQ-A-200/11, Class A. Refer to the production drawing for the machined thicknesses	

*[1] Note: T = Pre-manufactured thicknesses in inches (millimeters).





737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 3 FOR THE LIST OF MATERIALS.

Horizontal Stabilizer Center Section Thrust Beams Identification Figure 3





Table 3:


LIST OF MATERIALS FOR FIGURE 3				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Stiffener (2)		BAC1505-100542 7075-T73511 extrusion as given in QQ-A-200/11	
[2]	Gusset, Upper/Lower (4)		7075-T6 machined sheet as given QQ-A-250/12. Refer to the production drawing for the machined thicknesses	
[3]	Web	0.050 (1.27)	7075-T6 clad sheet as given in QQ-A-250/13	
[4]	Splice Plate (16)		7075-T7351 machined plate as given in QQ-A- 250/12. (Optional: 7075-T73511, Class A machined bar. Refer to to the production drawing for the machined thicknesses)	
[5]	Stiffener		BAC1505-100027 7075-T73511 extrusion as given in QQ-A-200/11	
[6]	Stiffener		AND10136-1501 7075-T73511 extrusion as given in QQ-A-200/11	
[7]	Web	0.063 (1.60)	7075-T6 chem-milled sheet as given in QQ-A- 250/12. Refer to the production drawing for the chem-milled thicknesses	
[8]	Chord, Upper/Lower (4)		BAC15005-100587 7075-T73511 as given in QQ-A-200/11. Refer to the production drawing for the machined thicknesses	
[9]	Chord, Upper (2)		BAC1505-100694 7075-T73511 machined extrusion as given in QQ-A-200/11. Refer to the production drawing for the machined thicknesses	
[10]	Chord, Lower (2)		BAC1506-3612 7075-T73511 machined extrusion as given in QQ-A-200/11. Refer to the production drawing for the machined thicknesses	
[11]	Gusset (3)	0.125 (3.18)	7075-T6 clad sheet as given in QQ-A-250/13	
[12]	Stiffener		AND10136-1608 7075-T73511 extrusion as given in QQ-A-200/11	
[13]	Forward Gusset (4)		7075-T6 machined sheet as given QQ-A-250/12. Refer to the production drawing for the machined thicknesses	
[14]	Web	0.080 (2.03)	7075-T6 chem-milled sheet as given in QQ-A- 250/12. Refer to the production drawing for the chem-milled thicknesses	

*[1] Note: T = Pre-manufactured thicknesses in inches (millimeters).





737-800 STRUCTURAL REPAIR MANUAL



Horizontal Stabilizer Center Section Aft Spar Identification Figure 4





Table 4:

LIST OF MATERIALS FOR FIGURE 4				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Splice Angle (16)		BAC1514-3163 7075-T73511 extrusion as given in QQ-A-200/11. Refer to the production drawing for machined thicknesses	
[2]	Splice Plate (4)	0.160 (4.64)	7075-T6 sheet as given in QQ-A-250/13	
[3]	Splice Plate (16)		7075-T7351 machined plate as given in QQ-A- 250/12. (Optional: 7075-T73511, Class A machined bar. Refer to to the production drawing for the machined thicknesses)	
[4]	Web Splice		Ti-6AI-4V machined titanium plate as given in MIL- T-9046, Code AB-1, annealed. Refer to the production drawing for the machined thicknesses	
[5]	Shear Tie		BAC1514-1081 7075-T73511 extrusion as given in QQ-A-200/11	
[6]	Reinforcing Plate LH/RH (4)		Ti-6AI-4V machined titanium plate as given in MIL- T-9046, Code AB-1, annealed. Refer to the production drawing for the machined thicknesses	

*[1] Note: T = Pre-manufactured thicknesses in inches (millimeters).





ALLOWABLE DAMAGE 1 - HORIZONTAL STABILIZER TRAILING EDGE BEAMS

1. Applicability

A. This subject gives the allowable damage limits for the horizontal stabilizer trailing edge beams shown in Horizontal Stabilizer Beam Location, Figure 101/ALLOWABLE DAMAGE 1 and Horizontal Stabilizer Beam Locations, Figure 102/ALLOWABLE DAMAGE 1.

2. General

A. Remove the damage as necessary.

- (1) Refer to 51-10-02 for the inspection and removal of damage.
- (2) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
- (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
- B. After you remove the damage, do the procedures that follow.


WARNING: MAKE SURE THAT YOU WEAR EYE PROTECTION WHEN YOU USE THE FLAP PEEN WHEEL. IF YOU DO NOT OBEY, AN INJURY CAN OCCUR.

- (1) Flap peen or shot peen the surfaces of the beams if you remove the damage.
 - (a) Refer to 51-20-06 for shot peen intensity and shot number.
 - (b) Refer to SOPM 20-10-03 for flap peen and shot peen procedures.
- (2) Apply a chemical conversion coating to the bare surfaces of the reworked areas of the beams. Refer to 51-20-01.
- (3) Apply one layer of BMS 10-11, Type I, primer to the reworked areas of the beams. Refer to SOPM 20-41-02.





737-800 STRUCTURAL REPAIR MANUAL




Horizontal Stabilizer Beam Location Figure 101



BOEING®

737-800 STRUCTURAL REPAIR MANUAL




Horizontal Stabilizer Beam Locations Figure 102 (Sheet 1 of 2)





737-800 STRUCTURAL REPAIR MANUAL



Horizontal Stabilizer Beam Locations Figure 102 (Sheet 2 of 2)





3. References

Reference	Title
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-06	SHOT PEENING
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-10-03	General - Shot Peening Procedures
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes


4. Allowable Damage Limits

- A. Zone 1
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A and B.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A, B, C, E, and F.
 - 1) The removal of damage, as shown in Details C and F, is permitted for the vertical flange only if:
 - a) There is no removal of damage, as shown in Details C and F, from the aft or forward flange at the same section.
 - (3) Dents are permitted as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Detail D.
 - (4) Holes and Punctures are not permitted.
- B. Zone 2
 - (1) Damage is not permitted.



BOEING

737-800 STRUCTURAL REPAIR MANUAL



D634A210


Page 106


Nov 01/2003

55-10-13



737-800 STRUCTURAL REPAIR MANUAL






D634A210

Page 107

Nov 01/2003

55-10-13





Allowable Damage Limits Figure 103 (Sheet 3 of 3)






ALLOWABLE DAMAGE 2 - HORIZONTAL STABILIZER CENTER SECTION

1. Applicability

- A. This subject gives the allowable damage limits for the center section beams and front spar shown in Horizontal Stabilizer Center Section Location, Figure 101/ALLOWABLE DAMAGE 2.
- B. Contact The Boeing Company for damage to the rear spar chord.




Horizontal Stabilizer Center Section Location Figure 101





737-800 STRUCTURAL REPAIR MANUAL




FWD 🖉

NOTE: ALL PARTS OTHER THAN THE REAR SPAR ARE MADE OF ALUMINUM.

Horizontal Stabilizer Center Section - Primary Beams Figure 102







NOTE: ALL PARTS OTHER THAN THE REAR SPAR ARE MADE OF ALUMINUM.

Horizontal Stabilizer Center Section - Thrust Beams Figure 103





2. General

- A. Remove the damaged aluminum material as necessary.
 - (1) Refer to 51-10-02 for the inspection and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (4) Make sure there is a surface smoothness of 63 microinches Ra or better on the damaged parts.
- B. After you remove the damage, do the procedures that follow:
 - (1) Do a High Frequency Eddy Current (HFEC) or dye penetrant inspection to the damaged parts to make sure that all the damage is removed. Refer to 737 NDT Part 6, 51-00-00, Figure 4.

WARNING: MAKE SURE THAT YOU WEAR EYE PROTECTION WHEN YOU USE THE FLAP PEEN WHEEL. IF YOU DO NOT OBEY, AN INJURY CAN OCCUR.

- (2) Flap peen the reworked areas of the front spar chord and splice angles as given in SOPM 20-10-03 and 51-20-06.
- C. Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to 51-20-01.
- D. Apply two layers of BMS 10-11, Type I, primer to the reworked areas. Refer to SOPM 20-41-02.

3. References

Reference	Title
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-06	SHOT PEENING
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-40-05, GENERAL	Fastener Hole Sizes
51-40-06, GENERAL	Fastener Edge Margins
SOPM 20-20-02	Penetrant Methods of Inspection
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes
737 NDT Part 6, 51-00-00	Structures - General

4. Allowable Damage Limits

- A. Front Spar Chord
 - (1) Cracks are not permitted.
 - (2) Nicks, Gouges, and Scratches:





- (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 2, Detail G.
 - **NOTE**: This only applies to damage caused by the sliding seal (part number 181A8004). If the cause of damage cannot be determined then contact The Boeing Company.
- (3) Corrosion is not permitted.
- (4) Dents are not permitted.
- (5) Holes and Punctures are not permitted.
- B. Attach Angles
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 2, Details A and B.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 2, Details A, B, C, D, and E.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- C. Forward Gusset Plates and Splice Angles
 - (1) Cracks are not permitted.
 - (2) Nicks, Gouges, and Scratches:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 2, Detail G.
 - **NOTE**: This only applies to damage caused by the sliding seal (part number 181A8004). If the cause of damage cannot be determined then contact The Boeing Company.
 - (3) Corrosion is not permitted.
 - (4) Dents are not permitted.
 - (5) Holes and Punctures are not permitted.
- D. Stiffeners
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 2, Details A, B, and E.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 2, Details A, B, C, D, and E.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are permitted as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 2, Detail F.
- E. Webs
 - (1) Cracks:






- (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 2, Details A and B.
- (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 2, Details A, B, C, D, and E.
 - (b) Damage that does not go through the clad surface is permitted.
- (3) Dents are not permitted.
- (4) Holes and Punctures are permitted if they are:
 - (a) A maximum of 0.25 inch in diameter.
 - (b) A minimum of 4D (D = the diameter of the damage) away from a hole, other damage, or the part edge.
 - (c) Filled with a 2117-T3 or 2117-T4 aluminum rivet installed without sealant.



BOEING

737-800 STRUCTURAL REPAIR MANUAL



D634A210


Page 107

Nov 01/2003

55-10-13




737-800 STRUCTURAL REPAIR MANUAL





737-800 STRUCTURAL REPAIR MANUAL






HOLES THAT ARE PERMITTED TO REMOVE DAMAGED MATERIAL IN WEB STIFFENERS

Allowable Damage Limits Figure 104 (Sheet 3 of 4)





737-800 STRUCTURAL REPAIR MANUAL



SECTION A-A

Allowable Damage Limits Figure 104 (Sheet 4 of 4)





REPAIR 1 - HORIZONTAL STABILIZER TRAILING EDGE BEAMS

1. Applicability


A. Repair 1 is applicable to damage to the trailing edge beams outboard of Elevator Station 176.64 as shown in Horizontal Stabilizer Beam Location, Figure 201/REPAIR 1 and Horizontal Stabilizer Beam Locations, Figure 202/REPAIR 1.

2. <u>References</u>

Reference	Title
51-70-12	EXTRUDED SECTION REPAIRS

3. <u>Repair Instructions</u>

A. Refer to 51-70-12 to repair the trailing edge beams outboard of Elevator Station 176.64.



Horizontal Stabilizer Beam Location Figure 201



REPAIR 1 Page 201 Nov 10/2006





737-800 STRUCTURAL REPAIR MANUAL





Figure 202 (Sheet 1 of 2)



55-10-13





Horizontal Stabilizer Beam Locations Figure 202 (Sheet 2 of 2)



REPAIR 1 Page 203 Nov 01/2003



REPAIR 2 - HORIZONTAL STABILIZER CENTER SECTION BEAMS

1. Applicability


A. Repair 2 is applicable to damage to the center section beams shown in Horizontal Stabilizer Center Section Beam Location, Figure 201/REPAIR 2.

2. References

Reference	Title
51-70-11	TYPICAL FORMED SECTION REPAIRS
51-70-12	EXTRUDED SECTION REPAIRS

3. Repair Instructions

- A. Refer to 51-70-11 to repair the formed parts.
- B. Refer to 51-70-12 to repair the extruded parts.




Horizontal Stabilizer Center Section Beam Location Figure 201





737-800 STRUCTURAL REPAIR MANUAL



NOTES

- ALL PARTS ARE MADE FROM ALUMINUM.
- 1 FOR THE PRIMARY BEAMS, NO REPAIRS ARE PERMITTED TO THE UPPER OR LOWER CHORDS AFT OF STA 1117.


Horizontal Stabilizer Center Section - Primary Beams Figure 202



REPAIR 2 Page 202 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



NOTE: ALL PARTS ARE MADE OF ALUMINUM.


Horizontal Stabilizer Center Section - Thrust Beams Figure 203



REPAIR 2 Page 203 Nov 01/2003



IDENTIFICATION 1 - HORIZONTAL STABILIZER TIP



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Horizontal Stabilizer Tip Location Figure 1


Table 1:

REFERENCE DRAWINGS			
DRAWING NUMBER	TITLE		
186A0001	Left Horizontal Stabilizer Collector		
186A0002	6A0002 Right Horizontal Stabilizer Collector		
189A1001	189A1001 Tip Cap Installation/Assembly - Horizontal Stabilizer		



EBBEING®

737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Horizontal Stabilizer Tip Identification Figure 2



Page 2




Table 2:

	LIST OF MATERIALS FOR FIGURE 2						
ITEM DESCRIPTION T ^{*[1]} MATERIAL EFFECTIVITY							
[1]	Composite Tip Cap		Refer to Figure 3				
[2]	Leading Edge Cap	0.090 (2.3)	2024-T42 clad sheet as given in QQ-A-250/5				
[3]	Trailing Edge Tip		A356.0-T6 aluminum casting as given in AMS 4218 with C30 cast roughness				
[4]	Ground Strap	0.020 (0.51)	2024-T3 clad sheet as given in QQ-A-250/5				
[5]	Splice Strap	0.063 (1.60)	2024-T3 clad sheet as given in QQ-A-250/5				

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





A-A

Ply Sequence for Figure 2, Item [1] Figure 3



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details




Table 3:

	PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [1]				
PLY	DIRECTION	MATERIAL			
P1, P2, P5, P6, P7, P9	0 or 90 degrees	Glass Fiber Reinforced Plastic (GFRP) as given in BMS 8-79, Class III, Grade B, Style 1581 Style 7781 is optional			
P3, P4, P8	+ or - 45 degrees	GFRP as given in BMS 8-79, Class III, Grade B, Style 1581. Style 7781 is optional			
P10	0 or 90 degrees	Expanded metal foil as given in BMS 8-336, Type I, Class 1, Grade 016, Form A. Aluminum coated epoxy impregnated glass fiber cloth as given in BMS 8-278, Type I, Class 250 is an alternative.			
P11		0.001 inch thick composite surfacing film as given in BMS 8-341, Type III			





IDENTIFICATION 2 - HORIZONTAL STABILIZER COVE



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Horizontal Stabilizer Cove Location Figure 1

Table 1:


REFERENCE DRAWINGS			
DRAWING NUMBER	TITLE		
185A0001	Trailing Edge Functional Collector - Left, Horizontal Stabilizer		
185A0002	Trailing Edge Functional Collector - Right, Horizontal Stabilizer		
185A3100	Installation - Cove Horizontal Stabilizer		




Page 1



737-800 STRUCTURAL REPAIR MANUAL





LEFT SIDE SHOWN, **RIGHT SIDE OPPOSITE**

Horizontal Stabilizer Cove Identification Figure 2



Page 2 Mar 10/2004

D634A210

BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details



Table 2:


LIST OF MATERIALS FOR FIGURE 2						
ITEM	ITEM DESCRIPTION T ^{*[1]} MATERIAL EFFECTIVITY					
[1]	Inboard Panel		Preimpregnated Glass Fabric Refer to Figure 3			
[2]	Outboard Panel		Preimpregnated Glass Fabric Refer to Figure 4			
[3]	Splice Plate	0.050	Clad 2024-T3 as given in QQ-A-250/5			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).







737-800 STRUCTURAL REPAIR MANUAL










PLAN VIEW

LEFT SIDE SHOWN, RIGHT SIDE OPPOSITE



A-A

Ply Direction and Ply Sequence for Horizontal Stabilizer Cove, Figure 2, Item [1] Figure 3






Table 3:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [1]				
PLY	DIRECTION	MATERIAL		
P1, P6	90 degrees	Preimpregnated Glass Fabric as given in BMS 8-79, Class III, Grade B, Type 1581 or 7781		
P2, P5	+ or - 45 degrees	Preimpregnated Glass Fabric as given in BMS 8-79, Class III, Grade B, Type 1581 or 7781		
P3, P4	0 degrees	Preimpregnated Glass Fabric as given in BMS 8-79, Class III, Grade B, Type 1581 or 7781		







737-800 STRUCTURAL REPAIR MANUAL




AFT VIEW





PLAN VIEW

LEFT SIDE SHOWN, RIGHT SIDE OPPOSITE



A-A

Ply Direction and Ply Sequence for Horizontal Stabilizer Cove, Figure 2, Item [2] Figure 4





Table 4:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [2]				
PLY	DIRECTION	MATERIAL		
P1, P6	90 degrees	Preimpregnated Glass Fabric as given in BMS 8-79, Class III, Grade B, Type 1581 or 7781		
P2, P5	+ or - 45 degrees	Preimpregnated Glass Fabric as given in BMS 8-79, Class III, Grade B, Type 1581 or 7781		
P3, P4 0 degrees Preimpregnated Glass Fabric as given in BMS 8-79, Class III, Grade B, Typ		Preimpregnated Glass Fabric as given in BMS 8-79, Class III, Grade B, Type 1581 or 7781		






ALLOWABLE DAMAGE 1 - HORIZONTAL STABILIZER TIP

1. Applicability

A. Allowable Damage 1 is applicable to damage on the horizontal stabilizer tip as shown in Horizontal Stabilizer Tip, Figure 101/ALLOWABLE DAMAGE 1.



Horizontal Stabilizer Tip Figure 101

2. General

- A. Do an inspection of the damaged area to find the length, width, and depth of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to 737 NDT Part 1, 51-01-02 for the inspection procedures.
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.

ALLOWABLE DAMAGE 1

55-10-30

Page 101


Jul 10/2005





- (1) Refer to Definitions of the Damage Size, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, and C for the definitions of the length, width, and depth of damage.
- B. Do the steps that follow if you have damage to the tip cap made of Glass Fabric Reinforced Plastic (GFRP).
 - (1) Remove all the contamination and water from the structure.
 - (a) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (b) Refer to 51-70-04 for the damage removal procedures.
 - (2) The tip cap has a layer of BMS 8-336 expanded aluminum foil mesh. If damage occurs to the expanded aluminum foil mesh, do the steps that follow:
 - (a) Refer to 51-70-14 for the allowable damage limits for the expanded aluminum foil mesh.
 - (b) Seal the damaged area as given in 51-70-14.
- C. Do the steps that follow if you have damage to the leading edge cap or the trailing edge tip cap made of aluminum.
 - (1) Remove the damage.
 - (a) Refer to 51-10-02 for the investigation and cleanup procedures.
 - (b) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (c) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (d) Make the surface texture roughness for all cut surfaces 125 microinches Ra or smoother.
 - (2) After you remove the damage, do the steps that follow:
 - (a) Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to 51-20-01.
 - (b) Apply one layer of BMS 10-11, Type I primer to the conversion coated, reworked areas. Refer to SOPM 20-41-02.
 - (c) Apply a decorative finish if necessary. Refer to AMM PAGEBLOCK 51-21-99/701.
- D. Make sure the aerodynamic smoothness is satisfactory or there will be a decrease in the economic performance of the airplane. Refer to 51-10-01.





Definitions of the Damage Size Figure 102

3. References

Reference	Title
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05, GENERAL	Repair Sealing
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-70-01, REPAIR GENERAL	Procedures to Rework or Fill Allowable Dents on the External Aerodynamic Surfaces of Metallic Parts
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-08, GENERAL	Resin Sweep-Fair Procedures





(Continued)

Reference	Title
51-70-14	STRUCTURES WITH ALUMINUM COATINGS AND FOILS
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Allowable Damage Limits

- A. Tip Cap (GFRP)
 - (1) Nicks, Gouges and Scratches that do not cause damage to the glass fibers are permitted.
 - (2) Nicks, Gouges and Scratches that cause damage to the glass fibers are permitted if they are:
 - (a) A maximum of one ply in depth

<u>NOTE</u>: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum of 5.0 inches in length
- (c) A maximum of 0.25 inch in width
- (d) A minimum of 0.50 inch away from the edge of a fastener hole
- (e) A minimum of 0.50 inch away from the edge of other damage. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies and
 - 2) Are sealed as given in Paragrah 2.
- (3) Dents are permitted if:
 - (a) They are a maximum of 2.0 inch in diameter.
 - (b) The edge of the damage is a minimum of 4D (D = the diameter of the damage) from other damage, fastener holes or material edges. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies and
 - 2) Are sealed as given in Paragrah 2.
- (4) Holes and Punctures are permitted if they are:
 - (a) A maximum of 1.50 inch in diameter
 - (b) A minimum of 4D (D = the diameter of the damage) from other damage, fastener holes or material edges. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies and
 - 2) Are sealed as given in Paragrah 2.
- (5) Delaminations are permitted if they are:
 - (a) A maximum of 1.5 inch in diameter
 - (b) A minimum of 4D (D = the diameter of the damage) from the edge of other damage, the edge of a hole, or the edge of the material. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies
 - 2) Are sealed as given in Paragrah 2.






- (6) Edge damage is permitted if it is:
 - (a) A maximum of 0.10 in depth
 - (b) A maximum of 0.50 inch in width
 - (c) A minimum of 2.5D (D = the diameter of the damage) from the edge of other damage, the edge of a hole, or the edge of the material. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies
 - 2) Are sealed as given in Paragrah 2.
- (7) Edge Erosion is permitted as shown in Cleanup and Sealing of Edge Erosion, Figure 103/ALLOWABLE DAMAGE 1.
- B. Leading Edge Cap and Trailing Edge Tip Cap (Aluminum)
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 1, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 1, Details A, B, C, D, and E.
 - (b) Damage that does not go through the clad surface is permitted.
 - (3) Dents:
 - (a) Dents are permitted if they agree with the conditions shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 1, Detail F.
 - (4) Holes and Punctures are permitted if:
 - (a) They are 0.25 inch in diameter or less
 - (b) The edge of the damage is a minimum of 1.0 inch away from another hole, an edge, or other damage
 - (c) They are filled with a 2017-T3 or 2117-T4 aluminum protruding head rivet. Install the rivet dry.



Page 105






Cleanup and Sealing of Edge Erosion Figure 103



BOEING

737-800 STRUCTURAL REPAIR MANUAL



D634A210

ALLOWABLE DAMAGE 1


55-10-30

Page 107


Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL








Allowable Damage Limits Figure 104 (Sheet 3 of 3)








ALLOWABLE DAMAGE 2 - HORIZONTAL STABILIZER COVE

1. Applicability

A. Allowable Damage 2 is applicable to damage on the horizontal stabilizer cove panels shown in Horizontal Stabilizer Cove, Figure 101/ALLOWABLE DAMAGE 2.



Horizontal Stabilizer Cove Figure 101

2. <u>General</u>

- A. Do an inspection of the damaged area to find the length, width, and depth of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to 737 NDT Part 1, 51-01-02 for inspection procedures.
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.

ALLOWABLE DAMAGE 2

55-10-30


Page 101

Jul 10/2005



- (1) Refer to Definitions of the Damage Size, Figure 102/ALLOWABLE DAMAGE 2, Details A, B, and C for the definitions of the length, width, and depth of the damage.
- B. Do the steps that follow for the cove panels made of Glass Fabric Reinforced Plastic (GFRP).
 - (1) Remove all the contamination and water from the structure.
 - (a) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (b) Refer to 51-70-04 for the damage removal procedures.
 - (2) Seal the damaged areas with the steps that follow.
 - (a) Seal the damage that is not more than one ply deep and that agrees with the allowable damage limits given in Paragraph 4./ALLOWABLE DAMAGE 2
 - 1) Make a temporary seal.
 - a) Apply aluminum foil tape (speed tape).
 - b) Keep a record of the location.
 - c) Make sure the tape is in satisfactory condition every 400 flight hours.
 - d) Seal the damage permanently at or before 5000 flight hours.
 - 2) Make a permanent seal.
 - a) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given in 51-70-08.
 - b) Apply one layer of BMS 10-79, Type 3 or BMS 10-103, Type 1 primer. Refer to SOPM 20-44-04.
 - c) Apply one layer of BMS 10-60 enamel to the areas sealed with epoxy resin. Refer to AMM PAGEBLOCK 51-21-99/701.
 - (b) Seal the damaged areas that are more than one ply deep and that agree with the allowable damage limits given in Paragraph 4./ALLOWABLE DAMAGE 2
 - 1) Use a vacuum and heat to remove moisture from the solid laminate or the honeycomb cells. Refer to 51-70-04.
 - 2) Make a temporary seal with aluminum foil tape (speed tape).
 - 3) Keep a record of the location.
 - 4) Repair the damage at or before 400 flight hours.





3. References

Reference	Title		
51-10-02, GENERAL	Inspection and Removal of Damage		
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS		
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS		
51-70-08	RESIN SWEEP-FAIR PROCEDURES		
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING		
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes		
SOPM 20-44-04	Application of Urethane Compatible Primers		
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage		





4. Allowable Damage Limits


- A. Inboard and Outboard Panels (GFRP Laminate)
 - (1) Nicks, Gouges and Scratches that do not cause damage to the glass fibers are permitted.
 - (2) Nicks, Gouges and Scratches that cause damage to the glass fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum of 5.0 inches in length
- (c) A maximum of 0.25 inch in width
- (d) A minimum of 0.50 inch away from the edge of a fastener hole
- (e) A minimum of 0.50 inch away from the edge of other damage. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies and
 - 2) Are sealed as given in paragraph 2.
- (3) Dents are permitted if:
 - (a) They are a maximum of 2.0 inch in diameter.
 - (b) The edge of the damage is a minimum of 2.5D (D = the diameter of the damage) from other damage, fastener holes or material edges. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies and
 - 2) Are sealed as given in paragraph 2.
- (4) Holes and Punctures are permitted if they are:
 - (a) A maximum of 2.0 inch in diameter
 - (b) A minimum of 2.5D (D = the diameter of the damage) from other damage, fastener holes or material edges. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies and
 - 2) Are sealed as given in paragraph 2.
- (5) Delaminations are permitted if they are:
 - (a) A maximum of 2.0 inch in diameter
 - (b) A minimum of 2.5D (D = the diameter of the damage) from the edge of other damage, the edge of a hole, or the edge of the material. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies
 - 2) Are sealed as given in paragraph 2.
- (6) Edge damage is permitted if it is:
 - (a) A maximum of 0.25 in depth
 - (b) A maximum of 1.00 inch in width
 - (c) A minimum of 2.5D (D = the diameter of the damage) from the edge of other damage, the edge of a hole, or the edge of the material. Other damage does not include nicks, gouges, and scratches that:



- 1) Do not cause damage to the glass fiber plies
- 2) Are sealed as given in paragraph 2.
- (7) Edge Erosion is permitted as shown in Cleanup and Sealing of Edge Erosion, Figure 103/ALLOWABLE DAMAGE 2.



Cleanup and Sealing of Edge Erosion Figure 103






REPAIR 1 - HORIZONTAL STABILIZER TIP

1. Applicability

- A. Repair 1 is applicable to the horizontal stabilizer tip cap made of Glass Fiber Reinforced Plastic (GFRP) shown in Horizontal Stabilizer Tip Cap Location, Figure 201/REPAIR 1.
- B. Repair 1 is applicable to damage that is more than the limits permitted in Allowable Damage 1. Refer to Allowable Damage 1 for the type and size of damage that is permitted.

2. General


- A. Repair 1 gives instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Get access to the damaged area.
 - (1) If necessary, remove the tip cap.
 - (2) Refer to 51-40-02 for information on fastener removal.
- C. Do an inspection of the damaged area to find the dimensions of the damage.
 - (1) Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 for inspection procedures.
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.
- D. Refer to Definitions of the Damage Size, Figure 202/REPAIR 1, Details A, B, and C for the definitions of the length, width, and depth of damage.
- E. Do the repair as given in Paragraph 4./REPAIR 1
- F. Put the tip cap back to the initial condition, as applicable.
 - (1) Install the tip cap, if it was removed.
 - (a) Refer to 51-40-02 for information on fastener installation.
 - (2) Make sure the aerodynamic smoothness is satisfactory or there will be a decrease in the performance of the airplane. Refer to 51-10-01.




REPAIR 1 Page 201 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL




LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE





REPAIR 1 Page 202 Nov 01/2003



Definitions of the Damage Size Figure 202

3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-20-05, GENERAL	Repair Sealing
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05, REPAIR GENERAL	Repair Procedures for Preimpregnated Materials
51-70-06	ROOM TEMPERATURE CURE REPAIRS
55-10-30, ALLOWABLE DAMAGE 1	Horizontal Stabilizer Tip
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage



REPAIR 1 Page 203 Jul 10/2005



4. Repair Instructions

- A. For dents that are a maximum of 2 inches in diameter and have no fiber damage and delamination, do the steps that follow:
 - (1) Fill the dent with BMS 5-28, Type 7 potting compound
 - (2) Apply a fiberglass patch over the potted area as given in 51-70-04.
- B. For dents that are not permitted by Paragraph 4.A./REPAIR 1 and for other damage that is not permitted by Allowable Damage 1, refer to Table 201/REPAIR 1.
- C. Use the instructions that follow to do a Category B repair with wet layup materials at room temperature cure.
 - (1) The edges of the repair must be 3 inches or more away from:
 - (a) The edge of other repairs
 - (b) The edge of the part
 - (c) The edge of other damage. This does not include damage that is permitted and sealed as given in Allowable Damage 1.

REPAIR DATA FOR THE 250°F (121°C) CURE TIP CAP						
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED LAYUP		
REPAIR CURE TEMPERATURE	Room Temperature	150°F (66°C)	200°F (93°C)	250°F (121°C)		
REPAIR SIZE	Damage that is a maximum of: - 1.5 inches in diameter - 30 percent of the smallest dimension across the panel at the damage location	Damage that is a maximum of: - 3.0 inches in diameter - 50 percent of the smallest dimension across the panel at the damage location	There are no limits on the dimension of the repair	There are no limits on the dimensions of the repair		
REPAIR INSTRUCTIONS	SRM 51-70-06 and Paragraph 4.C	SRM 51-70-04 and Paragraph 4.D	SRM 51-70-04 and Paragraph 4.E	SRM 51-70-05 and Paragraph 4.F		

Table	201	:
-------	-----	---

- (2) Repair the damage as given in 51-70-06.
- (3) Use the same number of repair plies as the number of initial plies that were removed.
- (4) Do an inspection of the repair each 800 flight hour interval or more frequently.
 - (a) If deterioration is found, replace the repair with a Category A repair.
- D. Use the instructions that follow to do a Category A repair with wet layup materials at 150°F (66°C) cure.
 - (1) The edges of the repair must be 3 inches or more away from:
 - (a) The edge of other repairs
 - (b) The edge of the part
 - (c) The edge of other damage. This does not include damage that is permitted and sealed as given in Allowable Damage 1.



REPAIR 1 Page 204 Nov 01/2003



- (2) Repair the damage as given in 51-70-04.
 - (a) Use the same number of repair plies as the number of initial plies that were removed.
 - (b) Add one structural ply of BMS 9-3, Type H-2 or Type H-3 glass fabric that is ± 45 degrees.
 - (c) Add a second structural ply of BMS 9-3, Type H-2 or Type H-3 glass fabric that is 0 or 90 degrees.
- E. Use the instructions that follow to do a Category A repair with wet layup materials at 200°F (93°C) cure.
 - (1) Repair the damage as given in 51-70-04.
 - (a) Use the same number of repair plies as the number of initial plies that were removed.
 - (b) Add one structural ply of BMS 9-3, Type H-2 or Type H-3 glass fabric that is ± 45 degrees.
 - (c) Add a second structural ply of BMS 9-3, Type H-2 or Type H-3 glass fabric that is 0 or 90 degrees.
- F. Use the instruction that follows to do a Category A repair with preimpregnated layup materials at 250°F (121°C) cure.
 - (1) Use the same number of repair plies as the number of initial plies that were removed.




REPAIR 1 Page 205 Nov 01/2003



REPAIR 2 - HORIZONTAL STABILIZER COVE

1. Applicability

- A. Repair 2 is applicable to the cove panels of the horizontal stabilizer made of Glass Fiber Reinforced Plastic (GFRP) shown in Horizontal Stabilizer Cove, Figure 201/REPAIR 2.
- B. Repair 2 is applicable to damage that is more than the limits permitted in Allowable Damage 2. Refer to Allowable Damage 2 for the type and size of damage that is permitted.



Horizontal Stabilizer Cove Figure 201

2. General

- A. Repair 2 gives instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Get access to the damaged area.



REPAIR 2 Page 201 Nov 01/2003




- (1) If necessary, remove the cove panels
- (2) Refer to 51-40-02 for information on fastener removal.
- C. Do an inspection of the damaged area to find the dimensions of the damage.
 - (1) Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 for inspection procedures.

NOTE: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.

- D. Refer to Definitions of the Damage Size, Figure 202/REPAIR 2, Details A, B, and C for the definitions of the length, width, and depth of damage.
- E. Do the repair as given in Paragraph 4./REPAIR 2
- F. Put the cove panels back to the initial condition, as applicable.
 - (1) Install the cove panels, if they were removed.
 - (a) Refer to 51-40-02 for information on fastener installation.



55-10-30



Definitions of the Damage Size Figure 202

3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-02, GENERAL	Inspection and Removal of Damage
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05, REPAIR GENERAL	Repair Procedures for Preimpregnated Materials
51-70-06	ROOM TEMPERATURE CURE REPAIRS
55-10-30, ALLOWABLE DAMAGE 2	Horizontal Stabilizer Cove
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage



REPAIR 2 Page 203 Jul 10/2005



4. Repair Instructions

- A. For dents that are a maximum of 2 inches in diameter and have no fiber damage and delamination, do the steps that follow:
 - (1) Fill the dent with BMS 5-28, Type 7 potting compound
 - (2) Apply a fiberglass patch over the potted area as given in 51-70-04.
- B. For dents that are not permitted by Paragraph 4.A./REPAIR 2 and for other damage that is not permitted by Allowable Damage 1, refer to Table 201/REPAIR 2.
- C. Use the instructions that follow to do a Category B repair with wet layup materials at room temperature cure.
 - (1) The edges of the repair must be 3.0 inch or more away from:
 - (a) The edge of other repairs
 - (b) The edge of the part
 - (c) The edge of other damage. This does not include damage that is permitted and sealed as given in Allowable Damage 2.
 - (2) Repair the damage as given in 51-70-06.
 - (3) Use the same number of repair plies as the number of initial plies that were removed.
 - (4) Do an inspection of the repair each 800 flight hour interval or more frequently.
 - (a) If deterioration is found, replace the repair with a Category A repair.

Table 201:	
------------	--

	REPAIR DATA FOR THE 250°F (121°C) CURE COVE PANELS				
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED LAYUP	
REPAIR CURE TEMPERATURE	Room Temperature	150°F (66°C)	200°F (93°C)	250°F (121°C)	
REPAIR SIZE	Damage that is a maximum of: - 1.5 inches in diameter	Damage that is a maximum of: - 3.0 inches in diameter	There are no limits on the dimensions of the repair	There are no limits on the dimensions of the repair	
	- 30 percent of the smallest dimension across the panel at the damage location	- 50 percent of the smallest dimension across the panel at the damage location			
	One repair is permitted for each 144 square inches of panel area	One repair is permitted for each 144 square inches of panel area			
REPAIR INSTRUCTIONS	SRM 51-70-06 and Paragraph 4.C	SRM 51-70-04 and Paragraph 4.D	SRM 51-70-04 and Paragraph 4.E	SRM 51-70-05 and Paragraph 4.F	

- D. Use the instructions that follow to do a Category A repair with wet layup materials at 150°F (66°C) cure.
 - (1) The edges of the repair must be 3.0 inch or more away from:
 - (a) The edge of other repairs
 - (b) The edge of the part



REPAIR 2 Page 204 Jul 10/2004




- (c) The edge of other damage. This does not include damage that is permitted and sealed as given in Allowable Damage 2.
- (2) Repair the damage as given in 51-70-04.
 - (a) Use the same number of repair plies as the number of initial plies that were removed.
 - (b) Add one structural ply of BMS 9-3, Type H-2 or Type H-3 glass fabric that is ± 45 degrees.
 - (c) Add a second structural ply of BMS 9-3, Type H-2 or Type H-3 glass fabric that is 0 or 90 degrees.
- E. Use the instructions that follow to do a Category A repair with wet layup materials at 200°F (93°C) cure.
 - (1) Repair the damage as given in 51-70-04.
 - (a) Use the same number of repair plies as the number of initial plies that were removed.
 - (b) Add one structural ply of BMS 9-3, Type H-2 or Type H-3 glass fabric that is ± 45 degrees.
 - (c) Add a second structural ply of BMS 9-3, Type H-2 or Type H-3 glass fabric that is 0 or 90 degrees.
- F. Use the instruction that follows to do a Category A repair with preimpregnated layup materials at 250°F (121°C) cure.
 - (1) Use the same number of repair plies as the number of initial plies that were removed.



REPAIR 2 Page 205 Jul 10/2004




IDENTIFICATION 1 - HORIZONTAL STABILIZER FITTINGS



Horizontal Stabilizer Fitting Location Figure 1 (Sheet 1 of 2)







Horizontal Stabilizer Fitting Location Figure 1 (Sheet 2 of 2)



D634A210


BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details




Table 1:

	REFERENCE DRAWINGS					
DRAWING NUMBER	TITLE					
001A8001	Section 82 Left Horizontal Stabilizer - Product Collector					
182A1500	Rear Spar Assembly/Installation - Horizontal Stabilizer					
185A0001	Trailing Edge Functional Collector - Left, Horizontal Stabilizer					
185A0003	Horizontal Stabilizer Rework Collector - Left Side					
185A1210	Clevis Installation - Trim Tab Lock, Horizontal Stabilizer					
185A1335	Rib Installation - Trailing Edge, Elevator Station 66.54, Rework					
185A1345	Rib Installation - Trailing Edge, Elevator Station 94.07, Rework					
185A1355	Rib Installation - Trailing Edge, Elevator Station 121.59, Rework					
185A1365	Rib Installation - Trailing Edge, Elevator Station 149.12, Rework					
185A1415	Rib Installation - Trailing Edge, Elevator Station 195.00, Rework					
185A1435	Rib Installation - Trailing Edge, Elevator Station 231.70, Rework					
186A0001	Leading Edge and Miscellaneous Functional Collector - Left Horizontal Stabilizer					
186A1000	Left Hand Horizontal - (Premodule)					
186A3000	Left Hand Horizontal Stabilizer Assembly - I/R					





LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE



Horizontal Stabilizer Rear Spar Termination Fitting Identification Figure 2



D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



Table 2:


LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Termination Fitting		Ti-6AI-4V machined titanium bar as given in MIL-T- 9047, in the annealed condition. Refer to the production drawing for the machined thicknesses	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





737-800 STRUCTURAL REPAIR MANUAL





Horizontal Stabilizer Outboard Closure Rib Fitting Identification Figure 3



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details





Table 3:

	LIST OF MATERIALS FOR FIGURE 3			
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Rib Fitting		7075-T7351 plate as given in QQ-A-250/12 (Grain direction controlled part) Refer to the production drawing for the machined thicknesses	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).












737-800 STRUCTURAL REPAIR MANUAL



HORIZONTAL STABILIZER ACCESS DOOR HINGE

Horizontal Stabilizer Hinge Plate Identification Figure 4 (Sheet 2 of 2)





Table 4:


		LIST OF	MATERIALS FOR FIGURE 4	
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Hinge Plate (2)		7075-T7351 rolled plate as given in QQ-A-250/12. Refer to the production drawing for the material thickness (Grain direction controlled part)	
[2]	Hinge Plate	0.70 (17.8)	7075-T7351 rolled plate as given in QQ-A-250/12 (Grain direction controlled part)	Cum Line Numbers 1 thru 84
		0.70 (17.8)	7050-T7451 rolled plate as given in BMS 7-323	Cum Line Numbers 1 1 thru 84 with SB 1067 incorporated and Cum Line Number 85 and on
[3]	Hinge Plate (2)	0.70 (17.8)	7075-T7351 rolled plate as given in QQ-A-250/12 (Grain direction controlled part)	Cum Line Numbers 1 thru 84
		0.70 (17.8)	15-5PH CRES plate as given in BMS 7-240 Type I, heat treated to 150 to 170 KSI	Cum Line Numbers 1 thru 84 with SB 1067 incorporated and Cum Line Number 85 and on
[4]	[4] Hinge Plate	0.50 (12.7)	7075-T7351 plate hogout as given in QQ-A-250/12 (Optional: 2024-T3511 extrusion as given in QQ-A- 200/3)	Cum Line Numbers 1 thru 84
		0.50 (12.7)	15-5PH CRES plate as given in BMS 7-240 Type I, Heat Treated to 150 to 170 KSI	Cum Line Numbers 1 thru 84 with SB 1067 incorporated and Cum Line Number 85 and on
[5]	Hinge Plate	0.50 (12.7)	7075-T7351 rolled plate as given in QQ-A-250/12 (Grain direction controlled part)	Cum Line Numbers 1 thru 84
		0.50 (12.7)	15-5PH CRES plate as given in BMS 7-240 Type I, Heat Treated to 150 to 170 KSI	Cum Line Numbers 1 thru 84 with SB 1067 incorporated and Cum Line Number 85 and on
[6]	Hinge Plate	0.50 (12.7)	7075-T7351 rolled plate as given in QQ-A-250/12 (Grain direction controlled part)	Cum Line Numbers 1 thru 84
		0.50 (12.7)	7050-T7451 rolled plate as given in BMS 7-323 (Grain direction controlled part)	Cum Line Numbers 1 thru 84 with SB 1067 incorporated and Cum Line Number 85 and on
[7]	Hinge Half	0.50 (12.7)	7075-T7351 plate hogout as given in QQ-A-250/12 (Optional: 2024-T3511 extrusion as given in QQ-A- 200/3)	
[8]	Hinge Half		BAC1520-2321 7075-T73511 extrusion as given in QQ-A-200/11 (Optional: 2024-T3511 extrusion as given in QQ-A-200/3 or 7075-T7351 plate as given in QQ-Q-250/12 that is 0.50 inch (12.7 mm) thick)	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





737-800 STRUCTURAL REPAIR MANUAL



Trim Tab Lock Clevis Identification Figure 5



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



Table 5:

	LIST OF MATERIALS FOR FIGURE 5			
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Clevis		7050-T7451 plate as given in AMS 4050	


*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





737-800 STRUCTURAL REPAIR MANUAL

IDENTIFICATION 2 - HORIZONTAL STABILIZER CENTER SECTION BEAM FITTINGS



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Horizontal Stabilizer Center Section Beam Fitting Locations Figure 1


Table 1:

	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
181A3000	Beam Installation - Center Section Horizontal Tail				
181A3102	Extruded Details - Primary Beam, Center Section Horizontal Tail				





737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Horizontal Stabilizer Center Section Primary Beam Fittings Identification Figure 2





Table 2:


	LIST OF MATERIALS FOR FIGURE 2			
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Attach Fitting (2)		Ti-6AI-4V machined titanium bar as given in MIL-T- 9047, in the annealed condition. Refer to the production drawing for the machined thicknesses	
[2]	Splice Fitting (2)		7075-T73511 extruded bar, as given in QQ-A-200/11, Class A. Refer to the production drawing for the machined thicknesses	
[3]	Attach Fitting (2)		Ti-6AI-4V machined titanium bar as given in MIL-T- 9047, in the annealed condition. Refer to the production drawing for the machined thicknesses	
[4]	Attach Fitting (2)		Ti-6Al-4V machined titanium bar as given in MIL-T- 9047, in the annealed condition. Refer to the production drawing for the machined thicknesses	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 3 FOR THE LIST OF MATERIALS.

Horizontal Stabilizer Center Section Thrust Beams Fittings Identification Figure 3






Table 3:

	LIST OF MATERIALS FOR FIGURE 3				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY	
[1]	Splice Fitting		BAC1520-1387 7075-T73511 extrusion as given in QQ-A-200/11. (Optional: 7050-T7451 plate as given in AMS 4050, Class A. Refer to the production drawing for the machined thicknesses and grain direction)		
[2]	Shear Tie Fitting (2)		7050-T7451 plate as given in BMS 7-323, Type I. Refer to the production drawing for the machined thicknesses and grain direction		

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).







Horizontal Stabilizer Center Section Aft Spar Fittings Identification Figure 4





Table 4:

	LIST OF MATERIALS FOR FIGURE 4			
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Upper Fitting		Ti-6AI-4V titanium forging as given in BMS 7-247, in the annealed condition. Refer to the production drawing for the machined thicknesses and grain direction	
[2]	Lower Fitting		7050-T74 forging as given in BMS 7-214, Class A. Refer to the production drawing for the machined thicknesses and grain direction	
[3]	Hinge Housing (2) Fitting		Ti-6AI-4V titanium as given in MIL-T-9046, Composition AB-1. Refer to the production drawing for the machined thicknesses and grain direction	
[4]	Brace Fitting (4)		7050-T7451 plate as given in AMS 4050, Class A. Refer to the production drawing for the machined thicknesses and grain direction	
[5]	Attach Fitting (2)		Ti-6AI-4V machined titanium bar as given in MIL-T- 9047, in the annealed condition. Refer to the production drawing for the machined thicknesses and grain direction	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





REPAIR 1 - HORIZONTAL STABILIZER OUTBOARD CLOSURE RIB LIGHTNING STRIKE REPAIR

1. Applicability

A. Repair 1 is applicable to damage from a lightning strike to the aft end of the horizontal stabilizer outboard closure rib upper and lower flange and to the tip cap attachment fasteners and nutplates.

2. General


A. Repair 1 is a Category A Repair. Refer to 51-00-06 for the definitions of the different types of repairs.

3. <u>References</u>

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-20-06	SHOT PEENING
51-30-01, GENERAL	Sheet Metal Materials
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-40-05	FASTENER HOLE SIZES
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-10-03	General - Shot Peening Procedures
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes
737 NDT Part 6, 51-00-00, Figure 3	Investigation of Fire Damage on Aircraft Structure
737 NDT Part 6, 51-00-00, Figure 4	Surface Inspection of Aluminum Parts
737 NDT Part 6, 51-00-00, Figure 8	Inspection of Subsurface Cracks in Aluminum Structure
737 NDT Part 6, 51-00-00, Figure 9	Inspection of Subsurface Cracks at Fastener Holes in Aluminum Structure

4. Repair Instructions

- A. Get access to the damaged area.
 - (1) Remove the necessary fasteners in the area of the damaged skin. Refer to 51-40-02, GENERAL.
 - (2) Remove the horizontal stabilizer outboard closure rib tip cap, as necessary.
 - (3) Remove the upper and/or lower horizontal stabilizer outboard aft trailing edge skin panels, as necessary.
 - (4) Remove the nutplates, as necessary, to install the Part [1] repair channel, as shown in Figure 201/REPAIR 1.
- B. Cut and remove the damaged part of the horizontal stabilizer outboard closure rib upper and/or lower aft flange, if necessary, as shown in Figure 201/REPAIR 1. Refer to 51-10-02, GENERAL.



REPAIR 1 Page 201 Nov 10/2007



- (1) Make the cut as shown in Figure 201/REPAIR 1.
 - (a) Refer to 51-10-02 for the inspection and removal of damage.
 - (b) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (c) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (d) Make sure the surface smoothness for all cut surfaces is 63 microinches (Ra) or smoother.
- C. Do a High Frequency Eddy Current (HFEC) inspection of the repair area to make sure that all of the damage is removed. Do a 0.040 inch (1.02 mm) insurance cut if no further damage is found. Refer to 737 NDT Part 6, 51-00-00, Figure 3, 737 NDT Part 6, 51-00-00, Figure 4, 737 NDT Part 6, 51-00-00, Figure 8 and 737 NDT Part 6, 51-00-00, Figure 9.
- D. Flap peen or shot peen the cut edges of the horizontal stabilizer outboard closure rib flange.
 - (1) Refer to 51-20-06 for shot peen intensity and shot number.
 - (2) Refer to SOPM 20-10-03 for flap peen and shot peen procedures.
- E. Make the repair parts as given in Table 201.
- F. Make the contour of the repair parts the same as the contour of the initial parts, as necessary. Refer to 51-30-01, GENERAL.
- G. Remove the horizontal stabilizer outboard closure rib finish that is common to the Part [1] repair channel.
- H. Assemble the repair parts as shown in Figure 201/REPAIR 1.

REPAIR MATERIAL					
ITEM	ITEM PART QUANTITY		MATERIAL		
[1]	Repair Channel	1	7075–T7351 plate, machined to a final thickness of 0.080 inch (0.20 cm), as given in drawing 182A5201, or 7075–0 sheet, 0.080 inch (0.20 cm) thick, heat treat to T73 after forming		
[2]	Filler	1	7075-T73 bare sheet, 0.050 inch (0.13 cm) thick		
[3]	Filler	1	7075–T73 bare sheet, 0.050 inch (0.13 cm) thick		

Table 201:

- Drill the necessary fastener holes in the repair parts. Use the initial fastener type, diameter and locations in the upper and lower flanges at the aft end of the horizontal stabilizer outboard closure rib. Refer to 51-40-05 for the fastener hole dimensions.
 - (1) Do not countersink the fastener holes more than 76 percent of the initial flange thickness.
 - (a) This will prevent a knife-edge condition of the initial flange.
- J. Disassemble the repair parts.
- K. Remove all the nicks, scratches, burrs, and sharp edges from the repair parts and bare surfaces of the initial parts.
- L. Install the repair parts dry.
 - (1) Do not apply sealant to the mating surfaces.
 - (2) Install the repair fasteners without sealant.
- M. Apply a chemical conversion coating to the repair parts and to the bare surfaces of the initial parts. Refer to 51-20-01.



REPAIR 1 Page 202 Nov 10/2006




- N. Apply two layers of BMS 10-11, Type I primer to the repair parts and to the bare surfaces of the initial parts, other than at areas common to the static wicks. Refer to SOPM 20-41-02.
- O. Fillet seal the repair parts and fill all gaps with BMS 5-95 sealant. Refer to 51-20-05.
- P. Attach the initial nutplates from 4.A.(4) above to the repair parts as shown in Figure 201/REPAIR 1.
 - (1) The initial nutplate fasteners will go through the Part [1] repair channel and the initial horizontal stabilizer outboard closure rib or the repair fillers, as shown in Figure 201/REPAIR 1.
- Q. Do a resistance check between the Part [1] repair channel and the initial horizontal stabilizer outboard closure rib as given in BAC 5117–6. Maximum resistance permitted is 0.010 ohms.
- R. Apply a layer of BMS 3-23, corrosion inhibiting compound, to all the interior structure of the repair area.
- S. Install the initial horizontal stabilizer outboard closure rib tip cap as given in drawing 189A1001.
- T. Install the initial upper and/or lower horizontal stabilizer outboard aft trailing edge skin panels as given in drawing 185A1801.
- U. Do a resistance check between the fastener head and the initial structure as given in BAC 5117–6. Maximum resistance permitted is 0.010 ohms.
- V. Apply a decorative finish if necessary. Refer to AMM PAGEBLOCK 51-21-99/701.



REPAIR 1 Page 203 Nov 10/2007



737-800 STRUCTURAL REPAIR MANUAL




Layout of the Repair Parts Figure 201 (Sheet 1 of 3)



REPAIR 1 Page 204 Nov 10/2005


BOEING®

737-800 STRUCTURAL REPAIR MANUAL






A-A



B-B




REPAIR 1 Page 205 Nov 10/2005

55-10-90



737-800 STRUCTURAL REPAIR MANUAL



NOTES

- 1 MAKE SURE THERE IS A MINIMUM OF 2D EDGE MARGIN.
- 2 MAKE SURE THERE IS A MINIMUM OF 3D TO 5D FASTENER SPACING FOR ALL NEW FASTENERS.
- 3 MAKE SURE THERE IS A MINIMUM OF 4D TO 6D FASTENER SPACING FOR ALL NEW FASTENERS.
- 4 MAKE SURE THERE IS A MAXIMUM OF 0.010 INCH GAP BETWEEN THE INITIAL PARTS AND THE REPAIR PARTS.

FASTENER SYMBOLS

- ↔ INITIAL FASTENER LOCATION. INSTALL THE SAME TYPE AND SIZE AS THE INITIAL FASTENER. REPLACE ANY DAMAGED NUT PLATES OR FASTENERS.
- ---- REFERENCE FASTENER LOCATION
- \oplus REPAIR FASTENER LOCATION. INSTALL A BACB30VT6 BOLT AND A BACC30BL COLLAR WITH COLLAR OUTBOARD. 1 > 3 > 4
- + REPAIR FASTENER LOCATION. INSTALL A BACR15CE6 RIVET. 1 > 2 > 4 > 4


Layout of the Repair Parts Figure 201 (Sheet 3 of 3)



REPAIR 1 Page 206 Nov 10/2005



IDENTIFICATION 1 - ELEVATOR UPPER SKIN



Elevator Upper Skin Location Figure 1


Table 1:

REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE			
183A0000	Elevator Installation			
183A0001	Elevator Integration Functional Product Collector			
183A0101	Elevator Assembly Functional Product Collector			
183A3000	Upper Skin Panel Installation - Elevator			





737-800 STRUCTURAL REPAIR MANUAL



(FOR AIRPLANE LINE NUMBERS 1 THRU 1174)

NOTES

• REFER TO TABLE 2 FOR THE LIST OF MATERIALS.


Elevator Upper Skin Identification Figure 2 (Sheet 1 of 2)



IDENTIFICATION 1 Page 2 Mar 10/2004


BOEING"

737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE SHOWN, RIGHT SIDE OPPOSITE (FOR AIRPLANE LINE NUMBERS 1175 AND ON)

Elevator Upper Skin Identification Figure 2 (Sheet 2 of 2)



IDENTIFICATION 1 Page 3 Nov 01/2003



Table 2:


LIST OF MATERIALS FOR FIGURE 2						
ITEM	DESCRIPTION	T*[1]	MATERIAL	EFFECTIVITY		
[1]	Elevator Upper Skin - Bonded Part		Carbon Fiber Reinforced Plastic (CFRP) woven fabric as given in BMS 8-256, Type IV, Class II, Style 3K-70-PW			
	Skin		Refer to Figure 3			
	Core (Inboard closure rib to ELEV STA 39.020)		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			
	Core (ELEV STA 39.020 to ELEV STA 132.39)		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			
	Core (Elev STA 132.39 to outboard closure rib)		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			
[2]	Hinge Cover		Epoxy sheet molding compound as given in BMS 8-327, Type I, Lytex 9063			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





737-800 STRUCTURAL REPAIR MANUAL



REFER TO TABLE 3 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN SECTIONS A-A, B-B, C-C, AND D-D.


Ply Direction, Core Ribbon Direction, and Ply Sequence for the Elevator Upper Skin Panel, Figure 2, Item [1] Figure 3 (Sheet 1 of 2)




IDENTIFICATION 1 Page 5 Mar 10/2004

BOEING®


737-800 STRUCTURAL REPAIR MANUAL




A-A



C-C



B–B



Ply Direction, Core Ribbon Direction, and Ply Sequence for the Elevator Upper Skin Panel, Figure 2, Item [1] Figure 3 (Sheet 2 of 2)

> IDENTIFICATION 1 55-20-01 Page 6 Nov 01/2003




Table 3:

PLY MATERIAL AND DIRECTION FOR FIGURE 3					
PLY	DIRECTION	MATERIAL			
P1		Surface composite film as given in BMS 8-341 Type II			
P2, P6, P8, P10, P11, P12, P16, P17, P18, P19, P23, P24, P26, P28, P32, P34, P36, P43, P44, P45, P46, P51, P52, P57, P58, P59, P60	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW			
P3, P4, P5, P7, P9, P13, P14, P15, P20, P21, P22, P25, P27, P29, P30, P31, P33, P35, P41, P42, P47, P48, P49, P50, P53, P54, P55, P56	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW			
P37, P38, P39	0 or 90 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-139, Style 108			
P40		1 mil White Tedlar as given in BAC 5317-4			





IDENTIFICATION 2 - ELEVATOR LOWER SKIN



Elevator Lower Skin Location Figure 1


Table 1:

REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE			
183A0000	Elevator Installation			
183A0001	Elevator Integration Functional Product Collector			
183A0101	Elevator Assembly Functional Product Collector			
183A3010	Lower Skin Panel Installation - Elevator			





737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE (FOR AIRPLANE LINE NUMBERS 1 THRU 1174)

NOTES


• REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Elevator Lower Skin Identification Figure 2 (Sheet 1 of 2)



IDENTIFICATION 2 Page 2 Mar 10/2004

737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE (FOR AIRPLANE LINE NUMBERS 1175 AND ON)

Elevator Lower Skin Identification Figure 2 (Sheet 2 of 2)



IDENTIFICATION 2 Page 3 Nov 01/2003

D634A210

BOEING PROPRIETARY - Copyright ${\rm (\sc)}$ Unpublished Work - See title page for details




Table 2:

LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Elevator Lower Skin - Bonded Part		Carbon Fiber Reinforced Plastic (CFRP) woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	
	Skin		Refer to Figure 3	
	Core (Inboard closure rib to ELEV STA 39.02)		Aramid honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0	
	Core (ELEV STA 39.02 to ELEV STA 132.39)		Aramid honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0	
	Core (ELEV STA 132.39 to outboard closure rib)		Aramid honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0	
[2]	Hinge Cover		Epoxy sheet molding compound as given in BMS 8-327, Type I, Lytex 9063	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).








Ply Direction, Core Ribbon Direction, and Ply Sequence for the Elevator Upper Skin Panel, Figure 2, Item [1] Figure 3 (Sheet 1 of 2)




IDENTIFICATION 2 Page 5 Mar 10/2004

BOEING®

737-800 STRUCTURAL REPAIR MANUAL





IDENTIFICATION 2 Page 6 Nov 01/2003




Table 3:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [1]		
PLY	DIRECTION	MATERIAL
P1		Composite surfacing film as given in BMS 8-341, Type II
P2, P5, P7, P9, P10, P13, P14, P15, P16, P19, P21, P23, P26, P27, P30, P37, P38, P39, P40, P44, P45, P46, P51, P52, P53, P56, P57	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P3, P4, P6, P8, P11, P12, P17, P18, P20, P22, P24, P25, P28, P29, P35, P36, P41, P42, P43, P47, P48, P49, P50, P54, P55	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P31, P32, P33	0 or 90 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-139, Style 108
P34		1 mil White Tedlar as given in BAC5317-4





IDENTIFICATION 3 - ELEVATOR TAB SKINS




NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Elevator Tab Skin Locations Figure 1

Table 1:

	REFERENCE DRAWINGS		
DRAWING NUMBER	TITLE		
183A8000	Elevator Tab Installation		
183A8100	Elevator Tab Assembly		
183A8200	Elevator Tab Bonded Part		
183A8210	Elevator Tab Skins Bonded Part		
183A8220	Elevator Tab Spar and Leading Edge Bonded Part		
183A8230	Elevator Tab End Closures		





NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.


Elevator Tab Skin Identification Figure 2 (Sheet 1 of 2)




IDENTIFICATION 3 Page 2 Mar 10/2004



737-800 STRUCTURAL REPAIR MANUAL



ELEVATOR TAB SKIN (FOR AIRPLANE LINE NUMBERS 1 THROUGH 1174)



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

A-A

Elevator Tab Skin Identification Figure 2 (Sheet 2 of 2)



IDENTIFICATION 3 Page 3 Nov 01/2003



Table 2:


LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Elevator Tab Skin Assembly - Bonded Part		Carbon Fiber Reinforced Plastic (CFRP) woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	
	Upper Skin		Refer to Figure 3	
	Lower Skin		Refer to Figure 4	
	Leading Edge Skin		Refer to Figure 5	
	Outer Skin		Refer to Figure 6	For airplane line numbers 1175 and on
	Core		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE VIEW IS ON THE TOOLSIDE (AERODYNAMIC) SURFACE PLY LAYUP DIRECTION AND CORE RIBBON DIRECTION

NOTES


- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PANEL.
- REFER TO SECTIONS A-A AND B-B FOR THE PLY SEQUENCE FOR THOSE LOCATIONS.
- REFER TO THE ENGINEERING DRAWING FOR MORE INFORMATION.
- REFER TO TABLE 3 FOR THE DIRECTION AND MATERIAL OF EACH PLY.

Ply Direction, Core Ribbon Direction and Ply Sequence for the Elevator Tab Upper Skin, Figure 2, Item [1] Figure 3 (Sheet 1 of 2)




IDENTIFICATION 3 Page 5 Mar 10/2004

BDEING® 737-800 STRUCTURAL REPAIR MANUAL



PLY LAYUP SEQUENCE

A-A



Ply Direction, Core Ribbon Direction and Ply Sequence for the Elevator Tab Upper Skin, Figure 2, Item [1] Figure 3 (Sheet 2 of 2)






Table 3:

PLY MATERIAL AND DIRECTION FOR FIGURE 3		
PLY	DIRECTION	MATERIAL
P1, P4	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW.
P2, P3	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW.
P5 through P30	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW.







LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE VIEW IS ON THE TOOLSIDE (AERODYNAMIC) SURFACE PLY LAYUP DIRECTION AND CORE RIBBON DIRECTION (A)

NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PANEL.
- REFER TO SECTIONS A-A AND B-B FOR THE PLY SEQUENCE FOR THOSE LOCATIONS.
- REFER TO THE ENGINEERING DRAWING FOR MORE INFORMATION.
- REFER TO TABLE 4 FOR THE DIRECTION AND MATERIAL OF EACH PLY.


Ply Direction, Core Ribbon Dirction and Ply Sequence for the Elevator Tab Lower Skin, Figure 2, Item [1] Figure 4 (Sheet 1 of 2)



IDENTIFICATION 3 Page 8 Mar 10/2004




737-800 STRUCTURAL REPAIR MANUAL



VIEW IS ROTATED 90° COUNTERCLOCKWISE

PLY LAYUP SEQUENCE A-A



VIEW IS ROTATED 90° COUNTERCLOCKWISE PLY LAYUP SEQUENCE B-B

Ply Direction, Core Ribbon Dirction and Ply Sequence for the Elevator Tab Lower Skin, Figure 2, Item [1] Figure 4 (Sheet 2 of 2)




IDENTIFICATION 3 Page 9 Nov 01/2003



Table 4:

PLY MATERIAL AND DIRECTION FOR FIGURE 4		
PLY	DIRECTION	MATERIAL
P1, P4	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW.
P2, P3	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW.





A-A

NOTES

- THE PLY DIRECTION IS THE WRAP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PANEL.
- REFER TO SECTION A-A FOR THE PLY SEQUENCE FOR THAT LOCATION.
- REFER TO THE ENGINEERING DRAWING FOR MORE INFORMATION.
- REFER TO TABLE 5 FOR THE DIRECTION AND THE MATERIAL OF EACH PLY.

Ply Direction and Ply Sequence for the Elevator Tab Leading Edge Skin Figure 2, Item [1] Figure 5






Table 5:

PLY MATERIAL AND DIRECTION FOR FIGURE 5		
PLY	DIRECTION	MATERIAL
P1, P3	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P2	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW





737-800 STRUCTURAL REPAIR MANUAL



PLY DIRECTION AND PLY SEQUENCE FOR THE ELEVATOR TAB SKIN - FIGURE 2, ITEM 1 (TYPICAL SECTION AT HINGES 3 AND 4) (FOR AIRPLANE LINE NUMBERS 1175 AND ON)

NOTES

- 11 PLIES AT HINGES 1 AND 2
- 10 PLIES AT HINGES 3 AND 4
- 7 PLIES AT HINGES 5 AND 6

Ply Direction and Ply Sequence for the Elevator Tab Outer Skin Figure 6



Page 13 Mar 10/2004



Table 6:

PLY MATERIAL AND DIRECTION FOR FIGURE 6 (REFER TO THE PRODUCTION DRAWING FOR THE OTHER HINGE LOCATIONS)		
PLY	DIRECTION	MATERIAL
P1		Structural Adhesive as given in BMS 5-129, Type 4, Grade 5
P4, P7, P10	+45 degrees	CFRP unidirectional tape as given in BMS 8-256, Type II, Class 1, Grade 190
P3, P8, P11	-45 degrees	CFRP unidirectional tape as given in BMS 8-256, Type II, Class 1, Grade 190
P2, P5, P6, P9	+/- 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW






ALLOWABLE DAMAGE 1 - UPPER AND LOWER ELEVATOR SKIN PANELS

1. Applicability

A. Allowable Damage 1 is applicable to damage on the Upper and Lower Elevator Skin made of carbon fiber reinforced plastic (CFRP) shown in Upper and Lower Elevator Skin Location, Figure 101/ALLOWABLE DAMAGE 1.



Upper and Lower Elevator Skin Location Figure 101

2. General


- A. Do an inspection of the damaged area to find the dimensions of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to 737 NDT Part 1, 51-01-02 for the inspection procedures
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator, can be used.
 - (1) For the honeycomb core areas, the tap test is an alternative procedure to an instrumented NDT.
 - (2) Refer to Damage Definitions, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, and C for the definitions of the length, width, and depth of the damage.
 - (3) Refer to Definitions of the Facesheets, Figure 103/ALLOWABLE DAMAGE 1 for the definitions of the facesheets of a honeycomb core area.
- B. Remove all the contaminates and water from the structure. Refer to 51-30-05 and 51-70-04 for the tools and the cleanup procedures.
- C. Seal all damaged areas with the steps that follow.
 - (1) Seal the damage that is not more than one ply deep and that agrees with the allowable damage limits as given in Paragraph 4./ALLOWABLE DAMAGE 1





- (a) Make a temporary seal.
 - 1) Apply aluminum foil tape (speed tape).
 - 2) Keep a record of the location.
 - 3) Make sure the tape is in satisfactory condition at normal maintenance intervals.
- (b) Make a permanent seal.
 - 1) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given in 51-70-08.
 - 2) Apply one layer of BMS 10-79, Type 3 or BMS 10-103, Type 1 primer. Refer to SOPM 20-44-04.
 - Apply one layer of BMS 10-60, Type II enamel to the areas sealed with epoxy resin. Refer to AMM 51-21-00/701.
- (2) Seal all permitted damaged areas that are more than one ply deep. Refer to Paragraph 4./ALLOWABLE DAMAGE 1 for the allowable damage limits. Seal the damage as follows:
 - (a) Use a vacuum and heat to remove moisture from the solid laminate and the honeycomb cells. Refer to 51-70-04.
 - (b) Make a temporary seal with aluminum foil tape (speed tape).
 - (c) Keep a record of the location.
 - (d) Repair the damage at or before 250 flight cycles from the time the seal was made.
- (3) Refer to Upper and Lower Elevator Skin Panel Zones, Figure 104/ALLOWABLE DAMAGE 1 for the location of the elevator skin panel zones.
- (4) The definition of the words "other damage" as used in the allowable damage limit, does not include nicks, gouges, and scratches that do not cause carbon fiber damage are sealed.
- (5) Make sure the elevator is balanced. Refer to 51-60-04 for the balance procedures.











737-800 STRUCTURAL REPAIR MANUAL



Definitions of the Facesheets Figure 103






LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE UPPER SKIN PANEL IS SHOWN, LOWER SKIN PANEL IS ALMOST THE SAME

> Upper and Lower Elevator Skin Panel Zones Figure 104 (Sheet 1 of 4)

> > ALLOWABLE DAMAGE 1 55-20-01 Page 105 Mar 10/2004




Upper and Lower Elevator Skin Panel Zones Figure 104 (Sheet 2 of 4)

> ALLOWABLE DAMAGE 1 55-20-01 Page 106 Mar 10/2004



737-800 STRUCTURAL REPAIR MANUAL




Upper and Lower Elevator Skin Panel Zones Figure 104 (Sheet 3 of 4)



Page 107

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details





ELEV STA 176.64 IS SHOWN, ELEV STA 213.32 IS SIMILAR UPPER SKIN HINGE CUTOUT

В

ZONE 9

Upper and Lower Elevator Skin Panel Zones Figure 104 (Sheet 4 of 4)



D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



3. References

Reference	Title
51-10-01, GENERAL	Aerodynamic Smoothness Requirements
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05, GENERAL	Repair Sealing
51-30-03, GENERAL	Sources for Non-Metallic Repair Materials
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-60-04	ELEVATOR BALANCE PROCEDURE
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-06, REPAIR GENERAL	Room Temperature Cure Repairs With Wet Layup Materials For Glass Fabric Reinforced Plastic Solid Laminates and Honeycomb Core Panels
51-70-08	RESIN SWEEP-FAIR PROCEDURES
AMM 51-21-00/701	Interior And Exterior Finishes - Cleaning/Painting
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Allowable Damage Limits

- A. Zone 1, 2 and 3 Honeycomb Core Area
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
 - (3) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum of 5.00 inches in length
- (c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies and
 - 2) Are sealed as given in Paragraph 2.
- (4) Dents that do not cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one carbon ply in depth
 - **NOTE**: Use the limits for holes and punctures if the damage is more than one carbon ply in depth.
 - (b) A maximum of 2.00 inches in diameter
 - (c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies and
 - 2) Are sealed as given in Paragraph 2.





- (5) Holes and Punctures are permitted if they are:
 - (a) A maximum of 2.00 inches in diameter
 - (b) A minimum of 5.00 inches away from the edge of other damage. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies and
 - 2) Are sealed as given in Paragraph 2.
- (6) Delaminations are permitted if they are:
 - (a) A maximum of 2.00 inches in diameter of the carbon ply
 - (b) A minimum distance of 5.00 inches away from the edge of other damage. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass or carbon fiber plies and
 - 2) Are sealed as given in Paragraph 2.
- B. Zone 4 and 5 CFRP Solid Laminate Area
 - (1) Nicks, Gouges, and Scratches that cause damage to the glass fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
 - (3) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if:
 - (a) The depth is a maximum of one ply.

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth

- (b) The length is a maximum of 0.625 inch
- (c) The width is a maximum of 0.25 inch
- (d) Not more than one fastener or fastener hole in eight is damaged
- (e) The edge of other damage is a minimum of 5.00 inches away from the edge of other damage. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the fiber plies and
 - 2) Are sealed as given in Paragraph 2.
- (4) Dents are permitted if:
 - (a) Not more than one fastener or fastener hole in eight is damaged
 - (b) They are a maximum of 1 ply in depth
 - (c) They are a maximum of 0.625 inch in diameter
 - (d) They are a minimum of 5.00 inches away from the edge of other damage. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the fiber plies and
 - 2) Are sealed as given in Paragraph 2.
- (5) Holes and Punctures are permitted if:
 - (a) Not more than one fastener or fastener hole in eight is damaged
 - (b) They are a maximum of 0.625 inch in diameter
 - (c) They are a minimum distance of 5.00 inches away from the edge of other damage. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies and






- 2) Are sealed as given in Paragraph 2.
- (6) Delaminations are permitted if:
 - (a) Not more than one fastener or fastener hole in eight is damaged
 - (b) They are a maximum of 0.625 inch in diameter
 - (c) They are a minimum of 5.00 inches away from the edge of other damage. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies
 - 2) Are sealed as given in Paragraph 2.
- (7) Edge Erosion is permitted as shown in Upper and Lower Elevator Skin Panel Allowable Damage, Figure 105/ALLOWABLE DAMAGE 1.
- (8) Edge damage is permitted if it is:
 - (a) A maximum of one carbon ply in depth
 - (b) A maximum of 0.25 inch in width.
- C. Zone 6 Solid Laminate Area (Upper Skin)
 - (1) Damage is permitted provided:
 - (a) The maximum cross sectional area loss is not more than 0.30 square inches
 - (b) It is sealed as given in Paragraph 2.
- D. Zone 7 Solid Laminate Area (Upper Skin)
 - (1) Damage is permitted for the entire thickness of the part provided:
 - (a) The maximum length of damage away from the cutout is not more than 0.25 inch
 - (b) It is sealed as given in Paragraph 2.
- E. Zone 8 Solid Laminate Area (Upper Skin)
 - (1) Damage is permitted provided:
 - (a) The maximum cross sectional area loss is not more than 0.50 square inches.
 - (b) It is sealed as given in Paragraph 2.
- F. Zone 9 Solid Laminate Area (Upper Skin)
 - (1) Damage is permited provided:
 - (a) The maximum cross sectional area loss is not more than 0.15 square inches.
 - (b) It is sealed as given in Paragraph 2.







SEALING OF EROSION DAMAGE AT AN EDGE OF COMPOSITE PARTS

Upper and Lower Elevator Skin Panel Allowable Damage Figure 105






ALLOWABLE DAMAGE 2 - ELEVATOR TAB SKINS

1. Applicability

- A. The allowable damage limits are only applicable if they are sealed as given in in Paragraph 2.C.
 - **NOTE**: THIS ALLOWABLE DAMAGE IS APPLICABLE TO AIRPLANE LINE NUMBERS 1 THROUGH 1174 PRIOR TO COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082. REFER TO 55-20-01, ALLOWABLE DAMAGE 3 FOR AIRPLANE LINE NUMBERS EQUAL TO OR GREATER THAN 1175 AND FOR ALL LINE NUMBERS WITH COMPLETIONS OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082.





Elevator Tab Skin Location Figure 101



BOEING"

737-800 STRUCTURAL REPAIR MANUAL





Elevator Tab Skin Figure 102

> ALLOWABLE DAMAGE 2 Page 102 Nov 01/2003



2. General

A. Do an inspection of the damaged area to find the length, width, and depth of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 for inspection procedures.

NOTE: Other equivalent inspection methods that have been examined and found to be satisfactory by the operator can be used.

- (1) For the honeycomb core areas, the tap test is an alternative procedure to an instrumented NDT.
- (2) Refer to Damage Definitions, Figure 103/ALLOWABLE DAMAGE 2, Details A, B, and C for the definitions of the length, width, and depth of damage.
- (3) Refer to Definitions of the Facesheets, Figure 104/ALLOWABLE DAMAGE 2 for the definitions of the facesheets of a honeycomb core area.
- B. Remove all the contamination and water from the structure.
 - (1) Refer to 51-30-03 for possible sources of the abrasive and other materials.
 - (2) Refer to 51-30-05 for possible sources of the equipment and tools.
 - (3) Refer to 51-70-04 for the cleanup procedures.
- **CAUTION:** DO NOT EXCEED A MAXIMUM OF FOUR PERMITTED DAMAGE LOCATIONS THAT ARE SEALED OR ONE REPAIR LOCATION AS GIVEN IN SRM 55-20-01, REPAIR 2. REPAIRS ARE NOT PERMITTED INBOARD OF ELEVATOR STA 45.0. FOR ANY REPAIRS INBOARD OF ELEVATOR STATION 45.0, CONTACT BOEING. IF YOU DO NOT OBEY, THEN DAMAGE TO STRUCTURE COULD OCCUR.
- C. Seal all damaged areas with the steps that follow.
 - (1) Seal the damage that is not more than one ply deep and that agrees with the allowable damage limits given in Paragraph 4./ALLOWABLE DAMAGE 2
 - (a) Make a temporary seal.
 - 1) Apply aluminum foil tape (speed tape).
 - 2) Keep a record of the location.
 - 3) Make sure the tape is in satisfactory condition at normal maintenance intervals.
 - (b) Make a permanent seal.
 - 1) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given in 51-70-08.
 - 2) Apply one layer of BMS 10-79, Type 3 or BMS 10-103, Type 1 primer. Refer to SOPM 20-44-04.
 - Apply one layer of BMS 10-60 enamel to the areas sealed with epoxy resin. Refer to AMM PAGEBLOCK 51-21-99/701.
 - (2) Seal all permitted damaged areas that are more than one ply deep. Refer to Paragraph 4./ALLOWABLE DAMAGE 2 for the allowable damage limits. Seal the damage as follows:
 - (a) Use a vacuum and heat to remove moisture from the solid laminate or the honeycomb cells. Refer to 51-70-04.
 - (b) Make a temporary seal with aluminum foil tape (speed tape).
 - (c) Keep a record of the location.
 - (d) Repair the damage before 250 flight cycles have occurred.






- D. Make sure the aerodynamic smoothness is satisfactory or there will be a decrease in the economic performance of the airplane.
- E. Restore the aircraft exterior paint system in the area where damage has been removed, as applicable. Refer to AMM PAGEBLOCK 51-21-99/701.
 - **NOTE**: Wherever the elevator tab skins need to be refinished, the initial finishes including paint, primer, and/or surface filler, must be removed before application of new exterior paint system. Make sure the finish thicknesses are as given in AMM PAGEBLOCK 51-21-99/701.
- F. Sealing of damage as given in Allowable Damage 2 is an Alternate Method of Compliance (AMOC) to the Federal Aviation Administration (FAA) Airworthiness Directive (AD) 2001-08-09, Paragraph (d).



BOEING

737-800 STRUCTURAL REPAIR MANUAL



D634A210 55-20-01


ALLOWABLE DAMAGE 2

Page 105

Nov 01/2003

DEDEING®

737-800 STRUCTURAL REPAIR MANUAL



Definitions of the Facesheets Figure 104



D634A210



3. References

Reference	Title
51-10-01, GENERAL	Aerodynamic Smoothness Requirements
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05, GENERAL	Repair Sealing
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-08	RESIN SWEEP-FAIR PROCEDURES
55-20-01	ELEVATOR SKIN
AMM 27-31-31 P/B 401	ELEVATOR TAB - REMOVAL/INSTALLATION
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Allowable Damage Limits

A. Upper and Lower Trailing Edge Skins - Honeycomb Core Area

- (1) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
- (2) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth.

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum diameter (D) of 1.0 inch
- (c) A minimum of 2.5 X (D) away from a fastener hole or part edge
- (d) A maximum of 2.0 X (D) edge to edge from any other damage, and no more than one damage site for each 15.0 square inches.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the carbon fiber plies
- Are sealed as given in Paragraph 2.C.
- (e) Sealed as given in in Paragraph 2.C.
- (3) Dents that do not cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of 1.0 inch in diameter
 - (b) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if there is carbon fiber damage or if the dent depth is more than one ply.

(c) A minimum of 2.5 X (D) away from a fastener hole or part edge



(d) A maximum of 2.0 X (D) edge to edge from any other damage, and no more than one damage site for each 15.0 square inches.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the carbon fiber plies
- Are sealed as given in in Paragraph 2.C.
- (e) Sealed as given in in Paragraph 2.C.
- (4) Holes and Punctures are permitted if they are:
 - (a) A maximum of 0.50 inch in diameter
 - (b) A minimum of 2.5 X (D) away from a fastener hole or part edge
 - (c) A maximum of 2.0 X (D) edge to edge from any other damage, and no more than one damage site for each 15.0 square inches.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the carbon fiber plies
- Are sealed as given in in Paragraph 2.C.
- (d) Sealed as given in in Paragraph 2.C.
- (5) Delaminations are permitted if they are:
 - (a) A maximum of 0.50 inch in diameter
 - (b) A minimum of 2.5 X (D) away from a fastener hole or part edge
 - (c) A maximum of 2.0 X (D) edge to edge from any other damage, and no more than one damage site for each 15.0 square inches.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the carbon fiber plies
- Are sealed as given in in Paragraph 2.C.
- (d) Sealed as given in in Paragraph 2.C.
- B. Leading Edge Solid Laminate Areas
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth.

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum of 1.00 inch in diameter
- (c) A minimum of 2.5 X (D) away from a fastener hole or part edge
- (d) A maximum of 2.0 X (D) edge to edge from any other damage, and no more than one damage site for each 15.0 square inches.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the carbon fiber plies
- Are sealed as given in in Paragraph 2.C.
- (e) Sealed as given in in Paragraph 2.C.
- (3) Dents that do not cause damage to the carbon fibers are permitted if they are:





- (a) A maximum of 1.00 inch in diameter
- (b) A maximum of one ply in depth

<u>NOTE</u>: Use the limits for holes and punctures if there is carbon fiber damage or if the dent depth is more than one ply in depth.

- (c) A minimum of 2.5 X (D) away from a fastener hole or part edge
- (d) A maximum of 2.0 X (D) edge to edge from any other damage, and no more than one damage site for each 15.0 square inches.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the carbon fiber plies
- Are sealed as given in in Paragraph 2.C.
- (e) Sealed as given in in Paragraph 2.C.
- (4) Holes and Punctures are permitted if they are:
 - (a) A maximum of 0.50 inch in diameter
 - (b) A minimum of 2.5 X (D) away from a fastener hole or part edge
 - (c) A maximum of 2.0 X (D) edge to edge from any other damage, and no more than one damage site for each 15.0 square inches.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the carbon fiber plies
- Are sealed as given in in Paragraph 2.C.
- (d) Are sealed as given in in Paragraph 2.C.
- (5) Delaminations are permitted if they are:
 - (a) A maximum of 0.50 inch in diameter
 - (b) A minimum of 2.5 X (D) away from a fastener hole or part edge
 - (c) A maximum of 2.0 X (D) edge to edge from any other damage, and no more than one damage site for each 15.0 square inches.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the carbon fiber plies
- Are sealed as given in in Paragraph 2.C.
- (d) Sealed as given in in Paragraph 2.C.
- (6) Edge Erosion is permitted as shown in Elevator Tab Skin Allowable Damage, Figure 105/ALLOWABLE DAMAGE 2, Detail A .
- (7) Edge damage not more than one ply in depth is permitted if it is:
 - (a) A maximum of 2.00 inches in length in the spanwise direction
 - (b) A maximum of 0.50 inch in width
 - (c) A maximum of 2.0 X (D) edge to edge from any other damage, and no more than one damage site for each 15.0 square inches.
 - (d) Not more than the limits as shown in Elevator Tab Skin Allowable Damage, Figure 105/ALLOWABLE DAMAGE 2, Detail A .
- (8) Edge damage that is more than one ply in depth is permitted if:






- (a) It is not more than the limits as shown in Elevator Tab Skin Allowable Damage, Figure 105/ALLOWABLE DAMAGE 2, Details B, C, and D.
- (b) You remove moisture and seal as given in Paragraph 2.B./ALLOWABLE DAMAGE 2 and Paragraph 2.C./ALLOWABLE DAMAGE 2









SEALING OF EROSION DAMAGE AT AN EDGE OF COMPOSITE PARTS (A)

Elevator Tab Skin Allowable Damage Figure 105 (Sheet 1 of 2)




D634A210

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL




BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details



ALLOWABLE DAMAGE 3 - ELEVATOR TAB SKINS FOR AIRPLANE LINE NUMBERS 1175 AND ON AND LINE NUMBERS 1 THROUGH 1174 WITH COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082


1. Applicability

- A. The allowable damage limits are only applicable if they are sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
 - NOTE: THIS ALLOWABLE DAMAGE IS APPLICABLE TO AIRPLANE LINE NUMBERS 1175 AND ON AND LINE NUMBERS 1 THROUGH 1174 WITH COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082. REFER TO 55-20-01, ALLOWABLE DAMAGE 2 FOR AIRPLANE LINE NUMBERS 1 THROUGH 1174 PRIOR TO COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082.



Elevator Tab Skin Location Figure 101







ALLOWABLE DAMAGE 3 Page 102 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL





(FOR AIRPLANE LINE NUMBERS 1 THRU 1174 WITH COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082) A-A

> Elevator Tab Skin Allowable Damage Figure 102 (Sheet 2 of 2)

> > ALLOWABLE DAMAGE 3 Page 103 Nov 01/2003

D634A210



2. General

A. Do an inspection of the damaged area to find the length, width, and depth of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 for inspection procedures.


NOTE: Other equivalent inspection methods that have been examined and found to be satisfactory by the operator can be used.

- (1) For the honeycomb core areas, the tap test is an alternative procedure to an instrumented NDT.
- (2) Refer to Damage Definitions, Figure 103/ALLOWABLE DAMAGE 3, Details A, B, and C for the definitions of the length, width, and depth of damage.
- (3) Refer to Definitions of the Facesheets, Figure 104/ALLOWABLE DAMAGE 3 for the definitions of the facesheets of a honeycomb core area.
- B. Remove all the contamination and water from the structure.
 - (1) Refer to 51-30-03 for possible sources of the abrasive and other materials.
 - (2) Refer to 51-30-05 for possible sources of the equipment and tools.
 - (3) Refer to 51-70-04 for the cleanup procedures.
- C. Seal all damaged areas with the steps that follow.
 - (1) Seal the damage that is not more than one ply deep and that agrees with the allowable damage limits given in Paragraph 4./ALLOWABLE DAMAGE 3
 - (a) Make a temporary seal.
 - 1) Apply aluminum foil tape (speed tape).
 - 2) Keep a record of the location.
 - 3) Make sure the tape is in satisfactory condition at normal maintenance intervals.
 - (b) Make a permanent seal.
 - 1) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given 51-70-08.
 - 2) Apply one layer of BMS 10-79, Type 3 or BMS 10-103, Type 1 primer. Refer to SOPM 20-44-04.
 - 3) Apply one layer of BMS 10-60 enamel to the areas sealed with epoxy resin. Refer to AMM PAGEBLOCK 51-21-99/701.
 - (2) Seal all permitted damaged areas that are more than one ply deep. Refer to Paragraph 4./ALLOWABLE DAMAGE 3 for the allowable damage limits. Seal the damage as follows:
 - (a) Use a vacuum and heat to remove moisture from the solid laminate or the honeycomb cells. Refer to 51-70-04.
 - (b) Make a temporary seal with aluminum foil tape (speed tape).
 - (c) Keep a record of the location.
 - (d) Repair the damage before 250 flight cycles have occurred.
- D. Make sure the aerodynamic smoothness is satisfactory or there will be a decrease in the economic performance of the airplane.
- E. Restore the aircraft exterior paint system in the area where damage has been removed, as applicable. Refer to AMM PAGEBLOCK 51-21-99/701.



BOEING

737-800 STRUCTURAL REPAIR MANUAL



D634A210

ALLOWABLE DAMAGE 3


55-20-01

Page 105

Nov 01/2003

DEDEING®

737-800 STRUCTURAL REPAIR MANUAL



Definitions of the Facesheets Figure 104



D634A210



3. References

Reference	Title
51-10-01, GENERAL	Aerodynamic Smoothness Requirements
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05, GENERAL	Repair Sealing
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-08	RESIN SWEEP-FAIR PROCEDURES
55-20-01	ELEVATOR SKIN
AMM 27-31-31 P/B 401	ELEVATOR TAB - REMOVAL/INSTALLATION
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Allowable Damage Limits

A. Upper and Lower Trailing Edge Skins - Honeycomb Core Area

- (1) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
- (2) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth.

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum of 0.50 inch in length
- (c) A minimum of 1.00 inch away from a fastener hole or part edge
- (d) A minimum of 3.00 inches away from any other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the carbon fiber plies
 - Are sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
- (e) Sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
- (3) Dents that do not cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of 0.50 inch in diameter
 - (b) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if there is carbon fiber damage or if the dent depth is more than one ply.

- (c) A minimum of 1.00 inch away from a part edge
- (d) A minimum of 3.00 inches away from any other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:





- Do not cause damage to the carbon fiber plies
- Are sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
- (e) Sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
- (4) Holes and Punctures are permitted if they are:
 - (a) A maximum of 0.30 inch in diameter
 - (b) A minimum of 3.00 inches away from the edge of other damage.
 - **NOTE:** Other damage does not include nicks, gouges, and scratches that:
 - Do not cause damage to the carbon fiber plies
 - Are sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
 - (c) Sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
- (5) Delaminations are permitted if they are:
 - (a) A maximum of 0.50 inch in diameter for each square foot of total area
 - (b) A minimum distance of 1.00 inch away from a fastener hole or part edge
 - (c) A minimum distance of 3.00 inches away from the edge of other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the carbon fiber plies
- Are sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
- (d) Sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
- B. Leading Edge Solid Laminate Areas
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth.

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum of 0.50 inch in length
- (c) A minimum of 1.00 inch away from a part edge
- (d) A minimum of 3.00 inches away from any other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the carbon fiber plies
- Are sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
- (e) Sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
- (3) Dents that do not cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of 0.50 inch in diameter
 - (b) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if there is carbon fiber damage or if the dent depth is more than one ply in depth.

(c) A minimum of 1.00 inch away from a part edge






- (d) A minimum of 3.00 inches away from any other damage.
 - NOTE: Other damage does not include nicks, gouges, and scratches that:
 - Do not cause damage to the carbon fiber plies
 - Are sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
- (e) Sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
- (4) Holes and Punctures are permitted if they are:
 - (a) A maximum of 0.30 inch in diameter
 - (b) A minimum of 1.00 inch from the part edge
 - (c) A minimum of 3.00 inches away from the edge of other damage.
 - **NOTE:** Other damage does not include nicks, gouges, and scratches that:
 - Do not cause damage to the carbon fiber plies
 - Are sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
 - (d) Are sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
- (5) Delaminations are permitted if they are:
 - (a) A maximum of 0.50 inch in diameter
 - (b) A maximum of one damage area for each 144 square inches of skin area
 - (c) A minimum of 1.00 inch away from a part edge
 - (d) A minimum distance of 3.00 inches away from the edge of other damage.
 - NOTE: Other damage does not include nicks, gouges, and scratches that:
 Do not cause damage to the carbon fiber plies
 - Are sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
 - (e) Sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3
- (6) Edge Erosion is permitted as shown in Elevator Tab Skin Allowable Damage, Figure 105/ALLOWABLE DAMAGE 3.
- (7) Edge damage is permitted if it is:
 - (a) A maximum of 2.00 inches in length in the spanwise direction
 - (b) A maximum of one ply in depth
 - (c) A maximum of 0.25 inch in width
 - (d) A minimum of 3.0 inches away from other damage
 - (e) Sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3

ALLOWABLE DAMAGE 3

Page 109

Nov 10/2007





SEALING OF EROSION DAMAGE AT AN EDGE OF COMPOSITE PARTS

Elevator Tab Skin Allowable Damage Figure 105



D634A210

BOEING PROPRIETARY - Copyright ${\rm (\sc)}$ Unpublished Work - See title page for details



REPAIR 1 - ELEVATOR SKINS

1. Applicability

- A. Repair 1 is applicable to damage to elevator skin panels made of Carbon Fiber Reinforced Plastic (CFRP) as shown in Upper and Lower Elevator Skin Panel Location, Figure 201/REPAIR 1.
- B. Repair 1 is applicable to damage that is more than the limits permitted in Allowable Damage 1. Refer to Allowable Damage 1 for the type and size of damage that is permitted.

2. General


- A. Repair 1 gives repair instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Remove the elevator, as necessary. Refer to AMM 27-31-31/401.
 - (1) Remove the necessary fasteners. Refer to 51-40-02 for information on fastener removal.
 - (2) If a fastener hole is damaged, refer to 51-70-04 or 51-70-05, as applicable.
- C. Do an inspection of the damaged area to find the dimensions of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to 737 NDT Part 1, 51-01-02 of the inspection procedures.

NOTE: Other equivalent inspection methods that have been examined and found to be satisfactory by the operator, can be used.

- (1) Refer to Definitions of Damage Size, Figure 202/REPAIR 1 for the definitions of diameter and depth of damage.
- (2) Refer to Definitions of Facesheets, Figure 203/REPAIR 1 for the definitions of the facesheets of a honeycomb core area.
- D. Do the repair as given in Paragraph 4./REPAIR 1
- E. Make sure the aerodynamic smoothness is satisfactory or there can be a loss in the airplane safety performance. Refer to 51-10-01.
- F. Make sure that the elevator is balanced. Refer to 51-60-04 for the balance procedures.
- G. Install the elevator, as applicable. Refer to AMM 27-31-31/401.



REPAIR 1 Page 201 Nov 10/2006




Upper and Lower Elevator Skin Panel Location Figure 201



REPAIR 1 Page 202 Nov 01/2003

D634A210





Definitions of Damage Size Figure 202




REPAIR 1 Page 203 Nov 01/2003





737-800 STRUCTURAL REPAIR MANUAL



Definitions of Facesheets Figure 203




REPAIR 1 Page 204 Nov 01/2003





737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE UPPER SKIN PANEL IS SHOWN, LOWER SKIN PANEL IS ALMOST THE SAME

> Upper and Lower Elevator Skin Zones Figure 204



REPAIR 1 Page 205 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-60-04	ELEVATOR BALANCE PROCEDURE
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05	REPAIR PROCEDURES FOR PREIMPREGNATED MATERIALS
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 27-31-31/401	Elevator Tab - Removal/Installation
737 NDT Part 1, 51-01-01	Inspection of Repairs to Composite Structure
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Repair Instructions

- A. If a dent is 1.50 inches in diameter or less, and has no fiber damage or delamination, then fill the dent with potting compound and apply a fiberglass patch as given in Repair 14 of 51-70-04.
- B. If Paragraph 4.A./REPAIR 1 is not applicable, then refer to:
 - (1) Table 201/REPAIR 1 for the repair data that is applicable to damage in Zones 1 and 2.
 - (2) Table 202/REPAIR 1 for the repair data that is applicable to damage in Zone 3.
- C. For repairs made with wet layup materials, do as follows:
 - (1) Use one repair ply of fabric for each initial ply that was damaged. Table 201/REPAIR 1 for panel areas other than the edgebands.
 - (2) Add two structural plies of fabric for each facesheet that is repaired. Put one structural ply at ± 45 degrees to the core ribbon direction and the other at 0 or 90 degrees.
 - **NOTE**: Repair plies or added plies are not necessary in the repair of delaminations at an edge if the delamination is a minimum of 6D (D = fastener diameter) away from a fastener hole and agrees with the allowable damage limits.
- D. Use the instructions that follow to do a Category A repair with preimpregnated layup materials and 250°F (121°C) cure.
 - (1) Use the same number of repair plies as the number of initial plies that were damaged.
 - (2) Add two structural plies of fabric for each facesheet, or side of the part that is repaired. Put on structural ply at ± 45 degrees to the core ribbon direction and the other a 0 or 90 degrees.
- E. Use the instructions that follow to do a Category A repair with preimpregnated layup materials and 350°F (177°C) cure.
 - (1) Use the same number of repair plies as the number of initial plies that were damaged.



REPAIR 1 Page 206 Jul 10/2005



Table 201:

REPAIR DATA FOR ALL ZONES OF THE HONEYCOMB PANELS 350°F (177°C) CURE ELEVATOR SKINS				
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED IAYUP	CATEGORY A PREIMPREGNATED LAYUP
REPAIR CURE TEMPERATURE	150°F (66°C)	200°F (93°C)	250°F (121°C)	350°F (177°C)
REPAIR SIZE AND LIMITS	- Contact the Boeing Company for this temperature repair	Damage that is a maximum of: - 5.00 inches in diameter One repair for each 144 square inches 3.0 inches minimum clearance from: - other repairs - fastener holes - panel edges	Damage that is a maximum of: - 5.00 inches in diameter One repair for each 144 square inches 3.0 inches minimum clearance from: - other repairs - fastener holes - panel edges	There are no size limits on the repair.
REPAIR PROCEDURES		SRM 51-70-04 and Paragraph 4.C	SRM 51-70-05 and Paragraph 4.D	SRM 51-70-05 and Paragraph 4.E

Table 202:

REPAIR DATA FOR ZONE 3 OF THE 350°F (177°C) CURE ELEVATOR SKIN PANELS				
REPAIR TYPE	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED LAYUP	CATEGORY A PREIMPREGNATED LAYUP	
REPAIR CURE TEMPERATURE	200°F (93°C)	250°F (121°C)	350°F (177°C)	
REPAIR SIZE AND LIMITS	Damage that is a maximum of: - 3.00 inches across largest dimension of damage - 10 percent of the edgeband length on the side of the damage, as applicable	Damage that is a maximum of: - 3.00 inches across largest dimension of damage - 10 percent of the edgeband length on the side of the damage, as applicable	There are no size limits on the repair.	
REPAIR PROCEDURES	SRM 51-70-04 and Paragraph 4.C	SRM 51-70-05 and Paragraph 4.D	SRM 51-70-05 and Paragraph 4.E	



REPAIR 1 Page 207 Mar 10/2007


D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



REPAIR 2 - ELEVATOR TAB SKINS

1. Applicability

- A. Repair 2 is applicable to the elevator tab skins made from Carbon Fiber Reinforced Plastic shown in Elevator Tab Skin, Figure 201/REPAIR 2.
 - **NOTE**: THIS REPAIR IS APPLICABLE TO AIRPLANE LINE NUMBERS 1 THROUGH 1174 PRIOR TO COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082. REFER TO 55-20-01, REPAIR 3 FOR ALL AIRPLANE LINE NUMBERS EQUAL TO OR GREATER THAN 1175 AND FOR ALL LINE NUMBERS WITH COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082.
- B. Refer to Allowable Damage 2 for the type and dimensions of the damage that is permitted.



Elevator Tab Skin Figure 201 (Sheet 1 of 2)





REPAIR 2 Page 201 Nov 01/2003





737-800 STRUCTURAL REPAIR MANUAL





(FOR AIRPLANE LINE NUMBERS 1 THRU 1174) A-A

> Elevator Tab Skin Figure 201 (Sheet 2 of 2)



REPAIR 2 Page 202 Nov 01/2003





2. General


- A. Repairs done as given in Repair 2 are an Alternate Method of Compliance (AMOC) to the Federal Aviation Administration (FAA) Airworthiness Directive (AD) 2001-08-09, Paragraph (d).
- B. Repair 2 gives instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- C. Remove the elevator tab, as necessary. Refer to AMM 27-31-31/401.
- D. Do an inspection of the damaged area to find the dimensions of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to 737 NDT Part 1, 51-01-02 and 737 NDT Part 1, 51-01-03 for the inspection procedures.

NOTE: Other equivalent inspection methods that have been examined and found to be satisfactory by the operator can be used.

- (1) For the honeycomb core areas, the tap test is an alternative procedure to an instrumented NDT.
- (2) Refer to Figure 202, Details A, B, and C for the definitions of the length, width, and depth of damage.
- (3) Refer to Figure 203 for the definitions of the facesheets of a honeycomb core area.
- **CAUTION:** DO NOT EXCEED A MAXIMUM OF FOUR PERMITTED DAMAGE LOCATIONS THAT ARE SEALED AS GIVEN IN SRM 55-20-01, ALLOWABLE DAMAGE 2 OR ONE REPAIR LOCATION. REPAIRS ARE NOT PERMITTED INBOARD OF ELEVATOR STA 45.0. FOR ANY REPAIRS INBOARD OF ELEVATOR STATION 45.0, CONTACT BOEING. IF YOU DO NOT OBEY, THEN DAMAGE TO THE STRUCTURE COULD OCCUR. A REPAIR OF A DAMAGED CORE BY USING POTTING COMPOUND IS NOT PERMITTED.
- E. Do the repair as given in Paragraph 4./REPAIR 2
- F. Make sure the elevator tab is balanced after all repairs are complete. Refer to 51-60-06.
- G. Install the elevator tab, if it was removed. Refer to AMM 27-31-31/401.
- H. Make sure the aerodynamic smoothness is satisfactory or there will be a decrease in the economic performance of the airplane.
- I. Restore the elevator tab exterior finish, as applicable. Refer to AMM PAGEBLOCK 51-21-99/701.
 - **NOTE**: Wherever the elevator tab skins need to be refinished, the initial finishes including paint, primer, and/or surface filler, must be removed before application of new exterior paint system. Make sure the finish thicknesses are as given in AMM PAGEBLOCK 51-21-99/701.



REPAIR 2 Page 203 Nov 10/2007




55-20-01

REPAIR 2 Page 204 Nov 01/2003

D634A210



737-800 STRUCTURAL REPAIR MANUAL



Definitions of the Facesheets Figure 203

3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01, GENERAL	Aerodynamic Smoothness Requirements
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05, GENERAL	Repair Sealing
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-60-06	ELEVATOR TAB BALANCE PROCEDURE
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05	REPAIR PROCEDURES FOR PREIMPREGNATED MATERIALS
55-20-01	ELEVATOR SKIN
55-20-01, ALLOWABLE DAMAGE 2	Elevator Tab Skins
55-20-01, ALLOWABLE DAMAGE 3	Elevator Tab Skins For Airplane Line Numbers 1175 And On And Line Numbers 1 Through 1174 With Completion of Service Bulletins 737-55-1080 and 737-55-1082
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 27-31-31/401	Elevator Tab - Removal/Installation
SOPM 20-10-08	Removal of Faying Surface Sealed Metal Fittings from Composite Structures
737 NDT Part 1, 51-01-01	Inspection of Repairs to Composite Structure
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage
737 NDT Part 1, 51-01-03	NDT Assessment of Lightning Strike Damage to Graphite/Epoxy Composite Structure

4. Repair Instructions

- **NOTE**: If necessary, refer to 55-20-01, Identification 3 to find the material and the build-up of the part of the elevator tab skins that you want to repair.
- A. Do as follows when you make a repair:
 - (1) For the tab honeycomb wedge, it is permitted to wrap the repair plies around the trailing edge to repair the upper and lower skins.



REPAIR 2 Page 205 Nov 10/2007



- (2) Make the size of the repair plies with overlap as given in 51-70-04 and 51-70-05 and with a tolerance of ± 0.1 inch.
- B. Refer to Table 201/REPAIR 2 for the repair data that is applicable to damage to the honeycomb core areas of the elevator tab trailing edge skins.
- C. Refer to Table 202/REPAIR 2 for the repair data that is applicable to damage to the solid laminate areas of the elevator tab trailing and leading edge skins.
- D. For repairs made with wet layup materials, do as follows:
 - (1) Use one repair ply of fabric for each initial ply that was damaged.
 - (2) Add two structural plies of fabric for each facesheet, or side of the part that is repaired. Put one structural ply at ± 45 degrees to the core ribbon direction and the other at 0 or 90 degrees.
 - (3) Do an inspection of Category B repairs after each 400 flight hour interval or more frequently. Refer to 737 NDT Part 1, 51-01-01 for inspection procedures. If deterioration is found, then they must be replaced with Category A repairs.

NOTE: Other equivalent inspection methods that have been examined and found to be satisfactory by the operator, can be used.

- E. Repairs with preimpregnated layup materials at 250°F (121°C) cure are not permitted.
- F. Use the instructions that follow to do a Category A repair with preimpregnated layup materials at 350°F (177°C) cure.
 - (1) Use the same number of repair plies as the number of initial plies that were removed.

REPAIR DATA FOR THE HONEYCOMB CORE AREA ON THE 350°F (177°C) CURE, ELEVATOR TAB TRAILING EDGE SKINS				
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED LAYUP	CATEGORY A PREIMPREGNATED LAYUP
REPAIR CURE TEMPERATURE	150°F (66°C) *[1]*[2]	200°F (93°C) *[1]*[2]	250°F (121°C)	350°F (177°C) *[1]*[2]
REPAIR SIZE AND LIMITS	Damage that is a maximum of: - 0.50 inch across the largest dimension of the damage Damage must be a minimum of 2.5 X (D) away from a fastener hole or part edge.	Damage that is a maximum of: - 0.50 inch across the largest dimension of the damage Damage must be a minimum of 2.5 X (D) away from a fastener hole or part edge.	Repair is not permitted.	Damage that is a maximum of: - 1.0 inch across the largest dimension of the damage
REPAIR PROCEDURES	SRM 51-70-04 and Paragraph 4.D	SRM 51-70-04 and Paragraph 4.D		SRM 51-70-05 and Paragraph 4.F

Table 201:

*[1] Only one repair is permitted for the upper or lower skin plus honeycomb core area on each elevator tab.

*[2] For damage that is more than the limits given in this table, contact The Boeing Company for repair data.



REPAIR 2 Page 206 Mar 10/2007



Table 202:

REPAIR DATA FOR THE SOLID LAMINATE AREA ON THE 350°F (177°C) CURE ELEVATOR TAB TRAILING EDGE AND LEADING EDGE SKINS				
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED LAYUP	CATEGORY A PREIMPREGNATED LAYUP
REPAIR CURE TEMPERATURE	150°F (66°C) *[1] *[2]	200°F (93°C) *[1]_*[2]	250°F (121°C)	350°F (177°C) ≛[1]_*[2]
REPAIR SIZE AND LIMITS	Damage that is a maximum of: - 0.50 inch across the largest dimension of the damage Damage must be a minimum of 2.5 X (D) away from a fastener hole or part edge.	Damage that is a maximum of: - 0.50 inch across the largest dimension of the damage Damage must be a minimum of 2.5 X (D) away from a fastener hole or part edge.	Repair is not permitted.	Damage that is a maximum of: - 1.0 inch across the largest dimension of the damage
REPAIR PROCEDURES	SRM 51-70-04 and Paragraph 4.D	SRM 51-70-04 and Paragraph 4.D		SRM 51-70-05 and Paragraph 4.F

*[1] Only one repair is permitted for the upper or lower skin plus honeycomb core area on each elevator tab.

*[2] For damage that is more than the limits given in this table, contact The Boeing Company for repair data.



REPAIR 2 Page 207


Nov 01/2003



REPAIR 3 - ELEVATOR TAB SKINS FOR AIRPLANE LINE NUMBERS 1175 AND ON AND LINE NUMBERS 1 THROUGH 1174 WITH COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082

1. Applicability

- A. Repair 3 is applicable to the elevator tab skins made from Carbon Fiber Reinforced Plastic shown in Elevator Tab Skin, Figure 201/REPAIR 3.
 - **NOTE**: THIS REPAIR IS APPLICABLE TO AIRPLANE LINE NUMBERS 1175 AND ON AND LINE NUMBERS 1 THROUGH 1174 WITH COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082. REFER TO 55-20-01, REPAIR 2 FOR AIRPLANE LINE NUMBERS 1 THROUGH 1174 PRIOR TO COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082.
- B. Refer to Allowable Damage 3 for the type and dimensions of the damage that is permitted.




Elevator Tab Skin Figure 201



REPAIR 3 Page 201 Nov 01/2003







55-20-01

REPAIR 3 Page 202 Nov 01/2003

BOEING"

737-800 STRUCTURAL REPAIR MANUAL





(FOR AIRPLANE LINE NUMBERS 1 THRU 1174 WITH COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082) A-A

> Elevator Tab Skin Repairs Figure 202 (Sheet 2 of 2)



REPAIR 3 Page 203 Nov 01/2003

D634A210



2. General


- A. Repair 3 gives instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Remove the elevator tab, as necessary. Refer to AMM 27-31-31/401.
- C. Do an inspection of the damaged area to find the dimensions of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to 737 NDT Part 1, 51-01-02 and 737 NDT Part 1, 51-01-03 for the inspection procedures.

NOTE: Other equivalent inspection methods that have been examined and found to be satisfactory by the operator can be used.

- (1) For the honeycomb core areas, the tap test is an alternative procedure to an instrumented NDT.
- (2) Refer to Damage Definitions, Figure 203/REPAIR 3, Details A, B, and C for the definitions of the length, width, and depth of damage.
- (3) Refer to Definitions of the Facesheets, Figure 204/REPAIR 3 for the definitions of the facesheets of a honeycomb core area.
- D. Do the repair as given in Paragraph 4./REPAIR 3
- E. Make sure the elevator tab is balanced after all repairs are complete. Refer to 51-60-06.
- F. Install the elevator tab, if it was removed. Refer to AMM 27-31-31/401.
- G. Make sure the aerodynamic smoothness is satisfactory or there will be a decrease in the economic performance of the airplane.
- H. Restore the elevator tab exterior finish, as applicable. Refer to AMM PAGEBLOCK 51-21-99/701.



REPAIR 3 Page 204 Nov 10/2007




REPAIR 3 Page 205 Nov 01/2003

55-20-01

D634A210

DEDEING®

737-800 STRUCTURAL REPAIR MANUAL



Definitions of the Facesheets Figure 204



REPAIR 3 Page 206 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01, GENERAL	Aerodynamic Smoothness Requirements
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05, GENERAL	Repair Sealing
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-60-06	ELEVATOR TAB BALANCE PROCEDURE
51-70-04, REPAIR GENERAL	Repair Procedures for Wet Layup Materials
51-70-05, REPAIR GENERAL	Repair Procedures for Preimpregnated Materials
55-20-01	ELEVATOR SKIN
55-20-01, ALLOWABLE DAMAGE 2	Elevator Tab Skins
55-20-01, ALLOWABLE DAMAGE 3	Elevator Tab Skins For Airplane Line Numbers 1175 And On And Line Numbers 1 Through 1174 With Completion of Service Bulletins 737-55-1080 and 737-55-1082
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 27-31-31/401	Elevator Tab - Removal/Installation
SOPM 20-10-08	Removal of Faying Surface Sealed Metal Fittings from Composite Structures
737 NDT Part 1, 51-01-01	Inspection of Repairs to Composite Structure
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage
737 NDT Part 1, 51-01-03	NDT Assessment of Lightning Strike Damage to Graphite/Epoxy Composite Structure

4. Repair Instructions

- **NOTE**: If necessary, refer to 55-20-01, Identification 3 to find the material and the build-up of the part of the elevator tab skins that you want to repair.
- A. Do as follows when you make a repair:
 - (1) When you remove the damage, do not cut or make an abrasion into the radius of the structure.
 - (2) If the repair plies make an overlap of a hole or cutout, do the steps that follow:
 - (a) Cure the repair.
 - (b) Drill or cut the plies to the initial diameter of the hole of the cutout.
 - (3) If you need clearance with adjacent structure, install a tapered shim on each side of the repair.
 - (4) It is permitted to put the repair plies around the full width of the structure.
 - (a) Do not make an overlap of the edges of the structure.
- B. Refer to Table 201/REPAIR 3 for the repair data that is applicable to damage to the honeycomb core areas of the elevator tab skin.
- C. Refer to Table 202/REPAIR 3 for the repair data that is applicable to damage to the solid laminate areas of the elevator tab skin.
- D. For repairs made with wet layup materials, do as follows:
 - (1) Use one repair ply of fabric for each initial ply that was damaged.



REPAIR 3 Page 207 Nov 10/2007



- (2) Add two structural plies of fabric for each facesheet, or side of the part that is repaired. Put one structural ply at ± 45 degrees to the core ribbon direction and the other at 0 or 90 degrees.
- E. Use the instructions that follow to do a Category A repair with preimpregnated layup materials at 250°F (121°C) cure.
 - (1) Use the same number of repair plies as the number of initial plies that were removed.
 - (2) Add two structural plies of fabric for each facesheet, or side of the part that is repaired. Put one structural ply at ± 45 degrees to the core ribbon direction and the other at 0 or 90 degrees.
- F. Use the instructions that follow to do a Category A repair with preimpregnated layup materials at 350°F (177°C) cure.
 - (1) Use the same number of repair plies as the number of initial plies that were removed.

REPAIR DATA FOR THE HONEYCOMB AREA ON THE 350°F (177°C) CURE, ELEVATOR TAB SKIN				
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED LAYUP	CATEGORY A PREIMPREGNATED LAYUP
REPAIR CURE TEMPERATURE	150°F (66°C)	200°F (93°C)	250°F (121°C)	350°F (177°C)
REPAIR SIZE AND LIMITS	- Contact The Boeing Company for this temperature repair.	Damage that is a maximum of: - 1.5 inches across the largest dimension of the damage	Damage that is a maximum of: - 1.5 inches across the largest dimension of the damage	Damage that is a maximum of: - 1.5 inches across the largest dimension of the damage
		- 50 percent of the smallest dimension across the part at the damage location	- 50 percent of the smallest dimension across the part at the damage location	- 50 percent of the smallest dimension across the part at the damage location
		One repair for each 144 square inches	One repair for each 144 square inches	One repair for each 144 square inches
		1.0 inch minimum clearance from:	1.0 inch minimum clearance from:	1.0 inch minimum clearance from:
		- fastener holes - panel edges	- fastener holes - panel edges	- fastener holes - panel edges
		3.0 inches minimum clearance from other repairs	3.0 inches minimum clearance from other repairs	3.0 inches minimum clearance from other repairs
REPAIR PROCEDURES		SRM 51-70-04 and Paragraph 4.D	SRM 51-70-05 and Paragraph 4.E	SRM 51-70-05 and Paragraph 4.F

Table 201:



REPAIR 3 Page 208 Jul 10/2004



Table 202:

REPAIR DA	REPAIR DATA FOR THE SOLID LAMINATE AREA ON THE 350°F (177°C) CURE, ELEVATOR TAB SKIN				
REPAIR TYPE	REPAIR TYPE CATEGORY B WET LAYUP		CATEGORY A PREIMPREGNATED LAYUP	CATEGORY A PREIMPREGNATED LAYUP	
REPAIR CURE TEMPERATURE	150°F (66°C)	200°F (93°C)	250°F (121°C)	350°F (177°C)	
REPAIR SIZE AND LIMITS	- Contact The Boeing Company for this temperature repair	Damage that is a maximum of:	Damage that is a maximum of:	Damage that is a maximum of:	
		- 1.5 inches across the largest dimension of the damage	- 1.5 inches across the largest dimension of the damage	- 1.5 inches across the largest dimension of the damage	
		- 50 percent of the smallest dimension across the part at the damage location	- 50 percent of the smallest dimension across the part at the damage location	- 50 percent of the smallest dimension across the part at the damage location	
		One repair for each 144 square inches	One repair for each 144 square inches	One repair for each 144 square inches	
		1.0 inch minimum clearance from:	1.0 inch minimum clearance from:	1.0 inch minimum clearance from:	
		- fastener holes - panel edges	- fastener holes - panel edges	- fastener holes - panel edges	
		3.0 inches minimum clearance from other repairs	3.0 inches minimum clearance from other repairs	3.0 inches minimum clearance from other repairs	
REPAIR PROCEDURES		SRM 51-70-04 and Paragraph 4.D	SRM 51-70-05 and Paragraph 4.E	SRM 51-70-05 and Paragraph 4.F	



REPAIR 3 Page 209 Jul 10/2004



REPAIR 4 - ELEVATOR HINGE COVER CRACK

1. Applicability


A. Repair 4 is applicable to damage to elevator hinge cover panels made of Epoxy Sheet Molding as shown in Elevator Hinge Cover Panel Location, Figure 201/REPAIR 4 and Elevator Hinge Covers, Figure 202/REPAIR 4.

2. General

- A. Repair 4 gives repair instructions for a Category A repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Remove the elevator hinge covers, as necessary. Refer to AMM 06-42-00.
 - (1) Remove the necessary fasteners. Refer to 51-40-02 for information on fastener removal.
 - (2) If a fastener hole is damaged, refer to 51-70-04 as applicable.
- C. Do an inspection of the damaged area to find the dimensions of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to 737 NDT Part 1, 51-01-02 of the inspection procedures.

NOTE: Other equivalent inspection methods that have been examined and found to be satisfactory by the operator, can be used.


- (1) Refer to Damage Definitions, Figure 203/REPAIR 4 for the definitions of width and depth of damage.
- D. Do the repair as given in Paragraph 4./REPAIR 4
- E. Make sure the aerodynamic smoothness is satisfactory or there can be a loss in the airplane safety performance. Refer to 51-10-01.
- F. Make sure that the elevator is balanced. Refer to 51-60-04 for the balance procedures.
- G. Install the elevator hinge cover, as applicable. Refer to AMM 06-42-00.



REPAIR 4 Page 201 Jul 10/2005




737-800 STRUCTURAL REPAIR MANUAL



Elevator Hinge Cover Panel Location Figure 201



REPAIR 4 Page 202 Nov 01/2003




Elevator Hinge Covers Figure 202 (Sheet 1 of 2)



REPAIR 4 Page 203 Nov 01/2003

BOEING"

737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE SHOWN, RIGHT SIDE OPPOSITE (FOR AIRPLANE LINE NUMBERS 1175 AND ON)


> Elevator Hinge Covers Figure 202 (Sheet 2 of 2)



REPAIR 4 Page 204 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



Damage Definitions Figure 203



REPAIR 4 Page 205 Nov 01/2003

D634A210

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-60-04	ELEVATOR BALANCE PROCEDURE
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 06-42-00	Aircraft Maintenance Manual
737 NDT Part 1, 51-01-01	Inspection of Repairs to Composite Structure
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Repair Instructions

- A. Completely remove the crack damage and blend smooth with the initial edges.
- B. Refer to Table 201/REPAIR 4 for the repair data that is applicable to the damage.
- C. For repairs made with wet layup materials, do as follows:
 - (1) Use two repair plies of BMS 9-3, Type H2 or H3 fabric with BMS 8-301, Class 1, Grade 1 resin as given in 51-70-04 to the damaged areas. Put one repair ply at 0 degrees along the long edge of the panel. Extend this ply a minimum of 0.50 inch beyond the damage. Put the next ply at \pm 45 degrees to the edge of the panel and extend the ply 0.50 inch beyond the first ply end.
 - (2) On the opposite side, fill the blended area with BMS 8-301, Class 1, Grade 1 resin and milled glass fibers. Add two repair plies of BMS 9-3, Type H2 or H3 fabric with BMS 8-301, Class 1, Grade 1 resin as given in 51-70-04 to the damage area. Put one repair ply at 0 degrees along the long edge of the panel. Extend this ply a minimum of 0.50 inch beyond the damage. Put the next ply at ±45 degrees to the edge of the panel and extend the ply 0.50 inch beyond the first ply end.
 - (3) Refinish as given in 51-70-04.

	REPAIR DATA FOR THE ELEVATOR HINGE COVERS			
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED IAYUP	CATEGORY A PREIMPREGNATED LAYUP
REPAIR CURE TEMPERATURE	150°F (66°C)	200°F (93°C)	250°F (121°C)	350°F (177°C)
REPAIR SIZE AND LIMITS FOR EDGE CRACKS	- Contact the Boeing Company for this temperature repair.	Damage that is a maximum of: - 1.5 inches in length	This temperature repair is not permitted.	This temperature repair is not permitted.
		- 2 edge cracks for each panel. The crack must be a minimum of 1.5 inches away from another crack.		

Table 201:



REPAIR 4 Page 206 Jul 10/2005




	REPAIR DATA FOR THE ELEVATOR HINGE COVERS				
REPAIR TYPE CATEGORY B WET LAYUP		CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED IAYUP	CATEGORY A PREIMPREGNATED LAYUP	
REPAIR CURE TEMPERATURE	150°F (66°C)	200°F (93°C)	250°F (121°C)	350°F (177°C)	
REPAIR SIZE AND LIMITS FOR CRACKS FROM FASTENER HOLES	- Contact The Boeing Company for this temperature repair.	Damage that is a maximum of: - 0.5 inch in length away from a fastener hole edge. - 2 fastener cracks for each panel.	This temperature repair is not permitted.	This temperature repair is not permitted.	
REPAIR PROCEDURES		SRM 51-70-04 AND PARAGRAPH 4.C			



REPAIR 4



IDENTIFICATION 1 - ELEVATOR LEADING EDGE STRUCTURE



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Elevator Leading Edge Structure Location Figure 1

To	ble	- 1 -
- I a	Die	

	REFERENCE DRAWINGS			
DRAWING NUMBER	TITLE			
183A1000	Front Spar Assembly - Elevator			
183A2020	Balance Panel Assembly - Bay No. 2, Elevator			
183A2030	Balance Panel Assembly - Bay No. 3, Elevator			
183A2040	Balance Panel Assembly - Bay No. 4, Elevator			
183A2050	Balance Panel Assembly - Bay No. 5, Elevator			
183A6000	Leading Edge Installation - Elevator			







	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
183A7000	Balance Horn Assembly - Elevator				





737-800 STRUCTURAL REPAIR MANUAL









Figure 2 (Sheet 1 of 2)




BOEING®

737-800 STRUCTURAL REPAIR MANUAL



A-A



B-B

Leading Edge Structure Identification Figure 2 (Sheet 2 of 2)



1DENTIFICATION 1 Page 4 Mar 10/2004

D634A210

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details




Table 2:

	LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION T ^{'[1]} MATERIAL EFFECTIVITY			EFFECTIVITY	
[1]	Front Spar - Bonded Part		Carbon Fiber Reinforced Plastic (CFRP) honeycomb sandwich with a Glass Fiber Reinforced Plastic (GFRP) isolation ply		
	Skin		Refer to Figure 3		
	Core ELEV STA 39 to 66.5 ELEV STA 66.5 to 121.5		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0		
[2]	Rib Post (3)		CFRP solid laminate		
	Skin		Refer to Figure 4 for a typical rib post		
[3]	Stiffener (2)		CFRP solid laminate		
	Skin		Refer to Figure 5 for a typical stiffener		
[4]	Rib, Leading Edge	0.050 (1.27)	2024-T42 clad		
[5]	Balance Panel Assembly		Refer to Figure 6 for a typical Balance Panel		
	Rib, Inboard End		7075-T7351 plate		
	Rib, Outboard End		7075-T7351 plate		
	Rib, Inboard Center		7075-T7351 plate		
	Rib, Outboard Center		7075-T7351 Type V, Grade 3.0		
	Hinge Plate	0.025 (0.64)	7075-T651 plate as given in QQ-A-250/12		
	Stiffener (2)	0.032 (0.81)	2024-T42 clad sheet		
[6]	Balance Horn Assembly		Refer to Figure 7 for the Balance Horn		
	Rib, Inboard End		7075-T7351 plate		
	Rib, Outboard End		7075-T7351 plate		

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





PLY LAYUP AND CORE RIBBON DIRECTION


А

NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC, REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION AND THE CORE RIBBON DIRECTION.
- REFER TO SECTIONS A-A, B-B, C-C, AND D-D FOR THE PLY SEQUENCE AT THOSE LOCATIONS.
- REFER TO TABLE 3 FOR THE DIRECTION AND MATERIAL FOR EACH PLY.

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Front Spar, Figure 2, Item [1] Figure 3 (Sheet 1 of 4)





IDENTIFICATION 1


55-20-02

Page 7


Mar 10/2004



STRUCTURAL REPAIR MANUAL








B-B

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Front Spar, Figure 2, Item [1] Figure 3 (Sheet 3 of 4)






737-800 STRUCTURAL REPAIR MANUAL



C-C



D-D

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Front Spar, Figure 2, Item [1] Figure 3 (Sheet 4 of 4)






Table 3:

	PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [1]				
PLY	DIRECTION	MATERIAL			
P1	Optional	Epoxy impregnated glass woven fabric as given in BMS 8-139, Style 108			
P2, P4, P6 thru P8, P13, P14, P17, P18, P21, P22, P24, P26	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW			
P3, P5, P9 thru P12, P15, P16, P19, P20, P23, P25	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW			





NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC, REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION.
- REFER TO SECTIONS A-A AND B-B FOR THE PLY SEQUENCE AT THOSE LOCATIONS.
- REFER TO TABLE 4 FOR THE DIRECTION AND MATERIAL FOR EACH PLY.

Ply Direction and Ply Sequence for Rib Post, Figure 2, Item [2] Figure 4






Table 4:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [2]				
PLY	DIRECTION	MATERIAL		
P1, P3, P5, P8, P10, P12	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW		
P2, P4, P6, P7, P9, P11	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW		





NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC, REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION.
- REFER TO SECTIONS A-A THRU C-C FOR THE PLY SEQUENCE AT THOSE LOCATIONS.
- REFER TO TABLE 5 FOR THE DIRECTION AND MATERIAL FOR EACH PLY.

Ply Direction and Ply Sequence for Stiffener, Figure 2, Item [3] Figure 5






Table 5:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [3]		
PLY	DIRECTION	MATERIAL
P1, P3, P5, P8, P10, P12	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P2, P4, P6, P7, P9, P11	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW








LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Balance Panel Assembly for Figure 2, Item [5] Figure 6 (Sheet 1 of 2)





737-800 STRUCTURAL REPAIR MANUAL



В-В

Balance Panel Assembly for Figure 2, Item [5] Figure 6 (Sheet 2 of 2)




Page 16 Mar 10/2004





737-800 STRUCTURAL REPAIR MANUAL




Balance Horn for Figure 2, Item [2] Figure 7



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



IDENTIFICATION 2 - ELEVATOR RIB STRUCTURE



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Elevator Rib Structure Location Figure 1


- T .		I	-	
- 1 4	ab	P		•


	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
183A0101	Elevator Assembly Functional Product Collector				
183A5000	Rib Installation - Station 39.6 - 42.6, Elevator				
183A5020	Rib Installation - Station 132.39 - 134.51, Elevator				
183A5030	Rib Installation - Outboard Closure, Elevator				
183A5040	Rib Installation - Inboard Closure, Elevator				
183A5050	Rib Installation - Tab Cutout Closure, Elevator				




BOEING

737-800 STRUCTURAL REPAIR MANUAL







(FOR AIRPLANE LINE NUMBERS 1175 AND ON)

NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

ELEVATOR RIBS

Elevator Rib Structure Identification Figure 2



Page 2




Table 2:

LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T*[1]	MATERIAL	EFFECTIVITY
[1]	Station 41 Rib - Bonded Part		Carbon Fiber Reinforced Plastic (CFRP) honeycomb sandwich	
	Skin		Refer to Figure 3	
	Core		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 3	
[2]	Station 133 Rib - Bonded Part		CFRP honeycomb sandwich	
	Skin		Refer to Figure 4	
	Core		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 4	
[3]	Outboard Closure Rib - Bonded Part		CFRP solid laminate	
	Skin		Refer to Figure 5	
[4]	Inboard Closure Rib - Bonded Part		CFRP honeycomb sandwich	
	Skin		Refer to Figure 6	
	Core		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 6	
[5]	Tab Cutout Closure Rib - Bonded Part		CFRP solid laminate	
	Skin		Refer to Figure 7	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).







• THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE BONDED PART.

PLY LAYUP SEQUENCE

A-A

[P3] [P2]

- EP13

- REFER TO SECTION A-A FOR THE PLY SEQUENCE AT THAT LOCATION. REFER TO THE ENGINEERING DRAWING FOR MORE INFORMATION.
- REFER TO TABLE 3 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN SECTION A-A.

CP103-

[P11]

[P12]

Ply Direction, Core Ribbon Direction and Ply Sequence for Figure 2, Item [1] Figure 3





Table 3:


PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [1]		
PLY	DIRECTION	MATERIAL
P1, P12	Optional	1 Mil White Tedlar as given in BAC 5317-4
P2, P6, P7, P11	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P3, P4, P9, P10	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P5, P8	Optional	Adhesive film as given in BMS 8-245, Type II, Class 1, Grade 03A



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details




737-800 STRUCTURAL REPAIR MANUAL



PLY LAYUP AND CORE RIBBON DIRECTION





PLY LAYUP SEQUENCE

A-A

NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE BONDED PART.
- REFER TO SECTION A-A FOR THE PLY SEQUENCE AT THAT LOCATION. REFER TO THE . ENGINEERING DRAWING FOR MORE INFORMATION.
- REFER TO TABLE 4 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN . SECTION A-A.

Ply Direction, Core Ribbon Direction and Ply Sequence for Figure 2, Item [2] Figure 4



Page 6

Mar 10/2004


D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



Table 4:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [2]		
PLY	DIRECTION	MATERIAL
P1, P12	Optional	1 Mil White Tedlar as given in BAC 5317-4
P2, P6, P7, P11	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P3, P4, P9, P10	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P5, P8	Optional	Adhesive film as given in BMS 8-245, Type II, Class 1, Grade 03A





A-A

NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE BONDED PART.
- REFER TO SECTION A-A FOR THE PLY SEQUENCE AT THAT LOCATION. REFER TO THE ENGINEERING DRAWING FOR MORE INFORMATION.
- REFER TO TABLE 5 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN SECTION A-A.

Ply Direction, and Ply Sequence for Figure 2, Item [3] Figure 5






Table 5:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [3]		
PLY	DIRECTION	MATERIAL
P1, P3, P4, P6	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P2, P5	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P7	Optional	1 Mil white Tedlar as given in BAC 5317-4





NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR . THE O DEGREE PLY DIRECTION OF THE BONDED PART.
- REFER TO SECTION A-A FOR THE PLY SEQUENCE AT THAT LOCATION. REFER TO THE ENGINEERING DRAWING FOR MORE INFORMATION.
- REFER TO TABLE 6 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN . SECTION A-A.

Ply Direction, Core Ribbon Direction and Ply Sequence for Figure 2, Item [4] Figure 6



Page 10


Mar 10/2004



Table 6:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [4]		
PLY	DIRECTION	MATERIAL
P1, P17	Optional	1 Mil white Tedlar as given in BAC 5317-4
P2, P4, P8, P9, P13, P15	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P3, P5, P7, P10, P12, P14	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P6, P11	Optional	Adhesive film as given in BMS 8-245, Type II, Class 1, Grade 03A
P16	Optional	Epoxy impregnated glass woven fabric as given in BMS 8-139, Class 3, Style 108





PLY LAYUP SEQUENCE

A-A

NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE BONDED PART.
- REFER TO SECTION A-A FOR THE PLY SEQUENCE AT THAT LOCATION. REFER TO THE ENGINEERING DRAWING FOR MORE INFORMATION.
- REFER TO TABLE 7 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN SECTION A-A.

Ply Direction and Ply Sequence Figure 7






Table 7:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [5]		
PLY	DIRECTION	MATERIAL
P1, P3, P4, P6	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P2, P5	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P7	Optional	1 MIL white Tedlar as given in BAC 5317-4





IDENTIFICATION 3 - ELEVATOR REAR SPAR STRUCTURE



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Elevator Rear Spar Structure Location Figure 1


Table 1:

REFERENCE DRAWINGS		
DRAWING NUMBER	TITLE	
183A0009	Elevator Installation - Rework	
183A0109	Elevator Assembly - Rework	
183A4000	Rear Spar Installation - Elevator	



BOEING

737-800 STRUCTURAL REPAIR MANUAL



REAR VIEW А

NOTES

• REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Elevator Rear Spar Structure Identification Figure 2 (Sheet 1 of 2)





Page 2

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details

BOEING


737-800 STRUCTURAL REPAIR MANUAL





(FOR AIRPLANE LINE NUMBERS 1175 AND ON)

A-A



Elevator Rear Spar Structure Identification Figure 2 (Sheet 2 of 2)



Page 3 Nov 01/2003





Table 2:

LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Rear Spar Assembly		Carbon Fiber Reinforced Plastic (CFRP) solid laminate. Refer to Figure 3	
[2]	Rib Post		CFRP solid laminate. Refer to Figure 4	
[3]	Angle		CFRP solid laminate. Refer to Figure 5	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).








PLY LAYUP FOR THE REAR SPAR







NOTES

- THE PLY DIRECTION IS THE WRAP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PART.
- REFER TO SECTION A-A FOR THE PLY SEQUENCE AT THAT LOCATION. REFER TO THE . ENGINEERING DRAWING FOR MORE INFORMATION.
- REFER TO TABLE 3 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN . SECTION A-A.

Ply Direction and Ply Sequence for Figure 2, Item [1] Figure 3




Page 5




Table 3:


PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [1]		
PLY	DIRECTION	MATERIAL
P1, P3, P5, P7, P9	+ or - 45 degrees	CFRP as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P2, P4, P6, P8	0 or 90 degrees	CFRP as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P10	Optional	Epoxy impregnated glass woven fabric as given in BMS 8-139, Style 108







PLY LAYUP FOR THE RIB POSTS



A-A

NOTES

- . THE PLY DIRECTION IS THE WRAP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PART.
- REFER TO SECTION A-A FOR THE PLY SEQUENCE AT THAT LOCATION. REFER TO THE . ENGINEERING DRAWING FOR MORE INFORMATION.
- REFER TO TABLE 4 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN . SECTION A-A.

Ply Direction And Ply Sequence for Figure 2, Item [2] Figure 4



Page 7




Table 4:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [2]		
PLY	DIRECTION	MATERIAL
P1, P3, P6, P8	+ or - 45 degrees	CFRP solid laminate as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P2, P4, P5, P7	0 or 90 degrees	CFRP solid laminate as given in BMS 8-256, Type I IV, Class 2, Style 3K-70-PW





737-800 STRUCTURAL REPAIR MANUAL



NOTES

- THE PLY DIRECTION IS THE WRAP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION OF THE PART.
- REFER TO SECTION A-A FOR THE PLY SEQUENCE AT THAT LOCATION. REFER TO THE ENGINEERING DRAWING FOR MORE INFORMATION.
- REFER TO TABLE 5 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN SECTION A-A.

Ply Direction and Play Sequence for Figure 2, Item [3] Figure 5





Table 5:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [3]		
PLY	DIRECTION	MATERIAL
P1, P3, P5, P8, P10, P12	+ or - 45 degrees	CFRP solid laminate as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW
P2, P4, P6, P7, P9, P11	0 or 90 degrees	CFRP solid laminate as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW





ALLOWABLE DAMAGE 1 - ELEVATOR STRUCTURE

1. Applicability

A. This subject gives the allowable damage limits for the elevator structure shown in Elevator Location, Figure 101/ALLOWABLE DAMAGE 1 and Elevator Structure Allowable Damage, Figure 104/ALLOWABLE DAMAGE 1.

2. General

- A. Remove the damaged material from the aluminum parts as necessary.
 - (1) Refer to 51-10-02 for the inspection and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
- B. After you remove the damage, do the procedures that follow for the aluminum parts:
 - (1) Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to 51-20-01.
 - (2) Apply one layer of BMS 10-79, Type III, primer to the reworked areas. Refer to SOPM 20-44-04
- C. Do an inspection of the damaged composite area to find the length, width and depth of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 and NDT, Part 1, 51-01-03 for inspection procedures.

NOTE: Other equivalent inspection methods that have been examined and found to be satisfactory by the operator can be used.

- (1) For the honeycomb core areas, the tap test is an alternative procedure to an instrumented NDT. Refer to NDT, Part 1, 51-05-01 for the inspection procedures.
- (2) Refer to Damage Definitions, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, and C for the definitions of the length, width, and depth of the damage.
- D. Remove all contamination and water from the structure.
 - (1) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (2) Refer to 51-30-05 for possible sources of equipment and tools you can use to remove the damage.
 - (3) Refer to 51-70-04 for the damage removal procedures.
- E. Seal all permitted damage areas that are not more than one ply deep and agree with the allowable damage limits. Refer to Paragraph 4./ALLOWABLE DAMAGE 1 Seal the damage with one of the two methods that follows:
 - (1) Make a temporary seal.
 - (a) Apply aluminum foil tape (speed tape).
 - (b) Keep a record of the location.
 - (c) Make sure that the tape is in satisfactory condition at normal maintenance intervals.
 - (2) Make a permanent seal.
 - (a) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given in 51-70-08.





- (b) Apply one layer of BMS 10-79, Type III or BMS 10-103, Type I primer. Refer to SOPM 20-44-04.
- (c) Apply one layer of BMS 10-60, Type II enamel to the exterior surfaces of the areas sealed with epoxy resin. Refer to AMM 51-21-00/701.
- F. Seal all permitted damage areas that are more than one ply deep and agree with the allowable damage limits as follows:
 - (1) Use a vacuum and heat to remove moisture from the solid laminate and/or honeycomb cells. Refer to 51-70-04.
 - (2) Make a temporary seal with aluminum foil tape (speed tape).
 - (3) Keep a record of the location.
 - (4) Repair the damage at or before 250 flight cycles from the time the seal was made.
- G. The definition of the words "other damage" as used in the allowable damage limits, does not include nicks, gouges, and scratches that do not cause carbon fiber damage and are sealed.
- H. Make sure that the elevator is balanced. Refer to 51-60-04 for the balance procedures.
- I. Refer to Definitions of the Facesheets, Figure 103/ALLOWABLE DAMAGE 1 for the definitions of the facesheets of a honeycomb core area.
- J. Refer to Table 101/ALLOWABLE DAMAGE 1 for the references for the allowable damage limits.
- K. Refer to Elevator Structure Allowable Damage, Figure 104/ALLOWABLE DAMAGE 1 for the locations of the allowable damage zones.


PARAGRAPH REFERENCES FOR THE ALLOWABLE DAMAGE LIMITS			
TYPE OF STRUCTURE	ZONE LOCATION	PARAGRAPH	
LEADING EDGE RIBS, BALANCE HORN RIBS, BALANCE PANEL RIBS (ALUMINUM)		4.A.	
SOLID LAMINATE AREAS OF THE FRONT SPAR, REAR SPAR, RIBS, AND CLOSURE RIBS	ZONE 1 ZONE 2 ZONE 3 ZONE 4 ZONE 5 ZONE 6	4.B.	
HONEYCOMB CORE AREAS OF THE FRONT SPAR, RIBS, AND INBOARD CLOSURE RIB	ZONE 1 ZONE 2 ZONE 3 ZONE 4 ZONE 5 ZONE 6	4.C.	

Table 101:





737-800 STRUCTURAL REPAIR MANUAL




Elevator Location Figure 101



BOEING

737-800 STRUCTURAL REPAIR MANUAL






Page 104






737-800 STRUCTURAL REPAIR MANUAL



Definitions of the Facesheets Figure 103






(FOR AIRPLANE LINE NUMBERS 1 THROUGH 1174)

NOTE: REFER TO TABLE 101 FOR THE ALLOWABLE DAMAGE REFERENCES.

Elevator Structure Allowable Damage Figure 104 (Sheet 1 of 9)








NOTE: REFER TO TABLE 101 FOR THE ALLOWABLE DAMAGE REFERENCES.

Elevator Structure Allowable Damage Figure 104 (Sheet 2 of 9)





737-800 STRUCTURAL REPAIR MANUAL






Elevator Structure Allowable Damage Figure 104 (Sheet 3 of 9)





737-800 STRUCTURAL REPAIR MANUAL






Page 109

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



FWD 🦾

CROSS-SECTION OF THE FRONT SPAR WHERE HONEYCOMB CORE IS LOCATED IN THE WEB


A-A

CROSS-SECTION OF THE FRONT SPAR WHERE THE WEB IS SOLID LAMINATE

0.5 [']INCH

0.5 INCH

В-В




Elevator Structure Allowable Damage Figure 104 (Sheet 5 of 9)





737-800 STRUCTURAL REPAIR MANUAL




Elevator Structure Allowable Damage Figure 104 (Sheet 6 of 9)





737-800 STRUCTURAL REPAIR MANUAL




Elevator Structure Allowable Damage Figure 104 (Sheet 7 of 9)



D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL





ZONE 4

C-C


Elevator Structure Allowable Damage Figure 104 (Sheet 8 of 9)



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL







3. References

Reference	Title
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-60-04	ELEVATOR BALANCE PROCEDURE
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-08	RESIN SWEEP-FAIR PROCEDURES
AMM 51-21-00/701	Interior And Exterior Finishes - Cleaning/Painting
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage
737 NDT Part 1, 51-01-03	NDT Assessment of Lightning Strike Damage to Graphite/Epoxy Composite Structure
737 NDT Part 1, 51-05-01	Tap Test Inspection of Honeycomb Sandwich Structure

4. Allowable Damage Limits

- A. Leading Edge Ribs, Balance Horn Ribs, Balance Panel Ribs Aluminum
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 105/ALLOWABLE DAMAGE 1, Details A, B, and F.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 105/ALLOWABLE DAMAGE 1, Details A, B, C, E, and F.
 - (b) Damage that does not go through the clad surface is permitted.
 - (3) Dents are permitted as shown in Allowable Damage Limits, Figure 105/ALLOWABLE DAMAGE 1, Detail D.
 - (4) Holes and Punctures are permitted if they are:
 - (a) A maximum diameter of 0.25 inch
 - (b) A minimum of 4D away from the edge of a hole or other damage. D is equal to the maximum dimension of the damage
 - (c) A minimum of 2D away from the edge of the part
 - (d) Filled with a 2117-T3 or 2117-T4 aluminum rivet.
 - 1) Install the rivet without sealant.
- B. Front Spar, Rear Spar, Ribs, and Closure Ribs Solid Laminate Areas All Zones
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth
 <u>NOTE</u>: Use the limits for holes and punctures if the damage is more than one ply in depth.
 - (b) A maximum of 0.50 inch in length





- (c) A maximum of 0.25 inch in width
- (d) A minimum of 3.0 inches away from a hole
- (e) A minimum of 1.5 inches away from the edge of the part
- (f) A minimum of 6.0 inches away from other damage.
- (3) Dents that do not cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum diameter of 0.50 inch
 - (b) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if there is fiber damage or the dent depth is more than one ply.

- (c) A minimum of 3.0 inches away from a hole
- (d) A minimum of 1.5 inch away from the edge of the part
- (e) A minimum of 6.0 inches away from other damage.
- (4) Holes and Punctures are permitted if they are:
 - (a) A maximum diameter of 0.25 inch
 - (b) A minimum of 6D away from the edge of a hole or other damage. D is equal to the maximum dimension of the damage
 - (c) A minimum of 2D away from the edge of the part.
- (5) Delaminations are permitted as shown in Allowable Damage Limits for the Front Spar, Rear Spar, Ribs, and Closure Ribs - Solid Laminate Areas - Zones 2, 4, and 6, Figure 106/ALLOWABLE DAMAGE 1, if they are:
 - (a) A maximum diameter of 0.50 inch
 - (b) A maximum of one ply in depth
 - **NOTE**: Use the limits for holes and punctures if the damage is more than one ply in depth.
 - (c) A minimum of 6D away from the edge of a hole or other damage. D is equal to the maximum dimension of the damage
 - (d) A minimum of 2D away from the edge of the part.
- (6) Edge damage is permitted if it is:
 - (a) A maximum of one ply in depth
 - (b) A maximum of 0.25 inch in width
 - (c) A minimum of 0.50 inch away from the edge of a fastener hole.
- C. Front Spar, Ribs, and Inboard Closure Rib Honeycomb Core Areas All Zones
 - (1) Nicks, Gouges, and Scratches that cause damage to the glass fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum length of 0.5 inch
- (c) A maximum width of 0.25 inch





- (d) A minimum distance away from the edge of a hole, part edge, or other damage of 3.0 inches.
- (3) Dents are permitted if they are:
 - (a) A maximum diameter of 0.5 inch
 - (b) A maximum of one ply in depth


<u>NOTE</u>: Use the limits for holes and punctures if there is fiber damage or the dent depth is more than one ply.

- (c) A minimum distance away from the edge of a hole, part edge, or other damage of 6D. Refer to Allowable Damage Limits for the Front Spar, Ribs, and Inboard Closure Rib -Honeycomb Core Areas - Zones 1, 3, and 5, Figure 107/ALLOWABLE DAMAGE 1 for the permitted damage and the value of D.
- (4) Holes and Punctures are not permitted.
- (5) Delaminations are not permitted.



BOEING

737-800 STRUCTURAL REPAIR MANUAL







Page 118



737-800 STRUCTURAL REPAIR MANUAL






55-20-02 Mar 10/2007

Page 119



737-800 STRUCTURAL REPAIR MANUAL




X = THE WIDTH OF THE MATERIAL THAT IS REMOVED = A MAXIMUM OF 10 PERCENT OF THE WIDTH OF THE FLANGE

REMOVAL OF DAMAGED MATERIAL ON AN EDGE

Allowable Damage Limits Figure 105 (Sheet 3 of 3)







NOTE: TO FIND DELAMINATION, YOU CAN USE NONDESTRUCTIVE INSPECTION PROCEDURES. REFER TO NDT PART 1, 51-01-02.

THE DIAMETER OF A DAMAGE AREA IS EITHER THE DIAMETER OF THE VISUAL DAMAGE OR THE DIAMETER OF THE DELAMINATION. USE THE DIAMETER OF THE LARGER DAMAGE.

D IS THE LARGER DIAMETER OF TWO ADJACENT DAMAGE AREAS AND CAN BE A MAXIMUM OF 0.50 INCH.

d is the smaller diameter of two adjacent damage areas.

X IS THE DISTANCE BETWEEN TWO ADJACENT DAMAGE AREAS.

THE MINIMUM X THAT IS PERMITTED IS 6D.


DAMAGE THAT IS PERMITTED TO COMPOSITE PANELS

Allowable Damage Limits for the Front Spar, Rear Spar, Ribs, and Closure Ribs - Solid Laminate Areas - Zones 2.4. and 6 Figure 106



Page 121





NOTE: TO FIND DELAMINATION, YOU CAN USE NONDESTRUCTIVE INSPECTION PROCEDURES. REFER TO NDT PART 1, 51-01-02.

THE DIAMETER OF A DAMAGE AREA IS EITHER THE DIAMETER OF THE VISUAL DAMAGE OR THE DIAMETER OF THE DELAMINATION. USE THE DIAMETER OF THE LARGER DAMAGE. D IS THE LARGER DIAMETER OF TWO ADJACENT DAMAGE AREAS AND CAN BE A MAXIMUM OF 0.5 INCH.

d is the smaller diameter of two adjacent damage areas.

X IS THE DISTANCE BETWEEN TWO ADJACENT DAMAGE AREAS.

THE MINIMUM X THAT IS PERMITTED IS 6D.


DAMAGE THAT IS PERMITTED TO COMPOSITE PANELS

Allowable Damage Limits for the Front Spar, Ribs, and Inboard Closure Rib - Honeycomb Core Areas - Zones 1, 3, and 5 Figure 107



Page 122





NOTE: TO FIND DELAMINATION, YOU CAN USE NONDESTRUCTIVE INSPECTION PROCEDURES. REFER TO NDT PART 1, 51-01-02. THE DIAMETER OF A DAMAGE AREA IS EITHER THE DIAMETER OF THE VISUAL DAMAGE OR THE DIAMETER OF THE DELAMINATION. USE THE DIAMETER OF THE LARGER DAMAGE. D IS THE LARGER DIAMETER OF TWO ADJACENT DAMAGE AREAS AND CAN BE A MAXIMUM OF 0.50 INCHES. d IS THE SMALLER DIAMETER OF TWO ADJACENT DAMAGE AREAS. X IS THE DISTANCE BETWEEN TWO ADJACENT DAMAGE AREAS.

THE MINIMUM X THAT IS PERMITTED IS 6D.

DAMAGE THAT IS PERMITTED TO COMPOSITE PANELS

Allowable Damage Limits for the Front Spar, Ribs, and Inboard Closure Rib - Honeycomb Core Areas - Zones 2, 4, and 6 Figure 108



Page 123



ALLOWABLE DAMAGE 2 - ELEVATOR TAB SPAR

1. Applicability

- A. This subject is applicable for damage to the elevator tab spar shown in Elevator Tab Spar Allowable Damage, Figure 101/ALLOWABLE DAMAGE 2.
 - **NOTE**: This Allowable Damage Subject ie applicable to airplane line nunbers 1 through 1174 that have not been modified as given in Service Bulletins 737-55-1080 and 737-55-1082. Refer to ALLOWABLE DAMAGE 3 for the airplanes with line nunbers equal to or greater than 1175 and for all the other airplanes that have been modified as given in Service Bulletins 737-55-1080 and 737-55-1082.

2. General

A. Damage is not permitted. Refer to 55-20-02, REPAIR 2, for repairs to the elevator tab spar.




Figure 101

3. References

Reference	e
55-20-02,	REPAIR 2

Title Elevator Tab Spar

4. Allowable Damage Limits

A. Damage is not permitted. Refer to 55-20-02, REPAIR 2, for repairs to the elevator tab spar.





ALLOWABLE DAMAGE 3 - ELEVATOR TAB SPAR FOR AIRPLANE LINE NUMBERS 1175 AND ON AND LINE NUMBERS 1 THROUGH 1174 WITH COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082

1. Applicability

- A. This subject gives the allowable damage limits for the elevator tab spar shown in Elevator Tab Spar Allowable Damage, Figure 101/ALLOWABLE DAMAGE 3.
 - **NOTE:** THIS ALLOWABLE DAMAGE IS APPLICABLE TO AIRPLANE LINE NUMBERS 1175 AND ON AND LINE NUMBERS 1 THROUGH 1174 WITH COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082. REFER TO 55-20-02, ALLOWABLE DAMAGE 2 FOR AIRPLANE LINE NUMBERS 1 THROUGH 1174 PRIOR TO COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082.

2. General

A. Do an inspection of the damaged composite area to find the length, width and depth of the damage. Boeing recommends that you use an instrumented Nondestructive Inspection (NDI) procedure. Refer to 737 NDT Part 1, 51-01-02 and 737 NDT Part 1, 51-01-03 for inspection procedures.

NOTE: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.


- (1) Refer to Damage Definitions, Figure 102/ALLOWABLE DAMAGE 3, Details A, B, and C for the definitions of the length, width, and depth of damage.
- B. Remove all the contamination and water from the structure.
 - (1) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (2) Refer to 51-70-04 for the removal procedures.
- C. Seal all permitted damage areas that are not more than one ply deep. Refer to the allowable damage limits. Seal the damage with one of the two methods that follows:
 - (1) Make a temporary seal.
 - (a) Apply aluminum foil tape (speed tape).
 - (b) Keep a record of the location.
 - (c) Make sure the tape is in satisfactory condition at normal maintenance intervals.
 - (2) Make a permanent seal.
 - (a) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given 51-70-08.
 - (b) Apply one layer of BMS 10-79, Type 3 or BMS 10-103, Type I primer. Refer to SOPM 20-44-04.
 - 1) Apply one layer of BMS 10-60, Type II enamel to the exterior surfaces of the areas sealed with epoxy resin. Refer to AMM 51-21-00/701.
- D. Seal all permitted damaged areas that are more than one ply deep. Refer to the allowable damage limits. Seal the damage as follows:
 - (1) Use a vacuum and heat to remove moisture from the solid laminate and/or honeycomb cells. Refer to 51-70-04.
 - (2) Make a temporary seal with aluminum foil tape (speed tape).
 - (3) Keep a record of the location.
 - (4) Repair the damage before 250 flight cycles has occurred.





- E. The definition of the words "other damage" as used in the allowable damage limits, does not include nicks, gouges, and scratches that do not cause carbon fiber damage and are sealed.
- F. Make sure the elevator tab is balanced. Refer to 51-60-06 for the balance procedures.






ALLOWABLE DAMAGE 3 **55-20-02** Page 103 Nov 01/2003


BOEING®

737-800 STRUCTURAL REPAIR MANUAL





В




(FOR AIRPLANE LINE NUMBERS 1 THRU 1174 WITH COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082) A-A

> Elevator Tab Spar Allowable Damage Figure 101 (Sheet 2 of 2)

> > ALLOWABLE DAMAGE 3 **55-20-02** Page 104 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL





Page 105



3. References

Reference	Title
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-30-03, GENERAL	Sources for Non-Metallic Repair Materials
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-60-06	ELEVATOR TAB BALANCE PROCEDURE
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-08	RESIN SWEEP-FAIR PROCEDURES
55-20-02	ELEVATOR STRUCTURE
AMM 51-21-00/701	Interior And Exterior Finishes - Cleaning/Painting
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage
737 NDT Part 1, 51-01-03	NDT Assessment of Lightning Strike Damage to Graphite/Epoxy Composite Structure

4. Allowable Damage Limits

- A. Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
- B. Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are:
 - (1) A maximum of one ply in depth.

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (2) A maximum of 0.50 inch in length
- (3) A minimum of 1.00 inch away from a hole
- (4) A minimum of 1.0 inch away from the edge of a part
- (5) A minimum of 3.0 inches away from other damage
- (6) A minimum of 1.0 inch away from a hinge or actuator location.
- C. Dents are permitted if they are:
 - (1) A maximum diameter of 0.50 inch
 - (2) A minimum of 1.0 inch away from the edge of a hole.
 - (3) A minimum of 1.0 inch away from the edge of the part.
 - (4) A minimum of 3.0 inches away from the edge of other damage.
- D. Holes and Punctures are permitted if they are:
 - (1) A maximum diameter of 0.30 inch
 - (2) A minimum of 3.0 inches away from other damage.
 - (3) A minimum of 1.0 inch away from the edge of the part
 - (4) A minimum of 1.0 inch away from a hinge or actuator location.
- E. Delaminations are permitted if they are:
 - (1) A maximum of 0.50 inch in diameter
 - (2) A maximum of 1 damage area for each 144 square inches of skin area
 - (3) A minimum of 1.0 inch away from a hinge or actuator location or part edge.





- (4) A minimum of 3.0 inches away from the edge of other damage.
- F. Edge damage is permitted if it is:
 - (1) A maximum of 2.0 inches in length
 - (2) A maximum of 1 ply in depth
 - (3) A maximum of 0.25 inch in width
 - (4) A minimum of 3.0 inches away from other damage.
 - (5) Sealed as given in Paragraph 2.C./ALLOWABLE DAMAGE 3








REPAIR 1 - ELEVATOR STRUCTURE

1. Applicability

A. Repair 1 is applicable to the composite parts of the elevator structure shown in Elevator Location, Figure 201/REPAIR 1.



Elevator Location Figure 201

2. General

- A. Repair 1 gives instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Remove the elevator, as necessary. Refer to AMM 27-31-11/401.
- C. Remove the skin panels, as necessary, to get access to the spars and ribs.
- D. Remove the fittings or leading edge ribs from the spars, as necessary, to get access to the spars. Refer to SOPM 20-10-08.
- E. Refer to Definitions of the Facesheets, Figure 202/REPAIR 1 for the definitions of the facesheets of a honeycomb core area.
- F. Do an inspection of the damaged composite area to find the length, width and depth of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 and NDT, Part 1, 51-01-03 for inspection procedures.

<u>NOTE</u>: Other equivalent inspection methods that have been examined and found to be satisfactory by the operator can be used.


(1) For the honeycomb core areas, the tap test is an alternative procedure to an instrumented NDT. Refer to NDT, Part 1, 51-05-01 for the inspection procedures.



REPAIR 1 Page 201 Nov 01/2003



- (2) Refer to Damage Definitions, Figure 203/REPAIR 1, Details A, B, and C, f for the definitions of the length, width, and depth of the damage.
- G. Do the repair as given in Paragraph 4./REPAIR 1
- H. Install the fittings or leading edge ribs on the spars if they were removed.
 - (1) Apply BMS 5-95 sealant to the mating surfaces. Refer to 51-20-05.
 - (2) Apply BMS 5-95 sealant to all parts that connect the fittings. Refer to 51-20-05.
- I. Refer to Elevator Structure Repairs, Figure 204/REPAIR 1 for the locations of the repair zones.
- J. Install the skin panels, as applicable. Refer to 51-40-02 for the fastener installation procedures.
- K. Make sure the elevator is balanced after all repairs are complete. Refer to 51-60-04.
- L. Install the elevator, as applicable. Refer to AMM 27-31-11/401.




Definitions of the Facesheets Figure 202





BOEING


737-800 STRUCTURAL REPAIR MANUAL



55-20-02

REPAIR 1 Page 203

Nov 01/2003




NOTE: REFER TO TABLE 201 FOR THE REPAIR REFERENCES.

Elevator Structure Repairs Figure 204 (Sheet 1 of 8)



REPAIR 1 Page 204 Nov 01/2003





NOTE: REFER TO TABLE 201 FOR THE REPAIR REFERENCES.


Elevator Structure Repairs Figure 204 (Sheet 2 of 8)



REPAIR 1 Page 205 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL




55-20-02

Page 206

Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL





CROSS-SECTION OF THE FRONT SPAR WHERE HONEYCOMB CORE IS LOCATED IN THE WEB


A-A

CROSS-SECTION OF THE FRONT SPAR WHERE THE WEB IS SOLID LAMINATE

0.5 'INCH

0.5 INCH

B–B




Elevator Structure Repairs Figure 204 (Sheet 4 of 8)



REPAIR 1 Page 207 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



(FOR AIRPLANE LINE NUMBERS 1 THROUGH 1174) REAR SPAR


> Elevator Structure Repairs Figure 204 (Sheet 5 of 8)



REPAIR 1 Page 208 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL




Elevator Structure Repairs Figure 204 (Sheet 6 of 8)



REPAIR 1 Page 209 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL





ZONE 4

C-C


Elevator Structure Repairs Figure 204 (Sheet 7 of 8)



REPAIR 1 Page 210 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL





REPAIR 1 Page 211 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05	REPAIR SEALING
51-30-03, GENERAL	Sources for Non-Metallic Repair Materials
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-60-04	ELEVATOR BALANCE PROCEDURE
51-70-04, REPAIR P/B REPAIR	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05, REPAIR GENERAL	Repair Procedures for Preimpregnated Materials
55-20-02, ALLOWABLE DAMAGE 1	Elevator Structure
AMM 51-21-00 P/B 701	INTERIOR AND EXTERIOR FINISHES - CLEANING/PAINTING
AMM 27-31-11/401	Elevator - Removal/Installation
SOPM 20-10-08	Removal of Faying Surface Sealed Metal Fittings from Composite Structures
737 NDT Part 1, 51-01-01	Inspection of Repairs to Composite Structure
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage
737 NDT Part 1, 51-01-03	NDT Assessment of Lightning Strike Damage to Graphite/Epoxy Composite Structure
737 NDT Part 1, 51-05-01	Tap Test Inspection of Honeycomb Sandwich Structure

4. Repair Instructions

A. Do as follows when you make a repair:

- (1) When you remove the damage, do not cut or make an abrasion into the radius of the structure.
- (2) If the repair plies make an overlap of a hole or cutout, do the steps that follow:
 - (a) Cure the repair.
 - (b) Drill or cut the plies to the initial diameter of the hole or cutout.
- (3) If you need clearance with adjacent structure, install a tapered shim on each side of the repair.
- (4) It is permitted to put the repair plies around the full width of the structure.
 - (a) Do not make an overlap of the edges of the structure.
- B. For repairs made with wet layup materials, do as follows, as applicable:
 - (1) Use one repair ply of fabric for each initial ply that was damaged.
 - (2) Add two structural plies of fabric for each facesheet or side of the part that is repaired. Put one structural ply at ± 45 degrees to the core ribbon direction and the other at 0 or 90 degrees.
- C. For repairs made with preimpregnated layup materials, use the same number of repair plies as the number of initial plies that were damaged. Include a filler ply as applicable.



REPAIR 1 Page 212 Jul 10/2005



Table 201:

TABLE REFERENCES FOR THE REPAIR ZONES			
TYPE OF STRUCTURE	ZONE LOCATION	TABLE	
LEADING EDGE RIBS, BALANCE HORN RIBS, BALANCE PANEL RIBS, (ALUMINUM)		THERE ARE NO REPAIRS FOR THESE PARTS IN THE STRUCTURAL REPAIR MANUAL AT THIS TIME	
SOLID LAMINATE AREAS OF THE FRONT SPAR, REAR SPAR, RIBS, AND CLOSURE RIBS	ZONE 1 ZONE 3 ZONE 5	202	
SOLID LAMINATE AREAS OF THE FRONT SPAR, REAR SPAR, RIBS, AND CLOSURE RIBS	ZONE 2 ZONE 4 ZONE 6	203	
HONEYCOMB CORE AREAS OF THE FRONT SPAR, RIBS, AND INBOARD CLOSURE RIB	ZONE 1 ZONE 3 ZONE 5	204	
HONEYCOMB CORE AREAS OF THE FRONT SPAR, RIBS, AND INBOARD CLOSURE RIB	ZONE 2 ZONE 4 ZONE 6	205	

Table 202:

REPAIR DATA FOR	REPAIR DATA FOR THE SOLID LAMINATE AREA OF ALL ZONES ON THE 350°F (177°C) CURE - ELEVATOR STRUCTURE			
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED IAYUP	CATEGORY A PREIMPREGNATED LAYUP
REPAIR CURE TEMPERATURE	150°F (66°C)	200°F (93°C)	250°F (121°C)	350°F (177°C)
REPAIR SIZE AND LIMITS	This repair is not permitted in these zones	Damage that is a maximum of: - 3.00 inches across largest dimension of damage - 10 percent of the smallest dimension across the part at the damage location 3.0 inches minimum clearance from: - other repairs - fastener holes - other holes - part edges	Damage that is a maximum of: - 3.00 inches across largest dimension of damage - 10 percent of the smallest dimension across the part at the damage location 3.0 inches minimum clearance from: - other repairs - fastener holes - other holes - part edges	There are no limits on the dimensions of the repair
REPAIR PROCEDURES	Not permitted	SRM 51-70-05 and Paragraph 4.C	SRM 51-70-05 and Paragraph 4.C	SRM 51-70-05 and Paragraph 4.C





Table 203:

REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED IAYUP	CATEGORY A PREIMPREGNATED LAYUP
REPAIR CURE TEMPERATURE	150°F (66°C)	200°F (93°C)	250°F (121°C)	350°F (177°C)
REPAIR SIZE AND LIMITS	Contact Boeing for repair instructions	Damage that is a maximum of: - 3.0 inches in diameter - 30 percent of the smallest dimension across the part at the	Damage that is a maximum of: - 3.0 inches in diameter - 30 percent of the smallest dimension across the part at the	There are no limits on the dimensions of the repair
		damage location 3.0 inches minimum clearance from:	damage location 3.0 inches minimum clearance from:	
		- other repairs - fastener holes - other holes - part edges	 other repairs fastener holes other holes part edges 	
REPAIR PROCEDURES	Not Permitted	SRM 51-70-04 and Paragraph 4.B	SRM 51-70-05 and Paragraph 4.C	SRM 51-70-05 and Paragraph 4.C



REPAIR 1





REPAIR 2 - ELEVATOR TAB SPAR

1. Applicability


- A. Repair 2 is applicable to the elevator tab spar shown in Elevator Tab Spar Repairs, Figure 201/REPAIR 2.
 - **NOTE**: THIS REPAIR IS APPLICABLE TO AIRPLANE LINE NUMBERS 1 THROUGH 1174 PRIOR TO COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082. REFER TO 55-20-02, REPAIR 3 FOR AIRPLANE LINE NUMBERS EQUAL TO OR GREATER THAN LINE NUMBER 1175 AND FOR ALL LINE NUMBERS WITH COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082.

2. General

- A. Repairs done as given in Repair 2 are an Alternate Method of Compliance (AMOC) to the Federal Aviation Administration (FAA) Airworthiness Directive (AD) 2001-08-09, Paragraph (d).
- B. Repair 2 gives instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- C. Remove the elevator tab, as necessary. Refer to AMM 27-31-31/401.
- D. Remove the skin panels, as necessary, to get access to the spar.
- E. Remove the fittings, as necessary, to get access to the spar. Refer to SOPM 20-10-08.
- F. Do an inspection of the damaged composite area to find the length, width and depth of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to 737 NDT Part 1, 51-01-02 and 737 NDT Part 1, 51-01-03 for inspection procedures.
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator, can be used.
 - (1) Refer to Damage Definitions, Figure 202/REPAIR 2, Details A, B, and C the definitions of the length, width, and depth of the damage.
- **CAUTION:** DO NOT EXCEED ONE REPAIR LOCATION. REPAIRS ARE NOT PERMITTED INBOARD OF ELEVATOR STA 45.0. FOR ANY REPAIRS INBOARD OF ELEVATOR STATION 45.0, CONTACT BOEING. IF YOU DO NOT OBEY, THEN DAMAGE TO STRUCTURE COULD OCCUR.
- G. Do the repair as given in Paragraph 4./REPAIR 2 and Table 201/REPAIR 2.
- H. Install the fittings on the spar, if they were removed.
 - (1) Apply BMS 5-95 sealant to the mating surfaces. Refer to 51-20-05.
 - (2) Apply BMS 5-95 sealant to all parts that connect the fittings. Refer to 51-20-05.
- I. Install the skin panels, if they were removed.
- J. Make sure the elevator tab is balanced after all repairs are complete. Refer to 51-60-06.
- K. Install the elevator tab, as applicable. Refer to AMM 27-31-31/401.



REPAIR 2 Page 201 Jul 10/2005






REPAIR 2 Page 202 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL





REPAIR 2 Page 203 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05	REPAIR SEALING
51-30-03, GENERAL	Sources for Non-Metallic Repair Materials
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-60-06	ELEVATOR TAB BALANCE PROCEDURE
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05	REPAIR PROCEDURES FOR PREIMPREGNATED MATERIALS
55-20-02	ELEVATOR STRUCTURE
AMM 51-21-00 P/B 701	INTERIOR AND EXTERIOR FINISHES - CLEANING/PAINTING
AMM 27-31-31/401	Elevator Tab - Removal/Installation
SOPM 20-10-08	Removal of Faying Surface Sealed Metal Fittings from Composite Structures
737 NDT Part 1, 51-01-01	Inspection of Repairs to Composite Structure
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage
737 NDT Part 1, 51-01-03	NDT Assessment of Lightning Strike Damage to Graphite/Epoxy Composite Structure

4. Repair Instructions

- A. Do as follows when you make a repair:
 - (1) It is permitted to put the repair plies around the full width of the structure.
 - (2) Make the size of the repair plies with overlap as given in 51-70-04 and 51-70-05 and with a tolerance of +/- 0.10 inch.
- B. Refer to Table 201/REPAIR 2 for the repair data that is applicable to damage to the solid laminate areas for the elevator tab spar.
- C. For repairs made with wet layup materials, do as follows, as applicable:
 - (1) Use one repair ply of fabric for each initial ply that was damaged.
 - (2) Add two structural plies of fabric for each facesheet, or side of the part that is repaired. Put one structural ply at ± 45 degrees to the core ribbon direction and the other at 0 or 90 degrees.
 - **NOTE**: Repair plies or added plies are not necessary in the repair of delamination at an edge if the delamination is a minimum of 2d (d = fastener diameter) away from a fastener hole.
 - (3) Do an inspection of Category B repairs after each 800 flight hour interval or more frequently. Refer to 737 NDT Part 1, 51-01-01 for inspection procedures. If deterioration is found, then they must be replaced with Category A repairs.
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator, can be used.
- D. Use the instructions that follow to do a Category A repair with preimpregnated layup materials at 350°F (177°C) cure.



REPAIR 2 Page 204 Jul 10/2005



- (1) Use the same number of repair plies as the number of initial plies that were removed.
- E. Repairs with preimpregnated layup materials at 250°F (121°C) cure are not permitted.

		Table 201:		
REPAIR DATA FOR	THE TAB SPAR MADE OF	SOLID LAMINATE ON TH	E 350°F (177°C) CURE, EL	EVATOR TAB SPAR
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED LAYUP	CATEGORY A PREIMPREGNATED LAYUP
REPAIR CURE TEMPERATURE	150°F (66°C) *[1]*[2]	200°F (93°C) *[1]*[2]	250°F (121°C)	350°F (177°C) ≛[1]*[2]
REPAIR SIZE AND LIMITS	Damage that is a maximum of: - 0.50 inch across the largest dimension of the damage Damage must be a minimum of 2.5 X (D) away from a fastener hole or part edge.	Damage that is a maximum of: - 0.50 inch across the largest dimension of the damage Damage must be a minimum of 2.5 X (D) away from a fastener hole or part edge.	Damage is not permitted.	Damage that is a maximum of: - 1.0 inch across the largest dimension of the damage
REPAIR PROCEDURES	SRM 51-70-04 and Paragraph 4.C	SRM 51-70-04 and Paragraph 4.C		SRM 51-70-05 and Paragraph 4.D

*[1] Only one repair is permitted for each elevator tab spar.

*[2] For damage that is more than the limits given in this table, ask The Boeing Company for repair data.





REPAIR 3 - ELEVATOR TAB SPAR FOR AIRPLANE LINE NUMBERS 1175 AND ON AND LINE NUMBERS 1 THROUGH 1174 WITH COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082

1. Applicability


- A. Repair 3 is applicable to the elevator tab spar shown in Elevator Tab Spar Repairs, Figure 201/REPAIR 3.
 - **NOTE:** THIS REPAIR IS APPLICABLE TO AIRPLANE LINE NUMBERS 1175 AND ON AND LINE NUMBERS 1 THROUGH 1174 WITH COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082. REFER TO 55-20-02, REPAIR 2 FOR AIRPLANE LINE NUMBERS 1 THROUGH 1174 PRIOR TO COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082.

2. General

- A. Repair 3 gives instructions for Category A repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Remove the elevator tab, as necessary. Refer to AMM 27-31-31/401.
- C. Remove the skin panels, as necessary, to get access to the spar.
- D. Remove the fittings, as necessary, to get access to the spar. Refer to SOPM 20-10-08.
- E. Do an inspection of the damaged composite area to find the length, width and depth of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to 737 NDT Part 1, 51-01-02 and 737 NDT Part 1, 51-01-03 for inspection procedures.
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator, can be used.
 - (1) Refer to Damage Definitions, Figure 202/REPAIR 3, Details A, B, and C, f or t he definitions of the length, width, and depth of the damage.
- F. Do the repair as given in Paragraph 4./REPAIR 3 and Table 201/REPAIR 3.
- G. Install the fittings on the spar, if they were removed.
 - (1) Apply BMS 5-95 sealant to the mating surfaces. Refer to 51-20-05.
 - (2) Apply BMS 5-95 sealant to all parts that connect the fittings. Refer to 51-20-05.
- H. Install the skin panels, if they were removed.
- I. Make sure the elevator tab is balanced after all repairs are complete. Refer to 51-60-06.
- J. Install the elevator tab, as applicable. Refer to AMM 27-31-31/401.




REPAIR 3 Page 201 Jul 10/2005




REPAIR 3 Page 202 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL







(FOR AIRPLANE LINE NUMBERS 1 THRU 1174 WITH COMPLETION OF SERVICE BULLETINS 737-55-1080 AND 737-55-1082) A-A


> Elevator Tab Spar Repairs Figure 201 (Sheet 2 of 2)



REPAIR 3 Page 203 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL





REPAIR 3 Page 204 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05	REPAIR SEALING
51-30-03, GENERAL	Sources for Non-Metallic Repair Materials
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-60-06	ELEVATOR TAB BALANCE PROCEDURE
51-70-04, REPAIR GENERAL	Repair Procedures for Wet Layup Materials
51-70-05, REPAIR GENERAL	Repair Procedures for Preimpregnated Materials
55-20-02	ELEVATOR STRUCTURE
AMM 51-21-00 P/B 701	INTERIOR AND EXTERIOR FINISHES - CLEANING/PAINTING
AMM 27-31-31/401	Elevator Tab - Removal/Installation
SOPM 20-10-08	Removal of Faying Surface Sealed Metal Fittings from Composite Structures
737 NDT Part 1, 51-01-01	Inspection of Repairs to Composite Structure
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage
737 NDT Part 1, 51-01-03	NDT Assessment of Lightning Strike Damage to Graphite/Epoxy Composite Structure

4. Repair Instructions

- A. Do as follows when you make a repair:
 - (1) When you remove the damage, do not cut or make an abrasion into the radius of the structure.
 - (2) If the repair plies make an overlap of a hole or cutout, do the steps that follow:
 - (a) Cure the repair.
 - (b) Drill or cut the plies to the initial diameter of the hole or cutout.
 - (3) If you need clearance with adjacent structure, install a tapered shim on each side of the repair.
 - (4) It is permitted to put the repair plies around the full width of the structure.
 - (a) Do not make an overlap of the edges of the structure.
- B. For repairs made with wet layup materials, do as follows, as applicable:
 - (1) Use one repair ply of fabric for each initial ply that was damaged.
 - (2) Add two structural plies of fabric for each facesheet, or side of the part that is repaired. Put one structural ply at ± 45 degrees to the core ribbon direction and the other at 0 or 90 degrees.
 - **NOTE**: Repair plies or added plies are not necessary in the repair of delamination at an edge if the delamination is a minimum of 2D (D = fastener diameter) away from a fastener hole.
- C. For repairs made with preimpregnated materials, use the same number of repair plies as the number of initial plies that were damaged.



REPAIR 3 Page 205 Jul 10/2005



Table 201:


REPAIR DATA FOR THE TAB SPAR MADE OF SOLID LAMINATE ON THE 350°F (177°C) CURE, ELEVATOR TAB STRUCTURE				
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED LAYUP	CATEGORY A PREIMPREGNATED LAYUP
REPAIR CURE TEMPERATURE	150°F (66°C)	200°F (93°C)	250°F (121°C)	350°F (177°C)
REPAIR SIZE AND LIMITS	- Contact The Boeing Company for this temperature repair	Damage that is a maximum of: - 1.5 inches in diameter	Damage that is a maximum of: - 1.5 inches in diameter	Damage that is a maximum of: - 1.5 inches in diameter
		- 50 percent of the smallest dimension across the part at the damage location	- 50 percent of the smallest dimension across the part at the damage location	 50 percent of the smallest dimension across the part at the damage location
		One repair for each 144 square inches	One repair for each 144 square inches	One repair for each 144 square inches
		3.0 inches minimum clearance from other repairs	3.0 inches minimum clearance from other repairs	3.0 inches minimum clearance from other repairs
		1.0 inch minimum clearance from: - part edges - fastener holes	1.0 inch minimum clearance from: - part edges - fastener holes	1.0 inch minimum clearance from: - part edges - fastener holes
REPAIR PROCEDURES		SRM 51-70-04 and Paragraph 4.B	SRM 51-70-05 and Paragraph 4.C	SRM 51-70-05 and Paragraph 4.C



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



IDENTIFICATION 1 - ELEVATOR BALANCE HORN FAIRING



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.


Elevator Balance Horn Fairing Location Figure 1

	Table 1:		
	REFERENCE DRAWINGS		
DRAWING NUMBER	TITLE		
183A0101	Elevator Assembly - Functional Product Collector		
183A6000	Elevator Leading Edge Installation		
183A7000	Elevator Balance Horn Assembly		
183A7400	Elevator Balance Horn Fairing		





737-800 STRUCTURAL REPAIR MANUAL



THE LEFT ELEVATOR BALANCE HORN FAIRING IS SHOWN, THE RIGHT ELEVATOR BALANCE HORN FAIRING IS OPPOSITE

Elevator Balance Horn Fairing Identification Figure 2

Table 2:


LIST OF MATERIALS FOR FIGURE 2				
ITEM	ITEM DESCRIPTION T ^{*[1]} MATERIAL EFFECTIVITY			
[1]	Fairing		Refer to Figure 3	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).






737-800 STRUCTURAL REPAIR MANUAL







NOTE: REFER TO TABLE 3 FOR THE DIRECTION AND MATERIAL OF THE PLIES.

Ply Direction and Ply Layup Sequence for the Elevator Balance Horn Fairing Figure 3



Page 3



Table 3:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [1]			
PLY DIRECTION MATERIAL			
P1, P14	0 or 90 degrees	Glass Fiber Reinforced Plastic (GFRP) as given in BMS 8-79, Class 3, Grade B, Style 120	
P2, P13	+ or - 45 degrees	GFRP as given in BMS 8-79, Class 3, Grade B, Style 120	
P3, P5, P7, P8, P10, P12	0 or 90 degrees	GFRP as given in BMS 8-79, Class 3, Grade B, Style 1581	
P4, P6, P9, P11	+ or - 45 degrees	GFRP as given in BMS 8-79, Class 3, Grade B, Style 1581	







ALLOWABLE DAMAGE 1 - ELEVATOR BALANCE HORN FAIRING

1. Applicability

A. Allowable Damage 1 is applicable to damage on the elevator balance horn fairing skin as shown in Elevator Balance Horn Fairing Location, Figure 101/ALLOWABLE DAMAGE 1.



REFER TO SRM 55-20-70 FOR THE ELEVATOR FAIRING AND THE ELEVATOR TAB FAIRING



Elevator Balance Horn Fairing Location Figure 101

2. General

- A. Do an inspection of the damaged area to find the length, width, and depth of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 for inspection procedures.
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.






- (1) Refer to Damage Definitions, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, and C for the definitions of the length, width, and depth of the damage.
- B. Remove all the contamination and water from the fairing.
 - (1) Refer to 51-30-05 for possible sources of the tools and equipment you can use to remove the damage.
 - (2) Refer to 51-70-04 for the cleanup procedures.
- C. Seal all the permitted damage areas that are not more than one ply in depth. Refer to the allowable damage limits in Paragraph 4./ALLOWABLE DAMAGE 1 Use one of the two methods that follow:
 - (1) Make a temporary seal.
 - (a) Apply aluminum foil tape (speed tape).
 - (b) Keep a record of the location of the damage.
 - (c) If the tape is on the external surface of the fairing, then make sure that it is in satisfactory condition at normal maintenance intervals.
 - (2) Make a permanent seal.
 - (a) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given in 51-70-08.
 - (b) Apply one layer of BMS 10-79, Type III or BMS 10-103, Type I primer. Refer to SOPM 20-44-04.
 - (c) Apply one layer of BMS 10-60, Type II enamel to the external surfaces of the fairing that area sealed with epoxy resin. Refer to AMM PAGEBLOCK 51-21-99/701.
- D. Seal all of the damage areas that are more than one ply in depth. Refer to the allowable damage limits given in Paragraph 4./ALLOWABLE DAMAGE 1
 - (1) Use a vacuum and heat to remove moisture from the solid laminate. Refer to 51-70-04.
 - (2) Make a temporary seal with aluminum foil tape (speed tape).
 - (3) Keep a record of the location of the damage.
 - (4) Repair the damage at or before 250 flight cycless from the time the seal was made.
- E. The definition of the words "other damage", as used in the allowable damage limits, does not include nicks, gouges, and scratches that do not cause damage to the glass fibers and are sealed.






737-800 STRUCTURAL REPAIR MANUAL



DEFINITIONS OF THE SIZES FOR NICK, GOUGE, AND SCRATCH DAMAGE

А





D634A210



3. References

Reference	Title
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05, GENERAL	Repair Sealing
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-60-04, GENERAL	Elevator Balance Procedure For Airplane Line Numbers 1 Through 1174 Prior To Completion of Service Bulletins 737-55-1080, 737-55-1081, and 737-55-1082
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-08	RESIN SWEEP-FAIR PROCEDURES
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Allowable Damage Limits

- A. Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted.
- B. Nicks, Gouges, and Scratches that cause damage to the glass fibers are permitted if:
 - (1) The depth is a maximum of one ply.

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (2) The length is a maximum of 5.0 inches (127.0 mm)
- (3) The damage is a minimum of 4D (D = the diameter of the damage) away from the edge of other damage.
- C. Dents that do not cause damage to the glass fibers are permitted if:
 - (1) The depth is a maximum of 0.05 inch (1.27 mm)

NOTE: Use the limits for holes and punctures if the damage is more than 0.05 inch (1.27 mm) in depth.

- (2) The diameter is a maximum of 2.0 inches (50.80 mm)
- (3) The damage is a minimum of 4D (D = the diameter of the damage) away from the edge of other damage, a hole, or the edge of the part.
- D. Holes and Punctures are permitted if:
 - (1) The diameter is a maximum of 2.0 inch (50.80 mm)
 - (2) The damage is a minimum of 4D (D = the diameter of the damage) away from the edge of other damage, a hole, or the edge of the part.
- E. Delaminations are permitted if:
 - (1) The diameter is a maximum of 2.0 inch (50.8 mm)
 - (2) The damage is a minimum of 2D (D = the diameter of the damage) away from the edge of other damage, a hole, or the edge of the part.
 - (3) Edge damage is permitted if:
 - (a) The depth is a maximum of 0.10 inch (2.54 mm)
 - (b) The width is a maximum of 0.50 inch (12.70 mm)





(4) The damage is a minimum of 4D (D = the diameter of the damage) away from the edge of other damage.





REPAIR 1 - ELEVATOR BALANCE HORN FAIRING

1. Applicability


- A. Repair 1 is applicable to the elevator balance horn fairing made of Glass Fiber Reinforced Plastic (GFRP) as shown in Elevator Balance Horn Fairing Location, Figure 201/REPAIR 1.
- B. Repair 1 is applicable to damage that is more than the limits permitted in Allowable Damage 1. Refer to Allowable Damage 1 for the type and size of damage that is permitted.

2. General

- A. Repair 1 gives the instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Get access to the damaged area.
 - (1) If necessary, remove the elevator balance horn fairing.
 - (2) Refer to 51-40-02 for information on fastener removal.
- C. Do an inspection of the damaged area to find the dimensions of the damage.
 - (1) Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 for the inspection procedures.
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.
- D. Refer to Damage Definitions, Figure 202/REPAIR 1, Details A, B, and C for the definitions of the length, width, and depth of damage.
- E. Do the repair as given in Paragraph 4./REPAIR 1
- F. Put the balance horn fairing back to the initial condition, as applicable.
 - (1) Install the fairing if it was removed. Refer to 51-40-02 for the data about fastener installation.
- G. Do a check of the elevator balance. Refer to 51-60-04



REPAIR 1 Page 201 Nov 01/2003






REPAIR 1 Page 202 Nov 01/2003

D634A210



737-800 STRUCTURAL REPAIR MANUAL



DEFINITIONS OF THE SIZES FOR NICK, GOUGE, AND SCRATCH DAMAGE

А




Figure 202



REPAIR 1 Page 203 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01, GENERAL	Aerodynamic Smoothness Requirements
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-05, GENERAL	Repair Sealing
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-60-04	ELEVATOR BALANCE PROCEDURE
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05, REPAIR GENERAL	Repair Procedures for Preimpregnated Materials
51-70-06, REPAIR GENERAL	Room Temperature Cure Repairs With Wet Layup Materials For Glass Fabric Reinforced Plastic Solid Laminates and Honeycomb Core Panels
737 NDT Part 1, 51-01-01	Inspection of Repairs to Composite Structure
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Repair Instructions

- A. If a dent is 2 inches (50.80 mm) in diameter or less, and has no fiber damage or delamination, then fill the dent with potting compound and apply a fiberglass patch as given in Repair 14 of 51-70-04.
- B. If Paragraph 4.A./REPAIR 1 is not applicable, then refer to Table 201/REPAIR 1 for the repair data that is applicable to damage to the elevator balance horn fairing.
- C. For repairs made with wet layup materials, do the staps that follow, as applicable:
 - (1) Use one repair ply of fabric for each initial ply that was damaged.
 - (2) Add two structural plies of fabric for each facesheet that is repaired. Put one structural ply at ± 45 degrees to the core ribbon direction and the other at 0 or 90 degrees.
 - **NOTE**: Repair plies or added plies are not necessary in the repair of delamination at an edge if the delamination is a minimum of 2D (D = fastener diameter) away from a fastener hole.
 - (3) Examine Category B repairs after each interval of 800 flight hours or more frequently. Refer to 737 NDT Part 1, 51-01-01 for the inspection procedures. If deterioration is found, then they must be replaced with Category A repairs.

NOTE: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.

D. For repairs made with preimpregnated layup materials, use the same number of repair plies as the number of initial plies that were damaged.



REPAIR 1 Page 204 Jul 10/2005



Table 201:


RE	REPAIR DATA FOR THE ELEVATOR BALANCE HORN FAIRING - 250°F (121°C) CURE					
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED LAYUP		
REPAIR CURE TEMPERATURE	Room Temperature	150°F (66°C)	200°F (93°C)	250°F (121°C)		
REPAIR SIZE AND LIMITS	Contact Boeing for repair instructions	Damage that is a maximum of: -5.0 in. (127 mm) in diameter	Damage that is a maximum of: - 5 in. (127 mm) in diameter	There are no limits on the dimensions of the repair		
		- 2.0 inches (50.80 mm) minimum clearance from:	-2.0 inches (50.80 mm) minimum clearance from:			
		- other repairs - fastener holes - panel edges	- other repairs - fastener holes - panel edges			
REPAIR PROCEDURES	Not permitted	SRM 51-70-04 and Paragraph 4.C	SRM 51-70-04 and Paragraph 4.C	SRM 51-70-05 and Paragraph 4.D		



D634A210



IDENTIFICATION 1 - ELEVATOR FAIRING AND ELEVATOR TAB FAIRING SKIN




NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Elevator Fairing Skin Location Figure 1

Table 1:					
	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
001A0001	Final Assembly - Product Collector				
183A0001	Elevator Integration Functional Product Collector				
183A0002	Elevator Integration Functional Product Collector				
183A0101	Elevator Assembly Functional Product Collector				
183A3000	Upper Skin Panel Installation - Elevator				
183A3300	Fairing - Tab Control Rod, Elevator				
183A8000	Tab Installation - Elevator				
183A8100	Tab Assembly - Elevator				
183A8500	Mast Arm Fairing - Tab, Elevator				



IDENTIFICATION 1 Page 1 Jul 10/2004



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

(FOR AIRPLANE LINE NUMBERS 1175 AND ON)

Elevator Fairing Skin Identification Figure 2



Page 2




Table 2:

	LIST OF MATERIALS FOR FIGURE 2				
ITEM	ITEM DESCRIPTION T ⁽¹⁾ MATERIAL EFFECTIVITY				
[1]	Fairing - Tab Control Rod		Epoxy sheet molding compound as given in BMS 8-327, Type I-Lytex 9063		

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).



D634A210



NOTE: REFER TO TABLE 3 FOR THE LIST OF MATERIALS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE (FOR AIRPLANE LINE NUMBERS 1 THROUGH 1174)

> Elevator Tab Fairing Skin Identification Figure 3





Table 3:

	LIST OF MATERIALS FOR FIGURE 3				
ITEM	ITEM DESCRIPTION T ⁽¹⁾ MATERIAL EFFECTIVITY				
[1]	Fairing - Mast Arm		Epoxy sheet molding compound as given in BMS 8-327, Type I-Lytex 9063		

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





ALLOWABLE DAMAGE 1 - ELEVATOR FAIRING SKIN AND ELEVATOR TAB FAIRING SKIN

1. Applicability

A. This subject gives the allowable damage limits for the elevator tab control rod fairing and the elevator tab mast arm fairing as shown in Elevator Fairing Skin Allowable Damage, Figure 101/ALLOWABLE DAMAGE 1. Refer to Elevator Fairing Skin Allowable Damage, Figure 102/ALLOWABLE DAMAGE 1 for the elevator tab control rod fairing details. Refer to Elevator Tab Fairing Skin Allowable Damage, Figure 103/ALLOWABLE DAMAGE 1 for the elevator tab control rod fairing details.

2. General

A. Do an inspection of the damaged area to find the length, width and depth of the damage. Boeing recommends that you do an instrumented Non-Destructive Test (NDT) procedure. Refer to 737 NDT Part 1, 51-01-02 for inspection procedures.


NOTE: Other inspection procedures that are satisfactory to the operator can be used.

- B. Refer to Definitions of the Damage Size, Figure 104/ALLOWABLE DAMAGE 1, Details A, B, and C for the definitions of the length, width, and depth of damage.
- C. Remove contamination and water from the structure surface.
 - (1) Refer to 51-30-05 for possible sources of the tools and equipment you can use to remove the damage.
 - (2) Refer to 51-70-04 for the damage removal procedures.
- D. Seal all permitted damage areas. Refer to the allowable damage limits. Seal the damage with one of the two methods that follow:
 - (1) Make a temporary seal.
 - (a) Apply aluminum foil tape (speed tape).
 - (b) Keep a record of the location.
 - (c) Monitor and re-apply the tape as necessary at normal maintenance intervals.
 - (2) Make a permanent seal.
 - (a) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given 51-70-08.
 - (b) Apply one layer of BMS 10-79, Type 3 primer. Refer to SOPM 20-44-04.
 - (c) Apply one layer of BMS 10-60 enamel to the areas sealed with epoxy resin. Refer to AMM PAGEBLOCK 51-21-99/701.






737-800 STRUCTURAL REPAIR MANUAL




Elevator Fairing Skin Allowable Damage Figure 101






D634A210








737-800 STRUCTURAL REPAIR MANUAL



SIZE DEFINITIONS FOR NICK, GOUGE, OR SCRATCH DAMAGE (A)



Definitions of the Damage Size Figure 104







3. References

Reference	Title
51-30-03, GENERAL	Sources for Non-Metallic Repair Materials
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-08	RESIN SWEEP-FAIR PROCEDURES
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Allowable Damage Limits


- A. Nicks, Gouges, and Scratches are permitted if they are:
 - (1) A maximum of 0.01 inch in depth.
 - (2) A maximum of 3.00 inches in length for the elevator fairing skin.
 - (3) A maximum of 2.50 inches in length for the elevator tab fairing skin.
 - (4) A minimum of 1.00 inches (edge to edge) from other damage, a hole or part edge.
- B. Dents are permitted if they are:
 - (1) A maximum of 0.50 inch diameter.
 - (2) A maximum of 0.025 inch in depth.
 - **NOTE**: Use the limits for holes and punctures if the dent damage is more than 0.025 inch in depth.
 - (3) A minimum (edge to edge) of 4D (D = dimension of the damage) from other damage, a hole or part edge.
- C. Holes and Punctures are permitted if they are:
 - (1) A maximum diameter of 0.50 inch.
 - (2) A minimum (edge to edge) of 4D (D = dimension of the damage) from other damage, from a hole or part edge.
- D. Edge damage is permitted if it is:
 - (1) A maximum of 0.10 inch depth.
 - (2) A maximum of 0.25 inch width.
 - (3) A minimum of 1.00 inch (edge to edge) away from other damage, a fastener hole or part edge.



Page 106




REPAIR 1 - ELEVATOR FAIRING AND ELEVATOR TAB FAIRING SKIN



Elevator Fairing Skin Repair Figure 201




REPAIR 1 Page 201 Nov 01/2003



Elevator Fairing Skin Repair Figure 202



REPAIR 1 Page 202 Mar 10/2007




Elevator Tab Fairing Skin Repair Figure 203



REPAIR 1 Page 203 Mar 10/2007



IDENTIFICATION 1 - ELEVATOR FRONT SPAR HINGE FITTINGS



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS. LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE


Elevator Front Spar Hinge Fittings Figure 1

Table 1:					
	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
183A1000	Elevator Front Spar Assembly				
183A1310	Elevator Hinge Fitting Assembly				
183A1320	Elevator Hinge Fitting Assembly				
183A1330	Elevator Hinge Fitting Assembly				
183A1340	Elevator Hinge Fitting Assembly				
183A1350	Elevator Hinge Fitting Assembly				
183A1360	Elevator Hinge Fitting Assembly				
183A1370	Elevator Hinge Fitting Assembly				






737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE (FOR AIRPLANE LINE NUMBERS 1 THROUGH 1174)



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE (FOR AIRPLANE LINE NUMBERS 1175 AND ON)

> **Elevator Front Spar Hinge Fittings Location** Figure 2




Page 2

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL




NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Elevator Front Spar Hinge Fittings Identification Figure 3 (Sheet 1 of 2)



ABDEING®

737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Elevator Front Spar Hinge Fittings Identification Figure 3 (Sheet 2 of 2)





Table 2:


LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Mast Arm Fitting Assembly			
	Mast Arm Fitting		7050-T7451 plate as given in BMS 7-323	
	Failsafe Strap		7075-T7351 plate	
[2]	Elevator Hinge Fitting Assembly		7050-T7451 plate as given in BMS 7-323	
[3]	Tab Control Bracket Assembly			
	Bracket		7075-T7351 plate	
	Bracket Doubler	0.09 (2.29)	7075-T6 sheet	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





IDENTIFICATION 2 - ELEVATOR REAR SPAR HINGE FITTINGS



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Elevator Rear Spar Hinge Fittings Locations Figure 1


Table 1:

	REFERENCE DRAWINGS				
DRAWING NUMBER TITLE					
183A4000	183A4000 Elevator Rear Spar Assembly				
183A4210	183A4210 Elevator Rear Spar Hinge Fitting				



Page 1






Elevator Rear Spar Hinge Fitting Locations Figure 2 (Sheet 1 of 2)



IDENTIFICATION 2 Page 2 Mar 10/2004

D634A210





LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE (FOR AIRPLANE LINE NUMBERS 1175 AND ON)



Elevator Rear Spar Hinge Fitting Locations Figure 2 (Sheet 2 of 2)



IDENTIFICATION 2 Page 3 Nov 01/2003

D634A210

BOEING PROPRIETARY - Copyright ${\rm (\sc)}$ Unpublished Work - See title page for details




Table 2:

LIST OF MATERIALS FOR FIGURE 2			
ITEM	DESCRIPTION	MATERIAL	EFFECTIVITY
[1]	Hinge Fitting	7075-T7351 plate as given in QQ-A-250/12	For airplane line numbers 1 though 1174
		7050-T7451 plate as given in BMS 7-323, Type III	For airplane line numbers 1175 and on





IDENTIFICATION 3 - ELEVATOR TAB FITTINGS



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Elevator Tab Fittings Location Figure 1

Table 1:

REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE			
183A8000	Elevator Tab Installation			
183A8100	Elevator Tab Assembly			




Page 1

D634A210




737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE (FOR AIRPLANE LINE NUMBERS 1 THROUGH 1174)



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE (FOR AIRPLANE LINE NUMBERS 1175 AND ON)

Elevator Tab Fittings Identification

Figure 2



Page 2



Table 2:

LIST OF MATERIALS FOR FIGURE 2					
ITEM	DESCRIPTION	т	MATERIAL	EFFECTIVITY	
[1]	Hinge/Mast Arm		7050-T7451 plate as given in BMS 7-323, Type III		
[2]	Hinge Fitting		7075-T7351 plate as given in QQ-A-250/12	For cum lines 1 through 1174	
			7050-T7451 plate as given in BMS 7-323, Type III	For cum lines 1175 and on	



IDENTIFICATION 3 Page 3 Nov 01/2003

D634A210



ALLOWABLE DAMAGE 1 - ELEVATOR FRONT SPAR HINGE FITTINGS

1. Applicability

A. This subject gives the allowable damage limits for the elevator front spar hinge fittings shown in Elevator Front Spar Hinge Fittings Location, Figure 101/ALLOWABLE DAMAGE 1.


2. General

- A. Refer to Paragraph 4./ALLOWABLE DAMAGE 1 for the allowable damage limits.
- B. Remove the damage as necessary.
 - (1) Refer to 51-10-02 for the investigation and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of non-metallic materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (4) Put a surface finish of 125 microinches Ra or better on the reworked areas.
- C. After you remove the damage, do the steps that follow:

WARNING: MAKE SURE THAT YOU WEAR EYE PROTECTION WHEN YOU USE THE FLAP PEEN WHEEL. IF YOU DO NOT OBEY, AN INJURY CAN OCCUR.

- (1) Flap peen or shot peen the reworked areas of the parts, but not the inner surfaces of the lug bores.
 - (a) Refer to 51-20-06 for the shot peen intensity and shot number.
 - (b) Refer to SOPM 20-10-03 for the flap peen and shot peen procedures.
- (2) Apply a chemical conversion coating to the reworked areas. Refer to 51-20-01.
- (3) Apply a layer of BMS 10-79, Type III primer to the reworked areas. Refer to SOPM 20-44-04.






BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details

BOEING®

737-800 STRUCTURAL REPAIR MANUAL




(FOR AIRPLANE LINE NUMBERS 1175 AND ON)

Elevator Front Spar Hinge Fittings Figure 102 (Sheet 1 of 5)



BOEING®

737-800 STRUCTURAL REPAIR MANUAL




(FOR AIRPLANE LINE NUMBERS 1 THROUGH 1174)

Elevator Front Spar Hinge Fittings Figure 102 (Sheet 2 of 5)





737-800 STRUCTURAL REPAIR MANUAL



Elevator Front Spar Hinge Fittings Figure 102 (Sheet 3 of 5)


Α



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL



В

Elevator Front Spar Hinge Fittings Figure 102 (Sheet 4 of 5)




Page 106

D634A210 BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL







3. References

Reference	Title
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-06	SHOT PEENING
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
SOPM 20-10-03	General - Shot Peening Procedures
SOPM 20-20-02	Penetrant Methods of Inspection
SOPM 20-44-04	Application of Urethane Compatible Primers


4. Allowable Damage Limits

- A. Mast Arm Fitting and Elevator Hinge Fittings (Except at ELEV STA 39.02 and ELEV STA 66.54)
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A, B, C, D, and E.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- B. Elevator Hinge Fittings (ELEV STA 39.02 and ELEV STA 66.54)
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A and B.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 1, Details A, B, and E.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.






737-800 STRUCTURAL REPAIR MANUAL




Allowable Damage Limits Figure 103 (Sheet 1 of 3)

> ALLOWABLE DAMAGE 1 55-20-90 Page 109 Nov 01/2003

BOEING



BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details




NOTE: DAMAGED SEALANT IS NOT PERMITTED. IF THE SEALANT IS DAMAGED, LOOK FOR MIGRATION OR ROTATION OF THE BUSHING. IF THERE IS NO MIGRATION, ROTATION, OR CORROSION, REMOVE THE DAMAGED SEALANT AND APPLY A NEW FILLET SEAL.

REMOVAL OF SURFACE AND EDGE DAMAGE FROM A LUG THAT HAS A BUSHING



SURFACE DAMAGE MUST BE A MINIMUM OF 0.20 INCH FROM THE EDGE OF THE BUSHING



B–B

Allowable Damage Limits Figure 103 (Sheet 3 of 3)

> ALLOWABLE DAMAGE 1 55-20-90 Page 111 Nov 01/2003



ALLOWABLE DAMAGE 2 - ELEVATOR REAR SPAR HINGE FITTINGS

1. Applicability

A. This subject gives the allowable damage limits for the elevator rear spar hinge fittings shown in Figure 101.

2. General

- A. Refer to Paragraph 4./ALLOWABLE DAMAGE 2 for the allowable damage limits.
- B. Remove the damage as necessary.
 - (1) Refer to 51-10-02 for the investigation and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of non-metallic materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (4) Put a surface finish of 125 microinches Ra or better on the reworked areas.
- C. After you remove the damage, do the steps that follow:


WARNING: MAKE SURE THAT YOU WEAR EYE PROTECTION WHEN YOU USE THE FLAP PEEN WHEEL. IF YOU DO NOT OBEY, AN INJURY CAN OCCUR.

- (1) Flap peen or shot peen the reworked areas of the parts, but not the inner surfaces of the lug bores.
 - (a) Refer to 51-20-06 for the shot peen intensity and shot number.
 - (b) Refer to SOPM 20-10-03 for the flap peen and shot peen procedures.
- (2) Apply a chemical conversion coating to the reworked areas. Refer to 51-20-01.
- (3) Apply a layer of BMS 10-79, Type III primer to the reworked areas. Refer to SOPM 20-44-04.



BOEING

737-800 STRUCTURAL REPAIR MANUAL



Elevator Rear Spar Hinge Fitting Locations Figure 101 (Sheet 1 of 2)




Page 102

Nov 01/2003

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details





LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE (FOR AIRPLANE LINE NUMBERS 1175 AND ON)

> **Elevator Rear Spar Hinge Fitting Locations** Figure 101 (Sheet 2 of 2)




Page 103

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details

BOEING

737-800 STRUCTURAL REPAIR MANUAL






Page 104

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL




ELEVATOR REAR SPAR HINGE FITTINGS (FOR AIRPLANE LINE NUMBERS 1175 AND ON) В

Elevator Rear Spar Hinge Fittings Figure 102 (Sheet 2 of 3)



Page 105

D634A210



D634A210



3. References

Reference	Title
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-06	SHOT PEENING
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
SOPM 20-10-03	General - Shot Peening Procedures
SOPM 20-20-02	Penetrant Methods of Inspection
SOPM 20-44-04	Application of Urethane Compatible Primers


4. Allowable Damage Limits

- A. Hinge Fittings (Except at ELEV STA 37.63)
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 103/ALLOWABLE DAMAGE 2, Details A, B, C, D, and E.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- B. Hinge Fitting at ELEV STA 37.63
 - (1) Damage is not permitted.



BOEING


737-800 STRUCTURAL REPAIR MANUAL



Allowable Damage Limits Figure 103 (Sheet 1 of 3)




Page 108



BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL



Allowable Damage Limits Figure 103 (Sheet 3 of 3)

> ALLOWABLE DAMAGE 2 Page 110 Nov 01/2003


D634A210



ALLOWABLE DAMAGE 3 - ELEVATOR TAB FITTINGS

1. Applicability

A. This subject gives the allowable damage limits for the elevator tab fittings shown in Elevator Tab Fitting Location, Figure 101/ALLOWABLE DAMAGE 3.




Elevator Tab Fitting Location Figure 101 (Sheet 1 of 4)





737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE (FOR AIRPLANE LINE NUMBERS 1175 AND ON)


> Elevator Tab Fitting Location Figure 101 (Sheet 2 of 4)




D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL






Elevator Tab Fitting Location Figure 101 (Sheet 3 of 4)




D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL





Elevator Tab Fitting Location Figure 101 (Sheet 4 of 4)



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



2. General

- A. Refer to Paragraph 4./ALLOWABLE DAMAGE 3 for the allowable damage limits.
- B. Remove the damage as necessary.
 - (1) Refer to 51-10-02 for the investigation and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of non-metallic materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (4) Put a surface finish of 125 microinches Ra or better on the reworked areas.
- C. After you remove the damage, do the steps that follow:

WARNING: MAKE SURE THAT YOU WEAR EYE PROTECTION WHEN YOU USE THE FLAP PEEN WHEEL. IF YOU DO NOT OBEY, AN INJURY CAN OCCUR.

- (1) Flap peen or shot peen the reworked areas of the parts, but not the inner surfaces of the lug bores.
 - (a) Refer to 51-20-06 for the shot peen intensity and shot number.
 - (b) Refer to SOPM 20-10-03 for the flap peen and shot peen procedures.
- (2) Apply a chemical conversion coating to the reworked areas. Refer to 51-20-01.
- (3) Apply a layer of BMS 10-79, Type III primer to the reworked areas. Refer to SOPM 20-44-04.

3. References

Reference	Title
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-06	SHOT PEENING
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
SOPM 20-10-03	General - Shot Peening Procedures
SOPM 20-20-02	Penetrant Methods of Inspection
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Allowable Damage Limits


- A. Hinge Fittings
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 3, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 3, Details A, B, C, D, and E.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- B. Mast Fitting
 - (1) Damage is not permitted.





BOEING


737-800 STRUCTURAL REPAIR MANUAL




Allowable Damage Limits Figure 102 (Sheet 1 of 3)



Page 106 Nov 01/2003



BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



Allowable Damage Limits Figure 102 (Sheet 3 of 3)

55-20-90


ALLOWABLE DAMAGE 3

Page 108

Nov 01/2003



REPAIR 1 - ELEVATOR FRONT SPAR HINGE FITTINGS



<u>NOTE</u>: BOEING HAS NOT FOUND IT NECESSARY TO SUPPLY REPAIRS FOR THIS PART IN THE STRUCTURAL REPAIR MANUAL AT THIS TIME.

Elevator Front Spar Hinge Fitting Locations Figure 201




REPAIR 1 Page 201 Nov 10/2006



A BOEING®

737-800 STRUCTURAL REPAIR MANUAL



NOTE: THERE ARE NO REPAIRS FOR THIS PART IN THE STRUCTURAL REPAIR MANUAL AT THIS TIME.

(FOR AIRPLANE LINE NUMBERS 1175 AND ON)


Elevator Front Spar Hinge Fitting Repair Figure 202 (Sheet 1 of 2)



REPAIR 1 Page 202 Mar 10/2007

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



FWD

<u>NOTE</u>: THERE ARE NO REPAIRS FOR THIS PART IN THE STRUCTURAL REPAIR MANUAL AT THIS TIME.

(FOR AIRPLANE LINE NUMBERS 1 THROUGH 1174)

Elevator Front Spar Hinge Fitting Repair Figure 202 (Sheet 2 of 2)




REPAIR 1 Page 203 Mar 10/2007



737-800 STRUCTURAL REPAIR MANUAL

REPAIR 2 - ELEVATOR REAR SPAR HINGE FITTINGS



STRUCTURAL REPAIR MANUAL AT THIS TIME.

Elevator Rear Spar Hinge Fitting Locations Figure 201 (Sheet 1 of 2)




REPAIR 2 Page 201 Nov 01/2003





737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE (FOR AIRPLANE LINE NUMBERS 1175 AND ON)

Elevator Rear Spar Hinge Fitting Locations Figure 201 (Sheet 2 of 2)




REPAIR 2 Page 202 Nov 01/2003





737-800 STRUCTURAL REPAIR MANUAL



<u>NOTE</u>: THERE ARE NO REPAIRS FOR THIS PART IN THE STRUCTURAL REPAIR MANUAL AT THIS TIME.

ELEVATOR REAR SPAR HINGE FITTINGS


(FOR AIRPLANE LINE NUMBERS 1 THROUGH 1174)

Elevator Rear Spar Hinge Fitting Repair Figure 202 (Sheet 1 of 2)



REPAIR 2 Page 203 Mar 10/2007

737-800 STRUCTURAL REPAIR MANUAL



<u>NOTE</u>: THERE ARE NO REPAIRS FOR THIS PART IN THE STRUCTURAL REPAIR MANUAL AT THIS TIME.

(FOR AIRPLANE LINE NUMBERS 1175 AND ON)


Elevator Rear Spar Hinge Fitting Repair Figure 202 (Sheet 2 of 2)



REPAIR 2 Page 204 Mar 10/2007



REPAIR 3 - ELEVATOR TAB FITTINGS



NOTE: THERE ARE NO REPAIRS FOR THIS PART IN THE STRUCTURAL REPAIR MANUAL AT THIS TIME.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

(FOR AIRPLANE LINE NUMBERS 1175 AND ON)



Elevator Tab Fitting Repair Figure 201 (Sheet 1 of 2)




REPAIR 3 Page 201 Mar 10/2007





737-800 STRUCTURAL REPAIR MANUAL



NOTE: THERE ARE NO REPAIRS FOR THIS PART IN THE STRUCTURAL REPAIR MANUAL AT THIS TIME.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE (FOR AIRPLANE LINE NUMBERS 1 THROUGH 1174)

В

Elevator Tab Fitting Repair Figure 201 (Sheet 2 of 2)



REPAIR 3 Page 202 Mar 10/2007






IDENTIFICATION GENERAL - VERTICAL STABILIZER AND RUDDER STATION DIAGRAM

1. General

A. The vertical stabilizer and rudder station diagram gives the locations of the structural components on the vertical stabilizer and rudder (Refer to Vertical Stabilizer Station Diagram, Figure 1/IDENTIFICATION GENERAL).




Vertical Stabilizer Station Diagram Figure 1 (Sheet 1 of 3)






737-800 STRUCTURAL REPAIR MANUAL



Vertical Stabilizer Station Diagram Figure 1 (Sheet 2 of 3)





Vertical Stabilizer Station Diagram Figure 1 (Sheet 3 of 3)





IDENTIFICATION 1 - VERTICAL STABILIZER LEADING EDGE SKIN

A
h/h Refer to SRM 55–30–30 For
LE STA 📈 // THE VERTICAL STABILIZER
297.56 — 📈 // / TIP SKIN IDENTIFICATION
LE STA REFER TO FIGURE 2 FOR
232.07 - H H
LE STA
166.58 - /]
LE STA
98.03 - (
REFER TO SRM 55-30-01,
IDENTIFICATION 6 FOR
THE DORSAL FIN SKIN

NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.


LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Vertical Stabilizer Leading Edge Skin Locations Figure 1

Table 1:

REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE			
176A0001	Leading Edge and Miscellaneous Functional Collector - Vertical Fin			
176A1001	Removable Leading Edge Assembly/Installation - Vertical Fin			
176A1100	Skin Assembly - Removable Leading Edge Vertical Fin			
176A3001	Fixed Leading Edge Installation - Vertical Fin			
176A3009	Skin Assembly - Fixed Leading Edge, Vertical Fin			





NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Vertical Fin Leading Edge Panel Identification Figure 2



Page 2



Table 2:


	LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY	
[1]	Skin	0.040 (1.02)	2024-T3 clad sheet as given in QQ-A-250/5		
[2]	Skin	0.071 (1.80)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 3 for the chem-mill areas		
[3]	Fiberglass Strap		Glass Fabric Reinforced Plastic (GFRP) as given in BMS 8-79, Class III, Grade B, Style 1581		
[4]	Splice	0.050 (1.27)	2024-T3 clad sheet as given in QQ-A-250/5		
[5]	Skin	0.071 (1.80)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 4 for the chem-mill areas		
[6]	Lower Strap	0.312 (7.92)	7050-T7451 machined plate as given in AMS 4050		
[7]	Upper Strap	0.500 (12.70)	7050-T7451 machined plate as given in AMS 4050		

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).




BOEING®

737-800 STRUCTURAL REPAIR MANUAL



Chem-Milled Areas for Figure 2, Item [2] Figure 3






Chem-Milled Areas for Figure 2, Item [5] Figure 4





IDENTIFICATION 2 - VERTICAL STABILIZER LEFT INSPAR SKIN



Vertical Stabilizer Inspar Skin Locations Figure 1


Table 1:

	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
172A0001	Torque Box Functional Collector - Vertical Fin				
172A4001	Skin Installation - Inspar, Vertical Fin				
172A6120	Panel Installation - Fin to Body, Vertical Fin				
172A6121	Panel Assembly, Closeout - Vertical Fin				
172A6122	Door Assembly, Access - Vertical Fin				





737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN

NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Vertical Stabilizer Inspar Skin Identification Figure 2



IDENTIFICATION 2 Page 2 Mar 10/2004




Table 2:

	LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY	
[1]	Access Door	0.100 (2.54)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 3 for the chem-mill areas		
[2]	Inspar Closeout Panel - Bonded Assembly		Glass Fabric Reinforced Plastic (GFRP) honeycomb sandwich		
	Skin		Refer to Figure 4 for the 0 degree ply direction, material, and ply sequence		
	Core		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 4 for the core ribbon direction		
[3]	Aft Closeout Panel	0.100 (2.54)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 5 for the chem-mill areas		
[4]	Skin Panel - Lower Left Hand	0.071 (1.80)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 6 for the chem-mill areas		
[5]	Skin Panel - Upper Left Hand	0.071 (1.80)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 7 for the chem-mill areas		
[6]	Door	0.071 (1.80)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 8 for the chem-mill areas		
[7]	Door	0.071 (1.80)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 9 for the chem-mill areas		
[8]	Doubler	0.250 (6.35)	7075-T7351 plate as given in QQ-A-250/12		
[9]	Doubler	0.063 (1.60)	2024-T3 clad sheet as given in QQ-A-250/5		
[10]	Doubler	0.025 (0.64)	2024-T3 clad sheet as given in QQ-A-250/5		
[11]	Door	0.071 (1.80)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 10 for the chem-mill areas		
[12]	Strap	0.090 (2.29)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Boeing production drawings for the chem-mill thicknesses		
[13]	Strap	0.100 (2.54)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Boeing production drawings for the chem-mill thicknesses		

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).







Chem-milled Areas for Figure 2, Item [1] Figure 3






Table 3:

	PLY MATERIAL AND DIRECTION FOR FIGURE 4					
PLY	DIRECTION	MATERIAL				
P1, P2, P5, P6	+ or - 45 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781				
P3, P4	90 degrees	Epoxy/Graphite tape as given in BMS 8-168, Type II, Class I, Grade 145				
P7		0.001 inch (0.025 mm) thick white bondable tedlar film				
P8		Bondable teflon				



DEING®

737-800 STRUCTURAL REPAIR MANUAL




Ply Direction, Core Ribbon Direction, and Ply Sequence for the Inspar Closeout Panel, Figure 2, Item [2] Figure 4 (Sheet 1 of 2)





737-800 STRUCTURAL REPAIR MANUAL






Ply Direction, Core Ribbon Direction, and Ply Sequence for the Inspar Closeout Panel, Figure 2, Item [2] Figure 4 (Sheet 2 of 2)





737-800 STRUCTURAL REPAIR MANUAL




Chem-milled Areas for Figure 2, Item [3] Figure 5



ABDEING®


737-800 STRUCTURAL REPAIR MANUAL



NOTE: ALL DIMENSIONS SHOWN ARE THICKNESSES IN INCHES.

Chem-milled Areas for Figure 2, Item [4] Figure 6

> IDENTIFICATION 2 Page 9 Mar 10/2004




Chem-milled Areas of Figure 2, Item [5] Figure 7






737-800 STRUCTURAL REPAIR MANUAL



Chem-milled Areas of Figure 2, Item [6] Figure 8



737-800 STRUCTURAL REPAIR MANUAL




Chem-milled Areas of Figure 2, Item [7] Figure 9



BOEING®

737-800 STRUCTURAL REPAIR MANUAL



Chem-milled Areas of Figure 2, Item [11] Figure 10



Page 13 Mar 10/2004


D634A210

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL

IDENTIFICATION 3 - VERTICAL STABILIZER LEFT TRAILING EDGE PANELS



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.


LEFT SIDE IS SHOWN

Vertical Stabilizer Trailing Edge and Closeout Panel Locations Figure 1

Table 1:

	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
172A0001	Torque Box Functional Collector - Vertical Fin				
172A6123	Panel Assembly - Trailing Edge Closeout, Vertical Fin				
175A0001	Trailing Edge Functional Collector - Vertical Fin				
175A1701	Panel Installation - Trailing Edge, Vertical Fin				
175A1703	Door Assembly - Trailing Edge, Vertical Fin				
175A1801	Seal Installation - Mass Balance Cavity, Fin WL 151.17, Vertical Fin				





NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

LEFT SIDE IS SHOWN

Vertical Stabilizer Trailing Edge and Closeout Panel Skin Identification Figure 2



Page 2

D634A210 BOEING PROPRIETARY - Copyright ${\rm (\sc)}$ Unpublished Work - See title page for details



Table 2:

	LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY	
[1]	Closeout Panel Assembly -		Glass Fabric Reinforced Plastic (GFRP) honeycomb sandwich		
	Skin		Refer to Figure 3 for the 0 degree ply direction, material, and ply sequence		
	Core		Nonmetallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 3 for the core ribbon direction		
[2]	Trailing Edge Panel Assembly - Bonded Panel		GFRP honeycomb sandwich		
	Skin		Refer to Figure 4 for the 0 degree ply direction, material, and ply sequence		
	Core		Nonmetallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 4 for the core ribbon direction		
[3]	Trailing Edge Skin Panel	0.100 (2.54)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 5 for the chem-mill areas		
[4]	Trailing Edge Panel Assembly - Bonded panel		GFRP honeycomb sandwich		
	Skin		Refer to Figure 6 for the 0 degree ply direction, material, and ply sequence		
	Core (3)		Nonmetallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 6 for the core ribbon direction		
	Door	0.050 (1.27)	2024-T3 clad sheet as given in QQ-A-250/5		
[5]	Mass Balance Cavity Panel - Bonded Panel		GFRP honeycomb sandwich		
	Skin		Refer to Figure 7 for the 0 degree ply direction, material, and ply sequence		
	Core		Nonmetallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 7 for the core ribbon direction		
[6]	Trailing Edge Panel Assembly - Bonded Panel		GFRP honeycomb sandwich		
	Skin		Refer to Figure 8 for the 0 degree ply direction, material, and ply sequence		
	Core (2)		Nonmetallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 8 for the core ribbon		
	Cover	0.050 (1.27)	2024-T3 clad sheet as given in QQ-A-250/5		
[7]	Trailing Edge Panel Assembly - Bonded Panel		GFRP honeycomb sandwich		
	Skin		Refer to Figure 9 for the 0 degree ply direction, material, and ply sequence		
	Core (3)		Nonmetallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 9 for the core ribbon		
	Cover	0.050 (1.27)	2024-T3 clad sheet as given in QQ-A-250/5		

IDENTIFICATION 3 Page 3 Nov 01/2003




	LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY	
[8]	Door	0.100 (2.54)	2024-T3 clad sheet as given in QQ-A-250/5		
[9]	Doubler	0.050 (2.54)	2024-T3 clad sheet as given in QQ-A-250/5		

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).



BOEING®

737-800 STRUCTURAL REPAIR MANUAL



Ply Configuration for Figure 2, Item [1] Figure 3







Table 3:

PLY MATERIAL AND DIRECTION FOR FIGURE 3					
PLY	DIRECTION	MATERIAL			
P1, P3, P6, P8	0 or 90 degrees	GFRP honeycomb sandwich as given in BMS 8-79 Class III, Grade B, Style 1581 or 7781			
P2, P4, P5, P7	+ or - 45 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781			
P9		0.001 inch (0.025 mm) thick white bondable tedlar film			
P10		Bondable teflon			









IDENTIFICATION 3 Page 7 Mar 10/2004




Table 4:

PLY MATERIAL AND DIRECTION FOR FIGURE 4					
PLY	DIRECTION	MATERIAL			
P1, P3, P6, P8	0 or 90 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781			
P2, P4, P5, P7	+ or - 45 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781			
P9		0.001 inch (0.025 mm) thick white bondable tedlar film			
P10		Bondable teflon			



BOEING®

737-800 STRUCTURAL REPAIR MANUAL



Chem-milled Areas for Figure 2, Item [3] Figure 5





737-800 STRUCTURAL REPAIR MANUAL







Table 5:


PLY MATERIAL AND DIRECTION FOR FIGURE 6					
PLY	DIRECTION	MATERIAL			
P1, P3, P6, P8	0 or 90 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781			
P2, P4, P5, P7	+ or - 45 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781			
P9		0.001 inch (0.025 mm) thick white bondable tedlar film			
P10		Bondable teflon			





737-800 STRUCTURAL REPAIR MANUAL





Ply Configuration for Figure 2, Item [5] Figure 7






Table 6:

PLY MATERIAL AND DIRECTION FOR FIGURE 7				
PLY	DIRECTION	MATERIAL		
P1, P3, P5, P6, P8, P10	0 or 90 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781		
P2, P4, P7, P9	+ or - 45 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781		
P11		0.001 inch (0.025 mm) thick white bondable tedlar film		
P11		0.001 inch thick white bondable tedlar film		
P12		Bondable teflon		






737-800 STRUCTURAL REPAIR MANUAL



```
DIRECTION
```



Ply Configuration for Figure 2, Item [6] Figure 8

> IDENTIFICATION 3 Page 14 Mar 10/2004




Table 7:

PLY MATERIAL AND DIRECTION FOR FIGURE 8				
PLY	DIRECTION	MATERIAL		
P1, P3, P6, P8	0 or 90 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781		
P2, P4, P5, P7	+ or - 45 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781		
P9		0.001 inch (0.025 mm) thick white bondable tedlar film		





737-800 STRUCTURAL REPAIR MANUAL



IDENTIFICATION 3 Page 16 Mar 10/2004




Table 8:

PLY MATERIAL AND DIRECTION FOR FIGURE 9				
PLY	DIRECTION	MATERIAL		
P1, P3, P6, P8	0 or 90 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781		
P2, P4, P5, P7	+ or - 45 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781		
P9		0.001 inch (0.025 mm) thick white bondable tedlar film		





IDENTIFICATION 4 - VERTICAL STABILIZER RIGHT INSPAR SKIN



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

RIGHT SIDE IS SHOWN

Vertical Stabilizer Inspar Skin Locations Figure 1

Table 1:

	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
172A0001	Torque Box Functional Collector - Vertical Fin				
172A4001	Skin Installation - Inspar, Vertical Fin				
172A6120	Panel Installation - Fin to Body, Vertical Fin				
172A6121	Panel Assembly, Closeout - Vertical Fin				
172A6122	Door Assembly, Access - Vertical Fin				





737-800 STRUCTURAL REPAIR MANUAL








Table 2:


	LIST OF MATERIALS FOR FIGURE 2					
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY		
[1]	Access Door	0.100 (2.54)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 3 for the chem-mill areas			
[2]	Inspar Closeout Panel - Bonded Assembly		Glass Fiber Reinforced Plastic (GFRP) honeycomb sandwich			
	Skin		Refer to Figure 4 for the 0 degree ply direction, material, and ply sequence			
	Core		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 3 for the core ribbon direction			
[3]	Aft Closeout Panel	0.100 (2.54)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 5 for the chem-mill areas			
[4]	Skin Panel - Lower Left Hand	0.071 (1.80)	2024-T3 clad sheet as shown in QQ-A-250/5. Refer to Figure 6 for the chem-mill areas			
[5]	Skin Panel - Upper Left Hand	0.071 (1.80)	2024-T3 clad sheet as shown in QQ-A-250/5. Refer to Figure 7 for the chem-mill areas			
[6]	Doubler	0.025 (0.64)	2024-T3 clad sheet as given in QQ-A-250/5			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).



BOEING®

737-800 STRUCTURAL REPAIR MANUAL





Chem-milled Areas for Figure 2, Item [1] Figure 3



DEING®

737-800 STRUCTURAL REPAIR MANUAL





Ply Configuration for Figure 2, Item [2] Figure 4






Table 3:

PLY MATERIAL AND DIRECTION FOR FIGURE 4					
PLY	DIRECTION	MATERIAL			
P1, P2, P5, P6	+ or - 45 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781			
P3, P4	90 degrees	Epoxy/Graphite tape as given in BMS 8-168, Type II, Class I, Grade 145			
P7		0.001 inch (0.025 mm) thick white bondable tedlar film			
P8		Bondable teflon			





737-800 STRUCTURAL REPAIR MANUAL




Chem-milled Areas for Figure 2, Item [3] Figure 5



(BOEING®

737-800 STRUCTURAL REPAIR MANUAL




Chem-milled Areas for Figure 2, Item [4] Figure 6



Page 8



737-800 STRUCTURAL REPAIR MANUAL




Chem-milled Areas for Figure 2, Item [5] Figure 7





IDENTIFICATION 5 - VERTICAL STABILIZER RIGHT TRAILING EDGE PANELS



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS. RIGHT SIDE IS SHOWN

Vertical Stabilizer Trailing Edge and Closeout Panel Locations Figure 1


Table 1:

REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE			
172A0001	Torque Box Functional Collector - Vertical Fin			
172A6123	Panel Assembly - Trailing Edge Closeout, Vertical Fin			
175A0001	Trailing Edge Functional Collector - Vertical Fin			
175A1701	Panel Installation - Trailing Edge, Vertical Fin			
175A1703	Door Assembly - Trailing Edge, Vertical Fin			
175A1801	Seal Installation - Mass Balance Cavity, Fin WL 151.17, Vertical Fin			



(BOEING®

737-800 STRUCTURAL REPAIR MANUAL



S FWD

RIGHT SIDE IS SHOWN

Vertical Stabilizer Trailing Edge and Closeout Panel Identification Figure 2



Page 2



Table 2:

	LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T*[1]	MATERIAL	EFFECTIVITY	
[1]	Closeout Panel Assembly - Bonded Panel		Glass Fabric Reinforced Plastic (GFRP) honeycomb sandwich		
	Skin		Refer to Figure 3 for the 0 degree ply, material, and ply sequence		
	Core		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 3 for the core ribbon direction		
[2]	Trailing Edge Panel Assembly - Bonded Panel		GFRP honeycomb sandwich		
	Skin		Refer to Figure 4 for the 0 degree ply, material, and ply sequence		
	Core		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 4 for the core ribbon direction		
[3]	Trailing Edge Skin Panel	0.100 (2.54)	2024-T3 clad sheet as given in QQ-A-250/5. Refer to Figure 5 for the chem-mill areas		
[4]	Trailing Edge Panel Assembly - Bonded Panel		GFRP honeycomb sandwich		
	Skin		Refer to Figure 6 for the 0 degree ply, material, and ply sequence		
	Core (3)		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 6 for the core ribbon direction		
	Door	0.050 (1.27)	2024-T3 clad sheet as given in QQ-A-250/5		
[5]	Mass Balance Cavity Panel - Bonded Panel		GFRP honeycomb sandwich		
	Skin		Refer to Figure 7 for the 0 degree ply, material, and ply sequence		
	Core		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 7 for the core ribbon direction		
[6]	Trailing Edge Panel Assembly - Bonded Panel		GFRP honeycomb sandwich		
	Skin		Refer to Figure 8 for the 0 degree ply, material, and ply sequence		
	Core (3)		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 8 for the core ribbon direction		
	Cover	0.050 (1.27)	2024-T3 clad sheet as given in QQ-A-250/5		
[7]	Trailing Edge Panel Assembly - Bonded Panel		GFRP honeycomb sandwich		
	Skin		Refer to Figure 9 for the 0 degree ply, material, and ply sequence		
	Core (3)		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 9 for the core ribbon direction		
	Cover	0.050 (1.27)	2024-T3 clad sheet as given in QQ-A-250/5		

IDENTIFICATION 5 Page 3 Nov 01/2003






	LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY	
[8]	Door	0.100 (2.54)	2024-T3 clad sheet as given in QQ-A-250/5		
[9]	Doubler	0.050 (1.27)	2024-T3 clad sheet as given in QQ-A-250/5		


*[1] Note: T = Pre-manufactured thickness in inches (millimeters).



BOEING®

737-800 STRUCTURAL REPAIR MANUAL





A-A

Ply Configuration for Figure 2, Item [1] Figure 3






Table 3:

PLY MATERIAL AND DIRECTION FOR FIGURE 3					
PLY	DIRECTION	MATERIAL			
P1, P3, P6, P8	0 or 90 degrees	GFRP honeycomb sandwich as given in BMS 8-79 Class III, Grade B, Style 1581 or 7781			
P2, P4, P5, P7	+ or - 45 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781			
P9		White bondable tedlar film 0.001 inch (0.025 mm) thick			
P10		Bondable teflon			





737-800 STRUCTURAL REPAIR MANUAL



B-B

Ply Configuration for Figure 2, Item [2] Figure 4






Table 4:

PLY MATERIAL AND DIRECTION FOR FIGURE 4					
PLY	DIRECTION	MATERIAL			
P1, P3, P6, P8	0 or 90 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781			
P2, P4, P5, P7	+ or - 45 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781			
P9		White bondable tedlar film 0.001 inch (0.025 mm) thick			
P10		Bondable teflon			





737-800 STRUCTURAL REPAIR MANUAL



Chem-milled Areas for Figure 2, Item [3] Figure 5









Table 5:


PLY MATERIAL AND DIRECTION FOR FIGURE 6				
PLY	DIRECTION	MATERIAL		
P1, P3, P6, P8	0 or 90 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781		
P2, P4, P5, P7	+ or - 45 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781		
P9		White bondable tedlar film 0.001 inch (0.025 mm) thick		
P10		Bondable teflon		





737-800 STRUCTURAL REPAIR MANUAL













Table 6:

PLY MATERIAL AND DIRECTION FOR FIGURE 7				
PLY	DIRECTION	MATERIAL		
P1, P3, P5, P6, P8, P10	0 or 90 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781		
P2, P4, P7, P9	+ or - 45 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781		
P11		White bondable tedlar film 0.001 inch (0.025 mm) thick		
P12		Bondable teflon		





737-800 STRUCTURAL REPAIR MANUAL



Ply Configuration of Figure 2, Item [6] Figure 8





Table 7:

PLY MATERIAL AND DIRECTION FOR FIGURE 8				
PLY DIRECTION MATERIAL				
P1, P3, P6, P8	0 or 90 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781		
P2, P4, P5, P7	+ or - 45 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781		
P9		White bondable tedlar film 0.001 inch (0.025 mm) thick		



D634A210

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL






Table 8:


PLY MATERIAL AND DIRECTION FOR FIGURE 9					
PLY DIRECTION MATERIAL					
P1, P3, P6, P8	0 or 90 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781			
P2, P4, P5, P7	+ or - 45 degrees	GFRP honeycomb sandwich as given in BMS 8-79, Class III, Grade B, Style 1581 or 7781			
P9		White bondable tedlar film 0.001 inch (0.025 mm) thick			



IDENTIFICATION 5 Page 17 Nov 01/2003



IDENTIFICATION 6 - DORSAL FIN SKIN



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Dorsal Fin Skin Location Figure 1


Table 1:

REFERENCE DRAWINGS			
DRAWING NUMBER	TITI F		
174A0101	Dorsal Fin Installation		
174A2100	Dorsal Fin Panel - Bonded Part		





737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

LEFT SIDE PANEL IS SHOWN, RIGHT SIDE PANEL IS OPPOSITE


Dorsal Fin Skin Panel Identification Figure 2

Table 2:

LIST OF MATERIALS FOR FIGURE 2					
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY	
[1]	Skin Panel - Dorsal Fin - Bonded Part		Glass Fiber Reinforced Plastic (GFRP) honeycomb sandwich		
	Skin		Refer to Figure 3 for the zero degree ply direction and ply layup sequence		
	Core	0.35 (8.89)	Aramid honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0. Refer to Figure 3 for the core ribbon direction		

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





LEFT SIDE DORSAL FIN SKIN PANEL IS SHOWN, RIGHT SIDE DORSAL FIN SKIN PANEL IS OPPOSITE VIEW IS ON THE BAGSIDE (NON-AERODYNAMIC) SURFACE PLY LAYUP DIRECTION AND CORE RIBBON DIRECTION

NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION AND THE CORE RIBBON DIRECTION.
- REFER TO SECTIONS A-A, B-B, C-C, D-D, E-E, F-F, AND G-G FOR THE PLY SEQUENCE OVER EACH CORE.
- REFER TO TABLE 3 FOR THE DIRECTION AND MATERIAL FOR EACH PLY.

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Dorsal Fin Skin Panel, Figure 2, Item [1] Figure 3 (Sheet 1 of 4)

D634A210

IDENTIFICATION 6


55-30-01

Page 3


Mar 10/2004

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



PLY LAYUP SEQUENCE A-A



B–B


Ply Direction, Core Ribbon Direction, and Ply Sequence for the Dorsal Fin Skin Panel, Figure 2, Item [1] Figure 3 (Sheet 2 of 4)

IDENTIFICATION 6 Page 4 Nov 01/2003




ABDEING®


737-800 STRUCTURAL REPAIR MANUAL




PLY LAYUP SEQUENCE C-C



PLY LAYUP SEQUENCE D-D



E-E




PLY LAYUP SEQUENCE F-F

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Dorsal Fin Skin Panel, Figure 2, Item [1] Figure 3 (Sheet 3 of 4)





737-800 STRUCTURAL REPAIR MANUAL



PLY LAYUP SEQUENCE G-G

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Dorsal Fin Skin Panel, Figure 2, Item [1] Figure 3 (Sheet 4 of 4)

	Table 3.		
TYPICAL PLY MATERIAL AND DIRECTION FOR FIGURE 3			
PLY	DIRECTION	MATERIAL	
P1, P3, P16, P19, P20, P22	+ or - 45 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Style 1581 or Style 7781, Class III. (Optional: A ply of BMS 8-79, Style 120 in place of a ply of Style 1581 or add Style 120 plies to agree with the thickness range)	
P2, P17, P18, P21	0 or 90 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Style 1581 or Style 7781, Cass III. (Optional: A ply of BMS 8-79, Style 120 in place of a ply of Style 1581 or add Style 120 plies to agree with the thickness range)	
P4 through P15		Adhesive film as given in BMS 5-129, Type 4, Grade 5	
P23	Optional	1 mil white Tedlar film	

Table 3:





ALLOWABLE DAMAGE 1 - VERTICAL STABILIZER LEADING EDGE SKINS


1. Applicability

A. This subject gives the allowable damage limits for the vertical stabilizer leading edge skins shown in Vertical Stabilizer Leading Edge Skin Locations, Figure 101/ALLOWABLE DAMAGE 1.

2. General

- A. Remove the damaged material as necessary.
 - (1) Refer to 51-10-02 for the inspection and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (4) If countersink rivets are removed to clean up the damage, then do the steps that follow:
 - (a) Install new rivets that have the same material and diameter as the initial rivets.
 - 1) Use oversize rivets as necessary.
 - 2) It is optional to install NAS1399D blind rivets.
 - 3) If you install the NAS1399D blind rivets, make an inspection at each 400 flight hour interval.
 - 4) Replace the blind rivets with solid rivets after no more than 5000 flight hours.
 - (b) If the head is above the skin surface, remove the unwanted material with the microshave flush procedure as specified in 51-10-01.
 - 1) The maximum head height that is permitted above the skin is 0.006 inch.
- B. Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to 51-20-01.
- C. Apply two layers of BMS 10-79, Type II or III, primer to the reworked areas. Refer to SOPM 20-44-04.
- D. Apply the decorative finish to the reworked areas as given in AMM PAGEBLOCK 51-21-99/701.
- E. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes.





LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Vertical Stabilizer Leading Edge Skin Locations Figure 101





3. References

Title
AERODYNAMIC SMOOTHNESS
INSPECTION AND REMOVAL OF DAMAGE
PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
NON-METALLIC MATERIALS
EQUIPMENT AND TOOLS FOR REPAIRS
REPAIRS FOR MINOR DENTS IN METALLIC SHEET MATERIALS
DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
Application of Urethane Compatible Primers

4. Allowable Damage Limits

- A. Cracks:
 - (1) Damage is permitted as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Detail A .
- B. Nicks, Gouges, Scratches, and Corrosion:
 - (1) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A, D, and E.
 - (a) Only one area of damage removal, as shown in Detail D, is permitted for each 15.0 square inches of panel.
- C. Holes and Punctures are permitted if:
 - (1) They are a maximum of 0.25 inch in diameter
 - (2) There is not more than one hole or puncture for each 15.0 square inches of panel area
 - (3) The edge of the damage is a minimum of 1.00 inch away from the edge of a fastener hole, other damage, or the panel.
 - (4) They are filled with a 2117-T3 or 2117-T4 aluminum flush head rivet.
 - (a) If the head is above the skin, use the microshave flush procedure as specified in 51-10-01.
 - (b) It is optional to install a 2117-T3 or 2117-T4 aluminum protruding head rivet, or a NAS1399D blind rivet. Do the steps that follow when you install the blind rivets:
 - 1) Make an inspection of blind rivets at each 400 flight hour interval.
 - 2) Replace the blind rivets with solid rivets after no more than 5000 flight hours.
- D. Dents above LE STA 204 away from the High Frequency (HF) Flush Antenna:
 - (1) Dents are permitted for the general conditions of Paragraph 4.D.(2)/ALLOWABLE DAMAGE 1 and for the specified conditions of Paragraph 4.D.(3)/ALLOWABLE DAMAGE 1 For dents that are permitted in the area of the HF antenna, refer to Paragraph 4.E./ALLOWABLE DAMAGE 1
 - (a) Refer to Definition of Dent Dimensions, Figure 103/ALLOWABLE DAMAGE 1 for the definitions of the dimensions for a dent.
 - (b) Refer to Allowable Damage Limits for Leading Edge Skin Dents, Figure 104/ALLOWABLE DAMAGE 1 for the relation of dent dimensions.





- (c) Refer to Damage Size and Spacing Limits for Adjacent Dents, Figure 105/ALLOWABLE DAMAGE 1 for the definition of the dimensions for adjacent dents.
- (d) Refer to Equivalent Length of Dents When the Depth is Large, Figure 106/ALLOWABLE DAMAGE 1 for the definition of the length if there is more than one dent in a bay.
- (2) General Conditions:
 - (a) The edge of the damage is a minimum of 1.0 inch away from a hole.
 - (b) There are no pulled or loose fasteners or missing fastener locations.
 - (c) There are no sharp creases, gouges, or cracks.
 - (d) There is no damage to the structure that is below the skin panels.
 - (e) There are no dents at the rib chord locations.
 - (f) The conditions of Table 101/ALLOWABLE DAMAGE 1 are kept.

Table 101:

CONDITIONS FOR THE LOCATIONS AND QUANTITY OF DENTS		
DEPTH OF DENT (Y), INCH	LIMITS FOR PERMITTED DENTS	
If (Y) is more than or equal to 0.50 but less than 1.0	There must be 5 bays that are not damaged on each side of the damaged bay. There must be no other damage in the damaged bay	
If (Y) is more than or equal to 0.40 but less than 0.50	There must be 3 bays that are not damaged on each side of the damaged bay. There must be no other damage in the damaged bay	
If (Y) is more than or equal to 0.30 but less than 0.40	There must be 2 bays that are not damaged on each side of the damaged bay	
If (Y) is more than or equal to 0.20 but less than 0.30	There must be 1 bay that is not damaged on each side of the damaged bay	


- (3) Specified Conditions:
 - (a) Dents are permitted in Area 1 as shown in Allowable Damage Limits for Leading Edge Skin Dents, Figure 104/ALLOWABLE DAMAGE 1.
 - 1) For dents that are more than the limits shown in Allowable Damage Limits, Figure 107/ALLOWABLE DAMAGE 1, fill the dents as given in 51-70-01.
 - (b) Dents are permitted in Area 2 if you make an inspection of the damage after no more than 5000 flight hours. Refer to Allowable Damage Limits for Leading Edge Skin Dents, Figure 104/ALLOWABLE DAMAGE 1.
 - **NOTE**: It is recommended that you remove or repair the damage after no more than 5000 flight hours or 18 months, that which occurs first.
 - 1) For dents that are more than the limits shown in Allowable Damage Limits, Figure 107/ALLOWABLE DAMAGE 1, fill the dents as given in 51-70-01.
 - (c) Dents are permitted in Area 3 as shown in Allowable Damage Limits for Leading Edge Skin Dents, Figure 104/ALLOWABLE DAMAGE 1 if you do the steps that follow:
 - 1) Fill the dent as given in 51-70-01.
 - 2) Seal the damage with 3M-436 aluminum foil tape (speed tape) or the equivalent.
 - 3) Make a detailed visual inspection of the damage at each 400 flight hour interval. If there are cracks or the damage has become larger, repair the damage immediately.
 - 4) Install a permanent repair after no more than 5000 flight hours or 18 months, that which occurs first.






- (d) Dents are permitted in Area 4 as shown in Allowable Damage Limits for Leading Edge Skin Dents, Figure 104/ALLOWABLE DAMAGE 1 if you do the steps that follow:
 - 1) For dents with a depth less than 0.50 inch, fill the dent as given in 51-70-01.
 - 2) For dents with a depth equal to or greater than 0.50 inch, do the steps that follow:
 - a) Fill the dent as given in 51-70-01.
 - b) Fill half of the depth of the dent with potting compound and permit it to fully cure.
 - c) Fill the remaining depth of the dent and permit the compound to fully cure.
 - **NOTE**: BMS 5-92 adhesive is the better alternative to the potting compounds given in 51-70-01.
 - 3) Seal the damage with 3M-436 aluminum foil tape (speed tape) or the equivalent.
 - 4) Make a detailed visual inspection of the damage each day. If there are cracks or the damage has become larger, repair the damage immediately.
 - 5) Install an external doubler repair with blind fasteners or a permanent flush repair in 90 days. If you do a repair that has blind rivets, do the steps that follow:
 - a) Make an inspection of blind fastener repairs at each 400 flight hour interval
 - b) Replace the blind fastener repair with a permanent flush repair after no more than 5000 flight hours.
- E. Dents below LE STA 204:
 - (1) Refer to Damage Size and Spacing Limits for Adjacent Dents, Figure 105/ALLOWABLE DAMAGE 1 for the definition of the dimensions for adjacent dents.
 - (2) Refer to Equivalent Length of Dents When the Depth is Large, Figure 106/ALLOWABLE DAMAGE 1 for the definition of the length if there is more than one dent in a bay.
 - (3) Dents are permitted as shown in Allowable Damage Limits, Figure 107/ALLOWABLE DAMAGE 1, Detail A if:
 - (a) The edge of the damage is a minimum of 1.0 inch away from a hole
 - (b) There are no pulled or loose fasteners or missing fastener locations
 - (c) There are no sharp creases, gouges, or cracks
 - (d) There is no damage to the structure that is below the skin panels
 - (e) There are no dents at the rib chord locations.
 - (f) The edge of the dent is a minimum 4D from the edge of any other damage. D is the maximum dimension of the largest damage.







D634A210

ALLOWABLE DAMAGE 1


55-30-01


Page 106

Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL






Definition of Dent Dimensions Figure 103



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details

BOEING®

737-800 STRUCTURAL REPAIR MANUAL




FOR AREA NUMBER	SEE ALLOWABLE DAMAGE PARAGRAPH
1	4. D. (3) (a)
2	4. D. (3) (b)
3	4. D. (3) (c)
4	4. D. (3) (d)

TABLE A

Allowable Damage Limits for Leading Edge Skin Dents Figure 104







NOTE: D IS THE LARGEST LENGTH OF THE ADJACENT DENTS.

Damage Size and Spacing Limits for Adjacent Dents Figure 105




D634A210

BOEING PROPRIETARY - Copyright ${\rm (\sc)}$ Unpublished Work - See title page for details




737-800 STRUCTURAL REPAIR MANUAL



- NOTE: IF THE DEPTH OF THE DENT IS 0.050 INCH OR MORE, THEN 1) ADD THE LENGTH OF EACH DENT TO GET THE EQUIVALENT LENGTH (L) OF THE DENTS. $L = L_1 + L_2 + L_3$
 - 2) AND APPLY THE ALLOWABLE DAMAGE LIMITS FOR ONE DENT.

Equivalent Length of Dents When the Depth is Large Figure 106





A

Allowable Damage Limits Figure 107



D634A210

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



ALLOWABLE DAMAGE 2 - VERTICAL STABILIZER INSPAR SKINS

1. Applicability

A. This subject gives the allowable damage limits for the vertical stabilizer inspar skins, door skins, and the AFT closeout panel. Refer to Vertical Stabilizer Inspar Skin Locations, Figure 101/ALLOWABLE DAMAGE 2 and Vertical Stabilizer Inspar Skin Locations, Figure 102/ALLOWABLE DAMAGE 2.

2. General

A. Remove the damaged material as necessary.

- (1) Refer to 51-10-02 for the inspection and removal of damage.
- (2) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
- (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
- (4) If countersink rivets are removed to clean up the damage, then do the steps that follow:
 - (a) Install new rivets that have the same material and diameter as the initial rivets.
 - 1) Use oversize rivets as necessary.
 - 2) It is optional to install solid protruding head rivets or NAS1399D blind rivets with countersink washers. Refer to Vertical Stabilizer Inspar Skins - Permitted Locations of Blind Rivets, Figure 103/ALLOWABLE DAMAGE 2 to install blind rivets.
 - 3) If you install the NAS1399D blind rivets, make an inspection at each 400 flight hour interval.
 - 4) Replace the blind rivets with solid rivets after no more than 5000 flight hours.
 - (b) Make sure the countersink depth is not more than 80 percent of the skin thickness.
 - (c) If the head is above the skin surface, remove the unwanted material with the microshave flush procedure as specified in 51-10-01.
 - 1) The maximum head height that is permitted above the skin is 0.006 inch.
- B. Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to 51-20-01.
- C. Apply two layers of BMS 10-79, Type II or III, primer to the reworked areas. Refer to SOPM 20-44-04.
- D. Apply the decorative finish to the reworked areas as given in AMM PAGEBLOCK 51-21-99/701.
- E. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.




Page 101

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL




Vertical Stabilizer Inspar Skin Locations Figure 101





737-800 STRUCTURAL REPAIR MANUAL






Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL




Vertical Stabilizer Inspar Skins - Permitted Locations of Blind Rivets Figure 103 (Sheet 1 of 2)





737-800 STRUCTURAL REPAIR MANUAL



BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details




3. References

Reference	Title
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Allowable Damage Limits

- A. Cracks:
 - (1) Damage is permitted as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 2, Detail A.
- B. Nicks, Gouges, Scratches, and Corrosion:
 - (1) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 2, Details A, D, F, G, and H.
 - (a) Only one area of damage removal, as shown in Detail D, is permitted for each 15.0 square inches of panel.
- C. Dents are permitted as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 2, Detail E if:
 - (1) The edge of the dent is a minimum 4D from the edge of any other damage. D is the maximum dimension of the largest damage.
- D. Holes and Punctures are permitted if:
 - (1) They are a maximum of 0.25 inch in diameter
 - (2) There is not more than one hole or puncture for each 15.0 square inches of panel area
 - (3) They are not more than the limits shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 2, Details G and H
 - (4) The edge of the damage is a minimum of 1.00 inch away from the edge of a fastener hole, other damage, or the panel
 - (5) They are filled with a 2117-T3 or 2117-T4 aluminum flush head rivet.
 - (a) The countersink depth must not be more than 80 percent of the skin thickness.
 - (b) If the head is above the skin surface, remove the unwanted material with the microshave flush procedure as specified in 51-10-01.
 - (c) It is optional to install a 2117-T3 or 2117-T4 aluminum protruding head rivet or a NAS1399D blind rivet. Refer to Vertical Stabilizer Inspar Skins Permitted Locations of Blind Rivets , Figure 103/ALLOWABLE DAMAGE 2 to install blind rivets. Do the steps that follow when you install the blind rivets:
 - 1) Make an inspection of blind rivets at each 400 flight hour interval.
 - 2) Replace the blind rivets with solid rivets before 5000 flight hours.






The depth of the radius minimum aterial removed by the second sec

Allowable Damage Limits Figure 104 (Sheet 1 of 6)


> ALLOWABLE DAMAGE 2 Page 107 Nov 01/2003






BOEING

737-800 STRUCTURAL REPAIR MANUAL



Allowable Damage Limits Figure 104 (Sheet 3 of 6)





Allowable Damage Limits Figure 104 (Sheet 4 of 6)



BOEING®

737-800 STRUCTURAL REPAIR MANUAL





Figure 104 (Sheet 5 of 6)



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL



 D_1 , D_4 = DIAMETERS OF THE INITIAL FASTENER HOLES D_2 , D_3 = DIAMETERS OF THE HOLES WHERE THERE IS DAMAGE W = WIDTH OF THE SKIN AT THE CROSS-SECTION BETWEEN POINTS A AND B T = THICKNESS OF THE SKIN AS GIVEN BY THE NOMINAL THICKNESS ON THE PRODUCTION DRAWING A₁ = INITIAL AREA OF THE SKIN = THE TOTAL CROSS-SECTIONAL AREA MINUS THE CROSS-SECTIONAL AREA OF THE INITIAL FASTENERS HOLES (AS MANUFACTURED BY BOEING) = WT - D_1T - DT_4 A₁ = CROSS-SECTIONAL AREA OF THE DAMAGE THAT IS REMOVED AT LOCATION 1 A₂ = CROSS-SECTIONAL AREA OF THE DAMAGE THAT IS REMOVED AT LOCATION 2 A₃ = CROSS-SECTIONAL AREA OF THE DAMAGE THAT IS REMOVED AT LOCATION 3 $\left(\frac{A_1 + A_2 + A_3}{A_1}\right)$ X 100 = PERCENT OF CROSS-SECTIONAL AREA REMOVED AS GIVEN IN TABLE 101

THE TOTAL CROSS-SECTIONAL AREA REMOVED IN ALL ZONES A-B (3.00 INCH (76.2 mm) ON EACH SIDE OF A LINE A-B) MUST NOT BE MORE THAN THE LIMITS GIVEN IN TABLE 101

С-С

Allowable Damage Limits Figure 104 (Sheet 6 of 6)





ALLOWABLE DAMAGE 3 - VERTICAL STABILIZER TRAILING EDGE PANELS

1. Applicability

A. This subject gives the allowable damage limits for the vertical stabilizer trailing edge panels shown in Vertical Stabilizer Trailing Edge and Closeout Panel Locations, Figure 101/ALLOWABLE DAMAGE 3 and Vertical Stabilizer Trailing Edge and Closeout Panel Locations, Figure 102/ALLOWABLE DAMAGE 3. Limits are also given for the closeout panels and the balance weight cover panels shown in Vertical Stabilizer Trailing Edge and Closeout Panel Locations, Figure 101/ALLOWABLE DAMAGE 3 and Vertical Stabilizer Trailing Edge and Closeout Panel Locations, Figure 101/ALLOWABLE DAMAGE 3 and Vertical Stabilizer Trailing Edge and Closeout Panel Locations, Figure 102/ALLOWABLE DAMAGE 3.


2. General

- A. Use a Non-Destructive Test (NDT) to find the length, width, and depth of damage.
 - (1) For the honeycomb core areas that have damage on a facesheet with 3 or less plies, Boeing recommends that you use an instrumented NDT procedure. The tap test procedure is optional. Refer to 737 NDT Part 1, 51-01-02, 737 NDT Part 1, 51-01-03, and 737 NDT Part 1, 51-05-01 for the inspection procedures.
 - (2) For the honeycomb core areas that have damage on a facesheet with 4 or more plies, Boeing recommends that you use an instrumented NDT procedure. Refer to 737 NDT Part 1, 51-01-02 and 737 NDT Part 1, 51-01-03 for the inspection procedures.
 - **NOTE**: The tap test procedure as given in 737 NDT Part 1, 51-05-01 is optional only if it can be shown that the defects (that are less than or equal to the allowable damage limits) can be found.
 - (3) For damage in the solid laminate areas, Boeing recommends that you use an instrumented NDT procedure. Refer to 737 NDT Part 1, 51-01-02 and 737 NDT Part 1, 51-01-03 for the inspection procedures.
 - (4) Refer to Definitions of Damage Size, Figure 103/ALLOWABLE DAMAGE 3, Details A, B, and C for the definitions of the length, width, and depth of damage.
 - (5) Refer to Definitions of the Facesheets, Figure 104/ALLOWABLE DAMAGE 3 for the definitions of the facesheets of a honeycomb core area.
- B. Remove all contamination and water from the structure.
 - (1) Refer to 51-30-05 for possible sources of equipment and tools you can use to remove the damage.
 - (2) Refer to 51-70-04 for the damage removal procedures.
- C. Seal all permitted damage areas that are not more than one ply deep. Refer to Paragraph 4./ALLOWABLE DAMAGE 3 for the allowable damage limits. Seal the damage with one of the two methods that follow:
 - (1) Make a temporary seal.
 - (a) Apply aluminum foil tape (speed tape).
 - (b) Keep a record of the location.
 - (c) Make sure that the tape is in satisfactory condition at each 400 flight hour interval.
 - (d) Repair the damage after no more than 5000 flight hours.
 - (2) Make a permanent seal.
 - (a) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given in 51-70-08.



- (b) Apply one layer of BMS 10-79, Type 3 primer. Refer to SOPM 20-44-04.
- (c) Apply one layer of BMS 10-60 enamel to the areas sealed with epoxy resin. Refer to AMM PAGEBLOCK 51-21-99/701.
- D. Seal all permitted damage areas that are more than one ply deep. Refer to Paragraph 4./ALLOWABLE DAMAGE 3 for the allowable damage limits. Seal the damage as follows:
 - (1) Use vacuum and heat to remove moisture from the solid laminate and/or honeycomb cells. Refer to 51-70-04.
 - (2) Make a temporary seal with aluminum foil tape (speed tape).
 - (3) Keep a record of the location.
 - (4) Repair the damage after no more than 400 flight hours.






Vertical Stabilizer Trailing Edge and Closeout Panel Locations Figure 101

> ALLOWABLE DAMAGE 3 Page 103 Nov 01/2003

BOEING®


737-800 STRUCTURAL REPAIR MANUAL



ALLOWABLE DAMAGE 3 Page 104 Nov 01/2003


BOEING

737-800 STRUCTURAL REPAIR MANUAL




SIZE DEFINITIONS FOR NICK, GOUGE, OR SCRATCH DAMAGE

А



SIZE DEFINITIONS FOR DENT DAMAGE

В



SIZE DEFINITIONS FOR EDGE DAMAGE

С

Definitions of Damage Size Figure 103




Page 105

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL



Definitions of the Facesheets Figure 104

3. <u>References</u>

Reference	Title
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-08	RESIN SWEEP-FAIR PROCEDURES
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage
737 NDT Part 1, 51-01-03	NDT Assessment of Lightning Strike Damage to Graphite/Epoxy Composite Structure
737 NDT Part 1, 51-05-01	Tap Test Inspection of Honeycomb Sandwich Structure

4. Allowable Damage Limits

- A. Trailing Edge and Closeout Panels Solid Laminate Areas
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted if:
 - (a) They are sealed as given in Paragrah 2.
 - (2) Nicks, Gouges, and Scratches that cause damage to the glass fibers are permitted if:
 - (a) Not more than one fastener hole in six is damaged
 - (b) Not more than 10 percent of the edgeband for each side of panel is damaged
 - (c) They are sealed as given in Paragraph 2.
 - (3) Dents are permitted if:
 - (a) Not more than one fastener hole in six is damaged
 - (b) Not more than 10 percent of the edgeband for each side of panel is damaged
 - (c) They are sealed as given in Paragraph 2.
 - (4) Holes and Punctures are permitted if:
 - (a) They are a maximum 0.25 inch in diameter
 - (b) Not more than one fastener hole in six is damaged
 - (c) Not more than 10 percent of the edgeband for each side of panel is damaged
 - (d) They are sealed as given in Paragraph 2.





- (5) Delaminations are permitted if:
 - (a) Not more than one fastener hole in six is damaged
 - (b) Not more than 10 percent of the edgeband for each side of panel is damaged
 - (c) They are sealed as given in Paragraph 2.
- (6) Edge Erosion is permitted as shown in Edge Erosion Damage Removal, Figure 105/ALLOWABLE DAMAGE 3 if:
 - (a) Not more than 10 percent of the edgeband for each side of panel is damaged
 - (b) It is sealed as given in Paragraph 2.
- (7) Edge damage is permitted if:
 - (a) It is a maximum 0.10 inch in depth
 - (b) Not more than 10 percent of the edgeband for each side of panel is damaged
 - (c) It is removed as shown in Allowable Damage Limits, Figure 106/ALLOWABLE DAMAGE 3, Detail A
 - (d) It is sealed as given in Paragraph 2.
- B. Trailing Edge and Closeout Panels Honeycomb Core Area
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted if:
 - (a) They are sealed as given in Paragraph 2.
 - (2) Nicks, Gouges, and Scratches that cause damage to the glass fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum length of 1.50 inches
- (c) A maximum width of 1.50 inches
- (d) A minimum distance away from the edge of any hole, part edge, or other damage of 4D. Refer to Damage Size and Spacing Limits, Figure 107/ALLOWABLE DAMAGE 3 for damage and spacing limits and the value of D. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass ply and
 - 2) Are sealed as given in Paragraph 2.
- (e) Sealed as given in Paragraph 2.
- (3) Dents are permitted if:
 - (a) They are a maximum of one facesheet
 - (b) They are a maximum diameter of 1.50 inches
 - (c) They are a minimum distance away from the edge of any hole, part edge, or other damage of 4D. Refer to Damage Size and Spacing Limits, Figure 107/ALLOWABLE DAMAGE 3 for damage and spacing limits and the value of D. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass ply and
 - 2) Are sealed as given in Paragraph 2.
 - (d) There is no fiber damage or delamination

Page 107



- (e) The damage is sealed as given in Paragraph 2.
- (4) Holes and Punctures are permitted if they are:
 - (a) A maximum of one facesheet and the core in depth
 - (b) A maximum diameter of 1.50 inches
 - (c) A minimum distance away from the edge of any hole, part edge, or other damage of 4D. Refer to Damage Size and Spacing Limits, Figure 107/ALLOWABLE DAMAGE 3 for damage and spacing limits and the value of D. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass ply and
 - 2) Are sealed as given in Paragraph 2.
 - (d) Sealed as given in Paragraph 2.


NOTE: Do not remove the damage unless it is necessary to remove resin burrs that extend into the surface contour.

- (5) Delaminations are permitted if they are:
 - (a) On a maximum of one facesheet
 - (b) A maximum diameter of 1.50 inches
 - (c) A minimum distance away from the edge of any hole, part edge, or other damage of 4D. Refer to Damage Size and Spacing Limits, Figure 107/ALLOWABLE DAMAGE 3 for damage and spacing limits and the value of D. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass ply and
 - 2) Are sealed as given in Paragraph 2.
 - (d) Sealed as given in Paragraph 2.
- C. Balance Weight Cover Panel Solid Laminate Areas
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted if:
 - (a) They are sealed as given in Paragraph 2.
 - (2) Nicks, Gouges, and Scratches that cause damage to the glass fibers are permitted if:
 - (a) Not more than one fastener hole in six is damaged
 - (b) Not more than 10 percent of the edgeband for each side of panel is damaged
 - (c) They are sealed as given in Paragraph 2.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
 - (5) Delaminations are not permitted.
 - (6) Edge Erosion is permitted as shown in Edge Erosion Damage Removal, Figure 105/ALLOWABLE DAMAGE 3 if:
 - (a) Not more than 10 percent of the edgeband for each side of panel is damaged
 - (b) It is sealed as given in Paragraph 2.
 - (7) Edge damage is permitted if:
 - (a) It is a maximum 0.10 inch in depth
 - (b) Not more than 10 percent of the edgeband for each side of panel is damaged






- (c) It is removed as shown in Allowable Damage Limits, Figure 106/ALLOWABLE DAMAGE 3, Detail A
- (d) It is sealed as given in Paragraph 2.



Edge Erosion Damage Removal Figure 105





AREA OF MATERIAL MARGIN REMOVED

REMOVAL OF DAMAGED MATERIAL AT EDGES WHERE THE FASTENER EDGE MARGINS DO NOT HAVE AN OVERLAP REMOVAL OF DAMAGED MATERIAL AT EDGES WHERE THE FASTENER EDGE MARGINS HAVE AN OVERLAP


= 0.10 INCH MAXIMUM

Allowable Damage Limits Figure 106

> ALLOWABLE DAMAGE 3 Page 110 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



NOTE: TO FIND DELAMINATION YOU CAN USE NONDESTRUCTIVE INSPECTION PROCEDURES (REFER TO NDT PART 1, 51-01-02).

THE DIAMETER OF A DAMAGE AREA IS EITHER THE DIAMETER OF THE VISUAL DAMAGE OR THE DIAMETER OF THE DELAMINATION. USE THE DIAMETER OF THE LARGER DAMAGE.

A DAMAGE AREA DOES NOT INCLUDE NICKS, GOUGES, AND SCRATCHES THAT DO NOT CAUSE DAMAGE TO THE GLASS AND CARBON FIBER PLIES IF:

- YOU MAKE A TEMPORARY SEAL OF THE DAMAGE AS GIVEN IN PARAGRAPH 2 OR - YOU MAKE A PERMANENT SEAL OF THE DAMAGE AS GIVEN IN PARAGRAPH 2

(D) IS THE LARGER DIAMETER OF TWO ADJACENT DAMAGE AREAS AND IS A MAXIMUM OF 1.50 INCHES

(d) IS THE SMALLER DIAMETER OF TWO ADJACENT DAMAGE AREAS.

(a) IS THE DISTANCE BETWEEN TWO ADJACENT DAMAGE AREAS. THE MINIMUM (a) THAT IS PERMITTED IS (4D).

> **Damage Size and Spacing Limits** Figure 107



Page 111




ALLOWABLE DAMAGE 4 - VERTICAL STABILIZER LEADING EDGE SKINS, EROSION DAMAGE

1. Applicability

A. This subject gives the allowable damage limits for the vertical stabilizer leading edge skins that have erosion damage. These limits are for the skin panels shown in Vertical Stabilizer Leading Edge Skin Locations, Figure 101/ALLOWABLE DAMAGE 4. Do not use the limits of this subject for the fin tip. Refer to Allowable Damage 1 for other types of damage limits permitted.





55-30-01

ALLOWABLE DAMAGE 4

Page 102

Jul 10/2004



2. General

- A. Do what follows for the aluminum leading edge skins:
 - (1) Remove the damaged material as given in Paragraph 4./ALLOWABLE DAMAGE 4 The maximum depth of material that can be removed is equal to 25% of the initial thickness of the skin.
 - (a) Refer to 51-10-02 for the inspection and removal of damage.
 - (b) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (c) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (2) Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.

3. References

Reference	Title
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-01, GENERAL	Aerodynamic Smoothness Requirements
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-08	EROSION PROTECTION
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
AMM 51-21-00 P/B 701	INTERIOR AND EXTERIOR FINISHES - CLEANING/PAINTING

4. Allowable Damage Limits

WARNING: MATERIALS THAT ARE USED TO CLEAN AND COAT ARE TOXIC AND FLAMMABLE. MAKE SURE THERE IS A GOOD FLOW OF AIR AND YOU OBEY ALL FIRE PRECAUTIONS.

- A. Light Erosion Damage to the Aluminum Skin:
 - (1) Make the metal contour smooth.
 - (a) Apply masking tape to the areas where there is no damage.
 - (b) Clean the surface with a moist cheesecloth. Use water to make the cheesecloth moist.
 - (c) Polish or sand the damaged area to make a smooth surface. The maximum depth of removal must not be more than 25% of the initial skin thickness.

NOTE: Use aluminum oxide abrasives or aluminum wool. Do not use silicon carbide abrasives or steel wool.

- (d) Where the skin has been pushed in, make the skin contour smooth with the adjacent skin.
 - 1) Use powdered household cleanser or 400-grit aluminum oxide paper.
 - 2) Refer to Vertical Stabilizer Leading Edge Skin Locations, Figure 101/ALLOWABLE DAMAGE 4, Section A-A, for surface contour limits.
- (e) Clean the surface with a moist new cheesecloth. Use MIBK to make the cheesecloth moist.
- (f) Find the depth of material that has been removed.





- 1) Use a Vidigage, Branson digital caliper, dial gage, or a straight edge with feeler gages to find the depth.
- 2) Repair the leading edge skin if the depth of material removed is more than 25% of the initial skin thickness.
- 3) Apply a chemical conversion coating if the depth of material removed is less than 25% of the initial skin thickness. Apply the conversion coating to the bare surfaces of the skin as given in 51-20-01.
- **CAUTION:** DO NOT APPLY AN EROSION PROTECTION TO THE AREA OF THE SKIN FORWARD OF THE HIGH FREQUENCY (HF) ANTENNA. THERE COULD BE A DANGEROUS EFFECT TO THE PERFORMANCE OF THE HF SYSTEM. THIS AREA OF THE SKIN IS ADJACENT TO THE HF FIBERGLASS STRAP ATTACHED TO THE SKIN.
- (g) For more protection of leading edge skins, apply a new layer of erosion tape or an erosion coating. Refer to 51-20-08.
 - 1) Replace the tape or erosion coating if there is too much wear.
 - 2) When the bare metal shows or the aerodynamic smoothness limits are not kept, there is too much wear. Refer to 51-10-01 for the aerodynamic smoothness limits.
- B. Moderately damaged to badly damaged areas of the aluminum skin:
 - (1) Prepare the metal areas.
 - (a) Apply masking tape to the areas where there is no damage.
 - (b) Close and seal all openings to keep all material out of the structure.
 - (c) Static ground the airplane and the abrasive blast equipment.
 - (d) Use a spray gun with water or toluene to clean the eroded area of the skin.

CAUTION: DO NOT USE A CLOTH OR OTHER FABRIC TO CLEAN THE ABRASIVE BLASTED AREA. UNWANTED LINT ON THE CLEANED AREA WILL DECREASE THE LIFE OF THE EROSION COATING.

- (e) Use an abrasive blast to remove the erosion damage as given in 51-10-02.
 - 1) Make sure all of the oxide and corrosion has been removed from the eroded areas.
 - 2) Refer to Vertical Stabilizer Leading Edge Skin Locations, Figure 101/ALLOWABLE DAMAGE 4, Section A-A, for the limits of a good taper.
- (f) Find the depth of material that has been removed.
 - 1) Use a Vidigage, Branson digital caliper, dial gage, or a straight edge with feeler gages to find the depth.
 - 2) Repair the leading edge skin if the depth of material removed is more than 25% of the initial skin thickness.
 - Apply a chemical conversion coating if the depth of material removed is less than 25% of the initial skin thickness. Apply the conversion coating to the bare surfaces of the skin as given in 51-20-01.

ALLOWABLE DAMAGE 4

55-30-01

Page 104

Jul 10/2004





- **CAUTION:** DO NOT APPLY AN EROSION PROTECTION TO THE AREA OF THE SKIN FORWARD OF THE HIGH FREQUENCY (HF) ANTENNA. THERE COULD BE A DANGEROUS EFFECT TO THE PERFORMANCE OF THE HF SYSTEM. THIS AREA OF THE SKIN IS ADJACENT TO THE HF FIBERGLASS STRAP ATTACHED TO THE SKIN.
- (g) For more protection of leading edge skins, apply a new layer of erosion tape or an erosion coating. Refer to 51-20-08.
 - 1) Replace the tape or erosion coating if there is too much wear.
 - 2) When the bare metal shows or the aerodynamic smoothness limits are not kept, there is too much wear. Refer to 51-10-01 for the aerodynamic smoothness limits.
- C. Damage to the erosion coating on the Fiberglass Strap for the HF antenna:
 - **CAUTION:** EROSION OF THE FIBERGLASS SURFACE IS NOT PERMITTED. DO NOT TRY TO REMOVE THE FIBERGLASS DAMAGE. MAKE SURE THERE IS ALWAYS A LAYER OF EROSION TAPE OR AN EROSION COATING ON THE FIBERGLASS SURFACE. STRUCTURAL DAMAGE TO THE FIBERGLASS STRAP WILL OCCUR IF YOU DO NOT OBEY.
 - (1) Make an inspection of the fiberglass strap at intervals for damage to the erosion protection.
 - (2) Remove and replace the erosion coating or erosion tape as given in Paragraph 4.D./ALLOWABLE DAMAGE 4 and 51-20-08 if:
 - (a) The bare fiberglass surface shows
 - (b) The aerodynamic smoothness limits are not kept as given 51-10-01.
- D. Damage to the initial layer of erosion protection:
 - (1) Areas of bare metal or unsatisfactory aerodynamic smoothness are caused by damage to the erosion protection. Refer to 51-10-01 for the aerodynamic smoothness limits and do what follows for these areas:
 - (a) Remove the erosion coating with MIBK.
 - 1) Soak the coating with MIBK with the use of cheesecloth.
 - 2) Keep the cheesecloth on the coating until it is soft.
 - 3) Use a plastic scraper to remove the erosion coating.
 - (b) Remove the erosion tape.
 - 1) Soak the tape edge sealer with MIBK with the use of cheesecloth.
 - 2) Keep the cheesecloth on the edge sealer until it is sufficiently soft to remove.
 - 3) Heat (150°F maximum temperature) can be used to make the tape soft.
 - 4) Use a plastic scraper, razor, or knife to start the removal of the tape at edges. Use your hand to pull the tape away from the metal skin.
 - (c) For more protection of leading edge skins, apply a new layer of erosion tape or an erosion coating. Refer to 51-20-08.
 - 1) Replace the tape or erosion coating if there is too much wear.
 - 2) When the bare metal shows or the aerodynamic smoothness limits are not kept, there is too much wear. Refer to 51-10-01 for the aerodynamic smoothness limits.





ALLOWABLE DAMAGE 5 - DORSAL FIN SKIN

1. Applicability

- A. This subject gives the allowable damage limits for the dorsal fin skin made of Glass Fiber Reinforced Plastic (GFRP) honeycomb sandwich material. Refer to Dorsal Fin Skin Location, Figure 101/ALLOWABLE DAMAGE 5.
- B. The composite structure allowable damage limits are applicable only if they are sealed as given in Paragraph 2.

2. <u>General</u>

- A. Do an inspection of the damaged area to find the length, width, and depth of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to 737 NDT Part 1, 51-01-02 for inspection procedures.
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.
 - (1) For the honeycomb core areas, the tap test is an alternative procedure to an instrumented NDT procedure.
 - (2) Refer to Definitions of the Dimensions of the Different Types of Damage, Figure 102/ALLOWABLE DAMAGE 5 for the definitions of the length, width, and depth of the damage.
 - (3) Refer to Definitions of the Facesheets, Figure 103/ALLOWABLE DAMAGE 5 for the definitions of the facesheets of a honeycomb core area.
- B. Remove all of the contamination and water from the fairing.
 - (1) Refer to 51-70-04 for the damage removal procedures.
 - (2) Refer to 51-30-03 for possible sources of the non-metallic materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment you can use to remove the damage.
 - (4) Seal all the permitted damage areas that are not more than one ply in depth. Refer to the allowable damage limits given in Paragraph 4./ALLOWABLE DAMAGE 5 Seal the damage with one of the two methods that follow:
 - (a) Make a temporary seal.
 - 1) Apply aluminum foil tape (speed tape).
 - 2) Keep a record of the location.
 - 3) Make sure that the tape is in satisfactory condition at normal maintenance intervals.
 - (b) Make a permanent seal.
 - 1) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given in 51-70-08.
 - 2) Apply one layer of BMS 10-79, Type 3 or BMS 10-103, Type 1 primer. Refer to SOPM 20-44-04.
 - 3) Apply one layer of BMS 10-60, Type II enamel to the external surfaces sealed with epoxy resin. Refer to AMM PAGEBLOCK 51-21-99/701.
 - (5) Seal all of the damage areas that are more than one ply in depth. Refer to the allowable damage limits given in Paragraph 4./ALLOWABLE DAMAGE 5 Seal the damage as follows:
 - (a) Use a vacuum and heat to remove moisture from the solid laminate and/or honeycomb cells. Refer to 51-70-04.



- (b) Make a temporary seal with aluminum foil tape (speed tape).
- (c) Keep a record of the location.
- (d) Repair the damage at or before 24 months from the time the seal was made.
- (6) The definition of the words "other damage", as used in the allowable damage limits, does not include nicks, gouges, and scratches that do not cause damage to the glass fibers and is sealed.


Table 101:

PARAGRAPH REFERENCES FOR THE ALLOWABLE DAMAGE LIMITS		
TYPE OF STRUCTURE	AREA LOCATION	PARAGRAPH
DORSAL FIN SKIN GFRP HONEYCOMB SANDWICH	HONEYCOMB CORE AREA	4.A
	SOLID LAMINATE AREA	4.B




BOEING®

737-800 STRUCTURAL REPAIR MANUAL






737-800 STRUCTURAL REPAIR MANUAL



DEFINITIONS OF THE SIZES FOR NICK, GOUGE, AND SCRATCH DAMAGE




Definitions of the Dimensions of the Different Types of Damage Figure 102







737-800 STRUCTURAL REPAIR MANUAL



Definitions of the Facesheets Figure 103

3. References

Reference	Title
51-10-01, GENERAL	Aerodynamic Smoothness Requirements
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05, GENERAL	Repair Sealing
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-08	RESIN SWEEP-FAIR PROCEDURES
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Allowable Damage Limits

- A. Honeycomb Core Areas
 - (1) Nicks, Gouges and Scratches that do not cause damage to the glass fibers are permitted.
 - (2) Nicks, Gouges and Scratches that cause damage to the glass fibers are permitted if they are:
 - (a) A maximum depth of one ply

NOTE: Use the limits for holes and punctures if the depth of the damage is more than one ply.

- (b) A maximum length of 5.0 inches (127.00 mm)
- (c) A minimum of 0.50 inch (12.70 mm) away from the edge of a fastener hole
- (d) A minimum distance from the edge of other damage as shown in Allowable Damage Details for Honeycomb Core Areas, Figure 104/ALLOWABLE DAMAGE 5, Detail A.
- (3) Dents that do not cause damage to the glass fibers are permitted if they are:
 - (a) A maximum depth of 2 plies
 - (b) A maximum diameter of 2.0 inches (50. 80 mm)
 - (c) A minimum of 0.50 inch (12.70 mm) away from the edge of a fastener hole





- (d) A minimum distance from the edge of other damage as shown in Allowable Damage Details for Honeycomb Core Areas, Figure 104/ALLOWABLE DAMAGE 5, Detail A.
- (4) Holes and Punctures are permitted if they are:
 - (a) A maximum diameter of 2.0 inches (50.8 mm)
 - (b) A minimum of 0.50 inch (12.70 mm) away from the edge of a fastener hole
 - (c) A minimum distance from the edge of other damage as shown in Allowable Damage Details for Honeycomb Core Areas, Figure 104/ALLOWABLE DAMAGE 5, Detail A.
- (5) Delaminations are permitted if they are:
 - (a) A maximum length of 2.0 inches (50.80 mm)
 - (b) A maximum width of 2.0 inches (50.80 mm)
 - (c) A minimum of 0.50 inch (12.70 mm) away from the edge of a fastener hole
 - (d) A minimum distance from the edge of other damage as shown in Allowable Damage Details for Honeycomb Core Areas, Figure 104/ALLOWABLE DAMAGE 5, Detail A.
- B. Solid Laminate Areas
 - (1) Nicks, Gouges and Scratches that do not cause damage to the glass fibers are permitted.
 - (2) Nicks, Gouges and Scratches that cause damage to the glass fibers are permitted if they are:
 - (a) A maximum depth of one ply

NOTE: Use the limits for holes and punctures if the depth of the damage is more than one ply.

- (b) A maximum length of 1.0 inch (25.4 mm)
- (c) A maximum width of 0.25 inch (6.35 mm)
- (d) A minimum of 0.50 inch (12.70 mm) away from the edge of a fastener hole
- (e) A minimum distance from the edge of other damage as shown in Allowable Damage Limits for the Solid Laminate Areas, Figure 105/ALLOWABLE DAMAGE 5, Detail A.
- (3) Dents that do not cause damage to the glass fibers are permitted if they are:
 - (a) A maximum depth of 2 plies
 - (b) A maximum diameter of 0.625 inch (15.88 mm)
 - (c) A minimum of 0.50 inch (12.70 mm) away from the edge of a fastener hole
 - (d) A minimum distance from the edge of other damage as shown in Allowable Damage Limits for the Solid Laminate Areas, Figure 105/ALLOWABLE DAMAGE 5, Detail A.
- (4) Holes and Punctures are permitted if they are:
 - (a) A maximum diameter of 0.625 inch (15.88 mm)
 - (b) A minimum of 0.50 inch (12.70 mm) away from the edge of a fastener hole
 - (c) A minimum distance from the edge of other damage as shown in Allowable Damage Limits for the Solid Laminate Areas, Figure 105/ALLOWABLE DAMAGE 5, Detail A.
- (5) Delaminations are permitted if they agree with all of the conditions that follow:
 - (a) A maximum length of 0.625 inch (15.88 mm) in length
 - (b) A maximum width of 0.625 inch (15.88 mm)
 - (c) A minimum of 0.50 inch (12.70 mm) away from the edge of a fastener hole






- (d) A minimum distance from the edge of other damage as shown in Allowable Damage Limits for the Solid Laminate Areas, Figure 105/ALLOWABLE DAMAGE 5, Detail A.
- (6) Edge damage is permitted as shown in Allowable Damage Limits for the Solid Laminate Areas, Figure 105/ALLOWABLE DAMAGE 5, Detail A, if it is:
 - (a) A maximum of 2 plies in depth
 - (b) A minimum of 0.50 inch (12.70 mm) away from the edge of a fastener hole
- (7) Edge erosion damage is permitted as shown in Allowable Damage Limits for the Solid Laminate Areas, Figure 105/ALLOWABLE DAMAGE 5, Detail B.



BOEING

737-800 STRUCTURAL REPAIR MANUAL



AREAS OF ADJACENT DAMAGE THAT ARE LESS THAN 3 INCHES (76.2 mm) APART

<u>NOTE</u>: TO FIND DELAMINATION USE NONDESTRUCTIVE INSPECTION PROCEDURES AS GIVEN IN NDT PART 1, 51-01-02.

THE DIAMETER OF A DAMAGE AREA IS THE LARGER OF THE DIAMETER OF THE VISUAL DAMAGE OR THE DIAMETER OF THE DELAMINATION.

D IS THE LARGER DIAMETER OF TWO ADJACENT DAMAGE AREAS.

d IS THE SMALLER DIAMETER OF TWO ADJACENT DAMAGE AREAS.

a IS THE DISTANCE BETWEEN TWO ADJACENT DAMAGE AREAS.


THE MINIMUM a THAT IS PERMITTED IS 2.5D.

Allowable Damage Details for Honeycomb Core Areas Figure 104






737-800 STRUCTURAL REPAIR MANUAL



A GROUP OF SMALL DAMAGE AREAS THAT ARE NEAR EACH OTHER CAN BE SEEN AS ONE DAMAGE AREA



NOTE: TO FIND DELAMINATION, YOU CAN USE NONDESTRUCTIVE INSPECTION PROCEDURES. REFER TO NDT PART 1, 51-01-02.

THE DIAMETER OF A DAMAGE AREA IS EITHER THE DIAMETER OF THE VISUAL DAMAGE OR THE DIAMETER OF THE DELAMINATION. USE THE DIAMETER OF THE LARGER DAMAGE.

D IS THE LARGER DIAMETER OF TWO ADJACENT DAMAGE AREAS AND CAN BE A MAXIMUM OF 1.0 INCH.

d is the smaller diameter of two adjacent damage areas.

a IS THE DISTANCE BETWEEN TWO ADJACENT DAMAGE AREAS.

THE MINIMUM A THAT IS PERMITTED IS 4D.

DAMAGE THAT IS PERMITTED TO COMPOSITE PANELS

А

Allowable Damage Limits for the Solid Laminate Areas Figure 105 (Sheet 1 of 2)




Page 109

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL



Allowable Damage Limits for the Solid Laminate Areas Figure 105 (Sheet 2 of 2)






REPAIR 1 - VERTICAL STABILIZER LEADING EDGE SKIN EXTERNAL REPAIR

1. Applicability

- A. Repair 1 is applicable to damage to the vertical stabilizer leading edge skins shown in Vertical Stabilizer Leading Edge Skin Locations, Figure 201/REPAIR 1 if:
 - (1) You do inspections of the repair as given in Paragraph 5./REPAIR 1
 - (2) You replace Repair 1 no more than 15,000 hours after installation with one of the repairs that follow:
 - (a) A permanent flush repair as shown in Repair 2
 - (b) A replacement of the blind rivets with solid flush rivets for a permanent external repair.





LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Vertical Stabilizer Leading Edge Skin Locations Figure 201



REPAIR 1 Page 202 Nov 01/2003



2. General

- A. Repair 1 gives instructions for a Category C repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes.
- C. Repair 1 can be used only if you install the blind rivets flush against the internal structure.

3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-00, GENERAL	Fasteners
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-40-05, GENERAL	Fastener Hole Sizes
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES

4. Repair Instructions

- A. Drill a stop hole at the ends of all skin cracks that do not end at fastener holes. Refer to Vertical Stabilizer Leading Edge Skin External Repair, Figure 202/REPAIR 1 and SRM 51-10-02 for the procedures to drill a stop hole. For other damage, do what follows:
 - Cut and remove the damaged part of the skin as shown in Vertical Stabilizer Leading Edge Skin External Repair, Figure 202/REPAIR 1. Refer to 51-10-02 for the procedures to remove the damage.
 - (a) Make the cut in the shape of a rectangle with the longest sides parallel to the leading edge ribs.
 - (b) Make the corner radii of the cut a minimum of 0.50 inch.
 - (c) Make sure there is a minimum of two rows of repair fasteners around the edges of the cut.
- B. Put the skin that is around the damage back to the initial contour.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes. Refer to 51-10-01.
- C. Make the part [1] doubler as shown in Vertical Stabilizer Leading Edge Skin External Repair, Figure 202/REPAIR 1. Refer to Table 201/REPAIR 1 for the repair material.
 - (1) Make the contour of the part [1] doubler the same as the initial contour of the skin.



REPAIR 1 Page 203 Nov 10/2007



Table 201:

REPAIR MATERIAL			
ITEM	PART	QUANTITY	MATERIAL
[1]	Doubler	1	Use clad 2024-T3 that is 0.063 inch thick when the initial skin is 0.040 inch thick. Use clad 2024-T3 that is one gage thicker than the initial skin when the thickness is more than 0.040 inch


- D. Assemble the part [1] doubler as shown in Vertical Stabilizer Leading Edge Skin External Repair, Figure 202/REPAIR 1.
- E. Drill and countersink the fastener holes.
- F. Remove the part [1] doubler.
- G. Remove the nicks, scratches, gouges, burrs, and sharp edges from the doubler and the bare surfaces of the skin.
- H. Apply a chemical conversion coating to the part [1] doubler and bare surfaces of the skin. Refer to 51-20-01 for the chemical conversion coating procedures.
- I. Install the part [1] doubler with BMS 5-95 sealant between the mating surfaces. Refer to 51-20-05 for the procedures to apply the sealant.
- J. Install the fasteners dry.
- K. Apply BMS 5-95 sealant around the edges of the part [1] doubler as given in 51-20-05.
- L. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.



REPAIR 1 Page 204 Nov 10/2007

DEING

737-800 STRUCTURAL REPAIR MANUAL



FLAT PATTERN OF THE REPAIR

NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENERS. USE (D) TO CALCULATE EDGE MARGINS.
- MAKE SURE THAT THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.


FASTENER SYMBOLS

➡ REPAIR FASTENER LOCATION. INSTALL A BACR15FP5E() OR A NAS 1739E5 BLIND RIVET. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.


> Vertical Stabilizer Leading Edge Skin External Repair Figure 202 (Sheet 1 of 2)



REPAIR 1 Page 205 Nov 01/2003







REPAIR 1 Page 206 Nov 01/2003

55-30-01



5. Inspection Instructions

A. Do a detailed visual inspection of the repair at each 5000 flight hour interval or more frequently. Inspect the blind rivets carefully. Blind rivets that are loose, missing, or damaged must be replaced.



REPAIR 1 Page 207 Nov 01/2003




REPAIR 2 - FLUSH REPAIR OF THE VERTICAL STABILIZER LEADING EDGE SKIN

1. Applicability

A. Repair 2 is applicable to damage to the vertical stabilizer leading edge skins shown in Vertical Stabilizer Leading Edge Skin Locations, Figure 201/REPAIR 2. Repair 2 is also applicable as a replacement repair for Repair 1.



REPAIR 2 Page 201 Nov 01/2003



LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Vertical Stabilizer Leading Edge Skin Locations Figure 201



REPAIR 2 Page 202 Nov 01/2003



2. General

- A. Repair 2 gives instructions for a Category A repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Make sure the aerodynamic smoothness is satisfactory or there will be a decrease in the performance of the aircraft. Refer to 51-10-01.

3. <u>References</u>

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05	REPAIR SEALING
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-00, GENERAL	Fasteners
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-40-05, GENERAL	Fastener Hole Sizes
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Repair Instructions

- A. Remove the damaged leading edge section.
- B. If this repair replaces an external repair, remove the repair fasteners, repair doubler, and sealant of the external repair. Refer to 51-40-02 for the procedures to remove the repair fasteners.
- C. Cut and remove the damaged part of the skin as shown in Vertical Stabilizer Leading Edge Skin Flush Repair, Figure 202/REPAIR 2. Refer to 51-10-02 for the procedures to remove the damage.
 - (1) Make the cut in the shape of a rectangle with the longest sides parallel to the leading edge ribs.
 - (2) Make the corner radii of the cut a minimum of 0.50 inch.
 - (3) Make the edges of the cut smooth to a surface finish of 125 microinches.
 - (4) Make sure there is a minimum of two rows of repair fasteners around the edges of the cut.
- D. Put the skin that is around the damage back to the initial contour.
- E. Make the repair parts as shown in Vertical Stabilizer Leading Edge Skin Flush Repair, Figure 202/REPAIR 2. Refer to Table 201/REPAIR 2 for the repair material.
 - (1) Make the contour of the repair parts the same as the initial contour of the skin.



REPAIR 2 Page 203 Nov 10/2007



Table 201:

REPAIR MATERIAL			
ITEM	PART	QUANTITY	MATERIAL
[1]	Doubler	1	Use clad 2024-T3 that is 0.063 inch thick when the initial skin is 0.040 inch thick. Use clad 2024-T3 that is one gage thicker than the initial skin when the thickness is more than 0.040 inch
[2]	Filler	1	Use clad 2024-T3 that is the same thickness as the initial skin


- F. Assemble the repair parts as shown in Vertical Stabilizer Leading Edge Skin Flush Repair, Figure 202/REPAIR 2.
- G. Drill and countersink the fastener holes.
 - (1) Align fastener holes in the part [1] doubler with holes in the skin made from an external repair.
- H. Remove the repair parts.
- I. Remove the nicks, scratches, gouges, burrs, and sharp edges from the repair parts and the bare surfaces of the skin.
- J. Install the repair parts with BMS 5-95 or BMS 5-26 sealant between the mating surfaces as shown in Vertical Stabilizer Leading Edge Skin Flush Repair, Figure 202/REPAIR 2. Refer to 51-20-05 for the procedures to apply the sealant.
- K. Install the rivets without sealant.
- L. Apply BMS 5-95 or BMS 5-26 sealant in the gap between the filler and the edge of the skin cut. Refer 51-20-05 for the procedures to apply the sealant.
- M. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.



REPAIR 2 Page 204 Nov 10/2007



737-800 STRUCTURAL REPAIR MANUAL



FLAT PATTERN OF THE REPAIR

NOTES

- ALL DIMENSIONS ARE IN INCHES
- (D) IS THE DIAMETER OF THE REPAIR FASTENER. USE (D) TO CALCULATE EDGE MARGINS.

FASTENER SYMBOLS

REPAIR FASTENER LOCATION. INSTALL A BACR15GF5D() SOLID RIVET. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.


> Vertical Stabilizer Leading Edge Skin Flush Repair Figure 202 (Sheet 1 of 2)



REPAIR 2 Page 205 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



SECTION THROUGH LEADING EDGE REPAIR

Vertical Stabilizer Leading Edge Skin Flush Repair Figure 202 (Sheet 2 of 2)



REPAIR 2 Page 206 Nov 01/2003



REPAIR 3 - VERTICAL STABILIZER INSPAR SKIN EXTERNAL REPAIR BETWEEN RIBS - FIN STATIONS 73.400 THRU 196.663

1. Applicability

- A. Repair 3 is applicable to damage to the vertical stabilizer inspar skins shown in Vertical Stabilizer Inspar Skin Locations, Figure 201/REPAIR 3 if:
 - (1) The damage is between Fin Stations 73.400 and 196.663.
 - (2) You do inspections of the repair as given in Paragraph 5./REPAIR 3
 - (3) You replace Repair 3 no more than 15,000 hours after installation with one of the repairs that follow:
 - (a) A permanent flush repair as shown in Repair 5 or Repair 6
 - (b) A replacement of the blind rivets with solid flush rivets for a permanent external repair.

2. General

- A. Repair 3 gives instructions for a Category C repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes.
 - (2) The conditions for aerodynamic smoothness shown in Vertical Stabilizer Inspar Skins -Aerodynamic Limits of Repairs with Protruding Head Fasteners, Figure 202/REPAIR 3 must be kept.
- C. Repair 3 can be used only if you install the blind rivets flush against the internal structure.
- D. It is optional to make an access door in the inspar skin. Use these openings to make sure the repair fasteners are installed correctly. Refer to Repairs 10 and 11 to make an access door.



REPAIR 3 Page 201 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL





Figure 201



REPAIR 3 Page 202 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL




Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 1 of 3)



REPAIR 3 Page 203 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



 $B_1 + B_2 + B_3 + B_4 = A$ MAXIMUM OF $\frac{H}{4} = 68.5$ INCHES MAXIMUM

NOTES

1 ONLY ONE REPAIR IS PERMITTED ACROSS THE AIRFLOW. A SECOND REPAIR DOWNSTREAM IS NOT PERMITTED.

В

Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 2 of 3)



REPAIR 3 Page 204 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL




Figure 202 (Sheet 3 of 3)



REPAIR 3 Page 205 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-00, GENERAL	Fasteners
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-40-05, GENERAL	Fastener Hole Sizes
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 6, 51-00-00	Structures - General
737 NDT Part 6, 51-00-00, Figure 1	Fastener Holes in Aluminum Parts (Meter Display)

4. Repair Instructions

- A. Drill a stop hole at the ends of all skin cracks that do not end at fastener holes. Refer to Inspar Skin External Repair Fin Stations 73.400 thru 196.663, Figure 203/REPAIR 3, Inspar Skin External Repair Fin Stations 73.400 thru 196.663, Figure 204/REPAIR 3, and SRM 51-10-02 for the procedures to drill a stop hole. For other damage, do what follows:
 - (1) Cut and remove the damaged part of the skin as shown in Inspar Skin External Repair Fin Stations 73.400 thru 196.663, Figure 203/REPAIR 3 or Inspar Skin External Repair - Fin Stations 73.400 thru 196.663, Figure 204/REPAIR 3. Refer to 51-10-02 for the procedures to remove the damage.
 - (a) For large cuts, make the cut in the shape of a rectangle with the longer sides parallel to the inspar ribs.
 - (b) Make the corner radii of the cut a minimum of 0.50 inch.
- B. Put the skin that is around the damage back to the initial contour.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes. Refer to 51-10-01.
- C. Make the part [1] doubler as shown in Inspar Skin External Repair Fin Stations 73.400 thru 196.663, Figure 203/REPAIR 3 or Inspar Skin External Repair - Fin Stations 73.400 thru 196.663, Figure 204/REPAIR 3. Refer to Table 201/REPAIR 3 for the repair material.
 - (1) Make the contour of the part [1] doubler the same as the initial contour of the skin.



REPAIR 3 Page 206 Nov 10/2007



Table 201:

	REPAIR MATERIAL			
ITEM PART QUANTITY MATERIAL		MATERIAL		
[1]	Doubler	1	Use clad or bare 2024-T3. Refer to Table 202 for the necessary thickness of the material. The use of clad material is recommended	

- D. Assemble the part [1] doubler as shown in Inspar Skin External Repair Fin Stations 73.400 thru 196.663, Figure 203/REPAIR 3 or Inspar Skin External Repair - Fin Stations 73.400 thru 196.663, Figure 204/REPAIR 3.
- E. Drill the fastener holes.
- F. Remove the part [1] doubler.
- G. Remove the nicks, scratches, gouges, burrs, and sharp edges from the doubler and the bare surfaces of the skin.


REPAIR PART THICKNESSES AND REPAIR FASTENER DIAMETERS FOR INITIAL SKIN THICKNESSES				
INITIAL SKIN THICKNESS (INCH)	ITEM [1] DOUBLER THICKNESS (INCH)	REPAIR FASTENER DIAMETER (INCH)		
0.032	0.050	5/32		
0.040	0.063	5/32		
0.041	0.063	5/32		
0.060	0.080	5/32		
0.071	REPAIR NOT PERMITTED			

Table 202:

- H. Apply a chemical conversion coating to the part [1] doubler and bare surfaces of the skin. Refer to 51-20-01 for the chemical conversion coating procedures.
- I. Apply one layer of BMS 10-79, Type II or III, primer to the area of the repair. Refer to SOPM 20-44-04 for the procedures to apply the primer.
 - (1) Apply the primer to the part [1] doubler.
 - (2) Apply the primer to the bare surfaces of the skin.
- J. Install repair washers in countersink holes for the initial fastener locations.
- K. Install the part [1] doubler with BMS 5-95 sealant between the mating surfaces. Refer to 51-20-05 for the procedures to apply the sealant.
- L. Install the fasteners without sealant.
- M. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.



REPAIR 3 Page 207 Nov 10/2007



Inspar Skin External Repair - Fin Stations 73.400 thru 196.663 Figure 203 (Sheet 1 of 3)





REPAIR 3 Page 208 Nov 01/2003

D634A210

BOEING®

737-800 STRUCTURAL REPAIR MANUAL





SECTION THROUGH REPAIR OF CHEM-MILLED SKIN

SECTION THROUGH REPAIR OF SKIN WITH CONSTANT THICKNESS

55-30-01

• FASTENER


€ FASTENER


0.10 INCH MINIMUM


KEEP A 0.20 INCH MINIMUM DISTANCE FROM THE CHEM-MILLED

RADIUS

A-A







REPAIR 3 Page 209 Nov 01/2003





NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENER. USE (D) TO CALCULATE EDGE MARGINS AND THE DISTANCE BETWEEN FASTENERS.
- MAKE SURE THAT THERE IS A MINIMUM OF SIX ROWS OF FASTENERS AROUND THE DAMAGE.
- MAKE SURE THAT THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.

FASTENER SYMBOLS

- REPAIR FASTENER LOCATION. INSTALL A BACR15FP5E BLIND RIVET. INSTALL A BACR15DS7D RIVET FOR A PERMANENT REPAIR. REFER TO SRM 51-40-00 THROUGH 51-40-06 FOR THE FASTENER DATA.
- + INITIAL FASTENER LOCATION. INSTALL A BACR15FP()E BLIND RIVET THAT IS THE SAME DIAMETER (UP TO 1/32 INCH DIAMETER OVERSIZE) AS THE INITIAL FASTENER. INSTALL A BACR15CE() RIVET FOR A PERMANENT REPAIR. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.
- ★ REPAIR FASTENER LOCATION. INSTALL A BACR15FP5E BLIND RIVET WHEN THERE IS CRACK DAMAGE. INSTALL A BACR15DS7D RIVET FOR A PERMANENT REPAIR. REFER TO SRM 51-40-00 THROUGH 51-40-06 FOR THE FASTENER DATA.


Inspar Skin External Repair - Fin Stations 73.400 thru 196.663 Figure 203 (Sheet 3 of 3)



REPAIR 3 Page 210 Nov 01/2003

D634A210

737-800 STRUCTURAL REPAIR MANUAL



NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENER. USE (D) TO CALCULATE EDGE MARGINS AND THE DISTANCE BETWEEN FASTENERS.
- MAKE SURE THAT THERE IS A MINIMUM OF THREE ROWS OF FASTENERS AROUND THE DAMAGE.
- MAKE SURE THAT THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.

FASTENER SYMBOLS

- ➡ REPAIR FASTENER LOCATION. INSTALL A BACR15CE6 OR A BACR15CE8 SOLID RIVET. REFER TO SRM 51-40-00 THROUGH 51-40-06 FOR THE FASTENER DATA.
- + INITIAL FASTENER LOCATION. INSTALL A BACR15CE() SOLID RIVET THAT IS THE SAME DIAMETER (UP TO 1/32 INCH DIAMETER OVERSIZE) AS THE INITIAL FASTENER. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.
- ✤ REPAIR FASTENER LOCATION. INSTALL A BACR15CE6 OR A BACR15CE8 SOLID RIVET WHEN THERE IS CRACK DAMAGE. REFER TO SRM 51-40-00 THROUGH 51-40-06 FOR THE FASTENER DATA.

Inspar Skin External Repair - Fin Stations 73.400 thru 196.663 Figure 204 (Sheet 1 of 2)





REPAIR 3 Page 211 Nov 01/2003

D634A210

BOEING


737-800 STRUCTURAL REPAIR MANUAL







OF CHEM-MILLED SKIN

A-A





SECTION THROUGH REPAIR OF SKIN WITH CONSTANT THICKNESS



55-30-01

Inspar Skin External Repair - Fin Stations 73.400 thru 196.663 Figure 204 (Sheet 2 of 2)

> **REPAIR 3** Page 212 Nov 01/2003





5. Inspection Instructions

- A. Do a detailed visual inspection of the repair at each 5000 flight hour interval or more frequently. Inspect the blind rivets carefully. Blind rivets that are loose, missing, or damaged must be replaced.
- B. When you remove the temporary repair and replace it with the permanent repair shown in Inspar Skin External Repair Fin Stations 73.400 thru 196.663, Figure 203/REPAIR 3, do what follows:
 - (1) Remove the BACR15FP()E rivets and ream the holes 1/64 inch oversize to remove the damage.
 - (2) Make an inspection of the holes with the eddy current procedures. Refer to 737 NDT Part 6, 51-00-00, Figure 1 or Figure 16 and SRM 51-10-02.
 - (a) If no cracks are found, make the holes larger to install the BACR15DS7D or BACR15CE() rivets.
 - (b) If you find cracks, make the holes 1/64 inch larger in diameter to remove all remaining fatigue damaged material.
 - (c) Make a final inspection of the holes with the eddy current procedures.





REPAIR 4 - VERTICAL STABILIZER INSPAR SKIN EXTERNAL REPAIR BETWEEN RIBS - FIN STATIONS 196.663 THRU 343.863

1. Applicability

- A. Repair 4 is applicable to damage to the vertical stabilizer inspar skins shown in Vertical Stabilizer Inspar Skin Locations, Figure 201/REPAIR 4 if:
 - (1) The damage is between Fin Stations 196.663 and 343.863.
 - (2) You do inspections of the repair as given in Paragraph 5./REPAIR 4
 - (3) You replace Repair 4 no more than 15,000 hours after installation with one of the repairs that follow:
 - (a) A permanent flush repair as shown in Repair 7 or Repair 8
 - (b) A replacement of the blind rivets with solid flush rivets for a permanent external repair.

2. General


- A. Repair 4 gives instructions for a Category C repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes.
 - (2) The conditions for aerodynamic smoothness shown in Vertical Stabilizer Inspar Skins -Aerodynamic Limits of Repairs with Protruding Head Fasteners, Figure 202/REPAIR 4 must be kept.
- C. Repair 4 can be used only if you install the blind rivets flush against the internal structure.
- D. It is optional to make an access door in the inspar skin. Use these openings to make sure the repair fasteners are installed correctly. Refer to Repairs 10 and 11 to make an access door.



REPAIR 4 Page 201 Nov 01/2003

BOEING"

737-800 STRUCTURAL REPAIR MANUAL




Vertical Stabilizer Inspar Skin Locations Figure 201



REPAIR 4 Page 202 Nov 01/2003

BOEING"

737-800 STRUCTURAL REPAIR MANUAL



Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 1 of 3)




REPAIR 4 Page 203 Nov 01/2003



BOEING®

737-800 STRUCTURAL REPAIR MANUAL



 $B_1 + B_2 + B_3 + B_4 = A$ MAXIMUM OF $\frac{H}{4} = 68.5$ INCHES MAXIMUM

NOTES

1 ONLY ONE REPAIR IS PERMITTED ACROSS THE AIRFLOW. A SECOND REPAIR DOWNSTREAM IS NOT PERMITTED.

В

Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 2 of 3)



REPAIR 4 Page 204 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL




Figure 202 (Sheet 3 of 3)



REPAIR 4 Page 205 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-01, GENERAL	Fasteners
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-40-05, GENERAL	Fastener Hole Sizes
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 6, 51-00-00	Structures - General
737 NDT Part 6, 51-00-00, Figure 1	Fastener Holes in Aluminum Parts (Meter Display)
737 NDT Part 6, 51-00-00, Figure 16	Aluminum Part Fastener Hole Inspection (Rotary Scanner)

4. Repair Instructions

- A. Drill a stop hole at the ends of all skin cracks that do not end at fastener holes. Refer to Inspar Skin External Repair Fin Stations 196.663 thru 343.863, Figure 203/REPAIR 4, Inspar Skin External Repair Fin Stations 196.663 thru 343.863, Figure 204/REPAIR 4, and SRM 51-10-02 for the procedures to drill a stop hole. For other damage, do what follows:
 - (1) Cut and remove the damaged part of the skin as shown in Inspar Skin External Repair Fin Stations 196.663 thru 343.863, Figure 203/REPAIR 4 or Inspar Skin External Repair - Fin Stations 196.663 thru 343.863, Figure 204/REPAIR 4. Refer to 51-10-02 for the procedures to remove the damage.
 - (a) For large cuts, make the cut in the shape of a rectangle with the longer sides parallel to the inspar ribs.
 - (b) Make the corner radii of the cut a minimum of 0.50 inch.
- B. Put the skin that is around the damage back to the initial contour.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes. Refer to 51-10-01.
- C. Make the part [1] doubler as shown in Inspar Skin External Repair Fin Stations 196.663 thru 343.863, Figure 203/REPAIR 4 or Inspar Skin External Repair - Fin Stations 196.663 thru 343.863, Figure 204/REPAIR 4. Refer to Table 201/REPAIR 4 for the repair material.
 - (1) Make the contour of the part [1] doubler the same as the initial contour of the skin.



REPAIR 4 Page 206 Nov 10/2007



Table 201:

	REPAIR MATERIAL			
ITEM PART QUANTITY MATERIAL		MATERIAL		
[1]	Doubler	1	Use clad or bare 2024-T3. Refer to Table 202 for the necessary thickness of the material. The use of clad material is recommended	

- D. Assemble the part [1] doubler as shown in Inspar Skin External Repair Fin Stations 196.663 thru 343.863, Figure 203/REPAIR 4 or Inspar Skin External Repair - Fin Stations 196.663 thru 343.863, Figure 204/REPAIR 4.
- E. Drill the fastener holes.
- F. Remove the part [1] doubler.
- G. Remove the nicks, scratches, gouges, burrs, and sharp edges from the doubler and the bare surfaces of the skin.

Table 202:


REPAIR PART THICKNESSES AND REPAIR FASTENER DIAMETERS FOR INITIAL SKIN THICKNESSES				
INITIAL SKIN THICKNESS (INCH) ITEM [1] DOUBLER THICKNESS (INCH) REPAIR FASTENER DIAMETER (I				
0.032	0.050	5/32		
0.041	0.063	5/32		

- H. Apply a chemical conversion coating to the part [1] doubler and bare surfaces of the skin. Refer to 51-20-01 for the chemical conversion coating procedures.
- I. Apply one layer of BMS 10-79, Type II or III, primer to the area of the repair. Refer to SOPM 20-44-04 for the procedures to apply the primer.
 - (1) Apply the primer to the part [1] doubler.
 - (2) Apply the primer to the bare surfaces of the skin.
- J. Install repair washers in countersink holes for the initial fastener locations.
- K. Install the part [1] doubler with BMS 5-95 sealant between the mating surfaces. Refer to 51-20-05 for the procedures to apply the sealant.
- L. Install the fasteners without sealant.
- M. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.



REPAIR 4 Page 207 Nov 10/2007

737-800 STRUCTURAL REPAIR MANUAL



NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENER. USE (D) TO CALCULATE EDGE MARGINS AND THE DISTANCE BETWEEN FASTENERS.
- MAKE SURE THAT THERE IS A MINIMUM OF FOUR ROWS OF FASTENERS AROUND THE DAMAGE.
- MAKE SURE THAT THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.

FASTENER SYMBOLS

- ➡ REPAIR FASTENER LOCATION. INSTALL A BACR15FP5E BLIND RIVET. INSTALL A BACR15DS7D RIVET FOR A PERMANENT REPAIR. REFER TO SRM 51-40-00 THROUGH 51-40-06 FOR THE FASTENER DATA.
- + INITIAL FASTENER LOCATION. INSTALL A BACR15FP()E BLIND RIVET THAT IS THE SAME DIAMETER (UP TO 1/32 INCH DIAMETER OVERSIZE) AS THE INITIAL FASTENER. INSTALL A BACR15CE() RIVET FOR A PERMANENT REPAIR. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.
- ♣ REPAIR FASTENER LOCATION. INSTALL A BACR15FP5E BLIND RIVET WHEN THERE IS CRACK DAMAGE. INSTALL A BACR15DS7D RIVET FOR A PERMANENT REPAIR. REFER TO SRM 51-40-00 THROUGH 51-40-06 FOR THE FASTENER DATA.


Inspar Skin External Repair - Fin Stations 196.663 thru 343.863 Figure 203 (Sheet 1 of 2)



REPAIR 4 Page 208 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL




REPAIR 4 Page 209 Nov 01/2003

55-30-01

DEING®

737-800 STRUCTURAL REPAIR MANUAL



NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENER. USE (D) TO CALCULATE EDGE MARGINS AND THE DISTANCE BETWEEN FASTENERS.
- MAKE SURE THAT THERE IS A MINIMUM OF THREE ROWS OF FASTENERS AROUND THE DAMAGE.
- MAKE SURE THAT THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.

FASTENER SYMBOLS

- ➡ REPAIR FASTENER LOCATION. INSTALL A BACR15CE6 OR A BACR15CE8 SOLID RIVET. REFER TO SRM 51-40-00 THROUGH 51-40-06 FOR THE FASTENER DATA.
- + INITIAL FASTENER LOCATION. INSTALL A BACR15CE() SOLID RIVET THAT IS THE SAME DIAMETER (UP TO 1/32 INCH DIAMETER OVERSIZE) AS THE INITIAL FASTENER. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.
- ✤ REPAIR FASTENER LOCATION. INSTALL A BACR15CE6 OR A BACR15CE8 SOLID RIVET WHEN THERE IS CRACK DAMAGE. REFER TO SRM 51-40-00 THROUGH 51-40-06 FOR THE FASTENER DATA.

Inspar Skin External Repair - Fin Stations 196.663 thru 343.863 Figure 204 (Sheet 1 of 2)




REPAIR 4 Page 210 Nov 01/2003

D634A210




737-800 STRUCTURAL REPAIR MANUAL



SECTION THROUGH REPAIR OF CHEM-MILLED SKIN

A-A



REPAIR 4 Page 211 Nov 01/2003

55-30-01



5. Inspection Instructions

- A. Do a detailed visual inspection of the repair at each 5000 flight hour interval or more frequently. Inspect the blind rivets carefully. Blind rivets that are loose, missing, or damaged must be replaced.
- B. When you remove the temporary repair and replace it with the permanent repair shown in Inspar Skin External Repair Fin Stations 196.663 thru 343.863, Figure 203/REPAIR 4, do what follows:
 - (1) Remove the BACR15FP()E rivets and ream the holes 1/64 inch oversize to remove the damage.
 - (2) Make an inspection of the holes with the eddy current procedures. Refer to 737 NDT Part 6, 51-00-00, Figure 1 or Figure 16 and SRM 51-10-02.
 - (a) If no cracks are found, make the holes larger to install the BACR15DS7D or BACR15CE() rivets.
 - (b) If you find cracks, make the holes 1/64 inch larger in diameter to remove all remaining fatigue damaged material.
 - (c) Make a final inspection of the holes with the eddy current procedures.





REPAIR 5 - VERTICAL STABILIZER INSPAR SKIN FLUSH REPAIR BETWEEN RIBS - FIN STATIONS 73.400 THRU 196.663

1. Applicability

A. Repair 5 is applicable:

- (1) To damage to the vertical stabilizer inspar skins shown in Vertical Stabilizer Inspar Skin Locations, Figure 201/REPAIR 5 between Fin Stations 73.400 and 196.663.
- (2) As a replacement repair for Repair 3.
- (3) As an alternative to Repair 6.

2. General


- A. Repair 5 gives instructions for a Category A repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes.
 - (2) The conditions for aerodynamic smoothness shown in Vertical Stabilizer Inspar Skins -Aerodynamic Limits of Repairs with Protruding Head Fasteners, Figure 202/REPAIR 5 must be kept.
- C. It is optional to make an access door in the inspar skin. Use these openings to make sure the repair fasteners are installed correctly. Refer to Repairs 10 and 11 to make an access door.



REPAIR 5 Page 201 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS ALMOST THE SAME

Vertical Stabilizer Inspar Skin Locations Figure 201




REPAIR 5 Page 202 Nov 01/2003

D634A210

BOEING®

737-800 STRUCTURAL REPAIR MANUAL




Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 1 of 3)



REPAIR 5 Page 203 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



 $B_1 + B_2 + B_3 + B_4 = A$ MAXIMUM OF $\frac{H}{4} = 68.5$ INCHES MAXIMUM

NOTES

1 ONLY ONE REPAIR IS PERMITTED ACROSS THE AIRFLOW. A SECOND REPAIR DOWNSTREAM IS NOT PERMITTED.

В

Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 2 of 3)



REPAIR 5 Page 204 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL




Figure 202 (Sheet 3 of 3)



REPAIR 5 Page 205 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-00, GENERAL	Fasteners
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-40-05, GENERAL	Fastener Hole Sizes
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Repair Instructions

- A. If this repair replaces an external repair, remove the repair fasteners, repair doubler, and sealant of the external repair. Refer to 51-40-02 for the procedures to remove the repair fasteners.
- B. Get access to the damaged area of the inspar skin as follows:
 - (1) Remove the leading edge skin panels or install an access door.
- C. Cut and remove the damaged part of the skin as shown in Vertical Stabilizer Inspar Skin Flush Repair Between Ribs - Fin Stations 73.400 through 196.663, Figure 203/REPAIR 5. Refer to 51-10-02 for the procedures to remove the damage.
 - (1) Make the cut in the shape of a rectangle with the longer sides parallel to the inspar ribs.
 - (2) Make the corner radii of the cut a minimum of 0.50 inch.
- D. Put the skin that is around the damage back to the initial contour.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes. Refer to 51-10-01.
- E. Make the repair parts as shown in Vertical Stabilizer Inspar Skin Flush Repair Between Ribs Fin Stations 73.400 through 196.663, Figure 203/REPAIR 5. Refer to Table 201/REPAIR 5 for the repair material.
 - (1) Make the contour of the repair parts the same as the initial contour of the skin.

REPAIR MATERIAL			
ITEM PART QUANTITY MATERIAL			
[1]	Doubler	1	Use clad or bare 2024-T3. Refer to Table 202 for the necessary thickness of the material. The use of clad material is recommended

Table 201:







	REPAIR MATERIAL			
ITEM PART QUANTITY MATERIAL				
[2]	Filler	1	Use clad or bare 2024-T3 that is the same thickness as the initial skin. The use of clad material is recommended	


Table 202:

REPAIR PART THICKNESSES AND REPAIR FASTENER DIAMETERS FOR INITIAL SKIN THICKNESSES				
INITIAL SKIN THICKNESS (INCH)	ITEM [1] DOUBLER THICKNESS (INCH)	REPAIR FASTENER DIAMETER (INCH)		
0.032	0.050	5/32		
0.040	0.063	5/32		
0.041	REPAIR NOT PERMITTED			
0.060	REPAIR NOT PERMITTED			
0.071	71 REPAIR NOT PERMITTED			

- F. Assemble the repair parts as shown in Vertical Stabilizer Inspar Skin Flush Repair Between Ribs -Fin Stations 73.400 through 196.663, Figure 203/REPAIR 5.
- G. Drill the fastener holes.
 - (1) Align fastener holes in the repair parts with holes in the skin made from an external repair.
- H. Remove the repair parts.
- I. Remove the nicks, scratches, gouges, burrs, and sharp edges from the repair parts and the bare surfaces of the skin.
- J. Apply a chemical conversion coating to the repair parts and bare surfaces of the skin. Refer to 51-20-01 for the chemical conversion coating procedures.
- K. Apply one layer of BMS 10-79, Type II or III, primer to the area of the repair. Refer to SOPM 20-44-04 for the procedures to apply the primer.
 - (1) Apply the primer to the repair parts.
 - (2) Apply the primer to the bare surfaces of the skin.
- L. Install the repair parts with BMS 5-95 sealant between the mating surfaces. Refer to 51-20-05 for the procedures to apply the sealant.
- M. Install the rivets without sealant in the repair parts and skin.
- N. Apply BMS 5-95 or BMS 5-26 sealant in the space between the filler and the edge of the skin cut. Refer 51-20-05 for the procedures to apply the sealant.
- O. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.



REPAIR 5 Page 207 Nov 10/2007



TYPICAL REPAIR

NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENER. USE (D) TO CALCULATE EDGE MARGINS AND THE DISTANCE BETWEEN FASTENERS.
- MAKE SURE THAT THERE IS A MINIMUM OF THREE ROWS OF FASTENERS AROUND THE DAMAGE.
- MAKE SURE THAT THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.

FASTENER SYMBOLS

- + INITIAL FASTENER LOCATION. INSTALL A FASTENER THAT IS THE SAME TYPE AND DIAMETER (UP TO 1/32 INCH DIAMETER OVERSIZE) AS THE INITIAL FASTENER.
- REPAIR FASTENER LOCATION. INSTALL A BACR15FT5D() SOLID RIVET. REFER TO SRM 51-40-00 THROUGH 51-40-06 FOR THE FASTENER DATA.


Vertical Stabilizer Inspar Skin Flush Repair Between Ribs - Fin Stations 73.400 through 196.663 Figure 203 (Sheet 1 of 2)




REPAIR 5 Page 208 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL







Vertical Stabilizer Inspar Skin Flush Repair Between Ribs - Fin Stations 73.400 through 196.663 Figure 203 (Sheet 2 of 2)



REPAIR 5 Page 209 Nov 01/2003



REPAIR 6 - VERTICAL STABILIZER INSPAR SKIN FLUSH REPAIR WITH SPLICED DOUBLER BETWEEN RIBS -FIN STATIONS 73.400 THRU 196.663

1. Applicability

A. Repair 6 is applicable:

- (1) To damage to the vertical stabilizer inspar skins shown in Vertical Stabilizer Inspar Skin Locations, Figure 201/REPAIR 6 between Fin Stations 73.400 and 196.663.
- (2) As a replacement repair for Repair 3.
- (3) As an alternative to Repair 5 if there is not sufficient clearance to install the repair doubler in one piece.

2. General


- A. Repair 6 gives instructions for a Category A repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes.
 - (2) The conditions for aerodynamic smoothness shown in Vertical Stabilizer Inspar Skins -Aerodynamic Limits of Repairs with Protruding Head Fasteners, Figure 202/REPAIR 6 must be kept.
- C. It is optional to make an access door in the inspar skin. Use these openings to make sure the repair fasteners are installed correctly. Refer to Repairs 10 and 11 to make an access door.



REPAIR 6 Page 201 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS ALMOST THE SAME


Vertical Stabilizer Inspar Skin Locations Figure 201



REPAIR 6 Page 202 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL




Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 1 of 3)



REPAIR 6 Page 203 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



 $B_1 + B_2 + B_3 + B_4 = A$ MAXIMUM OF $\frac{H}{4} = 68.5$ INCHES MAXIMUM

NOTES

1 ONLY ONE REPAIR IS PERMITTED ACROSS THE AIRFLOW. A SECOND REPAIR DOWNSTREAM IS NOT PERMITTED.

В

Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 2 of 3)



REPAIR 6 Page 204 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL




Figure 202 (Sheet 3 of 3)



REPAIR 6 Page 205 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-00, GENERAL	Fasteners
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-40-05, GENERAL	Fastener Hole Sizes
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Repair Instructions

- A. If this repair replaces an external repair, remove the repair fasteners, repair doubler, and sealant of the external repair. Refer to 51-40-02 for the procedures to remove the repair fasteners.
- B. Get access to the damaged area of the inspar skin as follows:
 - (1) Remove the leading edge skin panels or install an access door.
- C. Cut and remove the damaged part of the skin as shown in Vertical Stabilizer Inspar Skin Flush Repair with Spliced Doubler Between Ribs - Fin Stations 73.400 through 196.663, Figure 203/REPAIR 6. Refer to 51-10-02 for the procedures to remove the damage.
 - (1) Make the cut in the shape of a rectangle with the longer sides parallel to the inspar ribs.
 - (2) Make the corner radii of the cut a minimum of 0.50 inch.
- D. Put the skin that is around the damage back to the initial contour.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes. Refer to 51-10-01.
- E. Make the repair parts as shown in Vertical Stabilizer Inspar Skin Flush Repair with Spliced Doubler Between Ribs Fin Stations 73.400 through 196.663, Figure 203/REPAIR 6. Refer to Table 201/REPAIR 6 for the repair material.
 - (1) Make the contour of the repair parts the same as the initial contour of the skin.
- F. Assemble the repair parts as shown in Vertical Stabilizer Inspar Skin Flush Repair with Spliced Doubler Between Ribs Fin Stations 73.400 through 196.663, Figure 203/REPAIR 6.
- G. Drill the fastener holes.
 - (1) Align fastener holes in the repair parts with holes in the skin made from an external repair.
- H. Remove the repair parts.



REPAIR 6 Page 206 Nov 10/2007



I. Remove the nicks, scratches, gouges, burrs, and sharp edges from the repair parts and the bare surfaces of the skin.

Та	ble	e 2	01:

	REPAIR MATERIAL			
ITEM PART QUANTITY MATERIAL		MATERIAL		
[1]	Doubler	1	Use clad or bare 2024-T3. Refer to Table 202 for the necessary thickness of the material. The use of clad material is recommended.	
[2]	Filler	1	1 Use clad or bare 2024-T3 that is the same thickness as the initial skin. The use of clad material is recommended.	
[3]	Doubler Splice	1	Use clad or bare 2024-T3. Refer to Table 202 for the necessary thickness of the material. The use of clad material is recommended.	


Table 202:

REPAIR PART THICKNESSES AND REPAIR FASTENER DIAMETERS FOR INITIAL SKIN THICKNESSES		
INITIAL SKIN THICKNESS (INCH)	ITEM [1] DOUBLER AND ITEM [3] DOUBLER SPLICE THICKNESSES (INCH)	REPAIR FASTENER DIAMETER (INCH)
0.032	0.050	5/32
0.040	0.063	5/32
0.041	REPAIR NOT PERMITTED	
0.060	REPAIR NOT PERMITTED	
0.071	REPAIR NOT PERMITTED	

- J. Apply a chemical conversion coating to the repair parts and bare surfaces of the skin. Refer to 51-20-01 for the chemical conversion coating procedures.
- K. Apply one layer of BMS 10-79, Type II or III, primer to the area of the repair. Refer to SOPM 20-44-04 for the procedures to apply the primer.
 - (1) Apply the primer to the repair parts.
 - (2) Apply the primer to the bare surfaces of the skin.
- L. Install the repair parts with BMS 5-95 sealant between the mating surfaces. Refer to 51-20-05 for the procedures to apply the sealant.
- M. Install the rivets without sealant in the repair parts and skin.
- N. Apply BMS 5-95 or BMS 5-26 sealant in the space between the filler and the edge of the skin cut. Refer 51-20-05 for the procedures to apply the sealant.
- O. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.



REPAIR 6 Page 207 Nov 10/2007



NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENER. USE (D) TO CALCULATE EDGE MARGINS AND THE DISTANCE BETWEEN FASTENERS.
- MAKE SURE THAT THERE IS A MINIMUM OF THREE ROWS OF FASTENERS AROUND THE DAMAGE.
- MAKE SURE THAT THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.

FASTENER SYMBOLS

- -I- REFERENCE FASTENER LOCATION
- + INITIAL FASTENER LOCATION. INSTALL A FASTENER THAT IS THE SAME TYPE AND DIAMETER (UP TO 1/32 INCH DIAMETER OVERSIZE) AS THE INITIAL FASTENER.
- ➡ REPAIR FASTENER LOCATION. INSTALL A BACR15FT5D() SOLID RIVET. REFER TO SRM 51-40-00 THROUGH 51-40-06 FOR THE FASTENER DATA.

Vertical Stabilizer Inspar Skin Flush Repair with Spliced Doubler Between Ribs - Fin Stations 73.400 through 196.663


Figure 203 (Sheet 1 of 2)



REPAIR 6 Page 208 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



T = RIB FLANGE THICKNESS JOGGLE (TYPICAL)

Vertical Stabilizer Inspar Skin Flush Repair with Spliced Doubler Between Ribs - Fin Stations 73.400 through 196.663 Figure 203 (Sheet 2 of 2)



REPAIR 6 Page 209 Nov 01/2003



REPAIR 7 - VERTICAL STABILIZER INSPAR SKIN FLUSH REPAIR BETWEEN RIBS - FIN STATIONS 196.663 THRU 343.863

1. Applicability

A. Repair 7 is applicable:

- (1) To damage to the vertical stabilizer inspar skins shown in Vertical Stabilizer Inspar Skin Locations, Figure 201/REPAIR 7 between Fin Stations 196.663 and 343.863.
- (2) As a replacement repair for Repair 4.
- (3) As an alternative to Repair 8.

2. General


- A. Repair 7 gives instructions for a Category A repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes.
 - (2) The conditions for aerodynamic smoothness shown in Vertical Stabilizer Inspar Skins -Aerodynamic Limits of Repairs with Protruding Head Fasteners, Figure 202/REPAIR 7 must be kept.
- C. It is optional to make an access door in the inspar skin. Use these openings to make sure the repair fasteners are installed correctly. Refer to Repairs 10 and 11 to make an access door.



REPAIR 7 Page 201 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL




Vertical Stabilizer Inspar Skin Locations Figure 201



REPAIR 7 Page 202 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL




Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 1 of 3)



REPAIR 7 Page 203 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



 $B_1 + B_2 + B_3 + B_4 = A$ MAXIMUM OF $\frac{H}{4} = 68.5$ INCHES MAXIMUM

NOTES

1 ONLY ONE REPAIR IS PERMITTED ACROSS THE AIRFLOW. A SECOND REPAIR DOWNSTREAM IS NOT PERMITTED.

В

Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 2 of 3)



REPAIR 7 Page 204 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL




Figure 202 (Sheet 3 of 3)



REPAIR 7 Page 205 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-00, GENERAL	Fasteners
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-40-05, GENERAL	Fastener Hole Sizes
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Repair Instructions

- A. If this repair replaces an external repair, remove the repair fasteners, repair doubler, and sealant of the external repair. Refer to 51-40-02 for the procedures to remove the repair fasteners.
- B. Get access to the damaged area of the inspar skin as follows:
 - (1) Remove the leading edge skin panels or install an access door.
- C. Cut and remove the damaged part of the skin as shown in Vertical Stabilizer Inspar Skin Flush Repair Between Ribs - Fin Stations 196.663 through 343.863, Figure 203/REPAIR 7. Refer to 51-10-02 for the procedures to remove the damage.
 - (1) Make the cut in the shape of a rectangle with the longer sides parallel to the inspar ribs.
 - (2) Make the corner radii of the cut a minimum of 0.50 inch.
- D. Put the skin that is around the damage back to the initial contour.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes. Refer to 51-10-01.
- E. Make the repair parts as shown in Vertical Stabilizer Inspar Skin Flush Repair Between Ribs Fin Stations 196.663 through 343.863, Figure 203/REPAIR 7. Refer to Table 201/REPAIR 7 for the repair material.
 - (1) Make the contour of the repair parts the same as the initial contour of the skin.

REPAIR MATERIAL				
ITEM	ITEM PART QUANTITY MATERIAL			
[1]	Doubler	1	Use clad or bare 2024-T3. Refer to Table 202 for the necessary thickness of the material. The use of clad material is recommended	

Table 201:







REPAIR MATERIAL				
ITEM	ITEM PART QUANTITY MATERIAL			
[2]	[2] Filler 1 Use clad or bare 2024-T3 that is the same thickness as the initial skin. The us clad material is recommended			


Table 202:

REPAIR PART THICKNESSES AND REPAIR FASTENER DIAMETERS FOR INITIAL SKIN THICKNESSES				
INITIAL SKIN THICKNESS (INCH) ITEM [1] DOUBLER THICKNESS (INCH) REPAIR FASTENER DIAMETER				
0.032	0.050	5/32		
0.041	0.063	5/32		

- F. Assemble the repair parts as shown in Vertical Stabilizer Inspar Skin Flush Repair Between Ribs -Fin Stations 196.663 through 343.863, Figure 203/REPAIR 7.
- G. Drill the fastener holes.
 - (1) Align fastener holes in the repair parts with holes in the skin made from an external repair.
- H. Remove the repair parts.
- I. Remove the nicks, scratches, gouges, burrs, and sharp edges from the repair parts and the bare surfaces of the skin.
- J. Apply a chemical conversion coating to the repair parts and bare surfaces of the skin. Refer to 51-20-01 for the chemical conversion coating procedures.
- K. Apply one layer of BMS 10-79, Type II or III, primer to the area of the repair. Refer to SOPM 20-44-04 for the procedures to apply the primer.
 - (1) Apply the primer to the repair parts.
 - (2) Apply the primer to the bare surfaces of the skin.
- L. Install the repair parts with BMS 5-95 sealant between the mating surfaces. Refer to 51-20-05 for the procedures to apply the sealant.
- M. Install the rivets without sealant in the repair parts and skin.
- N. Apply BMS 5-95 or BMS 5-26 sealant in the space between the filler and the edge of the skin cut. Refer 51-20-05 for the procedures to apply the sealant.
- O. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.



REPAIR 7 Page 207 Nov 10/2007



TYPICAL REPAIR

NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENER. USE (D) TO CALCULATE EDGE MARGINS AND THE DISTANCE BETWEEN FASTENERS.
- MAKE SURE THAT THERE IS A MINIMUM OF THREE ROWS OF FASTENERS AROUND THE DAMAGE.
- MAKE SURE THAT THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.

FASTENER SYMBOLS

- + INITIAL FASTENER LOCATION. INSTALL A FASTENER THAT IS THE SAME TYPE AND DIAMETER (UP TO 1/32 INCH DIAMETER OVERSIZE) AS THE INITIAL FASTENER.
- REPAIR FASTENER LOCATION. INSTALL A BACR15FT5D() SOLID RIVET. REFER TO SRM 51-40-00 THROUGH 51-40-06 FOR THE FASTENER DATA.


Vertical Stabilizer Inspar Skin Flush Repair Between Ribs - Fin Stations 196.663 through 343.863 Figure 203 (Sheet 1 of 2)




REPAIR 7 Page 208 Nov 01/2003

BOEING

737-800 STRUCTURAL REPAIR MANUAL







Vertical Stabilizer Inspar Skin Flush Repair Between Ribs - Fin Stations 196.663 through 343.863 Figure 203 (Sheet 2 of 2)



REPAIR 7 Page 209 Nov 01/2003



REPAIR 8 - VERTICAL STABILIZER INSPAR SKIN FLUSH REPAIR WITH SPLICED DOUBLER BETWEEN RIBS -FIN STATIONS 196.663 THRU 343.863

1. Applicability

A. Repair 8 is applicable:

- (1) To damage to the vertical stabilizer inspar skins shown in Vertical Stabilizer Inspar Skin Locations, Figure 201/REPAIR 8 between Fin Stations 196.663 and 343.863.
- (2) As a replacement repair for Repair 4.
- (3) As an alternative to Repair 7 if there is not sufficient clearance to install the repair doubler in one piece.

2. General


- A. Repair 8 gives instructions for a Category A repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes.
 - (2) The conditions for aerodynamic smoothness shown in Vertical Stabilizer Inspar Skins -Aerodynamic Limits of Repairs with Protruding Head Fasteners, Figure 202/REPAIR 8 must be kept.
- C. It is optional to make an access door in the inspar skin. Use these openings to make sure the repair fasteners are installed correctly. Refer to Repairs 10 and 11 to make an access door.



REPAIR 8 Page 201 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS ALMOST THE SAME


Vertical Stabilizer Inspar Skin Locations Figure 201

55-30-01

REPAIR 8 Page 202 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 1 of 3)




REPAIR 8 Page 203 Nov 01/2003



BOEING®

737-800 STRUCTURAL REPAIR MANUAL



 $B_1 + B_2 + B_3 + B_4 = A$ MAXIMUM OF $\frac{H}{4} = 68.5$ INCHES MAXIMUM

NOTES

1 ONLY ONE REPAIR IS PERMITTED ACROSS THE AIRFLOW. A SECOND REPAIR DOWNSTREAM IS NOT PERMITTED.

В

Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 2 of 3)



REPAIR 8 Page 204 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL





Figure 202 (Sheet 3 of 3)



REPAIR 8 Page 205 Nov 01/2003



3. References

Reference Title		
51-00-06	STRUCTURAL REPAIR DEFINITIONS	
51-10-01	AERODYNAMIC SMOOTHNESS	
51-10-02	INSPECTION AND REMOVAL OF DAMAGE	
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS	
51-20-05	REPAIR SEALING	
51-30-05, GENERAL	Equipment and Tools For Repairs	
51-40-00, GENERAL Fasteners		
51-40-02	FASTENER INSTALLATION AND REMOVAL	
51-40-03, GENERAL	Fastener Substitution	
51-40-05, GENERAL	Fastener Hole Sizes	
51-40-06, GENERAL	Fastener Edge Margins	
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures	
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING	
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES	
SOPM 20-44-04	Application of Urethane Compatible Primers	

4. Repair Instructions

- A. If this repair replaces an external repair, remove the repair fasteners, repair doubler, and sealant of the external repair. Refer to 51-40-02 for the procedures to remove the repair fasteners.
- B. Get access to the damaged area of the inspar skin as follows:
 - (1) Remove the leading edge skin panels or install an access door.
- C. Cut and remove the damaged part of the skin as shown in Vertical Stabilizer Inspar Skin Flush Repair with Spliced Doubler Between Ribs - Fin Stations 196.663 through 343.863, Figure 203/REPAIR 8. Refer to 51-10-02 for the procedures to remove the damage.
 - (1) Make the cut in the shape of a rectangle with the longer sides parallel to the inspar ribs.
 - (2) Make the corner radii of the cut a minimum of 0.50 inch.
- D. Put the skin that is around the damage back to the initial contour.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes. Refer to 51-10-01.
- E. Make the repair parts as shown in Vertical Stabilizer Inspar Skin Flush Repair with Spliced Doubler Between Ribs - Fin Stations 196.663 through 343.863, Figure 203/REPAIR 8. Refer to Table 201/REPAIR 8 for the repair material.
 - (1) Make the contour of the repair parts the same as the initial contour of the skin.
- F. Assemble the repair parts as shown in Vertical Stabilizer Inspar Skin Flush Repair with Spliced Doubler Between Ribs Fin Stations 196.663 through 343.863, Figure 203/REPAIR 8.
- G. Drill the fastener holes.
 - (1) Align fastener holes in the repair parts with holes in the skin made from an external repair.
- H. Remove the repair parts.



REPAIR 8 Page 206 Nov 10/2007



- I. Remove the nicks, scratches, gouges, burrs, and sharp edges from the repair parts and the bare surfaces of the skin.
- J. Apply a chemical conversion coating to the repair parts and bare surfaces of the skin. Refer to 51-20-01 for the chemical conversion coating procedures.
- K. Apply one layer of BMS 10-79, Type II or III, primer to the area of the repair. Refer to SOPM 20-44-04 for the procedures to apply the primer.
 - (1) Apply the primer to the repair parts.
 - (2) Apply the primer to the bare surfaces of the skin.

Table 201

REPAIR MATERIAL				
ITEM PART QUANTITY MATERIAL		MATERIAL		
[1]	Doubler	1	Use clad or bare 2024-T3. Refer to Table 202 for the necessary thickness of the material. The use of clad material is recommended	
[2]	Filler	1	Use clad or bare 2024-T3 that is the same thickness as the initial skin. The use clad material is recommended	
[3]	Doubler Splice	1	Use clad or bare 2024-T3. Refer to Table 202 for the necessary thickness of the material. The use of clad material is recommended	


Table	202:
IGNIC	

REPAIR PART THICKNESSES AND REPAIR FASTENER DIAMETERS FOR INITIAL SKIN THICKNESSES				
INITIAL SKIN THICKNESS (INCH)	ITEM [1] DOUBLER AND ITEM [3] DOUBLER SPLICE THICKNESSES (INCH)	REPAIR FASTENER DIAMETER (INCH)		
0.032	0.050	5/32		
0.041	0.063	5/32		

- L. Install the repair parts with BMS 5-95 sealant between the mating surfaces. Refer to 51-20-05 for the procedures to apply the sealant.
- M. Install the rivets without sealant in the repair parts and skin.
- N. Apply BMS 5-95 or BMS 5-26 sealant in the space between the filler and the edge of the skin cut. Refer 51-20-05 for the procedures to apply the sealant.
- O. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.



REPAIR 8 Page 207 Nov 10/2007



NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENER. USE (D) TO CALCULATE EDGE MARGINS AND THE DISTANCE BETWEEN FASTENERS.
- MAKE SURE THAT THERE IS A MINIMUM OF THREE ROWS OF FASTENERS AROUND THE DAMAGE.
- MAKE SURE THAT THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.

FASTENER SYMBOLS

- -I- REFERENCE FASTENER LOCATION
- + INITIAL FASTENER LOCATION. INSTALL A FASTENER THAT IS THE SAME TYPE AND DIAMETER (UP TO 1/32 INCH DIAMETER OVERSIZE) AS THE INITIAL FASTENER.
- ➡ REPAIR FASTENER LOCATION. INSTALL A BACR15FT5D() SOLID RIVET. REFER TO SRM 51-40-00 THROUGH 51-40-06 FOR THE FASTENER DATA.

Vertical Stabilizer Inspar Skin Flush Repair with Spliced Doubler Between Ribs - Fin Stations 196.663 through 343.863


Figure 203 (Sheet 1 of 2)



REPAIR 8 Page 208 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



Vertical Stabilizer Inspar Skin Flush Repair with Spliced Doubler Between Ribs - Fin Stations 196.663 through 343.863 Figure 203 (Sheet 2 of 2)



REPAIR 8 Page 209 Nov 01/2003

D634A210



REPAIR 9 - VERTICAL STABILIZER TRAILING EDGE AND CLOSEOUT PANELS

1. Applicability

- A. Repair 9 is applicable to damage to the vertical stabilizer trailing edge and closeout panels shown in Vertical Stabilizer Trailing Edge and Closeout Panel Locations, Figure 201/REPAIR 9. These panels are made of Glass Fiber Reinforced Plastic (GFRP) and Carbon Fiber Reinforced Plastic (CFRP).
- B. Repair 9 is applicable to damage that is more than the limits permitted in Allowable Damage 3. Refer to Allowable Damage 3 for the type and size of damage that is permitted.

2. General


- A. Repair 9 gives instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Get access to the damaged area.
 - (1) If necessary, remove the trailing edge panels as given in AMM 55-30-00/401.
 - (2) Refer to 51-40-02 for information on fastener removal.
- C. Refer to Damage Definitions, Figure 202/REPAIR 9, Details A, B, and C for the definitions of the length, width, and depth of damage.
- D. Refer to Definitions of the Facesheets, Figure 203/REPAIR 9 for the definitions of the facesheets of a honeycomb core area.
- E. Some trailing edge panels have a protective layer of Teflon film. If damage occurs, refer to AMM 51-21-81/701 for the procedures to repair the Teflon film.
- F. The conditions that follow must be true for panel areas other than the edgeband:
 - (1) The edges of the room-temperature Category B repairs must be 6 inches or more away from:
 - (a) The edge of other repairs
 - (b) The panel edge
 - (c) The edge of other damage. This does not include damage that is permitted and sealed as given in Allowable Damage 3.
 - (2) The edges of the 150°F (66°C) and 200° F(93°C) cure Category A repairs must be 3 inches or more away from:
 - (a) The edge of other repairs
 - (b) The panel edge
 - (c) The edge of other damage. This does not include damage that is permitted and sealed as given in Allowable Damage 3.
- G. Do the repair as given in Paragraph 4./REPAIR 9
- H. Put the trailing edge panels back to the initial condition, as applicable.
 - (1) Install the trailing edge panels as given in AMM 55-30-00/401, if they were removed.
 - (a) Refer to 51-40-02 for information on fastener installation.
 - (2) Make sure the aerodynamic smoothness is satisfactory or there will be a decrease in the performance of the airplane. Refer to 51-10-01.



REPAIR 9 Page 201 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



Vertical Stabilizer Trailing Edge and Closeout Panel Locations Figure 201




REPAIR 9 Page 202 Nov 01/2003




BOEING

737-800 STRUCTURAL REPAIR MANUAL







55-30-01


Page 203

Nov 01/2003

D634A210



737-800 STRUCTURAL REPAIR MANUAL



Definitions of the Facesheets Figure 203

3. <u>References</u>

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-20-05, GENERAL	Repair Sealing
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05, REPAIR GENERAL	Repair Procedures for Preimpregnated Materials
51-70-06	ROOM TEMPERATURE CURE REPAIRS
51-70-14, REPAIR GENERAL	Structures With Aluminum Coatings and Foils
55-30-01, ALLOWABLE DAMAGE 3	Vertical Stabilizer Trailing Edge Panels
AMM 51-21-81/701	Abrasion-resistant Teflon Finish - Cleaning/Painting
AMM 55-30-00/401	Vertical Stabilizer Removal/Installation

4. Repair Instructions

- A. For dents that are a maximum of 2 inches in diameter and have no fiber damage and delamination, do the steps that follow:
 - (1) Fill the dent with BMS 5-28, Type 7 potting compound.
 - (2) Apply a fiberglass patch over the potted area as given in 51-70-04.
- B. For dents that are not permitted by Paragraph 4.A./REPAIR 9 and for other damage that is not permitted by Allowable Damage 3, refer to:
 - (1) Table 201/REPAIR 9 for panel areas other than the edgeband
 - (2) Table 202/REPAIR 9 for the edgebands.
- C. Use the instructions that follow to do a Category B repair with wet layup materials at room temperature cure.
 - (1) Repair the damage as given in 51-70-06, but for each facesheet or solid laminate area that is damaged, do the steps that follow:
 - (a) Use the same number of repair plies as the number of initial plies that were removed. Refer to Definitions of the Facesheets, Figure 203/REPAIR 9 for the definition of a facesheet.



REPAIR 9 Page 204 Nov 01/2003



- (b) Add one ply (structural) of BMS 9-3, Type H-2, (or Type H-3) glass fabric that is ± 45 degrees.
- (c) Add a second ply (structural) of BMS 9-3, Type H-2 (or Type H-3) glass fabric that is 0 or 90 degrees.
- (d) You must do an inspection at the repair every 800 flight hours or sooner.

Table 201:

REPAIR DATA FOR THE 250 $^{\circ}$ F (121 $^{\circ}$ C) cure trailing edge panels for panel areas other than the edgebands				
REPAIR TYPE	CATEGORY B WET LAYUP REPAIR AS GIVEN IN SRM 51-70-06	CATEGORY A WET LAYUP REPAIR AS GIVEN IN SRM 51-70-04	CATEGORY A WET LAYUP REPAIR AS GIVEN IN SRM 51-70-04	CATEGORY A PREIMPREGNATED LAYUP REPAIR AS GIVEN IN SRM 51-70-05
REPAIR CURE TEMPERATURE	Room Temperature	150°F (66°C)	200°F (93°C)	250°F (121°C)
REPAIR SIZE	Damage that is a maximum of: - 2.0 inches in diameter - 30 percent of the smallest dimension across the panel at the damage location - One facesheet and the honeycomb core in depth	Damage that is a maximum of: - 4.0 inches in diameter - 50 percent of the smallest dimension across the panel at the damage location	Damage that is a maximum of: - 6.0 inches in diameter - 50 percent of the smallest dimension across the panel at the damage location	There are no limits on the size of the repair
REPAIR INSTRUCTIONS	Refer to Paragraph 4.C	Refer to Paragraph 4.D	Refer to Paragraph 4.E	Refer to Paragraph 4.F

Table 202:

REPAIR DATA FOR THE EDGEBANDS OF 250°F (121°C) CURE TRAILING EDGE PANELS				
REPAIR TYPE	CATEGORY B WET LAYUP REPAIR AS GIVEN IN SRM 51-70-06	CATEGORY A WET LAYUP REPAIR AS GIVEN IN SRM 51-70-04	CATEGORY A WET LAYUP REPAIR AS GIVEN IN SRM 51-70-04	CATEGORY A PREIMPREGNATED LAYUP REPAIR AS GIVEN IN SRM 51-70-05
REPAIR CURE TEMPERATURE	Room Temperature	150°F (66°C)	200°F (93°C)	250°F (121°C)
REPAIR SIZE	Damage that is a maximum of: - 15 percent of the cross- sectional area of the edgeband at the damage location - 10 percent of the length of the edgeband on the side of the damage	Damage that is a maximum of: - 15 percent of the crosssectional area of the edgeband at the damage location - 10 percent of the length of the edgeband on the side of the damage	There are no size limits on the dimensions of the repair	There are no limits on the size of the repair
REPAIR INSTRUCTIONS	Refer to Paragraph 4.C	Refer to Paragraph 4.D	Refer to Paragraph 4.E	Refer to Paragraph 4.F

- D. Use the instructions that follow to do a Category A repair with wet layup materials at 150°F (66°C) cure.
 - (1) Repair the damage as given in 51-70-04, but for each facesheet or solid laminate area that is damaged, do the steps that follow:



REPAIR 9 Page 205 Nov 01/2003



- (a) Use the same number of repair plies as the number of initial plies that were removed. Refer to Definitions of the Facesheets, Figure 203/REPAIR 9 for the definition of a facesheet.
- (b) Add one ply (structural) of BMS 9-3, Type H-2, (or Type H-3) glass fabric that is ± 45 degrees.
- (c) Add a second ply (structural) of BMS 9-3, Type H-2 (or Type H-3) glass fabric that is 0 or 90 degrees.
- E. Use the instructions that follow to do a Category A repair with wet layup materials at 200°F (93°C) cure.
 - (1) Repair the damage as given in 51-70-04, but for each facesheet or solid laminate area that is damaged, do the steps that follow:
 - (a) Use the same number of repair plies as the number of initial plies that were removed. Refer to Definitions of the Facesheets, Figure 203/REPAIR 9 for the definition of a facesheet.
 - (b) Add one ply (structural) of BMS 9-3, Type H-2, (or Type H-3) glass fabric that is ± 45 degrees.
 - (c) Add a second ply (structural) of BMS 9-3, Type H-2 (or Type H-3) glass fabric that is 0 or 90 degrees.
- F. Use the instruction that follows to do a Category A repair with preimpregnated layup materials at 250°F (121°C) cure.
 - (1) Use the same number and type of repair plies as the initial plies that were removed.



REPAIR 9 Page 206 Nov 01/2003



REPAIR 10 - VERTICAL STABILIZER ACCESS PANEL INSTALLATION WITH A ONE-PIECE DOUBLER


1. Applicability

- A. Repair 10 can be used to make an access hole in the inspar skins of the vertical stabilizer shown in Vertical Stabilizer Inspar Skin Locations, Figure 201/REPAIR 10.
- B. Repair 10 is applicable to:
 - (1) The vertical stabilizer skin from Fin WL 150.67 and above to the tip
 - (2) Locations where there is sufficient clearance to install a one-piece doubler.



BOEING®

737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS ALMOST THE SAME

Vertical Stabilizer Inspar Skin Locations Figure 201



REPAIR 10 Page 202 Nov 01/2003

D634A210




2. General

- A. Repair 10 is a Category A repair. Refer to 51-00-06 for the definitions of the different categories of repairs.
- B. The repair that follows is an alternative to Repair 10:
 - (1) Repair 11 is an access panel installation with a two-piece doubler for locations where there is not sufficient clearance to install a one-piece doubler.
- C. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes.
 - (2) The conditions for aerodynamic smoothness shown in Vertical Stabilizer Inspar Skins -Aerodynamic Limits of Repairs with Protruding Head Fasteners, Figure 202/REPAIR 10 must be kept.



BOEING®

737-800 STRUCTURAL REPAIR MANUAL



Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 1 of 3)




REPAIR 10 Page 204 Nov 01/2003



BOEING®

737-800 STRUCTURAL REPAIR MANUAL



 $B_1 + B_2 + B_3 + B_4 = A$ MAXIMUM OF $\frac{H}{4} = 68.5$ INCHES MAXIMUM

NOTES

1 ONLY ONE REPAIR IS PERMITTED ACROSS THE AIRFLOW. A SECOND REPAIR DOWNSTREAM IS NOT PERMITTED.

В

Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 2 of 3)



REPAIR 10 Page 205 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL




Figure 202 (Sheet 3 of 3)



REPAIR 10 Page 206 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-40-05	FASTENER HOLE SIZES
51-40-06, GENERAL	Fastener Edge Margins
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-44-01	Application of Special Purpose Coatings and Finishes
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Repair Instructions

A. Cut the hole in the skin.

- (1) Make the cut in the shape shown in Vertical Stabilizer Access Panel Installation, Figure 203/REPAIR 10.
- (2) Refer to 51-10-02 for the procedures to cut the skin.
- B. Remove the fasteners from the rib chords as necessary.
 - (1) Refer to 51-40-02.
- C. Make the repair parts. Refer to Table 201/REPAIR 10.
- D. Assemble the part [2] doubler and the part [3] shim as shown in Vertical Stabilizer Access Panel Installation, Figure 203/REPAIR 10.
- E. Drill the fastener holes that go through the skin, rib chords, the part [2] doubler, and the part [3] shim. Refer to 51-40-05 for the fastener hole dimensions.
- F. Disassemble the repair parts.
- G. Remove the nicks, scratches, gouges, and burrs from the initial parts and from the part [2] doubler and the part [3] shim.

REPAIR MATERIAL				
ITEM	PART	QUANTITY	MATERIAL	
[1]	Cover Plate	1	Use bare or clad 2024-T3 that is 0.070 inch thick	
[2]	Doubler	1	Use bare or clad 2024-T3 that is 0.190 inch thick	
[3]	Shim	1	Use bare or clad 2024-T3 that is 0.030 inch thick	

Table	201	2
-------	-----	---

- H. Apply a chemical conversion coating to the bare surfaces of the initial parts and to the part [2] doubler and the part [3] shim. Refer to 51-20-01.
- I. Apply one layer of BMS 10-79, Type II or III, primer to the bare surfaces of the initial parts and to the part [2] doubler and the part [3] shim. Refer to SOPM 20-44-04.



REPAIR 10 Page 207 Nov 10/2007




- J. Install the part [2] doubler and the part [3] shim.
 - (1) Apply BMS 5-95 sealant to the mating surfaces. Refer to 51-20-05.
 - (2) Install the rivets without sealant.
 - (3) If you use hex drive bolts, install the fasteners wet with BMS 5-95 sealant.
- K. Put the part [1] cover plate in position as shown in Vertical Stabilizer Access Panel Installation, Figure 203/REPAIR 10.
- L. Drill the 0.190 to 0.199 inch diameter holes for the nutplates as shown in Vertical Stabilizer Access Panel Installation, Figure 203/REPAIR 10.
- M. Remove part [1].
- N. Put the nutplates in position on the part [2] doubler and drill the holes for the rivets.
- O. Remove the nicks, scratches, gouges, and burrs from the part [1] cover plate, the part [2] doubler, and the part [3] shim.
- P. Apply a chemical conversion coating to the part [1] cover plate and the bare surfaces of the part [2] doubler and the part [3] shim. Refer to 51-20-01.
- Q. Apply one layer of BMS 10-79, Type II or III, primer to the part [1] cover plate and the bare surfaces of the part [2] doubler and the part [3] shim. Refer to SOPM 20-44-04.
- R. Install the nutplates on the part [2] doubler.
 - (1) Install the rivets without sealant.
- S. Apply BMS 10-86, Type I white abrasion resistant coating to the mating surfaces of the part [1] cover plate and the part [2] doubler. Refer to SOPM 20-44-01.
- T. Install the part [1] cover plate.
 - (1) Apply BMS 5-95 sealant to the mating surfaces. Refer to 51-20-05.
 - (2) Install the fasteners wet with BMS 5-95 sealant.
 - (3) Put BMS 5-95 sealant into the space between the skin and the part [1] cover plate.
- U. Apply the decorative finish to the repair area if necessary. Refer to AMM PAGEBLOCK 51-21-99/701.



REPAIR 10 Page 208 Nov 10/2007

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



NOTES

USE THE FASTENER SPACING AS FOLLOWS: - 0.80 INCH FOR FIN WL 150.67 TO THE TIP

> Vertical Stabilizer Access Panel Installation Figure 203 (Sheet 1 of 2)




REPAIR 10 Page 209 Nov 01/2003

D634A210

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



A-A

FASTENER SYMBOLS

- + INITIAL FASTENER LOCATION. INSTALL A FASTENER THAT IS THE SAME TYPE AND DIAMETER AS THE INITIAL FASTENER. YOU CAN INSTALL A FASTENER THAT IS UP TO 1/32 INCH DIAMETER OVERSIZE.
- + REPAIR FASTENER LOCATION. INSTALL A BACB30VT5K HEX DRIVE BOLT.
- REPAIR FASTENER LOCATION. INSTALL BACN10JR03CFM NUTPLATE WITH BACR15BA3D RIVETS. INSTALL A BACB30EL3-() BOLT TO ATTACH THE PART [1] COVER PLATE.

Vertical Stabilizer Access Panel Installation Figure 203 (Sheet 2 of 2)



REPAIR 10 Page 210 Nov 01/2003

D634A210



REPAIR 11 - VERTICAL STABILIZER ACCESS PANEL INSTALLATION WITH A TWO-PIECE DOUBLER

1. Applicability

- A. Repair 11 can be used to make an access hole in the inspar skins of the vertical stabilizer shown in Vertical Stabilizer Inspar Skin Locations, Figure 201/REPAIR 11.
- B. Repair 11 is applicable to:
 - (1) The vertical stabilizer skin from Fin WL 150.67 and above to the tip
 - (2) Locations where there is not sufficient clearance to install a one-piece part [2] doubler.

2. General


- A. Repair 11 is a Category A repair. Refer to 51-00-06 for the definitions of the different categories of repairs.
- B. The repair that follows is an alternative to Repair 11:
 - (1) Repair 10 is an access panel installation for locations where there is sufficient clearance to install a one-piece doubler.
- C. Make sure the aerodynamic smoothness is satisfactory and not more than the limits given in 51-10-01. If the aerodynamic smoothness is not satisfactory, there will be a decrease in the performance of the aircraft.
 - (1) The conditions for aerodynamic smoothness must be kept for the area around or upstream of the feel system pitot probes.
 - (2) The conditions for aerodynamic smoothness shown in Vertical Stabilizer Inspar Skins -Aerodynamic Limits of Repairs with Protruding Head Fasteners, Figure 202/REPAIR 11 must be kept.



REPAIR 11 Page 201 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



LEFT SIDE IS SHOWN, RIGHT SIDE IS ALMOST THE SAME


Vertical Stabilizer Inspar Skin Locations Figure 201



REPAIR 11 Page 202 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL




Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 1 of 3)



REPAIR 11 Page 203 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



 $B_1 + B_2 + B_3 + B_4 = A$ MAXIMUM OF $\frac{H}{4} = 68.5$ INCHES MAXIMUM

NOTES

1 ONLY ONE REPAIR IS PERMITTED ACROSS THE AIRFLOW. A SECOND REPAIR DOWNSTREAM IS NOT PERMITTED.

В

Vertical Stabilizer Inspar Skins - Aerodynamic Limits of Repairs with Protruding Head Fasteners Figure 202 (Sheet 2 of 3)



REPAIR 11 Page 204 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL




Figure 202 (Sheet 3 of 3)



REPAIR 11 Page 205 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-40-05	FASTENER HOLE SIZES
51-40-06, GENERAL	Fastener Edge Margins
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-44-01	Application of Special Purpose Coatings and Finishes
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Repair Instructions

A. Cut the hole in the skin.

- (1) Cut the hole in the shape shown in Vertical Stabilizer Access Panel Installation, Figure 203/REPAIR 11.
- (2) Refer to 51-10-02 for the procedures to cut the skin.
- B. Remove the fasteners from the rib chords as necessary.
 - (1) Refer to 51-40-02.
- C. Make the repair parts. Refer to Table 201/REPAIR 11.
- D. Assemble the part [2] doublers and the part [3] shims as shown in Vertical Stabilizer Access Panel Installation, Figure 203/REPAIR 11.
- E. Drill the fastener holes that go through the skin, the rib chords, the part [2] doublers, and the part [3] shims. Refer to 51-40-05 for the fastener hole dimensions.
- F. Assemble the part [4] splice plates as shown in Vertical Stabilizer Access Panel Installation, Figure 203/REPAIR 11.

	REPAIR MATERIAL				
ITEM	PART	QUANTITY	MATERIAL		
[1]	Cover Plate	1	Use bare or clad 2024-T3 that is 0.070 inch thick		
[2]	Doubler	2	Use bare or clad 2024-T3 that is 0.190 inch thick		
[3]	Shim	2	Use bare or clad 2024-T3 that is 0.030 inch thick		
[4]	Splice Plate	2	Use bare or clad 2024-T3 that is 0.190 inch thick		

Table 201:

- G. Drill the fastener holes that go through the skin, the part [2] doublers, and the part [4] splice plates. Refer to 51-40-05 for the fastener hole dimensions.
- H. Disassemble the repair parts.



REPAIR 11 Page 206 Nov 10/2007




- I. Remove the nicks, scratches, gouges, and burrs from the initial parts and from the part [2] doublers, the part [3] shims, and the part [4] splice plates.
- J. Apply a chemical conversion coating to the bare surfaces of the initial parts and to the part [2] doublers, the part [3] shims, and the part [4] splice plates. Refer to 51-20-01.
- K. Apply one layer of BMS 10-79, Type II or III, primer to the bare surfaces of the initial parts and to the part [2] doubler, the part [3] shims, and the part [4] splice plate. Refer to SOPM 20-44-04.
- L. Install the part [2] doubler, the part [3] shims, and the part [4] splice plate.
 - (1) Apply BMS 5-95 sealant to the mating surfaces. Refer to 51-20-05.
 - (2) Install the rivets without sealant.
 - (3) If you use hex drive bolts, install the fasteners wet with BMS 5-95 sealant.
- M. Put the part [1] cover plate in position as shown in Vertical Stabilizer Access Panel Installation, Figure 203/REPAIR 11.
- N. Drill the 0.190 to 0.199 inch diameter holes for the nutplates as shown in Vertical Stabilizer Access Panel Installation, Figure 203/REPAIR 11.
- O. Remove the part [1] cover plate.
- P. Put the nutplates in position on the part [2] doubler and drill the holes for the rivets.
- Q. Remove the nicks, scratches, gouges, and burrs from the repair parts.
- R. Apply a chemical conversion coating to the part [1] cover plate and the bare surfaces of the part [2] doublers, the part [3] shims, and the part [4] splice plates. Refer to 51-20-01.
- S. Apply one layer of BMS 10-79, Type II or III, primer to part [1] cover plate and the bare surfaces of the part [2] doublers, the part [3] shims, and the part [4] splice plates. Refer to SOPM 20-44-04.
- T. Install the nutplates on the part [2] doubler.
 - (1) Install the rivets without sealant.
- U. Apply BMS 10-86, Type I white abrasion resistant coating to the mating surfaces of the part [1] cover plate and the part [2] doublers. Refer to SOPM 20-44-01.
- V. Install the part [1] cover plate.
 - (1) Apply BMS 5-95 sealant to the mating surfaces. Refer to 51-20-05.
 - (2) Install the fasteners wet with BMS 5-95 sealant.
 - (3) Put BMS 5-95 sealant into the space between the skin and the part [1] cover plate.
- W. Apply the decorative finish to the repair area if necessary. Refer to AMM PAGEBLOCK 51-21-99/701.



REPAIR 11 Page 207 Nov 10/2007

BOEING®

737-800 STRUCTURAL REPAIR MANUAL



NOTES

1 USE THE FASTENER SPACING AS FOLLOWS: - 0.80 INCH FOR FIN WL 150.67 TO THE TIP


> Vertical Stabilizer Access Panel Installation Figure 203 (Sheet 1 of 2)

> > 55-30-01


REPAIR 11 Page 208 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



A-A



B-B

FASTENER SYMBOLS

- H INITIAL FASTENER LOCATION. INSTALL A FASTENER THAT IS THE SAME TYPE AND DIAMETER AS THE INITIAL FASTENER. YOU CAN INSTALL A FASTENER THAT IS UP TO 1/32 INCH DIAMETER OVERSIZE.
- + REPAIR FASTENER LOCATION. INSTALL A BACB30VT5K HEX DRIVE BOLT.
- ➡ REPAIR FASTENER LOCATION. INSTALL BACN10JR03CFM NUTPLATE WITH BACR15BA3D RIVETS. INSTALL A BACB30EL3-() BOLT TO ATTACH THE PART [1] COVER PLATE.

Vertical Stabilizer Access Panel Installation Figure 203 (Sheet 2 of 2)



REPAIR 11 Page 209 Nov 01/2003



REPAIR 12 - DORSAL FIN SKIN

1. Applicability

- A. Repair 12 is applicable to the dorsal fin skins made of Glass Fiber Reinforced Plastic (GFRP) and non-metallic honeycomb core shown in Dorsal Fin Skin Location, Figure 201/REPAIR 12.
- B. Repair 12 is applicable to damage that is more than the limits permitted in Allowable Damage 5. Refer to Allowable Damage 2 for the type and size of damage that is permitted.

2. General

- A. Repair 12 gives the instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Get access to the damaged area.
 - (1) If necessary, remove the dorsal fin skin. Refer to AMM 55-32-11/401.
- C. Do an inspection of the damaged area to find the dimensions of the damage.
 - (1) Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 for the inspection procedures.

NOTE: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.


- (2) For the honeycomb core areas, the tap test is an alternative procedure to an instrumented NDT procedure.
- (3) Refer to Damage Definitions, Figure 202/REPAIR 12, for the definitions of the length, width, and depth of damage.
- D. Do the repair as given in Paragraph 4./REPAIR 12
- E. Make sure the aerodynamic smoothness is satisfactory or there will be a decrease in the performance of the airplane. Refer to 51-10-01.
- F. Put the dorsal fin skin back to the initial condition, as applicable.
 - (1) Install the skin if it was removed. Refer to AMM 55-32-11/401.



REPAIR 12 Page 201 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL






REPAIR 12 Page 202 Nov 01/2003




737-800 STRUCTURAL REPAIR MANUAL



DEFINITIONS OF THE SIZES FOR NICK, GOUGE, AND SCRATCH DAMAGE

А





REPAIR 12 Page 203 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02, GENERAL	Inspection and Removal of Damage
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05, REPAIR GENERAL	Repair Procedures for Preimpregnated Materials
51-70-06, REPAIR GENERAL	Room Temperature Cure Repairs With Wet Layup Materials For Glass Fabric Reinforced Plastic Solid Laminates and Honeycomb Core Panels
51-70-14	STRUCTURES WITH ALUMINUM COATINGS AND FOILS
AMM 51-21	INTERIOR AND EXTERIOR FINISHES
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 55-32-11/401	Removal and Installation of the Dorsal Fin
737 NDT Part 1, 51-01-01	Inspection of Repairs to Composite Structure
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Repair Instructions

- A. If a dent is 2 inches (50.80 mm) in diameter or less, and has no fiber damage or delamination, then fill the dent with potting compound and apply a fiberglass patch as given in Repair 14 of 51-70-04.
- B. If Paragraph 4.A./REPAIR 12 is not applicable, then refer to:
 - (1) Table 201/REPAIR 12 for the repair data that is applicable to damage in the honeycomb sandwich areas
 - (2) Table 202/REPAIR 12 for the repair data that is applicable to damage in the edgeband or solid laminate areas.
- C. For repairs made with wet layup materials, do as follows, as applicable:
 - (1) Use one repair ply of fabric for each initial ply that was damaged.
 - (2) Add two structural plies of fabric for each facesheet that is repaired. Put one structural ply at ± 45 degrees to the core ribbon direction and the other at 0 or 90 degrees. Refer to Identification 6 for the ply materials and ply direction.
 - **NOTE**: Repair plies or added plies are not necessary in the repair of delamination at an edge if the delamination is a minimum of 2D (D = the fastener diameter) away from a fastener hole.
 - (3) Examine Category B repairs after each interval of 800 flight hours or more frequently. Refer to 737 NDT Part 1, 51-01-01 for the inspection procedures. If deterioration is found, then they must be replaced with Category A repairs.
 - **NOTE**: Other inspection methods, equivalent to the methods used by Boeing, that have been examined and found to be satisfactory by the operator can be used.
- D. For repairs made with preimpregnated layup materials, use the same number of repair plies as the number of initial plies that were damaged.



REPAIR 12 Page 204 Mar 10/2006



E. For repairs made to parts that have BMS 8-278 aluminum coated glass fabric, BMS 8-289 bonded aluminum foil, or BMS 8-336 expanded aluminum mesh, refer to 51-70-14.

REPAIR DATA	FOR THE 250°F (121°C) CL	IRE DORSAL FIN SKIN PAI	NELS IN THE HONEYCOME	B CORE AREAS
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREPREG LAYUP REPAIR
REPAIR CURE TEMPERATURE	Room Temperature	150°F (66°C)	200°F (93°C)	250°F (121°C)
REPAIR SIZE	Contact The Boeing Company	Damage that is a maximum of: - 3.0 inches (76.2 mm) in diameter - One repair for each 144 square inches (929.03 cm ²) - 2.0 inches (50.8 mm) minimum clearance	Damage that is a maximum of: - 6.0 inches (152.4 mm) in diameter - One repair for each 144 square inches (929.03 cm ²) - 2.0 inches (50.8 mm) minimum clearance	There are no limits on the dimensions of the repair
		from: - other repair - fastener holes - panel edges	from: - other repairs - fastener holes - panel edges	
REPAIR PROCEDURES		SRM 51-70-04 and Paragraph 4.D	SRM 51-70-04 and Paragraph 4.E	SRM 51-70-05 and Paragraph 4.F

Table 201:

Table 202:


REPAIR DATA FOI	REPAIR DATA FOR THE 250°F (121°C) CURE EDGEBAND AND SOLID LAMINATE AREAS OF THE DORSAL FIN SKIN				
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREPREG LAYUP REPAIR	
REPAIR CURE TEMPERATURE	Room Temperature	150°F (66°C)	200°F (93°C)	250°F (121°C)	
REPAIR SIZE	Contact The Boeing Company	Damage that is a maximum of: - 3.0 inches (76.2 mm) across the largest dimension of the damage - 10 percent of the edgeband length on the damage side	Damage that is a maximum of - 6.0 inches (152.4 mm) across the largest dimension of the damage - 30 percent of the edgeband length on the damage side	There are no limits on the dimensions of the repair	
REPAIR PROCEDURES		SRM 51-70-04 and Paragraph 4.D	SRM 51-70-04 and Paragraph 4.E	SRM 51-70-05 and Paragraph 4.F	

REPAIR 12 Page 205 Nov 10/2006

55-30-01



IDENTIFICATION 1 - VERTICAL STABILIZER LEADING EDGE RIBS



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.


Vertical Stabilizer Leading Edge Rib Locations Figure 1

т.			-	
та	D	е		
		-		٠

	REFERENCE DRAWINGS			
DRAWING NUMBER	TITLE			
001A7001	Section 70 Vertical Fin - Product Collector			
176A0001	Leading Edge and Miscellaneous Functional Collector - Vertical Fin			
176A1001	Removable Leading Edge Assembly/Installation Vertical Fin			
176A1201	Rib Assembly - Leading Edge Station 98.030 Vertical Fin			
176A1202	Rib Assembly - Leading Edge Station 108.150 Vertical Fin			
176A3001	Fixed Leading Edge Installation - Vertical Fin			
176A3002	Rib Assembly - Body Station 1007.65, Fixed Leading Edge			



IDENTIFICATION 1 Page 1 Jul 10/2004



Vertical Stabilizer Leading Edge Rib Identification Figure 2



D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



Table 2:


	LIST OF MATERIALS FOR FIGURE 2			
ITEM	ITEM DESCRIPTION T ^{*[1]} MATERIAL EFFECTIVITY			
[1]	Rib, Removable LE	0.040 (1.016)	2024-T42 clad sheet as given in QQ-A-250/5	
[2]	Rib, Removable LE		Glass Fiber Reinforced Plastic (GFRP) laminate as given in BMS 8-79, Style 1581, Class III, Grade A	
[3]	Rib Assembly Web Chord	0.050 (1.270)	2024-T42 clad sheet as given in QQ-A-250/5 BAC1506-1950 7075-T62 extrusion as given in QQ- A-200/11	
[4]	Rib, Fixed LE	0.040 (1.016)	2024-T42 high formability clad sheet as given in BMS 7-305	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





IDENTIFICATION 2 - VERTICAL STABILIZER INSPAR RIBS



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.


Vertical Stabilizer Inspar Rib Locations Figure 1

Table 1:

	REFERENCE DRAWINGS			
DRAWING NUMBER	TITLE			
001A7001	Section 70 Vertical Fin - Product Collector			
172A0001	Torque Box Functional Collector - Vertical Fin			
172A3101	Closure Rib Assembly/Installation-Lower, Vertical Fin			
172A3202	Rib Installation-Fin WL 274.000, Vertical Fin			
175A1307	Inspar and T.E. Hinge Rib Installation-Rudder Station 276.24			



IDENTIFICATION 2 Page 1 Jul 10/2004



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Vertical Stabilizer Inspar Rib Identification Figure 2



IDENTIFICATION 2 Page 2 Mar 10/2004



Table 2:

			MATERIALS FOR FIGURE 2			
ITEM	ITEM DESCRIPTION T ^{*[1]} MATERIAL EFFECTIVITY					
[1]	Strap (2)	0.300 (7.620)	7075-T7351 plate as given in QQ-A-250/12			
[2]	Closure Rib Assembly-					
	Primary Chord (2)		BAC1506-4289 2024-T3511 extrusion as given in QQ-A-200/3			
	Failsafe Chord (2)		BAC1506-1785 7075-T6511 extrusion as given in QQ-A-200/11			
	Stiffener		BAC1506-4288 7075-T6511 extrusion as given in QQ-A-200/11			
	Web	0.200 (5.080)	7075-T6 as given in QQ-A-250/12. Refer to Figure 3 for the chem-milled thicknesses			
	Doubler	0.063 (1.600)	7075-T6 as given in QQ-A-250/12			
	Doubler (2)	0.100 (2.540)	7075-T6 as given in QQ-A-250/12			
[3]	Rib		7075-T7351 plate as given in QQ-A-250/12. Refer to the production drawing for the machined thicknesses. Refer to Figure 4 for an example of a typical machined rib			
[4]	Rib Assembly					
	Rib		7075-T7351 plate as given in QQ-A-250/12. Refer to the production drawing for the machined thicknesses. Refer to Figure 5 for an example of a typical machined rib			
	Doubler	0.050 (1.270)	2024-T3 clad as given in QQ-A-250/5			
[5]	Rib Assembly					
	Rib		7075 T7351 plate as given in QQ-A-250/12. Refer to the production drawing for the machined thicknesses. Refer to Figure 6 for an example of a typical machined rib			
	Splice Strap	0.063 (1.600)	2024-T3 clad as given in QQ-A-250/5			
[6]	Rib Assembly					
	Rib		7075-T7351 plate as given in QQ-A-250/12. Refer to the production drawing for the machined thicknesses. Refer to Figure 7 for an example of a typical machined rib			
	Doubler	0.040 (1.016)	2024-T3 clad as given in QQ-A-250/5			
[7]	Fitting Assembly					
	Stiffener		BAC1506-1844 7075-T6511 as given in QQ-A-200/11			
	Stiffener		BAC1503-1509 7075-T6511 as given in QQ-A-200/11			
	Fitting		7050-T7451 plate as given in BMS 7-323, Type I			
[8]	Angle	0.063 (1.600)	7075-T62 clad as given in QQ-A-250/13			

IDENTIFICATION 2 Page 3 Nov 01/2003

D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details




	LIST OF MATERIALS FOR FIGURE 2			
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[9]	Rib Assembly			
	Strap (2)		Glass Fiber Reinforced Plastic (GFRP) as given in BMS 8-79, Style 1581 or 7781, Class III	
	Chord (2)		Glass Fiber Reinforced Plastic (GFRP) as given in BMS 8-79, Style 1581 or 7781, Class III (Optional: BAC 5317-2, die mold, minimum 50 psi, cured at $265^{\circ}F \pm 10^{\circ}F$ for a minimum of 60 minutes)	
	Web	0.040 (1.016)	2024-T3 clad sheet as given in QQ-A-250/5	
	Plate	0.040 (1.016)	2024-T42 clad sheet as given in QQ-A-250/5	
	Chord (2)		BAC1514-3145 7075-T62 extrusion as given in QQ- A-200/11	
	Stiffener (3)		BAC1503-470 7075-T62 extrusion as given in QQ-A- 200/11	
	Stiffener		AND10136-1301 7075-T6511 extrusion as given in QQ-A-200/11	
	Angle	0.063 (1.600)	7075-T62 clad sheet as given in QQ-A-250/13	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





737-800 STRUCTURAL REPAIR MANUAL



NOTE: ALL DIMENSIONS ARE IN INCHES.

Chem-Milled Areas of Figure 2, Item [2] Figure 3




Page 5 Mar 10/2004

D634A210

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL



TYPICAL MACHINED RIB

Machined Areas for Figure 2, Item [3] Figure 4




Page 6

D634A210 BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details

BOEING®

737-800 STRUCTURAL REPAIR MANUAL




TYPICAL MACHINED RIB

Machined Areas for Figure 2, Item [4] Figure 5





737-800 STRUCTURAL REPAIR MANUAL



TYPICAL MACHINED RIB


Machined Areas for Figure 2, Item [5] Figure 6



Page 8



737-800 STRUCTURAL REPAIR MANUAL



TYPICAL MACHINED RIB

Machined Areas for Figure 2, Item [6] Figure 7




Page 9

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



IDENTIFICATION 3 - VERTICAL STABILIZER TRAILING EDGE RIBS



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Vertical Stabilizer Trailing Edge Rib Locations Figure 1

Table 1:


	REFERENCE DRAWINGS		
DRAWING NUMBER	TITLE		
001A7001	Section 70 Vertical Fin - Product Collector		
170A1540	Vertical Fin Centerline Diagram		
175A0001	Trailing Edge Functional Collector - Vertical Fin		
175A1201	Trailing Edge Hinge Rib Assembly/Installation-Rudder Station 6.96		
175A1204	Trailing Edge Hinge Rib Installation - Rudder Station 56.48		
175A1207	Trailing Edge Hinge Rib Assembly/Installation-Rudder Station 66.42		

IDENTIFICATION 3 Page 1 Mar 10/2004



REFERENCE DRAWINGS					
DRAWING NUMBER	TITLE				
175A1210	Trailing Edge Hinge Rib Installation - Rudder Station 74.80				
175A1213	Trailing Edge Hinge Rib Assembly/Installation-Rudder Station 129.74				
175A1215	Trailing Edge Hinge Rib Installation - Rudder Station 257.93				
175A1301	Trailing Edge Rib Installation - Rudder Station 184.67				
175A1304	Trailing Edge Hinge Rib Installation - Rudder Station 239.61				
175A1310	Trailing Edge Rib Installation - Rudder Station 212.15				
175A1403	Trailing Edge Rib Assembly/Installation - Fin WL 147.09				
175A1404	Trailing Edge Rib Assembly/Installation - Fin WL 155.25				
175A1410	Trailing Edge Rib Installation - Rudder Station 102.27				





NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Vertical Stabilizer Trailing Edge Rib Identification Figure 2



IDENTIFICATION 3 Page 3 Mar 10/2004



Table 2:


	LIST OF MATERIALS FOR FIGURE 2					
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY		
[1]	Rib Assembly					
	Angle (2)		7050-T7451 plate as given in AMS 4050 (Grain direction controlled part). Refer to the production drawings for the grain direction			
	Chord (2)		7050-T7451 plate as given in AMS 4050 (Grain direction controlled part). Refer to the production drawings for the grain direction			
	Stiffener		BAC1503-100593 7075-T6511 extrusion as given in QQ-A-200/11			
	Web	0.040 (1.016)	2024-T3 clad as given in QQ-A-250/5			
[2]	Rib Assembly					
	Fitting		7050-T7451 plate as given in BMS 7-323, Type I (Grain direction controlled part). Refer to the production drawings for the grain direction			
	Channel (2)	0.040 (1.016)	2024-T3 clad sheet as given in QQ-A-250/5			
	Support (3)	0.040 (1.016)	2024-T3 clad sheet as given in QQ-A-250/5			
[3]	Rib Assembly					
	Fitting		7050-T7451 plate as given in BMS 7-323, Type I (Grain direction controlled part). Refer to the production drawings for the grain direction			
	Pan	0.032 (0.813)	2024-T3 clad sheet as given in QQ-A-250/5			
[4]	Rib Assembly					
	Fitting		7050-T7451 plate as given in BMS 7-323, Type I (Grain direction controlled part). Refer to the production drawings for the grain direction			
[5]	Rib Assembly					
	Fitting		7050-T7451 plate as given in AMS 4050 (Grain direction controlled part). Refer to the production drawings for the grain direction			
[6]	Rib Assembly					
	Fitting		7050-T7451 plate as given in AMS 4050 (Grain direction controlled part). Refer to the production drawings for the grain direction			
	Support	0.063 (1.600)	2024-T42 clad as given in QQ-A-250/5			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





IDENTIFICATION 4 - DORSAL FIN STRUCTURE



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Dorsal Fin Structure Location Figure 1


Table 1:

REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE			
174A0101	Dorsal Fin Installation			





737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Dorsal Fin Structure Identification Figure 2



Page 2

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



Table 2:

	LIST OF MATERIALS FOR FIGURE 2					
ITEM	DESCRIPTION	T*[1]	MATERIAL	EFFECTIVITY		
[1]	Seal Retainer	0.025 (0.63)	2024-T42 clad sheet as given in QQ-A-250/5			
[2]	Rib - BS 1005.7	0.050 (1.27)	2024-T42 clad sheet as given in QQ-A-250/5			
[3]	Stiffener		AND10134-0702 7075-T73511 extrusion			
[4]	Gusset	0.040 (1.02)	2024-T42 sheet as given in QQ-A-250/5			
[5]	Rib - BS 986.50	0.050 (1.27)	2024-T42 clad sheet as given in QQ-A-250/5			
[6]	Rib - BS 966.70	0.050 (1.27)	2024-T42 clad sheet as given in QQ-A-250/5			
[7]	Rib - BS 947.50	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5			
[8]	Drag Load Fitting	1.40 (36.6)	7075-T7451 machined plate as given in AMS 4050			
[9]	Rib - BS 926.70	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5			
[10]	Rib - BS 906.70	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5			
[11]	Rib - BS 867	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5			
[12]	Forward Leading Edge Cap		BAC1513-432 7075-T73511 extrusion			
[13]	Aft Leading Edge Cap		7050-T7451 plate as given in BMS 7-323, Type 1			
[14]	Attach Clip		BAC1503-100605 7075-T73511 extrusion as given in QQ-A-200/11			
[15]	Attach Clip		BAC1503-100698 7075-T73511 extrusion as given in QQ-A-200/11			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).




Page 3



ALLOWABLE DAMAGE 2 - DORSAL FIN STRUCTURE


1. Applicability


A. This subject gives the allowable damage limits for the dorsal fin structure shown in Dorsal Fin Structure Location, Figure 101/ALLOWABLE DAMAGE 2.



Dorsal Fin Structure Location Figure 101 (Sheet 1 of 3)







BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details



2. General

- A. Remove the damaged material as necessary.
 - (1) Refer to 51-10-02 for the procedures.
 - (2) Refer to 51-30-03 for sources of non-metallic materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for sources of equipment and tools you can use to remove the damage.
- B. After you remove the damage, do as follows:
 - (1) Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to 51-20-01.
 - (2) Apply two layers of BMS 10-79, Type III primer to the bare surfaces of the reworked areas. Refer to SOPM 20-44-04.

3. References

Reference	Title
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05, GENERAL	Repair Sealing
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-40-05, GENERAL	Fastener Hole Sizes
51-40-06, GENERAL	Fastener Edge Margins
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Allowable Damage Limits

- A. Ribs and Gussets
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Details, Figure 102/ALLOWABLE DAMAGE 2, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Details, Figure 102/ALLOWABLE DAMAGE 2, Details A, B, C, D, E, and F.
 - (3) Dents are permitted as shown in Allowable Damage Details, Figure 102/ALLOWABLE DAMAGE 2, Detail G.
 - (4) Holes and Punctures:
 - (a) Damage is permitted in the free flange as shown in Allowable Damage Details, Figure 102/ALLOWABLE DAMAGE 2, Detail I.
 - (b) Do the steps that follow to remove the damage in the web:
 - 1) Drill out the damage to a maximum diameter of 0.25 inch (6.35 mm)
 - 2) The damage must be a minimum of 1.0 inch (25.4 mm) away from a fastener hole, material edge, or other damage.
 - 3) Install a 2117-T3 or 2117-T4 aluminum protruding head rivet. Install the rivet without sealant.






- B. Stiffeners, Leading Edge Caps, and Drag Fittings
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Details, Figure 102/ALLOWABLE DAMAGE 2, Details A, B, H, and J.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Details, Figure 102/ALLOWABLE DAMAGE 2, Details A, B, D, E, H, and J.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.






737-800 STRUCTURAL REPAIR MANUAL







BOEING

737-800 STRUCTURAL REPAIR MANUAL








B-B

Allowable Damage Details Figure 102 (Sheet 4 of 5)

> ALLOWABLE DAMAGE 2 55-30-09 Page 109 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



X = WIDTH OF THE MATERIAL REMOVED = A MAXIMUM OF 10 PERCENT OF THE WIDTH OF THE FLANGE

REMOVAL OF DAMAGED MATERIAL AT AN EDGE

Allowable Damage Details Figure 102 (Sheet 5 of 5)






REPAIR 2 - DORSAL FIN STRUCTURE

1. Applicability

A. Repair 2 is applicable to damage to the dorsal fin structure shown in 201.



- REFER TO SRM 51-70-12 FOR THE TYPICAL EXTRUDED SECTION REPAIRS FOR THE ANGLES OF THE RIB ASSEMBLIES.
- YOU CAN USE THESE TYPICAL REPAIRS WHERE THEY ARE APPLICABLE IF:
 - SUFFICIENT SPACE IS AVAILABLE FOR THE INSTALLATION OF THE REPAIR PARTS, AND - THE REPAIR PARTS DO NOT TOUCH ADJACENT STRUCTURE.

Dorsal Fin Structure Repair Figure 201

2. General

- A. The typical repairs given in 51-70-12 can be used when applicable if:
 - (1) There is sufficient clearance with the adjacent structure for the installation of repair parts.
- B. Refer to the limits of the typical repairs given in 51-70-12 before you start a repair.



REPAIR 2 Page 201 Nov 10/2006



3. References

Reference	Title
51-70-12	EXTRUDED SECTION REPAIRS
55-30-09	VERTICAL STABILIZER RIBS
55-30-09, ALLOWABLE DAMAGE 2	Dorsal Fin Structure
55-30-09, IDENTIFICATION 4	Dorsal Fin Structure

4. Repair Instructions

A. Dorsal Fin Structure

(1) Refer to Table 201/REPAIR 2 to find the applicable repairs of the dorsal fin structure.

NOTE: If necessary, refer to 55-30-09, Identification 4 to find the material and the process that was used to make the part which you want to repair.

Table 201:


REPAIR REFERENCES FOR THE DORSAL FIN STRUCTURE		
COMPONENT	REPAIR	
Extruded Angles	Refer to SRM 51-70-12	
Ribs and Gussets	There are no repairs for these components in the Structural Repair Manual at this time.	
Leading Edge Caps	There are no repairs for these components in the Structural Repair Manual at this time. If the damage to the structure is more than the limits given in SRM 53-40-13, Allowable Damage 1, contact Boeing for a repair.	



REPAIR 2 Page 202 Nov 10/2006



IDENTIFICATION 1 - VERTICAL STABILIZER FRONT SPAR STRUCTURE




NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Vertical Stabilizer Front Spar Structure Locations Figure 1


Table 1:				
REFERENCE DRAWINGS				
DRAWING NUMBER TITLE				
001A7001	Section 70 Vertical Fin - Product Collector			
172A0001	Torque Box Functional Collector - Vertical Fin			
172A2001	Front Spar Assembly/Installation - Vertical Fin			





Vertical Stabilizer Front Spar Structure Identification Figure 2 (Sheet 1 of 2)





Vertical Stabilizer Front Spar Structure Identification Figure 2 (Sheet 2 of 2)






Table 2:

LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Web	0.090 (2.29)	7075-T6 aluminum sheet as given in QQ-A-250/12, chem-milled to different thick- nesses. Refer to Figure 3	Cum Line numbers 1 thru 4
	Web Assembly			Cum Line numbers 5 and on
	Web	0.100 (2.54)	7075-T6 aluminum sheet as given in QQ-A-250/12, chem-milled to different thick-nesses. Refer to Figure 3	
	Cover Panel (5)	0.100 (2.54)	7075-T6 aluminum sheet as given in QQ-A-250/12. Refer to Figure 3	
[2]	Web	0.063 (1.60)	7075-T6 aluminum sheet as given in QQ-A-250/12, chem-milled to different thick-nesses. Refer to Figure 4	
[3]	Web	0.040 (1.02)	7075-T6 aluminum sheet as given in QQ-A-250/12 milled to different thicknesses. Refer to Figure 5	
[4]	Stiffener		BAC1506-4406 7075-T73511 aluminum extrusion as given in QQ-A-200/11	
[5]	Stiffener		BAC1506-4407 7075-T73511 aluminum extrusion as given in QQ-A-200/11	
[6]	Stiffener		BAC1506-4408 7075-T73511 aluminum extrusion as given in QQ-A-200/11	
[7]	Stiffener		BAC1514-3266 7075-T73511 aluminum extrusion as given in QQ-A-200/11	
[8]	Stiffener		BAC1506-4410 7075-T73511 aluminum extrusion as given in QQ-A-200/11	
[9]	Stiffener		7075-T351 aluminum plate as given in QQ-A-250/12	
[10]	Chord		BAC1506-4319 7150-T77511 aluminum sheet as given in BMS 7-306	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





NOTES

- REFER TO TABLE 2 FOR THE LIST OF MATERIALS.
- ALL DIMENSIONS ARE IN INCHES.
- 1 FOR CUM LINE NUMBERS 1 THRU 4
- 2 FOR CUM LINE NUMBER 5 AND ON


Chem-Milled Areas for Figure 2, Item [1] Figure 3



Page 5



737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS. ALL DIMENSIONS ARE IN INCHES.


> Chem-Milled Areas for Figure 2, Item [2] Figure 4



Page 6

D634A210 BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details





NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS. ALL DIMENSIONS ARE IN INCHES.


> Chem-Milled Areas for Figure 2, Item [3] Figure 5



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



IDENTIFICATION 2 - VERTICAL STABILIZER REAR SPAR STRUCTURE




NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Vertical Stabilizer Rear Spar Structure Locations Figure 1

Table 1:

REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE			
001A7001	001A7001 Section 70 Vertical Fin - Product Collector			
172A1001 Rear Spar Assembly/Installation - Vertical Fin				
175A0001	Trailing Edge Functional Collector - Vertical Fin			






NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Vertical Stabilizer Rear Spar Structure Locations Figure 2 (Sheet 1 of 2)





NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Vertical Stabilizer Rear Spar Structure Locations Figure 2 (Sheet 2 of 2)





Table 2:

LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Primary Chord		BAC1506-4440 2024-T3511 extrusion as given in QQ-A-200/3	
[2]	Failsafe Chord		BAC1520-2796 7075-T6511 extrusion as given in QQ-A-200/11	
[3]	Web Assembly			
	Failsafe Fitting	0.600 (15.2)	7075-T651 plate as given in QQ-A-250/12	
	Web	0.100 (2.54)	7075-T6 sheet as given in QQ-A-250/12. Refer to Figure 3 for the chem-milled thicknesses	
[4]	Stiffener		BAC1505-100575 7075-T6511 extrusion as given in QQ-A-200/11	
[5]	Stiffener		BAC1505-100574 7075-T6511 extrusion as given in QQ-A-200/11	
[6]	Stiffener		BAC1518-585 7075-T6511 extrusion as given in QQ- A-200/11	
[7]	Stiffener		BAC1505-100876 7075-T6511 extrusion as given in QQ-A-200/11	
[8]	Stiffener		BAC1503-100854 7075-T6511 extrusion as given in QQ-A-200/11	
[9]	Stiffener		BAC1505-100570 7075-T6511 extrusion as given in QQ-A-200/11	
[10]	Stiffener		BAC1506-4435 7075-T6511 extrusion as given in QQ-A-200/11	
[11]	Stiffener		BAC1506-4436 7075-T6511 extrusion as given in QQ-A-200/11	
[12]	Stiffener		BAC1506-4434 7075-T6511 extrusion as given in QQ-A-200/11	
[13]	Stiffener		7075-T73511 extruded bar as given in QQ-A-200/11	
[14]	Stiffener		BAC1506-2401 7075-T73511 extrusion as given in QQ-A-200/11 (Optional: Make the necessary cross-section from 7075-T73511 extruded bar as given in QQ-A-200/11)	
[15]	Stiffener		BAC1506-1826 7075-T6511 extrusion as given in QQ-A-200/11	
[16]	Stiffener		BAC1505-100573 7075-T6511 extrusion as given in QQ-A-200/11	
[17]	Web Assembly			
	Web	0.025 (0.64)	7075-T6 clad sheet as given in QQ-A-250/13	
	Doubler	0.025 (0.64)	7075-T6 clad sheet as given in QQ-A-250/13	
[18]	Web Assembly			
	Web	0.032 (0.81)	7075-T6 clad sheet as given in QQ-A-250/13	
	Doubler	0.050 (1.27)	7075-T6 clad sheet as given in QQ-A-250/13	
[19]	Web Assembly			
	Web	0.040 (1.02)	7075-T6 clad sheet as given in QQ-A-250/13	


IDENTIFICATION 2 Page 4 Nov 01/2003



	LIST OF MATERIALS FOR FIGURE 2			
ITEM	DESCRIPTION	T*[1]	MATERIAL	EFFECTIVITY
	Doubler	0.050 (1.27)	7075-T6 clad sheet as given in QQ-A-250/13	
[20]	Angle	0.063 (1.60)	2024-T3 clad sheet as given in QQ-A-250/5	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS. ALL DIMENSIONS ARE IN INCHES.

> Chem-Milled Areas for Figure 2, Item [3] Figure 3



Page 6




ALLOWABLE DAMAGE 1 - VERTICAL STABILIZER FRONT SPAR

1. Applicability

A. This subject gives the allowable damage limits for the vertical stabilizer front spar shown in Vertical Stabilizer Front Spar Location, Figure 101/ALLOWABLE DAMAGE 1.











2. General

- A. Remove the damage as necessary.
 - (1) Refer to 51-10-02 for the inspection and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
- B. After you remove the damage, do the procedures that follow.
 - (1) Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to 51-20-01.
 - (2) Apply one layer of BMS 10-11, Type I, primer to the reworked areas of the stiffeners and the chords. Refer to SOPM 20-41-02.
 - (3) Apply two layers of BMS 10-11, Type I, primer to the reworked areas of the webs. Refer to SOPM 20-41-02.

3. References

Reference	Title
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-06	SHOT PEENING
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
55-30-90, ALLOWABLE DAMAGE 1	Vertical Stabilizer Fittings
SOPM 20-10-03	General - Shot Peening Procedures
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes

4. Allowable Damage Limits

- A. Chords
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A and B.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, C, E, and F.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.

WARNING: MAKE SURE THAT YOU WEAR EYE PROTECTION WHEN YOU USE THE FLAP PEEN WHEEL. IF YOU DO NOT OBEY, INJURY TO PERSONS CAN OCCUR.

- (5) Flap peen or shot peen the surfaces if you remove the damage.
 - (a) Refer to 51-20-06 for shot peen intensity and shot number.
 - (b) Refer to SOPM 20-10-03 for flap peen and shot peen procedures.
- B. Stiffeners



- (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, and F.
 - (b) The total cross-sectional area removed must not be more than the limits given in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Detail H.
- (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, C, E, and F.
 - (b) The total cross-sectional area removed must not be more than the limits given in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Detail H.
- (3) Dents are not permitted.
- (4) Holes and Punctures are not permitted.
- C. Webs
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A and B.
 - (b) Damage is permitted as shown in Vertical Stabilizer Front Spar Bay Location, Figure 103/ALLOWABLE DAMAGE 1 and Table 101.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, C, E, and F.
 - (b) Damage is permitted as shown in Vertical Stabilizer Front Spar Bay Location, Figure 103/ALLOWABLE DAMAGE 1 and Table 101.

PERCENT OF CROSS-SECTIONAL AREA REMOVED FROM A WEB OF THE FRONT SPAR				
BAY NUMBER	MAXIMUM PERCENTAGE OF THE INITIAL CROSS-SECTIONAL AREA PERMITTED (AS MANUFACTURED BY BOEING)			
1, 2, AND 3	15			
4	5			
5	10			
6	NO DAMAGE PERMITTED			
7	10			
8	NO DAMAGE PERMITTED			
9	10			
10 AND 11	5			
12	10			
13 THRU 31	15			

Table 101:

- (3) Dents are permitted as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Detail D.
- (4) Holes and Punctures are permitted as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Detail G, and F igure 103 if:





- (a) They are a maximum diameter D of 1.00 inch. (D = the maximum dimension of the largest damage)
- (b) There are not more than two holes in each bay between two stiffeners
- (c) The edge of the damage is a minimum of 4D away from the edge of:
 - 1) An initial hole
 - 2) A fastener hole
 - 3) Other damage.
- (d) The edge of the damage is a minimum of 3D away from the edge of the part
- (e) They are filled with a 2117-T3 or 2117-T4 aluminum protruding head rivet installed without sealant


NOTE: Do not fill holes and punctures that are more than 0.25 inch in diameter.

- (f) The total cross-sectional area removed from the web:
 - 1) Includes the cross-sectional area of all new fastener holes
 - 2) Includes the cross-sectional area of all damaged material that was removed
 - 3) Is not more than the limits given in Table 101/ALLOWABLE DAMAGE 1 between Points A and B of Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Detail G
 - Is not more than the limits given in Table 101/ALLOWABLE DAMAGE 1 between Points M and N of Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Detail G.



BOEING

737-800 STRUCTURAL REPAIR MANUAL






Page 106


Nov 01/2003

55-30-10



737-800 STRUCTURAL REPAIR MANUAL






Page 107

Nov 01/2003

55-30-10



737-800 STRUCTURAL REPAIR MANUAL



X = THE WIDTH OF THE MATERIAL THAT IS REMOVED = A MAXIMUM OF 10 PERCENT OF THE WIDTH OF THE FLANGE


REMOVAL OF DAMAGED MATERIAL ON AN EDGE

Allowable Damage Limits Figure 102 (Sheet 3 of 5)





737-800 STRUCTURAL REPAIR MANUAL



D = THE MAXIMUM DIMENSION OF THE DAMAGE REMOVAL

= 1.00 INCH MAXIMUM

-^I_I- FASTENER LOCATION

HOLES THAT ARE PERMITTED TO REMOVE DAMAGED MATERIAL IN WEBS


G

Allowable Damage Limits Figure 102 (Sheet 4 of 5)





737-800 STRUCTURAL REPAIR MANUAL








Figure 103



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details




ALLOWABLE DAMAGE 2 - VERTICAL STABILIZER REAR SPAR

1. Applicability

A. This subject gives the allowable damage limits for the vertical stabilizer rear spar shown in Vertical Stabilizer Rear Spar Location, Figure 101/ALLOWABLE DAMAGE 2.











2. General

- A. Remove the damage as necessary.
 - (1) Refer to 51-10-02 for the inspection and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
- B. After you remove the damage, do the procedures that follow.
 - (1) Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to 51-20-01.
 - (2) Apply one layer of BMS 10-11, Type I, primer to the reworked areas of the stiffeners and the chords. Refer to SOPM 20-41-02.
 - (3) Apply two layers of BMS 10-11, Type I, primer to the reworked areas of the webs. Refer to SOPM 20-41-02.

3. References

Refere	ence	Title
51-10-	-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-	-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-	-06	SHOT PEENING
51-30-	-03	NON-METALLIC MATERIALS
51-30-	-05	EQUIPMENT AND TOOLS FOR REPAIRS
55-30-	-90, ALLOWABLE DAMAGE 1	Vertical Stabilizer Fittings
SOPM	1 20-10-03	General - Shot Peening Procedures
SOPM	1 20-41-02	Application of Chemical and Solvent Resistant Finishes
	0 .0 00	с С

4. Allowable Damage Limits

- A. Chords
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 2, Details A and B.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 2, Details A, B, C, E, and F.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.

WARNING: MAKE SURE THAT YOU WEAR EYE PROTECTION WHEN YOU USE THE FLAP PEEN WHEEL. IF YOU DO NOT OBEY, AN INJURY CAN OCCUR.

- (5) Flap peen or shot peen the surfaces if you remove the damage.
 - (a) Refer to 51-20-06 for shot peen intensity and shot number.
 - (b) Refer to SOPM 20-10-03 for flap peen and shot peen procedures.
- B. Stiffeners



- (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 2, Details A, B, and F.
- (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 2, Details A, B, C, E, F, and H.
- (3) Dents are not permitted.
- (4) Holes and Punctures are not permitted.
- C. Webs
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 2, Details A and B.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 2, Details A, B, C, E, and F.
 - (3) Dents are permitted as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 2, Detail D.
 - (4) Holes and Punctures are permitted as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 2, Detail G if:
 - (a) They are a maximum diameter (D) of 1.00 inch. D is the maximum dimension of the largest damage.
 - (b) There is not more than two holes in each bay between two stiffeners
 - (c) The edge of the damage is a minimum of 4D away from the edge of:
 - 1) An initial hole
 - 2) A fastener hole
 - 3) Other damage
 - (d) The edge of the damage is a minimum of 3D away from the edge of the part
 - (e) They are filled with a 2117-T3 or 2117-T4 aluminum protruding head rivet:
 - 1) Do not fill holes and punctures that are more than 0.25 inch in diameter.
 - 2) Install the rivets without sealant.
 - (f) The total cross-sectional area removed from the web:
 - 1) Includes the cross-sectional area of all new fastener holes
 - 2) Includes the cross-sectional area of all damaged material that was removed
 - 3) Is not more than 15 percent of the initial cross-sectional area (as given by the nominal thickness on the production drawing) between Points A and B of Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 2, Detail G
 - 4) Is not more than 15 percent of the initial cross-sectional area (as given by the nominal thickness on the production drawing) between Points M and N of Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 2, Detail G.

ALLOWABLE DAMAGE 2


55-30-10

Page 104

Jul 10/2004

BOEING

737-800 STRUCTURAL REPAIR MANUAL



D634A210

ALLOWABLE DAMAGE 2


55-30-10


Page 105

Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL






55-30-10

ALLOWABLE DAMAGE 2

Page 106

Nov 01/2003





X = THE WIDTH OF THE MATERIAL THAT IS REMOVED = A MAXIMUM OF 10 PERCENT OF THE WIDTH OF THE FLANGE

REMOVAL OF DAMAGED MATERIAL ON AN EDGE

Allowable Damage Limits Figure 102 (Sheet 3 of 5)




D634A210

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details

BOEING®

737-800 STRUCTURAL REPAIR MANUAL




D = THE MAXIMUM DIMENSION OF THE DAMAGE REMOVAL= 1.00 INCH MAXIMUM-'- FASTENER LOCATION

> HOLES THAT ARE PERMITTED TO REMOVE DAMAGED MATERIAL IN WEBS

> > G

Allowable Damage Limits Figure 102 (Sheet 4 of 5)





- T = THE THICKNESS OF THE FLANGE
- X = THE DEPTH OF THE MATERIAL THAT IS REMOVED= A MAXIMUM OF 0.05T

REMOVAL OF DAMAGED MATERIAL FROM THE STABILIZATION FLANGE OF A STIFFENER

Allowable Damage Limits Figure 102 (Sheet 5 of 5)





REPAIR 1 - VERTICAL STABILIZER SPAR

1. Applicability

A. Repair 1 is applicable to damage to:

- (1) The front spar shown in Vertical Stabilizer Front Spar Repairs, Figure 201/REPAIR 1
- (2) The rear spar shown in Vertical Stabilizer Rear Spar Repairs, Figure 202/REPAIR 1.

2. Repair Instructions

A. Refer to:


- (1) Table 201 to find the applicable repair for a component of the front spar shown in Vertical Stabilizer Front Spar Repairs, Figure 201/REPAIR 1.
- (2) Table 202 to find the applicable repair for a component of the rear spar shown in Vertical Stabilizer Rear Spar Repairs, Figure 202/REPAIR 1.

Table 201:		
REPAIR REFERENCES FOR THE VERTICAL STABILIZER FRONT SPAR		
COMPONENT	REPAIR	
Stiffeners (Extrusion)	Refer to SRM 51-70-12	
Stiffeners (Plate)	There are no repairs for this component in the Structural Repair Manual at this time.	
Chords (Extrusion)	Refer to SRM 51-70-12	
Webs	Refer to SRM 55-30-10, Repair 2	

Table 202:	
REPAIR REFERENCES FOR THE VERTICAL STABILIZER REAR SPAR	
COMPONENT REPAIR	
Stiffeners (Extrusion)	Refer to SRM 51-70-12
Stiffeners (Bar Extrusion)	Refer to SRM 51-70-12
Chords	There are no repairs for this component in the Structural Repair Manual at this time.
Webs	Refer to SRM 55-30-10, Repair 3



REPAIR 1 Page 201 Mar 10/2007






REPAIR 1 Page 202 Nov 01/2003


BOEING

737-800 STRUCTURAL REPAIR MANUAL



REPAIR 1 Page 203 Nov 01/2003

55-30-10





REPAIR 1 Page 204 Nov 01/2003

BOEING

737-800 STRUCTURAL REPAIR MANUAL




Figure 202 (Sheet 2 of 2)



REPAIR 1 Page 205 Nov 01/2003




REPAIR 2 - VERTICAL STABILIZER FRONT SPAR WEB

1. Applicability

A. Repair 2 is applicable to damage to the web of the vertical stabilizer front spar if the damage is between Fin Station 73.40 and Rudder Station 276.24. Refer to Vertical Stabilizer Front Spar Location, Figure 201/REPAIR 2.



REPAIR 2 Page 201 Nov 01/2003





REPAIR 2 Page 202 Nov 01/2003



2. General

- A. Repair 2 gives instructions for a Category A repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.

3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-40-00, GENERAL	Fasteners
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-40-05	FASTENER HOLE SIZES
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
51-70-09	BONDED METAL STRUCTURE REPAIR PROCEDURES
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes

4. Repair Instructions

- A. Remove initial fasteners from skin assemblies as necessary to get access to the damaged area of the web. Refer to 51-40-02.
- B. Drill a stop hole at the ends of all web cracks that do not end at fastener holes. Refer to Vertical Stabilizer Front Spar Web Repair, Figure 202/REPAIR 2 and SRM 51-10-02 for the procedures to drill a stop hole. For other damage, do what follows:
 - (1) Cut and remove the damaged part of the web as shown in Vertical Stabilizer Front Spar Web Repair, Figure 202/REPAIR 2. Refer to 51-10-02 for the procedures to remove the damage.
- C. Assemble the repair part as shown in Vertical Stabilizer Front Spar Web Repair, Figure 202/REPAIR 2.
- D. Drill the fastener holes. Refer to 51-40-05 for the fastener hole dimensions.
- E. Remove the repair part.
- F. Remove the nicks, scratches, gouges, burrs, and sharp edges from the repair part and the bare surfaces of the web.
- G. Remove the initial web fasteners and stiffeners as necessary for the repair.
- H. Make the repair part as shown in Vertical Stabilizer Front Spar Web Repair, Figure 202/REPAIR 2. Refer to Table 201/REPAIR 2 for the repair material.



REPAIR 2 Page 203 Nov 10/2007



Table 201:

	REPAIR MATERIAL		
ITEM	PART	QUANTITY	MATERIAL
[1]	Doubler	1	Use clad or bare 7075-T6 sheet. Refer to Table 202 for the necessary thickness of the material. The use of clad material is recommended. You are permitted to make the repair part from 7075-T6 plate

Table 202:

REPAIR PART THICKNESSES FOR INITIAL WEB THICKNESS			
INITIAL WEB LOCATION OF DAMAGE (FIN STATION, FS) (RUDDER STATION, THICKNESS (INCH) RS)		ITEM [1] DOUBLER THICKNESS (INCH)	
0.090	FS 73.40 TO FS 91.55	0.100	
0.100	FS 91.55 TO FS 143.15	0.100	
0.070	FS 143.15 TO FS 159.86	0.080	
0.063	FS 159.86 TO FS 251.86	0.071	
0.050	FS 251.86 TO FS 316.26	0.063	
0.025 FS 316.26 TO RS 276.24		0.040	


- I. Apply a chemical conversion coating to the repair part and bare surfaces of the web. Refer to 51-20-01 for the chemical conversion coating procedures.
- J. Apply one layer of BMS 10-11, Type I, primer to the area of the repair. Refer to SOPM 20-41-02 for the procedures to apply the primer.
 - (1) Apply the primer to the repair part.
 - (2) Apply the primer to the bare surfaces of the web.
- K. Install the repair part with BMS 5-95 sealant between the mating surfaces. Refer to 51-20-05 for the procedures to apply the sealant.
 - (1) It is optional to bond the repair part to the initial web as given in 51-70-09. This option will increase the fatigue life of the repair.
- L. Install the initial web stiffeners.
- M. Install the fasteners.
 - (1) Install the hex drive fasteners wet with BMS 5-95 sealant in transition fit holes.
 - (2) Install the rivets at the initial locations without sealant.
- N. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.
- O. Install the skin assemblies, if they were removed.



REPAIR 2 Page 204 Nov 10/2007

Deing®

737-800 STRUCTURAL REPAIR MANUAL



NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENER.
- 1 MAKE SURE THAT THERE IS A MINIMUM OF THREE HORIZONTAL ROWS OF FASTENERS ON EACH SIDE OF THE DAMAGED AREA.

2 PUT THE LAST ROW OF FASTENERS AWAY FROM A STIFFENER.

FASTENER SYMBOLS

- --- INITIAL FASTENER LOCATION. INSTALL A FASTENER THAT IS THE SAME TYPE AND DIAMETER (UP TO 1/32 INCH DIAMETER OVERSIZE) AS THE INITIAL FASTENER.
- ➡ REPAIR FASTENER LOCATION. INSTALL A BACB30VT5K OR BACB30FM5A HEX DRIVE BOLT. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.
- + INITIAL FASTENER LOCATION. INSTALL A BACB30MY()K()X HEX DRIVE BOLT THAT IS UP TO 1/64 INCH DIAMETER OVERSIZE. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.


Vertical Stabilizer Front Spar Web Repair Figure 202 (Sheet 1 of 3)



REPAIR 2 Page 205 Nov 01/2003




737-800 STRUCTURAL REPAIR MANUAL





REPAIR 2 Page 206 Nov 01/2003





REPAIR SHOWN WITH OPTIONAL MACHINED DOUBLER

Vertical Stabilizer Front Spar Web Repair Figure 202 (Sheet 3 of 3)



REPAIR 2 Page 207 Nov 01/2003

D634A210


BOEING PROPRIETARY - Copyright ${\rm (\sc)}$ Unpublished Work - See title page for details




REPAIR 3 - VERTICAL STABILIZER REAR SPAR WEB - FIN STATIONS 251.86 TO 350.00

1. Applicability

- A. Repair 3 is applicable to damage to the web of the vertical stabilizer rear spar shown in Vertical Stabilizer Rear Spar Location, Figure 201/REPAIR 3 if:
 - (1) The damage is between Fin Stations 251.86 and 350.00.







REPAIR 3 Page 202 Nov 01/2003



2. General

- A. Repair 3 gives instructions for a Category A repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.

3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-40-00, GENERAL	Fasteners
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-40-05	FASTENER HOLE SIZES
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
51-70-09	BONDED METAL STRUCTURE REPAIR PROCEDURES
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes

4. Repair Instructions

- A. Remove initial fasteners from skin assemblies as necessary to get access to the damaged area of the web. Refer to 51-40-02.
- B. Drill a stop hole at the ends of all web cracks that do not end at fastener holes. Refer to Vertical Stabilizer Rear Spar Web Repair, Figure 202/REPAIR 3 and SRM 51-10-02 for the procedures to drill a stop hole. For other damage, do what follows:
 - (1) Cut and remove the damaged part of the web as shown in Vertical Stabilizer Rear Spar Web Repair With the Area of Damage Removed , Figure 203/REPAIR 3. Refer to 51-10-02 for the procedures to remove the damage.
- C. Remove the initial web fasteners and stiffeners as necessary for the repair.
- D. Make the repair parts as shown in Vertical Stabilizer Rear Spar Web Repair, Figure 202/REPAIR 3 or Vertical Stabilizer Rear Spar Web Repair With the Area of Damage Removed, Figure 203/REPAIR 3, as applicable. Refer to Table 201/REPAIR 3 for the repair materials.
- E. Assemble the repair parts as shown in Vertical Stabilizer Rear Spar Web Repair, Figure 202/REPAIR 3 or Vertical Stabilizer Rear Spar Web Repair With the Area of Damage Removed, Figure 203/REPAIR 3, as applicable.
- F. Drill the fastener holes. Refer to 51-40-05 for the fastener hole dimensions.
- G. Remove the repair parts.
- H. Remove the nicks, scratches, gouges, burrs, and sharp edges from the repair parts and the bare surfaces of the web.



REPAIR 3 Page 203 Nov 10/2007



I. Apply a chemical conversion coating to the repair parts and bare surfaces of the web. Refer to 51-20-01 for the chemical conversion coating procedures.

Table	201	
-------	-----	--

	REPAIR MATERIAL		
ITEM	PART	QUANTITY	MATERIAL
[1]	Doubler	1	Use clad or bare 7075-T6 sheet. Refer to Table 202 for the necessary thickness of the material. The use of clad material is recommended
[2]	Tapered Shim	4	Use clad or bare 7075-T6 sheet. The use of clad material is recommended
[3]	Web Filler	1	Use clad or bare 7075-T6 sheet. Make the thickness of the filler the same as the initial web. The use of clad material is recommended. This part is applicable only for the repair shown in Figure 203


Table 202:

REPAIR PART THICKNESSES FOR INITIAL WEB THICKNESSES		
INITIAL WEB THICKNESS (INCH) LOCATION OF DAMAGE (FIN STATION, FS)		ITEM [1] DOUBLER THICKNESS (INCH)
0.032	FS 251.86 to FS 288.66	0.040
0.025 FS 288.66 to FS 350.00 0.032		0.032

- J. Apply one layer of BMS 10-11, Type I, primer to the area of the repair. Refer to SOPM 20-41-02 for the procedures to apply the primer.
 - (1) Apply the primer to the repair parts.
 - (2) Apply the primer to the bare surfaces of the web.
- K. Install the repair parts with BMS 5-95 sealant between the mating surfaces. Refer to 51-20-05 for the procedures to apply the sealant.
 - (1) It is optional to bond the part [1] doubler to the initial web as given in 51-70-09. This option will increase the fatigue life of the repair.
- L. Install the initial web stiffeners.
- M. Install the fasteners.
 - (1) Install the rivets at the repair and initial locations without sealant.
 - (2) Install the hex drive fasteners at the initial locations wet with BMS 5-95 sealant in transition fit holes.
- N. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.
- O. Install the skin assemblies if they were removed.



REPAIR 3 Page 204 Nov 10/2007




NOTES

- 1 MAKE SURE THERE IS A MINIMUM OF FOUR HORIZONTAL ROWS OF FASTENERS ON EACH SIDE OF THE DAMAGE.
- 2 PUT THE LAST ROW OF FASTENERS AWAY FROM A STIFFENER.
 - (D) IS THE DIAMETER OF THE REPAIR FASTENER.
 - MAKE SURE THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.

FASTENER SYMBOLS

- --- REFERENCE FASTENER LOCATION
- + INITIAL FASTENER LOCATION. INSTALL A FASTENER THAT IS THE SAME TYPE AND DIAMETER (UP TO 1/32 INCH DIAMETER OVERSIZE FOR RIVETS AND 1/64 INCH DIAMETER OVERSIZE FOR HEX DRIVE BOLTS) AS THE INITIAL FASTENER.
- REPAIR FASTENER LOCATION. INSTALL A BACR15BB5D() RIVET. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.


Vertical Stabilizer Rear Spar Web Repair Figure 202 (Sheet 1 of 2)



REPAIR 3 Page 205 Nov 01/2003




737-800 STRUCTURAL REPAIR MANUAL



···· \--


A-A



Vertical Stabilizer Rear Spar Web Repair Figure 202 (Sheet 2 of 2)



REPAIR 3 Page 206 Nov 01/2003



NOTES

- 1 MAKE SURE THERE IS A MINIMUM OF FOUR HORIZONTAL ROWS OF FASTENERS ON EACH SIDE OF THE DAMAGE.
- 2 PUT THE LAST ROW OF FASTENERS AWAY FROM A STIFFENER.
 - (D) IS THE DIAMETER OF THE REPAIR FASTENER.
 - MAKE SURE THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.

FASTENER SYMBOLS

- --- REFERENCE FASTENER LOCATION
- + INITIAL FASTENER LOCATION. INSTALL A FASTENER THAT IS THE SAME TYPE AND DIAMETER (UP TO 1/32 INCH DIAMETER OVERSIZE FOR RIVETS AND 1/64 INCH DIAMETER OVERSIZE FOR HEX DRIVE BOLTS) AS THE INITIAL FASTENER.
- REPAIR FASTENER LOCATION. INSTALL A BACR15BB5D() RIVET. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.


Vertical Stabilizer Rear Spar Web Repair With the Area of Damage Removed Figure 203 (Sheet 1 of 3)




REPAIR 3 Page 207 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL







Vertical Stabilizer Rear Spar Web Repair With the Area of Damage Removed Figure 203 (Sheet 2 of 3)




REPAIR 3 Page 208 Nov 01/2003






737-800 STRUCTURAL REPAIR MANUAL





В-В



Vertical Stabilizer Rear Spar Web Repair With the Area of Damage Removed Figure 203 (Sheet 3 of 3)



REPAIR 3 Page 209 Nov 01/2003





REPAIR 4 - VERTICAL STABILIZER REAR SPAR WEB REPAIR - FIN STATIONS 215.06 THRU 251.86


1. Applicability

- A. Repair 4 is applicable to damage to the web of the vertical stabilizer rear spar shown in Figure 201/REPAIR 4 if:
 - (1) The damage is between Fin Stations 215.06 and 251.86.

2. General

- A. Repair 4 gives instructions for a Category A repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Refer to 51-30-05 for possible sources of the equipment and tools you need to remove the damage.





cal Stabilizer Rear Spar Loc Figure 201



REPAIR 4 Page 202 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-40-00, GENERAL	Fasteners
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-40-05	FASTENER HOLE SIZES
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
51-70-09	BONDED METAL STRUCTURE REPAIR PROCEDURES
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes
737 NDT Part 4, 55-30-01	Vertical Stabilizer Rear Spar Primary Chords

4. Repair Instructions

- A. Remove initial fasteners from skin assemblies as necessary to get access to the damaged area of the web. Refer to 51-40-02.
- B. Drill a stop hole at the ends of all web cracks that do not end at fastener holes. Refer to Vertical Stabilizer Rear Spar Web Repair Damage Near Center of Web, Fin Stations 215.06 thru 251.86, Figure 202/REPAIR 4, Vertical Stabilizer Rear Spar Web Repair with Web Splice, Damage Near Edge of Web Fin Stations 215.06 thru 251.86, Figure 203/REPAIR 4, and SRM 51-10-02 for the procedures to drill a stop hole. For other damage, do what follows:
 - (1) Cut and remove the damaged part of the web as shown in Vertical Stabilizer Rear Spar Web Repair - Damage Near Center of Web, Fin Stations 215.06 thru 251.86, Figure 202/REPAIR 4 or Vertical Stabilizer Rear Spar Web Repair with Web Splice, Damage Near Edge of Web -Fin Stations 215.06 thru 251.86, Figure 203/REPAIR 4. Refer to 51-10-02 for the procedures to remove the damage.
- C. Remove the initial web fasteners and stiffeners as necessary for the repair.
- D. Make the repair part as shown in Vertical Stabilizer Rear Spar Web Repair Damage Near Center of Web, Fin Stations 215.06 thru 251.86, Figure 202/REPAIR 4 or Vertical Stabilizer Rear Spar Web Repair with Web Splice, Damage Near Edge of Web - Fin Stations 215.06 thru 251.86, Figure 203/REPAIR 4. Refer to Table 201/REPAIR 4 for the repair material.
- E. Assemble the repair part as shown in Vertical Stabilizer Rear Spar Web Repair Damage Near Center of Web, Fin Stations 215.06 thru 251.86, Figure 202/REPAIR 4 or Vertical Stabilizer Rear Spar Web Repair with Web Splice, Damage Near Edge of Web - Fin Stations 215.06 thru 251.86, Figure 203/REPAIR 4.
- F. Drill the fastener holes. Refer to 51-40-05 for the fastener hole dimensions.
- G. Remove the repair part.



REPAIR 4 Page 203 Nov 10/2007



- H. Remove the nicks, scratches, gouges, burrs, and sharp edges from the repair part and the bare surfaces of the web.
- I. Apply a chemical conversion coating to the repair part and bare surfaces of the web. Refer to 51-20-01 for the chemical conversion coating procedures.

	REPAIR MATERIAL		
ITEM PART QUANTITY MATERIAL		MATERIAL	
[1]	Doubler	1	Use clad or bare 7075-T6 that is 0.050 inch thick. Make the thickness 0.090 inch thick if you make the Part [2] Splice shown in Figure 203. The use of clad material is recommended
[2]	Splice	1	Use clad or bare 7075-T6 that is 0.090 inch thick. The use of clad material is recommended. This part is needed for the repair shown in Figure 203
[3]	Filler	1	Use clad or bare 7075-T6. The use of clad material is recommended. Use this filler when you do the repair shown in Figure 203
[4]	Filler	2	Use clad or bare 7075-T6 that is 0.090 inch thick. The use of clad material is recommended. Use these fillers when you do the repair shown in Figure 203
[5]	Stiffener	2	Make the stiffeners from a 7075-T6511 extrusion. Make the stiffeners the same shape as the initial stiffeners on the production drawing except for a shorter flange height. Use these stiffeners when you do the repair shown in Figure 203

Table 201:


- J. Apply one layer of BMS 10-11, Type I, primer to the area of the repair. Refer to SOPM 20-41-02 for the procedures to apply the primer.
 - (1) Apply the primer to the repair part.
 - (2) Apply the primer to the bare surfaces of the web.
- K. Install the repair part with BMS 5-95 sealant between the mating surfaces. Refer to 51-20-05 for the procedures to apply the sealant.
 - (1) It is optional to bond the part [1] doubler to the initial web as given in 51-70-09. This option will increase the fatigue life of the repair.
- L. Install the initial web stiffeners, as necessary.
- M. Install the fasteners.
 - (1) Install the hex drive fasteners at the repair and initial locations wet with BMS 5-95 sealant in transition fit holes.
 - (2) Install the rivets at the initial locations without sealant.
- N. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.
- O. Install the skin assemblies, if they were removed.



REPAIR 4 Page 204 Nov 10/2007



737-800 STRUCTURAL REPAIR MANUAL




Vertical Stabilizer Rear Spar Web Repair - Damage Near Center of Web, Fin Stations 215.06 thru 251.86 Figure 202 (Sheet 1 of 3)



REPAIR 4 Page 205 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



Vertical Stabilizer Rear Spar Web Repair - Damage Near Center of Web, Fin Stations 215.06 thru 251.86 Figure 202 (Sheet 2 of 3)



REPAIR 4 Page 206 Nov 01/2003

BOEING

NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENER.
- MAKE SURE THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.
- 1 MAKE SURE THERE IS A MINIMUM OF THREE ROWS OF REPAIR FASTENERS ALL AROUND THE DAMAGE.
- 2 PUT THE LAST ROW OF FASTENERS AWAY FROM A STIFFENER.

FASTENER SYMBOLS

- --- REFERENCE FASTENER LOCATION.
- + INITIAL FASTENER LOCATION. INSTALL A FASTENER THAT IS THE SAME TYPE AND DIAMETER (UP TO 1/32 INCH DIAMETER OVERSIZE FOR RIVETS AND 1/64 INCH DIAMETER OVERSIZE FOR HEX DRIVE BOLTS) AS THE INITIAL FASTENER.
- REPAIR FASTENER LOCATION. INSTALL A BACB30NX6K() HEX DRIVE BOLT. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.


Vertical Stabilizer Rear Spar Web Repair - Damage Near Center of Web, Fin Stations 215.06 thru 251.86 Figure 202 (Sheet 3 of 3)



REPAIR 4 Page 207 Nov 01/2003

BOEING®

737-800 STRUCTURAL REPAIR MANUAL




Vertical Stabilizer Rear Spar Web Repair with Web Splice, Damage Near Edge of Web - Fin Stations 215.06 thru 251.86 Figure 203 (Sheet 1 of 3)



REPAIR 4 Page 208 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



Vertical Stabilizer Rear Spar Web Repair with Web Splice, Damage Near Edge of Web - Fin Stations 215.06 thru 251.86 Figure 203 (Sheet 2 of 3)



REPAIR 4 Page 209 Nov 01/2003

BOEING

NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENER.
- MAKE SURE THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.
- 1 MAKE SURE THERE IS A MINIMUM OF FOUR HORIZONTAL ROWS OF FASTENERS ON EACH SIDE OF THE DAMAGE.
- 2 PUT THE LAST ROW OF FASTENERS AWAY FROM A STIFFENER.

FASTENER SYMBOLS

- --- REFERENCE FASTENER LOCATION
- + INITIAL FASTENER LOCATION. INSTALL A FASTENER THAT IS THE SAME TYPE AND DIAMETER (UP TO 1/32 INCH DIAMETER OVERSIZE FOR RIVETS AND 1/64 INCH DIAMETER OVERSIZE FOR HEX DRIVE BOLTS) AS THE INITIAL FASTENER.
- ➡ REPAIR FASTENER LOCATION. INSTALL A BACB30NX6K() HEX DRIVE BOLT. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA.
- 🔶 INITIAL FASTENER LOCATION. INSTALL A BACB30NX6K() HEX DRIVE BOLT.

Vertical Stabilizer Rear Spar Web Repair with Web Splice, Damage Near Edge of Web - Fin Stations 215.06 thru 251.86 Figure 203 (Sheet 3 of 3)



REPAIR 4 Page 210 Nov 01/2003




REPAIR 5 - VERTICAL STABILIZER REAR SPAR WEB REPAIR - FIN STATIONS 88.44 THRU 215.06

1. Applicability

- A. Repair 5 is applicable to damage to the web of the vertical stabilizer rear spar shown in Vertical Stabilizer Rear Spar Location, Figure 201/REPAIR 5 if:
 - (1) The damage is between Fin Stations 88.44 and 215.06
 - (2) There is no damage to the failsafe chords.



55-30-10



Vertical Stabilizer Rear Spar Locatior Figure 201



REPAIR 5 Page 202 Nov 01/2003



2. General

- A. Repair 5 gives instructions for a Category A repair. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.

3. <u>References</u>

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05	REPAIR SEALING
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-40-00, GENERAL	Fasteners
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-40-05	FASTENER HOLE SIZES
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
51-70-09	BONDED METAL STRUCTURE REPAIR PROCEDURES
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-31-00 P/B 201	SEALS AND SEALING - MAINTENANCE PRACTICES
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes

4. Repair Instructions

- A. Remove initial fasteners from skin assemblies as necessary to get access to the damaged area of the web. Refer to 51-40-02.
- B. Drill a stop hole at the ends of all web cracks that do not end at fastener holes. Refer to Vertical Stabilizer Rear Spar Web Repair - Fin Stations 88.44 thru 215.06, Figure 202/REPAIR 5 and SRM 51-10-02 for the procedures to drill a stop hole. For other damage, do what follows:
 - (1) Cut and remove the damaged part of the web as shown in Vertical Stabilizer Rear Spar Web Repair - Fin Stations 88.44 thru 215.06, Figure 202/REPAIR 5. Refer to 51-10-02 for the procedures to remove the damage.
- C. Remove the initial web fasteners and stiffeners as necessary for the repair.
- D. Make the repair parts as shown in Vertical Stabilizer Rear Spar Web Repair Fin Stations 88.44 thru 215.06, Figure 202/REPAIR 5. Refer to Table 201/REPAIR 5 for the repair material.

	REPAIR MATERIAL					
ITEM	ITEM PART QUANTITY MATERIAL					
[1]	Doubler	1	Use clad or bare 7075-T6. Refer to Table 202 for the necessary thickness of the material. The use of clad material is recommended			
[2]	Tapered Shim	4	Use clad or bare 7075-T6. The use of clad material is recommended			

Table 201:



55-30-10



Table 202:

REPAIR PART THICKNESSES FOR INITIAL WEB THICKNESSES					
INITIAL WEB THICKNESS (INCH) LOCATION OF DAMAGE (FIN STATION, FS) ITEM [1] DOUBLER TH					
0.080	FS 88.44 TO FS 93.47	0.100			
0.070	FS 93.47 TO FS 115.24	0.090			
0.090	FS 115.24 TO FS 133.27	0.125			
0.060	FS 133.27 TO FS 143.26	0.080			
0.050	FS 143.26 TO FS 169.06	0.063			
0.040	FS 169.06 TO FS 215.06	0.050			


- E. Assemble the repair parts as shown in Vertical Stabilizer Rear Spar Web Repair Fin Stations 88.44 thru 215.06, Figure 202/REPAIR 5.
- F. Drill the fastener holes. Refer to 51-40-05 for the fastener hole dimensions.
- G. Remove the repair parts.
- H. Remove the nicks, scratches, gouges, burrs, and sharp edges from the repair parts and the bare surfaces of the web.
- I. Apply a chemical conversion coating to the repair parts and bare surfaces of the web. Refer to 51-20-01 for the chemical conversion coating procedures.
- J. Apply one layer of BMS 10-11, Type I, primer to the area of the repair. Refer to SOPM 20-41-02 for the procedures to apply the primer.
 - (1) Apply the primer to the repair parts.
 - (2) Apply the primer to the bare surfaces of the web.
- K. Install the repair parts with BMS 5-95 sealant between the mating surfaces. Refer to 51-20-05 for the procedures to apply the sealant.
 - (1) It is optional to bond the part [1] doubler to the initial web as given in 51-70-09. This option will increase the fatigue life of the repair.
- L. Install the initial web stiffeners.
- M. Install the fasteners.
 - (1) Install the hex drive fasteners at the repair and initial locations wet with BMS 5-95 sealant in transition fit holes.
 - (2) Install the rivets at the initial locations without sealant.
- N. Apply the decorative finish to the repair area as given in AMM PAGEBLOCK 51-21-99/701.
- O. Install the skin assemblies, if they were removed.



REPAIR 5 Page 204 Nov 10/2007



737-800 STRUCTURAL REPAIR MANUAL




Vertical Stabilizer Rear Spar Web Repair - Fin Stations 88.44 thru 215.06 Figure 202 (Sheet 1 of 3)




REPAIR 5 Page 205 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL







Vertical Stabilizer Rear Spar Web Repair - Fin Stations 88.44 thru 215.06 Figure 202 (Sheet 2 of 3)



REPAIR 5 Page 206 Nov 01/2003

BOEING

NOTES

- (D) IS THE DIAMETER OF THE REPAIR FASTENER.
- MAKE SURE THE REPAIR IS SYMMETRICAL AROUND THE DAMAGE.
- 1 MAKE SURE THERE IS A MINIMUM OF THREE ROWS OF REPAIR FASTENERS ALL AROUND THE DAMAGE.
- 2 PUT THE LAST ROW OF FASTENERS AWAY FROM THE STIFFENER.

FASTENER SYMBOLS

- --- REFERENCE FASTENER LOCATION
- + INITIAL FASTENER LOCATION. INSTALL FASTENER THAT IS THE SAME TYPE AND DIAMETER (UP TO 1/32 INCH DIAMETER OVERSIZE FOR RIVETS AND 1/64 INCH DIAMETER OVERSIZE FOR HEX DRIVE BOLTS) AS THE INITIAL FASTENER.
- REPAIR FASTENER LOCATION. INSTALL A BACB30NX()K() HEX DRIVE BOLT OR A BACR15BB()D() RIVET THAT IS SAME DIAMETER AS THE INITIAL FASTENERS IN THE WEB AND CHORDS. REFER TO SRM 51-40-00 THROUGH 51-40-08 FOR THE FASTENER DATA. THE FASTENER DIAMETER IS 3/16 INCH BETWEEN FIN STATIONS 143.25 AND 215.06 AND 1/4 INCH BELOW FIN STATION 143.26.


Vertical Stabilizer Rear Spar Web Repair - Fin Stations 88.44 thru 215.06 Figure 202 (Sheet 3 of 3)



REPAIR 5 Page 207 Nov 01/2003



IDENTIFICATION 1 - VERTICAL STABILIZER BEAM




NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Vertical Stabilizer Beam Location Figure 1

Table 1:

	REFERENCE DRAWINGS					
DRAWING NUMBER	TITLE					
001A7001	Section 70 Vertical Fin - Product Collector					
175A0001	Trailing Edge Functional Collector - Vertical Fin					





NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

VERTICAL STABILIZER BEAM UPPER AND LOWER SECTIONS

Vertical Stabilizer Beam Identification Figure 2





Table 2:

	LIST OF MATERIALS FOR FIGURE 2					
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY		
[1]	Beam Assembly (2)					
	Beam		BAC1518-1188 7075-T6511 extrusion as given in QQ-A-200/11			
	Strap	0.080 (2.03)	7075-T6 clad sheet as given in QQ-A-250/13			
(2)	Beam		BAC1518-1188 7075-T6511 extrusion as given in QQ-A-200/11			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





ALLOWABLE DAMAGE 1 - VERTICAL STABILIZER TRAILING EDGE BEAMS


1. Applicability

A. This subject gives the allowable damage limits for the vertical stabilizer trailing edge beams shown in Vertical Stabilizer Upper and Lower Beam Locations, Figure 101/ALLOWABLE DAMAGE 1.





737-800 STRUCTURAL REPAIR MANUAL







2. General

- A. Remove the damage as necessary.
 - (1) Refer to 51-10-02 for the inspection and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
- B. After you remove the damage, do the procedures that follow.

WARNING: MAKE SURE THAT YOU WEAR EYE PROTECTION WHEN YOU USE THE FLAP PEEN WHEEL. IF YOU DO NOT OBEY, AN INJURY CAN OCCUR.

- (1) Flap peen or shot peen the surfaces of the beams if you remove the damage.
 - (a) Refer to 51-20-06 for shot peen intensity and shot number.
 - (b) Refer to SOPM 20-10-03 for flap peen and shot peen procedures.
- (2) Apply a chemical conversion coating to the bare surfaces of the reworked areas of the beams. Refer to 51-20-01.
- (3) Apply one layer of BMS 10-11, Type I, primer to the reworked areas of the beams. Refer to SOPM 20-41-02.

3. <u>References</u>

Reference	Title
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-06	SHOT PEENING
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-10-03	General - Shot Peening Procedures
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes


4. Allowable Damage Limits

- A. Cracks:
 - (1) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A and B
- B. Nicks, Gouges, Scratches, and Corrosion:
 - (1) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, C, D, and E
- C. Dents are not permitted.
- D. Holes and Punctures are not permitted.



BOEING

737-800 STRUCTURAL REPAIR MANUAL






Page 104

Nov 01/2003

55-30-13

BOEING

737-800 STRUCTURAL REPAIR MANUAL



Nov 01/2003



REPAIR 1 - VERTICAL STABILIZER TRAILING EDGE BEAM

1. Applicability

A. Repair 1 is applicable to damage to the trailing edge beams shown in Vertical Stabilizer Upper and Lower Beam Locations, Figure 201/REPAIR 1.

2. <u>References</u>

Reference	Title
51-70-12	EXTRUDED SECTION REPAIRS

3. Repair Instructions


A. Refer to 51-70-12 to repair the trailing edge beams.



REPAIR 1 Page 201 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL






REPAIR 1 Page 202 Nov 01/2003



IDENTIFICATION 1 - VERTICAL STABILIZER TIP



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Vertical Stabilizer Tip Location Figure 1

|--|


	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
172A0001	Torque Box Functional Collector - Vertical Fin				
172A3701	Nutplate Installation - FWL 274.570, Vertical Fin				
284A0510	Antenna Installation - VOR				



Page 1



737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Vertical Stabilizer Tip Identification Figure 2



Page 2

D634A210 BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details



Table 2:

	LIST OF MATERIALS FOR FIGURE 2					
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY		
[1]	Ground Strap	0.016 (0.41)	6061-0 sheet as given in QQ-A-250/11			
[2]	Leading Edge Access Assembly					
	Nose	0.050 (1.27)	2024-T42 clad sheet as given in QQ-A-250/5			
	Doubler	0.050 (1.27)	2024-T42 clad sheet as given in QQ-A-250/5			
[3]	Canopy Assembly					
	Lightning Strip		BAC1511-3787 6061-0 extrusion as given in QQ-A- 200/8 (Optional: 6061-T6)			
	Canopy		Glass Fabric Reinforced Plastic (GFRP) as given in BAC 5449. Glass fabric number 181, warp direction optional			
	Splice (2)	0.050 (1.27)	2024-T42 clad sheet as given in QQ-A-250/5			
	Splice (2)		GFRP as given in BAC 5449. Glass fabric number 181, warp direction optional			
[4]	Trailing Edge Assembly					
	Skin	0.040 (1.02)	6061-T6 clad sheet as given in QQ-A-321			
	Former	0.063 (1.60)	2024-T42 clad sheet as given in QQ-A-250/5			
	Doubler	0.063 (1.60)	2024-T3 clad sheet as given in QQ-A-250/5			
	Splice Plate	0.050 (1.27)	2024-T3 clad sheet as given in QQ-A-250/5			
[5]	Fitting-Trailing Edge, Fin Tip		A360 aluminum die casting, Class II B, as given in QQ-A-591 (Optional: Machine from 2024-T351 rolled bar as given in AMS QQ-A-225/6. Grain direction is parallel to the length of the rolled bar)			


*[1] Note: T = Pre-manufactured thickness in inches (millimeters).



IDENTIFICATION 1 Page 3 Nov 01/2003



IDENTIFICATION 2 - VERTICAL STABILIZER COVE



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Vertical Stabilizer Cove Location Figure 1


Table 1:

REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE			
176A0001	Leading Edge and Miscellaneous Functional Collector - Vertical Fin			





737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Vertical Stabilizer Cove Identification Figure 2

Table 2:

	LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY	
[1]	Cove Assembly		Glass Fiber Reinforced Plastic (GFRP) laminate as given in BMS 8-79, Class III, Grade B, Type 1581 or 7781. Warp direction is optional		

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).








ALLOWABLE DAMAGE 1 - VERTICAL STABILIZER TIP

1. Applicability

A. Allowable Damage 1 is applicable to damage on the vertical stabilizer tip skin and fitting as shown in Vertical Stabilizer Tip, Figure 101/ALLOWABLE DAMAGE 1.



2. General

- A. Do the steps that follow for the canopy made of Glass Fabric Reinforced Plastic (GFRP).
 - (1) Refer to Vertical Stabilizer Tip, Figure 101/ALLOWABLE DAMAGE 1 for the location of the canopy.
 - (2) Remove all the contamination and water from the structure. Refer to 51-30-05 and 51-70-04 for the tools and the cleanup procedures.






- (3) Refer to Definitions of the Damage Size, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, and C for the definitions of the length, width, and depth of damage.
- (4) Seal the damaged areas with the steps that follow:
 - (a) Seal the damage that is not more than one ply deep and that agrees with the allowable damage limits given in Paragraph 4./ALLOWABLE DAMAGE 1
 - 1) Make a temporary seal.
 - a) Apply aluminum foil tape (speed tape).
 - b) Keep a record of the location.
 - c) Make sure the tape is in satisfactory condition at each 400 flight hour interval or more frequently.
 - d) Seal the damage permanently no later than 5000 flight hours from the time the seal was made.
 - 2) Make a permanent seal.
 - a) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given in 51-70-08.
 - b) Apply one layer of BMS 10-79, Type 3 or BMS 10-103, Type 1 primer. Refer to SOPM 20-44-04.
 - c) Apply one layer of BMS 10-60 enamel to the areas sealed with epoxy resin. Refer to AMM 51-21-00/701.
 - (b) Seal the damaged areas that are more than one ply deep and that agree with the allowable damage limits given in Paragraph 4./ALLOWABLE DAMAGE 1
 - 1) Use a vacuum and heat to remove moisture from the solid laminate or the honeycomb cells. Refer to 51-70-04.
 - 2) Make a temporary seal with aluminum foil tape (speed tape).
 - 3) Keep a record of the location.
 - 4) Repair the damage no later than 400 flight hours from the time the seal was made.
- B. Do the steps that follow for the parts made of aluminum.
 - (1) Refer to Vertical Stabilizer Tip, Figure 101/ALLOWABLE DAMAGE 1 for the location of the parts made of aluminum.
 - (2) Refer to Paragraph 4 for the allowable damage limits
 - (3) Remove the damage.
 - (a) Refer to 51-10-02 for the investigation and cleanup procedures.
 - (b) Refer to 51-30-03 for possible sources of the abrasive and other materials you need to remove the damage.
 - (c) Refer to 51-30-05 for possible sources of the equipment and tools you need to remove the damage.
 - (d) Make the surface texture roughness for all cut surfaces 125 microinches Ra or smoother.
 - (4) After you remove the damage, do the steps that follow:
 - (a) For lightning strike damage to the trailing edge fin tip fitting or the trailing edge skin remove all finishes and do as follows:
 - 1) Do a High Frequency Eddy Current (HFEC) inspection to the damaged area as given in NDT Part 6 51-00-00, Figures 3 and 4.





- 2) Do a resistance check between the fastener head and the initial structure as given in BAC 5117-6. The maximum resistance that is permitted is 0.010 ohms.
- (b) Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to 51-20-01.
- (c) Apply one layer of BMS 10-11, Type I primer to all the conversion coated, reworked areas other than the trailing edge fin tip fitting. Apply two layers of BMS 10-11, Type I primer to the conversion coated, reworked areas of the trailing edge fin tip fitting. Refer to SOPM 20-41-02.
- (d) Apply a decorative finish if necessary. Refer to AMM PAGEBLOCK 51-21-99/701.
- C. Make sure the aerodynamic smoothness is satisfactory or there will be a decrease in the economic performance of the airplane. Refer to 51-10-01.



D634A210

Page 103

Nov 10/2007

55-30-30



3. References

Reference	Title
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-05, GENERAL	Repair Sealing
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-70-01, REPAIR GENERAL	Procedures to Rework or Fill Allowable Dents on the External Aerodynamic Surfaces of Metallic Parts
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-08	RESIN SWEEP-FAIR PROCEDURES
51-70-14, ALLOWABLE DAMAGE GENERAL	Damage Limits and Sealing Instructions for Aluminum Coatings and Foils
55-30-30, REPAIR 1	Vertical Stabilizer Tip
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
AMM 51-21-00/701	Interior And Exterior Finishes - Cleaning/Painting
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Allowable Damage Limits

- A. Canopy (GFRP)
 - (1) Nicks, Gouges and Scratches that do not cause damage to the glass fibers are permitted.
 - (2) Nicks, Gouges and Scratches that cause damage to the glass fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum of 5.0 inches in length
- (c) A maximum of 0.25 inch in width
- (d) A minimum of 0.50 inch away from the edge of a fastener hole
- (e) A minimum of 0.50 inch away from the edge of other damage. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies
 - 2) Are sealed as given in Paragraph 2.
- (3) Dents are permitted if:
 - (a) They are a maximum of 2.0 inch in diameter
 - (b) The edge of the damage is a minimum of 4D (D = the diameter of the damage) from other damage, fastener holes or material edges. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies
 - 2) Are sealed as given in Paragraph 2.
- (4) Holes and Punctures are permitted if they are:





- (a) A maximum of 1.50 inch in diameter
- (b) A minimum of 4D (D = the diameter of the damage) from other damage, fastener holes or material edges. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies
 - 2) Are sealed as given in Paragraph 2.
- (5) Delaminations are permitted if they are:
 - (a) A maximum of 1.5 inch in diameter
 - (b) A minimum of 4D (D = the diameter of the damage) from the edge of other damage, the edge of a hole, or the edge of the material. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies
 - 2) Are sealed as given in Paragraph 2.
- (6) Edge damage is permitted if it is:
 - (a) A maximum of 0.10 in depth
 - (b) A maximum of 0.50 inch in width
 - (c) The edge of the damage is a minimum of 2.5D (D = the diameter of the damage) from other damage, fastener holes or material edges. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies
 - 2) Are sealed as given in Paragraph 2.
- (7) Edge Erosion is permitted as shown in Cleanup and Sealing of Edge Erosion, Figure 103/ALLOWABLE DAMAGE 1.
- B. Leading Edge Cap and Trailing Edge Skin (Aluminum)
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 1, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 1, Details A, B, C, D, and E.
 - (b) Damage that does not go through the clad surface is permitted.
 - (3) Dents:
 - (a) Dents are permitted if they agree with the conditions shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 1, Detail F.
 - (4) Holes and Punctures are permitted if:
 - (a) They are 0.25 inch in diameter or less
 - (b) The edge of the damage is a minimum of 1.0 inch away from another hole, an edge, or other damage
 - (c) They are filled with a 2017-T3 or 2117-T4 aluminum protruding head rivet. Install the rivet without sealant.
 - 1) Install the rivet without sealant.
 - (5) Trailing Edge Skin and Trailing Edge Fin Tip Fitting Lightning Strike damage is permitted if:






(a) You remove the damage as shown in Figure 104, Details D and G.

NOTE: If the damage is more than the limits shown in Figure 104, Details D and G then refer to 55-30-30, REPAIR 1.

- (b) Make sure there is a minimum 1.0 inch (25.4 mm) blend radius at a 20:1 blend ratio at all locations.
- (c) Make sure there is a minimum distance of 2.0 inches (50.8 mm) between any two adjacent damage locations.
- (d) No fasteners are damaged.




Cleanup and Sealing of Edge Erosion Figure 103



BOEING

737-800 STRUCTURAL REPAIR MANUAL



D634A210

ALLOWABLE DAMAGE 1


55-30-30

Page 107


Nov 10/2005

BOEING

737-800 STRUCTURAL REPAIR MANUAL







Allowable Damage Limits Figure 104 (Sheet 3 of 4)




Page 109

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL



TRAILING EDGE FIN TIP FITTING (LIGHTNING STRIKE LIMITS)

G



Allowable Damage Limits Figure 104 (Sheet 4 of 4)




Page 110 Nov 10/2005



ALLOWABLE DAMAGE 2 - VERTICAL STABILIZER COVE

1. Applicability

A. Allowable Damage 2 is applicable to damage on the vertical stabilizer cove panel shown in Vertical Stabilizer Cove, Figure 101/ALLOWABLE DAMAGE 2.



Vertical Stabilizer Cove Figure 101

2. <u>General</u>

- A. Do an inspection of the damaged area to find the length, width, and depth of the damage. Boeing recommends that you use and instrumented Non-Destructive Test (NDT) procedure. Refer to 737 NDT Part 1, 51-01-02 for inspection procedures.
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.



ALLOWABLE DAMAGE 2


Page 101

Jul 10/2005



- (1) Refer to Definitions of the Damage Size, Figure 102/ALLOWABLE DAMAGE 2, Details A, B, and C for the definitions of the length, width, and length of damage.
- B. Do the steps that follow for the cove panel made of Glass Fabric Reinforced Plastic (GFRP).
 - (1) Remove all the contamination and water from the structure.
 - (a) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (b) Refer to 51-70-04 for the damage removal procedures.
 - (2) Refer to Definitions of the Damage Size, Figure 102/ALLOWABLE DAMAGE 2, Details A, B, and C for the definitions of the length, width, and depth of damage.
 - (3) Seal the damaged areas with the steps that follow.
 - (a) Seal the damage that is not more than one ply deep and that agrees with the allowable damage limits given in Paragraph 4./ALLOWABLE DAMAGE 2
 - 1) Make a temporary seal.
 - a) Apply aluminum foil tape (speed tape).
 - b) Keep a record of the location.
 - c) Make sure the tape is in satisfactory condition every 400 flight hours.
 - d) Seal the damage permanently at or before 5000 flight hours.
 - 2) Make a permanent seal.
 - a) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given in 51-70-08.
 - b) Apply one layer of BMS 10-79, Type 3 or BMS 10-103, Type 1 primer. Refer to SOPM 20-44-04.
 - c) Apply one layer of BMS 10-60 enamel to the areas sealed with epoxy resin. Refer to AMM PAGEBLOCK 51-21-99/701.
 - (b) Seal the damaged areas that are more than one ply deep and that agree with the allowable damage limits given in Paragraph 4./ALLOWABLE DAMAGE 2
 - 1) Use a vacuum and heat to remove moisture from the solid laminate or the honeycomb cells. Refer to 51-70-04.
 - 2) Make a temporary seal with aluminum foil tape (speed tape).
 - 3) Keep a record of the location.
 - 4) Repair the damage at or before 400 flight hours.





Definitions of the Damage Size Figure 102

3. References

Reference	Title
51-10-02, GENERAL	Inspection and Removal of Damage
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-08	RESIN SWEEP-FAIR PROCEDURES
AMM 51-21-99 P/B 701	DECORATIVE EXTERIOR PAINT SYSTEM - CLEANING/PAINTING
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Allowable Damage Limits

A. Inboard and Outboard Panels (GFRP Laminate)






- (1) Nicks, Gouges and Scratches that do not cause damage to the glass fibers are permitted.
- (2) Nicks, Gouges and Scratches that cause damage to the glass fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum of 5.0 inches in length
- (c) A maximum of 0.25 inch in width
- (d) A minimum of 0.50 inch away from the edge of a fastener hole
- (e) A minimum of 0.50 inch away from the edge of other damage. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies, and
 - 2) Are sealed as given in Paragraph 2.
- (3) Dents are permitted if:
 - (a) They are a maximum of 2.0 inch in diameter.
 - (b) The edge of the damage is a minimum of 2.5D (D = the diameter of the damage) from other damage, fastener holes or material edges. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies, and
 - 2) Are sealed as given in Paragraph 2.
- (4) Holes and Punctures are permitted if they are:
 - (a) A maximum of 2.0 inch in diameter
 - (b) A minimum of 2.5D (D = the diameter of the damage) from other damage, fastener holes or material edges. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies, and
 - 2) Are sealed as given in Paragraph 2.
- (5) Delaminations are permitted if they are:
 - (a) A maximum of 2.0 inch in diameter
 - (b) A minimum of 2.5D (D = the diameter of the damage) from the edge of other damage, the edge of a hole, or the edge of the material. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies
 - 2) Are sealed as given in Paragraph 2.
- (6) Edge damage is permitted if it is:
 - (a) A maximum of 0.25 in depth
 - (b) A maximum of 1.00 inch in width
 - (c) A minimum of 2.5D (D = the diameter of the damage) from the edge of other damage, the edge of a hole, or the edge of the material. Other damage does not include nicks, gouges, and scratches that:
 - 1) Do not cause damage to the glass fiber plies
 - 2) Are sealed as given in Paragraph 2.



(7) Edge Erosion is permitted as shown in Cleanup and Sealing of Edge Erosion, Figure 103/ALLOWABLE DAMAGE 2.



Cleanup and Sealing of Edge Erosion Figure 103





REPAIR 1 - VERTICAL STABILIZER TIP

1. Applicability

- A. Repair 1 is applicable to the vertical stabilizer canopy made of Glass Fiber Reinforced Plastic (GFRP) and the vertical stabilizer trailing edge skin (Aluminum) shown in Vertical Stabilizer Tip Canopy Location, Figure 201/REPAIR 1.
- B. Repair 1 is applicable to damage that is more than the limits permitted in Allowable Damage 1. Refer to Allowable Damage 1 for the type and size of damage that is permitted.

2. General

- A. Repair 1 gives instructions for Category A and B repairs for the vertical stabilizer canopy and a Category A repair for the vertical stabilizer trailing edge skin. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Refer to Paragraphs 2.C through 2G for damage to the vertical stabilizer canopy. Refer to Paragraph 2.H for lightning strike damage to the vertical stabilizer trailing edge skin.
- C. Get access to the damaged area.
 - (1) If necessary, remove the tip cap. Refer to AMM 55-33-21/401.
 - (2) Refer to 51-40-02 for information on fastener removal.
- D. Do an inspection of the damaged area to find the dimensions of the damage.
 - (1) Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 for inspection procedures.
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.
- E. Refer to Definitions of the Damage Size, Figure 202/REPAIR 1, Details A, B, and C for the definitions of the length, width, and depth of damage.
- F. Do the repair as given in Paragraph 4./REPAIR 1
- G. Put the tip cap back to the initial condition, as applicable.
 - (1) Install the tip cap, if it was removed. Refer to AMM 55-33-21/401.
 - (a) Refer to 51-40-02 for information on fastener installation.
 - (2) Make sure the aerodynamic smoothness is satisfactory or there will be a decrease in the performance of the airplane. Refer to 51-10-01.
- H. For damage to the aluminum vertical stabilizer trailing edge skin do as follows:
 - (1) Remove the damage.
 - (2) Do a High Frequency Eddy Current (HFEC) inspection to the edge of the damage locations to make sure that all of the damage has been removed. Refer to NDT Part 6, 51-00-00, Figure 3.
 - (3) Make a 0.08 inch (2.03 mm) insurance cut around the damage perimeter.
 - (4) Do the repair instructions as given in Paragraph 4.




REPAIR 1 Page 201 Nov 10/2005



737-800 STRUCTURAL REPAIR MANUAL


SEE A FOR THE VERTICAL STABILIZER TIP



Vertical Stabilizer Tip Canopy Location Figure 201



REPAIR 1 Page 202 Nov 10/2005



Definitions of the Damage Size Figure 202

3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01	AERODYNAMIC SMOOTHNESS
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05, GENERAL	Repair Sealing
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-05, GENERAL	Fastener Hole Sizes
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05, REPAIR GENERAL	Repair Procedures for Preimpregnated Materials
51-70-06	ROOM TEMPERATURE CURE REPAIRS



REPAIR 1 Page 203 Nov 10/2005



(Continued)

Reference	Title
55-30-30, ALLOWABLE DAMAGE 1	Vertical Stabilizer Tip
AMM 55-33-21/401	Vertical Stabilizer (FIN) Tip Removal/Installation
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Repair Instructions

- A. Refer to paragraph 4.B through 4.G for damage to the vertical stabilizer canopy. Refer to Paragraph 4.H for damage to the vertical stabilizer trailing edge skins.
- B. For dents that are a maximum of 2 inches in diameter and have no fiber damage and delamination, do the steps that follow:
 - (1) Fill the dent with BMS 5-28, Type 7 potting compound.
 - (2) Apply a fiberglass patch over the potted area as given in 51-70-04.
- C. For dents that are not permitted by Paragraph 4.B./REPAIR 1 and for other damage that is not permitted by Allowable Damage 1, refer to Table 201.
- D. Use the instructions that follow to do a Category B repair with wet layup materials at room temperature cure.
 - (1) The edges of the repair must be 3 inches or more away from:
 - (a) The edge of other repairs
 - (b) The edge of the part
 - (c) The edge of other damage. This does not include damage that is permitted and sealed as given in Allowable Damage 1.
 - (2) Repair the damage as given in 51-70-06.
 - (3) Use the same number of repair plies as the number of initial plies that were removed.

Table 201:


	REPAIR DATA	FOR THE 250°F (121°C) C	URE CANOPY	1	
REPAIR TYPE CATEGORY B WET LAYUP		CATEGORY A WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED LAYUP	
REPAIR CURE TEMPERATURE	Room Temperature	150°F (66°C)	200°F (93°C)	250°F (121°C)	
REPAIR SIZE	Damage that is a maximum of: - 1.5 inches in diameter	Damage that is a maximum of: - 3.0 inches in diameter	There are no limits on the dimension of the repair	There are no limits on the dimensions of the repair	
	- 30 percent of the smallest dimension across the panel at the damage location	- 50 percent of the smallest dimension across the panel at the damage location			
REPAIR PROCEDURES	SRM 51-70-06 and Paragraph 4.C	SRM 51-70-04 and Paragraph 4.D	SRM 51-70-04 and Paragraph 4.E	SRM 51-70-05 and Paragraph 4.F	

(4) Do an inspection of the repair every 800 flight hours.

(a) If deterioration is found, replace the repair with a Category A repair.



REPAIR 1 Page 204 Nov 10/2005





- E. Use the instructions that follow to do a Category A repair with wet layup materials at 150°F (66°C) cure.
 - (1) The edges of the repair must be 3 inches or more away from:
 - (a) The edge of other repairs
 - (b) The edge of the part
 - (c) The edge of other damage. This does not include damage that is permitted and sealed as given in Allowable Damage 1.
 - (2) Repair the damage as given in 51-70-04.
 - (a) Use the same number of repair plies as the number of initial plies that were removed.
 - (b) Add one structural ply of BMS 9-3, Type H-2, or Type H-3 glass fabric that is ± 45 degrees.
 - (c) Add a second structural ply of BMS 9-3, Type H-2 or Type H-3 glass fabric that is 0 or 90 degrees.
- F. Use the instructions that follow to do a Category A repair with wet layup materials at 200°F (93°C) cure.
 - (1) Repair the damage as given in 51-70-04.
 - (a) Use the same number of repair plies as the number of initial plies that were removed.
 - (b) Add one structural ply of BMS 9-3, Type H-2, or Type H-3 glass fabric that is ± 45 degrees.
 - (c) Add a second structural ply of BMS 9-3, Type H-2 or Type H-3 glass fabric that is 0 or 90 degrees.
- G. Use the instruction that follows to do a Category A repair with preimpregnated layup materials at 250°F (121°C) cure.
 - (1) Use the same number of repair plies as the number of initial plies that were removed.
- H. For the Category A repair to the vertical stabilizer trailing edge skins do as follows:
 - (1) Remove the damage and initial finishes to a maximum 1.0 inch (25.4 mm) diameter hole as shown in Figure 203.
 - (2) Make sure the surface texture roughness for all cut surfaces is 63 microinches Ra, or smoother at all locations.
 - (3) Make the part [1] Doubler as given in Table 201. Make sure the part [1] Doubler has the same contour as the initial skin.
 - (4) Remove the finish from the trailing edge skin that is common to the part [1] Doubler.
 - (5) Assemble the part [1] Doubler as shown in Figure 203.
 - (6) Drill the necessary fastener holes as shown in Figure 203. Refer to 51-40-05, GENERAL for the fastener hole dimensions.
 - (a) Make sure that the maximum countersink depth is not more than 80 percent of the part [1] Doubler thickness. This will prevent a knife edge condition of the part [1] Doubler.
 - (7) Disassemble the part [1] Doubler.
 - (8) Remove all the nicks, scratches, gouges, burrs from the initial and repair parts.
 - (9) Chamfer the edge of the part [1] Doubler to a 20:1 ratio at all locations.
 - (10) Install the part [1] Doubler and fasteners without sealant.
 - (11) Apply a chemical conversion coating to the part [1] Doubler and to the bare surfaces of the initial skin. Refer to 51-20-01, GENERAL.



REPAIR 1 Page 205 Nov 10/2005



Table 202:

			REPAIR MATERIAL
ITEM	PART	QUANTITY	MATERIAL
[1]	Doubler	1	Use 2024-T3 sheet with a thickness of 0.050 inch (12.70 mm).


- (12) Apply (2) layers of BMS 10-11, Type I primer to the part [1] Doubler and to the bare surfaces of the initial skin. Refer to SOPM 20-41-02.
- (13) Fillet seal the edges of the part [1] doubler and all gaps with BMS 5-95 sealant. Refer to 51-20-05, GENERAL.
- (14) Do a resistance check between the part [1] Doubler and the initial trailing edge skin. Refer to BAC 5117-6 for the test procedures. The maximum resistance that is permitted is 0.010 ohms.
- (15) Apply all initial production drawing finishes as necessary.



55-30-30



737-800 STRUCTURAL REPAIR MANUAL



NOTES

- MAKE SURE THERE IS A MINIMUM OF 2D EDGE MARGIN AT ALL LOCATIONS.
- MAKE SURE THE FASTENER SPACING IS 4D-6D.

FASTENER SYMBOLS

+ REPAIR FASTENER LOCATION. INSTALL A BACR15CE4D() RIVET.

Trailing Edge Skin Lightning Strike Repair Figure 203




REPAIR 1 Page 207 Nov 10/2005



REPAIR 2 - VERTICAL STABILIZER COVE

1. Applicability

- A. Repair 2 is applicable to the vertical stabilizer cove panel made of Glass Fiber Reinforced Plastic (GFRP) shown in Vertical Stabilizer Cove, Figure 201/REPAIR 2.
- B. Repair 2 is applicable to damage that is more than the limits permitted in Allowable Damage 2. Refer to Allowable Damage 2 for the type and size of damage that is permitted.



Vertical Stabilizer Cove Figure 201

2. General

- A. Repair 2 gives instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Get access to the damaged area.



REPAIR 2 Page 201 Nov 01/2003




- (1) If necessary, remove the cove panel.
- (2) Refer to 51-40-02 for information on fastener removal.
- C. Do an inspection of the damaged area to find the dimensions of the damage.
 - (1) Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 for inspection procedures.

NOTE: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.

- D. Refer to Definitions of the Damage Size, Figure 202/REPAIR 2, Details A, B, and C for the definitions of the length, width, and depth of damage.
- E. Do the repair as given in Paragraph 4./REPAIR 2
- F. Put the cove panel back to the initial condition, as applicable.
 - (1) Install the cove panel, if it was removed.
 - (a) Refer to 51-40-02 for information on fastener installation.



55-30-30



Definitions of the Damage Size Figure 202

3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-02, GENERAL	Inspection and Removal of Damage
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05, REPAIR GENERAL	Repair Procedures for Preimpregnated Materials
51-70-06	ROOM TEMPERATURE CURE REPAIRS
55-10-30, ALLOWABLE DAMAGE 2	Horizontal Stabilizer Cove



REPAIR 2 Page 203 Jul 10/2004



4. Repair Instructions

- A. For dents that are a maximum of 2 inches in diameter and have no fiber damage and delamination, do the steps that follow:
 - (1) Fill the dent with BMS 5-28, Type 7 potting compound
 - (2) Apply a fiberglass patch over the potted area as given in 51-70-04.
- B. For dents that are not permitted by Paragraph 4.A./REPAIR 2 and for other damage that is not permitted by Allowable Damage 1, refer to Table 201/REPAIR 2.
- C. Use the instructions that follow to do a Category B repair with wet layup materials at room temperature cure.
 - (1) The edges of the repair must be 3.0 inch or more away from:
 - (a) The edge of other repairs
 - (b) The edge of the part
 - (c) The edge of other damage. This does not include damage that is permitted and sealed as given in Allowable Damage 2.
 - (2) Repair the damage as given in 51-70-06.
 - (3) Use the same number of repair plies as the number of initial plies that were removed.
 - (4) Do an inspection of the repair each 800 flight hour interval or more frequently.
 - (a) If deterioration is found, replace the repair with a Category A repair.

Table 201 :	Та	b	e	201	:
--------------------	----	---	---	-----	---

REPAIR DATA FOR THE 250°F (121°C) CURE COVE PANELS				
REPAIR TYPE CATEGORY B WET LAYUP		CATEGORY A WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED LAYUP
REPAIR CURE TEMPERATURE	Room Temperature	150°F (66°C)	200°F (93°C)	250°F (121°C)
REPAIR SIZE	Damage that is a maximum of:	Damage that is a maximum of:	There are no limits on the dimension of the repair	There are no limits on the dimensions of the repair
	- 1.5 inches in diameter	- 3.0 inches in diameter		
	- 30 percent of the smallest dimension across the panel at the damage location	- 50 percent of the smallest dimension across the panel at the damage location		
	One repair is permitted for each 144 square inches of panel area	One repair is permitted for each 144 square inches of panel area		
REPAIR PROCEDURES	SRM 51-70-06 and Paragraph 4.C	SRM 51-70-04 and Paragraph 4.D	SRM 51-70-04 and Paragraph 4.E	SRM 51-70-05 and Paragraph 4.F

- D. Use the instructions that follow to do a Category A repair with wet layup materials at 150°F (66°C) cure.
 - (1) The edges of the repair must be 3.0 inch or more away from:
 - (a) The edge of other repairs
 - (b) The edge of the part



REPAIR 2 Page 204 Jul 10/2004




- (c) The edge of other damage. This does not include damage that is permitted and sealed as given in Allowable Damage 2.
- (2) Repair the damage as given in 51-70-04.
 - (a) Use the same number of repair plies as the number of initial plies that were removed.
 - (b) Add one structural ply of BMS 9-3, Type H-2, or Type H-3 glass fabric that is ± 45 degrees.
 - (c) Add a second structural ply of BMS 9-3, Type H-2 or Type H-3 glass fabric that is 0 or 90 degrees.
- E. Use the instructions that follow to do a Category A repair with wet layup materials at 200°F (93°C) cure.
 - (1) Repair the damage as given in 51-70-04.
 - (a) Use the same number of repair plies as the number of initial plies that were removed.
 - (b) Add one structural ply of BMS 9-3, Type H-2, or Type H-3 glass fabric that is ± 45 degrees.
 - (c) Add a second structural ply of BMS 9-3, Type H-2 or Type H-3 glass fabric that is 0 or 90 degrees.
- F. Use the instruction that follows to do a Category A repair with preimpregnated layup materials at 250°F (121°C) cure.
 - (1) Use the same number of repair plies as the number of initial plies that were removed.



REPAIR 2 Page 205 Jul 10/2004



IDENTIFICATION 1 - VERTICAL STABILIZER FITTINGS



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Vertical Stabilizer Fittings Location Figure 1

Table 1:

REFERENCE DRAWINGS		
DRAWING NUMBER	TITLE	
172A1001	Rear Spar Assembly / Installation - Vertical Fin	
172A2001	Front Spar Assembly / Installation - Vertical Fin	
175A0001	Trailing Edge Functional Collector - Vertical Fin	



Page 1




Figure 2



Page 2

D634A210 BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details



Table 2:

LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Hinge Fitting		7050-T7451 plate as given in BMS 7-323, Type I. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)	
[2]	Rudder Attach Hinge Plate (4)		7075-T7351 rolled plate as given in QQ-A-250/12, Class A. Refer to the production drawing for the machined thicknesses. (Grain direction controlled part)	
[3]	Beam, Support Fitting		7050-T7451 plate as given in AMS 4050, Class A. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)	
[4]	Rudder Attach Hinge Plate (3)		7075-T7351 plate as given in QQ-A-250/12, Class A. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)	
[5]	Rudder Attach Hinge Plate Assembly			
	Hinge Plate		7075-T7351 plate as given in QQ-A-250/12, Class A. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)	
	Retainer		15-5PH CRES as given in BMS 7-240 Type I, heat treated to 180-200 KSI. Refer to the production drawing for the machined thicknesses	
	Retainer		7075-T7351 plate as given in QQ-A-250/12, Class A. Refer to the production drawing for the machined thicknesses	
[6]	Rudder Attach Hinge Plate Assembly			
	Hinge Plate		7075-T7351 plate as given in QQ-A-250/12, Class A. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)	
	Bearing Retainer		15-5PH CRES as given in BMS 7-240 Type I, heat treated to 180-200 KSI. Refer to the production drawing for the machined thicknesses	
[7]	Hinge Fitting Assembly			
	Fitting, Upper		7050-T7451 plate as given in AMS 4050, Class A. Refer to the production drawing for the machined thicknesses	
	Fitting, Lower		7050-T7451 plate as given in BMS 7-323, Type I. Refer to the production drawing for the machined thicknesses	
[8]	Rear Spar Primary Fitting (2)		Ti-6AI-4V titanium machined forged block as given in MIL-T-9047, annealed. Refer to the production drawing for the machined thicknesses	
[9]	Rear Spar Failsafe Fitting (2)		Ti-6AI-4V titanium machined forged block as given in MIL-T-9047, annealed. Refer to the production drawing for the machined thicknesses	
[10]	Rear Spar Tension Tie Fitting		7075-T73 forged block as given in BMS 7-186, Class A. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)	

IDENTIFICATION 1 Page 3 Nov 01/2003



	LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY	
[11]	Front Spar Termination Fitting		7075-T73 forging as given in BMS 7-186, Class A. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)		
[12]	Rear Spar Failsafe Fitting		7075-T651 plate as given in QQ-A-250/12. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)		
[13]	Rear Spar Fitting Strap (2)		7075-T7351 plate as given in QQ-A-250/12. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)		
[14]	Hinge Fitting		7050-T7451 plate as given in BMS 7-323, Type I. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)		
[15]	Hinge Fitting Assembly				
	Fitting		7050-T7451 plate as given in BMS 7-323, Type I. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)		
	Failsafe Doubler		7050-T7451 plate as given in BMS 7-323, Type I. Refer to the production drawing for the machined thicknesses (Optional: 7050-T7451 plate as given in AMS 4050 (Grain direction controlled part)		
[16]	Hinge Fitting (2)		7050-T7451 plate as given in AMS 4050, Class A. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)		
[17]	Hinge Fitting		7050-T7451 plate as given in AMS 4050, Class A. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)		
[18]	Hinge Fitting		7050-T7451 plate as given in BMS 7-323, Type I. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)		
[19]	Hinge Fitting		7050-T7451 plate as given in BMS 7-323, Type I. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)		
[20]	Hinge Fitting		7050-T7451 plate as given in BMS 7-323, Type I. Refer to the production drawing for the machined thicknesses (Grain direction controlled part)		
[21]	Beam Support Fitting		7050-T7451 plate as given in AMS 4050, Class A. Refer to the production drawing for the machined thicknesses		

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).




IDENTIFICATION 1 Page 4 Nov 01/2003



ALLOWABLE DAMAGE 1 - VERTICAL STABILIZER FITTINGS

1. Applicability

A. This subject gives the allowable damage limits for the fittings that attach to the vertical stabilizer shown in Vertical Stabilizer Fitting Locations, Figure 101/ALLOWABLE DAMAGE 1.




Vertical Stabilizer Fitting Locations Figure 101 (Sheet 1 of 2)





737-800 STRUCTURAL REPAIR MANUAL







2. General

- A. Remove the parts as necessary to get access to the vertical stabilizer fittings.
- B. Refer to Table 101/ALLOWABLE DAMAGE 1 for a list of the references for the allowable damage limits.

Table 101:

PARAGRAPH REFERENCES FOR THE ALLOWABLE DAMAGE LIMITS				
STRUCTURAL PART	PARAGRAPH			
End Pads	4.A			
Gussets	4.A			
Webs	4.A			
Attach Flanges	4.A			
Rear Spar Strap	4.A			
Hinge Plates	4.B			
Bearing Retainers	4.C			
Lugs	4.C			
Rear Spar Terminal Fittings	4.D			

- WARNING: SMALL PARTICLES AND THIN CUTS OF TITANIUM ARE FLAMMABLE. IN A SUFFICIENT CONCENTRATION, AN EXPLOSION CAN OCCUR. EXTINGUISH FIRES OF TITANIUM WITH FULLY DRY TALC, CALCIUM CARBONATE, SAND OR GRAPHITE. APPLY THE POWDER TO A DEPTH OF 1/2 INCH OR MORE ON THE AREA THAT IS ON FIRE. DO NOT USE FOAM, WATER, CARBON TETRACHLORIDE, HALON OR CARBON DIOXIDE. WATER IN CONTACT WITH MOLTEN TITANIUM CAN CAUSE A STREAM EXPLOSION. IF YOU DO NOT OBEY, AN INJURY CAN OCCUR.
- C. Do the steps that follow if you have damage to the aluminum, Corrosion Resistant Steel (CRES), or titanium parts:
- D. Remove the damage as necessary.
 - (1) Refer to 51-10-02 for the investigation and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of nonmetallic materials you need to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
- E. After you remove the damage, do the procedures that follow:
 - (1) Do a penetrant inspection to all parts except the rear spar strap and the bearing retainers to make sure that all the damage is removed. Refer to SOPM 20-20-02.
 - (2) Apply a chemical conversion coating to the bare surfaces of the aluminum parts. Refer to 51-20-01.
 - (3) Apply cadmium plating to the bare surfaces of the CRES parts. Refer to SOPM 20-42-05.
 - (4) Apply 2 layers of BMS 10-11, Type I primer to the surfaces of all reworked areas except the fitting straps, primary fittings, and failsafe fittings of the rear spar. Refer to SOPM 20-41-02.

NOTE: Do not apply the BMS 10-11, Type I primer to the holes of the fittings.






(5) Apply a layer of BMS 10-11, Type I primer to the surfaces of the fitting straps, primary fittings, and failsafe fittings of the rear spar. Refer to SOPM 20-41-02.

NOTE: Do not apply the BMS 10-11, Type I primer to the holes of the fittings.





NOTES


• ALL THE PARTS IDENTIFIED ARE MACHINED ALUMINUM.

Vertical Stabilizer Hinge and Beam Support Fittings Figure 102 (Sheet 1 of 7)




BOEING®

737-800 STRUCTURAL REPAIR MANUAL



HINGE FITTING AT RUDDER STATION 276.24

А




Vertical Stabilizer Hinge and Beam Support Fittings Figure 102 (Sheet 2 of 7)





737-800 STRUCTURAL REPAIR MANUAL




Vertical Stabilizer Hinge and Beam Support Fittings Figure 102 (Sheet 3 of 7)






737-800 STRUCTURAL REPAIR MANUAL



BOEING PROPRIETARY - Copyright ${\rm (\sc)}$ Unpublished Work - See title page for details

BOEING®

737-800 STRUCTURAL REPAIR MANUAL




D634A210

Page 109




737-800 STRUCTURAL REPAIR MANUAL





737-800 STRUCTURAL REPAIR MANUAL



HINGE FITTING AT RUDDER STATION 6.96

Vertical Stabilizer Hinge and Beam Support Fittings Figure 102 (Sheet 7 of 7)



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



3. <u>References</u>

Reference	Title
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-40-05, GENERAL	Fastener Hole Sizes
51-40-06, GENERAL	Fastener Edge Margins
51-40-08, GENERAL	Countersink Data and Procedures for Metal Structures
SOPM 20-20-02	Penetrant Methods of Inspection
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes
SOPM 20-42-05	Bright Cadmium Plating
SOPM 20-50-03	Bearing and Bushing Replacement

4. Allowable Damage Limits

A. End Pads, Gussets, Webs, Attach Flanges, and Rear Spar Strap

_....


- (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 105/ALLOWABLE DAMAGE 1, Details A, B, and C.
- (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 105/ALLOWABLE DAMAGE 1, Detail A, B, C, D, E, F, and G.
- (3) Dents are not permitted.
- (4) Holes and Punctures are not permitted.
- B. Hinge Plates
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 105/ALLOWABLE DAMAGE 1, Details A and B.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 105/ALLOWABLE DAMAGE 1, Detail A, B, D, and E.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- C. Lugs and Bearing Retainers
 - **NOTE**: No damage is permitted in the surface of the lug bore. You are permitted to drill the bore to a maximum oversize diameter of 0.06 inch more than the initial bore diameter if:
 - There is no damage on the edge of the lug initial bore





- You follow the bushing removal procedures as given in SOPM 20-50-03.
- (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 105/ALLOWABLE DAMAGE 1, Details H and I.
- (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 105/ALLOWABLE DAMAGE 1, Details H and I.
- (3) Dents are not permitted.
- (4) Holes and Punctures are not permitted.
- D. Rear Spar Terminal Fittings
 - (1) Damage is not permitted.






Vertical Stabilizer Rudder Attach Hinge Plates and Beam Support Figure 103 (Sheet 1 of 2)






737-800 STRUCTURAL REPAIR MANUAL




TYPICAL ATTACH HINGE FITTING (LOCATED AT RUDDER STATIONS 276.24, 257.93, 239.61, 212.15, 184.67, 129.74, 74.80, AND 6.96)

А




RUDDER ATTACH HINGE PLATE AT RUDDER STATION 66.42 (B)



RUDDER ATTACH HINGE PLATE AT RUDDER STATION 56.48


Vertical Stabilizer Rudder Attach Hinge Plates and Beam Support Figure 103 (Sheet 2 of 2)








737-800 STRUCTURAL REPAIR MANUAL




TYPICAL REAR SPAR TERMINAL, PRIMARY, AND FAILSAFE FITTING (A)






D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details







737-800 STRUCTURAL REPAIR MANUAL




Vertical Stabilizer Spar Fittings Figure 104 (Sheet 4 of 4)



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details

BOEING


737-800 STRUCTURAL REPAIR MANUAL




D634A210

Nov 01/2003









Allowable Damage Limits Figure 105 (Sheet 3 of 5)



D634A210






Allowable Damage Limits Figure 105 (Sheet 5 of 5)

> ALLOWABLE DAMAGE 1 55-30-90 Page 124 Nov 01/2003

D634A210



REPAIR GENERAL - VERTICAL STABILIZER HINGE FITTINGS




NOTE: THERE ARE NO REPAIRS FOR THESE PARTS IN THE STRUCTURAL REPAIR MANUAL AT THIS TIME.

Vertical Stabilizer Fitting Repair Figure 201 (Sheet 1 of 2)



REPAIR GENERAL Page 201 Nov 10/2006






D034A210



IDENTIFICATION 1 - RUDDER SKIN



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Rudder Skin Location Figure 1

Table 1:

	REFERENCE DRAWINGS		
DRAWING NUMBER	TITLE		
173A0000	Rudder Integration Functional Product Collector		
173A0001	Installation- Rudder		
173A0100	Rudder Functional Product Collector		
173A0150	Centerline Diagram - Rudder		
173A4000	Skin Panel Installation-Rudder		
173A4001	Skin Panel Assembly - Rudder		




D634A210



	REFERENCE DRAWINGS		
DRAWING NUMBER	TITLE		
173A4300	Cover Panel Assembly - Rudder		
173A4301	Gap Cover Assembly - Balance Arm, Rudder		
173A5000	Balance Arm Installation - Rudder		
173A5001	Balance Arm Assembly - Rudder		






BOEING PROPRIETARY - Copyright C Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.


LEFT SIDE BALANCE ARM IS SHOWN, RIGHT SIDE IS OPPOSITE (EXCEPT AS NOTED)

В

Rudder Skin Identification Figure 2 (Sheet 2 of 3)



IDENTIFICATION 1 Page 4 Nov 01/2003



Page 5



Table 2:


	LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY	
[1]	Rudder Skin - Bonded Part		Non-metallic honeycomb sandwich		
	Skin		Refer to Figure 3		
	Core - Lower Closure Rib to RUD STA 61.39		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0		
	Core - RUD STA 61.39 to RUD STA 164.90		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0		
	Core - RUD STA 164.90 to RUD STA 282.17		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0		
	Core - Aft of Rudder Front Spar RUD STA 282.17 to FIN WATERLINE 270		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0		
	Core - Forward of Rudder Front Spar RUD STA 282.17 to FIN WATERLINE 270		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0		
[2]	Conductive Frame	0.020 (0.51)	6061-T4 sheet		
[3]	Doubler, Balance Arm - Rudder	0.025 (0.64)	Ti-6AI-4V titanium plate as given in MIL-T-9046, AB-1, Condition A		
[4]	Strap - Bonded		Epoxy impregnated graphite woven fabric. Refer to Figure 4		
[5]	Strap - Bonded		Epoxy impregnated graphite woven fabric. Refer to Figure 5		
[6]	Skin Panel		Fiberglass prepreg fabric. Refer to Figure 6		
[7]	Skin Panel		Fiberglass prepreg fabric. Refer to Figure 7		
[8]	Skin Panel		Fiberglass prepreg fabric. Refer to Figure 8		
[9]	Skin Panel		Fiberglass prepreg fabric. Refer to Figure 9		
[10]	Cover Panel	0.063 (1.60)	2024-T3 clad sheet		
[11]	Cover Panels (2)	0.063 (1.60)	2024-T3 clad sheet		
[12]	Gap Cover Assembly				
	Cover	0.063 (1.60)	2024-T3 clad sheet		
	Splice Plate	0.080 (2.03)	2024-T3 clad sheet (Optional: 2024-T42)		

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





737-800 STRUCTURAL REPAIR MANUAL





Ply Direction, Ply Sequence and Core Ribbon Direction for Figure 2, Item [1] Figure 3 (Sheet 1 of 4)





737-800 STRUCTURAL REPAIR MANUAL











737-800 STRUCTURAL REPAIR MANUAL



PLY LAYUP SEQUENCE

D-D




E-E


Ply Direction, Ply Sequence and Core Ribbon Direction for Figure 2, Item [1] Figure 3 (Sheet 3 of 4)



BOEING®

737-800 STRUCTURAL REPAIR MANUAL






PLY LAYUP SEQUENCE

F-F

PLY LAYUP SEQUENCE

G-G



Ply Direction, Ply Sequence and Core Ribbon Direction for Figure 2, Item [1] Figure 3 (Sheet 4 of 4)






Table 3:


	PLY MATERIAL AND DIRECTION FOR FIGURE 3		
PLY	DIRECTION	MATERIAL	
P1		Co-cure surfacer as given in BMS 8-341, Type II	
P2, P53, P54, P55, P56, P57, P58, P59, P60	Optional	Epoxy impregnated glass woven fabric as given in BMS 8-139, Class III, Style 108	
P3, P5, P6, P7, P8, P13, P14, P15, P16, P19, P20, P32, P33, P35, P36, P37, P38, P43, P44, P45, P46, P49, P50, P52	+ or - 45 degrees	Epoxy impregnated graphite woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70- PW	
P4, P9, P10, P11, P12, P17, P18, P21, P34, P39, P40, P41, P42, P47, P48, P51	0 or 90 degrees	Epoxy impregnated graphite woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70- PW	
P22, P23, P24, P25, P26, P27, P28, P29, P30, P31		Adhesive film as given in BMS 8-245, Type II, Class 1, Grade 03A	
P61		1 mil white bondable tedlar film as given in BAC 5315-4	





737-800 STRUCTURAL REPAIR MANUAL





Ply Direction and Ply Sequence for Figure 2, Item [4] Figure 4






Table 4:

PLY MATERIAL AND DIRECTION FOR FIGURE 4			
PLY DIRECTION MATERIAL			
P1, P3, P5, P7	0 or 90 degrees	Epoxy impregnated graphite woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70- PW	
P2, P4, P6	+ or - 45 degrees	Epoxy impregnated graphite woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70- PW	



DEING®

737-800 STRUCTURAL REPAIR MANUAL



Ply Direction and Ply Sequence for Figure 2, Item [5] Figure 5






Table 5:


PLY MATERIAL AND DIRECTION FOR FIGURE 5			
PLY DIRECTION MATERIAL			
P1, P3, P5, P7, P9	0 or 90 degrees	Epoxy impregnated graphite woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70- PW	
P2, P4, P6, P8	+ or - 45 degrees	Epoxy impregnated graphite woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70- PW	





737-800 STRUCTURAL REPAIR MANUAL





A-A

Ply Direction and Ply Sequence for Figure 2, Item [6] Figure 6






Table 6:


PLY MATERIAL AND DIRECTION FOR FIGURE 6			
PLY DIRECTION MATERIAL			
P1, P3, P6, P8	+ or - 45 degrees	Fiberglass prepreg fabric as given in BMS 8-79, Style 7781, Class III, Grade B, (Style 1581 is optional)	
P2, P4, P5, P7	0 or 90 degrees	Fiberglass prepreg fabric as given in BMS 8-79, Style 7781, Class III, Grade B, (Style 1581 is optional)	





737-800 STRUCTURAL REPAIR MANUAL





Ply Direction and Ply Sequence for Figure 2, Item [7] Figure 7






Table 7:


PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [7]			
PLY DIRECTION MATERIAL			
P1, P3, P6, P8	+ or - 45 degrees	Fiberglass prepreg fabric as given in BMS 8-79, Style 7781, Class III, Grade B, (Style 1581 is optional)	
P2, P4, P5, P7	0 or 90 degrees	Fiberglass prepreg fabric as given in BMS 8-79, Style 7781, Class III, Grade B, (Style 1581 is optional)	





737-800 STRUCTURAL REPAIR MANUAL





Ply Direction and Ply Sequence for Figure 2, Item [8] Figure 8






Table 8:


PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [8]			
PLY DIRECTION MATERIAL			
P1, P3, P6, P8	+ or - 45 degrees	Fiberglass prepreg fabric as given in BMS 8-79, Style 7781, Class III, Grade B, (Style 1581 is optional)	
P2, P4, P5, P7	0 or 90 degrees	Fiberglass prepreg fabric as given in BMS 8-79, Style 7781, Class III, Grade B, (Style 1581 is optional)	





737-800 STRUCTURAL REPAIR MANUAL





A-A

Ply Direction and Ply Sequence for Figure 2, Item [9] Figure 9





Table 9:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [9]			
PLY DIRECTION MATERIAL			
P1, P3, P6, P8	+ or - 45 degrees	Fiberglass prepreg fabric as given in BMS 8-79, Style 7781, Class III, Grade B, (Style 1581 is optional)	
P2, P4, P5, P7	0 or 90 degrees	Fiberglass prepreg fabric as given in BMS 8-79, Style 7781, Class III, Grade B, (Style 1581 is optional)	




D634A210



ALLOWABLE DAMAGE 1 - RUDDER SKIN

1. Applicability

A. Allowable Damage 1 gives the allowable damage limits for the Rudder Skin shown in Rudder Skin Location, Figure 101/ALLOWABLE DAMAGE 1.



Rudder Skin Location Figure 101

2. General

- A. Do an inspection of the damaged area to find the length, width and depth of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 for inspection procedures.
 - **NOTE**: Other equivalent inspection methods that have been examined and found to be satisfactory by the operator can be used.
 - (1) For the honeycomb core areas, the tap test is an alternative procedure to an instrumented NDT.
 - (2) Refer to Definitions of Damage Size, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, and C for the definitions of the length, width, and depth of the damage.
- B. Remove all contamination and water from the structure.
 - (1) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (2) Refer to 51-30-05 for possible sources of equipment and tools you can use to remove the damage.
 - (3) Refer to 51-70-04 for the damage removal procedures.





- C. Seal all permitted damage areas that are not more than one ply deep and agree with the allowable damage limits. Refer to Paragraph 4./ALLOWABLE DAMAGE 1 Seal the damage with one of the two methods that follow:
 - (1) Make a temporary seal.
 - (a) Apply aluminum foil tape (speed tape).
 - (b) Keep a record of the location.
 - (c) Make sure that the tape is in satisfactory condition at normal maintenance intervals.
 - (2) Make a permanent seal.
 - (a) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given in 51-70-08.
 - (b) Apply one layer of BMS 10-79, Type III or BMS 10-103, Type I primer. Refer to SOPM 20-44-04.
 - (c) Apply one layer of BMS 10-60, Type II enamel to the exterior surfaces of the areas sealed with epoxy resin. Refer to AMM 51-21-00/701.
- D. Seal all permitted damage areas that are more than one ply deep and agrees with the allowable damage limits as follows:
 - (1) Use a vacuum and heat to remove moisture from the solid laminate and/or honeycomb cells. Refer to 51-70-04.
 - (2) Make a temporary seal with aluminum foil tape (speed tape).
 - (3) Keep a record of the location.
 - (4) Repair the damage at or before 250 flight cycles from the time the seal was made.
- E. Refer to Rudder Skin Zones, Figure 103/ALLOWABLE DAMAGE 1 for the locations of the rudder skin zones.
- F. Make sure that the rudder is balanced. Refer to 51-60-07 for the balance procedures.

PARAGRAPH REFERENCES FOR THE ALLOWABLE DAMAGE LIMITS		
TYPE OF STRUCTURE	ZONE LOCATION	PARAGRAPH
HONEYCOMB CORE AREA	1	4.A
	2	4.B
	3	4.C
	4	4.D
	5	4.E
SOLID LAMINATE AREA	6	4.F
	7	4.G

Table 101:

3. References

Reference	Title
51-10-01, GENERAL	Aerodynamic Smoothness Requirements
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05, GENERAL	Repair Sealing
51-30-03	NON-METALLIC MATERIALS

ALLOWABLE DAMAGE 1 **55-40-01** Page 102 Nov 10/2005

D634A210



(Continued)

Reference	Title
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-60-07	RUDDER BALANCE PROCEDURE
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-06, REPAIR GENERAL	Room Temperature Cure Repairs With Wet Layup Materials For Glass Fabric Reinforced Plastic Solid Laminates and Honeycomb Core Panels
51-70-08	RESIN SWEEP-FAIR PROCEDURES
AMM 51-21-00/701	Interior And Exterior Finishes - Cleaning/Painting
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Allowable Damage Limits

- A. Zone 1 Honeycomb Core Area
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
 - (3) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum of 5.00 inches in length
- (c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.
 - NOTE: Other damage does not include nicks, gouges, and scratches that:
 - Do not cause damage to the glass fiber plies
 - Are sealed as given in Paragraph 2
- (4) Dents that do not cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one carbon ply in depth

NOTE: Use the limits for holes and punctures if there is carbon fiber damage or if the dent depth is more than one carbon ply in depth.

- (b) A maximum of 2.0 inches in diameter
- (c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass fiber plies
- Are sealed as given in Paragraph 2
- (5) Holes and Punctures are permitted if they are:
 - (a) A maximum of 2.0 inches in diameter.
 - (b) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that are sealed as given in Paragraph 2.

(6) Delaminations are permitted if they are:





- (a) A maximum of 2.0 inches in diameter of the carbon ply
- (b) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass fiber plies
- Are sealed as given in Paragraph 2
- B. Zone 2 Honeycomb Core Area
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
 - (3) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum of 5.0 inches in length
- (c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass fiber plies
 - Are sealed as given in Paragraph 2
- (4) Dents that do not cause damage to the carbon fibers are permitted if they:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth

- (b) A maximum of 2.0 inches in diameter
- (c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass fiber plies
- Are sealed as given in Paragraph 2
- (5) Holes and Punctures are permitted if they are:
 - (a) A maximum of 2.0 inches in diameter
 - (b) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that are sealed as given in Paragraph 2.

- (6) Delaminations are permitted if they are:
 - (a) A maximum of 2.00 inches in diameter of the carbon ply
 - (b) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass or carbon fiber plies
- Are sealed as given in Paragraph 2
- C. Zone 3 Honeycomb Core Area
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted.



Page 104

Nov 10/2005



- (2) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
- (3) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum of 5.0 inches in length
- (c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass or carbon fiber plies
- Are sealed as given in Paragraph 2
- (4) Dents that do not cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one carbon ply in depth

- (b) A maximum of 2.0 inches in diameter
- (c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass or carbon fiber plies
- Are sealed as given in Paragraph 2
- (5) Holes and Punctures are permitted if they are:
 - (a) A maximum of 2.0 inch in diameter
 - (b) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that are sealed as given in Paragraph 2

- (6) Delaminations are permitted if they are:
 - (a) A maximum of 2.0 inches in diameter of the carbon ply
 - (b) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass or carbon fiber plies
- Are sealed as given in Paragraph 2
- D. Zone 4 Honeycomb Core Area
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
 - (3) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

(b) A Maximum of 5.0 inches in length

ALLOWABLE DAMAGE 1 55-40-01 Page 105 Nov 10/2005



(c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass or carbon fiber plies
- Are sealed as given in Paragraph 2
- (4) Dents that do not cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one carbon ply in depth.

- (b) A maximum of 2.0 inches in diameter
- (c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass or carbon fiber plies
- Are sealed as given in Paragraph 2
- (5) Holes and Punctures are permitted if they are:
 - (a) A maximum of 2.0 inches in diameter
 - (b) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.
 - **NOTE**: Other damage does not include nicks, gouges, and scratches that are sealed as given in Paragraph 2.
 - 1) Are sealed as given in Paragraph 2
- (6) Delaminations are permitted if they are:
 - (a) A maximum of 2.00 inches in diameter
 - (b) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.
 - NOTE: Other damage does not include nicks, gouges, and scratches that:
 - Do not cause damage to the glass or carbon fiber plies
 - Are sealed as given in Paragraph 2
- E. Zone 5 Honeycomb Core Area
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that cause damage to the glass fibers are permitted.
 - (3) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth
 - **NOTE**: Use the limits for holes and punctures if the damage is more than one ply in depth.
 - (b) A maximum of 5.0 inches in length
 - (c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass or carbon fiber plies
 - Are sealed as given in Paragraph 2
- (4) Dents that do not cause damage to the carbon fibers are permitted if they are:





(a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one carbon ply in depth.

- (b) A maximum of 2.0 inches in diameter
- (c) A minimum of 5.00 inches away from the edge
- (5) Holes and Punctures are permitted if they are:
 - (a) A maximum of 2.0 inches in diameter
 - (b) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that are sealed as given in Paragraph 2.

- (6) Delaminations are permitted if they are:
 - (a) The diameter is a maximum of 2.0 inches
 - (b) The damage is a minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass or carbon fiber plies
- Are sealed as given in Paragraph 2
- F. Zone 6 Solid Laminate Areas
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that cause damage to the glass fibers are permitted.
 - (3) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum of 0.625 inch in length
- (c) A maximum of 0.25 inch in width
- (d) Not more than one fastener or fastener hole in eight is damaged
- (e) A minimum of 5.00 inches away from the edge of any damaged hole, damaged part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass or carbon fiber plies
- Are sealed as given in Paragraph 2
- (4) Dents that do not cause damage to the carbon fibers are permitted if they are:
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum of 0.625 inch in diameter
- (c) Not more than one fastener hole in eight is damaged



- (d) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.
 - NOTE: Other damage does not include nicks, gouges, and scratches that:
 - Do not cause damage to the glass or carbon fiber plies
 - Are sealed as given in Paragraph 2
- (5) Holes and Punctures are permitted if:
 - (a) Not more than one fastener or fastener hole in eight is damaged
 - (b) A maximum of 0.625 inch in diameter
 - (c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that are sealed as given in Paragraph 2.

- (6) Delaminations are permitted if:
 - (a) Not more than one fastener or fastener hole in eight is damaged
 - (b) A maximum of 0.625 inch in diameter
 - (c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass or carbon fiber plies
 - Are sealed as given in Paragraph 2
- (7) Edge Erosion is permitted as shown in Upper and Lower Elevator Skin Panel Allowable Damage, Figure 104/ALLOWABLE DAMAGE 1.
- (8) Edge damage is permitted if it is:
 - (a) A maximum of one ply in depth
 - (b) A maximum of 0.25 inch in width
- G. Zone 7 Solid Laminate Areas
 - (1) Nicks, Gouges, and Scratches that do cause damage to the glass fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
 - (3) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if they are :
 - (a) A maximum of one ply in depth

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) A maximum of 0.625 inch in length
- (c) A maximum of 0.25 inch in width
- (d) Not more than one fastener or fastener hole in eight is damaged
- (e) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass or carbon fiber plies
 - Are sealed as given in Paragraph 2
- (4) Dents are permitted if:
 - (a) Not more than one fastener or fastener hole in ten is damaged
 - (b) They are a maximum of one ply in depth





- (c) A maximum of 0.625 inch in diameter
- (d) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass or carbon fiber plies
- Are sealed as given in Paragraph 2
- (5) Holes and Punctures are permitted if:
 - (a) Not more than one fastener or fastener hole in eight is damaged
 - (b) A maximum of 0.625 inch in diameter
 - (c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.
- (6) Delaminations are permitted if:
 - (a) Not more than one fastener or fastener hole in eight is damaged
 - (b) A maximum of 0.625 inch in diameter
 - (c) A minimum of 5.00 inches away from the edge of any hole, part edge or other damage.

NOTE: Other damage does not include nicks, gouges, and scratches that:

- Do not cause damage to the glass or carbon fiber plies
- Are sealed as given in Paragraph 2
- (7) Edge Erosion is permitted as shown in Upper and Lower Elevator Skin Panel Allowable Damage, Figure 104/ALLOWABLE DAMAGE 1.
- (8) Edge damage is permitted if it is:
 - (a) A maximum of one ply in depth
 - (b) A maximum of 0.25 inch in width.
- H. Zone 8 Honeycomb Core Area
 - (1) The same limits as described in either Zone 2 or Zone 4 are permitted.
- I. Lightning Strike Trailing Edge Damage
 - (1) You are permitted to remove damage as given in Figure 105 provided:
 - (a) There are a minimum of (10) fastener lengths not damaged between any (2) damaged fastener locations.
 - (b) The damage removal is to both the right and left side skin panel.
 - **NOTE:** Damage removal is permitted to both sides of the skin panel at the same fastener location. Refer to Figure 105.




Page 109

Nov 10/2005

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details

BOEING

737-800 STRUCTURAL REPAIR MANUAL



55-40-01 Page 110 Nov 01/2003





Figure 103

ALLOWABLE DAMAGE 1 Page 111 55-40-01 Nov 10/2005

D634A210





SEALING OF EROSION DAMAGE AT AN EDGE OF COMPOSITE PARTS


Upper and Lower Elevator Skin Panel Allowable Damage Figure 104



D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL



NOTES

1 DAMAGE IS NOT PERMITTED INTO THE HONEYCOMB RAMP AREA.

2 > make sure there are a minimum of ten (10) fasteners not damaged between any ADJACENT LIGHTNING STRIKE DAMAGE.

> Rudder Skin Trailing Edge Lightning Strike Damage Figure 105




Page 113



ALLOWABLE DAMAGE 2 - RUDDER BALANCE ARM SKIN

1. Applicability

A. This subject gives the allowable damage limits for the skin panels on the rudder balance arm as shown in Rudder Balance Arm Skin Location, Figure 101/ALLOWABLE DAMAGE 2.



Rudder Balance Arm Skin Location Figure 101

2. <u>General</u>

- A. Do an inspection of the damaged area to find the length, width and depth of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 for inspection procedures.
 - **NOTE**: Other equivalent inspection procedures that have been examined and found to be satisfactory by the operator, can be used.
- B. Refer to Definitions of Damage Size, Figure 102/ALLOWABLE DAMAGE 2, Details A, B, and C for the definitions of the length, width, and depth of damage.
- C. Remove contamination and water from the structure surface.
- D. Seal all permitted damage areas that agree with the allowable damage limits given in Paragraph 4./ALLOWABLE DAMAGE 2 Seal the damage with one of the two methods that follows:
 - (1) Make a temporary seal for damage 1 ply deep or less.
 - (a) Apply aluminum foil tape (speed tape).
 - (b) Keep a record of the location.
 - (c) Make sure that the tape is in a satisfactory condition at normal maintenance intervals.
 - (2) Make a permanent seal for damage 1 ply deep or less.






- (a) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given in 51-70-08.
- (b) Apply one layer of BMS 10-79, Type III primer. Refer to SOPM 20-44-04.
- (c) Apply one layer of BMS 10-60 enamel to the areas sealed with epoxy resin. Refer to AMM 51-21-00/701.
- (3) For damage to locations that are more 1 ply in depth then do as follows:
 - (a) Apply vacuum and heat to the damage area to remove all moisture.
 - (b) Apply aluminum foil tape (speed tape)
 - (c) Keep a record of the location
 - (d) Repair the damage before 250 flight cycles from the time the seal was made



BOEING

737-800 STRUCTURAL REPAIR MANUAL



ALLOWABLE DAMAGE 2 Page 103 Nov 01/2003



3. References

Reference	Title
51-30-03, GENERAL	Sources for Non-Metallic Repair Materials
51-30-05, GENERAL	Equipment and Tools For Repairs
51-70-08	RESIN SWEEP-FAIR PROCEDURES
AMM 51-21-00/701	Interior And Exterior Finishes - Cleaning/Painting
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Allowable Damage Limits

- A. Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted.
- B. Nicks, Gouges, and Scratches that cause damage to the glass fibers are permitted if:
 - (1) The depth is a maximum of one ply. If the depth is more than one ply, then use the limits for holes and punctures
 - (2) Not more than one fastener hole in six is damaged
 - (3) The damage is 6D (D = diameter of fastener) away from fasteners
 - (4) Damage is less than 0.625 inch in length
 - (5) Damage is a minimum of 4.0 inches away from other damage.
- C. Dents are permitted if:
 - (1) The glass fiber is not damaged. If the glass fiber is damaged, then use the limits for nicks, gouges and scratches
 - (2) The diameter is a maximum of 0.625 inch
 - (3) The depth is not more than one ply deep
 - (4) The dent is 6D (D = diameter of fastener) away from fastener locations
 - (5) Thd damage is a minimum of 4.0 inches away from other damage.
- D. Holes and Punctures are permitted if:
 - (1) The diameter is a maximum of 0.625 inch
 - (2) The damage is 6D (D = diameter of fastener) away from fastener locations
 - (3) The damage is a mimimum of 4.00 inches away from other damage.
- E. Delaminations are permitted if:
 - (1) The diameter is a maximum of 0.625 inch
 - (2) The damage is 6D (D = diameter of fastener) away from fastener locations
 - (3) The damage is 4.00 inches away from other damage.
- F. Edge damage is permitted if:
 - (1) The depth is a maximum of 0.10 inch
 - (2) The width is a maximum of 0.50 inch
 - (3) The damage is 4D (D = diameter of fastener) away from the edge of other damage.






REPAIR 1 - RUDDER SKIN

1. Applicability

- A. Repair 1 is applicable to the Rudder Skin panels as shown in Rudder Skin Location, Figure 201/REPAIR 1.
- B. Repair 1 is applicable to damage that is more than the limits permitted in Allowable Damage 1. Refer to Allowable Damage 1 for the type and size of damage that is permitted.



Rudder Skin Location Figure 201

2. General

- A. Repair 1 gives instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Remove the rudder, as necessary. Refer to AMM 27-21-11/401.
- C. Do an inspection of the damaged area to find the dimensions of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 for inspection procedures.

NOTE: Other inspection methods that have been examined and found to be satisfactory by the operator, can be used.


- (1) Refer to Definitions of Damage Size, Figure 202/REPAIR 1 for the definitions of the diameter and depth of damage.
- (2) Refer to Definitions of the Facesheets, Figure 203/REPAIR 1 for the definitions of the facesheets of a honeycomb core area.
- D. Do the repair as given in Paragraph 4./REPAIR 1.
- E. Make sure that the rudder is balanced. Refer to 51-60-07 for the balance procedures.



REPAIR 1 Page 201 Nov 10/2005



F. Install the rudder, as applicable. Refer to AMM 27-21-11/401.



Definitions of Damage Size Figure 202

TOOLSIDE FACESHEET (OUTER SURFACE) HONEYCOMB CORE BAGSIDE FACESHEET (INNER SURFACE)


Definitions of the Facesheets Figure 203



REPAIR 1 Page 202 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



Rudder Skin Zones Figure 204



REPAIR 1 Page 203 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-02, GENERAL	Fastener Installation and Removal
51-40-03, GENERAL	Fastener Substitution
51-60-07	RUDDER BALANCE PROCEDURE
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05, REPAIR GENERAL	Repair Procedures for Preimpregnated Materials
AMM 27-21-11/401	Rudder - Removal/Installation
737 NDT Part 1, 51-01-01	Inspection of Repairs to Composite Structure

4. Repair Instructions

- A. If a dent is 1.50 inches in diameter or less, and has no fiber damage or delamination, then fill the dent with potting compound and apply a fiberglass patch as given in Repair 14 of 51-70-04.
- B. If Paragraph 4.A./REPAIR 1 is not applicable, then refer to:
 - (1) Table 201 for the repair data that is applicable to damage in Zones 1, 2, and 3.
- C. For repairs made with wet layup materials, do as follows, as applicable:
 - (1) Use one repair ply of fabric for each initial ply that was damaged.
 - (2) Add two structural plies of fabric for each facesheet that is repaired. Put one structural ply at ± 45 degrees to the core ribbon direction and the other at 0 or 90 degrees.
 - **NOTE**: Repair plies or added plies are not necessary in the repair of delamination at an edge if the delamination is a minimum of 2.5D (D = fastener diameter) away from a fastener hole.
 - (3) Inspect Category B repairs after each 400 flight hour interval or more frequently. Refer to 737 NDT Part 1, 51-01-01 for inspection procedures. If deterioration is found, then they must be replaced with Category A repairs.
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator, can be used.
- D. For repairs made with preimpregnated layup materials, use the same number of repair plies as the number of initial plies that were damaged.

REPA	REPAIR DATA FOR ZONE 1, 2, AND 3 OF THE 350°F (177°C) CURE RUDDER SKIN PANELS					
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED LAYUP	CATEGORY A PREIMPREGNATED LAYUP		
REPAIR CURE TEMPERATURE	150°F (66°C)	200°F (93°C)	250°F (121°C)	350°F (177°C)		
REPAIR SIZE AND LIMITS	Contact The Boeing Company.	Damage that is a maximum of: - 5.0 inches in diameter	Damage that is a maximum of: - 5.0 inches in diameter	There are no size limits on the repair.		

Table 201:



REPAIR 1 Page 204 Mar 10/2006




REPAIR DATA FOR ZONE 1, 2, AND 3 OF THE 350°F (177°C) CURE RUDDER SKIN PANELS				
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED LAYUP	CATEGORY A PREIMPREGNATED LAYUP
REPAIR CURE TEMPERATURE	150°F (66°C)	200°F (93°C)	250°F (121°C)	350°F (177°C)
		One repair for each 144 square inches	One repair for each 144 square inches	
		3.0 inches minimum clearance from:	3.0 inches minimum clearance from:	
		- other repairs - fastener holes - panel edges	- other repairs - fastener holes - panel edges	
REPAIR PROCEDURES		SRM 51-70-04 and Paragraph 4.C	SRM 51-70-05 and Paragraph 4.D	SRM 51-70-05 and Paragraph 4.D



REPAIR 1 Page 205 Mar 10/2006



IDENTIFICATION 1 - RUDDER RIB STRUCTURE




NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Rudder Structure Location Figure 1

-	Table 1:			
	REFERENCE DRAWINGS			
DRAWING NUMBER				
173A0100	Rudder Functional Product Collector			
173A0150	Centerline Diagram - Rudder			
173A1001	Rib Installation - Lower Closure, Rudder			
173A1002	Rib Installation - Main Actuator, Rudder			
173A1005	Rib Installation - Balance Arm, Rudder			
173A1006	Rib Installation - Forward Tip Balance, Rudder			
173A1007	Rib Installation - Aft Tip Balance, Rudder			
173A1008	Rib Installation - Upper Closure, Rudder			





NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Rudder Rib Structure Identification Figure 2



Page 2




Table 2:

	LIST OF MATERIALS FOR FIGURE 2					
ITEM DESCRIPTION T*[1]			MATERIAL	EFFECTIVITY		
[1]	Lower Closure Rib - Bonded Part		Carbon Fiber Reinforced Plastic (CFRP) honeycomb sandwich	CUM LINE 001 THRU 472		
	Skin		Refer to Figure 3, Detail A			
	Core		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			
	Lower Closure Rib - Bonded Part Skin		CRFP solid laminate with Glass Fiber Reinforced Plastic (GFRP) isolation ply Refer to Figure 3, Detail B	CUM LINE 473 AND ON		
[2]	Main Actuator Rib - Bonded Part		CFRP honeycomb sandwich			
	Skin		Refer to Figure 4			
	Core		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			
[3]	Balance Arm Rib - Bonded Part		CFRP honeycomb sandwich			
	Skin		Refer to Figure 5			
	Core		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			
[4]	Forward Tip Balance Rib - Bonded Part		CFRP honeycomb sandwich			
	Skin		Refer to Figure 6			
	Core		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			
[5]	Aft Tip Balance Rib - Bonded Part		CFRP Woven Fabric			
	Skin		Refer to Figure 7			
[6]	Upper Closure Rib Assembly - Bonded Part		CFRP honeycomb sandwich			
	Skin		Refer to Figure 8			
	Core		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0			
(7)	Rib Post		CFRP Woven Fabric Refer to Figure 9			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).







PLAN VIEW IS SHOWN VIEW IS ON THE BAGSIDE SURFACE PLY LAYUP DIRECTION AND CORE RIBBON DIRECTION А

NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION AND THE CORE RIBBON DIRECTION.
- REFER TO SECTION A-A FOR THE PLY SEQUENCE AT THOSE LOCATIONS. REFER TO THE ENGINEERING DRAWINGS FOR MORE DATA.
- REFER TO TABLE 3 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN SECTION A-A.

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Lower Closure Rib, Figure 2, Item [1] Figure 3 (Sheet 1 of 4)




Page 4

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL




PLY LAYUP SEQUENCE A-A


Ply Direction, Core Ribbon Direction, and Ply Sequence for the Lower Closure Rib, Figure 2, Item [1] Figure 3 (Sheet 2 of 4)





737-800 STRUCTURAL REPAIR MANUAL






NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL B FOR THE O DEGREE PLY DIRECTION.
- REFER TO SECTION B-B FOR THE PLY SEQUENCE. REFER TO THE ENGINEERING DRAWINGS FOR MORE DATA.
- REFER TO TABLE 4 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN SECTION $c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathchar`-c\mathch$

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Lower Closure Rib, Figure 2, Item [1] Figure 3 (Sheet 3 of 4)

> IDENTIFICATION 1 55-40-02 Nov 01/2003





Ply Direction, Core Ribbon Direction, and Ply Sequence for the Lower Closure Rib, Figure 2, Item [1] Figure 3 (Sheet 4 of 4)





Table 3:

PLY MATERIAL AND DIRECTION FOR FIGURE 3, Detail A				
PLY	DIRECTION	MATERIAL		
P1	Optional	1 mil white Tedlar as given in BAC 5317-4		
P2, P4, P9, P11	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Style 3K-70-PW		
P3, P6, P7, P10	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW		
P5, P8	Optional	Adhesive film as given in BMS 8-245, Type II, Class 1, Grade 03A		


Table 4:

PLY MATERIAL AND DIRECTION FOR FIGURE 3, Detail B				
PLY DIRECTION		MATERIAL		
P1, P3, P6, P8	+ or - 45 degrees	CFRP woven fabric as given in BMS 9-8, Type 1, Class 2, Style 3K-70-P		
P2, P4, P5, P7	0 or 90 degrees	CFRP woven fabric as given in BMS 9-8, Type 1, Class 2, Style 3K-70-P		
P9	Optional	GFRP woven fabric as given in BMS 9-3, Type D, Class 7, Style 120		





737-800 STRUCTURAL REPAIR MANUAL



PLAN VIEW IS SHOWN VIEW IS ON THE BAGSIDE SURFACE PLY LAYUP DIRECTION AND CORE RIBBON DIRECTION

NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A . FOR THE O DEGREE PLY DIRECTION AND THE CORE RIBBON DIRECTION.
- REFER TO SECTION A-A FOR THE PLY SEQUENCE AT THOSE LOCATIONS. REFER TO THE ENGINEERING DRAWINGS FOR MORE DATA.
- REFER TO TABLE 5 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN SECTION A-A.

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Main Actuator Rib, Figure 2, Item [2] Figure 4 (Sheet 1 of 2)




Page 9

D634A210 BOEING PROPRIETARY - Copyright C Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL



PLY LAYUP SEQUENCE A-A

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Main Actuator Rib, Figure 2, Item [2] Figure 4 (Sheet 2 of 2)



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details




Table 5:

	PLY MATERIAL AND DIRECTION FOR FIGURE 4				
PLY	DIRECTION	MATERIAL			
P1, P10	Optional	1 mil white Tedlar as given in BAC 5317-4			
P2, P4, P7, P9	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW			
P3, P8	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW			
P5, P6	Optional	Adhesive film as given in BMS 8-245, Type II, Class 1, Grade 03A			





737-800 STRUCTURAL REPAIR MANUAL



PLAN VIEW IS SHOWN VIEW IS ON THE BAGSIDE SURFACE PLY LAYUP DIRECTION AND CORE RIBBON DIRECTION

NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION AND THE CORE RIBBON DIRECTION.
- REFER TO SECTION A-A FOR THE PLY SEQUENCE AT THOSE LOCATIONS. REFER TO THE ENGINEERING DRAWINGS FOR MORE DATA.
- REFER TO TABLE 6 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN SECTION A-A.


Ply Direction, Core Ribbon Direction, and Ply Sequence for the Balance Arm Rib, Figure 2, Item [3] Figure 5 (Sheet 1 of 2)



1DENTIFICATION 1 Page 12 Mar 10/2004



737-800 STRUCTURAL REPAIR MANUAL



PLY LAYUP SEQUENCE A-A

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Balance Arm Rib, Figure 2, Item [3] Figure 5 (Sheet 2 of 2)









Table 6:

PLY MATERIAL AND DIRECTION FOR FIGURE 5				
PLY	DIRECTION	MATERIAL		
P1, P14	Optional	1 mil white Tedlar as given in BAC 5317-4		
P2, P4, P7, P8, P11, P13	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW		
P3, P5, P10, P12	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW		
P6, P9	Optional	Adhesive film as given in BMS 8-245, Type II, Class 1, Grade 03A		





BOEING

PLAN VIEW IS SHOWN

VIEW IS ON THE BAGSIDE SURFACE

PLY LAYUP DIRECTION AND CORE RIBBON DIRECTION

A

NOTES


- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION AND THE CORE RIBBON DIRECTION.
- REFER TO SECTIONS A-A AND B-B FOR THE PLY SEQUENCE AT THOSE LOCATIONS. REFER TO THE ENGINEERING DRAWINGS FOR MORE DATA.
- REFER TO TABLE 7 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN SECTIONS A-A AND B-B.

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Forward Tip Balance Rib, Figure 2, Item [4] Figure 6 (Sheet 1 of 2)

> IDENTIFICATION 1 55-40-02 Page 15 Mar 10/2004



737-800 STRUCTURAL REPAIR MANUAL



Ply Direction, Core Ribbon Direction, and Ply Sequence for the Forward Tip Balance Rib, Figure 2, Item [4] Figure 6 (Sheet 2 of 2)



Page 16 Nov 01/2003




Table 7:

PLY MATERIAL AND DIRECTION FOR FIGURE 6				
PLY DIRECTION MATERIAL				
P1, P17	Optional	1 mil white Tedlar as given in BAC 5317-4		
P2, P4, P6, P11, P13, P15	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW		
P3, P5, P8, P9, P12, P14	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW		
P7, P10	Optional	Adhesive film as given in BMS 8-245, Type II, Class 1, Grade 03A		
P16	Optional	Epoxy impregnated glass woven fabric as given in BMS 8-139, Class III, Style 108		





737-800 STRUCTURAL REPAIR MANUAL



PLAN VIEW IS SHOWN VIEW IS ON THE BAGSIDE SURFACE PLY LAYUP DIRECTION А

NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A . FOR THE O DEGREE PLY DIRECTION.
- REFER TO SECTION A-A FOR THE PLY SEQUENCE AT THOSE LOCATIONS. REFER TO THE . ENGINEERING DRAWINGS FOR MORE DATA.
- REFER TO TABLE 8 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN SECTION . A-A.


Ply Direction, and Ply Sequence for the Aft Tip Balance Rib, Figure 2, Item [5] Figure 7 (Sheet 1 of 2)



Page 18



737-800 STRUCTURAL REPAIR MANUAL



PLY LAYUP SEQUENCE A-A

Ply Direction, and Ply Sequence for the Aft Tip Balance Rib, Figure 2, Item [5] Figure 7 (Sheet 2 of 2)






Table 8:

	PLY MATERIAL AND DIRECTION FOR FIGURE 7				
PLY	DIRECTION	MATERIAL			
P1, P10	Optional	1 mil white Tedlar as given in BAC 5317-4			
P2, P4, P7, P9	+ or - 45 degrees	Epoxy impregnated graphite woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70- PW			
P3, P5, P6, P8	0 or 90 degrees	Epoxy impregnated graphite woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70- PW			





PLAN VIEW IS SHOWN

VIEW IS ON THE BAGSIDE SURFACE

PLY LAYUP DIRECTION AND CORE RIBBON DIRECTION

А

NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION AND THE CORE RIBBON DIRECTION.
- REFER TO SECTIONS A-A, B-B, AND C-C FOR THE PLY SEQUENCE AT THOSE LOCATIONS. REFER TO THE ENGINEERING DRAWINGS FOR MORE DATA.
- REFER TO TABLE 9 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN SECTIONS A-A, B-B, AND C-C.


Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Closure Rib, Figure 2, Item [6] Figure 8 (Sheet 1 of 2)



D634A210



737-800 STRUCTURAL REPAIR MANUAL



C-C

Ply Direction, Core Ribbon Direction, and Ply Sequence for the Upper Closure Rib, Figure 2, Item [6] Figure 8 (Sheet 2 of 2)






Table 9:


PLY MATERIAL AND DIRECTION FOR FIGURE 8			
PLY	DIRECTION	MATERIAL	
P1, P17	Optional	1 mil white Tedlar as given in BAC 5317-4	
P2, P5, P8, P9, P12, P15	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	
P3, P4, P6, P11, P13, P14	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	
P7, P10	Optional	Adhesive film as given in BMS 8-245, Type II, Class 1, Grade 03A	
P16	Optional	Epoxy impregnated glass woven fabric as given in BMS 8-139, Class III, Style 108	





737-800 STRUCTURAL REPAIR MANUAL





PLY LAYUP SEQUENCE A-A

NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION.
- REFER TO SECTION A-A FOR THE PLY SEQUENCE. REFER TO THE ENGINEERING DRAWINGS . FOR MORE DATA.
- . REFER TO TABLE 10 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN SECTION A-A.

Ply Direction and Ply Sequence for the Rib Post, Figure 2, Item [7] Figure 9



Page 24

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details




Table 10:

PLY MATERIAL AND DIRECTION FOR FIGURE 9			
PLY	DIRECTION	MATERIAL	
P1, P3, P6, P8	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	
P2, P4, P5, P7	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	





IDENTIFICATION 2 - RUDDER SPAR RIB STRUCTURE




NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Rudder Spar Rib Structure Location Figure 1

Table 1:

REFERENCE DRAWINGS			
DRAWING NUMBER	TITLE		
173A0100	Rudder Functional Product Collector		
173A0150	Centerline Diagram - Rudder		
173A2001	Spar Installation - Rudder		





NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Rudder Spar Rib Structure Identification Figure 2



Page 2

D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



Table 2:


	LIST OF MATERIALS FOR FIGURE 2				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY	
[1]	Rudder Spar-Bonded Part		Carbon Fiber Reinforced Plastic (CFRP) and fiberglass honeycomb sandwich		
	Skin		Refer to Figure 3		
	Core - RUD STA 8.09 to RUD STA 48.10		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0		
	Core - RUD STA 79.02 to RUD STA 100.16		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0		
	Core - RUD STA 102.08 to RUD STA 126.30		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0		
	Core - RUD STA 189.00 to RUD STA 236.10		Non-metallic honeycomb as given in BMS 8-124, Class IV, Type V, Grade 3.0		
[2]	Rib Post		CFRP woven fabric Refer to Figure 4		
[3]	Stiffener		CFRP woven fabric Refer to Figure 5		
[4]	Rib Post		CFRP woven fabric Refer to Figure 6		
[5]	Air Rib Dam	0.063 (1.60)	2024-T42 clad as given in QQ-A-250/5		
[6]	Stiffener		CFRP woven fabric Refer to Figure 7		
[7]	Stiffener		CFRP woven fabric Refer to Figure 8		
[8]	Stiffener		CFRP woven fabric Refer to Figure 9		
[9]	Rib Post		CFRP woven fabric Refer to Figure 10		
[10]	Rib Post		CFRP woven fabric Refer to Figure 11		
[11]	Rib - RUD STA 4.50	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5		
[12]	Rib - RUD STA 11.00	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5	CUM LINE 001 THRU 120	
	Rib - RUD STA 11.00	0.063 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5	CUM LINE 121 AND ON	
[13]	Rib - RUD STA 45.70	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5	CUM LINE 001 THRU 120	
	Rib - RUD STA 45.70	0.063 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5	CUM LINE 121 AND ON	
[14]	Rib - RUD STA 79.92	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5		
[15]	Rib - RUD STA 127.30	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5		
[16]	Rib - RUD STA 133.80	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5		
[17]	Rib - RUD STA 182.20	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5		
[18]	Rib - RUD STA 188.90	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5		
[19]	Rib - RUD STA 237.15	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5		
[20]	Rib - RUD STA 243.80	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5		
[21]	Rib - RUD STA 255.45	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5		
[22]	Rib - RUD STA 262.10	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5		
[23]	Rib - RUD STA 273.85	0.040 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5		
[24]	Rib - RUD STA 28.39	0.063 (1.02)	2024-T42 clad sheet as given in QQ-A-250/5	CUM LINE 121 AND ON	


IDENTIFICATION 2 Page 3 Nov 01/2003

D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





PLY LAYUP AND CORE RIBBON DIRECTION FOR THE FRONT SPAR BETWEEN STATION O AND FIN WATERLINE 270.00

NOTES

- THE PLY DIRECTION IS THE WARP DIRECTION OF THE FABRIC. REFER TO DETAIL A FOR THE O DEGREE PLY DIRECTION AND THE CORE RIBBON DIRECTION.
- REFER TO SECTIONS A-A, B-B, C-C, D-D, E-E, F-F, G-G, AND H-H FOR THE PLY SEQUENCE AT THOSE LOCATIONS. REFER TO THE ENGINEERING DRAWING FOR MORE DATA.
- REFER TO TABLE 3 FOR THE DIRECTION AND MATERIAL OF THE PLIES SHOWN IN SECTIONS A-A, B-B, C-C, D-D, E-E, F-F, G-G, AND H-H.

Ply Direction, Ply Sequence and Core Ribbon Direction for Figure 2, Item [1] Figure 3 (Sheet 1 of 5)



2 Page 4 Jul 10/2004



NOTES

- FILM ADHESIVE USED AS GIVEN IN BMS 8-245, TYPE II, CLASS 1, GRADE 03A
- 1 > 1 PLY OF EPOXY PREIMPREGNATED GLASS WOVEN FABRIC AND 10 PLIES OF CFRP WOVEN FABRIC IN THIS AREA.
- 2 1 PLY OF FILM ADHESIVE AND 2 PLIES OF CFRP WOVEN FABRIC ON THE BAGSIDE SURFACE. 1 PLY OF FILM ADHESIVE AND 2 PLIES OF CFRP WOVEN FABRIC ON THE TOOLSIDE SURFACE.
- 3 THE NUMBER OF PLIES CHANGES IN THIS AREA. REFER TO THE ENGINEERING DRAWINGS FOR MORE DATA.
- 4 > 1 PLY OF EPOXY PREIMPREGNATED GLASS WOVEN FABRIC AND 16 PLIES OF CFRP WOVEN FABRIC IN THIS AREA.
- 5 1 PLY OF EPOXY PREIMPREGNATED GLASS WOVEN FABRIC AND 18 PLIES OF CFRP WOVEN FABRIC IN THIS AREA.
- 6 1 PLY OF EPOXY PREIMPREGNATED GLASS WOVEN FABRIC AND 14 PLIES OF CFRP WOVEN FABRIC IN THIS AREA.
- 7 3 PLIES OF CFRP WOVEN FABRIC ON THE BAGSIDE SURFACE. 3 PLIES OF CFRP WOVEN FABRIC AND 1 PLY OF EPOXY IMPREGNATED GLASS WOVEN FABRIC ON THE TOOLSIDE SURFACE.

Ply Direction, Ply Sequence and Core Ribbon Direction for Figure 2, Item [1] Figure 3 (Sheet 2 of 5)




2 Page 5 Jul 10/2004







737-800 STRUCTURAL REPAIR MANUAL



A-A



B-B



C-C

Ply Direction, Ply Sequence and Core Ribbon Direction for Figure 2, Item [1] Figure 3 (Sheet 3 of 5)




DENTIFICATION 2 Page 6 Jul 10/2004


D634A210

BOEING®


737-800 STRUCTURAL REPAIR MANUAL



D-D



E-E



F-F

Ply Direction, Ply Sequence and Core Ribbon Direction for Figure 2, Item [1] Figure 3 (Sheet 4 of 5)




1DENTIFICATION 2 Page 7 Jul 10/2004




BOEING®

737-800 STRUCTURAL REPAIR MANUAL



G-G



H-H

Ply Direction, Ply Sequence and Core Ribbon Direction for Figure 2, Item [1] Figure 3 (Sheet 5 of 5)



1DENTIFICATION 2 Page 8 Jul 10/2004






Table 3:


PLY MATERIAL AND DIRECTION FOR FIGURE 3			
PLY	DIRECTION	MATERIAL	
P1	Optional	Epoxy impregnated glass woven fabric as given in BMS 8-139, Class III, Style 108	
P2, P4, P5, P8, P9, P10, P12, P13, P14, P15, P17, P18, P19, P22, P23, P25	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	
P3, P6, P7, P11, P16, P20, P21, P24	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	





737-800 STRUCTURAL REPAIR MANUAL





A-A

Ply Direction and Ply Sequence for the Rib Post, Figure 2, Item [2] Figure 4



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



Table 4:


PLY MATERIAL AND DIRECTION FOR FIGURE 4			
PLY	DIRECTION	MATERIAL	
P1, P3, P6, P8	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	
P2, P4, P5, P7	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	




D634A210



737-800 STRUCTURAL REPAIR MANUAL





A-A

Ply Direction and Ply Sequence for the Stiffener, Figure 2, Item [3] Figure 5





Table 5:


PLY MATERIAL AND DIRECTION FOR FIGURE 5			
PLY	DIRECTION	MATERIAL	
P1, P3, P5, P8, P10, P12	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	
P2, P4, P6, P7, P9, P11	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	




D634A210



737-800 STRUCTURAL REPAIR MANUAL





A-A

Ply Direction and Ply Sequence for the Rib Post, Figure 2, Item [4] Figure 6





Table 6:


PLY MATERIAL AND DIRECTION FOR FIGURE 6			
PLY	DIRECTION	MATERIAL	
P1, P3, P5, P6, P8, P10	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	
P2, P4, P7, P9	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	




D634A210



737-800 STRUCTURAL REPAIR MANUAL





A-A

Ply Direction and Ply Sequence for the Stiffener, Figure 2, Item [6] Figure 7






Table 7:


PLY MATERIAL AND DIRECTION FOR FIGURE 7			
PLY	DIRECTION	MATERIAL	
P1, P3, P5, P8, P10, P12	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	
P2, P4, P6, P7, P9, P11	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	





737-800 STRUCTURAL REPAIR MANUAL





A-A

Ply Direction and Ply Sequence for the Stiffener, Figure 2, Item [7] Figure 8






Table 8:


PLY MATERIAL AND DIRECTION FOR FIGURE 8			
PLY	DIRECTION	MATERIAL	
P1, P3, P5, P8, P10, P12	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, TYpe IV, Class 2, Style 3K-70-PW	
P2, P4, P6, P7, P9, P11	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	





737-800 STRUCTURAL REPAIR MANUAL





A-A

Ply Direction and Ply Sequence for the Stiffener, Figure 2, Item [8] Figure 9





Table 9:


PLY MATERIAL AND DIRECTION FOR FIGURE 9			
PLY	DIRECTION	MATERIAL	
P1, P3, P5, P8, P10, P12	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	
P2, P4, P6, P7, P9, P11	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	




D634A210



737-800 STRUCTURAL REPAIR MANUAL







Ply Direction and Ply Sequence for the Rib Post, Figure 2, Item [9] Figure 10



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details




Table 10:

PLY MATERIAL AND DIRECTION FOR FIGURE 10			
PLY	DIRECTION	MATERIAL	
P1, P3, P5, P7, P10, P12, P14, P16	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	
P2, P4, P6, P8, P9, P11, P13, P15	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW	





737-800 STRUCTURAL REPAIR MANUAL



A-A

Ply Direction and Ply Sequence for the Rib Post, Figure 2, Item [10] Figure 11



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details




Table 11:

PLY MATERIAL AND DIRECTION FOR FIGURE 11				
PLY	DIRECTION	MATERIAL		
P1, P3, P5, P7, P10, P12, P14, P16	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW		
P2, P4, P6, P8, P9, P11, P13, P15	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW		





IDENTIFICATION 3 - RUDDER BALANCE ARM STRUCTURE



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Balance Arm Structure Location Figure 1


Table 1:

	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
173A0002	Rudder Adjust Weight Installation				
173A0100	Rudder Functional Product Collector				
173A0150	Centerline Diagram - Rudder				
173A5000	Balance Arm Installation - Rudder				
173A5001	Balance Arm Assembly - Rudder				





737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS.

Balance Arm Structure Identification Figure 2



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



Table 2:


LIST OF MATERIALS FOR FIGURE 2						
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY		
[1]	Rib Post		Carbon Fiber Reinforced Plastic (CFRP) woven fabric Refer to Figure 3			
[2]	Balance Arm Casting		A357.0-T6 high strength aluminum casting as given in MIL-A-21180 with Class 11 mechanical properties			
[3]	Balance Weight		Tungsten base high-density metal as given in MIL- T-21014			
[4]	Adjust Weight		Tungsten base high-density metal as given in MIL- T-21014			
[5]	Strut-Balance Arm	0.750 (19.1)	7050-T7451 plate as given in AMS 4050. Ultrasonic inspect as given in BAC 5439, Class B (Optional: Class A)			
[6]	Strut Support Fitting		7050-T7451 plate as given in AMS 4050. Ultrasonic inspect as given in BAC 5439, Class B (Optional: Class A)			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).



BOEING®

737-800 STRUCTURAL REPAIR MANUAL



Ply Direction and Ply Sequence for the Rib Post, Figure 2, Item [1] Figure 3



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



Table 3:

PLY MATERIAL AND DIRECTION FOR FIGURE 3					
PLY	DIRECTION	MATERIAL			
P1, P3, P5, P7, P10, P12, P14, P16	+ or - 45 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW			
P2, P4, P6, P8, P9, P11, P13, P15	0 or 90 degrees	CFRP woven fabric as given in BMS 8-256, Type IV, Class 2, Style 3K-70-PW			



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



ALLOWABLE DAMAGE 1 - RUDDER SPAR AND SPAR RIBS

1. Applicability

A. Allowable Damage 1 gives the allowable damage limits for the rudder spar and spar ribs shown in Rudder Structure Location, Figure 101/ALLOWABLE DAMAGE 1.

2. General

A. Do an inspection of the damaged area to find the length, width and depth of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to 737 NDT Part 1, 51-01-02 for inspection procedures.

NOTE: Other equivalent inspection methods that have been examined and found to be satisfactory by the operator can be used.

- (1) For the honeycomb core areas, the tap test is an alternative procedure to an instrumented NDT.
- (2) Refer to Definitions of Damage Size, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, and C for the definitions of the length, width, and depth of the damage.
- B. Remove all contamination and water from the structure. Refer to 51-30-05 and 51-70-04 for the tools and the cleanup procedures.
- C. Seal all permitted damage areas that are not more than one ply deep. Refer to the allowable damage limits. Seal the damage with one of the two methods that follows:
 - (1) Make a temporary seal.
 - (a) Apply aluminum foil tape (speed tape).
 - (b) Keep a record of the location.
 - (c) If the tape is on the external surface of the spar, then make sure that it is in satisfactory condition after each 400 flight hour interval or more frequently.
 - (d) Repair the damage at or before 5000 flight hours or 18 months, that which occurs first, from the time the seal was made.
 - (2) Make a permanent seal.
 - (a) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given in 51-70-08.
 - (b) Apply one layer of BMS 10-79, Type III or BMS 10-103, Type I primer. Refer to SOPM 20-44-04.
- D. Seal all permitted damage areas that are more than one ply deep. Refer to the allowable damage limits. Seal the damage as follows:
 - (1) Use a vacuum and heat to remove moisture from the solid laminate and/or honeycomb cells. Refer to 51-70-04.
 - (2) Make a temporary seal with aluminum foil tape (speed tape).
 - (3) Keep a record of the location.
 - (4) Repair the damage at or before 400 flight hours from the time the seal was made.
- E. The definition of the words "other damage" as used in the allowable damage limits, does not include nicks, gouges, and scratches that do not cause carbon fiber damage and are sealed.
- F. Make sure that the rudder is balanced. Refer to 51-60-07 for the balance procedures.






Table 101:


PARAGRAPH REFERENCES FOR THE ALLOWABLE DAMAGE LIMITS				
TYPE OF STRUCTURE	PARAGRAPH			
SOLID LAMINATE AREA	1	4.A		
	2	4.C		
HONEYCOMB CORE AREA	1	4.B		
	2	4.D		



D634A210

BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details








BOEING


737-800 STRUCTURAL REPAIR MANUAL








737-800 STRUCTURAL REPAIR MANUAL






BOEING"

737-800 STRUCTURAL REPAIR MANUAL



THE BALANCE ARM RIB IS SHOWN, THE OTHER RIBS ARE ALMOST THE SAME



B-B

ZONE 1


ZONE 2

NOTES

• USE THE ZONE 2 LIMITS FOR THE UPPER CLOSURE RIB, AFT TIP BALANCE RIB, AND FORWARD TIP BALANCE RIB.

Rudder Rib Zone Locations Figure 104







3. References

Reference	Title
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-05, GENERAL	Repair Sealing
51-30-03, GENERAL	Sources for Non-Metallic Repair Materials
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-60-07	RUDDER BALANCE PROCEDURE
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-08	RESIN SWEEP-FAIR PROCEDURES
AMM 51-21-00 P/B 701	INTERIOR AND EXTERIOR FINISHES - CLEANING/PAINTING
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Allowable Damage Limits for the Rudder Spar and Ribs

- A. Solid Laminate Area of Zone 1
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that cause damage to the fiberglass ply are permitted.
 - (3) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are not permitted.
 - (4) Holes and Punctures are not permitted.
 - (5) Dents are not permitted.
 - (6) Delaminations are not permitted.
 - (7) Edge damage is permitted if:
 - (a) The depth is a maximum of one ply
 - (b) The width is a maximum of 0.25 inch
 - (c) The damage is a minimum of 6 inches away from the edge of other damage.
- B. Honeycomb Core Area of Zone 1
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are not permitted.
 - (3) Dents that do not cause damage to the carbon fibers are permitted if:
 - (a) The depth is a maximum of one face sheet
 - (b) The diameter is a maximum of 0.5 inch
 - (c) The damage is a minimum of 6 inches away from the edge of other damage.
 - (4) Holes and Punctures are not permitted.
 - (5) Delaminations are not permitted.
- C. Solid Laminate Area of Zone 2
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that cause damage to the fiberglass ply are permitted.
 - (3) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if:





(a) The depth is a maximum of one ply

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (b) The length is a maximum of 1.0 inch
- (c) The width is a maximum of 0.25 inch
- (d) Not more than 1 fastener hole in 6 is damaged
- (e) The damage is a minimum of 3 inches away from the edge of other damage.
- (4) Dents that do not cause damage to the carbon fibers are permitted if:
 - (a) The depth is a maximum of one ply

NOTE: Use the limits for holes and punctures if there is carbon fiber damage or if the dent depth is more than one ply.

- (b) The diameter is a maximum of 0.625 inch
- (c) Not more than 1 fastener hole in 6 is damaged
- (d) The damage is a minimum of 3 inches away from the edge of other damage.
- (5) Holes and Punctures are permitted if:
 - (a) The diameter is a maximum of 0.25 inch
 - (b) The damage is a minimum of 3 inches away from the edge of other damage, a fastener hole, or a part edge.
- (6) Delaminations are permitted if:
 - (a) The depth is a maximum of one ply
 - (b) The diameter is a maximum of 0.50 inch
 - (c) The damage is a minimum of 3 inches away from the edge of other damage, a fastener hole, or a part edge.
- (7) Edge damage is permitted if:
 - (a) The depth is a maximum of one ply
 - (b) The width is a maximum of 0.25 inch
 - (c) The damage is a minimum of 3 inches away from the edge of other damage or a hole.
- D. Honeycomb Core Area of Zone 2
 - (1) Nicks, Gouges, and Scratches that do not cause damage to the carbon fibers are permitted.
 - (2) Nicks, Gouges, and Scratches that cause damage to the fiberglass fibers are permitted.
 - (3) Nicks, Gouges, and Scratches that cause damage to the carbon fibers are permitted if:
 - (a) The depth is a maximum of one ply
 - **NOTE:** Use the limits for holes and punctures if the damage is more than one ply in depth.
 - (b) The length is a maximum of 0.625 inch
 - (c) The width is a maximum of 0.25 inch
 - (d) The damage is a minimum of 3 inches away from the edge of other damage.
 - (4) Dents that do not cause damage to the carbon fibers are permitted if:



Page 108



(a) The depth is a maximum of one face sheet

NOTE: Use the limits for holes and punctures if there is carbon fiber damage or if the dent depth is more than one ply.

- (b) The diameter is a maximum of 0.5 inch
- (c) The damage is a minimum of 3 inches away from the edge of other damage.
- (5) Holes and Punctures are permitted if:
 - (a) A maximum of one face sheet and the core in depth
 - (b) The diameter is a maximum of 0.50 inch
 - (c) The damage is a minimum of 3 inches away from the edge of other damage or a fastener hole.
- (6) Delaminations are permitted if:
 - (a) The diameter is a maximum of 0.5 inch
 - (b) The damage is a minimum of 3 inches away from the edge of other damage or a fastener hole.





ALLOWABLE DAMAGE 2 - LEADING EDGE RIBS OF THE RUDDER STRUCTURE


1. Applicability

A. This subject gives the allowable damage limits for the leading edge ribs of the rudder structure shown in Leading Edge Rib Locations, Figure 101/ALLOWABLE DAMAGE 2.

2. General

- A. Remove the damaged material, as applicable. Make sure that the material to be removed is less than or equal to the allowable damage limits.
- B. Apply a chemical conversion coating to the bare surfaces of the reworked areas. Refer to 51-20-01.
- C. Apply a layer of BMS 10-79, Type III primer to the bare surfaces of the reworked areas. Refer to SOPM 20-44-04.
- D. Apply a layer of BMS 10-60 enamel to the reworked areas. Refer to AMM 51-21-00/701.







3. References

Reference	Title
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-30-03, GENERAL	Sources for Non-Metallic Repair Materials
51-30-05, GENERAL	Equipment and Tools For Repairs
AMM 51-21-00/701	Interior And Exterior Finishes - Cleaning/Painting
SOPM 20-20-02	Penetrant Methods of Inspection
SOPM 20-44-04	Application of Urethane Compatible Primers


4. Allowable Damage Limits

- A. Cracks:
 - (1) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 2, Details A, and B.
- B. Nicks, Gouges, Scratches, and Corrosion:
 - (1) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 2, Details A, B, C, D, and E.
- C. Dents:
 - (1) Refer to Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 2, Detail F for the damage that is permitted.
- D. Holes and Punctures:
 - (1) The maximum diameter of damage permitted is 0.25 inch (6.35 mm) after cleanup.
 - (2) The damage must be 1.00 inch (25.4 mm) minimum from other holes, part edge, or other damage.
 - (3) Fill the hole with a 2117-T3 or 2117-T4 aluminum rivet.
 - (a) Install the rivet without sealant.






737-800 STRUCTURAL REPAIR MANUAL






Nov 01/2003

Page 104







Allowable Damage Limits Figure 102 (Sheet 3 of 3)





ALLOWABLE DAMAGE 3 - RUDDER BALANCE ARM STRUCTURE

1. Applicability


A. This subject gives the allowable damage limits for the balance arm structure shown in Rudder Balance Arm Location, Figure 101/ALLOWABLE DAMAGE 3.

REFER TO FIGURE 102 FOR THE BALANCE ARM STRUCTURE FWD

Rudder Balance Arm Location Figure 101








NOTES

• ALL PARTS ARE MADE OF ALUMINUM UNLESS OTHERWISE NOTED.

Rudder Balance Arm Figure 102 (Sheet 1 of 2)








Rudder Balance Arm Figure 102 (Sheet 2 of 2)





737-800 STRUCTURAL REPAIR MANUAL



NOTES

NO DAMAGE IS PERMITTED

1 THE MAXIMUM DAMAGE DEPTH PERMITTED AT THE STRAP EDGES ACROSS FROM FASTENER LOCATIONS IS 0.15 INCH.

THE MAXIMUM DAMAGE DEPTH PERMITTED AT THE STRAP EDGES OTHER THAN EDGES ACROSS FROM FASTENER LOCATIONS IS 0.20 INCH.

REFER TO FIGURE 104, DETAIL F, FOR THE REMOVAL OF DAMAGE.

• IF DAMAGE IS FOUND ON THE FAIL SAFE STRAP, YOU MUST DO AN INSPECTION OF THE ADJACENT STRUCTURE.

MAKE SURE THERE IS NO DAMAGE IN THE ADJACENT STRUCTURE.

Allowable Damage Zones - Doubler and Fail Safe Strap Assembly Figure 103







2. General

- A. Refer to Paragraph 4./ALLOWABLE DAMAGE 3 for the allowable damage limits.
- B. Remove the damage material as necessary.
 - (1) Refer to 51-10-02 for inspection and removal of the damage.
 - (2) Refer to 51-30-03 for possible sources of the abrasive and other materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
- C. After you remove the damage, do the steps that follow.

WARNING: MAKE SURE THAT YOU WEAR EYE PROTECTION WHEN YOU USE THE FLAP PEEN WHEEL. IF YOU DO NOT OBEY, AN INJURY CAN OCCUR.

- (1) Flap peen or shot peen the reworked area of the balance arm struts, strut supports or support fittings.
 - (a) Refer to 51-20-06 for the shot peen intensity and shot number.
 - (b) Refer to SOPM 20-10-03 for the flap peen or shot peen procedures.
- (2) Apply a chemical conversion coating to the bare reworked surfaces of the aluminum parts. Refer to 51-20-01.
- (3) Apply a cadmium plating to the bare reworked surfaces of the CRES parts. Refer to SOPM 20-42-05.
- (4) Apply a layer of BMS 10-79, Type III primer to the bare reworked surfaces of the aluminum and CRES parts. Refer to SOPM 20-44-04.
- (5) Apply a layer of BMS 10-60 enamel to the reworked areas of the aluminum and CRES parts. Refer to AMM 51-21-00/701.
- (6) Make sure that the rudder is balanced. Refer to 51-60-07 for the balance procedures.

3. <u>References</u>

Reference	Title
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-06	SHOT PEENING
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-40-02, GENERAL	Fastener Installation and Removal
51-60-07	RUDDER BALANCE PROCEDURE
AMM 51-21-00/701	Interior And Exterior Finishes - Cleaning/Painting
SOPM 20-10-03	General - Shot Peening Procedures
SOPM 20-20-02	Penetrant Methods of Inspection
SOPM 20-42-05	Bright Cadmium Plating
SOPM 20-44-04	Application of Urethane Compatible Primers






4. Allowable Damage Limits

- A. Balance Arm, Support Fitting, Strut Support, Struts, Clips and Fillers
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 3, Details A, B, and D.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 3, Details A, B, C, D and E.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- B. Fail-Safe Straps
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 3, Detail F.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 104/ALLOWABLE DAMAGE 3, Details C, E and F.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- C. Doublers
 - (1) Cracks are not permitted.
 - (2) Nicks, Gouges, Scratches, and Corrosion are not permitted.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.





737-800 STRUCTURAL REPAIR MANUAL






Page 107

Nov 01/2003


D634A210 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



ALLOWABLE DAMAGE 3 55-40-02 Nov 01/2003

Page 108





X = DEPTH OF THE MATERIAL THAT IS REMOVED (REFER TO FIGURE 103 ON PAGE 106)

REMOVAL OF DAMAGED MATERIAL FROM THE FAIL-SAFE STRAP

Allowable Damage Limits Figure 104 (Sheet 3 of 3)





REPAIR 1 - RUDDER STRUCTURE

1. Applicability

- A. Repair 1 is applicable to the rudder structure as shown in Rudder Structure Location, Figure 201/REPAIR 1.
- B. Repair 1 is applicable to damage that is more than the limits permitted in Allowable Damage 1. Refer to Allowable Damage 1 for the type and size of damage that is permitted.

2. General


- A. Repair 1 gives instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Remove the rudder, as necessary. Refer to AMM 27-21-11/401.
- C. Remove the skin, as necessary to get access to the spar and ribs. Refer to 51-40-02 for fastener removal procedures.
- D. Remove the fittings or the leading edge ribs from the spar, as necessary to get access to the spar. Refer to SOPM 20-10-08.
- E. Do an inspection of the damaged area to find the dimensions of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02, and NDT, Part 1, 51-01-03 for inspection procedures.

NOTE: Other equivalent inspection methods that have been examined and found to be satisfactory by the operator, can be used.

- (1) For the honeycomb core areas, the tap test is an alternative procedure to an instrumented NDT. Refer to 737 NDT Part 1, 51-05-01 for the inspection procedures.
- (2) Refer to Definitions of Damage Size, Figure 202/REPAIR 1 for the definitions of the length, width and depth of damage.
- (3) Refer to Definitions of the Facesheets, Figure 203/REPAIR 1 for the definitions of the facesheets of a honeycomb core area.
- F. Refer to Rudder Spar Zone Locations, Figure 204/REPAIR 1 for the rudder spar zone locations.
- G. Refer to Rudder Rib Zone Locations, Figure 205/REPAIR 1 for the rudder rib zone locations.
- H. Do the repair as given in Paragraph 4./REPAIR 1
- I. Install the fittings or the leading edge ribs on the spar, as applicable.
 - (1) Apply BMS 5-95 sealant to the mating surfaces. Refer to 51-20-05.
- J. Install the skin, as applicable. Refer to 51-40-02 for fastener installation procedures.
- K. Make sure that the rudder is balanced. Refer to 51-60-03.
- L. Install the rudder, as applicable. Refer to AMM 27-21-11/401.




REPAIR 1 Page 201 Jul 10/2005



BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details

BOEING

737-800 STRUCTURAL REPAIR MANUAL






REPAIR 1 Page 203 Nov 01/2003




737-800 STRUCTURAL REPAIR MANUAL



Definitions of the Facesheets Figure 203




REPAIR 1 Page 204 Nov 01/2003





737-800 STRUCTURAL REPAIR MANUAL







REPAIR 1 Page 205 Nov 01/2003

BOEING"

737-800 STRUCTURAL REPAIR MANUAL



THE BALANCE ARM RIB IS SHOWN, THE OTHER RIBS ARE ALMOST THE SAME



B-B

ZONE 1

ZONE 2

NOTES

• USE THE ZONE 2 LIMITS FOR THE UPPER CLOSURE RIB, AFT TIP BALANCE RIB, AND FORWARD TIP BALANCE RIB.

Rudder Rib Zone Locations Figure 205



REPAIR 1 Page 206 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05	REPAIR SEALING
51-30-05, GENERAL	Equipment and Tools For Repairs
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-40-03, GENERAL	Fastener Substitution
51-60-03	AILERON TAB BALANCE PROCEDURE
51-60-07, GENERAL	Rudder Balance Procedure
51-70-04, REPAIR P/B REPAIR	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05, REPAIR GENERAL	Repair Procedures for Preimpregnated Materials
55-40-02, ALLOWABLE DAMAGE 1	Rudder Spar and Spar Ribs
55-40-02, ALLOWABLE DAMAGE 2	Leading Edge Ribs of the Rudder Structure
55-40-02, ALLOWABLE DAMAGE 3	Rudder Balance Arm Structure
AMM 51-21-00	INTERIOR AND EXTERIOR FINISHES
AMM 27-21-11/401	Rudder - Removal/Installation
SOPM 20-10-08	Removal of Faying Surface Sealed Metal Fittings from Composite Structures
737 NDT Part 1, 51-01-01	Inspection of Repairs to Composite Structure
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage
737 NDT Part 1, 51-01-03	NDT Assessment of Lightning Strike Damage to Graphite/Epoxy Composite Structure
737 NDT Part 1, 51-05-01	Tap Test Inspection of Honeycomb Sandwich Structure

4. Repair Instructions

- A. Do as follows when you make a repair:
 - (1) When you remove the damage, do not cut or make an abrasion into the radius of the structure.
 - (2) If the repair plies make an overlap of a hole or cutout, do the steps that follow:
 - (a) Cure the repair.
 - (b) Drill or cut the plies to the initial diameter of the hole or cutout.
 - (3) If you need clearance with adjacent structure, install a tapered shim on each side of the repair.
 - (4) It is permitted to put the repair plies around the full width of the structure.
 - (a) Do not make an overlap of the edges of the structure.
- B. Refer to:
 - (1) Table 201/REPAIR 1 for the repair data that is applicable to damage in the solid laminate area of Zone 1.
 - (2) Table 202/REPAIR 1 for the repair data that is applicable to damage in the honeycomb core area of Zone 1.
 - (3) Table 203/REPAIR 1 for the repair data that is applicable to damage in the solid laminate area of Zone 2.



REPAIR 1 Page 207 Jul 10/2005



- (4) Table 204/REPAIR 1 for the repair data that is applicable to damage in the honeycomb core area of Zone 2.
- C. For repairs made with wet layup materials, do as follows, as applicable:
 - (1) Use one repair ply of fabric for each initial ply that was damaged.
 - (2) Add two more structural plies of fabric for each facesheet, or side of the part that is repaired. Put one structural ply at ± 45 degrees to the core ribbon direction and the other at 0 or 90 degrees.
 - (3) Inspect Category B repairs after each 400 flight hour interval or more frequently. Refer to 737 NDT Part 1, 51-01-01 for inspection procedures. If deterioration is found, then they must be replaced with Category A repairs.

<u>NOTE</u>: Other equivalent inspection methods that have been examined and found to be satisfactory by the operator, can be used.

D. For repairs made with preimpregnated layup materials, use the same number of repair plies as the number of initial plies that were damaged (plus a filler ply).

REPAIR I	REPAIR DATA FOR THE SOLID LAMINATE AREA OF ZONE 1 ON THE 350°F (177°C) CURE RUDDER STRUCTURE				
REPAIR TYPE	PREIMPREGNATED LAYUP				
REPAIR CURE TEMPERATURE	350°E (177°C) CUBE				
REPAIR DIMENSIONS AND LIMITS	There are no limits on the dimensions of the repair				
REPAIR PROCEDURES	Refer to SRM 51-70-05 and Paragraph 4.D				

Table 201:

Table 202:

REPAIR D	REPAIR DATA FOR THE HONEYCOMB CORE AREA OF ZONE 1 ON THE 350°F (177°C) CURE RUDDER STRUCTURE					
REPAIR TYPE	CATEGORY A WET LAYUP					
REPAIR CURE TEMPERATURE	200°F (93°C)	250°F (121°C)	350°F (177°C)			
REPAIR SIZE AND LIMITS	Damage that is a maximum of: 1.00 inch (25.4 mm) in diameter	Damage that is a maximum of: 1.00 inch (25.4 mm) in diameter	There are no limits on the dimensions of the repair.			
	One facesheet and the honeycomb core in depth	One facesheet and the honeycomb core in depth				
	3.0 inches (76.2 mm) minimum clearance from:	3.0 inches (76.2 mm) minimum clearance from:				
	- other repairs - fastener holes - part edges	- other repairs - fastener holes - part edges				
REPAIR PROCEDURES	SRM 51-70-04 and Paragraph 4.C	SRM 51-70-05 and Paragraph 4.D	SRM 51-70-05 and Paragraph 4.D			



55-40-02



Table 203:

REPAIR DATA FO	REPAIR DATA FOR THE SOLID LAMINATE AREA OF ZONE 2 ON THE 350°F (177°C) CURE RUDDER STRUCTURE					
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED IAYUP	CATEGORY A PREIMPREGNATED LAYUP		
REPAIR CURE TEMPERATURE	150°F (66°C)	200°F (93°C)	250°F (121°C)	350°F (177°C)		
REPAIR SIZE AND LIMITS	Damage that is a maximum of: 0.50 inch (12.7 mm) in diameter	Damage that is a maximum of: 2.0 inches (50.8 mm) in diameter	Damage that is a maximum of: 2.0 inches (50.8 mm) in diameter	There are no limits on the dimensions of the repair.		
	20 percent of the smallest dimension across the part at the damage location	40 percent of the smallest dimension across the part at the damage location	40 percent of the smallest dimension across the part at the damage location			
	One repair for each 144 inches ² (929.03 cm ²)	One repair for each 144 inches ² (929.03 cm ²)	One repair for each 144 inches ² (929.03 cm ²)			
	3.0 inches (76.2 mm) minimum clearance from:	3.0 inches (76.2 mm) minimum clearance from:	3.0 inches (76.2 mm) minimum clearance from:			
	- other repairs - fastener holes - part edges	- other repairs - fastener holes - part edges	- other repairs - fastener holes - part edges			
REPAIR PROCEDURES	SRM 51-70-04 and Paragraph 4.C	SRM 51-70-04 and Paragraph 4.C	SRM 51-70-05 and Paragraph 4.D	SRM 51-70-05 and Paragraph 4.D		

Table 204:

REPAIR DATA FO	REPAIR DATA FOR THE HONEYCOMB CORE AREA OF ZONE 2 ON THE 350°F (177°C) CURE RUDDER STRUCTURE				
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED IAYUP	CATEGORY A PREIMPREGNATED LAYUP	
REPAIR CURE TEMPERATURE	150°F (66°C)	200°F (93°C)	250°F (121°C)	350°F (177°C)	
REPAIR SIZE AND LIMITS	Damage that is a maximum of:	Damage that is a maximum of:	Damage that is a maximum of:	There are no limits on the dimensions of the repair	
	0.50 inch (12.7 mm) in diameter	4.0 inches (101.6 mm) in diameter	4.0 inches (101.6 mm) in diameter		
	20 percent of the smallest dimension across the part at the damage location	50 percent of the smallest dimension a- cross the part at the damage location	50 percent of the smallest dimension across the part at the damage location		
	One facesheet and honeycomb core in depth				
	One repair for each 144 inches ² (929.03 cm ²)	One repair for each 144 inches ² (929.03 cm ²)	One repair for each 144 inches ² (929.03 cm ²)		
	3.0 inches (76.2 mm) minimum clearance from:	3.0 inches (76.2 mm) minimum clearance from:	3.0 inches (76.2 mm) minimum clearance from:		



55-40-02



REPAIR DATA FOR THE HONEYCOMB CORE AREA OF ZONE 2 ON THE 350°F (177°C) CURE RUDDER STRUCTURE					
REPAIR TYPE CATEGORY B CATEGORY A PREIMPRE		CATEGORY A PREIMPREGNATED IAYUP	CATEGORY A PREIMPREGNATED LAYUP		
REPAIR CURE TEMPERATURE 150°F (66°C)		200°F (93°C)	250°F (121°C)	350°F (177°C)	
	- other repairs - fastener holes - part edges	- other repairs - fastener holes - part edges	- other repairs - fastener holes - part edges		
REPAIR PROCEDURES	SRM 51-70-04 and Paragraph 4.C	SRM 51-70-04 and Paragraph 4.C	SRM 51-70-05 and Paragraph 4.D	SRM 51-70-05 and Paragraph 4.D	




REPAIR 1





IDENTIFICATION 1 - RUDDER TIP FAIRING SKINS



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.

Rudder Tip Fairing Skin Location Figure 1


	Table 1:				
	REFERENCE DRAWINGS				
DRAWING NUMBER	TITLE				
173A0100	Rudder Functional Product Collector				
173A4300	Cover Panel Assembly				
173A6000	Rudder Tip Installation				
173A6201	Rudder Tip Lower Fairing Assembly				
173A6210	Rudder Tip Upper Fairing - Bonded Part				



Page 1



737-800 STRUCTURAL REPAIR MANUAL



NOTE: REFER TO TABLE 2 FOR THE LIST OF MATERIALS. LEFT SIDE IS SHOWN, RIGHT SIDE IS OPPOSITE

Rudder Tip Fairing Skin Identification Figure 2

Table 2:


	LIST OF MATERIALS FOR FIGURE 2					
ITEM DESCRIPTION T ^{*[1]} MATERIAL				EFFECTIVITY		
[1]	Upper Fairing					
	Fairing		Glass Fiber Reinforced Plastic (GFRP) laminate with aluminum foil mesh lightning protec- tion. Refer to Figure 3			
	Wedge		Phenolic sheet as given in ASTM D709, Type IV, Grade G-3			
[2]	Splice Plate	0.063 (1.60)	6061-T4 clad sheet as given in QQ-A-250/11			
[3]	Hinge Cover		GFRP laminate. Refer to Figure 4			
[4]	Lower Fairing		GFRP laminate. Refer to Figure 5			
[5]	Closure		GFRP laminate. Refer to Figure 6			

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





737-800 STRUCTURAL REPAIR MANUAL



B-B


Ply Direction and Ply Sequence for the Upper Fairing, Figure 2, Item [1] Figure 3







Table 3:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [1]		
PLY DIRECTION MATERIAL		MATERIAL
P1		Adhesive film as given in BMS 5-129, Type 2, Grade 5
P2, P4, P6, P8	0 or 90 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Style 1581 or Style 7781, Class III, Grade B
P3, P5, P7	+ or - 45 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Style 1581 or Style 7781, Class III, Grade B
P9		Adhesive film as given in BMS 8-245, Type III, Class 1, Grade 05
P10		Expanded aluminum foil mesh as given in BMS 8-336, Type I, Class 1, Grade 016, Form A



THE LEFT HINGE COVER IS SHOWN, THE RIGHT HINGE COVER IS OPPOSITE





A-A (TYPICAL)

B-B

Ply Sequence for the Hinge Cover, Figure 2, Item [3] Figure 4



Page 4

D634A210 BOEING PROPRIETARY - Copyright ${\rm (\sc)}$ Unpublished Work - See title page for details



Table 4:


PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [3]		
PLY	PLY DIRECTION MATERIAL	
P1 through P7	Optional	Epoxy impregnated glass woven fabric as given in BMS 8-79, Style 1581 or Style 7781, Class III, Grade B




D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



737-800 STRUCTURAL REPAIR MANUAL





A-A

Ply Direction and Ply Sequence for the Lower Fairing, Figure 2, Item [4] Figure 5



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details





Table 5:

PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [4]		
PLY	DIRECTION MATERIAL	
P1, P3, P5, P7	0 or 90 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Style 1581 or Style 7781, Class III, Grade B
P2, P4, P6	+ or - 45 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Style 1581 or Style 7781, Class III, Grade B









A-A

Ply Direction and Ply Sequence for the Closure, Figure 2, Item [5] Figure 6



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



Table 6:

	PLY MATERIAL AND DIRECTION FOR FIGURE 2, ITEM [5]		
PLY	DIRECTION MATERIAL		
P1, P4	0 or 90 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Style 1581 or Style 7781, Class III, Grade B	
P2, P3	+ or - 45 degrees	Epoxy impregnated glass woven fabric as given in BMS 8-79, Style 1581 or Style 7781, Class III, Grade B	





ALLOWABLE DAMAGE 1 - RUDDER TIP FAIRING SKINS

1. Applicability

A. Allowable Damage 1 is applicable to damage on rudder tip fairing skins shown in Figure 101.

2. <u>General</u>

A. Do an inspection of the damaged area to find the length, width, and depth of the damage. Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 for inspection procedures.


NOTE: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.

- (1) Refer to Damage Definitions, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, and C for the definitions of the length, width, and depth of the damage.
- B. Remove all the contamination and water from the fairing.
 - (1) Refer to 51-30-05 for possible sources of the tools and equipment you can use to remove the damage.
 - (2) Refer to 51-70-04 for the cleanup procedures.
- C. Seal all the permitted damage areas that are not more than one ply in depth. Refer to the allowable damage limits given in Paragraph 4./ALLOWABLE DAMAGE 1 Use one of the two methods that follows:
 - (1) Make a temporary seal.
 - (a) Apply aluminum foil tape (speed tape).
 - (b) Keep a record of the location of the damage.
 - (c) If the tape is on the exterior surface of the fairing, then make sure that it is in satisfactory condition at normal maintenance intervals.
 - (2) Make a permanent seal.
 - (a) Apply BMS 8-207 or BMS 8-301 epoxy resin to the area as given in 51-70-08.
 - (b) Apply one layer of BMS 10-79, Type III or BMS 10-103, Type I primer. Refer to SOPM 20-44-04.
 - (c) Apply one layer of BMS 10-60, Type II enamel to the exterior surfaces of the rudder tip fairing skins that are sealed with epoxy resin. Refer to AMM 51-21-00/701.
- D. Seal all of the damage areas that are more than one ply in depth. Refer to the allowable damage limits given in Paragraph 4./ALLOWABLE DAMAGE 1
 - (1) Use a vacuum and heat to remove moisture from the solid laminate. Refer to 51-70-04.
 - (2) Make a temporary seal with aluminum foil tape (speed tape).
 - (3) Keep a record of the location of the damage.
 - (4) Repair the damage at or before 250 flight cycles from the time the seal was made.
- E. The definition of the words "other damage", as used in the allowable damage limits, does not include nicks, gouges, and scratches that do not cause damage to the glass fibers and are sealed.



BOEING®


737-800 STRUCTURAL REPAIR MANUAL



BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details




737-800 STRUCTURAL REPAIR MANUAL



DEFINITIONS OF THE SIZES FOR NICK, GOUGE, AND SCRATCH DAMAGE

А



Damage Definitions Figure 102





3. References

Reference	Title
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-01, GENERAL	Protective Treatment of Metallic and Composite Materials
51-20-05, GENERAL	Repair Sealing
51-30-03, GENERAL	Sources for Non-Metallic Repair Materials
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
51-60-04, GENERAL	Elevator Balance Procedure For Airplane Line Numbers 1 Through 1174 Prior To Completion of Service Bulletins 737-55-1080, 737-55-1081, and 737-55-1082
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-08	RESIN SWEEP-FAIR PROCEDURES
AMM 51-21-00/701	Interior And Exterior Finishes - Cleaning/Painting
SOPM 20-44-04	Application of Urethane Compatible Primers
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Allowable Damage Limits

- A. Nicks, Gouges, and Scratches that do not cause damage to the glass fibers are permitted.
- B. Nicks, Gouges, and Scratches that cause damage to the glass fibers are permitted if:
 - (1) The depth is a maximum of one ply.

NOTE: Use the limits for holes and punctures if the damage is more than one ply in depth.

- (2) The length is a maximum of 5.0 inches (127.00 mm)
- (3) The damage is a minimum of 4D (D = the diameter of the damage) away from the edge of other damage.
- C. Dents that do not cause damage to the glass fibers are permitted if:
 - (1) The depth is a maximum of 0.05 inch (1.27 mm)

NOTE: Use the limits for holes and punctures if the damage is more than 0.05 inch (1.27 mm) in depth.

- (2) The diameter is a maximum of 2.0 inches (50.80 mm)
- (3) The damage is a minimum of 4D (D = the diameter of the damage) away from the edge of other damage, a hole, or the edge of the part.
- D. Holes and Punctures are permitted if:
 - (1) The diameter is a maximum of 2.0 inches (50.80 mm)
 - (2) The damage is a minimum of 4D (D = the diameter of the damage) away from the edge of other damage, a hole, or the edge of the part.
- E. Delaminations are permitted if:
 - (1) The diameter is a maximum of 2.0 inches (50.80 mm)
 - (2) The damage is a minimum of 2D (D = the diameter of the damage) away from the edge of other damage, a hole, or the edge of the part.
- F. Edge damage is permitted if:
 - (1) The depth is a maximum of 0.10 inch (2.54 mm)





- (2) The width is a maximum of 0.50 inch (12.70 mm)
- (3) The damage is a minimum of 4D (D = the diameter of the damage) away from the edge of other damage.






REPAIR 1 - RUDDER TIP FAIRING SKINS

1. Applicability

- A. Repair 1 is applicable to the skin parts of the rudder tip fairing skins made of Glass Fiber Reinforced Plastic (GFRP) as shown in Rudder Tip Fairing Skin Location, Figure 201/REPAIR 1.
- B. Repair 1 is applicable to damage that is more than the limits permitted in Allowable Damage 1. Refer to Allowable Damage 1 for the type and size of damage that is permitted.



Rudder Tip Fairing Skin Location Figure 201

2. General

- A. Repair 1 gives the instructions for Category A and B repairs. Refer to 51-00-06 to find the definitions of the different categories of repairs.
- B. Get access to the damaged area.
 - (1) If necessary, remove the rudder tip fairing skins.
 - (2) Refer to 51-40-02 for information on fastener removal.
- C. Do an inspection of the damaged area to find the dimensions of the damage.
 - (1) Boeing recommends that you use an instrumented Non-Destructive Test (NDT) procedure. Refer to NDT, Part 1, 51-01-02 for the inspection procedures.
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.
- D. Refer to Damage Definitions, Figure 202/REPAIR 1, Details A, B, and C for the definitions of the length, width, and depth of damage.
- E. Do the repair as given in Paragraph 4./REPAIR 1



REPAIR 1 Page 201 Nov 01/2003




- F. Put the rudder tip fairing skin back to the initial condition, as applicable.
 - (1) Install the fairing if it was removed. Refer to 51-40-02 for the data about fastener installation.



REPAIR 1 Page 202 Nov 01/2003




737-800 STRUCTURAL REPAIR MANUAL



DEFINITIONS OF THE SIZES FOR NICK, GOUGE, AND SCRATCH DAMAGE

А



Damage Definitions Figure 202



REPAIR 1 Page 203 Nov 01/2003



3. References

Reference	Title
51-00-06	STRUCTURAL REPAIR DEFINITIONS
51-10-01, GENERAL	Aerodynamic Smoothness Requirements
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-05, GENERAL	Repair Sealing
51-40-02	FASTENER INSTALLATION AND REMOVAL
51-70-04	REPAIR PROCEDURES FOR WET LAYUP MATERIALS
51-70-05, REPAIR GENERAL	Repair Procedures for Preimpregnated Materials
51-70-06, REPAIR GENERAL	Room Temperature Cure Repairs With Wet Layup Materials For Glass Fabric Reinforced Plastic Solid Laminates and Honeycomb Core Panels
737 NDT Part 1, 51-01-01	Inspection of Repairs to Composite Structure
737 NDT Part 1, 51-01-02	NDT Examination of Composite Structure for Impact Damage

4. Repair Instructions

- A. If a dent is 2 inches (50.80 mm) in diameter or less, and has no fiber damage or delamination, then fill the dent with potting compound and apply a fiberglass patch as given in Repair 14 of 51-70-04.
- B. If Paragraph 4.A./REPAIR 1 is not applicable, then refer to Table 201/REPAIR 1 for the repair data that is applicable to damage to the rudder tip fairing skins.
- C. For repairs made with wet layup materials, do as follows, as applicable:
 - (1) Use one repair ply of fabric for each initial ply that was damaged.
 - (2) Add two structural plies of fabric for each facesheet that is repaired. Put one structural ply at ± 45 degrees to the core ribbon direction and the other at 0 or 90 degrees.
 - **NOTE**: Repair plies or added plies are not necessary in the repair of delamination at an edge if the delamination is a minimum of 2D (D = fastener diameter) away from a fastener hole.
 - (3) Examine Category B repairs after each interval of 800 flight hours or more frequently. Refer to 737 NDT Part 1, 51-01-01 for the inspection procedures. If deterioration is found, then they must be replaced with Category A repairs.
 - **NOTE**: Other inspection methods that have been examined and found to be satisfactory by the operator can be used.
- D. For repairs made with preimpregnated layup materials, use the same number of repair plies as the number of initial plies that were damaged.



REPAIR 1 Page 204 Jul 10/2005



Table 201:


REPAIR DATA FOR THE RUDDER TIP FAIRING SKINS - 250°F (121°C) CURE				
REPAIR TYPE	CATEGORY B WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A WET LAYUP	CATEGORY A PREIMPREGNATED LAYUP
REPAIR CURE TEMPERATURE	Room Temperature	150°F (66°C)	200°F (93°C)	250°F (121°C)
REPAIR SIZE AND LIMITS	Contact The Boeing Company	Damage that is a maximum of:	Damage that is a maximum of:	There are no limits on the dimensions of the repair
		- 5.0 inches (127.00 mm) in diameter	- 5.0 inches (127.00 mm) in diameter	
		- 2.0 inches (50.8 mm) minimum clearance from:	- 2.0 inches (50.8 mm) minimum clearance from:	
		- other repairs - fastener hole - panel edges	- other repairs - fastener holes - panel edges	
REPAIR PROCEDURES		SRM 51-70-04 and Paragraph 4.C	SRM 51-70-04 and Paragraph 4.C	SRM 51-70-05 and Paragraph 4.C



D634A210 D634A210 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



IDENTIFICATION 1 - RUDDER HINGE FITTINGS



NOTE: REFER TO TABLE 1 FOR THE REFERENCE DRAWINGS.


Rudder Hinge Fittings Location Figure 1

|--|

	REFERENCE DRAWINGS		
DRAWING NUMBER	TITLE		
173A0001	Rudder Installation		
173A0100	Rudder Functional Product Collector		
173A0103	Rudder Assembly		
173A2001	Spar Installation - Rudder		
173A2200	Fitting Assembly - Thrust and Actuator, Rudder		



Page 1



Rudder Hinge Fittings Identification Figure 2



IDENTIFICATION 1 Page 2 Mar 10/2004



Table 2:

LIST OF MATERIALS FOR FIGURE 1				
ITEM	DESCRIPTION	T ^{*[1]}	MATERIAL	EFFECTIVITY
[1]	Hinge Fitting STA 276.24		7050-T7451 plate as given in AMS 4050. Refer to the production drawing for the machined areas, and the grain direction	
[2]	Hinge Fitting STA 257.92		7050-T7451 plate as given in AMS 4050. Refer to the production drawing for the machined areas, and the grain direction	
[3]	Hinge Fitting STA 239.61		7050-T7451 plate as given in AMS 4050. Refer to the production drawing for the machined areas, and the grain direction	
[4]	Hinge Fitting STA 184.67		7050-T7451 plate as given in AMS 4050. Refer to the production drawing for the machined areas, and the grain direction	
[5]	Hinge Fitting STA 129.74		7050-T7451 plate as given in BMS 7-323. Refer to the production drawing for the machined areas, and the grain direction	
[6]	Hinge Fitting STA 74.80		7050-T7451 plate as given in BMS 7-323. Refer to the production drawing for the machined areas, and the grain direction	
[7]	Actuator Fitting		7050-T7451 plate as given in BMS 7-323. Refer to the production drawing for the machined areas, and the grain direction	
[8]	Thrust Fitting		7050-T7451 plate as given in BMS 7-323. Refer to the production drawing for the machined areas, and the grain direction	
[9]	Hinge Fitting STA 6.96		7050-T7451 plate as given in BMS 7-323. Refer to the production drawing for the machined areas, and the grain direction	

*[1] Note: T = Pre-manufactured thickness in inches (millimeters).





ALLOWABLE DAMAGE 1 - RUDDER HINGE FITTINGS

1. Applicability

A. This subject gives the allowable damage limits for the rudder hinge fittings shown in Rudder Hinge Fitting Location, Figure 101/ALLOWABLE DAMAGE 1.


2. General

- A. Refer to Paragraph 4./ALLOWABLE DAMAGE 1 for the allowable damage limits.
- B. Remove the damage as necessary.
 - (1) Refer to 51-10-02 for the investigation and removal of damage.
 - (2) Refer to 51-30-03 for possible sources of nonmetallic materials you can use to remove the damage.
 - (3) Refer to 51-30-05 for possible sources of the equipment and tools you can use to remove the damage.
 - (4) Put a surface finish of 125 microinches Ra or better on the reworked areas.
- C. After you remove the damage, do the steps that follow.

WARNING: MAKE SURE THAT YOU WEAR EYE PROTECTION WHEN YOU USE THE FLAP PEEN WHEEL. IF YOU DO NOT OBEY, AN INJURY CAN OCCUR.


- (1) Flap peen or shot peen the reworked areas of the parts, but not the inner surfaces of the lug bores.
 - (a) Refer to 51-20-06 for the shot peen intensity and shot number.
 - (b) Refer to SOPM 20-10-03 for the flap peen and shot peen procedures.
- (2) Apply a chemical conversion coating to the reworked areas. Refer to 51-20-01.
- (3) Apply a layer of BMS 10-79, Type III primer to the reworked areas. Refer to SOPM 20-44-04.








737-800 STRUCTURAL REPAIR MANUAL



ALLOWABLE DAMAGE 1 **55-40-90**Page 103 Nov 01/2003



737-800 STRUCTURAL REPAIR MANUAL



Rudder Hinge Fitting Location Figure 101 (Sheet 3 of 3)





3. References

Reference	Title
51-10-02	INSPECTION AND REMOVAL OF DAMAGE
51-20-01	PROTECTIVE TREATMENT OF METALLIC AND COMPOSITE MATERIALS
51-20-06	SHOT PEENING
51-30-03	NON-METALLIC MATERIALS
51-30-05	EQUIPMENT AND TOOLS FOR REPAIRS
SOPM 20-10-03	General - Shot Peening Procedures
SOPM 20-20-02	Penetrant Methods of Inspection
SOPM 20-44-04	Application of Urethane Compatible Primers

4. Allowable Damage Limits

- A. Hinge Fittings (Except at RSTA 129.74 and RSTA 184.67)
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, C, D, and E.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- B. Hinge Fitting at RSTA 129.74
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A and B.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A and B.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- C. Hinge Fitting at RSTA 184.67
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, and C.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, C, and D.
 - (3) Dents are not permitted.
 - (4) Holes and Punctures are not permitted.
- D. Actuator Thrust Fitting
 - (1) Damage is not permitted.






- E. Actuator Support Fitting
 - (1) Cracks:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A and B.
 - (2) Nicks, Gouges, Scratches, and Corrosion:
 - (a) Remove the damage as shown in Allowable Damage Limits, Figure 102/ALLOWABLE DAMAGE 1, Details A, B, and E.




BOEING

737-800 STRUCTURAL REPAIR MANUAL




Allowable Damage Limits Figure 102 (Sheet 1 of 3)





BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



C-C

55-40-90

OF 1.0 INCH (TYPICAL)

ALLOWABLE DAMAGE 1

Page 109

Nov 01/2003

D634A210

BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details

Allowable Damage Limits Figure 102 (Sheet 3 of 3)

EDGE

B-B

OF THE


BUSHING

SURFACE

DAMAGE



REPAIR 1 - RUDDER HINGE FITTINGS




Rudder Hinge Fitting Repair Figure 201 (Sheet 1 of 2)



REPAIR 1 Page 201 Nov 01/2003





REPAIR 1 Page 202 Nov 10/2006