# CHAPTER 52

## DOORS



#### CHAPTER 52 DOORS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
EFFECTIVE PAG	<b>BES</b>	52-10-01 REPAIR	R 1		VABLE DAMAGE 1
1 thru 5	May 20/2009	201	Jan 20/2005	(cont)	F I 00/0005
6	BLANK	202	Jan 20/2005	102	Feb 20/2005
52–CONTENTS		52-10-01 REPAIR	R 2	103	Feb 20/2005
1	May 20/2005	201	Jan 20/2005	104	Feb 20/2005
2	Feb 20/2005	202	Jan 20/2005	105	Feb 20/2005
3	Feb 20/2005	203	Jan 20/2005	106	Feb 20/2005
4	Feb 20/2005	204	BLANK	107	Feb 20/2005
5	Feb 20/2005	52-10-01 REPAIR	R 3	108	Feb 20/2005
6	BLANK	201	Jan 20/2005	52-10-02 REPAIR	R GENERAL
52-00-00 GENER		202	BLANK	201	May 20/2005
1	Sep 20/2007	52-10-01 REPAIR	R 4	202	BLANK
2	Sep 20/2007	201	Jan 20/2005	52-20-01 IDENTI	FICATION 1
3	May 20/2005	202	Jan 20/2005	1	Jan 20/2005
4	May 20/2005	52-10-01 REPAIR		2	BLANK
4 52-10-01 IDENTI		201	Jan 20/2005	52-20-01 IDENTI	FICATION 2
	Jan 20/2005	202	Jan 20/2005	1	Jan 20/2005
1 2	BLANK	52-10-01 REPAIR		2	BLANK
_		201	Feb 20/2005	52-20-01 ALLOW	VABLE DAMAGE 1
52-10-01 IDENTI		202	Feb 20/2005	101	Sep 20/2005
1	Jan 20/2005	202	Feb 20/2005	102	Sep 20/2005
2	BLANK	203	Feb 20/2005	103	Sep 20/2005
52-10-01 IDENTI		204	Feb 20/2005	104	BLANK
1	Jan 20/2005	205	Feb 20/2005	52-20-01 ALLOW	VABLE DAMAGE 2
2	BLANK			101	Jan 20/2005
52-10-01 IDENTI		52-10-02 IDENTI		102	Jan 20/2005
1	Jan 20/2005	1	Jan 20/2005	52-20-01 REPAIR	R 1
2	BLANK	2	Jan 20/2005	201	Jan 20/2005
	ABLE DAMAGE 1	52-10-02 IDENTI		202	Jan 20/2005
101	Jan 20/2005	1	Jan 20/2005	203	Jan 20/2005
102	Jan 20/2005	2	Jan 20/2005	204	BLANK
103	Jan 20/2005	3	Jan 20/2005	52-20-01 REPAIR	
104	Jan 20/2005	4	BLANK	201	Jan 20/2005
105	Jan 20/2005	52-10-02 IDENTI		202	Jan 20/2005
106	Jan 20/2005	1	Jan 20/2005	52-20-01 REPAIR	
107	Jan 20/2005	2	Jan 20/2005	201	Jan 20/2005
108	BLANK	52-10-02 IDENTI	FICATION 4	201	Jan 20/2005
52-10-01 ALLOW	ABLE DAMAGE 2	1	Jan 20/2005	52-20-01 REPAIR	
101	Jan 20/2005	2	Jan 20/2005		
102	Jan 20/2005	52-10-02 ALLOW	ABLE DAMAGE 1	201	Jan 20/2005
		101	Jan 20/2007	202	BLANK

A = Added, R = Revised, O = Overflow, D = Deleted

## **52-EFFECTIVE PAGES**

Page 1 May 20/2009



#### CHAPTER 52 DOORS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
52-20-02 IDENTI	FICATION 1	52-30-01 ALLOW	ABLE DAMAGE 1	52-30-02 IDENTIF	FICATION 3 (cont)
1	Jan 20/2005	(cont)		2	Jan 20/2005
2	Jan 20/2005	105	May 20/2005	52-30-02 IDENTIF	FICATION 4
3	Jan 20/2005	106	BLANK	1	Jan 20/2005
4	BLANK	52-30-01 ALLOW	ABLE DAMAGE 2	2	Jan 20/2005
52-20-02 IDENTI	FICATION 2	101	Jan 20/2005	52-30-02 ALLOW	ABLE DAMAGE 1
1	Jan 20/2005	102	Jan 20/2005	101	Jan 20/2007
2	Jan 20/2005	52-30-01 REPAIF	GENERAL	102	Jan 20/2005
3	Jan 20/2005	201	Jan 20/2005	103	Jan 20/2005
4	BLANK	202	BLANK	104	May 20/2005
52-20-02 ALLOW	ABLE DAMAGE 1	52-30-01 REPAIF	1	105	Jan 20/2005
101	Jan 20/2005	201	May 20/2005	106	Jan 20/2005
102	Jan 20/2005	202	May 20/2005	107	Jan 20/2005
103	Jan 20/2005	203	May 20/2005	108	BLANK
104	Jan 20/2005	204	BLANK	52-30-02 REPAIF	GENERAL
52-20-02 ALLOW	ABLE DAMAGE 2	52-30-01 REPAIF	12	201	Jan 20/2005
101	Jan 20/2005	201	May 20/2005	202	BLANK
102	Jan 20/2005	202	May 20/2005	52-40-01 IDENTIF	ICATION 1
103	Jan 20/2005	203	May 20/2005	1	Jan 20/2005
104	Jan 20/2005	204	BLANK	2	BLANK
52-20-02 REPAIF	R GENERAL	52-30-01 REPAIF		52-40-01 IDENTIF	FICATION 2
201	Jan 20/2005	201	May 20/2005	1	Jan 20/2005
202	BLANK	202	May 20/2005	2	BLANK
52-30-01 IDENTI	FICATION 1	52-30-01 REPAIF	R 4	52-40-01 IDENTIF	FICATION 3
1	Jan 20/2005	201	May 20/2005	1	Jan 20/2005
2	BLANK	202	May 20/2005	2	BLANK
52-30-01 IDENTI	FICATION 2	203	May 20/2005	52-40-01 IDENTIF	FICATION 4
1	Jan 20/2005	204	May 20/2005	1	Jan 20/2005
2	BLANK	205	May 20/2005	2	BLANK
52-30-01 IDENTI	FICATION 3	206	May 20/2005	52-40-01 IDENTIF	FICATION 5
1	Jan 20/2005	52-30-02 IDENTI		1	Jan 20/2005
2	BLANK	1	May 20/2006	2	BLANK
52-30-01 IDENTI	FICATION 4	2	May 20/2006	52-40-01 IDENTIF	FICATION 6
1	Jan 20/2005	3	May 20/2006	1	Jan 20/2005
2	Jan 20/2005	4	Sep 20/2006	2	BLANK
52-30-01 ALLOW	ABLE DAMAGE 1	52-30-02 IDENTI		52-40-01 IDENTIF	FICATION 7
101	Jan 20/2007	1	Jan 20/2005	1	Jan 20/2005
102	Jan 20/2005	2	Jan 20/2005	2	BLANK
103	May 20/2005	52-30-02 IDENTIF		52-40-01 IDENTIF	FICATION 8
104	Jan 20/2005	1	Jan 20/2005	1	Jan 20/2005

A = Added, R = Revised, O = Overflow, D = Deleted

## **52-EFFECTIVE PAGES**

Page 2 May 20/2009



#### CHAPTER 52 DOORS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
52-40-01 IDENTI	FICATION 8 (cont)	52-40-01 REPAIR	2	52-40-02 IDENTIF	FICATION 9 (cont)
2	BLANK	201	Jan 20/2005	2	Jan 20/2005
52-40-01 ALLOW	ABLE DAMAGE 1	202	Jan 20/2005	52-40-02 IDENTIF	FICATION 10
101	Jan 20/2005	52-40-01 REPAIR	3	1	Jan 20/2005
102	Jan 20/2005	201	Jan 20/2005	2	BLANK
103	Jan 20/2005	202	Jan 20/2005	52-40-02 IDENTIF	FICATION 11
104	BLANK	52-40-01 REPAIR	4	1	Jan 20/2005
52-40-01 ALLOW	ABLE DAMAGE 2	201	Jan 20/2005	2	BLANK
101	Jan 20/2005	202	Jan 20/2005	52-40-02 IDENTIF	FICATION 12
102	Jan 20/2005	52-40-01 REPAIR	5	1	Jan 20/2005
103	Jan 20/2005	201	Jan 20/2005	2	BLANK
104	BLANK	202	Jan 20/2005	52-40-02 IDENTIF	FICATION 13
52-40-01 ALLOW	ABLE DAMAGE 3	52-40-02 IDENTIF	FICATION 1	1	Jan 20/2005
101	Jan 20/2005	1	Jan 20/2005	2	BLANK
102	Jan 20/2005	2	BLANK	52-40-02 ALLOW	ABLE DAMAGE 1
103	Jan 20/2005	52-40-02 IDENTIF	FICATION 2	101	Jan 20/2005
104	BLANK	1	Jan 20/2005	102	Jan 20/2005
52-40-01 ALLOW	ABLE DAMAGE 4	2	Jan 20/2005	103	Jan 20/2005
101	Jan 20/2005	3	Jan 20/2005	104	BLANK
102	Jan 20/2005	4	BLANK	52-40-02 ALLOW	ABLE DAMAGE 2
103	Jan 20/2005	52-40-02 IDENTIF	FICATION 3	101	Jan 20/2005
104	BLANK	1	Jan 20/2005	102	Jan 20/2005
52-40-01 ALLOW	ABLE DAMAGE 5	2	BLANK	103	Jan 20/2005
101	Jan 20/2005	52-40-02 IDENTIF	FICATION 4	104	BLANK
102	Jan 20/2005	1	Jan 20/2005	52-40-02 ALLOW	ABLE DAMAGE 3
103	Jan 20/2005	2	BLANK	101	Jan 20/2005
104	BLANK	52-40-02 IDENTIF	FICATION 5	102	Jan 20/2005
52-40-01 ALLOW	ABLE DAMAGE 6	1	Jan 20/2005	103	Jan 20/2005
101	Jan 20/2005	2	Jan 20/2005	104	BLANK
102	Jan 20/2005	52-40-02 IDENTIF	FICATION 6	52-40-02 ALLOW	ABLE DAMAGE 4
103	Jan 20/2005	1	Jan 20/2005	101	Jan 20/2005
104	BLANK	2	BLANK	102	Jan 20/2005
52-40-01 ALLOW	ABLE DAMAGE 7	52-40-02 IDENTIF	FICATION 7	52-40-02 ALLOW	ABLE DAMAGE 5
101	Jan 20/2005	1	Jan 20/2005	101	Jan 20/2005
102	Jan 20/2005	2	Jan 20/2005	102	Jan 20/2005
103	Jan 20/2005	52-40-02 IDENTIF	FICATION 8	103	Jan 20/2005
104	BLANK	1	Jan 20/2005	104	BLANK
52-40-01 REPAIR	R 1	2	Jan 20/2005	52-40-02 ALLOW	ABLE DAMAGE 6
201	Jan 20/2005	52-40-02 IDENTIF	FICATION 9	101	Sep 20/2005
202	Jan 20/2005	1	Jan 20/2005	102	Sep 20/2005

A = Added, R = Revised, O = Overflow, D = Deleted

## **52-EFFECTIVE PAGES**

Page 3 May 20/2009



#### CHAPTER 52 DOORS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
52-40-02 ALLOW	ABLE DAMAGE 6	52-40-02 REPAIR	R 5 (cont)	52-80-02 IDENTI	FICATION 2
(cont)		204	BLANK	1	Jan 20/2005
103	Sep 20/2005	52-40-02 REPAIF	R 6	2	Jan 20/2005
104	BLANK	201	Jan 20/2005	3	Jan 20/2005
52-40-02 ALLOW	ABLE DAMAGE 7	202	Jan 20/2005	4	Jan 20/2005
101	Jan 20/2005	203	Jan 20/2005	5	Jan 20/2005
102	Jan 20/2005	204	BLANK	6	BLANK
103	Jan 20/2005	52-40-02 REPAIF	R 7	52-80-02 IDENTI	FICATION 3
104	Jan 20/2005	201	Jan 20/2005	1	Jan 20/2005
105	Jan 20/2005	202	Jan 20/2005	2	Jan 20/2005
106	BLANK	203	Jan 20/2005	3	Jan 20/2005
52-40-02 ALLOW	ABLE DAMAGE 8	204	BLANK	4	BLANK
101	Jan 20/2005	52-50-02 IDENTI	FICATION 1	52-80-02 IDENTI	FICATION 4
102	Jan 20/2005	1	Jan 20/2005	1	Jan 20/2005
103	Jan 20/2005	2	Jan 20/2005	2	BLANK
104	BLANK	52-50-02 ALLOW	ABLE DAMAGE 1	52-80-02 ALLOW	VABLE DAMAGE 1
52-40-02 REPAIF	R 1	101	Jan 20/2007	101	May 20/2006
201	Jan 20/2005	102	Jan 20/2005	102	May 20/2006
202	Jan 20/2005	103	Jan 20/2005	103	May 20/2006
203	Jan 20/2005	104	Jan 20/2005	104	Jan 20/2005
204	BLANK	52-50-02 REPAIR	R 1	105	Jan 20/2005
52-40-02 REPAIF	R 2	201	Jan 20/2005	106	Jan 20/2005
201	Jan 20/2005	202	Jan 20/2005	107	Jan 20/2005
202	Jan 20/2005	203	Jan 20/2005	108	Jan 20/2005
203	Jan 20/2005	204	Jan 20/2005	109	Jan 20/2005
204	BLANK	52-80-00 GENER	AL	110	Jan 20/2005
52-40-02 REPAIF	3	1	Jan 20/2005	52-80-02 ALLOW	VABLE DAMAGE 2
201	Jan 20/2005	2	BLANK	101	Jan 20/2005
202	Jan 20/2005	52-80-02 IDENTI	FICATION 1	102	Jan 20/2005
203	Jan 20/2005	1	Jan 20/2005	103	Jan 20/2005
204	BLANK	2	Jan 20/2005	104	Jan 20/2005
52-40-02 REPAIF	3 4	3	Jan 20/2005	105	Jan 20/2005
201	Jan 20/2005	4	Jan 20/2005	106	BLANK
202	Jan 20/2005	5	Jan 20/2005		VABLE DAMAGE 3
203	Jan 20/2005	6	Jan 20/2005	101	Jan 20/2005
204	BLANK	7	Jan 20/2005	102	Jan 20/2005
52-40-02 REPAIR	3 5	8	Jan 20/2005	103	Jan 20/2005
201	Jan 20/2005	9	Jan 20/2005	104	Jan 20/2005
202	Jan 20/2005	10	BLANK	105	Jan 20/2005
203	Jan 20/2005	-		106	BLANK

A = Added, R = Revised, O = Overflow, D = Deleted

## **52-EFFECTIVE PAGES**

Page 4 May 20/2009



#### CHAPTER 52 DOORS

Subject/Page	Date	Subject/Page	Date	Subject/Page	Date
52-80-02 ALLOW	ABLE DAMAGE 4				
101	Jan 20/2005				
102	Jan 20/2005				
103	Jan 20/2005				
104	Jan 20/2005				
52-80-02 REPAIF	8 1				
201	Jan 20/2005				
202	Jan 20/2005				
52-80-02 REPAIF	8 2				
201	Jan 20/2005				
202	Jan 20/2005				
52-80-02 REPAIF	3				
201	Jan 20/2005				
202	Jan 20/2005				
203	Jan 20/2005				
204	Jan 20/2005				
205	Jan 20/2005				
206	Jan 20/2005				
207	Jan 20/2005				
208	Jan 20/2005				
52-80-02 REPAIF	R 4				
201	Jan 20/2005				
202	Jan 20/2005				
203	Jan 20/2005				
204	BLANK				
52-80-02 REPAIF	₹5				
201	Jan 20/2005				
202	Jan 20/2005				

A = Added, R = Revised, O = Overflow, D = Deleted

## **52-EFFECTIVE PAGES**

Page 5 May 20/2009



#### CHAPTER 52 DOORS

<u>SUBJECT</u>	CHAPTER SECTION <u>SUBJECT</u>
DOORS - GENERAL	52-00-00
GENERAL - Doors	
ENTRY DOOR SKIN	52-10-01
IDENTIFICATION 1-No. 1 Entry Door Skin	
IDENTIFICATION 2-No. 2 Left Side Entry Door Skin	
IDENTIFICATION 3-No. 1 Right Side Service Door Skin	
IDENTIFICATION 4-No. 4 Passenger and Service Door Skin	
ALLOWABLE DAMAGE 1-Entry Door Skin	
ALLOWABLE DAMAGE 2-Operating Limits for Entry Door Skin	
REPAIR 1-Small Hole in Entry Door Skin - Flush Repair	
REPAIR 2-Entry Door Skin - Non-Flush Repair	
REPAIR 3-Small Hole in Entry Door Skin - External Repair	
REPAIR 4-Entry Door Skin - Typical Flush Repair at Beam	
REPAIR 5-Entry Door Skin - Flush Repair Between Beams (0.040 Chem-Mill Pocket Only)	
REPAIR 6-Passenger / Service Door Skin - Inner Doubler Repair of the Outer Skin Assembly at the Door Hinge Cutout	
MAIN ENTRY DOOR STRUCTURE	52-10-02
IDENTIFICATION 1-No. 1 Entry Door Structure	
IDENTIFICATION 2-No. 2 Left Side Passenger Door Structure	
IDENTIFICATION 3-No. 1 Right Side Service Door Structure	
IDENTIFICATION 4-No. 4 Passenger and Service Door Structure	
ALLOWABLE DAMAGE 1-Entry Door Structure	
REPAIR GENERAL-Entry Door Structure	
EMERGENCY EXIT DOOR SKIN	52-20-01
IDENTIFICATION 1-Overwing Emergency Exit Skin	

IDENTIFICATION 2-No. 3 Emergency Exit Door Skin

## **52-CONTENTS**

Page 1 May 20/2005



#### CHAPTER 52 DOORS

<u>SUBJECT</u>	SECTION SUBJECT
ALLOWABLE DAMAGE 1-Emergency Exit Door Skin	
ALLOWABLE DAMAGE 2-Operating Limits for Emergency Exit Door Skin	
REPAIR 1-Emergency Exit Door Skin - Flush Repair Between Stiffeners	
REPAIR 2-Emergency Exit Door Skin - Flush Repair at Stiffener	
REPAIR 3-Small Hole Flush Repair - Emergency Exit Door Skin	
REPAIR 4-Small Hole External Repair - Emergency Exit Door Skin	
EMERGENCY EXIT DOOR STRUCTURE	52-20-02
IDENTIFICATION 1-Overwing Emergency Exit Structure	
IDENTIFICATION 2-N0. 3 Emergency Exit Structure	
ALLOWABLE DAMAGE 1-Overwing Emergency Exit Door Structure	
ALLOWABLE DAMAGE 2-No. 3 Emergency Exit Door Structure	
REPAIR GENERAL - Emergency Exit Structure	
CARGO DOOR SKIN	52-30-01
IDENTIFICATION 1-No. 2 Cargo Door Skin	
IDENTIFICATION 2-No. 1 Cargo Door Skin	
IDENTIFICATION 3-No. 3 Cargo Door Skin	
IDENTIFICATION 4-Main Deck Cargo Door - Skin	
ALLOWABLE DAMAGE 1-Cargo Door Skin	
ALLOWABLE DAMAGE 2-Operating Limits for Cargo Door Skin	
REPAIR GENERAL-Typical Skin Repairs for Cargo Doors	
REPAIR 1-Cargo Doors - Flush Skin Repair Between Beams	
REPAIR 2-Cargo Doors - Small Hole - Flush Repair	
REPAIR 3-Cargo Doors - Small Hole - External Repair	
REPAIR 4-Cargo Doors - External Skin Repair	
CARGO DOOR STRUCTURE	52-30-02
IDENTIFICATION 1-No. 2 Cargo Door Structure	
IDENTIFICATION 2-No. 1 Cargo Door Structure	

## **52-CONTENTS**

Page 2 Feb 20/2005

CHAPTER



#### CHAPTER 52 DOORS

SUBJECT	SECTION
IDENTIFICATION 3-No. 3 Cargo Door Structure	
IDENTIFICATION 4-Main Deck Cargo Door Structure	
ALLOWABLE DAMAGE 1-Cargo Door Structure	
REPAIR GENERAL - Cargo Door Structure	
ACCESS DOOR SKIN	52-40-01
IDENTIFICATION 1-Forward Access Door Skin	
IDENTIFICATION 2-Elec/Elex Access Door Skin	
IDENTIFICATION 3-Elevator Control Access Door Skin	
IDENTIFICATION 4-Service and Pressure Relief Door Skin	
IDENTIFICATION 5- APU Access Door Skin	
IDENTIFICATION 6-Water Service Door	
IDENTIFICATION 7-Waste Disposal Access Door Skin	
IDENTIFICATION 8-Mid Lavatory Waste Door	
ALLOWABLE DAMAGE 1-Allowable Damage - Forward Access Door Skin	
ALLOWABLE DAMAGE 2-Allowable Damage - Elec/Elex Access Door Skin	
ALLOWABLE DAMAGE 3 - Allowable Damage - Elevator Control Access Door Skin	
ALLOWABLE DAMAGE 4-Allowable Damage - Aft Body Access Door Skin	
ALLOWABLE DAMAGE 5 - Allowable Damage - APU Access Door Skin	
ALLOWABLE DAMAGE 6 - Allowable Damage - Water Service Door Skin	
ALLOWABLE DAMAGE 7 - Allowable Damage - Waste Disposal Access Door Skin	
REPAIR 1-Small Hole Flush Repair - Access Doors	
REPAIR 2-Small Hole - External Repair	
REPAIR 3-APU Access Door - Flush Skin Repair Between Beams	
REPAIR 4-APU Accss Door - Flush Skin Repair at Frames	
REPAIR 5-APU Access Door - External Skin Repairs	
ACCESS DOOR STRUCTURE	52-40-02
IDENTIFICATION 1-Forward Access Door Structure	

**52-CONTENTS** 

CHAPTER



#### **CHAPTER 52** DOORS

#### SUBJECT

CHAPTER SECTION SUBJECT

IDENTIFICATION 2-Elec/Elex Access Door Structure **IDENTIFICATION 3-Elevator Control Access Door Structure IDENTIFICATION 4-Service and Pressure Relief Door Structure IDENTIFICATION 5-Hydraulic Access Door Structure IDENTIFICATION 6-APU Access Door Structure IDENTIFICATION 7-Air Conditioning Access Door Structure IDENTIFICATION 8-Ram Air Turbine Door Structure** IDENTIFICATION 9-Section 43 - Wing-to-Body Fairing Access Door Structure: Air Conditioning Inlet, Drain Mast, Ground Air Conditioning **IDENTIFICATION 10-Landing Gear Ground Access Door Structure** IDENTIFICATION 11-APU Intake Port - Frame/Door Structure **IDENTIFICATION 12-Fin Access Door Structure IDENTIFICATION 13-Toilet Drain Access Door Structure** ALLOWABLE DAMAGE 1- Ram Air Turbine Door ALLOWABLE DAMAGE 2-Air Conditioning Access Door ALLOWABLE DAMAGE 3-Hydraulic Access Door ALLOWABLE DAMAGE 4-Section 43 - Wing-to-Body Fairing Access Doors Air Conditioning Inlet, Drain Mast, Ground Air Conditioning ALLOWABLE DAMAGE 5-Landing Gear Ground Access Door ALLOWABLE DAMAGE 6-Fin Access Door ALLOWABLE DAMAGE 7 - APU Access Door Structure ALLOWABLE DAMAGE 8-Toilet Drain Access Door **REPAIR 1-Hydraulic Access Door Repairs REPAIR 2-Air Conditioning Access Door Repairs REPAIR 3-Ram Air Turbine Door Repairs** REPAIR 4-Section 43 - Wing to Body Fairing Access Door Repairs - Air Conditioning Inlet, Drain Mast, Ground Air Conditioning **REPAIR 5-Landing Gear Ground Access Door Repairs 52-CONTENTS** 

> Page 4 Feb 20/2005



#### CHAPTER 52 DOORS

<u>SUBJECT</u>	CHAPTER SECTION <u>SUBJECT</u>
REPAIR 6-Fin Access Door Repairs	
REPAIR 7-Toilet Drain Access Door Repairs	
FIXED INTERIOR DOORS STRUCTURE	52-50-02
IDENTIFICATION 1-Flight Deck Door Structure	
ALLOWABLE DAMAGE 1-Allowable Damage - Flight Deck Door Structure	
REPAIR 1-Flight Deck Door	
LANDING GEAR DOORS	52-80-00
GENERAL-Landing Gear Door Index	
LANDING GEAR DOOR STRUCTURE	52-80-02
IDENTIFICATION 1-Main Landing Gear Door	
IDENTIFICATION 2-Nose Landing Gear Door Skin	
IDENTIFICATION 3-Main Landing Gear Strut Door Skin	
IDENTIFICATION 4-Trunnion Fairing Door	
ALLOWABLE DAMAGE 1-Main Landing Gear Door	
ALLOWABLE DAMAGE 2-Nose Landing Gear Door	
ALLOWABLE DAMAGE 3 - Main Landing Gear Strut Door	
ALLOWABLE DAMAGE 4-Trunnion Fairing Door	
REPAIR 1-Main Landing Gear Strut Door	
REPAIR 2-Trunnion Fairing Door	
REPAIR 3-Main Landing Gear Door	
REPAIR 4-Nose Landing Gear Doors	
REPAIR 5-Repair of Delaminated Aramid Skin Plies - Nose Landing Gear Door	

## **52-CONTENTS**



#### **GENERAL - DOORS**

#### 1. Applicability to modified airplanes

- A. The data in this section is applicable to 757 airplanes and 757 airplanes with Boeing modifications only. Modifications that have been done independently of Boeing are not covered in this manual.
- B. Reference to "757-SF" airplanes refers to 757-200 airplanes modified to the Special Freighter configuration by The Boeing Company. These airplanes are listed in Table 1/GENERAL. Unless otherwise noted, reference to "757-200" includes Special Freighter airplanes.

	Opera	ator	Manufacturer			
Model-Series	Identification code	Effectivity Code	Block Number	Serial number	Line Number	Registration number
757–236	NA201	001	N0009	22172	9	OO-DLN
757–236	NA202	002	N0010	22173	10	OO-DPF
757–236	NA203	003	N0011	22174	11	G-BIKC
757–236	NA204	004	N0013	22175	13	OO-DLQ
757–236	NA206	006	N0016	22177	16	G-BIKF
757–236	NA207	007	N0023	22178	23	G-BIKG
757–236	NA208	008	N0024	22179	24	OO-DLP
757–236	NA209	009	N0025	22180	25	G-BIKI
757–236	NA210	010	N0029	22181	29	G-BIKJ
757–236	NA211	011	N0030	22182	30	G-BIKK
757–236	NA212	012	N0032	22183	32	OO-DPB
757–236	NA213	013	N0033	22184	33	G-BIKM
757–236	NA215	015	N0040	22186	50	G-BIKN
757–236	NA216	016	N0042	22187	52	G-BIKO
757–236	NA217	017	N0044	22188	54	G-BIKP
757–236	NA218	018	N0048	22189	58	OO-DPM
757–236	NA219	019	N0052	22190	63	G-BIKS
757–236	NA220	020	N0061	23398	77	G-BIKT
757–236	NA221	021	N0062	23399	78	G-BIKU
757–236	NA222	022	N0065	23400	81	G-BIKV
757–236	NA223	023	N0070	23492	89	OO-DPK
757–236	NA224	024	N0071	23493	90	OO-DPJ
757–236	NA225	025	N0072	23533	93	G-BIKY
757–236	NA226	026	N0076	23532	98	G-BIKZ
757–236	NA227	027	N0095	23710	123	G-BMRA
757–236	NA228	028	N0106	23975	145	G-BMRB
757–236	NA229	029	N0113	24072	160	G-BMRC
757–236	NA230	030	N0118	24073	166	G-BMRD

Table 1: 757-200 Special freighter aircraft modified by Boeing.





#### Table 1: 757-200 Special freighter aircraft modified by Boeing. (Continued)

	Opera	Operator		Manufacturer		
Model-Series	Identification code	Effectivity Code	Block Number	Serial number	Line Number	Registration number
757–236	NA231	031	N0120	24074	168	G-BMRE
757–236	NA232	032	N0126	24101	175	G-BMRF
757–236	NA233	033	N0128	24102	179	OO-DPI
757–236	NA234	034	N0142	24266	210	G-BMRH
757–236	NA235	035	N0143	24267	211	OO-DPL
757–236	NA236	036	N0146	24268	214	G-BMRJ

#### 2. Door locations - General

A. Refer to Figure 1/GENERAL for the door locations.



GENERAL Page 2 Sep 20/2007





Figure 1 (Sheet 1 of 2)



GENERAL Page 3 May 20/2005



757-200 STRUCTURAL REPAIR MANUAL




BOEING PROPRIETARY - Copyright  ${\rm (\sc )}$  Unpublished Work - See title page for details



757-200 STRUCTURAL REPAIR MANUAL

**IDENTIFICATION 1 - NO. 1 ENTRY DOOR SKIN** 



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	INNER SKIN	0.050	CLAD 7075-T6	
2	STRAP	0.071	7075-T6	
3	STRAP	0.050	CLAD 7075-T6	
4	STRAP	0.160	7075-T6	
5	STRAP	0.100	7075-T6, OPTIONAL: TI-6AL-4V	
6	STRAP	0.080	7075-T6	
7	OUTER SKIN	0.063	CLAD 2024-T3 (CHEM-MILLED TO 0.040 MIN)	
8	PAN	0.071	2024-T42	
9	DOUBLER	0.071	2024-T3	

LIST OF MATERIALS FOR DETAIL I

No. 1 Left Side Entry Door Skin Identification


Figure 1



IDENTIFICATION 1 Page 1 Jan 20/2005







RIGHT SIDE DOOR IS SHOWN, LEFT SIDE DOOR IS OPPOSITE DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	INNER SKIN	0.050	CLAD 7075-T6	
2	STRAP	0.100	7075-T6	
3	STRAP	1.071	7075-T6	
4	OUTER SKIN	0.063	CLAD 2024-T3 (CHEM-MILLED TO 0.040 MIN)	
5	DOUBLER	0.071	2024-т3	
6	PAN	0.063	2024-T42	

LIST OF MATERIALS

No. 2 Entry Door Skin Identification Figure 1




IDENTIFICATION 2 Page 1 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL

#### **IDENTIFICATION 3 - NO. 1 RIGHT SIDE SERVICE DOOR SKIN**



DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL EFFECTIVI	
1	OUTER SKIN	0.063	CLAD 2024-T3 (CHEM-MILLED TO 0.040 MIN)	
2	DOUBLER	0.071	2024-T3	
3	PAN	0.071	2024-T42	
4	INNER SKIN	0.050	CLAD 7075-T6	
5	STRAP	0.100	7075-т6	
6	STRAP	0.125	7075-T6	
7	STRAP	0.071	7075-T6	
8	STRAP	0.050	CLAD 7075-T6	

LIST OF MATERIALS FOR DETAIL I

No. 1 Right Side Service Door Skin Identification Figure 1




IDENTIFICATION 3 Page 1 Jan 20/2005









LEFT SIDE DOOR IS SHOWN, RIGHT SIDE DOOR IS OPPOSITE

DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	INNER SKIN	0.050	CLAD 7075-T6	
2	STRAP	0.063	CLAD 7075-T6	
3	DOUBLER	0.063	CLAD 7075-T6	
4	DOUBLER	0.20	7075-T6	
5	DOUBLER	0.19	7075–T6	
6	OUTER SKIN	0.063	CLAD 2024-T3 (CHEM-MILLED TO 0.040 MIN)	
7	DOUBLER	0.063	CLAD 2024-T3	
8	PAN	0.063	2024-T42	

LIST OF MATERIALS FOR DETAIL I

No. 4 Passenger and Service Door Skin Identification Figure 1




IDENTIFICATION 4 Page 1 Jan 20/2005





#### ALLOWABLE DAMAGE 1 - ENTRY DOOR SKIN




Entry Door Skin Allowable Damage Figure 101 (Sheet 1 of 7)



**BOEING**®


757-200 STRUCTURAL REPAIR MANUAL



ALLOWABLE DAMAGE 1 **52-10-01**Page 102 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL



#### **BOEING**®

757-200 STRUCTURAL REPAIR MANUAL

DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES
OUTER SKIN A	ВК	DK	L	EK
INNER SKIN	C	G	Ŀ	F
STRAPS AND DOUBLERS	В	D	SEE DETAIL VII	F
PAN	В	I	SEE DETAIL VII	Ţ

ALLOWABLE DAMAGE FOR DETAILS I, II, III AND IV

#### NOTES

- REFINISH REWORKED AREAS AS SHOWN IN AMM 51-20.
- REFER TO SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE.
- A REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE IS MORE THAN THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED.
- B CRACKS ARE NOT PERMITTED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED AS SHOWN IN DETAILS V AND IX.
- C FOR EDGE CRACKS SEE DETAIL V. FOR OTHERS SEE DETAIL X. FOR LIGHTENING HOLE EDGE CRACKS SEE DETAIL XI.
- REMOVE DAMAGE AS SHOWN IN DETAILS V, VI, VIII AND IX.
- E CLEAN OUT DAMAGE UP TO 0.25 INCH (6 mm) MAXIMUM DIAMETER AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OR T4 ALUMINUM RIVET.

ALL OTHER HOLES TO BE REPAIRED.

- F CLEAN OUT DAMAGE UP TO 0.25 INCH (6 mm)
   MAXIMUM DIAMETER AND NOT CLOSER THAN
   1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL
   EDGE, OR OTHER DAMAGE.
- G REMOVE DAMAGE AS SHOWN IN DETAILS V, VI, VIII AND IX. CORROSION MAY BE DRILLED OUT UP TO 0.5 INCH (13 mm) MAXIMUM DIAMETER PROVIDED EDGE MARGINS ARE MAINTAINED AS SHOWN IN DETAIL X.
- H 1.50 INCH (38 mm) MINIMUM TO EDGE OF INITIAL FASTENER HOLE, TO EDGE OF FLANGED HOLE OR TO EDGE OF CUTOUT.
- I REMOVE EDGE DAMAGE AS SHOWN IN DETAILS V AND IX. REMOVE CORROSION AROUND FASTENERS AS SHOWN IN DETAIL VIII. REMOVE SURFACE DAMAGE AS SHOWN IN DETAIL XII.

- I REMOVE THE DAMAGE TO A MAXIMUM DIAMETER OF 0.25 INCH (6 mm). THE EDGE OF THE DAMAGE CLEANUP MUST BE:
  - MORE THAN 1 INCH (25 mm) FROM ANY ADJACENT HOLE OR OTHER DAMAGE.
  - MORE THAN 1 INCH (25 mm) FROM THE EDGE OF THE PART.


ALL OTHER HOLES MUST BE REPAIRED.

INSTALL A 2117-T3 OR -T4 ALUMINUM RIVET INTO THE HOLE. MAKE SURE THE LATCH DOES NOT HIT THE HEAD OF THE RIVET WHEN THE LATCH IS OPERATED. IF THE LATCH HITS THE HEAD OF THE RIVET, THEN YOU MUST REMOVE THE RIVET AND REPAIR THE HOLE.

- K REFER TO ALLOWABLE DAMAGE 2 FOR THE PASSENGER/CREW ENTRY DOOR SKIN OPERATING LIMITS AFTER DAMAGE HAS BEEN REMOVED.
- L DENTS THAT ARE MORE THAN THE LIMITS SHOWN IN DETAIL VII SHOULD BE PERMANENTLY REPAIRED. HOWEVER, A REPAIR CAN BE DELAYED IF THE CONDITIONS THAT FOLLOW ARE MET:
  - DENTS MUST BE SMOOTH AND FREE FROM SHARP CREASES, GOUGES, OR CRACKS, AND SHOW NO EVIDENCE OF PULLED, LOOSE, OR MISSING FASTENERS
  - THERE ARE NO DAMAGED OR ELONGATED FASTENER HOLES
  - THE DENT IS NOT FILLED
  - AN EXAMINATION OF THE DENT IS MADE EVERY 300 FLIGHT CYCLES
  - A PERMANENT REPAIR IS MADE AT THE SUBSEQUENT C-CHECK OR BEFORE 24 MONTHS
  - THE DAMAGE IS A MINIMUM OF 0.5 INCH (13 mm) FROM ANY PART OF A BEAM, SKIN DOUBLER, STRAP, FRAME, INTERCOSTAL, OR STIFFENER
  - THE DAMAGE IS A MINIMUM OF 10.0 INCHES (250 mm) FROM A SKIN SPLICE OR CUTOUT, INCLUDING A HINGE CUTOUT OR A HANDLE PAN CUTOUT.


Entry Door Skin Allowable Damage Figure 101 (Sheet 4 of 7)

> ALLOWABLE DAMAGE 1 52-10-01 Page 104 Jan 20/2005




**BOEING**®

#### 757-200 STRUCTURAL REPAIR MANUAL






757-200 STRUCTURAL REPAIR MANUAL







757-200 STRUCTURAL REPAIR MANUAL



NOTES

- A SKIN THICKNESS DOES NOT INCLUDE THE THICKNESS OF THE DOUBLERS, TRIPLERS, OR STRAPS.
- B DAMAGE INCLUDES HOLES, PUNCTURES, NICKS, GOUGES, SCRATCHES, CORROSION AND CRACKS. DAMAGE DOES NOT INCLUDE DENTS.
- C CABIN PRESSURE LIMITS ARE FOR SKIN DAMAGE TO THE PRESSURIZED FUSELAGE SKIN ONLY.

**Operating Limits for Entry Door Skin** Figure 101 (Sheet 1 of 2)



Page 101 Jan 20/2005



CHART AREA	DAMAGE TREATMENT	ALLOWABLE AIRPLANE OPERATIONS
A	CLEAN UP AS SHOWN IN ALLOWABLE DAMAGE 1.	NO FLIGHT RESTRICTIONS.
В	CLEAN UP AS SHOWN IN ALLOWABLE DAMAGE 1 TO DAMAGE DEPTH.	LIMITED TO 50 HOURS OF FLIGHT OR 25 FLIGHTS, WHICHEVER COMES FIRST (INCLUDING REVENUE FLIGHTS).
	DO AN APPLICABLE REPAIR AS GIVEN IN SRM 52-10-01.	REFER TO THE APPLICABLE REPAIR FOR THE LIMITS.
С	CLEAN UP AS SHOWN IN ALLOWABLE DAMAGE 1 TO DAMAGE DEPTH. STOP DRILL 0.25 INCH (6 mm) DIAMETER HOLES AT THE ENDS OF THE CRACKS.	A NON-REVENUE FLIGHT TO A REPAIR STATION IS PERMITTED IF THE APPLICABLE REGULATORY AUTHORITY GIVES APPROVAL BEFORE THE FLIGHT. IT IS RECOMMENDED THAT THE PROPOSED REPAIR PROCEDURE BE GIVEN TO BOEING.
		THE MAXIMUM CABIN PRESSURE DIFFERENTIAL C IS LIMITED TO 6.0 PSIG UNLESS THE SKIN IS REPAIRED.
	DO AN APPLICABLE REPAIR AS GIVEN IN SRM 52-10-01.	REFER TO THE APPLICABLE REPAIR FOR THE LIMITS.
D	CLEAN UP AS SHOWN IN ALLOWABLE DAMAGE 1 TO DAMAGE DEPTH. STOP DRILL 0.25 INCH (6 mm) DIAMETER HOLES AT THE ENDS OF THE CRACKS.	A NON-REVENUE FLIGHT TO A REPAIR STATION IS PERMITTED IF THE APPLICABLE REGULATORY AUTHORITY GIVES APPROVAL BEFORE THE FLIGHT. IT IS RECOMMENDED THAT THE PROPOSED REPAIR PROCEDURE BE GIVEN TO BOEING.
		THE MAXIMUM CABIN PRESSURE DIFFERENTIAL [] IS LIMITED TO 6.0 PSIG UNLESS THE SKIN IS REPAIRED.
	DO AN APPLICABLE REPAIR AS GIVEN IN SRM 52-10-01.	REFER TO THE APPLICABLE REPAIR FOR THE LIMITS.
E	CLEAN UP AS SHOWN IN ALLOWABLE DAMAGE 1 TO DAMAGE DEPTH. STOP DRILL 0.25 INCH (6 mm) DIAMETER HOLES AT THE ENDS OF THE CRACKS.	A NON-REVENUE FLIGHT TO A REPAIR STATION IS PERMITTED IF THE APPLICABLE REGULATORY AUTHORITY GIVES APPROVAL BEFORE THE FLIGHT. IT IS RECOMMENDED THAT THE PROPOSED REPAIR PROCEDURE BE GIVEN TO BOEING.
		THE MAXIMUM CABIN PRESSURE DIFFERENTIAL C IS LIMITED TO ZERO PSIG.
	DO APPLICABLE REPAIR AS GIVEN IN SRM 52-10-01.	REFER TO THE APPLICABLE REPAIR FOR THE LIMITS.
F	CLEAN UP AS SHOWN IN ALLOWABLE DAMAGE 1 TO DAMAGE DEPTH. STOP DRILL 0.25 INCH (6 mm) DIAMETER HOLES AT THE ENDS OF THE CRACKS.	OPERATION IS NOT PERMITTED BEFORE BOEING AND THE APPLICABLE REGULATORY AUTHORITY GIVES APPROVAL.
r	DO APPLICABLE REPAIR AS GIVEN IN SRM 52-10-01.	REFER TO THE APPLICABLE REPAIR FOR THE LIMITS.

LIMITS FOR CORROSION, CRACKS, NICKS, GOUGES, AND HOLE DAMAGE

Operating Limits for Entry Door Skin Figure 101 (Sheet 2 of 2)





#### **REPAIR 1 - SMALL HOLE IN ENTRY DOOR SKIN - FLUSH REPAIR**

#### **REPAIR INSTRUCTIONS**

- Clean out the damaged hole to 1 inch (25 mm) diameter maximum. The center of the hole to an edge or cutout must not be less than 1/2 of dimension A from Table I.
- 2. Fabricate repair parts 1 and 2.
- 3. Break sharp edges of original and repair parts 0.015 to 0.030 inch (0.4 to 0.8 mm).
- Remove all nicks, scratches, burrs, sharp edges and corners from initial and repair parts.
- 5. Alodize all raw surfaces of repair and original parts as given in SRM 51-20-01.
- Apply one coat of BMS 10-11, type 1, primer to all of part 2 and to the raw edges and inner surface of part 1 in accordance with AMM 51-24.
- 7. Install the repair parts, making faying surface seals between all parts in accordance with SRM 51-20-05. A bead of sealant should be apparent all around repair parts after installation. Where there is sufficient sealant squeezed out it may be formed into a fillet, otherwise an additional fillet seal should be applied.
- Apply BMS 5-95 sealant in the gap between the filler, part 1, and the skin.
- 9. Replace inner skin panel.
- Restore surface finish in accordance with AMM 51-21.

#### NOTES

- NOT TO BE USED IN AREAS WITH DOUBLERS
- REFER TO THE FOLLOWING WHEN USING THIS REPAIR:
  - AMM 51-21 FOR INTERIOR AND EXTERIOR FINISHES
  - SRM 51-40 FOR FASTENER CODE, REMOVAL, INSTALLATION, HOLE SIZES AND EDGE MARGINS
  - SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS
  - SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
  - SRM 51-20-01 FOR PROTECTIVE TREATMENT OF METAL
  - SRM 51-20-05 FOR SEALING OF REPAIRS
- WHERE THIS REPAIR IS BEING USED IN A MACHINED OR CHEM-MILLED SKIN, SHIMS MAY BE USED BETWEEN DOUBLER AND SKIN TO MAKE UP VARIATIONS IN THICKNESS

Small Hole in Entry Door Skin - Flush Repair Figure 201 (Sheet 1 of 2)



REPAIR 1 Page 201 Jan 20/2005






757-200 STRUCTURAL REPAIR MANUAL

SKIN GAGE	PART 2 DOUBLER	A INCHES	B INCHES	C INCHES	INNER CIR		OUTER CIR	
GAGE	GAGE	INCHES	INCHES	INCHES	NUMBER	SIZE	NUMBER	SIZE
0.040	0.050	3.80	1.70	3.10	7	5/32	9	5/32
0.045	0.050	3.80	1.70	3.10	7	5/32	9	5/32
0.050	0.063	4.30	1.80	3.50	6	3/16	9	3/16
0.063	0.071	4.30	1.80	3.50	6	3/16	9	3/16

	ТΑ	BL	E	Ι
--	----	----	---	---



PLAN VIEW

SECTION THROUGH REPAIR

REPAIR MATERIAL					
PART QTY MATERIAL					
1	FILLER	1	SAME MATERIAL AND GAGE AS ORIGINAL SKIN		
2	DOUBLER	1	SAME MATERIAL AS ORIGINAL SKIN. FOR GAGE SEE TABLE 1		

#### SYMBOLS

REPAIR FASTENER LOCATION BACR15CE( )KE RIVET SEE TABLE 1 FOR SIZE AND NUMBER REQUIRED

#### Small Hole in Entry Door Skin - Flush Repair Figure 201 (Sheet 2 of 2)



REPAIR 1 Page 202 Jan 20/2005



#### **REPAIR 2 - ENTRY DOOR SKIN - NON-FLUSH REPAIR**

#### REPAIR INSTRUCTIONS

- 1. Remove the inner skin panel for access if required.
- Clean out the damage to the skin in a rectangular shape with a minimum of 0.50 inch (13 mm) radius at the corners. The cutout should be parallel to the centerline of the adjacent beam.
  - <u>NOTE</u>: When cleaning out damaged area take care not to damage the adjacent beam.
- 3. Fabricate repair parts.
- Assemble repair parts in installed positions and drill fastener holes.
- 5. Remove repair parts.
- Break sharp edges of original and repair parts 0.015 to 0.030 inch (0.4 to 0.8 mm).
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- 8. Alodize all raw edges of existing and repair parts as given in SRM 51-20-01.
- Apply one coat of BMS 10-11, type 1 primer in accordance with AMM 51-24 to all surfaces of part 2 and to faying surface of part 1.
- 10. Install countersunk repair washers in existing countersinks as given in SRM 51-40-08.
- 11. Install repair parts. Seal as given in SRM 51-20-05.
- 12. Replace inner skin panel if removed.
- 13. Apply aerodynamic smoother in critical areas as described in SRM 51-10-01.
- 14. Restore surface finish in accordance with AMM 51-21.

#### NOTES

- REFER TO THE FOLLOWING WHEN USING THIS REPAIR:
  - AMM 51-31 FOR SEALS AND SEALING
  - SRM 51-20-01 FOR PROTECTIVE TREATMENT OF METAL
  - SRM 51-20-05 FOR SEALING OF REPAIRS
  - SRM 51-40 FOR FASTENER CODE, REMOVAL, INSTALLATION, HOLE SIZES, AND EDGE MARGINS
  - SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
  - SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS
- A SAME MATERIAL AS ORIGINAL SKIN; ONE GAGE GREATER THAN ORIGINAL SKIN
- B SAME MATERIAL AS ORIGINAL SKIN; SAME GAGE AS ORIGINAL SKIN

#### FASTENER SYMBOLS

- REPAIR FASTENER LOCATIONS BACR15CE6KE (OPTIONAL: BACR15CE6D)
- ORIGINAL FASTENER LOCATIONS REMOVE AND REPLACE WITH BACR15CE()KE OR BACR15CE()D SAME SIZE AS ORIGINAL OR 1/32 OVERSIZE IF REQUIRED

REPAIR MATERIAL					
PA	RT	QTY	MATERIAL		
1 2	DOUBLER FILLER	1 1	A B		

#### Entry Door Skin - Non-Flush Repair Figure 201 (Sheet 1 of 3)




REPAIR 2 Page 201 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL




Entry Door Skin - Non-Flush Repair Figure 201 (Sheet 2 of 3)





REPAIR 2 Page 202 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL







SECTION A-A (TYP ALL EDGES)

SECTION THRU REPAIR

Entry Door Skin - Non-Flush Repair Figure 201 (Sheet 3 of 3)



REPAIR 2 Page 203 Jan 20/2005



#### **REPAIR 3 - SMALL HOLE IN ENTRY DOOR SKIN - EXTERNAL REPAIR**

#### REPAIR INSTRUCTIONS

- Clean out the damaged hole to 1-inch diameter maximum. The center of the hole to an edge or cutout must not be less than 4D.
- 2. Fabricate repair parts.
- 3. Break sharp edges of original and repair parts 0.015 to 0.030.
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- 5. Alodize all raw surfaces of repair and original parts per 51-20-01.
- Apply one coat of BMS 10-11, type I primer in accordance with 51-21-00 of the 757 Maintenance Manual to all surfaces of parts 2 and 3 and to faying surface of part 1.
- 7. Install repair parts. Seal per 51-20-05.
- Restore surface finish in accordance with 51-21-00 of the 757 Maintenance Manual.

#### NOTES

- THIS REPAIR IS NOT APPLICABLE TO PASSENGER/ CREW ENTRY DOORS IN SECTION 41
- REFER TO THE FOLLOWING WHEN USING THIS REPAIR:


51-40 FOR FASTENER CODE, REMOVAL, INSTAL-LATION, HOLE SIZES AND EDGE MARGINS


51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS

51-31 OF THE 757 MAINTENANCE MANUAL FOR SEALS AND SEALING

• THIS REPAIR IS NOT TO BE USED IN AREAS WITH DOUBLERS. THE AREA UNDER REPAIR PART 1 MUST NOT HAVE ANY FASTENERS, AND THE SKIN GAGE MUST BE CONSTANT.

REPAIR MATERIAL					
PA	RT	QTY	MATERIAL		
1	DOUBLER	1	2024-T3 TWICE SKIN GAGE		
2	FILLER	1	2024-T3 SAME GAGE AS SKIN		
3	DOUBLER	1	2024-T3 TWICE SKIN GAGE		





OPTIONAL METHOD

Small Hole in Entry Door Skin - External Repair Figure 201



REPAIR 3 Page 201 Jan 20/2005



#### **REPAIR 4 - ENTRY DOOR SKIN - TYPICAL FLUSH REPAIR AT BEAM**

#### REPAIR INSTRUCTIONS

- 1. Remove inner skin panel for access to the damaged area.
- Clean out damage to skin to a rectangular shape parallel to the beam, with a minimum corner radius of 0.50 inch (13 mm).
- Cut out beam flanges to width of repair plate to permit its insertion against the skin.
- 4. Make repair parts.
- Assemble repair parts and drill the fastener holes in original and new locations.
- 6. Remove repair parts.
- 7. Break sharp edges of original and repair parts 0.015 to 0.030 inch (0.4 to 0.8 mm).
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- Alodize raw edges of original parts and all surfaces of repair parts as given in SRM 51-20-01.
- 10. Apply one coat of BMS 10-11, type 1, primer to all of parts 1, 3 and to the raw edges and inner surfaces of part 2 in accordance with AMM 51-21-00.
- 11. Install the repair parts with the fasteners wet with BMS 5-95 sealant and making faying surface seals between all parts in accordance with SRM 51-20-05. A bead of sealant should be apparent all around repair parts after installation. Where there is sufficient sealant squeezed out it may be formed into a fillet, otherwise an additional fillet seal should be applied.
- 12. Apply BMS 5-95 sealant in the gap between the filler, part 2, and the skin.
- 13. Replace inner skin panel.
- 14. Restore surface finish in accordance with AMM 51-20-00.

#### NOTES

- REFER TO THE FOLLOWING WHEN USING THIS REPAIR:
  - AMM 51-21 FOR INTERIOR AND EXTERIOR FINISHES
  - AMM 51-31 FOR SEALS AND SEALING
  - SRM 51-20-01 FOR PROTECTIVE TREATMENT OF METAL
  - SRM 51-20-05 FOR REPAIR SEALING
  - SRM 51-40 FOR FASTENER CODE, REMOVAL, INSTALLATION, HOLE SIZES, AND EDGE MARGINS
  - SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS
  - SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- WHERE THIS REPAIR IS BEING USED IN A MACHINED OR CHEM-MILLED SKIN. SHIMS MAY BE USED BETWEEN REPAIR PLATE AND SKIN TO MAKE UP FOR VARIATIONS IN THICKNESS
- A MINIMUM OF FOUR FASTENERS IN EACH ROW JOINING REPAIR ANGLES TO ORIGINAL SECTION
- B SHIM AS REQUIRED BETWEEN ORIGINAL TEE, NEW ANGLES AND PLATE
- C THE COUNTERSINK DEPTH FOR ORIGINAL BACR15CE RIVETS MUST BE MAINTAINED AND THE EXCESS PORTION OF OVERSIZE RIVET HEAD SHAVED OFF AFTER INSTALLATION AS GIVEN IN SRM 51-10-01

	REPAIR MATERIAL				
	PART	QTY	MATERIAL		
1	PLATE	1	SAME MATERIAL AND GAGE AS ORIGINAL SKIN		
2	FILLER	1	SAME MATERIAL AND GAGE AS ORIGINAL SKIN		
3	ANGLE	2	SAME MATERIAL AND ONE GAGE HEAVIER THAN SKIN SIDE LEG OF ORIGINAL SECTION		

Passenger Entry Door Skin - Typical Flush Repair at Beam Figure 201 (Sheet 1 of 2)





REPAIR 4 Page 201 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL







REPAIR 4 Page 202 Jan 20/2005



#### **REPAIR 5 - ENTRY DOOR SKIN - FLUSH REPAIR BETWEEN BEAMS (0.040 CHEM-MILL POCKET ONLY)**

#### REPAIR INSTRUCTIONS

- 1. Remove the inner skin panel for access if required.
- Clean out the damage to skin to a rectangular shape with a minimum of 0.50 inch (13 mm) radius at the corners. The cutout should be parallel to the centerline of the adjacent beam.
- 3. Make repair parts 1 and 2.
- Assemble repair parts in installed positions and drill fastener holes.
- 5. Remove repair parts.
- Break sharp edges of original and repair parts 0.015 to 0.030 inch (0.4 to 0.8 mm).
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- Alodize raw edges of original parts and all surfaces of repair parts per SRM 51-20-01.
- Apply one coat of BMS 10–11, type 1, primer to all of part 1 and to the raw edges and inner surface of part 2 in accordance with AMM 51–21–00.
- 10. Install the repair parts with the fasteners wet with BMS 5-95 sealant and making faying surface seals between all parts in accordance with SRM 51-20-05. A bead of sealant should be apparent all around repair parts after installation. Where there is sufficient sealant squeezed out it may be formed into a fillet, otherwise an additional fillet seal should be applied.
- 11. Apply BMS 5-95 sealant in the gap between the filler, part 2, and the skin.
- 12. Refinish according to AMM 51-21-00.

#### NOTES

- REFER TO THE FOLLOWING WHEN USING THIS REPAIR:
  - AMM 51-21 FOR INTERIOR AND EXTERIOR FINISHES
  - AMM 51-31 FOR SEALS AND SEALING
  - SRM 51-20-01 FOR PROTECTIVE TREATMENT OF METAL
  - SRM 51-20-05 FOR SEALING OF REPAIRS
  - SRM 51-40 FOR FASTENER CODE, REMOVAL, INSTALLATION, HOLE SIZES AND EDGE MARGINS
  - SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS
  - SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- A THE ORIGINAL COUNTERSINK DEPTH FOR BACR15CE RIVETS MUST BE MAINTAINED. WHERE OVERSIZE RIVETS ARE INSTALLED THE PROTRUDING PORTION OF THE RIVET HEADS MUST BE SHAVED OFF PER SRM 51-10-01

#### FASTENER SYMBOLS



REPAIR FASTENER LOCATIONS


Crew Entry Door Skin - Flush Repair Between Beam (0.040 Chem-Mill Pocket 0nly) Figure 201 (Sheet 1 of 2)



REPAIR 5 Page 201 Jan 20/2005







SECTION THROUGH REPAIR

Crew Entry Door Skin - Flush Repair Between Beam (0.040 Chem-Mill Pocket 0nly) Figure 201 (Sheet 2 of 2)



REPAIR 5 Page 202 Jan 20/2005



### REPAIR 6 - PASSENGER / SERVICE DOOR SKIN - INNER DOUBLER REPAIR OF THE OUTER SKIN ASSEMBLY AT THE DOOR HINGE CUTOUT

### 1. Applicability

A. This Repair is applicable to gouge damage to the inner doubler of the outer skin of the No. 1 Passenger and Service Doors.

### 2. General

- A. This is a Category B Repair and LFEC Inspections are necessary. Refer to Figure 201/REPAIR 6, TABLE II for the inspection threshold and interval.
- B. D = Fastener Diameter.

### 3. References

Reference	Title
51-10-02, GENERAL	Inspection and Removal of Damage
51-20-01, GENERAL	Protective Treatment of Metallic and Nonmetallic Materials
51-20-05, GENERAL	Repair Sealing
51-40-01, GENERAL	Fasteners
51-40-02, GENERAL	Fastener Installation and Removal
51-40-05, GENERAL	Fastener Hole Sizes
51-40-06, GENERAL	Fastener Edge Margins
AMM 51-21-00/701	Interior and Exterior Finishes - Cleaning/Painting
NDT Part 6, 51-00-01	Aluminum Part Surface Inspection (Meter Display)
NDT Part 6, 51-00-06	Tapered Part Fastener Hole Inspection (Meter Display)
SOPM 20-41-02	Application of Chemical and Solvent Resistant Finishes

#### 4. Repair Instructions

A. Get Access to the repair area.

- **CAUTION:** DO NOT CAUSE GOUGES, SCRATCHES, OR BUCKLES IN THE STRUCTURE ADJACENT TO THE REPAIR AREA. USE A STAINLESS STEEL GUARD BETWEEN THE INNER DOUBLER AND THE OUTER SKIN TO PREVENT DAMAGE. THE RESULT CAN BE FURTHER DAMAGE AND MORE REPAIR MAY BE NECESSARY.
- B. Cut and remove the damaged part of the inner doubler on the outer skin assembly. Refer to Figure 201/REPAIR 6, Detail I.
  - (1) Use a sheet metal guard between the outer inner doubler and the outer skin when you remove the the damage to prevent damage to the outer skin.
  - (2) Keep a 0.50 in. (1.27 cm) minimum radius on the cutout.
  - (3) Make the edges of the cutout smooth with a surface finish of 125 microinches Ra or better.
  - (4) Keep a minimum edge margin of 2D (D = Fastener Diameter) from other fasteners when you make the cutout.
- C. Do a High Frequency Eddy Current (HFEC) inspection of the repair area to make sure that all the damage has been removed. Refer to NDT Part 6, 51-00-01. If you find more damage do Paragraph 4.B./REPAIR 6 and Paragraph 4.C./REPAIR 6 again.
- D. Make the repair parts. Refer to Table 201/REPAIR 6.



REPAIR 6 Page 201 Feb 20/2005



#### Table 201: Repair Material

PART		QUANTITY	MATERIAL
1	Doubler *[1]	1	0.071 2024-T3 Sheet

- \*[1] Make the repair doubler edges tapered as shown in Figure 201/REPAIR 6, Section A-A on all the edges, except for the edges which are common to the door hinge cutout.
  - **CAUTION:** MAKE SURE THERE IS SUFFICIENT CLEARANCE BETWEEN THE REPAIR FASTENER HOLES AND THE EDGE OF THE STRUCTURE BELOW. IF YOU DO NOT, DAMAGE TO THE SKIN DOUBLER, BEAMS AND FRAMES WILL RESULT WHEN YOU DRILL THE FASTENER HOLES.
  - E. Assemble the repair parts and drill the fastener holes.
  - F. Disassemble the repair parts.
  - G. Remove the nicks, scratches, gouges, burrs, and sharp edges from the repair parts and the door skin.
  - H. Apply a chemical conversion coating to the repair parts and the bare surfaces of the inner doubler. Refer to 51-20-01, GENERAL.
  - I. Apply two layers of BMS 10-11, Type I primer to the repair parts and to the bare surfaces of the inner doubler. Refer to SOPM 20-41-02.
  - J. Install the repair parts wet with BMS 5-95 sealant between the mating surfaces.
  - K. Install the fasteners. Fasteners that are not made of aluminum must be installed wet with BMS 5-95 sealant.
  - L. Apply a fillet seal of BMS 5-95 sealant to the external edges of the doubler. Refer to 51-20-05, GENERAL.
  - M. Apply the external decorative finish to the repair area. Refer to AMM 51-21-00/701.



REPAIR 6 Page 202 Feb 20/2005



NOTES (CONT)

- A MAKE THE REPAIR DOUBLER EDGES TAPERED AS GIVEN IN SECTION A-A ON ALL EDGES EXCEPT THE EDGES WHICH ARE COMMON TO THE DOOR HINGE CUTOUT.
- B MAKE SURE THE MINIMUM EDGE MARGIN FOR THE REPAIR DOUBLER IS 2D ON INITIAL AND REPAIR FASTENERS.
- C DO NOT END THE REPAIR DOUBLER AT AN EDGE OR FRAME LOCATION EXCEPT AT THE DOOR CUTOUT EDGE. EXTEND DOUBLER BY A MINIMUM OF ONE FASTENER ROW BEYOND A FRAME LOCATION.
- D THERE MUST BE A MINIMUM OF 3 ROWS OF FASTENERS FORWARD, AFT AND BELOW THE DAMAGE LOCATION.

### FASTENER SYMBOLS

- -1- REFERENCE FASTENER LOCATION.
- + INITIAL FASTENER LOCATION. INSTALL A BACR15CE6D() RIVET. (UP TO 1/32 INCH DIAMETER OVERSIZE).
- REPAIR FASTENER LOCATION. INSTALL A BACR15CE6D() RIVET.

Passenger / Service Door Skin - Inner Doubler Repair of the Outer Skin Figure 201 (Sheet 1 of 4)



REPAIR 6 Page 203 Feb 20/2005



757-200 STRUCTURAL REPAIR MANUAL

300 SEE DETAIL I FOR INNER DOUBLER GOUGE DAMAGE REPAIR OF THE OUTER SKIN ASSEMBLY AT THE DOOR HINGE CUTOUT SEE DETAIL II AND III INNER DOUBLER INNER SKIN ASSEMBLY OUTER SKIN-FWD INBD

DETAIL I


Passenger / Service Door Skin - Inner Doubler Repair of the Outer Skin Figure 201 (Sheet 2 of 4)




REPAIR 6 Page 204 Feb 20/2005

**BOEING**®

757-200 STRUCTURAL REPAIR MANUAL





REPAIR 6 Page 205 Feb 20/2005



CATEGORY B REPAIR INSPECTION REQUIREMENTS										
INSPECTION METHOD INTERVAL REFERENCE										
12,000 CYCLES AFTER REPAIR IS DONE. (ALSO SEE NOTE BELOW)	LOW FREQUENCY EDDY CURRENT (LFEC)	12,000 CYCLES	NDT PART 6 53-00-06							
DETAIL III. IF THE DO 37,500 AIRPLANE FLIGHT WERE RECORDED, START T										

CORRECT INTERVALS.

 $\mathbb{Z}$ 

THROUGH THE DOUBLER.

TABLE II BEAM NO.3 0.38 INCH (9.65mm) MINIMUM CORNER RADIUS (TYPICAL) 4 -1 (DOUBLER) - BEAM NO.4 STA INNER 336.32 DOUBLER (REF) DETAIL III INSPECTION AREA. DO THE INSPECTION OF THE SKIN EXTERNALLY


> Passenger / Service Door Skin - Inner Doubler Repair of the Outer Skin Figure 201 (Sheet 4 of 4)



REPAIR 6 Page 206 Feb 20/2005



757-200 STRUCTURAL REPAIR MANUAL



DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	WEB	0.080	7075–T6	
2	BEAM OUTER CHORD WEB	0.063	BAC1505-100543 2024-T42 CLAD 2024-T42	
3	BEAM OUTER CHORD WEB	0.063	BAC1506-3161 2024-T42 CLAD 2024-T42	
4	OUTER CHORD ANGLE	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
5	LOWER BEAM		7075-T73 FORGING	

LIST OF MATERIALS FOR DETAIL I

No. 1 Left Side Passenger Door Structure Identification Figure 1 (Sheet 1 of 2)



1DENTIFICATION 1 Page 1 Jan 20/2005






ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
6	ANGLE INTERCOSTAL	0.071 0.063	CLAD 2024-T42 7075-T6	
7	OUTER CHORD INTERCOSTAL	0.063	BAC1505-100543 2024-T42 CLAD 7075-T6	
8	INTERCOSTAL INTERCOSTAL	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
9	ANGLE INTERCOSTAL	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
10	OUTER TEE INTERCOSTAL	0.063	BAC1505-100543 2024-T42 CLAD 7075-T6	
11	OUTER TEE INTERCOSTAL	0.063	BAC1505-100962 2024-T42 CLAD 7075-T6	
12	WEB ANGLE	0.063 0.063	CLAD 7075-T6 CLAD 7075-T6	
13	OUTER CHORD INTERCOSTAL	0.063	BAC1505-100544 2024-T42 CLAD 7075-T6	
14	OUTER CHORD INTERCOSTAL	0.063	BAC1505-100650 2024-T42 CLAD 7075-T6	
15	INTERCOSTAL ANGLE	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
16	INTERCOSTAL ANGLE	0.071 0.063	CLAD 2024-T42 CLAD 7075-T6	
17	INNER ANGLE	0.063	CLAD 7075-T6	
18	INTERCOSTAL INTERCOSTAL	0.063	AISI631 CRES, HT TR 180-200 KSI CLAD 7075-T6	
19	INTERCOSTAL	0.063	7075-16	
20	STIFFENER STIFFENER	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
21	INTERCOSTAL INTERCOSTAL	0.050 0.063	CLAD 2024-T42 CLAD 7075-T6	
22	STIFFENER	0.063	CLAD 2024-T42	
23	SPLICE TEE		BAC1505-100052 2024-T42	
24	SPLICE TEE		BAC1505-100261 2024-T42	
25	GATE		A356-T61 OR A357-T61 ALUMINUM CASTING AZ91C-T6 MAGNESIUM CASTING	A B
26	HINGE ASSY		2024-T4	
27	HINGE FITTING		7075-T7351 PLATE	
28	HINGE FITTING		7075-T73 FORGING	
29	STOP FITTING		7075-T73 FORGING	
30	STOP FITTING		17-4PH CRES CASTING OR 15-5PH CRES PLATE HT TR 180-200 KSI	
31	FWD FRAME ANGLE FRAME	0.050 0.080	CLAD 7075-T6 2024-T42	
32	AFT FRAME	0.080	2024-T42	

LIST OF MATERIALS FOR DETAIL I


No. 1 Left Side Passenger Door Structure Identification Figure 1 (Sheet 2 of 2)



1DENTIFICATION 1 Page 2 Jan 20/2005



**IDENTIFICATION 2 - NO. 2 LEFT SIDE PASSENGER DOOR STRUCTURE** 



### NOTES

- A FOR CUM LINE NUMBERS: 1 THRU 8,12,17,20,21,22,27,28,31,35,36,38, 40,42,51 (BOEING REF: NA022 THRU NA028, NA193 THRU NA199)
- B FOR CUM LINE NUMBERS NOT LISTED IN A


No. 2 Passenger and Service Door Structure Identification Figure 1 (Sheet 1 of 3)



Page 1



757-200 STRUCTURAL REPAIR MANUAL



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	BEAM WEB OUTER CHORD	0.063	CLAD 7075-T6 BAC1505-100350 2024-T42	
2	BEAM WEB OUTER CHORD	0.063 2.5	CLAD 7075-T6 7075-T73 PLATE	
3	BEAM WEB OUTER CHORD	0.063 2.5	CLAD 7075-T6 7075-T6 PLATE	
4	WEB	0.080	7075-T6	
5	STOP BEAM		7075-T73 FORGING	
6	OUTER CHORD INNER CHORD		BAC1503-100142 2024-T42 BAC1503-2811 7075-T6	
7	INTERCOSTAL OUTER CHORD	0.056	CLAD 7075-T6 BAC1505-100052 2024-T42	
8	INTERCOSTAL OUTER CHORD	0.063	CLAD 7075-T6 BAC1505-100052 2024-T42	
9	INTERCOSTAL	0.056	CLAD 7075-T6	
10	INNER CHORD OUTER CHORD		BAC1503-2811 7075-T6 BAC1505-100350 2024-T42	
11	WEB INNER CHORD OUTER CHORD	0.063 0.063	CLAD 7075-T6 CLAD 7075-T6 BAC1505-100270 2024-T42	
12	INTERCOSTAL OUTER CHORD	0.056 0.063	CLAD 7075-T6 CLAD 2024-T42	

No. 2 Passenger and Service Door Structure Identification Figure 1 (Sheet 2 of 3)





ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
13	INTERCOSTAL OUTER CHORD	0.063	CLAD 7075-T6 BAC1505-100350 2024-T42	
14	INTERCOSTAL OUTER CHORD	0.056	CLAD 2024-T42 BAC1505-100350 2024-T42	
15	INTERCOSTAL OUTER CHORD	0.056	CLAD 7075-T6 BAC1505-100350 2024-T42	
16	OUTER CHORD		BAC1505-100350 2024-T42	
17	FITTING INNER CHORD		7075-T73 FORGING BAC1489-258 7075-T6	
18	INTERCOSTAL CHORD	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
19	INTERCOSTAL OUTER CHORD	0.056	CLAD 7075-T6 BAC1503-2731 2024-T42	
20	OUTER CHORD		BAC1505-100052 2024-T42	
21	INTERCOSTAL OUTER CHORD	0.056	CLAD 7075-T6 BAC1505-100270 2024-T42	
22	OUTER CHORD		BAC1505-100270 2024-T42	
23	STIFFENER	0.063	7075-T6	
24	INTERCOSTAL OUTER CHORD	0.056	CLAD 7075-T6 BAC1503-2771 2024-T42	
25	DOOR GATE		A356-T61 ALUMINUM CASTING AZ91C-T6 MAGNISIUM CASTING	AB
26	OUTER CHORD INTERCOSTAL INNER CHORD	0.063	BAC1503–2731 2024–T42 CLAD 7075–T6 BAC1505–100052 7075–T6	
27	INTERCOSTAL INTERCOSTAL	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
28	INTERCOSTAL	0.063	CLAD 2024-T42	
29	END FITTING OUTER CHORD		7075-T73 FORGING OR 7075-T7351 PLATE BAC1505-100052 2024-T42	
30	END FITTING		7075-T73 FORGING OR 7075-T7351 PLATE	
31	OUTER ANGLE INNER ANGLE	0.071 0.063	7075–т6 7075–т6	
32	FRAME	0.080	7075-т6	
33	STOP FITTING		7075-T73 FORGING	
34	STOP FITTING		15-5PH CRES FORGING OR BAR	

LIST OF MATERIALS FOR DETAIL I

No. 2 Passenger and Service Door Structure Identification Figure 1 (Sheet 3 of 3)




1DENTIFICATION 2 Page 3 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL

#### **IDENTIFICATION 3 - NO. 1 RIGHT SIDE SERVICE DOOR STRUCTURE**



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	BEAM SUPPORT ANGLE	0.080	7075-T6 BAC1503-521 7075-T6	
2	BEAM OUTER CHORD WEB	0.063	BAC1505-100543 2024-T42 CLAD 7075-T6	
3	BEAM OUTER CHORD WEB SPLICE CHORD	0.063	BAC1505–100543 2024–T42 CLAD 2024–T42 BAC1505–100696 2024–T3511	
4	BEAM OUTER CHORD WEB SPLICE CHORD	0.063	BAC1505–100544 2024–T42 CLAD 2024–T42 BAC1505–100696 2024–T3511	
5	BEAM OUTER CHORD WEB	0.063	BAC1505-100543 2024-T42 CLAD 2024-T42	
6	LOWER BEAM		7075-T73 FORGING	

LIST OF MATERIALS FOR DETAIL I

No. 1 Right Side Service Door Structure Identification Figure 1 (Sheet 1 of 2)





ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
7	INTERCOSTAL ANGLE	0.063 0.063	CLAD 7075-T6 CLAD 7075-T6	
8	ANGLE INTERCOSTAL	0.063 0.056	CLAD 2024-T42 CLAD 7075-T6	
9	OUTER CHORD INTERCOSTAL	0.056	BAC1505-100543 2024-T42 CLAD 7075-T6	
10	OUTER ANGLE INNER ANGLE	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
11	INTERCOSTAL INNER CHORD	0.063 0.056	CLAD 7075-T6 CLAD 7075-T6	
12	STOP FITTING		17-4 PH CRES INVESTMENT CASTING OR 15-5PH CRES PLATE	
13	OUTER CHORD INTERCOSTAL	0.056	BAC1505-100962 2024-T42 CLAD 7075-T6	
14	ANGLE INTERCOSTAL	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
15	OUTER CHORD ANGLE	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
16	WEB ANGLE	0.063 0.063	CLAD 7075-T6 CLAD 7075-T6	
17	OUTER ANGLE INNER ANGLE		BAC1514–1617 2024–T42 OR 7075–T6511 BAC1514–1617 2024–T42	
18	OUTER CHANNEL INNER ANGLE	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
19	OUTER WEB INNER WEB	0.063 0.063	AISI631 CRES 180-200 KSI CLAD 7075-T6	
20	OUTER WEB INNER WEB	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
21	OUTER CHORD INTERCOSTAL	0.056	BAC1505-100544 2024-T42 CLAD 7075-T6	
22	OUTER CHORD INTERCOSTAL	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
23	CLIP	0.063	CLAD 2024-T42	
24	STIFFENER	0.063	CLAD 7075-T6	
25	OUTER CHORD		BAC1505-35000 2024-T42	
26	OUTER CHORD		BAC1505-100543 2024-T42	
27	GATE		A356-T61 ALUMINUM CASTING AZ91C-T6 MAGNESIUM CASTING	A B
28	HINGE ASSY	0.056	2024-T42	
29	UPPER FRAME LOWER FRAME ANGLE	0.080 0.080 0.050	2024-T42 2024-T42 CLAD 7075-T6	
30	AFT FRAME	0.080	2024- <b>T</b> 42	
31	UPPER HINGE		7075-T7351 PLATE	
32	LWR HINGE		7075-T73 FORGING	
33	STOP FITTING		7075-T73 FORGING	

LIST OF MATERIALS FOR DETAIL I (CONTINUED)


No. 1 Right Side Service Door Structure Identification Figure 1 (Sheet 2 of 2)



1DENTIFICATION 3 Page 2 Jan 20/2005



### **IDENTIFICATION 4 - NO. 4 PASSENGER AND SERVICE DOOR STRUCTURE**



LEFT SIDE DOOR SHOWN RIGHT SIDE DOOR OPPOSITE

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	BEAM OUTER CHORD WEB INNER CHORD	0.080	BAC1505–100624 2024–T42 7075–T6 BAC1505–100624 7075–T6	
2	BEAM OUTER CHORD WEB INNER CHORD	0.063	BAC1505-100624 2024-T42 CLAD 2024-T3 BAC1505-100168 7075-T6	

LIST OF MATERIALS

No. 4 Passenger and Service Door Structure Identification Figure 1 (Sheet 1 of 2)



1DENTIFICATION 4 Page 1 Jan 20/2005





ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
3	BEAM OUTER CHORD WEB INNER CHORD	0.063	BAC1505–100624 2024–T42 CLAD 7075–T6 BAC1505–100624 7075–T6	
4	WEB	0.090	7075-T6	
5	STOP BEAM		7075-T73 FORGING	
6	OUTER CHORD PAN CHORD WEB INNER CHORD	0.090 0.063	BAC1505-100543 2024-T42 2024-T42 CLAD 7075-T6 BAC1505-100650 7075-T6	
7	OUTER CHORD WEB TEE	0.063	BAC1505–100543 2024–T42 CLAD 7075–T6 BAC1505–100543 2024–T42	
8	HINGE SUPPORT		7075-T73 PLATE	
9	OUTER CHORD INTERCOSTAL	0.063	BAC1505-100543 2024-T42 7075-T6	
10	HINGE SUPPORT		7075-T73 FORGING	
11	OUTER CHORD WEB	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
12	OUTER CHORD WEB	0.063	BAC1505-100543 2024-T42 CLAD 7075-T6	
13	OUTER TEE INTERCOSTAL	0.063	BAC1505-100543 7075-T6 CLAD 7075-T6	
14	OUTER CHORD INTERCOSTAL	0.063 0.063	CLAD 2024-T42 CLAD 7075-T6	
15	OUTER CHORD INTERCOSTAL	0.063	BAC1489-306 CLAD 2024-T42 CLAD 7075-T6	
16	WEB INNER CHORD	0.063 0.063	CLAD 7075-T6 CLAD 7075-T6	
17	OUTER CHORD INTERCOSTAL	0.063	BAC1489-235 CLAD 2024-T42 CLAD 7075-T6	
18	WEB	0.063	CLAD 7075-T6	
19	OUTER CHORD INNER CHORD		BAC1505-100543 CLAD 7075-T6	
20	OUTER CHORD INNER CHORD	0.090	2024-T42 BAC1490-2734 7075-T6	
21	OUTER TEE INTERCOSTAL	0.063	BAC1505-100261 2024-T42 CLAD 7075-T6	
22	GATE		A356-T61 ALUMINUM CASTING AZ1C-T6 MAGNESIUM CASTING	A B
23	TEE		BAC1505-100543 2024-T42	
24	AFT FRAME	0.080	2024-T42	
25	FWD FRAME SUPPORT ANGLE	0.080 0.050	2024-T42 CLAD 7075-T6	
26	STOP FITTING		7075-T73 FORGING	
27	STOP FITTING		15-5PH CRES BAR OR 17-4PH CRES CASTING	

LIST OF MATERIALS (CONTINUED)


No. 4 Passenger and Service Door Structure Identification Figure 1 (Sheet 2 of 2)




1DENTIFICATION 4 Page 2 Jan 20/2005



### ALLOWABLE DAMAGE 1 - ENTRY DOOR STRUCTURE







757-200 STRUCTURAL REPAIR MANUAL

DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES
CHORD				
EXTRUDED	A	D	NOT PERMITTED	NOT PERMITTED
MACHINED	A	D	NOT PERMITTED	Н
FORMED	В	E	SEE DETAIL VI	Н
FRAME	В	E	SEE DETAIL VI	H
STIFFENER	В	E	SEE DETAIL VI	H
ANGLE	В	E	SEE DETAIL VI	H
INTERCOSTAL	C	F	SEE DETAIL VI	Ħ
WEB	C	F	SEE DETAIL VI	Ξ
LOWER BEAM I	A	D	NOT PERMITTED	NOT PERMITTED
DOOR GATE	A	LM	NOT PERMITTED	NOT PERMITTED
STOP FITTING I	A	G	NOT PERMITTED	NOT PERMITTED
MACHINED FITTING I	А	D	NOT PERMITTED	NOT PERMITTED

ALLOWABLE DAMAGE FOR DETAILS I, II AND III

#### NOTES

- REFINISH REWORKED AREAS AS SHOWN IN AMM 51-20.
- A CRACKS ARE NOT PERMITTED EXCEPT FOR EDGE CRACKS, WHICH MUST BE REMOVED AS SHOWN IN DETAILS IV AND X.
- B CRACKS ARE NOT PERMITTED EXCEPT FOR EDGE CRACKS, WHICH MUST BE REMOVED AS SHOWN IN DETAILS IV AND IX.
- C CRACKS ARE NOT PERMITTED EXCEPT FOR EDGE CRACKS, WHICH MUST BE REMOVED AS SHOWN IN DETAILS IV AND VIII.
- D REMOVE DAMAGE AS SHOWN IN DETAILS IV, V, VII AND X.
- E REMOVE DAMAGE AS SHOWN IN DETAILS IV, V, VII AND IX.
- F REMOVE DAMAGE AS SHOWN IN DETAILS IV, V, VII AND VIII.
- G FOR EDGE DAMAGE SEE DETAILS IV AND X. FOR LUG DAMAGE, SEE DETAIL XI. FOR OTHER DAMAGE, SEE DETAIL V. DAMAGE IS NOT PERMITTED IN VICINITY OF BUSHINGS.


- H CLEAN OUT DAMAGE UP TO 0.25 INCH (6.35 mm) MAXIMUM DIAMETER AND NOT CLOSER THAN 1.0 INCH (25.4 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OR T4 ALUMINUM RIVET INSTALLED WET WITH BMS 5-95 SEALANT. ALL OTHER HOLES TO BE REPAIRED.
- I SHOT PEEN REWORKED AREAS AS SHOWN IN SRM 51-20-06.
- J FOR CUM LINE NUMBERS: 1 THRU 8, 12, 17, 24, 26, 27, 29, 32, 39, 41, 42, 43, 50, 51, 53, 54, 55, 59, 61, 62, 66 (BOEING REF: NA029-NA199)
- K FOR ALL AIRPLANES NOT IN J
- L FOR EDGE DAMAGE, SEE DETAILS IV AND XII. FOR LUG DAMAGE, SEE DETAIL XI. FOR OTHER DAMAGE, SEE DETAIL V. NO DAMAGE IS PERMITTED NEAR THE BUSHINGS.
- M FOR THE UPPER GATE LUG DAMAGE SEE DETAILS XIII AND XIV. DAMAGE REMOVAL IS PERMITTED NEAR THE UPPER GATE LUG BUSHINGS. REFER TO SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE.

**Entry Door Structure Allowable Damage** Figure 101 (Sheet 3 of 8)




Page 103 Feb 20/2005






BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details









BOEING PROPRIETARY - Copyright C Unpublished Work - See title page for details



757-200 STRUCTURAL REPAIR MANUAL



CROSS SECTION OF LOWER DOOR GATE DETAIL XII




SECTION C-C

Entry Door Structure Allowable Damage Figure 101 (Sheet 7 of 8)




D634N201 D634N201 BOEING PROPRIETARY - Copyright © Unpublished Work - See title page for details



BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details




**REPAIR GENERAL - ENTRY DOOR STRUCTURE** 



NOTES

• DAMAGED COMPONENTS IN THE DOOR STRUCTURE MAY BE REPLACED OR REPAIRED. IF REPAIRS ARE TO BE MADE, REFER TO SRM 51-70 FOR TYPICAL WEB, FORMED SECTION, OR EXTRUDED SECTION REPAIRS


> Passenger and Service Door Structure Repairs Figure 201



2 Page 201 May 20/2005



### **IDENTIFICATION 1 - OVERWING EMERGENCY EXIT SKIN**



DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	OUTER SKIN	0.063	CLAD 2024-T3 (CHEM-MILLED TO 0.040 MIN)	

### LIST OF MATERIALS


Overwing Emergency Exit Skin Identification Figure 1



IDENTIFICATION 1 Page 1 Jan 20/2005



### **IDENTIFICATION 2 - NO. 3 EMERGENCY EXIT DOOR SKIN**



### DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	OUTER SKIN	0.063	CLAD 2024-T3 (CHEM-MILLED TO 0.040 MIN)	

### LIST OF MATERIALS FOR DETAIL I


No. 3 Emergency Exit Door Skin Identification Figure 1



IDENTIFICATION 2 Page 1 Jan 20/2005



### ALLOWABLE DAMAGE 1 - EMERGENCY EXIT DOOR SKIN



DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES
OUTER SKIN	A D	BD	SEE DETAIL IV	93

Emergency Exit Door Skin Allowable Damage Figure 101 (Sheet 1 of 3)









NOTES

- REFINISH THE REWORKED AREAS AS SHOWN IN AMM 51-20
- REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE IS MORE THAN THE LIMITS AS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- A CRACKS ARE NOT PERMITTED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED AS SHOWN IN DETAILS II AND VI.
- B REMOVE DAMAGE AS SHOWN IN DETAILS II, III, V AND VI.


- C CLEAN OUT DAMAGE UP TO 0.25 INCH (6 mm) MAXIMUM DIAMETER AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OR T4 ALUMINUM RIVET INSTALLED WET WITH BMS 5-95 SEALANT. ALL OTHER HOLES TO BE REPAIRED.
- D REFER TO ALLOWABLE DAMAGE 2 FOR THE EMERGENCY EXIT DOOR SKIN OPERATING LIMITS AFTER DAMAGE HAS BEEN REMOVED.



DETAIL II




ALLOWABLE DAMAGE 1 **52-20-01** Page 102 Sep 20/2005





757-200 STRUCTURAL REPAIR MANUAL



NOTES

- A SKIN THICKNESS DOES NOT INCLUDE THE THICKNESS OF THE DOUBLERS, TRIPLERS, OR STRAPS.
- B DAMAGE INCLUDES HOLES, PUNCTURES, NICKS, GOUGES, SCRATCHES, CORROSION AND CRACKS. DAMAGE DOES NOT INCLUDE DENTS.
- C CABIN PRESSURE LIMITS ARE FOR SKIN DAMAGE TO THE PRESSURIZED FUSELAGE SKIN ONLY.

**Operating Limits for Emergency Exit Door Skin** Figure 101 (Sheet 1 of 2)



Page 101 Jan 20/2005



CHART AREA	DAMAGE TREATMENT	ALLOWABLE AIRPLANE OPERATIONS
A	CLEAN UP AS SHOWN IN ALLOWABLE DAMAGE 1.	NO FLIGHT RESTRICTIONS.
В	CLEAN UP AS SHOWN IN ALLOWABLE DAMAGE 1 TO DEMANSE DEPTH.	LIMITED TO 50 HOURS OF FLIGHT OR 25 FLIGHTS, WHICHEVER COMES FIRST (INCLUDING REVENUE FLIGHTS).
	DO AN APPLICABLE REPAIR AS GIVEN IN SRM 52-20-01.	REFER TO THE APPLICABLE REPAIR FOR THE LIMITS.
С	CLEAN UP AS SHOWN IN ALLOWABLE DAMAGE 1 TO DAMAGE DEPTH. STOP DRILL 0.25 INCH (6 mm) DIAMETER HOLES AT THE ENDS OF THE CRACKS.	A NON-REVENUE FLIGHT TO A REPAIR STATION IS PERMITTED IF THE APPLICABLE REGULATORY AUTHORITY GIVES APPROVAL BEFORE THE FLIGHT. IT IS RECOMMENDED THAT THE PROPOSED REPAIR PROCEDURE BE GIVEN TO BOEING.
		THE MAXIMUM CABIN PRESSURE DIFFERENTIAL C IS LIMITED TO 6.0 PSIG UNLESS THE SKIN IS REPAIRED.
	DO AN APPLICABLE REPAIR AS GIVEN IN SRM 52-20-01.	REFER TO THE APPLICABLE REPAIR FOR THE LIMITS.
D	CLEAN UP AS SHOWN IN ALLOWABLE DAMAGE 1 TO DAMAGE DEPTH. STOP DRILL 0.25 INCH (6 mm) DIAMETER HOLES AT THE ENDS OF THE CRACKS.	A NON-REVENUE FLIGHT TO A REPAIR STATION IS PERMITTED IF THE APPLICABLE REGULATORY AUTHORITY GIVES APPROVAL BEFORE THE FLIGHT. IT IS RECOMMENDED THAT THE PROPOSED REPAIR PROCEDURE BE GIVEN TO BOEING.
		THE MAXIMUM CABIN PRESSURE DIFFERENTIAL C IS LIMITED TO 6.0 PSIG UNLESS THE SKIN IS REPAIRED.
	DO AN APPLICABLE REPAIR AS GIVEN IN SRM 52-20-01.	REFER TO THE APPLICABLE REPAIR FOR THE LIMITS.
E	CLEAN UP AS SHOWN IN ALLOWABLE DAMAGE 1 TO DAMAGE DEPTH. STOP DRILL 0.25 INCH (6 mm) DIAMETER HOLES AT THE ENDS OF THE CRACKS.	A NON-REVENUE FLIGHT TO A REPAIR STATION IS PERMITTED IF THE APPLICABLE REGULATORY AUTHORITY GIVES APPROVAL BEFORE THE FLIGHT. IT IS RECOMMENDED THAT THE PROPOSED REPAIR PROCEDURE BE GIVEN TO BOEING.
		THE MAXIMUM CABIN PRESSURE DIFFERENTIAL C IS LIMITED TO ZERO PSIG.
	DO APPLICABLE REPAIR AS GIVEN IN SRM 52-20-01.	REFER TO THE APPLICABLE REPAIR FOR THE LIMITS.
F	CLEAN UP AS SHOWN IN ALLOWABLE DAMAGE 1 TO DAMAGE DEPTH. STOP DRILL 0.25 INCH (6 mm) DIAMETER HOLES AT THE ENDS OF THE CRACKS.	OPERATION IS NOT PERMITTED BEFORE BOEING AND THE APPLICABLE REGULATORY AUTHORITY GIVES APPROVAL.
г	DO APPLICABLE REPAIR AS GIVEN IN SRM 52-20-01.	REFER TO THE APPLICABLE REPAIR FOR THE LIMITS.

LIMITS FOR CORROSION, CRACKS, NICKS, GOUGES, AND HOLE DAMAGE

Operating Limits for Emergency Exit Door Skin Figure 101 (Sheet 2 of 2)

> ALLOWABLE DAMAGE 2 Page 102 Jan 20/2005



#### **REPAIR 1 - EMERGENCY EXIT DOOR SKIN - FLUSH REPAIR BETWEEN STIFFENERS**

#### REPAIR INSTRUCTIONS

- 1. Remove the inner skin panel and outer skin stiffeners for access as required.
- Clean out the damage to the skin in a rectangular shape with a minimum of 0.50 radius at the corners. The cutout should be parallel to the centerline of the adjacent stiffener.
- 3. Fabricate repair parts.
- Assemble repair parts in installed positions and drill fastener holes.
- 5. Remove repair parts.
- 6. Break sharp edges of original and repair parts 0.015 to 0.030.
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- Alodize all raw edges of existing parts and all surfaces and edges of new parts per 51–20–01.
- Apply one coat of BMS 10-11, type 1 primer per 51-24 of the 757 Maintenance Manual to inner surface of part 1, and to edges of existing skin, and to all surfaces and edges of remaining new parts and shims.
- 10. Install the repair parts with the fasteners wet with BMS 5-95 sealant and making faying surface seals between all parts in accordance with 51-20-05. If necessary, install 1/32 oversize fasteners in existing fastener locations. A bead of sealant should be apparent all around repair parts after installation. Where there is sufficient sealant squeezed out, it may be formed into a fillet, otherwise an additional fillet seal should be applied.
- 11. Reinstall inner skin panel.
- 12. Apply BMS 5–95 sealant in the gap between the filler, part 1, and the skin.
- 13. Refinish according to 51–20 of the 757 Maintenance Manual.

#### NOTES

• REFER TO THE FOLLOWING WHEN USING THIS REPAIR:

51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS

51-31 of the 757 maintenance manual for seals and sealing

51-40 FOR FASTENER CODE, REMOVAL, INSTAL-LATION, HOLE SIZES AND EDGE MARGINS

A THE ORIGINAL COUNTERSINK DEPTH FOR BACR15CE RIVETS MUST BE MAINTAINED. WHERE OVERSIZE RIVETS ARE INSTALLED, THE PROTRUDING PORTION OF THE RIVET HEADS MUST BE SHAVED OFF PER 51-10-01

Emergency Exit Door Skin - Flush Repair Between Stiffeners Figure 201 (Sheet 1 of 3)




REPAIR 1 Page 201 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL



FASTENER SYMBOLS + BACR15CE5D A + BACR15CE4D


> Emergency Exit Door Skin - Flush Repair Between Stiffeners Figure 201 (Sheet 2 of 3)



REPAIR 1 Page 202 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL





REPAIR MATERIAL					
P	ART	QTY	GAGE	MATERIAL	
1	FILLER	1	0.040	CLAD 2024-T3	
2	SHIM	AS REQ'D	0.020 OR 0.025	CLAD 2024-T3	
3	PLATE	1	0.050	CLAD 2024-T3	
4	SHIM	AS REQ'D	0.050	CLAD 2024-T3	

Emergency Exit Door Skin - Flush Repair Between Stiffeners Figure 201 (Sheet 3 of 3)



REPAIR 1 Page 203 Jan 20/2005



### **REPAIR 2 - EMERGENCY EXIT DOOR SKIN - FLUSH REPAIR AT STIFFENER**

#### REPAIR INSTRUCTIONS

- 1. Remove inner skin panel for access to the damaged area.
- 2. Remove stiffener from damaged area.
- 3. Clean out damage to skin to a rectangular shape parallel to the stiffener, with a minimum corner radius of 0.50 inch. The skin cutout must be in the .040 chem-milled area and at least 0.20 from chem-mill radius.
- 4. Make repair parts.
  - NOTE: Since the door outer skin is chemmilled, .020 or .025 shims must be used as required to fill the chemmill pockets between the repair plate and door skin. All shims are to be 2024-T3.
- 5. Assemble repair parts and drill the fastener holes in original and new locations.
- 6. Remove repair parts.
- 7. Break sharp edges of original and repair parts .015 to .030.
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- Alodize raw edges of original parts and all surfaces and edges of repair parts per 51-20-01.
- 10. Apply one coat of BMS 10-11, type I, primer to all of part 1 and to the raw edges and inner surface of part 2 in accordance with 51-21-00 of the 757 Maintenance Manual.
- 11. Install the repair parts and fasteners with BMS 5-95 sealant making faying surface seals between all parts in accordance with 51-20-05. A bead of sealant should be apparent all around repair parts after installation. Where there is sufficient sealant squeezed out it may be formed into a fillet, otherwise an additional fillet seal should be applied.
- 12. Apply BMS 5-95 sealant in the gap between the filler, part 2, and the skin.
- 13. Replace inner skin panel.
- 14. Restore surface finish in accordance with 51–21 of the 757 Maintenance Manual.

### NOTES

- REFER TO THE FOLLOWING WHEN USING THIS REPAIR:
  - 51-20-01 FOR PROTECTIVE TREATMENT OF METAL

51-20-05 FOR SEALING OF REPAIRS

51-40 FOR FASTENER CODE, REMOVAL, INSTALLA-TION, HOLE SIZES AND EDGE MARGINS

51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS

51-21 OF THE 757 MAINTENANCE MANUAL FOR INTERIOR AND EXTERIOR FINISHES

 $51\mapha31$  of the 757 maintenance manual for seals and sealing

A WHEN OVERSIZE FLUSH HEAD FASTENERS ARE INSTALLED, THE ORIGINAL COUNTERSUNK DEPTH FOR THE BACR15CE RIVETS REMOVED MUST BE MAINTAINED AND THE EXCESS PORTION OF THE REPAIR RIVET HEADS SHAVED OFF AFTER INSTAL-LATION PER 51-10-01

#### FASTENER SYMBOLS

- BACR15CE4D
- + BACR15CE5D A


	REPAIR MATERIAL						
PART QTY GAGE MATERIAL							
1	PLATE FILLER	1	0.063	2024-T3 2024-T3			
3	STIFFENER	1	2.305	BAC1498-212 2024-T42 OR EQUIVALENT			

Emergency Exit Door Skin - Flush Repair at Stiffener Figure 201 (Sheet 1 of 2)



REPAIR 2 Page 201 Jan 20/2005





Emergency Exit Door Skin - Flush Repair at Stiffener Figure 201 (Sheet 2 of 2)



REPAIR 2 Page 202 Jan 20/2005



### **REPAIR 3 - SMALL HOLE FLUSH REPAIR - EMERGENCY EXIT DOOR SKIN**

### REPAIR INSTRUCTIONS

- Clean out the damaged hole to 1-inch (25 mm) diameter maximum. The center of the hole to an edge or cutout must not be less than 1/2 of dimension A from Table I.
- 2. Fabricate repair parts 1 and 2.
- Break sharp edges of original and repair parts 0.015 to 0.030 INCH (0.4 to 0.8 mm).
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- Apply protective alodine to raw surfaces and edges of repair and original parts per SRM 51-20-01.
- Apply one coat of BMS 10-11, Type 1, primer to all of part 1 and to the raw edges and inner surface of part 2 in accordance with AMM 51-24.
- 7. Install the repair parts, making faying surface seals between all parts in accordance with SRM 51-20-05. A bead of sealant should be apparent all around repair parts after installation. Where there is sufficient sealant squeezed out it may be formed into a fillet, otherwise an additional fillet seal should be applied.
- 8. Apply BMS 5-95 sealant in the gap between the filler, part 1, and the skin.
- 9. Replace inner skin panel.
- 10. Restore surface finish in accordance with AMM 51-21.

#### NOTES

- NOT TO BE USED IN AREAS WITH DOUBLERS
- REFER TO THE FOLLOWING WHEN USING THIS REPAIR

SRM 51-21 OF THE 757 MAINTENANCE MANUAL FOR INTERIOR AND EXTERIOR FINISHES

SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS

SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE

SRM 51-20-01 FOR PROTECTIVE TREATMENT OF METAL

SRM 51-20-05 FOR SEALING OF REPAIRS

SRM 51-40 FOR FASTENER, REMOVAL, INSTALLATION, HOLE SIZES AND EDGE MARGINS

 WHERE THIS REPAIR IS BEING USED IN A MACHINED OR CHEM-MILLED SKIN, SHIMS MAY BE USED BETWEEN DOUBLER AND SKIN TO MAKE UP VARIATIONS IN THICKNESS

### SYMBOLS

REPAIR FASTENER LOCATION BACR15CE( )KE RIVET SEE TABLE 1 FOR SIZE AND NUMBER REQUIRED

REPAIR MATERIAL					
PART QTY MATERIAL					
1	FILLER	1	SAME MATERIAL AND GAGE AS ORIGINAL SKIN		
2	DOUBLER	1	SAME MATERIAL AS ORIGINAL SKIN. FOR GAGE SEE TABLE 1		

Small Hole Flush Repair - Emergency Exit Door Skin Figure 201 (Sheet 1 of 2)



REPAIR 3 Page 201 Jan 20/2005






757-200 STRUCTURAL REPAIR MANUAL

SKIN GAGE	PART 2 DOUBLER	A INCHES	BINCHES	C INCHES	INNER CIR		OUTER CIR	
GAGE	GAGE	INCHES	INCHES	INCHES	NUMBER	SIZE	NUMBER	SIZE
0.040	0.050	3.80	1.70	3.10	7	5/32	9	5/32
0.045	0.056	3.80	1.70	3.10	7	5/32	9	5/32
0.050	0.063	4.30	1.80	3.50	6	3/16	9	3/16
0.063	0.071	4.30	1.80	3.50	6	3/16	9	3/16

TABL	Е	Ι
------	---	---



Small Hole Flush Repair - Emergency Exit Door Skin Figure 201 (Sheet 2 of 2)



REPAIR 3 Page 202 Jan 20/2005



#### **REPAIR 4 - SMALL HOLE EXTERNAL REPAIR - EMERGENCY EXIT DOOR SKIN**

#### **REPAIR INSTRUCTIONS**

- Clean out the damaged hole to 1-inch diameter maximum. The center of the hole to an edge or cutout must not be less than 4D.
- Fabricate repair parts from material specified in Table I.
- 3. Break sharp edges of original and repair parts 0.015 to 0.030.
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- Apply protective alodine coating to raw surfaces and edges of existing parts and repair parts per 51-20-01.
- Apply one coat of BMS 10-11, type I primer in accordance with 51-21-00 of the 757 Maintenance Manual to all surfaces of parts 2 and 3 and to faying surface of part 1.
- 7. Install repair parts. Seal per 51-20-05.
- Restore surface finish in accordance with 51–21–00 of the 757 Maintenance Manual.

### NOTES

• REFER TO THE FOLLOWING WHEN USING THIS REPAIR:

51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS

51-20-01 FOR PROTECTIVE TREATMENT OF METALS

51-20-05 FOR SEALING OF REPAIRS


51-21 OF 757 MAINTENANCE MANUAL FOR FINISHES

51-40 FOR FASTENER CODE, REMOVAL, INSTAL-LATION, HOLE SIZES AND EDGE MARGINS

• THIS REPAIR IS NOT TO BE USED IN AREAS WITH DOUBLERS. THE AREA UNDER REPAIR PART 1 MUST NOT HAVE ANY FASTENERS, AND THE SKIN GAGE MUST BE CONSTANT

	REPAIR MATERIAL						
P	ART	QTY	MATERIAL				
1	DOUBLER	1	2024-T3 TWICE SKIN GAGE				
2	FILLER	1	2024-T3 SAME GAGE AS SKIN				
3	DOUBLER	1	2024-T3 TWICE SKIN GAGE				

TABLE I



Small Hole External Repair - Emergency Exit Door Skin Figure 201




REPAIR 4 Page 201 Jan 20/2005





### **IDENTIFICATION 1 - OVERWING EMERGENCY EXIT STRUCTURE**



Overwing Emergency Exit Structure Figure 1 (Sheet 1 of 3)



1DENTIFICATION 1 Page 1 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL




Figure 1 (Sheet 2 of 3)



1DENTIFICATION 1 Page 2 Jan 20/2005

REF DWG 144N6302



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	EDGE BEAM	0.071	2024-T42	
2	STOP BEAM		BAC1518-887 2024-T42	
3	INTERCOSTAL TEE WEB	0.063	BAC1505–100881 2024–T3511 2024–T42	
4	STOP FITTING		7075-T73 FORGING OR 7075-T73 FORGED BLOCK	
5	PIVOT FITTING	1.25	7075-T73 FORGING OR 7075-T7351 PLATE	
6	LATCH PIN FITTING		FORGING 7075-T73 OR FORGED BLOCK 7075-T73	
7	GUSSET	0.063	7075-T6	
8	INTERCOSTAL OUTER TEE INNER TEE WEB	0.063	BAC1505–100818 2024–T3511 OR 7075–T3511 BAC1505–100881 2024–T3511 OR 7075–T3511 2024–T42	
9	ZEE		BAC1517-130 2024-T42 OR 2024-T4	

LIST OF MATERIALS FOR DETAIL I

Overwing Emergency Exit Structure Figure 1 (Sheet 3 of 3)




1DENTIFICATION 1 Page 3 Jan 20/2005

D634N201

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



### **IDENTIFICATION 2 - NO. 3 EMERGENCY EXIT STRUCTURE**




REFER TO SRM 52-10-02

N0. 3 Emergency Exit Structure Figure 1 (Sheet 1 of 3)



**IDENTIFICATION 2** Page 1 Jan 20/2005





DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	BEAM OUTER CHORD INNER CHORD WEB SUPPORT FITTING	0.063 0.056	CLAD 2024-T42 BAC1506-1920 7075-T73511 CLAD 7075-T6 BAR 7075-T7351	
2	BEAM OUTER CHORD INNER CHORD WEB	0.063 0.063	BAC1506-1614 2024-T42 CLAD 7075-T6 CLAD 7075-T6	

LIST OF MATERIALS

N0. 3 Emergency Exit Structure Figure 1 (Sheet 2 of 3)



1DENTIFICATION 2 Page 2 Jan 20/2005





ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
3	BEAM			
	OUTER CHORD WEB	0.050	BAC1505-100543 2024-T42 CLAD 7075-T6	
4	BEAM			
	OUTER CHORD WEB	0.050	BAC1506-1401 2024-T42 CLAD 7075-T6	
5	BEAM			
	OUTER CHORD WEB ANGLE (2 LOCATIONS)	0.056 0.071	BAC1506-1920 2024-T42 CLAD 2024-T42 2024-T42	
6	UPPER FRAME			
	FRAME CHANNEL ANGLE	0.071 0.071 0.071	7075–T6 7075–T6 7075–T6	
7	SIDE FRAME			
	FRAME STRAP (2 LOCATIONS)	0.071 0.063	7075-T6 CLAD 7075-T6	
8	LOWER FRAME			
	WEB ANGLE BRACKET (2 LOCATIONS)	0.063 0.063 0.050	CLAD 2024-T42 CLAD 2024-T42 CLAD 7075-T6	
9	INTERCOSTAL			
	UPPER WEB LOWER WEB CHORD STIFFENER ANGLE BRACKET STRAP (2 LOCATIONS)	0.050 0.050 0.063 0.063	CLAD 7075-T6 CLAD 7075-T6 BAC1505-100052 2024-T42 BAC1505-100350 2024-T3511 BAC1490-2735 2024-T42 2024-T42 CLAD 2024-T3	
10	INTERCOSTAL			
	BRACKET	0.063	CLAD 2024-T42	
11	INTERCOSTAL			
	INTERCOSTAL ANGLE	0.050	CLAD 2024-T42 BAC1503-10031 7075-T73511	
12	STIFFENER		BAC1498-212 CLAD 2024-T42	
13	TEE		AND10136-1401 2024-T42	
14	STOP FITTING		BAC1520-1523 7075-T73511	
15	SEAL DEPRESSOR		CASTING 356-T51	
16	SEAL DEPRESSOR	0.050	CLAD 2024-T42	

LIST OF MATERIALS (CONTINUED)


N0. 3 Emergency Exit Structure Figure 1 (Sheet 3 of 3)



1DENTIFICATION 2 Page 3 Jan 20/2005



### ALLOWABLE DAMAGE 1 - OVERWING EMERGENCY EXIT DOOR STRUCTURE





757-200 STRUCTURAL REPAIR MANUAL

DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES
INTERCOSTAL WEB	В	E	SEE DETAIL IV	G
TEE	A	D	NOT ALLOWED	NOT ALLOWED
EDGE BEAM	В	E	SEE DETAIL IV	G
STOP BEAM	A	D	SEE DETAIL IV	G
GUSSET	В	E	SEE DETAIL IV	G
FITTINGS	C	F	NOT ALLOWED	NOT ALLOWED
ZEE	A	D	NOT ALLOWED	NOT ALLOWED

### NOTES

- REFER TO SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE.
- REFINISH REWORKED AREAS AS GIVEN IN AMM 51-20
- A CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED AS GIVEN IN DETAILS II VII
- B CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED AS GIVEN IN DETAILS II AND VI
- C CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED AS GIVEN IN DETAILS II AND VII. SHOT PEEN REWORKED AREA AS GIVEN IN SRM 51-20-06
- D REMOVE DAMAGE AS GIVEN IN DETAILS II, III, V AND VII
- E REMOVE DAMAGE AS GIVEN IN DETAILS II, III, V AND VI


- F FOR EDGE DAMAGE SEE DETAIL VII. FOR LUG DAMAGE, SEE DETAIL VIII. FOR OTHER DAMAGE, SEE DETAIL III. DAMAGE NOT ALLOWED IN VICINITY OF BUSHINGS. SHOT PEEN REWORKED AREA AS GIVEN IN SRM 51-20-06
- G CLEAN OUT DAMAGE UP TO 0.25 INCH (6 mm) MAX DIA AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OR T4 ALUMINUM RIVET INSTALLED WET WITH BMS 5-95 SEALANT. ALL OTHER HOLES TO BE REPAIRED

Allowable Damage - Overwing Emergency Exit Structure Figure 101 (Sheet 2 of 4)



Page 102







ALLOWABLE DAMAGE 1 52-20-02 Page 103 Jan 20/2005

D634N201



757-200 STRUCTURAL REPAIR MANUAL





DAMAGE CLEANUP FOR EDGES OF LUG DETAIL VIII


Allowable Damage - Overwing Emergency Exit Structure Figure 101 (Sheet 4 of 4)







### ALLOWABLE DAMAGE 2 - NO. 3 EMERGENCY EXIT DOOR STRUCTURE



No. 3 Emergency Exit Door Structure Figure 101 (Sheet 1 of 4)



Page 101 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL

DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES
CHORD EXTRUDED	A	D	NOT ALLOWED	NOT ALLOWED
FORMED	В	Ш	SEE DETAIL IV	G
FRAME	в	E	SEE DETAIL IV	G
INTERCOSTAL	В	E	SEE DETAIL IV	G
WEB	В	E	SEE DETAIL IV	G
STOP FITTING	C	F	NOT ALLOWED	NOT ALLOWED
STIFFENER	A	D	SEE DETAIL IV	G

#### NOTES

- REFINISH REWORKED AREAS AS GIVEN IN AMM 51-20
- REFER TO SRM 51-10-02 FOR INSPECTION AND ٠ REMOVAL OF DAMAGE
- A CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED AS GIVEN IN DETAILS II AND VII
- B CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED AS GIVEN IN DETAILS II AND VI
- C CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED GIVEN IN DETAILS II AND VII. SHOT PEEN REWORKED AREA AS GIVEN IN SRM 51-20-06
- D REMOVE DAMAGE AS GIVEN IN DETAILS II, III, V AND VII
- E REMOVE DAMAGE AS GIEN IN DETAILS II, III, V AND VI

- F FOR EDGE DAMAGE SEE DETAIL VII. FOR LUG DAMAGE, SEE DETAIL VIII. FOR OTHER DAMAGE, SEE DETAIL III. DAMAGE NOT ALLOWED IN VICINITY OF BUSHINGS. SHOT PEEN REWORKED AREA AS GIVEN IN SRM 51-20-06
- G CLEAN OUT DAMAGE UP TO 0.25 INCH (6 mm) MAXIMUM DIA AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OR T4 ALUMINUM RIVET INSTALLED WET WITH BMS 5-95 SEALANT. ALL OTHER HOLES TO BE REPAIRED


No. 3 Emergency Exit Door Structure Figure 101 (Sheet 2 of 4)



Page 102











757-200 STRUCTURAL REPAIR MANUAL





DAMAGE CLEANUP FOR EDGES OF LUG DETAIL VIII


> No. 3 Emergency Exit Door Structure Figure 101 (Sheet 4 of 4)



D634N201 D634N201 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



**REPAIR GENERAL - EMERGENCY EXIT STRUCTURE** 




NOTES

• DAMAGED COMPONENTS IN DOOR STRUCTURE MAY BE REPLACED OR REPAIRED. IF REPAIRS ARE TO BE MADE, SEE 51-70 FOR TYPICAL WEB, FORMED SECTION, OR EXTRUDED SECTION REPAIRS

> Emergency Exit Door Structure Repair Figure 201



2 Page 201 Jan 20/2005



DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	INNER SKIN	0.045	CLAD 7075-T6	
2	DOUBLER	0.032	CLAD 7075-T6	
3	STRAP	0.125	7075–T6	
4	STRAP	0.100	7075-T6	
5	DOUBLER	0.140	7075-T6	
6	STRAP	0.080	7075-T6	
7	OUTER SKIN	0.063	CLAD 2024-T3 (CHEM-MILLED TO 0.040 MIN)	
8	DOUBLER		2024-T351 PLATE	

LIST OF MATERIALS FOR DETAIL I

No. 2 Cargo Door Skin Figure 1




IDENTIFICATION 1 Page 1 Jan 20/2005





**IDENTIFICATION 2 - NO. 1 CARGO DOOR SKIN** 



DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	INNER SKIN	0.045	CLAD 7075-T6	
2	DOUBLER	0.032	CLAD 7075-T6	
3	STRAP	0.032	CLAD 2024-T3	
4	STRAP	0.100	CLAD 7075-T6	
5	STRAP		7075-T6 PLATE	
6	OUTER SKIN	0.063	CLAD 2024-T3 (CHEM-MILLED TO 0.040 MIN)	
7	DOUBLER		2024-T351 PLATE	

LIST OF MATERIALS FOR DETAIL I


No. 1 Cargo Door Skin Figure 1



IDENTIFICATION 2 Page 1 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	OUTER SKIN	0.071	CLAD 2024-T3 (CHEM-MILLED TO 0.040 MIN)	
2	INNER SKIN	0.063	CLAD 2024-T3	
3	STRAP	0.063	CLAD 2024-T3	

LIST OF MATERIALS


No. 3 Cargo Door Skin Figure 1



IDENTIFICATION 3 Page 1 Jan 20/2005



### **IDENTIFICATION 4 - MAIN DECK CARGO DOOR - SKIN**



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	UPPER SKIN ASSEMBLY SKIN BONDED DOUBLER	0.040 0.040	CLAD 2024-T3 CLAD 2024-T3	
2	LOWER SKIN	0.063	CLAD 2024-T3	

LIST OF MATERIALS FOR DETAIL I

Main Deck Cargo Door - Skin Figure 1 (Sheet 1 of 2)




IDENTIFICATION 4 Page 1 Jan 20/2005

REF DWG 65-25326



**BOEING**®

757-200 STRUCTURAL REPAIR MANUAL



(757-SF AIRPLANES ONLY)

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	SKIN	0.032	CLAD 7075-T6	

Main Deck Cargo Door - Skin Figure 1 (Sheet 2 of 2)




IDENTIFICATION 4 Page 2 Jan 20/2005






**ALLOWABLE DAMAGE 1 - CARGO DOOR SKIN** 





757-200 STRUCTURAL REPAIR MANUAL





DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES
OUTER SKIN A	BI	DI	ſ	EI
INNER SKIN	C	G	L	F
STRAPS AND DOUBLERS	В	D	SEE DETAIL VI	F

ALLOWABLE DAMAGE FOR DETAILS I, II , AND III

### NOTES

- THESE ALLOWABLE DAMAGE LIMITS ARE CATEGORY A REPAIRS. THE INSPECTIONS GIVEN IN THE MAINTENANCE PLANNING DATA (MPD) IN ADDITION TO THE INSPECTIONS REQUIRED IN THIS PROCEDURE, IF APPLICABLE, ARE SUFFICIENT TO MAINTAIN THE DAMAGE TOLERANCE OF THE INITIAL STRUCTURE WITH THIS ALLOWABLE DAMAGE. REFER TO SRM 51-00-06 FOR REPAIR CATEGORIES AND DEFINITIONS.
- REFINISH REWORKED AREAS AS SHOWN IN AMM 51-21
- REFER TO SRM 51-10-01 FOR AERODYNAMIC Α SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE IS MORE THAN THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED.
- B CRACKS ARE NOT PERMITTED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED AS SHOWN IN DETAILS IV AND VIII.
- FOR EDGE CRACKS, SEE DETAIL IV. FOR OTHERS, SEE DETAIL IX. FOR LIGHTENING HOLE EDGE CRACKS, SEE DETAIL X.
- D REMOVE DAMAGE AS SHOWN IN DETAILS IV, V, VII AND VIII.
- CLEAN OUT DAMAGE UP TO 0.25 INCH (6 mm) E MAXIMUM DIAMETER AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OR T4 ALUMINUM RIVET INSTALLED WET WITH BMS 5-95 SEALANT. ALL OTHER HOLES ARE TO BE REPAIRED.
- F CLEAN OUT DAMAGE UP TO 0.25 INCH (6 mm) MAXIMUM DIAMETER AND NOT CLOSER THAN 1.00 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE.


- G REMOVE DAMAGE AS SHOWN IN DETAILS IV, V, VII AND VIII. CORROSION MAY BE DRILLED OUT UP TO 0.5 INCH (12.7 mm) MAXIMUM DIAMETER PROVIDED EDGE MARGINS ARE MAINTAINED AS SHOWN IN DETAIL IX.
- H MAINTAIN 1.50 INCHES (38 mm) MINIMUM DISTANCE BETWEEN EDGE OF INITIAL FASTENER HOLE AND EDGE OF FLANGED HOLE, OR EDGE OF CUTOUT.
- I REFER TO ALLOWABLE DAMAGE 2 FOR THE CARGO DOOR SKIN OPERATING LIMITS AFTER DAMAGE HAS BEEN REMOVED.
- J DENTS THAT ARE MORE THAN THE LIMITS SHOWN IN DETAIL VI SHOULD BE PERMANENTLY REPAIRED. HOWEVER, A REPAIR CAN BE DELAYED IF THE CONDITIONS THAT FOLLOW ARE MET:
  - DENTS MUST BE SMOOTH AND FREE FROM SHARP CREASES, GOUGES, OR CRACKS, AND SHOW NO EVIDENCE OF PULLED, LOOSE, OR MISSING FASTENERS
  - THERE ARE NO DAMAGED OR ELONGATED FASTENER HOLES
  - THE DENT IS NOT FILLED
  - AN EXAMINATION OF THE DENT IS MADE EVERY 300 FLIGHT CYCLES
  - A PERMANENT REPAIR IS MADE AT THE SUBSEQUENT C-CHECK OR BEFORE 24 MONTHS
  - THE DAMAGE IS A MINIMUM OF 0.5 INCHES (12.7 mm) FROM ANY PART OF THE BEAM, SKIN DOUBLER, STRAP, FRAME, INTERCOSTAL, OR STIFFENER
  - THE DAMAGE IS A MINIMUM OF 10.0 INCHES (250 mm) FROM A SKIN SPLICE OR CUTOUT, INCLUDING A HINGE CUTOUT OR A HANDLE PAN CUTOUT.

Cargo Door Skin Figure 101 (Sheet 3 of 5)

> ALLOWABLE DAMAGE 1 52-30-01


Page 103


May 20/2005




BOEING

757-200 STRUCTURAL REPAIR MANUAL









SMOOTH BLENDOUT RADIUS 0.50 INCH MINIMUM. CORROSION CLEANUP AROUND ANY THREE FASTENERS IN TEN IS PERMITTED TO MAXIMUM DEPTH







REMOVAL OF NICK OR CRACK DAMAGE ON AN EDGE DETAIL VIII



FLANGED HOLE EDGE DAMAGE CLEAN UP DETAIL X



FIELD CRACK CLEAN UP DETAIL IX



X = DEPTH OF CLEANUP= 0.10 INCH MAXIMUM OR 1/2 FLANGE WIDTH, WHICHEVER IS LESS

- Y = LENGTH OF CLEANUP = 0.10 INCH MAXIMUM OR 1/2 FLANGE HEIGHT, WHICHEVER IS LESS

SECTION C-C


Cargo Door Skin Figure 101 (Sheet 5 of 5)







757-200 STRUCTURAL REPAIR MANUAL



NOTES

- A SKIN THICKNESS DOES NOT INCLUDE THE THICKNESS OF THE DOUBLERS, TRIPLERS, OR STRAPS.
- B DAMAGE INCLUDES HOLES, PUNCTURES, NICKS, GOUGES, SCRATCHES, CORROSION AND CRACKS. DAMAGE DOES NOT INCLUDE DENTS.
- C CABIN PRESSURE LIMITS ARE FOR SKIN DAMAGE TO THE PRESSURIZED FUSELAGE SKIN ONLY.

**Operating Limits for Cargo Door Skin** Figure 101 (Sheet 1 of 2)



Page 101 Jan 20/2005



DAMAGE DEPTH. WHICHEVER COMES FIRE FLIGHTS).	ONS. OF FLIGHT OR 25 FLIGHTS, ST (INCLUDING REVENUE
DAMAGE DEPTH. WHICHEVER COMES FIRE FLIGHTS).	
DO AN APPLICABLE REPAIR AS GIVEN IN REFER TO THE APPLICA SRM 52-30-01. LIMITS.	ABLE REPAIR FOR THE
C DAMAGE DEPTH. STOP DRILL 0.25 INCH (6 mm) PERMITTED IF THE APP DIAMETER HOLES AT THE ENDS OF THE CRACKS. AUTHORITY GIVES APP	ROVAL BEFORE THE FLIGHT. HAT THE PROPOSED REPAIR
	RESSURE DIFFERENTIAL C SIG UNLESS THE SKIN IS
DO AN APPLICABLE REPAIR AS GIVEN IN SRM 52-30-01. LIMITS.	ABLE REPAIR FOR THE
DAMAGE DEPTH. STOP DRILL 0.25 INCH (6 mm) PERMITTED IF THE APP DIAMETER HOLES AT THE ENDS OF THE CRACKS. AUTHORITY GIVES APP	ROVAL BEFORE THE FLIGHT. HAT THE PROPOSED REPAIR
	RESSURE DIFFERENTIAL C SIG UNLESS THE SKIN IS
DO AN APPLICABLE REPAIR AS GIVEN IN SRM 52-30-01. REFER TO THE APPLIC, LIMITS.	ABLE REPAIR FOR THE
E DAMAGE DEPTH. STOP DRILL 0.25 INCH (6 mm) PERMITTED IF THE APP DIAMETER HOLES AT THE ENDS OF THE CRACKS. AUTHORITY GIVES APP	ROVAL BEFORE THE FLIGHT. HAT THE PROPOSED REPAIR
THE MAXIMUM CABIN P IS LIMITED TO ZERO P	RESSURE DIFFERENTIAL C PSIG.
DO APPLICABLE REPAIR AS GIVEN IN SRM 52-30-01. REFER TO THE APPLIC. LIMITS.	ABLE REPAIR FOR THE
	RMITTED BEFORE BOEING REGULATORY AUTHORITY
DO APPLICABLE REPAIR AS GIVEN IN SRM 52-30-01. LIMITS.	ABLE REPAIR FOR THE


LIMITS FOR CORROSION, CRACKS, NICKS, GOUGES, AND HOLE DAMAGE

Operating Limits for Cargo Door Skin Figure 101 (Sheet 2 of 2)

> ALLOWABLE DAMAGE 2 **52-30-01**Page 102 Jan 20/2005



**REPAIR GENERAL - TYPICAL SKIN REPAIRS FOR CARGO DOORS** 



REPAIRS FOR CARGO DOORS:
 REFER TO REPAIR 1 FOR FLUSH SKIN REPAIR BETWEEN BEAMS
 REFER TO REPAIR 2 FOR SMALL HOLE - FLUSH REPAIR
 REFER TO REPAIR 3 FOR EXTERNAL REPAIR
 REFER TO REPAIR 4 FOR EXTERNAL REPAIR

Typical Skin Repairs for Cargo Doors Figure 201



REPAIR GENERAL Page 201 Jan 20/2005



### **REPAIR 1 - CARGO DOORS - FLUSH SKIN REPAIR BETWEEN BEAMS**

### REPAIR INSTRUCTIONS

- 1. Remove the inner skin panel for access if required.
- Clean out the damage to the skin to a rectangular shape with a minimum of 0.50 inch (12.7 mm) radius at the corners. The cutout should be parallel to the centerline of the adjacent beams.
- 3. Fabricate repair parts.
  - <u>NOTE</u>: Door outer skin is chem-milled. Fabricate repair parts as required to fill chem-milled pockets.
- 4. Assemble repair parts in installed positions and drill fastener holes.
- 5. Remove repair parts.
- Break sharp edges of original and repair parts 0.015 to 0.030 inch (0.4 to 0.8 mm).
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- Apply a chemical conversion coating to all bare edges of the existing and repair parts as given in SRM 51-20-01.
- Apply one coat of BMS 10–11, Type I, primer to inner surface of part 1 and to the edges and surfaces of part 2. Refer to SOPM 20–41–02.
- Install repair parts making a faying surface seal with BMS 5–95 sealant as given in SRM 51–20–05.
- 11. Install fasteners wet with BMS 5-95 sealant.
- 12. Form a fillet seal around the edge of the repair parts using the sealant squeezed out during installation. Apply additional sealant where necessary.
  - NOTE: Ensure that drain paths provided at manufacture are not covered by sealant. It is recommended that other accessible drain paths and drain holes are checked and cleared of accumulated debris.
- 13. Reinstall inner skin panel if removed for access.
- 14. Restore the surface finish in accordance with AMM 51-21-00.

### NOTES

- THIS REPAIR IS A CATEGORY A REPAIR. THE INSPECTIONS GIVEN IN THE MAINTENANCE PLANNING DATA (MPD) ARE SUFFICIENT TO MAINTAIN THE DAMAGE TOLERANCE OF THE INITIAL STRUCTURE WITH THIS REPAIR INSTALLED. REFER TO SRM 51-00-06 FOR REPAIR CATEGORIES AND DEFINITIONS.
- KEEP A MINIMUM OF 2D EDGE MARGIN ON ALL REPAIR PARTS.
- THE MAXIMUM PULL-UP PERMITTED BEFORE FASTENER INSTALLATION IS 0.005 INCH.
- D = FASTENER DIAMETER
- WHEN YOU USE THIS REPAIR, REFER TO:
  - AMM 51-21 FOR INTERIOR AND EXTERIOR FINISHES
  - SOPM 20-41-02 FOR APPLICATION OF CHEMICAL AND SOLVENT RESISTANT FINISHES
  - SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
  - SRM 51-20-01 FOR PROTECTIVE TREATMENT OF METAL
  - SRM 51-20-05 FOR SEALING OF FUSELAGE SKIN REPAIRS
  - SRM 51-40 FOR FASTENER CODE, REMOVAL, INSTALLATION, HOLE SIZES AND EDGE MARGINS
- A SEE SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS.
- B THE PART 1 DOUBLER MUST BE ONE BAY AWAY FROM AN ADJACENT DOUBLER REPAIR, CUTOUT AND/OR SPLICED JOINT.
- C WHERE COUNTERSINK RIVET SUBSTITUTIONS ARE MADE, THE COUNTERSINK DEPTH FOR BACR15CE RIVETS MUST BE MAINTAINED THE EXCESS PORTION OF THE SUBSTITUTE RIVET HEAD MUST BE SHAVED OFF AFTER INSTALLATION AS GIVEN IN SRM 51-10-01.

### FASTENER SYMBOLS

- + REPAIR FASTENER LOCATION. SEE TABLE III FOR FASTENER TYPE AND SIZE.
- --- REFERENCE FASTENER LOCATIONS

Cargo Doors - Flush Skin Repair Between Beams Figure 201 (Sheet 1 of 3)



REPAIR 1 Page 201 May 20/2005





	REPAIR MATERIAL			
PART QTY MATERIAL				
1	DOUBLER	1	CLAD 2024-T3. REFER TO TABLE II FOR THE NECESSARY THICKNESS.	
2	FILLER	1	CLAD 2024-T3. SAME THICKNESS AS THE TRIMMED SKIN.	

### TABLE I

PART 1 DOUBLER THICKNESS				
MAXIMUM TRIMMED SKIN GAGE (INCH)	DOUBLER GAGE (INCH)			
0.040	0.063			
0.045	0.063			
0.050	0.063			
0.056	0.063			
0.063	0.071			
0.071	0.080			

### TABLE II

REPAIR FASTENE	R REQUIREMENTS
SKIN GAGE THROUGH WHICH THE FASTENER IS INSTALLED (INCH)	FASTENERS C
0.040	BACR15BB5D
0.045	BACR15BB5D
0.050	BACR15BB5D
0.056	BACR15CE5D
0.063	BACR15CE6D
0.071	BACR15CE6D

TABLE III


Cargo Doors - Flush Skin Repair Between Beams Figure 201 (Sheet 2 of 3)



REPAIR 1 Page 202 May 20/2005



757-200 STRUCTURAL REPAIR MANUAL



Cargo Doors - Flush Skin Repair Between Beams Figure 201 (Sheet 3 of 3)



REPAIR 1 Page 203 May 20/2005



### **REPAIR 2 - CARGO DOORS - SMALL HOLE - FLUSH REPAIR**

#### APPLICABILITY

THIS REPAIR MUST NOT BE USED IN AREAS WITH DOUBLERS AND THE SKIN GAGE MUST BE CONSTANT.

#### **REPAIR INSTRUCTIONS**

- 1. Remove the inner skin panel for access if required.
- Clean out the damaged hole to 1-inch (25 mm) diameter maximum. The center of the hole to an edge or cutout must not be less than 1.90 inches (48 mm).
- 3. Make repair parts 1 and 2.
- 4. Assemble repair parts in installed positions and drill fastener holes.
- 5. Remove repair parts.
- Break sharp edges of original and repair parts 0.015 to 0.030 inch (0.4 to 0.8 mm).
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- Apply a chemical conversion coating to all bare edges of the existing and repair parts as given in SRM 51-20-01.
- Apply one coat of BMS 10–11, Type I, primer to all of part 2 and to the edges and inner surface of part 1. Refer to SOPM 20–41–02.
- Install repair parts, making a faying surface seal with BMS 5–95 sealant as described in SRM 51–20–05.
- 11. Install fasteners wet with BMS 5-95 sealant.
- 12. Form a fillet seal around the edge of the repair parts, using the sealant squeezed out during installation. Apply additional sealant where necessary.
  - NOTE: Ensure that drain paths provided at manufacture are not covered by sealant. It is recommended that other accessible drain paths and drain holes are checked and cleared of accumulated debris.
- 13. Reinstall inner skin panel if removed for access.
- 14. Restore the surface finish as given in AMM 51-21.

NOTES

- THIS REPAIR IS A CATEGORY A REPAIR. THE INSPECTIONS GIVEN IN THE MAINTENANCE PLANNING DATA (MPD) ARE SUFFICIENT TO MAINTAIN THE DAMAGE TOLERANCE OF THE INITIAL STRUCTURE WITH THIS REPAIR INSTALLED. REFER TO SRM 51-00-06 FOR REPAIR CATEGORIES AND DEFINITIONS.
- THE MAXIMUM PULL-UP PERMITTED BEFORE FASTENER INSTALLATION IS 0.005 INCH.
- KEEP A MINIMUM OF 2D EDGE MARGIN ON ALL REPAIR PARTS.
- D = FASTENER DIAMETER
- WHEN YOU USE THIS REPAIR, REFER TO:
  - AMM 51-21 FOR INTERIOR AND EXTERIOR FINISHES
  - SOPM 20-41-02 FOR APPLICATION OF CHEMICAL AND SOLVENT RESISTANT FINISHES
  - SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
  - SRM 51-20-01 FOR PROTECTIVE TREATMENT OF METAL
  - SRM 51-20-05 FOR SEALING OF FUSELAGE SKIN REPAIRS
  - SRM 51-40 FOR FASTENER CODE, REMOVAL, INSTALLATION, HOLE SIZES AND EDGE MARGINS.
- A SEE SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS
- B THE REPAIR DOUBLER MUST BE ONE BAY AWAY FROM AN ADJACENT DOUBLER REPAIR, CUTOUT AND/OR SPLICED JOINT
- C WHERE COUNTERSINK RIVET SUBSTITUTIONS ARE MADE, THE COUNTERSINK DEPTH FOR BACR15CE RIVETS MUST BE MAINTAINED. THE EXCESS PORTION OF THE SUBSTITUTE RIVET HEAD MUST BE SHAVED OFF AFTER INSTALLATION AS GIVEN IN SRM 51-10-01.

### FASTENER SYMBOLS

REPAIR FASTENER LOCATION. REFER TO TABLE III FOR THE FASTENER TYPE AND SIZE.

Cargo Doors - Small Hole - Flush Repair Figure 201 (Sheet 1 of 3)



REPAIR 2 Page 201 May 20/2005





	REPAIR MATERIAL					
PART QTY MATERIAL						
1	FILLER	1	CLAD 2024-T3. SAME THICKNESS AS THE TRIMMED SKIN.			
2	DOUBLER	1	CLAD 2024-T3. REFER TO TABLE II FOR THE NECESSARY THICKNESS.			

### TABLE I

PART 2 DOUBLER THICKNESS					
MAXIMUM TRIMMED SKIN GAGE (INCH)	DOUBLER GAGE (INCH)				
0.040	0.063				
0.045	0.063				
0.050	0.063				
0.056	0.063				
0.063	0.071				
0.071	0.080				

### TABLE II

REPAIR FASTENE	R REQUIREMENTS
SKIN GAGE THROUGH WHICH THE FASTENER IS INSTALLED (INCH)	FASTENERS େ
0.040	BACR15BB5D
0.045	BACR15BB5D
0.050	BACR15BB5D
0.056	BACR15CE5D
0.063	BACR15CE6D
0.071	BACR15CE6D


TABLE III

Cargo Doors - Small Hole - Flush Repair Figure 201 (Sheet 2 of 3)



REPAIR 2 Page 202 May 20/2005





DETAIL I

Cargo Doors - Small Hole - Flush Repair Figure 201 (Sheet 3 of 3)



REPAIR 2 Page 203 May 20/2005





#### **REPAIR 3 - CARGO DOORS - SMALL HOLE - EXTERNAL REPAIR**

### REPAIR INSTRUCTIONS

- 1. Remove the inner skin panel for access if required.
- Clean out the damaged hole to 1.00 inch (25 mm) diameter maximum. The center of the hole to an edge or cutout must not be less than 4 times the hole diameter. B
- 3. Fabricate repair parts.
- Break sharp edges of original and repair parts 0.015 to 0.030 inch (0.4 to 0.8 mm)
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- Apply a chemical conversion coating to all bare edges of the existing and repair parts as given in SRM 51-20-01.
- Apply one coat of BMS 10–11, Type I, primer to all of part 1 and to the edges and inner surface of part 2. Refer to SRM 20–41–02.
- Install repair parts, making a faying surface seal with BMS 5–95 sealant as described in SRM 51–20–05.
- 9. Install fasteners wet with BMS 5-95 sealant.
- Form a fillet seal around the edge of the repair parts, using the sealant squeezed out during installation. Apply additional sealant where necessary.
  - NOTE: Ensure that drain paths provided at manufacture are not covered by sealant. It is recommended that other accessible drain paths and drain holes are checked and cleared of accumulated debris.
- 11. Reinstall inner skin panel if removed for access.
- 12. Restore the surface finish in accordance with AMM 51-21.

### NOTES

- THIS REPAIR IS A CATEGORY C REPAIR. INSPECT THE BOLT, DOUBLER AND SURROUNDING SKIN EXTERNALLY EVERY 300 FLIGHT CYCLES. REPLACE THIS TIME-LIMITED REPAIR WITH A CATEGORY A REPAIR AT 2,500 FLIGHT CYCLES OR BEFORE IF DETERIORATION OCCURS. REFER TO SRM 51-00-06 FOR REPAIR CATEGORIES AND DEFINITIONS.
- WHEN YOU USE THIS REPAIR, REFER TO:
  - AMM 51-21 FOR INTERIOR AND EXTERIOR FINISHES
  - SOPM 20-41-02 FOR APPLICATION OF CHEMICAL AND SOLVENT RESISTANT FINISHES
  - SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
  - SRM 51-20-01 FOR PROTECTIVE TREATMENT OF METAL
  - SRM 51-20-05 FOR SEALING OF FUSELAGE SKIN REPAIRS
  - SRM 51-40 FOR FASTENER CODE, REMOVAL, INSTALLATION, HOLE SIZES, AND EDGE MARGINS AND SUBSTITUTION
- A SEE SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS
- B THIS REPAIR MUST BE ONE BAY AWAY FROM AN ADJACENT DOUBLER REPAIR, CUTOUT AND/OR SPLICED JOINT.

Cargo Doors - Small Hole - External Repair Figure 201 (Sheet 1 of 2)




REPAIR 3 Page 201 May 20/2005






REPAIR MATERIAL					
	PART QTY MATERIAL				
1	DOUBLER	1	CLAD 2024-T3. 0.126 INCH THICK		
2	FILLER	1	CLAD 2024-T3. SAME THICKNESS AS THE TRIMMED SKIN		
3	DOUBLER	1	CLAD 2024-T3. 0.126 INCH THICK		







DETAIL I

Cargo Doors - Small Hole - External Repair Figure 201 (Sheet 2 of 2)



REPAIR 3 Page 202 May 20/2005



#### **REPAIR 4 - CARGO DOORS - EXTERNAL SKIN REPAIR**

### REPAIR INSTRUCTIONS

- Remove inner skin panel for access to damage area if required.
- 2. Remove fasteners as necessary.
- Remove the damage to the skin to a rectangular shape with a minimum of 0.50 inch radius at the corners. The cutout must be parallel to the center line of the adjacent beams.
- 4. Make the repair parts given in Table I.
- 5. Assemble the repair parts and drill fastener holes.
- 6. Remove the repair parts.
- Break sharp edges of repair part 0.015 to 0.030 inch (0.4 to 0.8 mm).
- Remove all nicks, scratches, burrs, sharp edges and corners from the initial and repair parts.
- Apply a chemical conversion coating to the repair parts and the bare edges of initial part as given in SRM 51-20-01.
- 10. Apply one coat of BMS 10-79, Type II or III primer as given in SOPM 20-44-04.
- Between the doubler and skin, use a countersink repair washer in the initial countersinks as given in SRM 51-40-08.
- 12. Install the Part 1 Doubler and apply a faying surface seal with BMS 5–95 sealant as described in SRM 51–20–05.
  - <u>NOTE</u>: Clear drain paths and drain holes of accumulated debris in accessible areas.
- 13. Install fasteners wet with BMS 5-95 sealant.
- 14. Reinstall the inner skin panel if removed for access.
- 15. Restore finish in accordance with AMM 51-21.

#### NOTES

- THIS REPAIR IS A CATEGORY B REPAIR. THE CATEGORY B REPAIR HAS FAA APPROVAL IF YOU DO THE SUPPLEMENTAL INSPECTIONS GIVEN IN TABLE IV AND V AS APPLICABLE. INCORPORATION OF THESE INSPECTION REQUIREMENTS INTO THE AIRPLANE'S MAINTENANCE PROGRAM SATISFIES THE DAMAGE TOLERANCE ASSESSMENT OF THE REPAIR. REFER TO SRM 51-00-06 FOR THE REPAIR CATEGORIES AND DEFINITIONS.
- KEEP A MINIMUM OF 2D EDGE MARGIN ON ALL REPAIR PARTS.
- D = FASTENER DIAMETER.
- THE MAXIMUM PULL-UP PERMITTED BEFORE FASTENER INSTALLATION IN IS 0.005 INCH.

- REFER TO THE FOLLOWING WHEN YOU USE THIS REPAIR:
  - AMM 51-21 FOR INTERIOR AND EXTERIOR FINISHES
  - SOPM 20-44-04 FOR APPLICATION OF URETHANE COMPATIBLE PRIMER
  - SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
  - SRM 51-20-01 FOR PROTECTIVE TREATMENT OF METAL
  - SRM 51-20-05 FOR SEALING OF FUSELAGE SKIN REPAIRS
  - SRM 51-40 FOR FASTENER CODE, REMOVAL, INSTALLATION, HOLE SIZES, EDGE MARGINS AND SUBSTITUTION
  - SRM 51-40-08 FOR REPAIR WASHER INSTALLATION.
- A WHERE COUNTERSINK RIVET SUBSTITUTIONS ARE MADE, THE COUNTERSINK DEPTH FOR BACR15CE RIVETS MUST BE MAINTAINED. THE EXCESS PORTION OF THE SUBSTITUTE RIVET HEAD MUST BE SHAVED OFF AFTER INSTALLATION AS GIVEN IN SRM 51-10-01.
- B THIS REPAIR, WHEN INSTALLED AT THE BEAM AND INTERCOSTAL INTERSECTION ON LOWER LOBE FORWARD, AFT AND BULK CARGO DOORS, WILL HAVE AN EFFECT ON THE INSPECTIONS OF THE MAINTENANCE PLANNING DATA (MPD) ITEMS 5230-821-50E, 5230-822-50E AND 5230-823-50E. THE INSPECTIONS GIVEN IN TABLE IV WILL MEET THE INSPECTION REQUIREMENTS FOR THESE STRUCTURAL SIGNIFICANT ITEMS (SSI) REQUIRED BY THE MPD AND AD 2001-20-12. THEREFORE, THE INSPECTIONS GIVEN IN TABLE IV ARE AN ALTERNATE MEANS OF COMPLIANCE (AMOC) TO:
  - AD 2001-20-12 APPLICABLE TO LINE NUMBERS 1 THRU 764
  - MPD ITEM 5230-821-50E
  - MPD ITEM 5230-822-50E
  - MPD ITEM 5230-823-50E, IN THE AREA COVERED BY THIS REPAIR.
- C IF TOTAL DOOR FLIGHT CYCLES FROM DATE OF DELIVERY ARE NOT KNOWN, START THE REPEAT INSPECTIONS WITHIN 3,000 FLIGHT CYCLES AFTER THE REPAIR WAS INSTALLED.

### FASTENER SYMBOLS

- ➡ REPAIR FASTENER LOCATION. REFER TO TABLE III FOR THE FASTENER TYPE AND SIZE.
- INITIAL FASTENER LOCATION. REMOVE AND REPLACE WITH THE SAME TYPE AND SIZE AS THE INITIAL FASTENER OR 1/32 INCH OVERSIZE IF NECESSARY AS GIVEN IN SRM 51-40-02.
- Cargo Doors External Skin Repair Figure 201 (Sheet 1 of 6)



REPAIR 4 Page 201 May 20/2005



	REPAIR MATERIAL					
	PART QTY MATERIAL					
1	DOUBLER	1	CLAD 2024-T3. REFER TO TABLE II FOR THE NECESSARY THICKNESS.			
2	FILLER	1	CLAD 2024-T3. SAME THICKNESS AS THE THICKEST TRIMMED SKIN.			

TABLE I

PART 1 DOUBLER THICKNESS						
MAXIMUM TRIMMED SKIN GAGE (INCH)	DOUBLER GAGE (INCH)					
0.040	0.063					
0.045	0.063					
0.050	0.063					
0.056	0.063					
0.063	0.071					
0.071	0.080					
0.080	0.080					

TABLE II

REPAIR FASTENE	R REQUIREMENTS
PART 1 DOUBLER GAGE (INCH)	FASTENERS 🔺
0.063	BACR15CE5D
0.071 - 0.080	BACR15CE6D

TABLE III


Cargo Doors - External Skin Repair Figure 201 (Sheet 2 of 6)



REPAIR 4 Page 202 May 20/2005



757-200 STRUCTURAL REPAIR MANUAL





REPAIR 4 Page 203 May 20/2005



CATEGORY B REPAIR INSPECTION REQUIREMENTS FOR LOWER FORWARD, AFT AND BULK CARGO DOORS 🗉							
INSPECTION THRESHOLD	REPEAT INSPECTIONS         REFERENCE           ALTERNATIVE METHOD         INTERVAL						
37,500 TOTAL DOOR FLIGHT CYCLES FROM DATE	I	LOW FREQUENCY EDDY CURRENT (LFEC)	3,000 FLIGHT CYCLES	NDT PART 6, 53-00-06			
OF DELIVERY C	II	LOW FREQUENCY EDDY CURRENT (LFEC)	6,000 FLIGHT CYCLES	NDT PART 6, 53-00-07			
NOTES: - USE ALTERNATIVE (I) LFEC METHOD TO INSPECT THE SKIN EXTERNALLY THROUGH THE PART 1 DOUBLER AS SHOWN IN DETAIL II. - USE ALTERNATIVE (II) LFEC METHOD TO INSPECT THE BEAM OUTER FLANGE EXTERNALLY THROUGH THE PART 1 DOUBLER AND SKIN AT THE INTERCOSTAL INTERSECTION AS SHOWN IN DETAIL II.							

TABLE IV

CATEGORY B REPAIR INSPECTION REQUIREMENTS FOR MAIN DECK CARGO DOOR						
INSPECTION	REPEAT INSF	· · · -	REFERENCE			
THRESHOLD	METHOD	INTERVAL				
37,500 TOTAL DOOR FLIGHT LOW FREQUENCY 3,000 FLIGHT CYCLES FROM DATE EDDY CURRENT (LFEC) CYCLES NDT PART 6, 53-00-06 OF DELIVERY C						
NOTES: - USE LFEC METHOD TO INSPECT THE SKIN EXTERNALLY THROUGH THE PART 1 DOUBLER AS SHOWN IN DETAIL III.						

TABLE V


Cargo Doors - External Skin Repair Figure 201 (Sheet 4 of 6)



REPAIR 4 Page 204 May 20/2005



757-200 STRUCTURAL REPAIR MANUAL





ALTERNATIVE (I) LFEC METHOD INSPECTION AREA. DO THE INSPECTION OF THE SKIN EXTERNALLY THROUGH THE PART 1 DOUBLER AT EVERY 3,000 FLIGHT CYCLES.



ALTERNATIVES (I) AND (II) LFEC METHOD INSPECTION AREA. DO THE INSPECTION OF THE SKIN EXTERNALLY THROUGH THE PART 1 DOUBLER AT EVERY 3,000 FLIGHT CYCLES. DO THE INSPECTION OF THE BEAM OUTER FLANGE THROUGH THE PART 1 DOUBLER AND SKIN AT EVERY 6,000 FLIGHT CYCLES. B

ALTERNATIVE (II) LFEC METHOD INSPECTION AREA. DO THE INSPECTION OF THE BEAM OUTER FLANGE EXTERNALLY THROUGH THE PART 1 DOUBLER AND SKIN AT EVERY 6,000 FLIGHT CYCLES. B

> INSPECTIONS FOR THE NO. 1 CARGO DOOR ARE SHOWN, ALL OTHER LOWER LOBE CARGO DOORS ARE ALMOST THE SAME DETAIL II


> > Cargo Doors - External Skin Repair Figure 201 (Sheet 5 of 6)



REPAIR 4 Page 205 May 20/2005



757-200 STRUCTURAL REPAIR MANUAL





SKIN INSPECTION AREA. USE LFEC METHOD TO INSPECT THE SKIN EXTERNALLY THROUGH THE PART 1 DOUBLER AT EVERY 3,000 FLIGHT CYCLES.

INSPECTIONS FOR THE MAIN DECK CARGO DOOR DETAIL III

Cargo Doors - External Skin Repair Figure 201 (Sheet 6 of 6)



REPAIR 4 Page 206 May 20/2005



### **IDENTIFICATION 1 - NO. 2 CARGO DOOR STRUCTURE**




Figure 1 (Sheet 1 of 4)



Page 1 May 20/2006



757-200 STRUCTURAL REPAIR MANUAL

(146N662			(69-45561)	REFERENCE DRAWING 146N6603 REFER TO 52-30-01 FOR OUTER SKIN IDENTIFICATION 21 (65-6-234) 15 9 FWD
REFER TO FOR INNI IDENTIF		GAGE	8 (TYP) 24 (146N6621) 20 8 (TYP) MATERIAL	INBD C
1	BEAM			
	OUTER TEE WEB INNER ANGLE	0.071	BAC1506-1912 2024-T3511 OR BAC1506-1912 2024-T42 7075-T6 BAC1514-1776 7075-T6511	
2	OUTER TEE WEB	0.071	BAC1506-1912 2024-T42 7075-T6	
2 3	OUTER TEE WEB INNER ANGLE BEAM OUTER TEE WEB INNER ANGLE BEAM OUTER TEE WEB		BAC1506-1912 2024-T42 7075-T6 BAC1514-1776 7075-T6511 BAC1506-1926 2024-T3511 OR BAC1506-1926 2024-T42 7075-T6 BAC1514-1778 7075-T6511 BAC1506-1924 2024-T3511 OR BAC1506-1924 2024-T42 7075-T6	
3	OUTER TEE WEB INNER ANGLE BEAM OUTER TEE WEB INNER ANGLE WEB INNER ANGLE	0.063	BAC1506-1912 2024-T42 7075-T6 BAC1514-1776 7075-T6511 BAC1506-1926 2024-T3511 OR BAC1506-1926 2024-T42 7075-T6 BAC1514-1778 7075-T6511 BAC1506-1924 2024-T3511 OR BAC1506-1924 2024-T42	
	OUTER TEE WEB INNER ANGLE BEAM OUTER TEE WEB INNER ANGLE BEAM OUTER TEE WEB	0.063	BAC1506-1912 2024-T42 7075-T6 BAC1514-1776 7075-T6511 BAC1506-1926 2024-T3511 OR BAC1506-1926 2024-T42 7075-T6 BAC1514-1778 7075-T6511 BAC1506-1924 2024-T3511 OR BAC1506-1924 2024-T42 7075-T6	
3	OUTER TEE WEB INNER ANGLE BEAM OUTER TEE WEB INNER ANGLE BEAM OUTER TEE WEB INNER ANGLE BEAM	0.063	BAC1506-1912 2024-T42 7075-T6 BAC1514-1776 7075-T6511 BAC1506-1926 2024-T3511 OR BAC1506-1926 2024-T42 7075-T6 BAC1514-1778 7075-T6511 BAC1506-1924 2024-T3511 OR BAC1506-1924 2024-T42 7075-T6 BAC1514-1778 7075-T6511 BAC1506-1925 2024-T3511 OR	
3	OUTER TEE WEB INNER ANGLE BEAM OUTER TEE WEB INNER ANGLE BEAM OUTER TEE WEB INNER TEE WEB	0.063	BAC1506-1912 2024-T42 7075-T6 BAC1514-1776 7075-T6511 BAC1506-1926 2024-T3511 OR BAC1506-1926 2024-T42 7075-T6 BAC1514-1778 7075-T6511 BAC1506-1924 2024-T3511 OR BAC1506-1924 2024-T42 7075-T6 BAC1514-1778 7075-T6511 BAC1506-1925 2024-T3511 OR BAC1506-1925 2024-T42 7075-T6	

LIST OF MATERIALS

No. 2 Cargo Door Structure Identification Figure 1 (Sheet 2 of 4)



1DENTIFICATION 1 Page 2 May 20/2006





ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
6	BEAM OUTER TEE WEB	0.071	BAC1506-1918 2024-T3511 OR BAC1506-1918 2024-T42 7075-T6	
_	INNER TEE		BAC1506-1917 7075-T6511	
7	INTERCOSTAL WEB ANGLE TEE	0.050	CLAD 7075-T6 AND10133-1003 7075-T6511 AND10136-1503 7075-T6511	
8	TEE		BAC1505-100424 7075-T6511	
9	TEE		AND10136-2002 7075-T6511	
10	INTERCOSTAL OUTER TEE WEB INNER TEE	0.080	AND10136-2002 7075-T6511 7075-T6 BAC1505-100553	
11	INTERCOSTAL OUTER TEE WEB	0.063	AND10136-2002 7075-T6511 7075-T6	
12	INTERCOSTAL OUTER TEE WEB	0.063	BAC1505-100039 7075-T6511 7075-T6	
13	INTERCOSTAL OUTER TEE WEB INNER CHORD	0.080 0.080	AND10133-1002 7075-T6511 7075-T6 CLAD 7075-T6	
14	INTERCOSTAL OUTER ANGLE WEB INNER ANGLE	0.080	AND10133-1002 7075-T6511 7075-T6 BAC1490-2632 7075-T6511	
15	INTERCOSTAL OUTER TEE WEB	0.080	AND10136-2002 7075-T6511 7075-T6	
16	INTERCOSTAL OUTER TEE WEB INNER ANGLE	0.071	BAC1505-100424 7075-T6511 7075-T6 BAC1490-2556 7075-T6	

### LIST OF MATERIALS FOR DETAIL I

No. 2 Cargo Door Structure Identification Figure 1 (Sheet 3 of 4)



1DENTIFICATION 1 Page 3 May 20/2006



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
17	ANGLE		AND10133-1002 7075-T6511	
18	STIFFENER		AND10133-1002 7075-T6511	
19	BRACKET	0.063	CLAD 7075-T6	
20	CORNER	0.050	CLAD 2024-T42	
21	CORNER	0.032	CLAD 2024-T42	
22	UPPER FRAME SUPPORT ANGLE SEAL DEPRESSOR	0.080	7075-T6 BAC1520-1497 2024-T3511	
23	SIDE FRAME WEB CHORD SEAL	0.071	7075-T6 BAC1490-2816 2024-T42 BAC1493-605 2024-T42	
24	LOWER EDGE BEAM	0.050	CLAD 2024-T42	
25	STOP FITTING		7075-T73 FORGING	

LIST OF MATERIALS FOR DETAIL I

No. 2 Cargo Door Structure Identification Figure 1 (Sheet 4 of 4)




1DENTIFICATION 1 Page 4 Sep 20/2006

D634N201

BOEING PROPRIETARY - Copyright (C) Unpublished Work - See title page for details



### **IDENTIFICATION 2 - NO. 1 CARGO DOOR STRUCTURE**



D	E	Т	A	Ι	L	]

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	BEAM OUTER TEE WEB ANGLE	0.071	BAC1506-1910 2024-T3511 CLAD 7075-T6 BAC1514-1776 7075-T6511	
2	BEAM OUTER TEE WEB ANGLE	0.063	BAC1506-1926 2024-T3511 CLAD 7075-T6 BAC1514-1777 7075-T6511	
3	BEAM OUTER TEE WEB ANGLE	0.063	BAC1506-1924 2024-T3511 CLAD 7075-T6 BAC1514-1778 7075-T6	

LIST OF MATERIALS FOR DETAIL I

No. 1 Cargo Door Structure Identification Figure 1 (Sheet 1 of 2)



1DENTIFICATION 2 Page 1 Jan 20/2005



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
4	BEAM OUTER TEE WEB ANGLE	0.063	BAC1506-1925 2024-T3511 CLAD 7075-T6 BAC1514-1779 7075-T6511	
5	BEAM OUTER TEE WEB ANGLE	0.063	BAC1506–1926 2024–T3511 CLAD 7075–T6 BAC1514–1780 7075–T6511	
6	BEAM OUTER TEE WEB INNER TEE	0.071	BAC1506–1918 2024–T3511 CLAD 7075–T6 BAC1506–1917 7075–T6511	
7	INTERCOSTAL OUTER TEE INNER ANGLE	0.050	AN10136-1503 7075-T6 CLAD 7075-T6	
8	OUTER TEE		BAC1505-100424 7075-T6	
9	INTERCOSTAL OUTER TEE WEB INNER ANGLE	0.071	BAC1505-100424 7075-T6 7075-T6 BAC1490-2556 CLAD 7075-T6	
10	ANGLE		AND10133-1002 7075-T6511	
11	INTERCOSTAL OUTER ANGLE WEB INNER ANGLE SHEAR PLATE	0.071	AND1033-1002 7075-T6511 CLAD 7075-T6 BAC1490-2684 CLAD 7075-T6 7075-T6	
12	INTERCOSTAL OUTER TEE WEB	0.071	BAC1505-100424 7075-T6511 CLAD 7075-T6	
13	TEE		BAC1506-1926 2024-T3511	
14	INTERCOSTAL OUTER TEE WEB	0.063	BAC1505-100424 7075-T6511 CLAD 7075-T6	
15	INTERCOSTAL OUTER TEE WEB INNER TEE	0.071	BAC1505-100424 7075-T6511 CLAD 7075-T6 BAC1505-29548 7075-T6511	
16	BRACKET	0.063	CLAD 7075-T6	
17	UPPER FRAME CHANNEL ANGLE CORNER SEAL DEPRESSOR	0.080 0.080 0.032	CLAD 2024-T42 CLAD 7075-T6 CLAD 2024-T42 BAC1520-1497 2024-T3511	
18	SIDE FRAME WEB SEAL DEPRESSOR	0.080	CLAD 7075-T6 BAC1493-605 CLAD 2024-T42	
19	LOWER FRAME BEAM	0.050	CLAD 2024-T42	
20	STOP FITTING		7075-T73 FORGING	
21	CORNER (2 LOCATIONS)	0.050	CLAD 2024-T42	

LIST OF MATERIALS FOR DETAIL I (CONTINUED)

No. 1 Cargo Door Structure Identification Figure 1 (Sheet 2 of 2)




1DENTIFICATION 2 Page 2 Jan 20/2005





### **IDENTIFICATION 3 - NO. 3 CARGO DOOR STRUCTURE**






ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	HINGE		7075-T73 DIE FORGING OPTIONAL: 7075-T73 FORGED BLOCK	A
2	TEE		BAC1505-100274 2024-T4	
3	INTERCOSTAL OUTER CHORD INNER CHORD WEB	0.063	BAC1505-100274 2024-T42 BAC1505-100274 7075-T6 CLAD 7075-T6	
4	STOP FITTING		7075-T73 DIE FORGING	
5	FRAME ASSY WEB TEE	0.063	CLAD 7075-T6 BAC1505-100274 2024-T4	
6	INTERCOSTAL		BAC1505-100274 2024-T42	
7	FRAME	0.063	CLAD 2024-T42	
8	SUPPORT ZEE	0.063	CLAD 2024-T42	
9	INTERCOSTAL CHORD WEB	0.063	BAC1505-100274 2024-T42 CLAD 7075-T6	
10	STOP FITTING		7075-T73 DIE FORGING OPTIONAL: 7075-T73 FORGED BLOCK	A
11	BEAM ASSY OUTER CHORD INNER CHORD WEB	0.063	BAC1505-100543 2024-T42 BAC1505-101270 7075-T62 CLAD 7075-T6	
12	BEAM ASSY OUTER CHORD INNER CHORD WEB	0.063	BAC1505-100543 2024-T4 BAC1505-101054 7075-T6 CLAD 2024-T3	
13	BEAM ASSY OUTER CHORD INNER CHORD WEB	0.063	BAC1505-100543 2024-T42 BAC1505-101054 7075-T62 CLAD 2024-T3	
14	BEAM ASSY OUTER CHORD INNER CHORD WEB	0.063	BAC1505-100543 2024-T4 BAC1505-100543 7075-T6 CLAD 2024-T3	

LIST OF MATERIALS FOR DETAIL I

No. 3 Cargo Door Structure Identification Figure 1 (Sheet 2 of 2)



IDENTIFICATION 3 Page 2 Jan 20/2005





ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	FRAME	0.0800	CLAD 7075-T6	
2	FRAME		BAC1517-1099 CLAD 7075-T6	
3	FRAME ASSY UPPER FRAME OUTER CHORD MID CHORD LOWER FRAME	0.071	BAC1517–1099 CLAD 7075–T6 BAC1506–992 CLAD 7075–T6511 BAC1490–2631 7075–T6 CLAD 7075–T6	
4	FRAME ASSY UPPER FRAME ANGLE LOWER FRAME	0.071	BAC1506–993 7075–T6 AND10134–1602 7075–T6511 7075–T6	
5	FRAME ASSY UPPER FRAME FWD ANGLE AFT ANGLE LOWER FRAME	0.071	BAC1506–992 7075–T6 AND10133–1203 7075–T6 AND10134–1602 7075–T6 7075–T6	
6	FRAME ASSY CHORD WEB	0.071	BAC1506-992 7075-T6511 CLAD 7075-T6	
7	FRAME ASSY UPPER FRAME FWD ANGLE AFT ANGLE LOWER FRAME	0.071	BAC1506–992 7075–T6 AND10134–1602 7075–T6 AND10133–1203 7075–T6 CLAD 7075–T6	
8	STRINGER		BAC1506-2092 7075-T6511	
9	BEAM ASSY BEAM WEB	0.125 0.063	CLAD 7075-T6 CLAD 7075-T6	
10	STIFFENER ASSSY STIFFENER ANGLE		AND10135-1005 7075-T6511 AND10134-1206 7075-T6511	
11	STIFFENER		AND10136-1003 7075-T6	
12	STIFFENER		AND10135-1005 7075-T6	
13	INTERCOSTAL	0.063	CLAD 7075-T6	
14	INTERCOSTAL		BAC1506-992 7075-T6511	

LIST OF MATERIALS FOR DETAIL I


Main Deck Cargo Door Structure Identification Figure 1 (Sheet 2 of 2)



1DENTIFICATION 4 Page 2 Jan 20/2005




ALLOWABLE DAMAGE 1 - CARGO DOOR STRUCTURE






REF DWG 146N6850



NO.3 CARGO DOOR DETAIL II

Cargo Door Structure Allowable Damage Figure 101 (Sheet 2 of 7)





52-30-02 Page 103 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL

DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES
CHORD	A	D	NOT ALLOWED	NOT ALLOWED
FRAME	В	E	SEE DETAIL V	H
WEB	C	F	SEE DETAIL V	H
STOP FITTING I	A	G	NOT ALLOWED	NOT ALLOWED
HINGE I	A	G	NOT ALLOWED	NOT ALLOWED
MACHINED FITTING I	A	G	NOT ALLOWED	NOT ALLOWED
EDGE BEAM	В	E	SEE DETAIL V	H

ALLOWABLE DAMAGE FOR DETAILS I AND II

DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES
EXTRUDED CHORD AND ANGLE	A	D	NOT ALLOWED	NOT ALLOWED
FORMED ANGLE AND ZEE FRAME	В	E	SEE DETAIL V	H
WEB	C	F	SEE DETAIL V	H
STIFFENER AND ANGLE	A	D	NOT ALLOWED	NOT ALLOWED
FORMED INTERCOSTAL	В	E	SEE DETAIL V	н

ALLOWABLE DAMAGE FOR DETAIL III


### NOTES

- THESE ALLOWABLE DAMAGE LIMITS ARE CATEGORY A REPAIRS. THE INSPECTIONS GIVEN IN THE MAINTENANCE PLANNING DATA (MPD) ARE SUFFICIENT TO MAINTAIN THE DAMAGE TOLERANCE OF THE INITIAL STRUCTURE WITH THIS ALLOWABLE DAMAGE. REFER TO SRM 51-00-06 FOR REPAIR CATEGORIES AND DEFINITIONS.
- REFINISH REWORKED AREAS AS GIVEN IN AMM 51-21.
- A CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAILS III AND IX
- B CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAILS III AND VIII
- C CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAILS III AND VII

- D REMOVE DAMAGE PER DETAILS III, IV, VI AND IX
- E REMOVE DAMAGE PER DETAILS III, IV, VI AND VIII
- F REMOVE DAMAGE PER DETAILS III, IV, VI AND VII
- G FOR EDGE DAMAGE SEE DETAILS III AND IX. FOR LUG DAMAGE, SEE DETAIL X. FOR OTHER DAMAGE, SEE DETAIL IV. DAMAGE NOT ALLOWED IN VICINITY OF BUSHINGS
- H CLEAN OUT DAMAGE UP TO 0.25 INCH (6.4 mm) MAXIMUM DIAMETER AND NOT CLOSER THAN 1.0 INCH (25.4 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OR T4 ALUMINUM RIVET INSTALLED WET WITH BMS 5-95 SEALANT. ALL OTHER HOLES TO BE REPAIRED
- I SHOT PEEN REWORKED AREAS AS GIVEN IN SRM 51-20-06

Cargo Door Structure Allowable Damage Figure 101 (Sheet 4 of 7)

> ALLOWABLE DAMAGE 1 52-30-02 Page 104 May 20/2005




Cargo Door Structure Allowable Damage Figure 101 (Sheet 5 of 7)

> ALLOWABLE DAMAGE 1 52-30-02 Page 105 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL




Cargo Door Structure Allowable Damage Figure 101 (Sheet 6 of 7)

> ALLOWABLE DAMAGE 1 52-30-02 Page 106 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL



DAMAGE CLEANUP FOR EDGES OF LUG DETAIL X

Cargo Door Structure Allowable Damage Figure 101 (Sheet 7 of 7)




D634N201

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



**REPAIR GENERAL - CARGO DOOR STRUCTURE** 



### NOTES

• DAMAGED COMPONENTS IN DOOR STRUCTURE MAY BE REPLACED OR REPAIRED. IF REPAIRS ARE TO BE MADE, SEE 51-70 FOR TYPICAL WEB, FORMED SECTION, OR EXTRUDED SECTION REPAIRS


> Cargo Door Structure Repair Figure 201



2 Page 201 Jan 20/2005



### **IDENTIFICATION 1 - FORWARD ACCESS DOOR SKIN**



DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	INNER SKIN	0.032	CLAD 2024-T3 OR 2024-T42	
2	OUTER SKIN	0.063	CLAD 2024-T3 (CHEM-MILLED TO 0.042 MIN)	

LIST OF MATERIALS

Forward Access Door Skin Identification Figure 1




IDENTIFICATION 1 Page 1 Jan 20/2005

REF DWG

141N6960



### **IDENTIFICATION 2 - ELEC/ELEX ACCESS DOOR SKIN**



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY		
1 2 3	INNER SKIN STRAP OUTER SKIN	0.032 0.040 0.063	CLAD 2024-T3 CLAD 2024-T3 CLAD 2024-T3 (CHEM-MILLED TO 0.040 MIN)			
	LIST OF MATERIALS					

Elec/Elex Access Door Skin Identification


Figure 1




IDENTIFICATION 2 Page 1 Jan 20/2005









ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	INNER SKIN	0.040	CLAD 2024-T42	
2	OUTER SKIN	0.056	CLAD 7075-T6 (CHEM-MILLED TO 0.036 MIN)	

### LIST OF MATERIALS

Elevator Control Access Door Skin Identification Figure 1




IDENTIFICATION 3 Page 1 Jan 20/2005





### **IDENTIFICATION 4 - SERVICE AND PRESSURE RELIEF DOOR SKIN**



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	OUTER SKIN	0.056	CLAD 7075-T6 (CHEM-MILLED TO 0.036 MIN)	
2	INNER SKIN	0.040	CLAD 2024-T42	

LIST OF MATERIALS FOR DETAIL I

Service and Pressure Relief Door Skin Identification Figure 1




IDENTIFICATION 4 Page 1 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL





ITEM	DESCRIPTION GAGE MATERIAL		EFFECTIVITY	
1	SKIN	0.016	ALUMINUM LAMINATED SHEETS PER BMS 5-69, TYPE 1, CLASS 1, GRADE B	
2	VENTED DOOR			
	SKIN	0.04	CLAD 2024-T3	
	DOUBLER	0.056	CLAD 2024-T3	
3	DOUBLER	0.04	CLAD 2024-T42	

LIST OF MATERIALS FOR DETAIL I


APU Access Door Skin Identification Figure 1







### **IDENTIFICATION 6 - WATER SERVICE DOOR**



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	OUTER SKIN	0.040	CLAD 2024-T3	
2	INNER SKIN	0.032	CLAD 2024-T42	

LIST OF MATERIALS

Water Service Door Identification Figure 1




IDENTIFICATION 6 Page 1 Jan 20/2005





### **IDENTIFICATION 7 - WASTE DISPOSAL ACCESS DOOR SKIN**



### NOTES

DETAIL I

A FOR CUM LINE NUMBERS: 1 THRU 846

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	DOOR ASSY SKIN DOUBLER	0.036 0.025	CLAD 2024-T3 CLAD 2024-T42	
2 3	PAN STIFFENER	0.040	301 CRES, ANNEALED, SURFACE COND 2D AND10136-1302 7075-T6	

LIST OF MATERIALS


Waste Disposal Access Door Skin Identification Figure 1




IDENTIFICATION 7 Page 1 Jan 20/2005



### **IDENTIFICATION 8 - MID LAVATORY WASTE DOOR**



REF DWG 143N3411



MID LAVATORY WASTE DOOR (INTERNAL VIEW) DETAIL I

		1 DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1 DOOR SKIN 0.16 CLAD 2024-T3	1	DOOR SKIN	0.16	CLAD 2024-T3	

LIST OF MATERIALS FOR DETAIL I


Mid Lavatory Waste Door Identification Figure 1



Page 1



### ALLOWABLE DAMAGE 1 - ALLOWABLE DAMAGE - FORWARD ACCESS DOOR SKIN



ITEM	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES
OUTER SKIN A	В	D	SEE DETAIL IV	E
INNER SKIN	C	G	SEE DETAIL IV	F

#### NOTES

- REFER TO 51-10-01 FOR INVESTIGATION AND CLEANUP OF DAMAGE
- REFINISH REWORK AREAS PER 51-20 OF THE MAINTENANCE MANUAL
- A REFER TO 51-10-01 FOR AERODYNAMIC SMOOTH-NESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- B CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAILS II AND VI
- C SEE DETAIL VIII FOR LIGHTENING HOLE EDGE CRACKS. FOR OTHER EDGE CRACKS, SEE DETAIL II. FOR OTHER CRACKS, SEE DETAIL VII


- D REMOVE DAMAGE PER DETAILS II, III, V AND VI
- E CLEAN OUT DAMAGE UP TO 0.25 MAX DIA AND NOT CLOSER THAN 1.0 INCH TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OR T4 ALUMINUM RIVET INSTALLED WET WITH BMS 5-95 SEALANT. ALL OTHER HOLES TO BE REPAIRED
- F CLEAN OUT DAMAGE UP TO 0.50 MAX DIA AND NOT CLOSER THAN 1.0 INCH TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE
- G REMOVE DAMAGE PER DETAILS II, III, V AND VI. CORROSION MAY BE DRILLED OUT UP TO 0.5 MAX DIA PROVIDED FASTENER EDGE MARGINS ARE MAINTAINED PER DETAIL VII

Allowable Damage - Forward Access Door Skin Figure 101 (Sheet 1 of 3)




ALLOWABLE DAMAGE 1 Page 101 Jan 20/2005





D634N201


Jan 20/2005






757-200 STRUCTURAL REPAIR MANUAL

#### ALLOWABLE DAMAGE 2 - ALLOWABLE DAMAGE - ELEC/ELEX ACCESS DOOR SKIN





DETAIL I

ITEM	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES
OUTER SKIN A	В	D	SEE DETAIL IV	E
INNER SKIN	C	G	SEE DETAIL IV	F
STRAPS	В	D	SEE DETAIL IV	E

#### NOTES

- REFINISH REWORK AREAS PER AMM 51-20
- REFER TO 51-10-02 FOR INSPECTION AND ٠ REMOVAL OF DAMAGE
- A REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- B CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAILS II AND VI
- C SEE DETAIL VIII FOR LIGHTENING HOLE EDGE CRACKS. FOR OTHER EDGE CRACKS, SEE DETAIL II. FOR OTHER CRACKS, SEE DETAIL VII


- D REMOVE DAMAGE PER DETAILS II, III, V AND VI
- E CLEAN OUT DAMAGE UP TO 0.25 INCH (6 mm) MAX DIA AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OR T4 ALUMINUM RIVET INSTALLED WET WITH BMS 5-95 SEALANT. ALL OTHER HOLES TO BE REPAIRED
- F CLEAN OUT DAMAGE UP TO 0.50 INCH (12.7 mm) MAX DIA AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE
- G REMOVE DAMAGE PER DETAILS II, III, V AND VI. CORROSION MAY BE DRILLED OUT UP TO 0.5 INCH (12.7 mm) MAX DIA PROVIDED FASTENER EDGE MARGINS ARE MAINTAINED PER DETAIL VII

Allowable Damage - Elec/Elex Access Door Skin Figure 101 (Sheet 1 of 3)



Page 101 Jan 20/2005






D634N201

52-40-01


Jan 20/2005






757-200 STRUCTURAL REPAIR MANUAL

### ALLOWABLE DAMAGE 3 - ALLOWABLE DAMAGE - ELEVATOR CONTROL ACCESS DOOR SKIN





DETAIL I

ITEM	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES
OUTER SKIN A	В	D	SEE DETAIL IV	DE
INNER SKIN	C	G	SEE DETAIL IV	F

NOTES

- REFINISH REWORK AREAS PER AMM 51-20
- REFER TO 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- A REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- B CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAILS II AND VI
- C SEE DETAIL VIII FOR LIGHTENING HOLE EDGE CRACKS. FOR OTHER EDGE CRACKS, SEE DETAIL II. FOR OTHER CRACKS, SEE DETAIL VII

- D REMOVE DAMAGE PER DETAILS II, III, V AND VI
- E CLEAN OUT DAMAGE UP TO 0.25 INCH (6 mm) MAX DIA AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OR T4 ALUMINUM RIVET INSTALLED WET WITH BMS 5-95 SEALANT. ALL OTHER HOLES TO BE REPAIRED
- F CLEAN OUT DAMAGE UP TO 0.50 INCH (12.7 mm) MAX DIA AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE
- G REMOVE DAMAGE PER DETAILS II, III, V AND VI. CORROSION MAY BE DRILLED OUT UP TO 0.5 INCH (12.7 mm) MAX DIA PROVIDED FASTENER EDGE MARGINS ARE MAINTAINED PER DETAIL VII


Allowable Damage - Elevator Control Access Door Skin Figure 101 (Sheet 1 of 3)



ALLOWABLE DAMAGE 3 Page 101 Jan 20/2005








D634N201

52-40-01


Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL

### ALLOWABLE DAMAGE 4 - ALLOWABLE DAMAGE - AFT BODY ACCESS DOOR SKIN



ITE	EM	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURE'S
OUTER SK	(IN A	В	D	SEE DETAIL IV	E
INNER SK	CIN	C	G	SEE DETAIL IV	F

#### NOTES

- REFINISH REWORK AREAS PER AMM 51-20
- REFER TO 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- A REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- B CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAILS II AND VI
- C SEE DETAIL VIII FOR LIGHTENING HOLE EDGE CRACKS. FOR OTHER EDGE CRACKS, SEE DETAIL II. FOR OTHER CRACKS, SEE DETAIL VII

- D REMOVE DAMAGE PER DETAILS II, III, V AND VI
- E CLEAN OUT DAMAGE UP TO 0.25 INCH (6 mm) MAX DIA AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OR T4 ALUMINUM RIVET INSTALLED WET WITH BMS 5-95 SEALANT. ALL OTHER HOLES TO BE REPAIRED
- F CLEAN OUT DAMAGE UP TO 0.50 INCH (12.7 mm) MAX DIA AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE
- G REMOVE DAMAGE PER DETAILS II, III, V AND VI. CORROSION MAY BE DRILLED OUT UP TO 0.5 INCH (12.7 mm) MAX DIA PROVIDED FASTENER EDGE MARGINS ARE MAINTAINED PER DETAIL VII


Allowable Damage - Aft Body Access Door Skin Figure 101 (Sheet 1 of 3)



ALLOWABLE DAMAGE 4 Page 101 Jan 20/2005








D634N201


52-40-01

Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL

#### ALLOWABLE DAMAGE 5 - ALLOWABLE DAMAGE - APU ACCESS DOOR SKIN



DETAIL I

ITEM	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES
OUTER SKIN A	В	D	SEE DETAIL IV	E
INNER SKIN	C	G	SEE DETAIL IV	F
DOUBLER	В	D	SEE DETAIL IV	E

#### NOTES

- REFINISH REWORK AREAS PER AMM 51-20
- REFER TO 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- A REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- B CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAILS II AND VI
- C SEE DETAIL VIII FOR LIGHTENING HOLE EDGE CRACKS. FOR OTHER EDGE CRACKS, SEE DETAIL II. FOR OTHER CRACKS, SEE DETAIL VII

D REMOVE DAMAGE PER DETAILS II, III, V AND VI

E CLEAN OUT DAMAGE UP TO 0.25 INCH (6 mm) MAX DIA AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OR T4 ALUMINUM RIVET INSTALLED WET WITH BMS 5-95 SEALANT. ALL OTHER HOLES TO BE REPAIRED

F CLEAN OUT DAMAGE UP TO 0.50 INCH (12.7 mm) MAX DIA AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE


G REMOVE DAMAGE PER DETAILS II, III, V AND VI. CORROSION MAY BE DRILLED OUT UP TO 0.5 INCH (12.7 mm) MAX DIA PROVIDED FASTENER EDGE MARGINS ARE MAINTAINED PER DETAIL VII


Allowable Damage - APU Access Door Skin Figure 101 (Sheet 1 of 3)



ALLOWABLE DAMAGE 5 Page 101 Jan 20/2005










#### ALLOWABLE DAMAGE 6 - ALLOWABLE DAMAGE - WATER SERVICE DOOR SKIN



DETAIL I

ITEM	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURE'S
OUTER SKIN A	В	D	SEE DETAIL IV	E
INNER SKIN	C	G	SEE DETAIL IV	F

### NOTES

- REFINISH REWORK AREAS PER AMM 51-20
- REFER TO 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- A REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- B CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAILS II AND VI
- C SEE DETAIL VIII FOR LIGHTENING HOLE EDGE CRACKS. FOR OTHER EDGE CRACKS, SEE DETAIL II. FOR OTHER CRACKS, SEE DETAIL VII


- D REMOVE DAMAGE PER DETAILS II, III, V AND VI
- E CLEAN OUT DAMAGE UP TO 0.25 INCH (6 mm) MAX DIA AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OR T4 ALUMINUM RIVET INSTALLED WET WITH BMS 5-95 SEALANT. ALL OTHER HOLES TO BE REPAIRED
- F CLEAN OUT DAMAGE UP TO 0.50 INCH (12.7 mm) MAX DIA AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE
- G REMOVE DAMAGE PER DETAILS II, III, V AND VI. CORROSION MAY BE DRILLED OUT UP TO 0.5 INCH (12.7 mm) MAX DIA PROVIDED FASTENER EDGE MARGINS ARE MAINTAINED PER DETAIL VII

Allowable Damage - Water Service Door Skin Figure 101 (Sheet 1 of 3)




ALLOWABLE DAMAGE 6 Page 101 Jan 20/2005






BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details





757-200 STRUCTURAL REPAIR MANUAL

### ALLOWABLE DAMAGE 7 - ALLOWABLE DAMAGE - WASTE DISPOSAL ACCESS DOOR SKIN



DETAIL I

ITEM	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES
OUTER SKIN A	В	D	SEE DETAIL IV	E
PAN	C	G	SEE DETAIL IV	F

### NOTES

- REFINISH REWORK AREAS PER AMM 51-20
- REFER TO 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- A REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTH-NESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- B CRACKS NOT PERMITTED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED AS SHOWN IN DETAILS II AND II
- C SEE DETAIL VIII FOR LIGHTNING HOLE EDGE CRACKS. FOR OTHER EDGE CRACKS, SEE DETAIL II. FOR OTHER CRACKS, SEE DETAIL VII
- REMOVE DAMAGE AS SHOWN IN DETAILS II, III, V, AND VI

- E CLEAN OUT DAMAGE UP TO 0.25 INCH (6 mm) MAXIMUM DIAMETER AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OT T4 ALUMINUM RIVET INSTALLED WET WITH BMS 5-95 SEALANT. ALL OTHER HOLES TO BE REPAIRED
- F CLEAN OUT DAMAGE UP TO 0.50 INCH (12.7 mm) MAXIMUM DIAMETER AND NOT CLOSER THAN 1.0 INCH (25 mm) TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE
- G REMOVE DAMAGE AS SHOWN IN DETAILS II, III, V AND VI. CORROSION MAY BE DRILLED OUT UP TO 0.5 INCH (12.7 mm) MAXIMUM DIAMETER PROVIDED FASTENER EDGE MARGINS ARE MAINTAINED AS SHOWN IN DETAIL VII
- H FOR CUM LINE NUMBERS: 1 THRU 846


Allowable Damage - Waste Disposal Access Door Skin Figure 101 (Sheet 1 of 3)




ALLOWABLE DAMAGE 7 Page 101 Jan 20/2005







ALLOWABLE DAMAGE 7 **52-40-01** Jan 20/2005





### **REPAIR 1 - SMALL HOLE FLUSH REPAIR - ACCESS DOORS**

#### REPAIR INSTRUCTIONS

- 1. Remove the inner skin panel for access if required.
- Clean out the damaged hole to 1-inch (25 mm) diameter maximum. The center of the hole to an edge or cutout must not be less than 1.90 inches (48 mm).
- 3. Make repair parts 1 and 2.
- 4. Assemble repair parts in installed position and drill fastener holes.
- 5. Remove repair parts.
- Break sharp edges of original and repair parts 0.015 to 0.030 inch (0.4 to 0.8 mm).
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- Alodize all raw edges of existing and repair parts per SRM 51-20-01.
- Apply one coat of BMS 10-11, type 1, primer to all of part 2 and to the edges and inner surface of part 1 in accordance with AMM 51-21-00.
- Install repair parts, making a faying surface seal with BMS 5–95 sealant as described in SRM 51–20–05.
- 11. Install fasteners wet with BMS 5-95 sealant.
- 12. Form a fillet seal around the edge of the repair parts, using the sealant squeezed out during installation. Apply additional sealant where necessary.

- 13. Reinstall inner skin panel if removed for access.
- 14. Restore the surface finish in accordance with AMM 51-20-00.

#### NOTES

- THIS REPAIR IS NOT TO BE USED IN AREAS WITH DOUBLERS AND THE SKIN GAGE MUST BE CONSTANT
- REFER TO 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- REFER TO SRM 51-40 FOR FASTENER CODE, REMOVAL, INSTALLATION, HOLE SIZES, EDGE MARGINS AND SUBSTITUTIONS
- A REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS
- B WHERE RIVET SUBSTITUTIONS ARE MADE THE COUNTERSINK DEPTH FOR BACR15CE RIVETS MUST BE MAINTAINED AND THE EXCESS PORTION OF THE SUBSTITUTE RIVET HEAD SHAVED OFF AFTER INSTALLATION PER SRM 51-10-01
- C MATERIAL THICKNESS TO BE THE SAME GAGE AS TOTAL SKIN THICKNESS IN REPAIR AREA (LAMINATED SKINS)
- D MATERIAL THICKNESS TO BE ONE GAGE THICKER THAN TOTAL SKIN THICKNESS IN REPAIR AREA

### SYMBOLS

REPAIR FASTENER LOCATION

Small Hole Flush Repair - Access Doors Figure 201 (Sheet 1 of 2)




REPAIR 1 Page 201 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL



EXTERIOR VIEW

SECTION THROUGH REPAIR

	REPAIR MATERIAL					
PART QTY		GAGE	MATERIAL			
1	FILLER	1	C	CLAD 2024-T3		
2	DOUBLER	1	D	CLAD 2024-T3 FOR SEC 41 THRU SEC 46 CLAD 7075-T6 FOR SEC 48		

ORIGINAL SKIN THICKNESS	REPAIR RIVET
0.040	BACR15CE4D
0.040 THRU 0.050	BACR15CE5D
0.063 THRU 0.071	BACR15CE6D

TABLE I

Small Hole Flush Repair - Access Doors Figure 201 (Sheet 2 of 2)



REPAIR 1 Page 202 Jan 20/2005





### **REPAIR 2 - SMALL HOLE - EXTERNAL REPAIR**

### **REPAIR INSTRUCTIONS**

- 1. Remove the inner skin panel for access if required.
- Clean out the damaged hole to 1.00 inch (25 mm) diameter maximum. The center of the hole to an edge or cutout must not be less than 4D.
- 3. Fabricate repair parts.
- Break sharp edges of original and repair parts 0.015 to 0.030 inch (0.4 to 0.8 mm).
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- 6. Alodize all raw edges of existing and repair parts per SRM 51-20-01.
- 7. Apply one coat of BMS 10-11, type 1, primer to all of part 1 and to the edges and inner surface of part 2 in accordance with AMM 51-21-00.
- Install repair parts, making a faying surface seal with BMS 5-95 sealant as described in SRM 51-20-05.
- 9. Install fasteners wet with BMS 5-95 sealant.
- 10. Form a fillet seal around the edge of the repair parts, using the sealant squeezed out during installation. Apply additional sealant where necessary.

- Reinstall inner skin panel if removed for access.
- 12. Restore the surface finish in accordance with AMM 51-20-00.

#### NOTES

- REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS
- REFER TO SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- REFER TO SRM 51-40 FOR FASTENER CODE, REMOVAL, INSTALLATION, HOLE SIZES, EDGE MARGINS AND SUBSTITUTIONS
- A THIS REPAIR IS NOT TO BE USED IN AREAS WITH DOUBLERS. THE AREA UNDER REPAIR PART 1 MUST NOT HAVE ANY FASTENERS, AND THE SKIN GAGE MUST BE CONSTANT
- B MATERIAL THICKNESS TO BE 2 TIMES THE TOTAL SKIN THICKNESS IN REPAIR AREA
- C MATERIAL THICKNESS TO BE THE SAME GAGE AS TOTAL SKIN THICKNESS IN REPAIR AREA (LAMINATED SKINS)


Small Hole - External Repair Figure 201 (Sheet 1 of 2)




REPAIR 2 Page 201 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL





OPTIONAL METHOD

	REPAIR MATERIAL						
	PART	QTY	GAGE	MATERIAL			
1	DOUBLER	1	В	CLAD 2024-T3			
2	FILLER	1	C	CLAD 2024-T3			
3	DOUBLER	1	В	CLAD 2024-T3			

Small Hole - External Repair Figure 201 (Sheet 2 of 2)



REPAIR 2 Page 202 Jan 20/2005



### **REPAIR 3 - APU ACCESS DOOR - FLUSH SKIN REPAIR BETWEEN BEAMS**

#### REPAIR INSTRUCTIONS

- 1. Remove the inner skin panel for access if required.
- Clean out the damage to the skin to a rectangular shape with a minimum of 0.50 inch (12.7 mm) radius at the corners. The cutout should be parallel to the centerline of the adjacent beam.
- 3. Make repair parts 1 and 2.
- Assemble repair parts in installed positions and drill fastener holes.
- 5. Remove repair parts.
- Break sharp edges of original and repair parts 0.015 to 0.030 inch (0.4 to 0.8 mm).
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- Alodize all raw edges of existing and repair parts per SRM 51-20-01.
- 9. Apply one coat of BMS 10-11, type 1, primer to all of part 1 and to the edges and inner surface of part 2 in accordance with AMM 51-21-00.
- 10. Install repair parts, making a faying surface seal with BMS 5–95 sealant as described in SRM 51–20–05.
- 11. Install fasteners wet with BMS 5-95 sealant.
- 12. Form a fillet seal around the edge of the repair parts, using the sealant squeezed out during installation. Apply additional sealant where necessary.

- 13. Reinstall inner skin panel, if removed for access.
- 14. Restore the surface finish in accordance with AMM 51-20-00.

### NOTES

- REFER TO 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- REFER TO SRM 51-40 FOR FASTENER CODE, REMOVAL, INSTALLATION, HOLE SIZES, EDGE MARGINS AND SUBSTITUTIONS.
- A REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS
- B WHERE RIVET SUBSTITUTIONS ARE MADE THE COUNTERSINK DEPTH FOR BACR15CE RIVETS MUST BE MAINTAINED AND THE EXCESS PORTION OF THE SUBSTITUTE RIVET HEAD SHAVED OFF AFTER INSTALLATION PER SRM 51-10-01

#### SYMBOLS

REPAIR FASTENER LOCATION

APU Access Door - Flush Skin Repair Between Beams Figure 201 (Sheet 1 of 2)




REPAIR 3 Page 201 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL



	REPAIR MATERIAL						
	PART	QTY	GAGE	MATERIAL			
1	PLATE	1	0.040	CLAD 2024-T3			
2	FILLER	1	0.032	CLAD 2024-T3			

APU Access Door - Flush Skin Repair Between Beams Figure 201 (Sheet 2 of 2)



REPAIR 3 Page 202 Jan 20/2005



### **REPAIR 4 - APU ACCSS DOOR - FLUSH SKIN REPAIR AT FRAMES**

#### REPAIR INSTRUCTIONS

- Remove inner skin panel for access to the damaged area if required.
- Clean out damage to skin to a rectangular shape parallel to the frames with a minimum corner radius of 0.50 inch (12.7 mm).
- 3. Cut out frame flanges to width of repair plate to permit its insertion against the skin.
- 4. Make repair parts.
- Assemble repair parts and drill the fastener holes in original and new locations. Add spacer or shims between part 1 plate or inner side of frame flange and new angles, whichever is required to fill gap.
- 6. Remove repair parts.
- 7. Break sharp edges of original and repair parts 0.015 to 0.030 inch (0.4 to 0.8 mm).
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair parts.
- 9. Alodize raw edges of original and repair parts per SRM 51-20-01.
- 10. Apply one coat of BMS 10–11, type 1, primer to all of parts 1 and 3 and to the edges and inner surface of part 2 in accordance with AMM 51–21–00.
- Install repair parts, making a faying surface seal with BMS 5–95 sealant as described in SRM 51–20–05.
- 12. Install fasteners wet with BMS 5-95 sealant.
- 13. Form a fillet seal around the edge of the repair parts, using the sealant squeezed out during installation. Apply additional sealant where necessary.
- 14. Restore surface finish in accordance with AMM 51-20-00.

#### NOTES

- REFER TO SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- REFER TO SRM 51-40 FOR FASTENER CODE, REMOVAL, INSTALLATION, HOLE SIZES, EDGE MARGINS, COUNTERSINKING, AND FASTENER SUBSTITUTIONS
- A MINIMUM OF THREE FASTENERS IN EACH ROW JOINING REPAIR ANGLES TO ORIGINAL SECTION
- B FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS, REFER TO SRM 51-10-01
- C WHERE RIVET SUBSTITUTIONS ARE MADE, THE COUNTERSINK DEPTH FOR BACR15CE RIVETS MUST BE MAINTAINED AND THE EXCESS PORTION OF THE SUBSTITUTE RIVET HEAD SHAVED OFF AFTER INSTALLATION PER SRM 51-10-01
- SELECT MATERIAL SO THAT FORMED HEADS OF RIVET DO NOT RIDE RADIUS OF FORMED ANGLE
- E SAME GAGE AS ORIGINAL FRAME

### SYMBOLS

- REPAIR FASTNER LOCATION
- ORIGINAL FASTENER LOCATION REMOVE AND REPLACE WITH BACR15BB( )AD OR BACR15BB( )DD SAME SIZE AS ORIGINAL OR 1/32 OVERSIZE IF REQUIRED

APU Accss Door - Flush Skin Repair at Frames Figure 201 (Sheet 1 of 2)




REPAIR 4 Page 201 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL



APU Accss Door - Flush Skin Repair at Frames Figure 201 (Sheet 2 of 2)

1

2

3



REPAIR 4 Page 202 Jan 20/2005



#### **REPAIR 5 - APU ACCESS DOOR - EXTERNAL SKIN REPAIRS**

#### **REPAIR INSTRUCTIONS**

- 1. Remove inner skin panel for access to damaged area if required.
- 2. Drill 0.25 inch (6 mm) diameter stop hole at extremities of crack.
- 3. Remove fasteners as required.
- 4. Make repair part.
- 5. Assemble repair part and drill fastener holes.
- 6. Remove repair part.
- 7. Break sharp edges of repair part 0.015 to 0.030 inch (0.4 to 0.8 mm).
- Remove all nicks, scratches, burrs, sharp edges and corners from original and repair part.
- 9. Alodize the raw edges of repair part per SRM 51-20-01.
- 10. Apply one coat of BMS 10-11, type 1, primer in accordance with AMM 51-21-00.
- Install plate (part 1), making a faying surface seal with BMS 5–95 sealant as described in SRM 51–20–05.
- 12. Install fasteners wet with BMS 5-95 sealant.
- 13. Restore finish in accordance with AMM 51-20-00.

#### NOTES

- REFER TO SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- REFER TO SRM 51-40 FOR FASTENER CODE, REMOVAL, INSTALLATION, HOLE SIZES, EDGE MARGINS, COUNTERSINKING, AND FASTENER SUBSTITUTIONS
- A WHERE RIVET SUBSTITUTIONS ARE MADE, THE COUNTERSINK DEPTH FOR BACR15CE RIVETS MUST BE MAINTAINED AND THE EXCESS PORTION OF THE SUBSTITUTE RIVET HEAD SHAVED OFF AFTER IN-STALLATION PER SRM 51-10-01
- B REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS

### SYMBOLS

- REPAIR FASTNER LOCATION
- ORIGINAL FASTENER LOCATION REMOVE AND REPLACE WITH BACR15BB( )AD OR BACR15BB( )DD SAME SIZE AS ORIGINAL OR 1/32 OVERSIZE IF REQUIRED

APU Access Door - External Skin Repairs Figure 201 (Sheet 1 of 2)




REPAIR 5 Page 201 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL



REPAIR MATERIAL						
PART		QTY	GAGE	MATERIAL		
1	PLATE	1	0.040	CLAD 2024-T3		


APU Access Door - External Skin Repairs Figure 201 (Sheet 2 of 2)



REPAIR 5 Page 202 Jan 20/2005



### **IDENTIFICATION 1 - FORWARD ACCESS DOOR STRUCTURE**



### DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	BEAM WEB TEE	0.071	CLAD 7075-T6 BAC1505-100350 2024-T3511	
2	INTERCOSTAL WEB TEE	0.050	CLAD 7075-T6 BAC1506-2195 2024-T3511	
3	CHANNEL	0.071	CLAD 7075-T62	
4	ANGLE		BAC1490-2507 CLAD 7075-T6	
5	ANGLE		BAC1490-2736 CLAD 7075-T6	
6	LATCH FITTING		7075-T73 FORGING	
7	HINGE ARM	0.313	7075-T651	
8	PAN	0.050	CLAD 2024-T42	
9	STOP FITTING		BAC1520-2207 2024-T3511 OR BAC1520-2215 2024-T3511	

### LIST OF MATERIALS


Forward Access Door Structure Identification Figure 1



1DENTIFICATION 1 Page 1 Jan 20/2005



### **IDENTIFICATION 2 - ELEC/ELEX ACCESS DOOR STRUCTURE**





ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	INTERCOSTAL ANGLE WEB	0.050 0.050	CLAD 2024-T42 CLAD 2024-T42	
2	BEAM TEE WEB	0.050	BAC1505-100910 2024-T3511 CLAD 7075-T6	
3	INTERCOSTAL ANGLE WEB	0.050	BAC1490-2715 CLAD 2024-T42 CLAD 2024-T42	
4	ANGLE		BAC1490-2505 CLAD 2024-T42	
5	INTERCOSTAL ANGLE WEB	0.050	BAC1490-2506 CLAD 2024-T42 CLAD 2024-T42	
6	ZEE		BAC1517-1056 CLAD 2024-T42	
7	ANGLE	0.063	CLAD 2024-T42	
8	FRAME	0.050	CLAD 2024-T42	
9	STOP FITTING		BAC1520-2273 7075-T3511	
10	PLATE	0.080	CLAD 7075-T6	
11	HINGE FITTING		7075-T73 FORGING	

LIST OF MATERIALS FOR DETAIL I A

**Elec/Elex Access Door Structure Identification** Figure 1 (Sheet 2 of 3)




**IDENTIFICATION 2** 

D634N201

 ${\sf BOEING\ PROPRIETARY\ -\ Copyright} \ \textcircled{\ } {\sf Unpublished\ Work\ -\ See\ title\ page\ for\ details}$ 



REFERENCE DRAWING 143N6901





ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	FRAMEWORK		357.0-T6 CASTING AS GIVEN IN BMS 7-330	
2	HINGE FITTING		7075-T73 FORGING AS GIVEN IN BMS 7-186	
3	HINGE ATTACHMENT FITTING		BAC1509-100043 7075-T7351 PLATE (OPTIONAL: 7075-T73511 EXTRUSION)	
4	HINGE ATTACHMENT FITTING		BAC1505-100552 7075-T7351 PLATE (OPTIONAL: 7075-T73511 EXTRUSION)	
5	HANDLE PLATE		7050-T7451 PLATE (OPTIONAL: 7075-T7351 PLATE)	

LIST OF MATERIALS FOR DETAIL II B


Elec/Elex Access Door Structure Identification Figure 1 (Sheet 3 of 3)



1DENTIFICATION 2 Page 3 Jan 20/2005

757-200 STRUCTURAL REPAIR MANUAL

### **IDENTIFICATION 3 - ELEVATOR CONTROL ACCESS DOOR STRUCTURE**



DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	BEAM TEE ANGLE	0.040	BAC1505-101127 7075-T6511 CLAD 2024-T42	
2	GUSSET	0.040	CLAD 2024-T42	
3	CHORD	0.040	CLAD 2024-T42	
4	HINGE		7075-T6 FORGING	

LIST OF MATERIALS FOR DETAIL I

Elevator Control Access Door Structure Identification Figure 1




IDENTIFICATION 3 Page 1 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL

## **IDENTIFICATION 4 - SERVICE AND PRESSURE RELIEF DOOR STRUCTURE**



DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	CHORD	0.040	CLAD 2024-T42	
2	GUSSET	0.040	CLAD 2024-T42	
3	STRINGER ASSY			
	ANGLE	0.040	CLAD 2024-T42	
	TEE		BAC1505-101127 7075-T6511	
4	HINGE		7075-T6 FORGING	

LIST OF MATERIALS FOR DETAIL I

Service and Pressure Relief Door Structure Identification Figure 1




1DENTIFICATION 4 Page 1 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL

### **IDENTIFICATION 5 - HYDRAULIC ACCESS DOOR STRUCTURE**





ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	SKIN PANEL SKIN CORE		ARAMID/GRAPHITE/EPOXY HONEYCOMB SANDWICH SEE DETAIL I NOMEX HONEYCOMB PER BMS 8-124, CLASS IV, TYPE V, GRADE 3.0	
2	CLEVIS		FORGING OR FORGED BLOCK 7075-T73	

LIST OF MATERIALS FOR DETAIL I

Hydraulic Access Door Structure Identification Figure 1 (Sheet 1 of 2)









DIAGRAM OF PLY ORIENTATION. SEE PLY TABLE FOR INDIVIDUAL PLY ORIENTATION AND MATERIAL

VIEW ON DOOR PANEL



ITEM NO.	PLY NO.	MATERIAL	PLY ORIENTATION A
	P101 E	C	
	P101 F	G	
1	P1,P2	в	0° or 90°
	P3,P4, P23,P24	Þ	

MATERIAL AND PLY ORIENTATION SHOWN FOR FIELD AREAS ONLY. SEE BOEING DRAWING FOR EDGEBANDS AND AREAS WITH DOUBLERS

PLY TABLE

DETAIL II

### NOTES

- A PLY ORIENTATION DEGREES INDICATED, IS PARALLEL TO THE FABRIC WARP DIRECTION
- B ARAMID/EPOXY FABRIC PER BMS 8-219, STYLE 120, 250°F (121°C) CURE
- C ALUMINUM COATED FIBERGLASS PER BMS 8-278, TYPE II, CLASS 250, 250°F (121°C) CURE
- GRAPHITE/EPOXY FABRIC PER BMS 8-168, TYPE II, CLASS II, STYLE 3K-70-PW, 250°F (121°C) CURE

- E FOR CUM LINE NUMBERS: 1 THR 316
- F FOR CUM LINE NUMBERS: 317 AND ON
- G ALUMINUM COATED FIBERGLASS PER BMS 8-278, TYPE I, CLASS 250, 250°F (121°C) CURE

Hydraulic Access Door Structure Identification Figure 1 (Sheet 2 of 2)




DENTIFICATION 5 Page 2 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL

### **IDENTIFICATION 6 - APU ACCESS DOOR STRUCTURE**





ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	EDGE MEMBER	0.056	CLAD 2024-T42	
2	FRAME	0.071	CLAD 2024-T42	
3	FRAME	0.05	CLAD 2024-T42	
4	FRAME		BAC1517-334 CLAD 2024-T42	

LIST OF MATERIALS FOR DETAIL I


APU Access Door Structure Identification Figure 1



1DENTIFICATION 6 Page 1 Jan 20/2005



## **IDENTIFICATION 7 - AIR CONDITIONING ACCESS DOOR STRUCTURE**



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	DOOR PANEL SKIN CORE		ARAMID/GRAPHITE/EPOXY HONEYCOMB SANDWICH SEE DETAIL I NOMEX HONEYCOMB PER BMS 8-124, CLASS IV, TYPE V, GRADE 3.0	
2	HINGE FITTING		7075-T73 FORGING	

### LIST OF MATERIALS

#### NOTES

- A PLY ORIENTATION CONVENTION, O DEGREES IS PARALLEL TO THE FABRIC WARP DIRECTION
- B MATERIAL AND PLY ORIENTATION SHOWN FOR FIELD AREAS ONLY. SEE BOEING DRAWINGS FOR EDGE BANDS AND AREAS WITH DOUBLERS
- C DIAGRAM OF PLY ORIENTATION. SEE PLY TABLE FOR PLY ORIENTATION AND MATERIAL
- ARAMID/EPOXY FABRIC PER BMS 8-219, STYLE 120
- E GRAPHITE/EPOXY FABRIC PER BMS 8-168, TYPE II, CLASS II, STYLE 3K-70-PW


- F ARAMID/EPOXY FABRIC PER BMS 8-219, STYLE 285
- G ALUMINUM COATED FIBERGLASS PER BMS 8-278, TYPE II, CLASS 250, 250°F (121°C) CURE
- H FIBERGLASS/EPOXY FABRIC PER BMS 8-79
- TYPE 120
- I ALUMINUM COATED FIBERGLASS PER BMS 8-278, TYPE I, CLASS 250, 250°F (121°C) CURE
- J FOR CUM LINE NUMBERS: 1 THRU 316
- K FOR CUM LINE NUMBERS: 317 AND ON

Air Conditioning Access Door Structure Identification Figure 1 (Sheet 1 of 2)




DENTIFICATION 7 Page 1 Jan 20/2005





LEFT SIDE SHOWN RIGHT SIDE OPPOSITE VIEW ON PANEL C





ITEN NO		PLY NO.	MATERIAL	PLY ORIENTATION A						
		P1 J	G							
		Р1 К	Ι	0° or 90°						
		P2,P67	Þ							
	(7A)	P27	E	±45°						
								P35	E	0° or 90°
7			P28	F	OPTIONAL					
		P34	ш	±45°						
		P1	G	0° or 90°						
		P2	Þ	0° 0K 90°						
	(7B)	P14	H	OPTIONAL						
		P3,P13	E	0° or 90°						
		P4,P12	E	±45°						

## PLY TABLE B

DETAIL I


### Air Conditioning Access Door Structure Identification Figure 1 (Sheet 2 of 2)



1DENTIFICATION 7 Page 2 Jan 20/2005



## **IDENTIFICATION 8 - RAM AIR TURBINE DOOR STRUCTURE**



DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	DOOR PANEL SKIN CORE		ARAMID/GRAPHITE/EPOXY HONEYCOMB SANDWICH SEE DETAIL I NOMEX HONEYCOMB PER BMS 8-124, CLASS IV, TYPE V, GRADE 3.0	
2	HINGE FITTING		7075-T73 FORGING	


LIST OF MATERIALS FOR DETAIL I

Ram Air Turbine Door Structure Identification Figure 1 (Sheet 1 of 2)




1DENTIFICATION 8 Page 1 Jan 20/2005





ITEM NO.	PLY NO.	MATERIAL	PLY ORIENTATION A
	P1,P14	Þ	0° or 90°
	P2,P15 P3,P16	Þ	±45°
_	P17 K	E	
5	P17 L	H	
	P4	E	D° OR 9D°
	P101 I	F	
	P101 J	G	

PLY TABLE 🖪



SECTION THRU HONEYCOMB PANEL

DETAIL I

### NOTES

- A PLY ORIENTATION CONVENTION, DEGREES INDI-CATED PARALLEL TO THE FABRIC WARP DIRECTION
- B MATERIAL AND PLY ORIENTATION SHOWN FOR FIELD AREAS ONLY. SEE BOEING DRAWING FOR EDGE BANDS AND AREAS WITH DOUBLERS
- C DIAGRAM OF PLY ORIENTATION. SEE PLY TABLE FOR INDIVIDUAL PLY ORIENTATION AND MATERIAL
- GRAPHITE/EPOXY FABRIC PER BMS 8-168, TYPE II, CLASS II, STYLE 3K-70-PW, 250°F (121°C) CURE
- E ARAMID/EPOXY FABRIC PER BMS 8-219, STYLE 285, 250°F (121°C) CURE
- F ALUMINUM COATED FIBERGLASS PER BMS 8-278, TYPE II, CLASS 250, 250°F (121°C) CURE

- G ALUMINUM COATED FIBERGLASS PER BMS 8-278, TYPE I, CLASS 250, 250°F (121°C) CURE
- H FIBERGLASS/EPOXY FABRIC PER BMS 8-79 TYPE 120
- I FOR CUM LINE NUMBERS: 1 THRU 316
- J FOR CUM LINE NUMBERS: 317 AND ON
- K FOR CUM LINE NUMBERS: 1 THRU 167
- L FOR CUM LINE NUMBERS: 168 AND ON


Ram Air Turbine Door Structure Identification Figure 1 (Sheet 2 of 2)




DENTIFICATION 8 Page 2 Jan 20/2005



## IDENTIFICATION 9 - SECTION 43 - WING-TO-BODY FAIRING ACCESS DOOR STRUCTURE: AIR CONDITIONING INLET, DRAIN MAST, GROUND AIR CONDITIONING







REF DWG

AIR CONDITIONING INLET ACCESS DOOR

DETAIL I



DRAIN MAST ACCESS DOOR DETAIL II



GROUND AIR CONDITIONING ACCESS DOOR DETAIL III

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	DOOR PANEL		ARAMID/GRAPHITE/EPOXY LAMINATE SEE DETAIL IV	

LIST OF MATERIALS

Section 43 - Wing-to-Body Fairing Access Door Structure Identification: Air Conditioning Inlet, Drain Mast, Ground Air Conditioning Figure 1 (Sheet 1 of 2)

52-40-02

DENTIFICATION 9 Page 1 Jan 20/2005





ITEM NO.	PLY NO.	MATERIAL	PLY ORIENTATION A	
	P1 H P1 I	۵ و	0° or 90°	
	P2	E	±45°	
	P3	F	0° or 90°	
	P4	F		
	Р5	E	±45°	(OUTER SURFACE)
	P6	E	0° or 90°	P1
1	P7	E		
I	P8	E	±45°	
	Р9	E	0° or 90°	
	P10	E	±45°	Ī
	P11	E	0° or 90°	P16
	P12	E	0 08 90	(INNER SURFACE) SECTION THRU PAN
	P13	E	±45°	
	P14	F	0° or 90°	
	P15	F	0.04.90	
	P16	E	±45°	

PLY TABLE B



## NOTES

- A PLY ORIENTATION CONVENTION, DEGREES INDICATED IS PARALLEL TO THE FABRIC WARP DIRECTION
- B MATERIAL AND PLY ORIENTATION SHOWN FOR FIELD AREAS ONLY. SEE BOEING DRAWINGS FOR EDGE BANDS AND AREAS WITH DOUBLERS
- C DIAGRAM OF PLY ORIENTATION, SEE PLY TABLE FOR PLY ORIENTATION AND MATERIAL
- D ALUMINUM COATED FIBERGLASS PER BMS 8-278, TYPE II, CLASS 250, 250°F (121°C) CURE
- E ARAMID/EPOXY FABRIC PER BMS 8-219, STYLE 285, 250°F (121°C) CURE

- F GRAPHITE/EPOXY FABRIC PER BMS 8-168, TYPE II, CLASS II, STYLE 3K-70-PW, 250°F (121°C) CURE
- G ALUMINUM COATED FIBERGLASS PER BMS 8-278, TYPE I, CLASS 250, 250°F (121°C) CURE

PANEL

- H FOR CUM LINE NUMBERS: 1 THUR 193
- I FOR CUM LINE NUMBERS: 194 AND ON

Section 43 - Wing-to-Body Fairing Access Door Structure Identification: Air Conditioning Inlet, Drain Mast, **Ground Air Conditioning** Figure 1 (Sheet 2 of 2)





**IDENTIFICATION 9** Page 2 Jan 20/2005

-P2 THRU P15




## **IDENTIFICATION 10 - LANDING GEAR GROUND ACCESS DOOR STRUCTURE**





DETAIL I



SECTION THRU PANEL

ITEM NO.	PLY NO.	MATERIAL	PLY ORIENTATION A
1	P1 G P1 H	Þ	0° or 90°
	P2 THRU P11	E	

PLY TABLE B



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	DOOR PANEL		ARAMID/EPOXY LAMINATE SEE DETAIL II	

#### LIST OF MATERIALS FOR DETAIL I

## NOTES

- A PLY ORIENTATION CONVENTION, DEGREES INDICATED IS PARALLEL TO THE FABRIC WARP DIRECTION
- B MATERIAL AND PLY ORIENTATION SHOWN FOR FIELD AREAS ONLY, SEE BOEING DRAWINGS FOR EDGE BANDS AND AREAS WITH DOUBLERS
- C DIAGRAM OF PLY ORIENTATION, SEE PLY TABLE FOR PLY ORIENTATION AND MATERIAL
- ALUMINUM COATED FIBERGLASS PER BMS 8-278, TYPE II, CLASS 250, 250°F (121°C) CURE

- E ARAMID/EPOXY FABRIC PER BMS 8-219, STYLE 285, 250°F (121°C) CURE
- F ALUMINUM COATED FIBERGLASS PER BMS 8-278, TYPE I, CLASS 250, 250°F (121°C) CURE
- G FOR CUM LINE NUMBERS: 1 THRU 193
- H FOR CUM LINE NUMBERS:
- 194 AND ON


Landing Gear Ground Access Door Structure Identification Figure 1



1DENTIFICATION 10 Page 1 Jan 20/2005



### **IDENTIFICATION 11 - APU INTAKE PORT - FRAME/DOOR STRUCTURE**



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	FRAME		FIBERGLASS/GRAPHITE/EPOXY LAMINATE FIBERGLASS PLIES - EMS 8-79, TYPE 120 GRAPHITE PLIES - EMS 8-168, TYPE 2, CLASS 2, STYLE 3K-50-PW	
2	BONDED DOOR ASSY		FIBERGLASS/EPOXY HONEYCOMB SANDWICH	
	DOOR		FIBERGLASS CLOTH EPOXY PER BMS 8-79, STYLE 1581, 1584, 7781	
	INNER CORE		NON-METALLIC HONEYCOMB PER BMS 8-124, CLASS I, TYPE III	
	OUTER CORE		NON-METALLIC HONEYCOMB PER BMS 8-124, CLASS IV, TYPE V	
3	ACTUATOR FITTING		ALUMINUM CASTING 356-T6	

LIST OF MATERIALS

## NOTES

A PLY LAYUP AND HONEYCOMB CORE VARY THROUGH-OUT BONDED DOOR AND FRAME ASSEMBLY. SEE ENGINEERING DRAWINGS FOR DOOR AND FRAME CONFIGURATIONS


> APU Intake Port - Frame/Door Structure Identification Figure 1



1DENTIFICATION 11 Page 1 Jan 20/2005




### **IDENTIFICATION 12 - FIN ACCESS DOOR STRUCTURE**



### NOTES

- A PLY ORIENTATION CONVENTION, DEGREES INDICATED IS PARALLEL TO THE FABRIC WARP DIRECTION
- B MATERIAL AND PLY ORIENTATION SHOWN FOR FIELD AREAS ONLY, SEE BOEING DRAWINGS FOR EDGE BANDS AND AREAS WITH DOUBLERS
- C DIAGRAM OF PLY ORIENTATION, SEE PLY TABLE FOR PLY ORIENTATION AND MATERIAL
- ▶ FIBERGLASS/EPOXY FABRIC PER BMS 8-79, TYPE 1581 OR 7781, CLASS III, GRADE 1
- E FOR AIRPLANES WITH CUM LINE NUMBERS 139 AND ON AND AIRPLANES WITH SB 757-53-0038 INCORPORATED




REF DWG 148N3002

DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	DOOR PANEL SKINS CORE		FIBERGLASS/EPOXY HONEYCOMB SANDWICH SEE DETAIL II NONMETALLIC HONEYCOMB PER BMS 8-124 CLASS IV, TYPE 1, GRADE 4.0	E

LIST OF MATERIALS FOR DETAIL I



SECTION THRU PANEL

ITEM NO.	PLY NO.	MATERIAL	PLY A ORIENTATION						
1	P1,P2,P9,P10	D	0° or 90°						
PLY TABLE 🗊									

. . .

DETAIL II


Fin Access Door Structure Identification Figure 1



DENTIFICATION 12 Page 1 Jan 20/2005



### **IDENTIFICATION 13 - TOILET DRAIN ACCESS DOOR STRUCTURE**



DETAIL II

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	DOOR PANEL SKIN		FIBERGLASS/ARAMID/GRAPHITE LAMINATE SEE DETAIL II	
2	STIFFENER	0.050	CLAD 7075-T6	

## LIST OF MATERIALS FOR DETAIL I

### NOTES

- A PLY ORIENTATION CONVENTION, DEGREES INDICATED IS PARALLEL TO THE FABRIC WARP DIRECTION
- B ALUMINUM COATED FIBERGLASS PER BMS 8-278, TYPE II, CLASS 250, 250°F (121°C) CURE
- C ARAMID/EPOXY FABRIC PER BMS 8-219, STYLE 120, 250° (121°C) CURE
- ARAMID/EPOXY FABRIC PER BMS 8-219, STYLE 285, 250°F (121°C) CURE
- E GRAPHITE/EPOXY FABRIC PER BMS 8-168, TYPE II, CLASS II, STYLE 3K-70-PW, 250°F (121°C) CURE
- F MATERIAL AND PLY ORIENTATION SHOWN FOR FIELD AREAS ONLY. SEE BOEING DRAWING FOR EDGE BANDS AND AREAS WITH DOUBLERS

- G DIAGRAM OF PLY ORIENTATION. SEE PLY TABLE FOR INDIVIDUAL PLY ORIENTATION AND MATERIAL
- H FIBERGLASS/EPOXY FABRIC PER BMS 8-79, TYPE 120, 250°F (121°C) CURE
- I ALUMINUM COATED FIBERGLASS PER BMS 8-278, TYPE I, CLASS 250, 250°F (121°C) CURE
- J FOR CUM LINE NUMBERS: 1 THRU 316
- K FOR CUM LINE NUMBERS: 317 AND ON


Toilet Drain Access Door Structure Identification Figure 1



DENTIFICATION 13 Page 1 Jan 20/2005



## ALLOWABLE DAMAGE 1 - RAM AIR TURBINE DOOR



DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES	DELAMINATION	EDGE EROSION
DOOR PANEL	В	C	D	E	F	SEE DETAIL V
HINGE	G	H	NOT ALLOWED	NOT ALLOWED		

Ram Air Turbine Door Figure 101 (Sheet 1 of 3)





BOEING

#### NOTES

- REFINISH REWORKED AREAS AS GIVEN IN AMM 51-20.
- REFER TO SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- TYPICAL DAMAGE TO A PANEL EDGEBAND MAY CONSIST OF EDGE CRUSHING, CRACKS OR DELAMINATION. DAMAGE AROUND HOLES MAY CONSIST OF OVALIZATION, FASTENER PULL-THROUGH OR CRACKS OUT OF HOLE. DAMAGE MAY REDUCE THE EFFECTIVE CROSS-SECTIONAL AREA OF AN EDGEBAND. DAMAGE TO EDGES SHOULD BE BLENDED OUT TO LIMITATIONS GIVEN FOR COMPONENT
- A REMOVE MOISTURE FROM DAMAGE AREA. USE OF VACUUM AND HEAT (MAX OF 125°F) (52°C) TO REMOVE MOISTURE FROM HONEYCOMB CELLS IS RECOMMENDED. PROTECT DAMAGE FROM ENTRANCE OF WATER, SUNLIGHT OR OTHER FOREIGN MATTER BY SEALING WITH ALUMINUM FOIL TAPE (SPEED TAPE). RECORD THE LOCATION AND INSPECT EACH AIRPLANE "A" CHECK. REPLACE THE ALUMINUM FOIL TAPE IF ANY PEELING OR DETERIORATION IS EVIDENT. REPAIR NO LATER THAN NEXT AIRPLANE "C" CHECK
- B 2.0 INCH (50 mm) MAX LENGTH IN HONEYCOMB AREA IS ALLOWED PER SQUARE FOOT (930 SQUARE cm) OF AREA AND A MINIMUM OF 6.0 INCHES (150 mm) FROM ANY OTHER CRACK OR HINGE FITTING. CLEAN UP EDGE CRACKS PER DETAIL I. CRACKS THROUGH CONSECUTIVE FASTENERS OR THROUGH THE PANEL EDGEBAND ARE ALLOWED PROVIDED DAMAGE DOES NOT EXCEED 10% EDGEBAND LENGTH PER SIDE. A

MATERIAL REMOVED AT

CLEANUP OF DAMAGE

DEPTH X = 0.10 INCH

(2.5 mm) MAX

DAMAGE CLEANUP OF EDGES WHERE FASTENER EDGE MARGINS DO NOT OVERLAP

RADIUS DETERMINED BY


(R = 1.00 INCH (25 mm) MIN)

Ð

FASTENER EDGE MARGIN BOUNDARY (REF)

DEPTH X OF DAMAGE

- C DAMAGE ALLOWED ON SURFACE RESIN ONLY. DAMAGE TO FIBERS NOT ALLOWED. CLEAN UP EDGE DAMAGE PER DETAIL I. A
- D DENTS GENERALLY RESULT IN FIBER DAMAGE OR DELAMINATION. HOWEVER, IF THERE IS NO FIBER DAMAGE OR DELAMINATION, DENTS UP TO 1.5 INCH (38 mm) DIA MAX ARE ALLOWED. ONE DENT PER SQUARE FOOT (930 SQUARE cm) OF AREA ALLOWED WHICH MUST BE A MINIMUM OF 6 INCHES (150 mm) FROM ANY OTHER DAMAGE FASTENER HOLE, OR PANEL EDGE. SEE OR F IF FIBER DAMAGE OR DELAMINATION IS PRESENT
- E 1.0 INCH (25 mm) MAX DIA IS ALLOWED PROVIDED IS MIN OF 2.5 D FROM OTHER DAMAGE, NEAREST HOLE, OR MATERIAL EDGE. DO NOT CLEAN UP DAMAGE EXCEPT TO REMOVE RESIN BURRS EXTENDING INTO SURFACE CONTOUR. A
- F 1.0 INCH (25 mm) MAX DIA IS ALLOWED IN HONEYCOMB AREA. A MAXIMUM OF 0.10 INCH (2.5 mm) DELAMINATION FROM EDGE IS ALLOWED. REPAIR DELAMINATION IN HONEYCOMB AREA PER SRM 51-70 NO LATER THAN THE NEXT "C" CHECK. PROTECT EDGE DAMAGE PER A
- G CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAIL I. SHOT PEEN REWORKED AREAS PER SRM 51-20-06. SHOT PEEN INTENSITIES VARY WITH THE THICKNESS REMAINING AFTER REWORK
- H REMOVE CORNER DAMAGE PER DETAIL III. REMOVE LUG DAMAGE PER DETAIL IV. REMOVE OTHER DAMAGE PER DETAIL II. DAMAGE NOT ALLOWED IN VICINITY OF BUSHINGS. SHOT PEEN REWORKED AREAS PER SRM 51-20-06. SHOT PEEN INTENSITIES VARY WITH THE THICKNESS REMAINING AFTER REWORK



DAMAGE CLEANUP OF EDGES WHERE FASTENER EDGE MARGINS OVERLAP

DETAIL I


**Ram Air Turbine Door** Figure 101 (Sheet 2 of 3)



Page 102 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL






Page 103

D634N201 BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



## ALLOWABLE DAMAGE 2 - AIR CONDITIONING ACCESS DOOR



DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES	DELAMINATION	EDGE EROSION
DOOR PANEL	В	C	D	E	F	SEE DETAIL II

Air Conditioning Access Door Figure 101 (Sheet 1 of 3)





BOEING

#### NOTES

- REFINISH REWORKED AREAS AS GIVEN IN • AMM 51-20.
- REFER TO 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- TYPICAL DAMAGE TO A PANEL EDGEBAND MAY CONSIST OF EDGE CRUSHING, CRACKS OR DELAMINATION. DAMAGE AROUND HOLES MAY CONSIST OF OVALIZATION, FASTENER PULL-THROUGH OR CRACKS OUT OF HOLE. DAMAGE MAY REDUCE THE EFFECTIVE CROSS-SECTIONAL AREA OF AN EDGEBAND. DAMAGE TO EDGES SHOULD BE BLENDED OUT TO LIMITATIONS GIVEN FOR COMPONENT
- A REMOVE MOISTURE FROM DAMAGE AREA. USE OF VACUUM AND HEAT (MAX OF 125°F) (52°C) TO REMOVE MOISTURE FROM HONEYCOMB CELLS IS RECOMMENDED. PROTECT DAMAGE FROM ENTRANCE OF WATER, SUNLIGHT OR OTHER FOREIGN MATTER BY SEALING WITH ALUMINUM FOIL TAPE (SPEED TAPE). RECORD THE LOCATION AND INSPECT EACH AIRPLANE "A" CHECK. REPLACE THE ALUMINUM FOIL TAPE IF ANY PEELING OR DETERIORATION IS EVIDENT. REPAIR NO LATER THAN NEXT AIRPLANE "C" CHECK
- B 2.0 INCHES (50 mm) MAX LENGTH IN FACE SHEETS OF HONEYCOMB AREA NOT CLOSER THAN 10 INCHES (250 mm) TO ANY OTHER CRACK. ONE CRACK PER SQUARE FOOT (930 SQUARE cm) OF AREA ALLOWED. FOR CRACKS IN EDGEBAND, 1.0 INCH (25 mm) MAX LENGTH PER SQUARE FOOT (930 SQUARE cm) OF AREA AND A MIN OF 6 INCHES (150 mm) FROM ANY OTHER CRACK. CLEAN UP UP EDGE CRACKS PER DETAIL I. CRACKS THROUGH TWO CONSECUTIVE FASTENERS THROUGH THE EDGEBAND ARE ALLOWED. A


- C DAMAGE ALLOWED ON SURFACE RESIN ONLY. DAMAGE TO FIBERS NOT ALLOWED. CLEAN UP EDGE DAMAGE PER DETAIL I. A
- D DENTS GENERALLY RESULT IN FIBER DAMAGE OR DELAMINATION. HOWEVER, IF THERE IS NO FIBER DAMAGE OR DELAMINATION, DENTS UP TO 1.5 INCH (38 mm) DIA MAX ARE ALLOWED. ONE DENT PER SQUARE FOOT (930 SQUARE cm) OF AREA ALLOWED WHICH MUST BE A MINIMUM OF 6 INCHES (150 mm) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR PANEL EDGE. SEE OR F IF FIBER DAMAGE OR DELAMINATION IS PRESENT
- E 1.0 INCH (25 mm) MAX DIA ALLOWED PROVIDED DAMAGE IS MIN OF 2.5 D FROM OTHER DAMAGE, NEAREST HOLE, OR MATERIAL EDGE. DO NOT CLEAN UP DAMAGE EXCEPT TO REMOVE RESIN BURRS EXTENDING INTO SURFACE CONTOUR. A
- F 1.00 INCH (25 mm) MAX DIA IS ALLOWED IN HONEYCOMB AREA. A MAXIMUM OF 0.10 INCH (2.5 mm) DELAMINATION IN HONEYCOMB AREA PER SRM 51-70 NO LATER THAN THE NEXT "C" CHECK. PROTECT EDGE DAMAGE PER A

**Air Conditioning Access Door** Figure 101 (Sheet 2 of 3)




Page 102





DETAIL I




Air Conditioning Access Door Figure 101 (Sheet 3 of 3)





## ALLOWABLE DAMAGE 3 - HYDRAULIC ACCESS DOOR



DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES	DELAMINATION	EDGE EROSION
DOOR PANEL	В	C	Þ	E	F	SEE DETAIL II

Hydraulic Access Door Figure 101 (Sheet 1 of 3)







#### NOTES

- REFINISH REWORKED AREAS AS GIVEN IN AMM 51-20.
- REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- REFER TO 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- TYPICAL DAMAGE TO A PANEL EDGEBAND MAY CONSIST OF EDGE CRUSHING, CRACKS OR DELAMINATION. DAMAGE AROUND HOLES MAY CONSIST OF OVALIZATION, FASTENER PULL-THROUGH OR CRACKS OUT OF HOLE. DAMAGE MAY REDUCE THE EFFECTIVE CROSS-SECTIONAL AREA OF AN EDGEBAND. DAMAGE TO EDGES SHOULD BE BLENDED OUT TO LIMITATIONS GIVEN FOR COMPONENT
- A REMOVE MOISTURE FROM DAMAGE AREA. USE OF VACUUM AND HEAT (MAX OF 125°F) (52°C) TO REMOVE MOISTURE FROM HONEYCOMB CELLS IS RECOMMENDED. PROTECT DAMAGE FROM ENTRANCE OF WATER, SUNLIGHT OR OTHER FOREIGN MATTER BY SEALING WITH ALUMINUM FOIL TAPE (SPEED TAPE). RECORD THE LOCATION AND INSPECT EACH AIRPLANE "A" CHECK. REPLACE THE ALUMINUM FOIL TAPE IF ANY PEELING OR DETERIORATION IS EVIDENT. REPAIR NO LATER THAN NEXT AIRPLANE "C" CHECK
- B 2.0 INCHES (50 mm) MAX LENGTH IS ALLOWED PER SQUARE FOOT (930 SQUARE cm) OF AREA AND A MINIMUM OF 6.0 INCHES (150 mm) FROM ANY OTHER CRACK. CLEAN UP EDGE CRACKS PER DETAIL IV. CRACKS THROUGH CONSECUTIVE FASTENERS OR THROUGH THE PANEL EDGEBAND ARE ALLOWED PROVIDED DAMAGE DOES NOT EXCEED 10% EDGEBAND LENGTH PER SIDE.


- C DAMAGE ALLOWED ON SURFACE RESIN ONLY. DAMAGE TO FIBERS NOT ALLOWED. CLEAN UP EDGE DAMAGE PER DETAIL I. A
- D DENTS GENERALLY RESULT IN FIBER DAMAGE OR DELAMINATION. HOWEVER, IF THERE IS NO FIBER DAMAGE OR DELAMINATION, DENTS UP TO 1.5 INCHES (38 mm) DIA MAX ARE ALLOWED. ONE DENT PER SQUARE FOOT (930 SQUARE cm) OF AREA ALLOWED WHICH MUST BE A MINIMUM OF 6 INCHES (150 mm) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR PANEL EDGE. SEE OR F IF FIBER DAMAGE OR DELAMINATION IS PRESENT
- E 0.50 INCH (12.7 mm) MAX DIA ALLOWED PROVIDED DAMAGE IS MIN OF 3D FROM OTHER DAMAGE, NEAREST HOLE, OR MATERIAL EDGE. DO NOT CLEAN UP DAMAGE EXCEPT TO REMOVE RESIN BURRS EXTENDING INTO SURFACE CONTOUR. A
- F 1.50 INCHES (38 mm) MAX DIA IS ALLOWED IN HONEYCOMB AREA. A MAXIMUM OF 0.10 INCH (2.5 mm) DELAMINATION FROM EDGE IS ALLOWED. REPAIR DELAMINATION IN HONEYCOMB AREA PER SRM 51-70 NO LATER THAN THE NEXT "C" CHECK. PROTECT EDGE DAMAGE PER A

**Hydraulic Access Door** Figure 101 (Sheet 2 of 3)




Page 102 Jan 20/2005





DETAIL I




Hydraulic Access Door Figure 101 (Sheet 3 of 3)





## ALLOWABLE DAMAGE 4 - SECTION 43 - WING-TO-BODY FAIRING ACCESS DOORS AIR CONDITIONING INLET, DRAIN MAST, GROUND AIR CONDITIONING



DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES	DELAMINATION	EDGE EROSION
DOOR PANEL	В	C	D	E	F	SEE DETAIL V

Section 43 - Wing to Body Fairing Access Doors Air Conditioning Inlet, Drain Mast, Ground Air Conditioning Figure 101 (Sheet 1 of 2)



ALLOWABLE DAMAGE 4 Page 101 Jan 20/2005





#### NOTES

- REFINISH REWORKED AREAS AS GIVEN IN AMM 51-20.
- REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- REFER TO 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- TYPICAL DAMAGE TO A PANEL EDGEBAND MAY CONSIST OF EDGE CRUSHING, CRACKS OR DELAMINATION. DAMAGE AROUND HOLES MAY CONSIST OF OVALIZATION, FASTENER PULL-THROUGH OR CRACKS OUT OF HOLE. DAMAGE MAY REDUCE THE EFFECTIVE CROSS-SECTIONAL AREA OF AN EDGEBAND. DAMAGE TO EDGES SHOULD BE BLENDED OUT TO LIMITATIONS GIVEN FOR COMPONENT
- A REMOVE MOISTURE FROM DAMAGE AREA. USE OF VACUUM AND HEAT (MAX OF 125°F) (52°C) TO REMOVE MOISTURE FROM HONEYCOMB CELLS IS RECOMMENDED. PROTECT DAMAGE FROM ENTRANCE OF WATER, SUNLIGHT OR OTHER FOREIGN MATTER BY SEALING WITH ALUMINUM FOIL TAPE (SPEED TAPE). RECORD THE LOCATION AND INSPECT EACH AIRPLANE "A" CHECK. REPLACE THE ALUMINUM FOIL TAPE IF ANY PEELING OR DETERIORATION IS EVIDENT. REPAIR NO LATER THAN NEXT AIRPLANE "C" CHECK
- B 2.0 INCHES (50 mm) MAX LENGTH IS ALLOWED PER SQUARE FOOT (930 SQUARE cm) OF AREA AND A MINIMUM OF 6.0 INCHES (150 mm) FROM ANY OTHER CRACK. CLEAN UP EDGE CRACKS PER DETAIL IV. CRACKS THROUGH CONSECUTIVE FASTENERS OR THROUGH THE PANEL EDGEBAND ARE ALLOWED PROVIDED DAMAGE DOES NOT EXCEED 10% EDGEBAND LENGTH PER SIDE. A


- C DAMAGE ALLOWED ON SURFACE RESIN ONLY. DAMAGE TO FIBERS NOT ALLOWED. CLEAN UP EDGE DAMAGE PER DETAIL IV. A
- D 0.50 INCH (12.7 mm) MAX DIA ALLOWED PROVIDED DAMAGE IS MIN OF 3.0 D FROM OTHER DAMAGE, NEAREST HOLE, OR MATERIAL EDGE. DO NOT CLEAN UP DAMAGE EXCEPT TO REMOVE RESIN BURRS EXTENDING INTO SURFACE CONTOUR. A
- E 1.00 INCH (25 mm) MAX DIA IS ALLOWED. A MAXIMUM OF 0.10 INCH (2.5 mm) DELAMINATION FROM EDGE IS ALLOWED. PROTECT EDGE DAMAGE PER A
- F DENTS GENERALLY RESULT IN FIBER DAMAGE OR DELAMINATION. HOWEVER, IF THERE IS NO FIBER DAMAGE OR DELAMINATION, DENTS UP TO 1.5 INCHES (38 mm) DIA MAX ARE ALLOWED. ONE DENT PER SQUARE FOOT (930 SQUARE cm) OF AREA ALLOWED WHICH MUST BE A MINIMUM OF 6 INCHES (150 mm) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR PANEL EDGE. SEE D OR E IF FIBER DAMAGE OR DELAMINATION IS PRESENT

Section 43 - Wing to Body Fairing Access Doors Air Conditioning Inlet, Drain Mast, Ground Air Conditioning Figure 101 (Sheet 2 of 2)





## ALLOWABLE DAMAGE 5 - LANDING GEAR GROUND ACCESS DOOR



DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES	DELAMINATION	EDGE EROSION
DOOR PANEL	В	C	D	E	F	SEE DETAIL II

Landing Gear Ground Access Door Figure 101 (Sheet 1 of 3)







#### NOTES

- REFINISH REWORKED AREAS AS GIVEN IN AMM 51-20.
- REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- REFER TO 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- TYPICAL DAMAGE TO A PANEL EDGEBAND MAY CONSIST OF EDGE CRUSHING, CRACKS OR DELAMINATION. DAMAGE AROUND HOLES MAY CONSIST OF OVALIZATION, FASTENER PULL-THROUGH OR CRACKS OUT OF HOLE. DAMAGE MAY REDUCE THE EFFECTIVE CROSS-SECTIONAL AREA OF AN EDGEBAND. DAMAGE TO EDGES SHOULD BE BLENDED OUT TO LIMITATIONS GIVEN FOR COMPONENT
- A REMOVE MOISTURE FROM DAMAGE AREA. USE OF VACUUM AND HEAT (MAX OF 125°F) (52°C) TO REMOVE MOISTURE FROM HONEYCOMB CELLS IS RECOMMENDED. PROTECT DAMAGE FROM ENTRANCE OF WATER, SUNLIGHT OR OTHER FOREIGN MATTER BY SEALING WITH ALUMINUM FOIL TAPE (SPEED TAPE). RECORD THE LOCATION AND INSPECT EACH AIRPLANE "A" CHECK. REPLACE THE ALUMINUM FOIL TAPE IF ANY PEELING OR DETERIORATION IS EVIDENT. REPAIR NO LATER THAN NEXT AIRPLANE "C" CHECK
- B 2.0 INCHES (50 mm) MAX LENGTH IS ALLOWED PER SQUARE FOOT (930 SQUARE cm) OF AREA AND A MINIMUM OF 6.0 INCHES (150 mm) FROM ANY OTHER CRACK. CLEAN UP EDGE CRACKS PER DETAIL I. CRACKS THROUGH CONSECUTIVE FASTENERS OR THROUGH THE PANEL EDGEBAND ARE ALLOWED PROVIDED DAMAGE DOES NOT EXCEED 10% EDGEBAND LENGTH PER SIDE. A


- C DAMAGE ALLOWED ON SURFACE RESIN ONLY. DAMAGE TO FIBERS NOT ALLOWED. CLEAN UP EDGE DAMAGE PER DETAIL I. A
- D 0.50 INCH (12.7 mm) MAX DIA ALLOWED PROVIDED DAMAGE IS MIN OF 3.0 D FROM OTHER DAMAGE, NEAREST HOLE, OR MATERIAL EDGE. DO NOT CLEAN UP DAMAGE EXCEPT TO REMOVE RESIN BURRS EXTENDING INTO SURFACE CONTOUR. A
- E 1.00 INCH (25 mm) MAX DIA IS ALLOWED. A MAXIMUM OF 0.10 INCH (2.5 mm) DELAMINATION FROM EDGE IS ALLOWED. PROTECT EDGE DAMAGE PER A
- F DENTS GENERALLY RESULT IN FIBER DAMAGE OR DELAMINATION. HOWEVER, IF THERE IS NO FIBER DAMAGE OR DELAMINATION, DENTS UP TO 1.5 INCHES (38 mm) DIA MAX ARE ALLOWED. ONE DENT PER SQUARE FOOT (930 SQUARE cm) OF AREA ALLOWED WHICH MUST BE A MINIMUM OF 6 INCHES (150 mm) FROM ANY OTHER DAMAGE FASTENER HOLE, OR PANEL EDGE. SEE D OR E IF FIBER DAMAGE OR DELAMINATION IS PRESENT

Landing Gear Ground Access Door Figure 101 (Sheet 2 of 3)




Page 102





DETAIL I




Landing Gear Ground Access Door Figure 101 (Sheet 3 of 3)






## **ALLOWABLE DAMAGE 6 - FIN ACCESS DOOR**



REF DWG 148N3002





DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES	DELAMINATION	EDGE EROSION
DOOR PANEL	В	C	D	E	F	SEE DETAIL III

Fin Access Door Figure 101 (Sheet 1 of 3)







#### NOTES

- REFINISH REWORKED AREAS AS GIVEN IN • AMM 51-20.
- REFER TO 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- TYPICAL DAMAGE TO A PANEL EDGEBAND MAY CONSIST OF EDGE CRUSHING, CRACKS OR DELAMINATION. DAMAGE AROUND HOLES MAY CONSIST OF OVALIZATION, FASTENER PULL-THROUGH OR CRACKS OUT OF HOLE. DAMAGE MAY REDUCE THE EFFECTIVE CROSS-SECTIONAL AREA OF AN EDGEBAND. DAMAGE TO EDGES SHOULD BE BLENDED OUT TO LIMITATIONS GIVEN FOR COMPONENT
- A REMOVE MOISTURE FROM DAMAGE AREA. USE OF VACUUM AND HEAT (MAX OF 125°F) (52°C) TO REMOVE MOISTURE FROM HONEYCOMB CELLS IS RECOMMENDED. PROTECT DAMAGE FROM ENTRANCE OF WATER, SUNLIGHT OR OTHER FOREIGN MATTER BY SEALING WITH ALUMINUM FOIL TAPE (SPEED TAPE). RECORD THE LOCATION AND INSPECT EACH AIRPLANE "A" CHECK. REPLACE THE ALUMINUM FOIL TAPE IF ANY PEELING OR DETERIORATION IS EVIDENT. REPAIR NO LATER THAN NEXT AIRPLANE "C" CHECK
- B 2.0 INCHES (50 mm) MAX LENGTH IN FACE SHEETS OF HONEYCOMB AREA NOT CLOSER THAN 10 INCHES (250 mm) TO ANY OTHER CRACK. ONE CRACK PER SQUARE FOOT (930 SQUARE cm) OF AREA ALLOWED. FOR CRACKS IN EDGEBAND, 1.0 INCH (25 mm) MAX LENGTH PER SQUARE FOOT (930 SQUARE cm) OF AREA AND A MIN OF 6 INCHES (150 mm) FROM ANY OTHER CRACK. CLEAN UP EDGE CRACKS PER DETAIL II. CRACKS THROUGH TWO CONSECUTIVE FASTENERS THROUGH THE EDGEBAND ARE ALLOWED. A


- C DAMAGE ALLOWED ON SURFACE RESIN ONLY. DAMAGE TO FIBERS NOT ALLOWED. CLEAN UP EDGE DAMAGE PER DETAIL II. A
- D DENTS GENERALLY RESULT IN FIBER DAMAGE OR DELAMINATION. HOWEVER, IF THERE IS NO FIBER DAMAGE OR DELAMINATION, DENTS UP TO 1.5 INCH (38 mm) DIA MAX ARE ALLOWED. ONE DENT PER SQUARE FOOT (930 SQUARE cm) OF AREA ALLOWED WHICH MUST BE A MINIMUM OF 6 INCHES (150 mm) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR PANEL EDGE. SEE E OR F IF FIBER DAMAGE OR DELAMINATION IS PRESENT
- E 1.0 INCH (25 mm) MAX DIA IS ALLOWED PROVIDED IS MIN OF 2.5 D FROM OTHER DAMAGE, NEAREST HOLE, OR MATERIAL EDGE. DO NOT CLEAN UP DAMAGE EXCEPT TO REMOVE RESIN BURRS EXTENDING INTO SURFACE CONTOUR.
- F 1.0 INCH (25 mm) MAX DIA IS ALLOWED IN HONEYCOMB AREA. A MAXIMUM OF 0.10 INCH (2.5 mm) DELAMINATION FROM EDGE IS ALLOWED. REPAIR DELAMINATION IN HONEYCOMB AREA PER SRM 51-70 NO LATER THAN THE NEXT "C" CHECK. PROTECT EDGE DAMAGE PER A

Fin Access Door Figure 101 (Sheet 2 of 3)




Page 102





DETAIL II




Fin Access Door Figure 101 (Sheet 3 of 3)





## ALLOWABLE DAMAGE 7 - APU ACCESS DOOR STRUCTURE



DETAIL I

APU Access Door Structure Figure 101 (Sheet 1 of 5)





DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES
FRAME	В	C	SEE DETAIL IV	E
HINGE	A	D	NOT PERMITTED	NOT PERMITTED
EDGE MEMBER	В	C	SEE DETAIL IV	E

ALLOWABLE DAMAGE FOR DETAIL I


#### NOTES

- REFINISH REWORKED AREAS AS GIVEN IN AMM 51-20.
- A REMOVE EDGE CRACKS AS GIVEN IN DETAILS II AND VIII. CRACKS ON THE LUG ARE NOT PERMITTED.
- B REMOVE EDGE CRACKS AS GIVEN IN DETAILS II, VI AND X. FOR RADIUS CRACKS THAT ARE NOT MORE THAN 1.0 INCH IN LENGTH, SEE DETAIL X.
- C REMOVE DAMAGE AS GIVEN IN DETAILS II, III, V, AND VII.
- D FOR EDGE DAMAGE SEE DETAIL II. FOR LUG DAMAGE, SEE DETAIL IX. FOR OTHER DAMAGE, SEE DETAIL II. DAMAGE NOT PERMITTED IN AREA OF BUSHINGS.
- E CLEAN OUT DAMAGE UP TO 0.25 MAXIMUM DIAMETER AND NOT CLOSER THAN 1.0 INCH TO FASTENER HOLE, MATERIAL EDGE, OR OTHER DAMAGE. FILL HOLE WITH 2117-T3 OR T4 ALUMINUM RIVET. ALL OTHER HOLES MUST BE REPAIRED.

**APU Access Door Structure** Figure 101 (Sheet 2 of 5)



Page 102 Jan 20/2005




APU Access Door Structure Figure 101 (Sheet 3 of 5)





757-200 STRUCTURAL REPAIR MANUAL




APU Access Door Structure Figure 101 (Sheet 4 of 5)






757-200 STRUCTURAL REPAIR MANUAL



DAMAGE CLEANUP FOR EDGES OF LUG DETAIL IX



X = WIDTH OF THE MATERIAL THAT IS REMOVED A MAXIMUM OF 0.10 INCH

#### REMOVAL OF DAMAGED MATERIAL ON AN EDGE

DETAIL X

APU Access Door Structure Figure 101 (Sheet 5 of 5)




D634N201

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



## ALLOWABLE DAMAGE 8 - TOILET DRAIN ACCESS DOOR

REF DWG 149N7702



DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES	DELAMINATION	EDGE EROSION
DOOR PANEL	В	C	D	E	F	SEE DETAIL II

Toilet Drain Access Door Figure 101 (Sheet 1 of 3)







#### NOTES

- REFINISH REWORKED AREAS AS GIVEN IN AMM 51-20.
- REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- REFER TO 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- TYPICAL DAMAGE TO A PANEL EDGEBAND MAY CONSIST OF EDGE CRUSHING, CRACKS OR DELAMINATION. DAMAGE AROUND HOLES MAY CONSIST OF OVALIZATION, FASTENER PULL-THROUGH OR CRACKS OUT OF HOLE. DAMAGE MAY REDUCE THE EFFECTIVE CROSS-SECTIONAL AREA OF AN EDGEBAND. DAMAGE TO EDGES SHOULD BE BLENDED OUT TO LIMITATIONS GIVEN FOR COMPONENT
- A REMOVE MOISTURE FROM DAMAGE AREA. USE OF VACUUM AND HEAT (MAX OF 125°F) (52°C) TO REMOVE MOISTURE FROM HONEYCOMB CELLS IS RECOMMENDED. PROTECT DAMAGE FROM ENTRANCE OF WATER, SUNLIGHT OR OTHER FOREIGN MATTER BY SEALING WITH ALUMINUM FOIL TAPE (SPEED TAPE). RECORD THE LOCATION AND INSPECT EACH AIRPLANE "A" CHECK. REPLACE THE ALUMINUM FOIL TAPE IF ANY PEELING OR DETERIORATION IS EVIDENT. REPAIR NO LATER THAN NEXT AIRPLANE "C" CHECK
- B 2.0 INCHES (50 mm) MAX LENGTH IS ALLOWED PER SQUARE FOOT (930 SQUARE cm) OF AREA AND A MINIMUM OF 6.0 INCHES (150 mm) FROM ANY OTHER CRACK. CLEAN UP EDGE CRACKS PER DETAIL I. CRACKS THROUGH CONSECUTIVE FASTENERS OR THROUGH THE PANEL EDGEBAND ARE ALLOWED PROVIDED DAMAGE DOES NOT EXCEED 10% EDGEBAND LENGTH PER SIDE. A


- C DAMAGE ALLOWED ON SURFACE RESIN ONLY. DAMAGE TO FIBERS NOT ALLOWED. CLEAN UP EDGE DAMAGE PER DETAIL I. A
- D 0.50 INCH (12.7 mm) MAX DIA ALLOWED PROVIDED DAMAGE IS MIN OF 3.0 D FROM OTHER DAMAGE, NEAREST HOLE, OR MATERIAL EDGE. DO NOT CLEAN UP DAMAGE EXCEPT TO REMOVE RESIN BURRS EXTENDING INTO SURFACE CONTOUR. A
- E 1.00 INCH (25 mm) MAX DIA IS ALLOWED. A MAXIMUM OF 0.10 INCH (2.5 mm) DELAMINATION FROM EDGE IS ALLOWED. PROTECT EDGE DAMAGE PER A
- F DENTS GENERALLY RESULT IN FIBER DAMAGE OR DELAMINATION. HOWEVER, IF THERE IS NO FIBER DAMAGE OR DELAMINATION, DENTS UP TO 1.5 INCHES (38 mm) DIA MAX ARE ALLOWED. ONE DENT PER SQUARE FOOT (930 SQUARE cm) OF AREA ALLOWED WHICH MUST BE A MINIMUM OF 6 INCHES (150 mm) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR PANEL EDGE. SEE D OR E IF FIBER DAMAGE OR DELAMINATION IS PRESENT

**Toilet Drain Access Door** Figure 101 (Sheet 2 of 3)




Page 102





DETAIL I




Toilet Drain Access Door Figure 101 (Sheet 3 of 3)





## **REPAIR 1 - HYDRAULIC ACCESS DOOR REPAIRS**



Hydraulic Access Door Repairs Figure 201 (Sheet 1 of 3)



REPAIR 1 Page 201 Jan 20/2005



	INTERIM REPAIRS B		PERMANENT REPAIRS	
DAMAGE	WET LAYUP ROOM TEMP (SRM 51-70-03)	WET LAYUP 150°F (66°C) CURE (SRM 51-70-03)	WET LAYUP 200°F (93°C) CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-05)
CRACKS	UP TO 4.0 INCHES (100 mm) LONG, REPAIR WITH PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE
HOLES AND PUNC- TURES	4.0 INCHES (100 mm) MAXIMUM DIA NOT TO EXCEED 30% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	8.0 INCHES (200mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH FACESHEET REPAIRED C	12.0 INCHES (300 mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH FACESHEET REPAIRED C	NO SIZE LIMIT
DELAMI- NATION	CUT OUT AND REPAIR AS A HOLE			
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE			
DENTS	POTTING COMPOUND AND PA	TCH AS GIVEN IN SRM 51-7	AGE OR DELAMINATION, FILM 20-03, PAR. 5.L. C SE OR DELAMINATION, REPA	,

### REPAIR DATA FOR 250°F (121°C) CURE HONEYCOMB PANELS (GRAPHITE AND/OR ARAMID) TABLE I

#### NOTES

- WHEN YOU USE THIS REPAIR, REFER TO:
  - AMM 51-21-01 FOR APPLICATION OF FINISHES
  - SRM 51-10-01, FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE IS MORE THAN THE LIMITS GIVEN IN SRM 51-10-01, THOUGHT SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE THAT MAY OCCUR.
- A LIMITED TO REPAIR OF DAMAGE TO ONE FACESHEET SKIN AND HONEYCOMB CORE. ONE REPAIR FOR EACH SQUARE FOOT (930 SQUARE cm) OF AREA AND MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, EDGE OF PANEL OR A MINIMUM OF 2.0 INCHES (50 mm) FROM TAPERED EDGE OF HONEYCOMB CORE
- B INSPECT INTERIM REPAIR USING INSTRUMENTED NDT METHODS OR "TAP" TEST EVERY AIRPLANE AT "2A" CHECK. FOR "TAP" TEST, USE A SOLID METAL DISK AND TAP THE REPAIR AREA LIGHTLY BUT FIRMLY. VOID AREAS WILL GIVE A DULL SOUND INSTEAD OF A SHARP RING THAT YOU WILL HEAR ON A SOLID BONDED AREA. PERMANENT REPAIR IS REQUIRED IF ANY DETERIORATION IS FOUND. REFER TO SRM 51-70-03, PAR. 4.I. AND THE NONDESTRUCTIVE TEST MANUAL D

C ONE REPAIR FOR EACH SQUARE FOOT OF AREA AND A MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, EDGE OF PANEL, OR A MINIMUM OF 2.0 INCHES (50 mm) FROM TAPERED EDGE OF HONEYCOMB CORE

THIS REPAIR HAS FAA APPROVAL ONLY IF YOU DO THE INSPECTIONS GIVEN IN THIS REPAIR

Hydraulic Access Door Repairs Figure 201 (Sheet 2 of 3)




REPAIR 1 Page 202 Jan 20/2005



	INTERIM REPAIRS B	PERMANENT	REPAIRS	
DAMAGE	ROOM TEMP (SRM 51-70-03)	WET LAYUP - 200°F (93°C) CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-05)	
HOLES AND PUNCTURES	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-03, PAR. 5.K. B FOR ALL OTHER DAMAGE UP TO 10% OF THE EDGEBAND LENGTH, REPAIR AS GIVEN IN SRM 51-70-03, PAR. 5.G.	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-17, PAR. 4.K. FOR ALL OTHER DAMAGE, REPAIR AS GIVEN IN SRM 51-70-17, PAR. 4.G.	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-05, PAR. 5.K. FOR ALL OTHER DAMAGE, REPAIR AS GIVEN IN SRM 51-70-05, PAR. 5.G.	
DELAM- INATION	IF DELAMINATION IS NO LESS THAN 2D FROM ANY FASTENER HOLE OR PANEL EDGE, REPAIR AS GIVEN IN SRM 51-70-03, PAR. 5.A.(2). ANY OTHER DELAMINATION MUST BE CUT OUT AND REPAIRED AS A HOLE	CUT OUT AND REPAIR AS A HOLE	CUT OUT AND REPAIR AS A HOLE	
EDGE EROSION		FOR DAMAGE NOT THAT IS LARGER THICKNESS, REPAIR AS GIVEN IN LARGER DAMAGE, REPAIR AS GIVE	SRM 51-70-03, PAR. 5.0. FOR	
		SRM 51-70-17, PAR. 4.G.	SRM 51-70-05, PAR. 5.G.	
CRACKS	REPAIR AS A HOLE			
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE OR DELAMINATION, WHICHEVER IS APPLICABLE			
DENTS	IF THERE IS NO FIBER DAMAGE OR IF YOU FIND FIBER DAMAGE OR DEL WHICHEVER IS APPLICABLE			

### REPAIR DATA FOR EDGEBANDS OF 250°F (121°C) CURE HONEYCOMB PANELS (GRAPHITE AND/OR ARAMID) TABLE II


Hydraulic Access Door Repairs Figure 201 (Sheet 3 of 3)



**REPAIR 1** 



### **REPAIR 2 - AIR CONDITIONING ACCESS DOOR REPAIRS**



Air Conditioning Access Door Repairs Figure 201 (Sheet 1 of 3)



REPAIR 2 Page 201 Jan 20/2005





	INTERIM REPAIRS B		PERMANENT REPAIRS	
DAMAGE	WET LAYUP ROOM TEMP (SRM 51-70-03)	WET LAYUP 150°F (66°C) CURE (SRM 51-70-03)	WET LAYUP 200°F (93°C) CURE (SRM 51-70-17)	250°F (121°C)CURE (SRM 51-70-05)
CRACKS	UP TO 4.0 INCHES (100 mm) LONG, REPAIR WITH PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE
HOLES	4.0 INCHES MAXIMUM (100 mm) DIA NOT TO EXCEED 30% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	8.0 INCHES MAXIMUM (200 mm) DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH FACESHEET REPAIRED C	DIMENSION ACROSS	NO SIZE LIMIT
DELAMI- NATION	CUT OUT AND REPAIR AS A HOLE			
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE			
DENTS	UP TO 2.0 INCHES (50 mm) DIA WITH NO FIBER DAMAGE OR DELAMINATION, FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.L. C OVER 2.0 INCHES (50 mm) DIA OR WITH FIBER DAMAGE OR DELAMINATION, REPAIR AS A HOLE			

#### REPAIR DATA FOR 250°F (121°C) CURE HONEYCOMB PANELS (GRAPHITE AND/OR ARAMID) TABLE I

#### NOTES

- WHEN YOU USE THIS REPAIR, REFER TO:
  - SRM 51-10-01, FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE IS MORE THAN THE LIMITS GIVEN IN SRM 51-10-01, THOUGHT SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE THAT MAY OCCUR.

- AMM 51-21-01 FOR APPLICATION OF FINISHES

- A LIMITED TO REPAIR OF DAMAGE TO ONE FACESHEET SKIN AND HONEYCOMB CORE. ONE REPAIR FOR EACH SQUARE FOOT (930 SQUARE cm) OF AREA AND MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, EDGE OF PANEL OR A MINIMUM OF 2.0 INCHES (50 mm) FROM TAPERED EDGE OF HONEYCOMB CORE
- B INSPECT INTERIM REPAIR USING INSTRUMENTED NDT METHODS OR "TAP" TEST EVERY AIRPLANE AT "2A" CHECK. FOR "TAP" TEST, USE A SOLID METAL DISK AND TAP THE REPAIR AREA LIGHTLY BUT FIRMLY. VOID AREAS WILL GIVE A DULL SOUND INSTEAD OF A SHARP RING THAT YOU WILL HEAR ON A SOLID BONDED AREA. PERMANENT REPAIR IS REQUIRED IF ANY DETERIORATION IS FOUND. REFER TO SRM 51-70-03, PAR. 4.I. AND THE NONDESTRUCTIVE TEST MANUAL D
- C ONE REPAIR FOR EACH SQUARE FOOT (930 SQUARE cm) OF AREA AND A MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, EDGE OF PANEL, OR A MINIMUM OF 2.0 INCHES (50 mm) FROM TAPERED EDGE OF HONEYCOMB CORE
- THIS REPAIR HAS FAA APPROVAL ONLY IF YOU DO THE INSPECTIONS GIVEN IN THIS REPAIR

Air Conditioning Access Door Repairs Figure 201 (Sheet 2 of 3)



REPAIR 2 Page 202 Jan 20/2005



	INTERIM REPAIRS B	PERMANENT	REPAIRS	
DAMAGE	ROOM TEMP (SRM 51-70-03)	WET LAYUP - 200°F (93°C) CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-05)	
HOLES AND PUNCTURES	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN 51-70-03, PAR. 5.K. FOR ALL OTHER DAMAGE UP TO 10% OF THE EDGEBAND LENGTH, REPAIR AS GIVEN IN SRM 51-70-03, PAR. 5.G.	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN 51-70-17, PAR. 4.K. FOR ALL OTHER DAMAGE, REPAIR AS GIVEN IN SRM 51-70-17, PAR. 4.G.	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-05, PAR. 5.K. FOR ALL OTHER DAMAGE, REPAIR AS GIVEN IN SRM 51-70-05, PAR. 5.G.	
DELAM- INATION	IF DELAMINATION IS NO LESS THAN 2D FROM ANY FASTENER HOLE OR PANEL EDGE, REPAIR AS GIVEN IN SRM 51-70-03, PAR. 5.A.(2). ANY OTHER DELAMINATION MUST BE CUT OUT AND REPAIRED AS A HOLE	CUT OUT AND REPAIR AS A HOLE	CUT OUT AND REPAIR AS A HOLE	
EDGE EROSION		FOR DAMAGE NOT THAT IS LARGER THICKNESS, REPAIR AS GIVEN IN LARGER DAMAGE, REPAIR AS GIVEN	SRM 51-70-03, PAR. 5.0. FOR	
		SRM 51-70-17, PAR. 4.G.	SRM 51-70-05, PAR. 5.G.	
CRACKS	REPAIR AS A HOLE			
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE OR DELAMINATION, WHICHEVER IS APPLICABLE			
DENTS	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL DENTS AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE OR DELAMINATION, WHICHEVER IS APPLICABLE			

### REPAIR DATA FOR EDGEBANDS OF 250°F (121°C) CURE HONEYCOMB PANELS (GRAPHITE AND/OR ARAMID) TABLE II


Air Conditioning Access Door Repairs Figure 201 (Sheet 3 of 3)



**REPAIR 2** 



### **REPAIR 3 - RAM AIR TURBINE DOOR REPAIRS**



Ram Air Turbine Door Repairs Figure 201 (Sheet 1 of 3)



REPAIR 3 Page 201 Jan 20/2005





	INTERIM REPAIRS		PERMANENT REPAIRS	
DAMAGE	WET LAYUP ROOM TEMP (SRM 51-70-03)	WET LAYUP 150°F (66°C) CURE (SRM 51-70-03)	WET LAYUP 200°F (93°C) CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-05)
CRACKS	UP TO 4.0 INCHES (100 mm) LONG, REPAIR WITH PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE
HOLES	4.0 INCHES (100 mm) MAXIMUM DIA NOT TO EXCEED 30% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	SMALLEST DIMENSION	12.0 INCHES (300 mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH FACESHEET REPAIRED C	NO SIZE LIMIT
DELAMI- NATION	CUT OUT AND REPAIR AS HOLE			
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE			
DENTS	UP TO 2.0 INCHES (50 mm) DIA WITH NO FIBER DAMAGE OR DELAMINATION, FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.L. C OVER 2.0 INCHES (50 mm) DIA OR WITH FIBER DAMAGE OR DELAMINATION, REPAIR AS A HOLE			

#### REPAIR DATA FOR 250°F (121°C) CURE HONEYCOMB PANELS (GRAPHITE AND/OR ARAMID) TABLE I

#### NOTES

- WHEN YOU USE THIS REPAIR, REFER TO:
  - SRM 51-10-01, FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE IS MORE THAN THE LIMITS GIVEN IN SRM 51-10-01, THOUGHT SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE THAT MAY OCCUR.

- AMM 51-21-01 FOR APPLICATION OF FINISHES

- A LIMITED TO REPAIR OF DAMAGE TO ONE FACESHEET SKIN AND HONEYCOMB CORE. ONE REPAIR FOR EACH SQUARE FOOT (930 SQUARE cm) OF AREA AND MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, EDGE OF PANEL OR A MINIMUM OF 2.0 INCHES (50 mm) FROM TAPERED EDGE OF HONEYCOMB CORE
- B INSPECT INTERIM REPAIR USING INSTRUMENTED NDT METHODS OR "TAP" TEST EVERY AIRPLANE AT "2A" CHECK. FOR "TAP" TEST, USE A SOLID METAL DISK AND TAP THE REPAIR AREA LIGHTLY BUT FIRMLY. VOID AREAS WILL GIVE A DULL SOUND INSTEAD OF A SHARP RING THAT YOU WILL HEAR ON A SOLID BONDED AREA. PERMANENT REPAIR IS REQUIRED IF ANY DETERIORATION IS FOUND. REFER TO SRM 51-70-03, PAR. 4.I. AND THE NONDESTRUCTIVE TEST MANUAL D
- C ONE REPAIR FOR EACH SQUARE FOOT (930 SQUARE cm) OF AREA AND A MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, EDGE OF PANEL, OR A MINIMUM OF 2.0 INCHES (50 mm) FROM TAPERED EDGE OF HONEYCOMB CORE
- THIS REPAIR HAS FAA APPROVAL ONLY IF YOU DO THE INSPECTIONS GIVEN IN THIS REPAIR

Ram Air Turbine Door Repairs Figure 201 (Sheet 2 of 3)




REPAIR 3 Page 202 Jan 20/2005



	INTERIM REPAIRS 🖪	PERMANENT	REPAIRS
DAMAGE	ROOM TEMP (SRM 51-70-03)	WET LAYUP - 200°F (93°C) CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-05)
HOLES AND PUNCTURES	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-03, PAR. 5.K. FOR ALL OTHER DAMAGE UP TO 10% OF THE EDGEBAND LENGTH, REPAIR AS GIVEN IN SRM 51-70-03, PAR. 5.G.	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-17, PAR. 4.K. FOR ALL OTHER DAMAGE, REPAIR AS GIVEN IN SRM 51-70-17, PAR. 4.G.	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-05, PAR. 5.K. FOR ALL OTHER DAMAGE, REPAIR AS GIVEN IN SRM 51-70-05, PAR. 5.G.
DELAM- INATION	IF DELAMINATION IS NO LESS THAN 2D FROM ANY FASTENER HOLE OR PANEL EDGE, REPAIR AS GIVEN IN SRM 51-70-03, PAR. 5.A.(2). ANY OTHER DELAMINATION MUST BE CUT OUT AND REPAIRED AS A HOLE	CUT OUT AND REPAIR AS A HOLE	CUT OUT AND REPAIR AS A HOLE
EDGE EROSION		FOR DAMAGE NOT LARGER THAN 35% AS GIVEN IN SRM 51-70-03, PAR. AS GIVEN IN: SRM 51-70-17, PAR. 4.G.	OF EDGEBAND THICKNESS, REPAIR 5.0 FOR LARGER DAMAGE, REPAIR SRM 51-70-05, PAR. 5.G.
CRACKS	REPAIR AS A HOLE	SKH 51 10 11, TAK. 4.G.	SINT 51 10 05, TAK. 5.0.
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE OR DELAMINATION, WHICHEVER IS APPLICABLE		
DENTS		DELAMINATION, FILL DENTS AS GIV LAMINATION, THEN REPAIR AS A HO	

### REPAIR DATA FOR EDGEBANDS OF 250°F (121°C) CURE HONEYCOMB PANELS (GRAPHITE AND/OR ARAMID) TABLE II


Ram Air Turbine Door Repairs Figure 201 (Sheet 3 of 3)




**REPAIR 3** 



### REPAIR 4 - SECTION 43 - WING TO BODY FAIRING ACCESS DOOR REPAIRS - AIR CONDITIONING INLET, DRAIN MAST, GROUND AIR CONDITIONING





Section 43 - Wing to Body Fairing Access Door Repairs - Air Conditioning Inlet, Drain Mast, Ground Air Conditioning Figure 201 (Sheet 1 of 3)



REPAIR 4 Page 201 Jan 20/2005



	INTERIM REPAIRS B		PERMANENT REPAIRS	
DAMAGE	WET LAYUP ROOM TEMP (SRM 51-70-03)	WET LAYUP 150°F (66°C) CURE (SRM 51-70-03)	WET LAYUP 200°F (93°C) CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-05)
CRACKS	UP TO 2.0 INCHES (50 mm) LONG REPAIR WITH PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE
HOLES	2.0 INCHES (50 mm) MAXIMUM DIA NOT TO EXCEED 30% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	5.0 INCHES (125 mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH SIDE A	DIMENSION ACROSS	NO SIZE LIMIT
DELAMI- NATION	CUT OUT AND REPAIR AS A HOLE			
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE			
DENTS	UP TO 2.0 INCHES (50 mm) DIA WITH NO FIBER DAMAGE OR DELAMINATION, FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.L.A OVER 2.0 INCHES (50 mm) DIA OR WITH FIBER DAMAGE OR DELAMINATION, REPAIR A HOLE			

# REPAIR DATA FOR 250°F (121°C) CURE LAMINATES (FIBERGLASS OR GRAPHITE OR ARAMID)

TABLE I

#### NOTES

- WHEN YOU USE THIS REPAIR, REFER TO:
  - AMM 51-21-01 FOR APPLICATION OF FINISHES
  - SRM 51-10-01, FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE IS MORE THAN THE LIMITS GIVEN IN SRM 51-10-01, THOUGHT SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE THAT MAY OCCUR.
- A ONE REPAIR FOR EACH SQUARE FOOT OF AREA AND A MINIMUM OF 3.0 INCHES (75 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR EDGE OF PANEL
- B INSPECT INTERIM REPAIR USING INSTRUMENTED NDT METHODS OR "TAP" TEST EVERY AIRPLANE AT "2A" CHECK. FOR "TAP" TEST, USE A SOLID METAL DISK AND TAP THE REPAIR AREA LIGHTLY BUT FIRMLY. VOID AREAS WILL GIVE A DULL SOUND INSTEAD OF A SHARP RING THAT YOU WILL HEAR ON A SOLID BONDED AREA. PERMANENT REPAIR IS REQUIRED IF ANY DETERIORATION IS FOUND. REFER TO SRM 51-70-03, PAR. 4.I. AND THE NONDESTRUCTIVE TEST MANUAL C
- C THIS REPAIR HAS FAA APPROVAL ONLY IF YOU DO THE INSPECTIONS GIVEN IN THIS REPAIR

Section 43 - Wing to Body Fairing Access Door Repairs - Air Conditioning Inlet, Drain Mast, Ground Air Conditioning Figure 201 (Sheet 2 of 3)



REPAIR 4 Page 202 Jan 20/2005



	INTERIM REPAIRS B	PERMANENT	REPAIRS	
DAMAGE	ROOM TEMP (SRM 51-70-03)	WET LAYUP - 200°F (93°C) CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-05)	
HOLES AND PUNCTURES	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-03, PAR. 5.K. FOR ALL OTHER DAMAGE UP TO 10% OF THE EDGEBAND LENGTH, REPAIR AS GIVEN IN SRM 51-70-03, PAR. 5.G.	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-17, PAR. 4.K. FOR ALL OTHER DAMAGE, REPAIR AS GIVEN IN SRM 51-70-17, PAR. 4.G.	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-05, PAR. 5.K. FOR ALL OTHER DAMAGE, REPAIR AS GIVEN IN SRM 51-70-05, PAR. 5.G.	
DELAM- INATION	IF DELAMINATION FROM PANEL EDGE IS NO LESS THAN 2D FROM ANY FASTENER HOLE, REPAIR AS GIVEN IN SRM 51-70-03, PAR. 5.A.(2). ANY OTHER DELAMINATION MUST BE CUT OUT AND REPAIRED AS A HOLE	CUT OUT AND REPAIR AS A HOLE	CUT OUT AND REPAIR AS A HOLE	
EDGE EROSION		FOR DAMAGE NOT LARGER THAN 35% AS GIVEN IN SRM 51-70-03, PAR. REPAIR AS GIVEN IN:		
		SRM 51-70-17, PAR. 4.G.	SRM 51-70-05, PAR. 5.G.	
CRACKS	REPAIR AS A HOLE			
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE OR DELAMINATION, WHICHEVER IS APPLICABLE			
DENTS	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL DENTS AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE OR DELAMINATION, WHICHEVER IS APPLICABLE			

### REPAIR DATA FOR EDGEBANDS OF 250°F (121°C) CURE LAMINATES (GRAPHITE AND/OR ARAMID) TABLE II


Section 43 - Wing to Body Fairing Access Door Repairs - Air Conditioning Inlet, Drain Mast, Ground Air Conditioning Figure 201 (Sheet 3 of 3)


> EPAIR 4 Page 203 Jan 20/2005



### **REPAIR 5 - LANDING GEAR GROUND ACCESS DOOR REPAIRS**

REF DWG 149N7640





Landing Gear Ground Access Door Repairs Figure 201 (Sheet 1 of 3)



REPAIR 5 Page 201 Jan 20/2005





	INTERIM REPAIRS B		PERMANENT REPAIRS	
DAMAGE	WET LAYUP ROOM TEMP (SRM 51-70-03)	WET LAYUP 150°F (66°C) CURE (SRM 51-70-03)	WET LAYUP 200°F (93°C) CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-05)
CRACKS	UP TO 2.0 INCHES (50 mm) LONG, REPAIR WITH PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE
HOLES AND PUNC- TURES	2.0 INCHES (50 mm) MAXIMUM DIA NOT TO EXCEED 30% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	5.0 INCHES (125 mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH SIDE A	10.0 INCHES (250 mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH SIDE	NO SIZE LIMIT
DELAMI- NATION	CUT OUT AND REPAIR AS A	HOLE		
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE			
DENTS	UP TO 2.0 INCHES (50 mm) DIA WITH NO FIBER DAMAGE OR DELAMINATION, FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.L.A OVER 2.0 INCHES (50 mm) DIA OR WITH FIBER DAMAGE OR DELAMINATION, REPAIR AS A HOLE			

### REPAIR DATA FOR 250°F (121°C) CURE LAMINATES (GRAPHITE AND/OR ARAMID) TABLE I

#### NOTES

- WHEN YOU USE THIS REPAIR, REFER TO:
  - AMM 51-21-01 FOR APPLICATION OF FINISHES
  - SRM 51-10-01, FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE IS MORE THAN THE LIMITS GIVEN IN SRM 51-10-01, THOUGHT SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE THAT MAY OCCUR.
- A ONE REPAIR FOR EACH SQUARE FOOT OF AREA AND A MINIMUM OF 3.0 INCHES (75 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR EDGE OF PANEL
- B INSPECT INTERIM REPAIR USING INSTRUMENTED NDT METHODS OR "TAP" TEST EVERY AIRPLANE AT "2A" CHECK. FOR "TAP" TEST, USE A SOLID METAL DISK AND TAP THE REPAIR AREA LIGHTLY BUT FIRMLY. VOID AREAS WILL GIVE A DULL SOUND INSTEAD OF A SHARP RING THAT YOU WILL HEAR ON A SOLID BONDED AREA. PERMANENT REPAIR IS REQUIRED IF ANY DETERIORATION IS FOUND. REFER TO SRM 51-70-03, PAR. 4.I. AND THE NONDESTRUCTIVE TEST MANUAL C
- C THIS REPAIR HAS FAA APPROVAL ONLY IF YOU DO THE INSPECTIONS GIVEN IN THIS REPAIR

Landing Gear Ground Access Door Repairs Figure 201 (Sheet 2 of 3)




REPAIR 5 Page 202 Jan 20/2005



	INTERIM REPAIRS 🖪	PERMANENT	REPAIRS	
DAMAGE	ROOM TEMP (SRM 51-70-03)	WET LAYUP - 200°F (93°C) CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-05)	
HOLES AND PUNCTURES	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-03, PAR. 5.K.FOR ALL OTHER DAMAGE UP TO 10%OF THE EDGEBAND LENGTH, REPAIRAS GIVEN IN SRM 51-70-03, PAR. 5.G.	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-17, PAR. 4.K. FOR ALL OTHER DAMAGE, REPAIR AS GIVEN IN SRM 51-70-17, PAR. 4.G.	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-05, PAR. 5.K. FOR ALL OTHER DAMAGE, REPAIR AS GIVEN IN SRM 51-70-05, PAR. 5.G.	
DELAM- INATION	IF DELAMINATION FROM PANEL EDGE IS NO LESS THAN 2D FROM ANY FASTENER HOLE, REPAIR AS GIVEN IN SRM 51-70-03, PAR. 5.A.(2). ANY OTHER DELAMINATION MUST BE CUT OUT AND REPAIRED AS A HOLE	CUT OUT AND REPAIR AS A HOLE	CUT OUT AND REPAIR AS A HOLE	
EDGE EROSION		FOR DAMAGE NOT LARGER THAN 35% AS GIVEN IN SRM 51-70-03, PAR. REPAIR AS GIVEN IN:		
		SRM 51-70-17, PAR. 4.G.	SRM 51-70-05, PAR. 5.G.	
CRACKS	REPAIR AS A HOLE			
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE OR DELAMINATION, WHICHEVER IS APPLICABLE			
DENTS	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL DENTS AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE OR DELAMINATION, WHICHEVER IS APPLICABLE			

### REPAIR DATA FOR EDGEBANDS OF 250°F (121°C) CURE LAMINATES (GRAPHITE AND/OR ARAMID) TABLE II


Landing Gear Ground Access Door Repairs Figure 201 (Sheet 3 of 3)




**REPAIR 5** 



### **REPAIR 6 - FIN ACCESS DOOR REPAIRS**





DETAIL I

Fin Access Door Repairs Figure 201 (Sheet 1 of 3)



REPAIR 6 Page 201 Jan 20/2005



	INTERIM REPAIRS D		PERMANENT REPAIRS	
DAMAGE	WET LAYUP ROOM TEMP (SRM 51-70-06)	WET LAYUP 150°F (66°C) CURE (SRM 51-70-06)	WET LAYUP 200°F (93°C) CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-07)
CRACKS	UP TO 4.0 INCHES (100 mm) LONG, REPAIR WITH PATCH AS GIVEN IN SRM 51-70-06, PAR. 5.N.A	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE
HOLES	4.0 INCHES (100 mm) MAXIMUM DIA NOT TO EXCEED 30% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-06, PAR. 5.N. A	8.0 INCHES (200 mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH FACESHEET REPAIRED C	DIMENSION ACROSS	NO SIZE LIMIT
EDGE EROSION		IN SRM 51-70-06 PAR. 5.	HAN 35% OF EDGEBAND THI O. FOR LARGER DAMAGE, F SRM 51-70-17 PAR. 4.G.	REPAIR <sup>®</sup> AS GIVEN IN:
DELAMI- NATION	CUT OUT AND REPAIR AS HOLE			
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-06 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE			
DENTS	POTTING COMPOUND AND PA	TCH AS GIVEN IN SRM 51-	AGE OR DELAMINATION, FIL 70-06, PAR. 5.L.C GE OR DELAMINATION, REPA	

REPAIR DATA FOR 250°F (121°C) CURE HONEYCOMB PANELS (FIBERGLASS) TABLE I

#### NOTES

- WHEN YOU USE THIS REPAIR, REFER TO:
  - AMM 51-21-01 FOR APPLICATION OF FINISHES
  - SRM 51-10-01, FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE IS MORE THAN THE LIMITS GIVEN IN SRM 51-10-01, THOUGHT SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE THAT MAY OCCUR.
- A LIMITED TO REPAIR OF DAMAGE TO ONE FACESHEET SKIN AND HONEYCOMB CORE. ONE REPAIR FOR EACH SQUARE FOOT OF AREA AND MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, EDGE OF PANEL OR A MINIMUM OF 2.0 INCHES (50 mm) FROM TAPERED EDGE OF HONEYCOMB CORE
- B INSPECT INTERIM REPAIR USING INSTRUMENTED NDT METHODS OR "TAP" TEST EVERY AIRPLANE AT "ZA" CHECK. FOR "TAP" TEST, USE A SOLID METAL DISK AND TAP THE REPAIR AREA LIGHTLY BUT FIRMLY. VOID AREAS WILL GIVE A DULL SOUND INSTEAD OF A SHARP RING THAT YOU WILL HEAR ON A SOLID BONDED AREA. PERMANENT REPAIR IS REQUIRED IF ANY DETERIORATION IS EVIDENT. REFER TO SRM 51-70-03, PAR. 4.I. AND THE NONDESTRUCTIVE TEST MANUAL D
- C ONE REPAIR FOR EACH SQUARE FOOT OF AREA AND A MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, EDGE OF PANEL, OR A MINIMUM OF 2.0 INCHES (50 mm) FROM TAPERED EDGE OF HONEYCOMB CORE
- D THIS REPAIR HAS FAA APPROVAL ONLY IF YOU DO THE INSPECTIONS GIVEN IN THIS REPAIR

Fin Access Door Repairs Figure 201 (Sheet 2 of 3)



REPAIR 6 Page 202 Jan 20/2005



	INTERIM REPAIRS B	B PERMANENT REPAIRS				
DAMAGE	ROOM TEMP (SRM 51-70-06)	WET LAYUP - 200°F (93°C) CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-07)			
HOLES AND PUNCTURES	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-06, PAR. 5.K. FOR ALL OTHER DAMAGE, USE A PERMANENT REPAIR PROCEDURE. FOR ALL OTHER DAMAGE UP TO 10% OF THE EDGEBAND LENGTH, REPAIR AS GIVEN IN SRM 51-70-06, PAR. 5.G.	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-17, PAR. 4.K. FOR ALL OTHER DAMAGE, REPAIR AS GIVEN IN SRM 51-70-17, PAR. 4.G.	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-07, PAR. 5.K. FOR ALL OTHER DAMAGE, REPAIR AS GIVEN IN SRM 51-70-07, PAR. 5.G.			
DELAM- INATION	IF DELAMINATION FROM PANEL EDGE IS NO LESS THAN 2D FROM ANY FASTENER HOLE, REPAIR AS GIVEN IN SRM 51-70-06, PAR. 5.A.(2). ANY OTHER DELAMINATION MUST BE CUT OUT AND REPAIRED AS A HOLE	CUT OUT AND REPAIR AS A HOLE	CUT OUT AND REPAIR AS A HOLE			
CRACKS	REPAIR AS A HOLE					
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-06 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE OR DELAMINATION, WHICHEVER IS APPLICABLE					
DENTS	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL DENTS AS GIVEN IN SRM 51-70-06 IF YOU FIND FIBER DAMAGE OR DELAMINATION, REPAIR AS A HOLE OR DELAMINATION, WHICHEVER IS APPLICABLE					

REPAIR DATA FOR EDGEBANDS OF 250°F (121°C) CURE HONEYCOMB PANELS (FIBERGLASS) TABLE II

Fin Access Door Repairs Figure 201 (Sheet 3 of 3)




**REPAIR 6** 



### **REPAIR 7 - TOILET DRAIN ACCESS DOOR REPAIRS**

REF DWG 149N7702



Toilet Drain Access Door Repairs Figure 201 (Sheet 1 of 3)



REPAIR 7 Page 201 Jan 20/2005





	INTERIM REPAIRS B	PERMANENT REPAIRS				
DAMAGE	WET LAYUP ROOM TEMP (SRM 51-70-03)	WET LAYUP 150°F (66°C) CURE (SRM 51-70-03)	WET LAYUP 200°F (93°C) CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-05)		
CRACKS	UP TO 2.0 INCHES (50 mm) LONG, REPAIR WITH PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE		
HOLES	2.0 INCHES (50 mm) MAXIMUM DIA NOT TO EXCEED 30% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	5.0 INCHES (125 mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH SIDE A	10.0 INCHES (250 mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH SIDE	NO SIZE LIMIT		
DELAMI- NATION	CUT OUT AND REPAIR AS A HOLE					
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE					
DENTS	UP TO 2.0 INCHES (50 mm) DIA WITH NO FIBER DAMAGE OR DELAMINATION, FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.L.A OVER 2.0 INCHES (50 mm) DIA OR WITH FIBER DAMAGE OR DELAMINATION, REPAIR AS HOLE					

#### REPAIR DATA FOR 250°F (121°C) CURE LAMINATE (GRAPHITE AND/OR ARAMID) TABLE I

#### NOTES

- WHEN YOU USE THIS REPAIR, REFER TO:
  - AMM 51-21-01 FOR APPLICATION OF FINISHES
  - SRM 51-10-01, FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE IS MORE THAN THE LIMITS GIVEN IN SRM 51-10-01, THOUGHT SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE THAT MAY OCCUR.
- A ONE REPAIR FOR EACH SQUARE FOOT (930 SQUARE cm) OF AREA AND A MINIMUM OF 3.0 INCHES (75 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR EDGE OF PANEL
- B INSPECT INTERIM REPAIR USING INSTRUMENTED NDT METHODS OR "TAP" TEST EVERY AIRPLANE AT "2A" CHECK. FOR "TAP" TEST, USE A SOLID METAL DISK AND TAP THE REPAIR AREA LIGHTLY BUT FIRMLY. VOID AREAS WILL GIVE A DULL SOUND INSTEAD OF A SHARP RING THAT YOU WILL HEAR ON A SOLID BONDED AREA. PERMANENT REPAIR IS REQUIRED IF ANY DETERIORATION IS FOUND. REFER TO SRM 51-70-03, PAR. 4.I. AND THE NONDESTRUCTIVE TEST MANUAL C
- C THIS REPAIR HAS FAA APPROVAL ONLY IF YOU DO THE INSPECTIONS GIVEN IN THIS REPAIR

Toilet Drain Access Door Repairs Figure 201 (Sheet 2 of 3)




REPAIR 7 Page 202 Jan 20/2005



	INTERIM REPAIRS 🖪	PERMANENT REPAIRS			
DAMAGE	ROOM TEMP (SRM 51-70-03)	WET LAYUP - 200°F (93°C) CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-05)		
HOLES AND PUNCTURES	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-03, PAR. 5.K. FOR ALL OTHER DAMAGE UP TO 10% OF THE EDGEBAND LENGTH, REPAIR AS GIVEN IN SRM 51-70-03, PAR. 5.G.	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-17, PAR. 4.K. FOR ALL OTHER DAMAGE, REPAIR AS GIVEN IN SRM 51-70-17, PAR. 4.G.	REPAIR DAMAGE TO FASTENER HOLES AS GIVEN IN SRM 51-70-05, PAR. 5.K. FOR ALL OTHER DAMAGE, REPAIR AS GIVEN IN SRM 51-70-05, PAR. 5.G.		
DELAM- INATION	IF DELAMINATION FROM PANEL EDGE IS NO LESS THAN 2D FROM ANY FASTENER HOLE, REPAIR AS GIVEN IN SRM 51-70-03, PAR. 5.A.(2). ANY OTHER DELAMINATION MUST BE CUT OUT AND REPAIRED AS A HOLE	CUT OUT AND REPAIR AS A HOLE	CUT OUT AND REPAIR AS A HOLE		
EDGE EROSION		FOR DAMAGE NOT LARGER THAN 35% OF EDGEBAND THICKNESS, REPAIR AS GIVEN IN SRM 51-70-03, PAR. 5.0. FOR LARGER DAMAGE, REPAIR AS GIVEN IN:			
		SRM 51-70-17, PAR. 4.G.	SRM 51-70-05, PAR. 5.G.		
CRACKS	REPAIR AS A HOLE				
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE OR DELAMINATION, WHICHEVER IS APPLICABLE				
DENTS	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL DENTS AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE OR DELAMINATION, WHICHEVER IS APPLICABLE				

### REPAIR DATA FOR EDGEBANDS OF 250°F (121°C) CURE LAMINATES (GRAPHITE AND/OR ARAMID) TABLE II


Toilet Drain Access Door Repairs Figure 201 (Sheet 3 of 3)



**REPAIR 7** 



## **IDENTIFICATION 1 - FLIGHT DECK DOOR STRUCTURE**



NOTES

FOR CUM LINE NUMBERS:
 9, 10, 11, 13, 16, 17, 24, 27, 29, 31, 34, 35, 36, 37, 39, 41, 87, 88, 93, (BOEING REF NO.: NA220 THRU NA399)


Flight Deck Door Structure Figure 1 (Sheet 1 of 2)



1DENTIFICATION 1 Page 1 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL



ITEM DESCRIPTION GAGE MATERIAL EFFECTIVITY NONMETALLIC/FIBERGLASS HONEYCOMB SANDWICH 1 DOOR PANEL OUTER FWD SKIN ACOUSTIC FABRIC PER BMS 8-64, TYPE I FIBERGLASS PER BMS 8-151, TYPE IV, STYLE 8800 INNER FWD SKIN CORE NOMEX HONEYCOMB PER BMS 8-124, TYPE V, CLASS IV, GRADE 3.0 AFT SKIN FIBERGLASS PER BMS 8-151, TYPE I, STYLE 8800 Α 2 TEE BAC1505-11 2024-T3511 3 TRIM BAC1509-100151 6063-T5 4 TRIM BAC1490-2727 2024-T3 5 TRIM BAC1518-308 6063-T5 6 DOOR POST COVER 0.032 2024-T3

LIST OF MATERIALS FOR DETAIL I

Flight Deck Door Structure Figure 1 (Sheet 2 of 2)



1DENTIFICATION 1 Page 2 Jan 20/2005


REF DWG

417N1076





## ALLOWABLE DAMAGE 1 - ALLOWABLE DAMAGE - FLIGHT DECK DOOR STRUCTURE



DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES	DELAMINATION
DOOR PANELS	A	В	C	A	A
TEE	E	F	NOT ALLOWED	NOT ALLOWED	
EDGE TRIM	E	F	SEE DETAIL IV	G	

Allowable Damage - Flight Deck Door Structure Figure 101 (Sheet 1 of 4)



REF DWG

417N1076






#### NOTES

- REFINISH REWORKED AREAS PER 51-20 OF THE MAINTENANCE MANUAL
- REFER TO SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- THE ALLOWABLE DAMAGE LIMITS CONTAINED HERE-IN APPLY ONLY TO THE STRUCTURAL INTEGRITY OF THE DOOR. REWORK TO RESTORE ACOUSTIC PROPERTIES AND/OR COSMETIC APPEARANCE OF THE DOOR SHALL BE AN OPERATOR OPTION
- A DAMAGE TO SKIN PANEL EDGES MAY BE A COMBI-NATION OF EDGE DELAMINATION AND/OR CRACKS, GOUGES, ETC. WHICH CAN RESULT IN FIBER DAMAGE AND A LOSS OF CROSS-SECTIONAL AREA. REMOVE EDGE DAMAGE PER DETAILS I. 2.0 INCHES (50 mm) MAX DIA ALLOWED FOR SINGLE DAMAGE SITE IN HONEYCOMB AREA. MULTIPLE DAMAGE SITES MUST NOT BE CLOSER THAN A MINIMUM OF a/D = 3.0. SEE DETAIL V FOR DAMAGE CRITERIA. DAMAGE ALLOWED TO ONE SURFACE AND HONEYCOMB CORE ONLY. PROTECT DAMAGE NOT REWORKED PER D
- B DAMAGE ALLOWED ON SURFACE RESIN ONLY WITH NO FIBER DAMAGE. CLEAN UP EDGE DAMAGE PER DETAILS I. REFER TO A FOR FIBER DAMAGE IN OTHER AREAS
- C DENTS RESULT IN DELAMINATION AND FIBER DAMAGE AND MUST BE TREATED AS A HOLE OR PUNCTURE DAMAGE


- REMOVE MOISTURE FROM DAMAGE AREA. USE OF VACUUM AND HEAT (MAX OF 125°F (52°C)) TO REMOVE MOISTURE FROM HONEYCOMB CELLS IS RECOMMENDED. PROTECT DAMAGE FROM ENTRANCE OF WATER, SUNLIGHT OR OTHER FOREIGN MATTER BY SEALING WITH ALUMINUM FOIL TAPE (SPEED TAPE). RECORD THE LOCATION AND INSPECT EVERY AIRPLANE "A" CHECK. REPLACE THE ALUMINUM FOIL TAPE IF ANY PEELING OR DETER-IORATION EVIDENT. REPAIR NO LATER THAN NEXT AIRPLANE "C" CHECK. H
- E CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAIL II
- F REMOVE DAMAGE PER DETAILS II AND III
- G CLEAN OUT HOLE OR PUNCTURE DAMAGE UP TO 0.25 INCH (6 mm) DIAMETER. FILL HOLE WITH BMS 5-95 SEALANT
- H THESE ALLOWABLE DAMAGE LIMITS HAVE FAA APPROVAL CONTINGENT ON ACCOMPLISHMENT OF THE INSPECTIONS CONTAINED HEREIN



X = DEPTH OF CLEANUP = 0.25 MAX

REMOVAL OF NICK OR CRACK DAMAGE ON AN EDGE

DETAIL I




DAMAGE ON AN EDGE

DETAIL II


Allowable Damage - Flight Deck Door Structure Figure 101 (Sheet 2 of 4)








REMOVAL OF NICK, GOUGE AND SCRATCH DAMAGE ON A SURFACE DETAIL III






Allowable Damage - Flight Deck Door Structure Figure 101 (Sheet 3 of 4)





757-200 STRUCTURAL REPAIR MANUAL



SMALL DAMAGE SITES THAT ARE CLOSELY SPACED MAY BE GROUPED TOGETHER AND CONSIDERED AS ONE DAMAGE SITE

ADJACENT DAMAGE SITES ON SURFACE OF COMPOSITE PANEL

- DAMAGE TO COMPOSITE PANELS EXPOSED TO MULTIPLE IMPACTS, I.E., HAIL DAMAGE, CAN BE DETECTED BY USING INSTRUMENTED NON-DESTRUCTIVE INSPECTION METHODS OR BY TAPPING THE SUSPECTED DAMAGE AREA WITH A SMALL METALLIC DISK OBJECT. INSPECTION SHOULD COVER THE AREA WITHIN 3 DIAMETERS AROUND THE EDGE OF THE VISIBLE DAMAGE SITE. FOR TAP TEST, USE A SOLID METAL DISK AND TAP THE DAMAGE AREA LIGHTLY BUT FIRMLY. VOID AREAS SHOULD PRODUCE A DULL SOUND AS OPPOSED TO A SHARP RING ON A SOLID BONDED AREA
- DAMAGE SITE IS ANY SINGLE AREA OF A PANEL WHERE A DENT, CRACK, DELAMINATION, PUNCTURE OR ANY COMBINATION OF THESE EXIST. SMALL DAMAGE SITES THAT ARE CLOSELY SPACED MAY BE GROUPED TOGETHER AND CONSIDERED AS ONE DAMAGE SITE

- "D" IS DETERMINED BY MEASURING THE MAX DIMENSION OF A DENT, CRACK, OR OTHER DAMAGE, WHICHEVER IS GREATER
- "a" IS THE DISTANCE BETWEEN TWO ADJACENT DAMAGE SITES
- "d" IS THE MAX DIMENSION OF THE SMALLER ٠ OF TWO ADJACENT DAMAGE SITES
- CALCULATE a/D BY DIVIDING DISTANCE "a" BY DIAMETER "D"
- DAMAGE IS ALLOWED WHEN "D" IS EQUAL TO OR LESS THAN THE MAXIMUM ALLOWABLE "D" FROM TABLE I AND WHEN a/D IS EQUAL TO OR GREATER THAN THE MINIMUM a/D GIVEN IN TABLE

DAMAGE SIZING AND SPACING DATA FOR COMPOSITE PANELS DETAIL V

Allowable Damage - Flight Deck Door Structure Figure 101 (Sheet 4 of 4)



Page 104



#### **REPAIR 1 - FLIGHT DECK DOOR**

#### REPAIR INSTRUCTIONS

- Refer to 25-00-00 of the 757 Maintenance Manual for repair of nicks and scratches, for gouges not exceeding 1.5 inches, and for repairs to BMS 8-133 urethane foam.
- Refer to 51-70-06, figure 19 for repair of cracks up to 6.0. Restore the decorative surface per par. 4.
- Refer to details II and III for repair to BMS 8–143 and BMS 8–151 fiberglass plies and for repair to NOMEX honeycomb core. Use BMS 9–3 Type H–2 or H–3 glass fabric. Extra repair plies are not required.
  - <u>NOTE</u>: If this repair is used on the acoustical side, loss of acoustical attenuation may result.
- Restore the decorative surface with a nonreinforced decorative laminate A.
  - A. Remove trim and door knob.
    - NOTE: If the door panel surface has been repaired previously with the nonreinforced decorative laminate, then remove all of the old laminate before proceeding with this repair.
  - B. Apply filler paste B to area surrounding repair patch and in all dents, scratches, nicks, gouges and low spots on entire panel surface.
  - C. Allow to dry for 10 minutes before sanding.
  - D. Use 180 grit sandpaper to sand filler paste flush with surface. Finish smooth with 240 grit sandpaper.
  - CAUTION: DO NOT ALLOW STANDING TRICHLOR-OETHANE SOLVENT ON PART. DAMAGE TO PART WILL OCCUR.
  - E. Wipe entire panel surface clean with MEK solvent. After the panel is dry, wipe with trichloroethane solvent.
  - F. Cut the decorative laminate to fit the entire panel side that is being repaired.

- G. Remove backing slowly while applying the laminate to the panel surface.
- H. Smooth out any bubbles or wrinkles with hand as the laminate is applied.
- Expand the trim 0.010 if one side is repaired, to accommodate the decorative laminate. If both sides are repaired, expand trim 0.020.
- J. Reinstall trim and door knob.

#### NOTES

- REFER TO 51-70-06 FOR CLEANUP OF DAMAGE AND WET LAYUP CURE PROCEDURE
- A OBTAIN THIS MATERIAL FROM THE BOEING COMPANY; SPECIFY BMS 8-176 WITH TEDLAR/ ALUMINUM FOIL LAMINATE AND PRESSURE SENSITIVE ADHESIVE (BAC5596 TYPE III). REFER TO DWG 413T4999 FOR CUSTOMER COLOR CODES
- B MICRO ULTRA FILLER #15-3 INDUSTRIAL FILLER PASTE

AD-TECH PLASTIC SYSTEMS CORP. 570 E. MAIN STREET POTTERVILLE, MICHIGAN 48876

C CELL WALLS MUST BE ALIGNED IN THE SAME DIRECTION AS THE ORIGINAL HONEYCOMB

Flight Deck Door Figure 201 (Sheet 1 of 4)




REPAIR 1 Page 201 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL






Flight Deck Door Figure 201 (Sheet 2 of 4)



REPAIR 1 Page 202 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL




REPAIR OF DAMAGE TO ONE PANEL SIDE DETAIL II

> Flight Deck Door Figure 201 (Sheet 3 of 4)



REPAIR 1 Page 203 Jan 20/2005



REPAIR OF DAMAGE TO BOTH PANEL SIDES DETAIL III


> Flight Deck Door Figure 201 (Sheet 4 of 4)



REPAIR 1 Page 204 Jan 20/2005



### **GENERAL - LANDING GEAR DOOR INDEX**



### NOTES

• REFER TO THE FOLLOWING IN 52-80-02 FOR LANDING GEAR DOOR INDENTIFICATION:

IDENTIFICATION	1	-	MAIN LANDI	NG GE	AR DOORS
IDENTIFICATION	2	-	NOSE LANDI	NG GE	AR DOORS
IDENTIFICATION	3	-	MLG STRUT	DOORS	
IDENTIFICATION	4	-	TRUNNION F	AIRIN	IG DOORS

Landing Gear Door Index Figure 1




GENERAL Page 1 Jan 20/2005



#### **IDENTIFICATION 1 - MAIN LANDING GEAR DOOR**

REFERENCE DRAWING 149N6002



NOTES

- CORE DENSITIES VARY. SEE DRAWING 149N6003 FOR CORE POSITIONS.
- A PLY ORIENTATION CONVENTION, O DEGREES, IS PARALLEL TO THE FABRIC WARP DIRECTION.
- B GRAPHITE/EPOXY FABRIC PER BMS 8-212, TYPE IV, CLASS II, STYLE 3K-70-PW.
- C FOR AIRPLANES WITH CUM LINE NUMBERS: 1 THRU 36
- FOR AIRPLANES WITH CUM LINE NUMBERS: 37 AND ON
- E HEAT SHIELD PLY ORIENTATIONS ARE OPTIONAL.
- F HEAT SHIELD ON RH DOOR IS CENTERED AT RBL 53.75.
- G FOR AIRPLANES WITH ONE-PIECE MLG DOOR AND TANG.
- H FOR AIRPLANES WITH TWO-PIECE MLG DOOR AND TANG.

- I GRAPHITE/EPOXY FABRIC PER BMS 8-168, TYPE II, CLASS 2, STYLE 3K-70-PW.
- J FOR AIRPLANES WITH CUM LINE NUMBERS: 471 AND ON
- K FOR AIRPLANES WITH A TWO-PIECE MLG DOOR AND TANG THAT ARE NOT LISTED IN J.
- L FOR AIRPLANES WITH CUM LINE NUMBERS: 465 THRU 659 THAT HAVE INCORPORATED SB 757-52-0016 AND FOR AIRPLANES WITH CUM LINE NUMBERS: 660 AND ON
- M FOR AIRPLANES WITH A TWO-PIECE MLG DOOR AND TANG THAT ARE NOT LISTED IN L.


Main Landing Gear Door Figure 1 (Sheet 1 of 9)



1DENTIFICATION 1 Page 1 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL



DETAIL I G

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	HINGE FITTING		MACHINED, FORGED BLOCK 7075-T73	
2	STRONG BACK BEAM		FORGING 7075-T73	
3	CENTER HINGE FITTING		15-5PH CRES HT TR 180-200 KSI	
4	DOOR PANEL SKINS CORE		FIBERGLASS/GRAPHITE/EPOXY HONEYCOMB SANDWICH SEE DETAIL II NONMETALLIC HONEYCOMB PER BMS 8-124, CLASS I, TYPE I, GRADE 4.0	


LIST OF MATERIALS FOR DETAIL I G

Main Landing Gear Door Figure 1 (Sheet 2 of 9)



1DENTIFICATION 1 Page 2 Jan 20/2005





(INNER SURFACE)
SECTION THRU HONEYCOMB PANEL




DIAGRAM OF PLY ORIENTATION. SEE PLY TABLE FOR INDIVIDUAL PLY ORIENTATION AND MATERIAL.

VIEW ON DOOR PANEL

ITEM NO.	PLY NO.	MATERIAL	PLY A ORIENTATION
4	P1,P25,P26,P60 P2,P27	B	0° OR 90° ±45°

MATERIAL AND PLY ORIENTATIONN SHOWN FOR FIELD AREAS ONLY. SEE BOEING DRAWING FOR EDGE BANDS AND AREAS WITH DOUBLERS.

PLY TABLE

DETAIL II G

Main Landing Gear Door Figure 1 (Sheet 3 of 9)




1DENTIFICATION 1 Page 3 Jan 20/2005

D634N201

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details

BOEING"

757-200 STRUCTURAL REPAIR MANUAL



ITEM GAGE EFFECTIVITY DESCRIPTION MATERIAL 1 HEAT SHIELD PANEL ASSEMBLY ONE PLY OF ARAMID/EPOXY PREPREG PER BMS 8-218, INNER AND OUTER SKINS STYLE 285 BONDED TO CORE PLUS ONE PLY OF FIBER-GLASS/EPOXY PREPREG PER BMS 8-139, TYPE 120 E NONMETALLIC HONEYCOMB PER BMS 8-124, CLASS I, CORE TYPE I, GRADE 4.0

LIST OF MATERIALS FOR DETAILS III AND IV G

Main Landing Gear Door Figure 1 (Sheet 4 of 9)




DENTIFICATION 1 Page 4 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL



DETAIL V H

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	HINGE FITTING ASSEMBLY		FORGING 7075-T73	
2	STRONGBACK BEAM		FORGING 7075-T73	
3	CENTER HINGE FITTING		15-5PH CRES PER AMS 5659 HT TR TO 180-200 KSI	
4	DOOR PANEL ASSEMBLY SKINS CORE		FIBERGLASS/GRAPHITE/EPOXY HONEYCOMB SANDWICH SEE DETAIL VI NONMETALLIC HONEYCOMB PER BMS 8-124, CLASS 1, TYPE 1, GRADE 4.0	
5	HINGE FITTING		FORGING 7075-T73	
6	CLEVIS ASSEMBLY CLEVIS BASE PLATE	0.125	BAC1507-48821 7075-T73 EXTRUSION 15-5PH CRES SHEET HT TR TO 125-145 KSI	L
7	CLEVIS		BAC1507-48822 7075-T73 EXTRUSION	
8	DROP LINK		7075-T7351 PLATE	L
9	LINK FITTING ASSEMBLY LINK FITTING BASE PLATE	0.125	7075-T7351 PLATE 15-5PH CRES SHEET HT TR TO 125-145 KSI	M

LIST OF MATERIALS FOR DETAIL V H


Main Landing Gear Door Figure 1 (Sheet 5 of 9)



1DENTIFICATION 1 Page 5 Jan 20/2005










DIAGRAM OF PLY ORIENTATION. SEE PLY TABLE FOR INDIVIDUAL PLY ORIENTATION AND MATERIAL.

VIEW ON DOOR PANEL

SECTION THRU HONEYCOMB PANEL

ITEM NO.	PLY NO.	MATERIAL	PLY A ORIENTATION
4	P2,P4,P34,P36, P37,P39,P69,P71	В	0° or 90°
	P3,P13,P25,P35, P38,P48,P60,P70	В	±45°

MATERIAL AND PLY ORIENTATIONN SHOWN FOR THE FIELD AREAS ONLY. SEE BOEING DRAWING 149N6007 FOR EDGE BANDS AND FOR AREAS WITH DOUBLERS.

PLY TABLE

DETAIL VI H

Main Landing Gear Door Figure 1 (Sheet 6 of 9)




1DENTIFICATION 1 Page 6 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL



LEFT DOOR SHOWN RIGHT DOOR SIMILAR DETAIL VII H

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	HEAT SHIELD PANEL ASSEMBLY INNER SKIN OUTER SKIN CORE		TWO PLIES OF GLASS/EPOXY PREPREG PER BMS 8-139, TYPE 1581 THREE PLIES OF GLASS/EPOXY PREPREG PER BMS 8-139, TYPE 1581 NONMETALLIC HONEYCOMB PER BMS 8-124, CLASS I, TYPE I, GRADE 4.0	

LIST OF MATERIALS FOR DETAIL VII H


Main Landing Gear Door Figure 1 (Sheet 7 of 9)



1DENTIFICATION 1 Page 7 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL



DETAIL VIII 田

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	TANG ASSEMBLY INNER AND OUTER SKINS CORE		SEE DETAIL IX NONMETALLIC HONEYCOMB PER BMS 8-124, CLASS 4, TYPE V, GRADE 3.0	
2	LOWER CLEVIS FITTING		BAC1507-48823 7075-T73 EXTRUSION	I
3	UPPER CLEVIS FITTING		BAC1507-48822 7075-T73 EXTRUSION	J
4	LOWER CLEVIS FITTING		7075-T7351 PLATE	Μ
5	UPPER CLEVIS FITTING		BAC1507-48822 7075-T73511 EXTRUSION	ĸ


LIST OF MATERIALS FOR DETAIL VIII H

Main Landing Gear Door Figure 1 (Sheet 8 of 9)



1DENTIFICATION 1 Page 8 Jan 20/2005








DIAGRAM OF PLY ORIENTATION. SEE PLY TABLE FOR INDIVIDUAL PLY ORIENTATION AND MATERIAL.

VIEW ON TANG PANEL

SECTION THRU HONEYCOMB PANEL

ITEM NO.	PLY NO.	MATERIAL	PLY A ORIENTATION
	P1,P15,P22,P36	I	±45°
1	P2,P16,P21,P35	I	0° or 90°
	P37	I	OPTIONAL

MATERIAL AND PLY ORIENTATION IS SHOWN FOR THE FIELD AREAS ONLY. SEE BOEING DRAWING 149N6009 FOR EDGE BANDS.

PLY TABLE

DETAIL IX H


Main Landing Gear Door Figure 1 (Sheet 9 of 9)




1DENTIFICATION 1 Page 9 Jan 20/2005



#### **IDENTIFICATION 2 - NOSE LANDING GEAR DOOR SKIN**






Nose Landing Gear Door Figure 1 (Sheet 1 of 5)



DENTIFICATION 2 Page 1 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL



DETAIL I

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	ROD ATTACH FITTING		FORGED BLOCK 7075-T73	
2	HINGE FITTING		FORGED BLOCK 7075-T73 DIE FORGING 7075-T73	A B
3	DOOR STOP FITTING		EXTRUDED BAR 7075-T73511	
4	DOOR PANEL SKIN CORE		GRAPHITE HYBRID HONEYCOMB SANDWICH SEE DETAIL II FIBERGLASS HONEYCOMB PER BMS 8-124, CLASS 1, TYPE 1, GRADE 4.0	
5	DOOR PANEL SKIN CORE		GRAPHITE HYBRID HONEYCOMB SANDWICH SEE DETAIL III FIBERGLASS HONEYCOMB PER BMS 8-124, CLASS 1, TYPE 1, GRADE 4.0	
6	DOOR PANEL SKIN CORE		GRAPHITE HYBRID HONEYCOMB SANDWICH SEE DETAIL IV FIBERGLASS HONEYCOMB PER BMS 8-124, CLASS 1, TYPE 1, GRADE 4.0	
7	SCUFF PLATE	0.020	301 CRES	Н


LIST OF MATERIALS FOR DETAIL I


Nose Landing Gear Door Figure 1 (Sheet 2 of 5)



DENTIFICATION 2 Page 2 Jan 20/2005














DIAGRAM OF PLY ORIENTATION. SEE PLY TABLE FOR INDIVIDUAL PLY ORIENTATION AND MATERIAL.

VIEW ON DOOR PANEL









ITEM NO.	PLY NO.	MATERIAL	PLY ORIENTATION
4,	1,14	E G	0°
5,	2,6,9,13	F	+45°
6	4,11	F	-45°
	3,5,7,8, 10,12	F	0°

MATERIAL AND PLY ORIENTATION SHOWN FOR FIELD AREAS ONLY. SEE BOEING DRAWING FOR EDGE BANDS AND AREAS WITH DOUBLERS

PLY TABLE FOR DETAILS II, III, IV


Nose Landing Gear Door Figure 1 (Sheet 3 of 5)



DENTIFICATION 2 Page 3 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL



AFT DOOR LEFT DOOR SHOWN RIGHT DOOR OPPOSITE DETAIL V

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1 2 3	DOOR SUPPORT FITTING HINGE FITTING DOOR PANEL SKIN CORE		EXTRUDED BAR 7075-T73511 FORGED BLOCK 7075-T73 DIE FORGING 7075-T73 GRAPHITE HYBRID HONEYCOMB SANDWICH SEE DETAIL VI FIBERGLASS HONEYCOMB PER BMS 8-124, CLASS 1, TYPE 1, GRADE 4.0	A B


LIST OF MATERIALS FOR DETAIL V

**Nose Landing Gear Door** Figure 1 (Sheet 4 of 5)



**IDENTIFICATION 2** Page 4 Jan 20/2005





(INNER SURFACE)

SECTION THRU HONEYCOMB PANEL DETAIL VI




DIAGRAM OF PLY ORIENTATION. SEE PLY TABLE FOR INDIVIDUAL PLY ORIENTATION AND MATERIAL.

VIEW ON DOOR PANEL

ITEM NO.	PLY NO.	MATERIAL	PLY D ORIENTATION
	1,8	EG	0°
3	2,7	F	+45°
5	3,6	F	-45°
	4,5	F	0°

MATERIAL AND PLY ORIENTATIONN SHOWN FOR FIELD AREAS ONLY. SEE BOEING DRAWING FOR EDGE BANDS AND AREAS WITH DOUBLERS

PLY TABLE FOR DETAIL VI

Nose Landing Gear Door Figure 1 (Sheet 5 of 5)




1DENTIFICATION 2 Page 5 Jan 20/2005

D634N201

BOEING PROPRIETARY - Copyright  ${\rm \bigodot}$  Unpublished Work - See title page for details



#### **IDENTIFICATION 3 - MAIN LANDING GEAR STRUT DOOR SKIN**



D634N201

Jan 20/2005



ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	PLATE SERRATED	0.156	TI-6AL-4V ANNEALED PLATE PER MIL-T-9046, TYPE III, COMP C	
2	ATTACH FITTING		TI-6AL-4V CASTING PER BMS 7-181, TYPE I, COND A, GRADE B OR	
		1.75	TI-6AL-4V ANNEALED PLATE PER MIL-T-9046	
3	CENTER FITTING		TI-6AL-4V CASTING PER BMS 7-181, COND A, TYPE I, GRADE B OR	
		1.38	TI-6AL-4V ANNEALED PLATE PER MIL-T-9046, TYPE III, COMP C	
4	BEAM ATTACH FITTING		TI-6AL-4V CASTING PER BMS 7-181, COND A, GRADE B OR	
		2.1	TI-6AL-4V BAR PER MIL-T-9047, COMP 6, ANNEALED	
5	BEAM FITTING		TI-6AL-4V CASTING PER BMS 7-181, TYPE I, COND B, GRADE B OR	
			TI-6AL-4V ANNEALED FORGED BLOCK PER AMS 4926 OR	
		2.5	TI-6AL-4V ANNEALED BAR PER MIL-T-9047, COMP 6	
6	BEAM FITTING		TI-6AL-4V FORGING PER AMS 4928 ANNEALED	
			TI-6AL-4V ANNEALED FORGED BLOCK PER AMS 4926 OR TI-GAL-4V ANNEALED BAR PER MIL-T-9047, COMP 6	
7	BEAM FITTING		TI-6AL-4V ANNEALED FORGED BLOCK PER AMS 4928	н
-		2.5	OR TI-6AL-4V ANNEALED BAR PER MIL-T-9047, COMP 6	
8	BEAM FITTING	2.9	TI-6AL-4V CASTING PER BMS 7-181, TYPE I, COND A, GRADE B OR	
			TI-6AL-4V ANNEALED FORGED BLOCK PER MIL-I-8950, CLASS A OR	
		3.5	TI-6AL-4V ANNEALED BAR PER MIL-T-9047, COMP 6	
9	DOOR PANEL		GRAPHITE/EPOXY HONEYCOMB SANDWICH	
	SKIN CORE		SEE DETAIL I NONMETALLIC HONEYCOMB PER BMS 8-124, CLASS I, TYPE I, GRADE 8.0	
10	ACTUATOR SUPPORT FITTING		7075-T73 FORGED BLOCK PER BMS 7-186 OR 7075-T73 FORGING PER BMS 7-186	
11	BEAM FITTING		TI-6AL-4V CASTING PER BMS 7-181, TYPE I, COND A, GRADE B	E
12	BEAM FITTING		FORGING 7075-T73 PER BMS 7-186	G
13	BEAM ATTACH FITTING		FORGING 7075-T73 PER BMS 7-186	G
14	CENTER FITTING		FORGING 7075-T73 PER BMS 7-186	G
15	BEAM		FORGING 7075-T73 PER BMS 7-186	G

LIST OF MATERIALS FOR DETAIL I

Main Landing Gear Strut Door Identification Figure 1 (Sheet 2 of 3)



**IDENTIFICATION 3** Page 2 Jan 20/2005











DIAGRAM OF PLY ORIENTATION. SEE PLY TABLE FOR INDIVIDUAL PLY ORIENTATION AND MATERIAL (OUTER SURFACE)





SECTION THRU HONEYCOMB PANEL

ITEM NO.	PLY NO.	MATERIAL	PLY D ORIENTATION
	1,6 I	В	0° OR +90°
8	1,6 G	F	0° OR +90°
	2,5	A	+45°
	3,4	A	0° OR +90°

PLY TABLE

DETAIL I

Main Landing Gear Strut Door Identification Figure 1 (Sheet 3 of 3)




1DENTIFICATION 3 Page 3 Jan 20/2005





#### **IDENTIFICATION 4 - TRUNNION FAIRING DOOR**



A PLY LAYUP VARIES THROUGHOUT PANEL. SEE BOEING DWG FOR PLY MATERIAL AND ORIENTATION

ITEM	DESCRIPTION	GAGE	MATERIAL	EFFECTIVITY
1	TRUNNION DOOR PANEL SKIN		ARAMID/GRAPHITE/EPOXY HONEYCOMB SANDWICH	
	OUTER PLY		ARAMID FABRIC PER BMS 8-219, STYLE 285 A	
	INNER PLIES		GRAPHITE FABRIC PER BMS 8-168, CLASS II, TYPE II, STYLE 3K-70-PW A	
	CORE		NONMETALLIC HONEYCOMB PER BMS 8-124, CLASS I, TYPE I, GRADE 5.5	
2	HINGE		FORGED BLOCK OR DIE FORGING 7075-T73	
3	SUPPORT FITTING		FORGED BLOCK OR DIE FORGING 7075-T73	


LIST OF MATERIALS FOR DETAIL I


Trunnion Fairing Door Identification Figure 1





#### ALLOWABLE DAMAGE 1 - MAIN LANDING GEAR DOOR





DETAIL II X AA

Allowable Damage - Main Landing Gear Door Figure 101 (Sheet 2 of 10)




D634N201

BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



757-200 STRUCTURAL REPAIR MANUAL




### LEFT SIDE MAIN LANDING GEAR DOOR IS SHOWN, RIGHT SIDE IS OPPOSITE DETAIL III Y AA

Allowable Damage - Main Landing Gear Door Figure 101 (Sheet 3 of 10)






757-200 STRUCTURAL REPAIR MANUAL





757-200 STRUCTURAL REPAIR MANUAL




Allowable Damage - Main Landing Gear Door Figure 101 (Sheet 5 of 10)





757-200 STRUCTURAL REPAIR MANUAL



DETAIL IV

DESCRIPTION		CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES	DELAMINATION
	COLD WRAPPED FIBERGLASS EDGES	S	S	S	S	5
DOOR PANEL	FACE SKIN- CRITICAL AREAS (SHADED)	C	F	K	Μ	٩
	FACE SKIN- NON-CRITICAL AREAS	T	G	K	N	Q
STRONGBACK	REGION I	NOT ALLOWED	н	NOT Allowed	NOT Allowed	NOT APPLICABLE
BEAM R	REGION II	D				
HINGE FITTINGS R	FWD AND AFT CENTER	D	I	NOT Allowed	NOT Allowed	NOT APPLICABLE
TITANIUM EDGE CHANNELS	LBL 28.50 RBL 53.80	E	L	L	NOT Allowed	NOT APPLICABLE
FIBERGLASS HEAT SHIELD	LBL 28.50 RBL 53.80	T	U	K	0	V

Allowable Damage - Main Landing Gear Door Figure 101 (Sheet 6 of 10)





#### NOTES

- DAMAGE TO PANEL EDGES MAY BE CONFINED TO DELAMINATION OR MAY TAKE A FORM WHICH RESULTS IN DAMAGE TO FIBERS AND A LOSS OF EFFECTIVE CROSS-SECIIONAL AREA. THIS TYPE OF DAMAGE SHOULD BE REMOVED AND THE LIMITATIONS GIVEN FOR CRACKS APPLIED.
- REFINISH AREAS PER AMM 51-20
- REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED.
- REFER TO SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- A REMOVE MOISTURE FROM DAMAGE AREA. USE OF VACUUM AND HEAT (MAX OF 125°F E52°C]) TO REMOVE MOISTURE FROM HONEYCOMB CELLS IS RECOMMENDED. PROTECT DAMAGE FROM ENTRANCE OF WATER, SUNLIGHT OR OTHER FOREIGN MATTER BY SEALING WITH ALUMINUM FOIL TAPE (SPEED TAPE) 3M-Y436 OR EQUIVALENT. RECORD LOCATION AND INSPECT AT AIRPLANE "A" CHECK. REPLACE ALUMINUM FOIL TAPE IF ANY PEELING OR DETERIORATION OF TAPE IS EVIDENT. REPAIR DAMAGE PER SRM 51-70 NO LATER THAN THE NEXT "C" CHECK.
- B REMOVE MOISTURE FROM DAMAGE AREA. USE OF VACUUM AND HEAT (MAX OF 125°F (52°C)) TO REMOVE MOISTURE FROM HONEYCOMB CELLS IS RECOMMENDED. PROTECT DAMAGE FROM ENTRANCE OF WATER, SUNLIGHT OR OTHER FOREIGN MATTER BY SEALING WITH ALUMINUM FOIL TAPE (SPEED TAPE) 3M-Y436 OR EQUIVALENT. RECORD LOCATION AND INSPECT AIRPLANE EVERY 100 HOURS. REPLACE ALUMINUM FOIL TAPE IF ANY PEELING OR DETERIORATION OF TAPE IS EVIDENT. REPAIR DAMAGE PER SRM 51-70 BEFORE THE EXPIRATION OF 60 CALENDAR DAYS.
- C 2.0 INCHES (50 mm) MAX DIMENSION (D) IN HONEYCOMB AREA IS ALLOWED PER SQUARE FOOT (930 SQUARE cm) AREA AND A MINIMUM OF 6D (EDGE TO EDGE) FROM ANY OTHER CRACK, FITTING OR FASTENER HOLE AND A MINIMUM OF 6.0 INCHES (150 mm) FROM MATERIAL EDGE.
- D CLEAN UP EDGE CRACKS PER DETAILS VII AND X. CLEAN UP CORNER CRACKS PER DETAIL XI. OTHER CRACKS NOT ALLOWED. B
- E CLEAN UP EDGE CRACKS PER DETAILS VII AND XIII. CLEAN UP CORNER CRACKS PER DETAIL XI. OTHER CRACKS NOT ALLOWED.

- F DAMAGE ALLOWED ON SURFACE RESIN ONLY. DAMAGED TO FIBERS NOT ALLOWED. PROTECT EDGE DAMAGE PER B.
- G DAMAGE ALLOWED ON SURFACE RESIN ONLY. DAMAGE TO FIBERS NOT ALLOWED. PROTECT EDGE DAMAGE PER A .
- H CLEAN UP DAMAGE PER DETAILS VII, VIII, AND X. CLEAN UP CORNER DAMAGE PER DETAIL XI.
- I CLEAN UP EDGE DAMAGE PER DETAILS VII AND X. CLEAN UP LUG DAMAGE PER DETAIL XII. CLEAN UP OTHER DAMAGE PER DETAIL VIII.
- J REMOVE DAMAGE PER DETAILS VII, VIII, AND XIII.
- K DENTS GENERALLY RESULT IN FIBER DAMAGE OR DELAMINATION. HOWEVER, PROVIDED THAT THERE IS NO FIBER DAMAGE OR DELAMINATION DENTS UP TO 2.0 INCHES (50 mm) DIA MAX ARE ALLOWED. ONE DENT PER SQUARE FOOT (930 SQUARE cm) OF AREA ALLOWED WHICH MUST BE A MINIMUM OF 6.0 INCHES (150 mm) FROM ANY OTHER DAMAGE, FASTENER HOLE OR PANEL EDGE. REFER TO APPLICABLE DAMAGE DATA IN TABLE IF FIBER DAMAGE OR DELAMINATION EXISTS.
- L SEE DETAIL XIV.

Allowable Damage - Main Landing Gear Door Figure 101 (Sheet 7 of 10)



Page 107

Jan 20/2005

BOEING

#### 757-200 STRUCTURAL REPAIR MANUAL

#### NOTES (CONT)

- M 2.0 MAX DIMENSION (D) IN HONEYCOMB AREA IS ALLOWED PER SQUARE FOOT OF AREA AND A MINIMUM OF 6D (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FITTING OR FASTENER HOLE, AND A MINIMUM OF 6.0 INCHES FROM MATERIAL EDGE. DO NOT CLEAN UP DAMAGE EXCEPT TO REMOVE RESIN BURRS EXTENDING INTO SURFACE. B
- N 2.0 MAX DIMENSION (D) IN HONEYCOMB AREA IS ALLOWED PER SQUARE FOOT OF AREA AND A MINIMUM OF 6D (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR FITTING. DO NOT CLEAN UP DAMAGE EXCEPT TO REMOVE RESIN BURRS EXTENDING INTO SURFACE.
- 0 2.0 MAX DIMENSION (D) IN "HEAT SHIELD" ALLOWED PER SQUARE FOOT OF AREA AND A MINIMUM OF 6D (EDGE TO EDGE) FROM ANY OTHER DAMAGE OR MATERIAL EDGE. DO NOT CLEAN UP DAMAGE EXCEPT TO REMOVE RESIN BURRS EXTENDING INTO SURFACE CONTOUR AND PROTECT DAMAGE PER A.
- P 2.0 MAX DIMENSION (D) DELAMINATION IN HONEYCOMB AREA IS ALLOWED PER SQUARE FOOT OF AREA AND A MINIMUM OF 6D (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FITTING OR FASTENER HOLE, AND A MINIMUM OF 6.0 FROM PANEL EDGE. REPAIR DELAMINATION IN HONEYCOMB AREA AS GIVEN IN SRM 51-70 BEFORE THE EXPIRATION OF 60 CALENDAR DAYS. PROTECT EDGE DAMAGE PER в.
- Q 2.0 MAX DIMENSION (D) DELAMINATION IN HONEYCOMB AREA IS ALLOWED PER SQUARE FOOT OF AREA AND A MINIMUM OF 6D (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FITTING OR FASTENER HOLE. REPAIR DELAMINATION IN HONEYCOMB AREA AS GIVEN IN SRM 51-70 NO LATER THAN THE NEXT "C" CHECK. PROTECT EDGE DAMAGE PER A.
- R SHOT PEEN REWORKED AREAS AS GIVEN IN SRM 51-20-06 SHOT PEEN INTENSITIES WILL VARY WITH THE THICKNESS REMAINING AFTER REWORK.
- S 12.0 MAX DIMENSION ALLOWED. MAXIMUM DEPTH OF DAMAGE, 0.50. PROTECT DAMAGE PER B
- T 2.0 MAX DIMENSION (D) IN HONEYCOMB AREA IS ALLOWED PER SQUARE FOOT AREA AND A MINIMUM OF 6D (EDGE TO EDGE) FROM ANY OTHER DAMAGE, MATERIAL EDGE OR FASTENER HOLE. A


- U DAMAGE ALLOWED ON SURFACE RESIN ONLY. DAMAGE TO FIBERS NOT ALLOWED. PROTECT EDGE DAMAGE PER A .
- V 2.0 MAX DIMENSION (D) DELAMINATION IN HONEYCOMB AREA IS ALLOWED PER SQUARE FOOT OF AREA AND A MINIMUM OF 6D (EDGE TO EDGE) FROM ANY OTHER DAMAGE OR MATERIAL EDGE. REPAIR DELAMINATION IN HONEYCOMB AREA AS GIVEN IN SRM 51-70 NO LATER THAN THE NEXT "C" CHECK. PROTECT EDGE DAMAGE PER A.
- W HEAT SHIELD ON THE RH DOOR IS CENTERED AT RBL 53.75.
- Х FOR CUM LINE NUMBERS: 1 THRU 36
- Y FOR CUM LINE NUMBERS: 37 AND ON
- AA FOR ONE-PIECE DOOR AND TANG. REFER TO FIGURE 1.
- FOR TWO-PIECE DOOR AND TANG. REFER TO AB FIGURE 1.

Allowable Damage - Main Landing Gear Door Figure 101 (Sheet 8 of 10)



Page 108 Jan 20/2005






D634N201 52-80-02

Page 109

Jan 20/2005




757-200 STRUCTURAL REPAIR MANUAL







#### ALLOWABLE DAMAGE 2 - NOSE LANDING GEAR DOOR





DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES	DELAMINATION
DOOR PANELS	В	C	D	E	F
HINGE FITTINGS	G	H	NOT ALLOWED	NOT ALLOWED	
DOOR STOP FITTING	G	Н	NOT ALLOWED	NOT ALLOWED	
DOOR SUPPORT FITTING	G	H	NOT ALLOWED	NOT ALLOWED	
ROD ATTACH FITTING	G	H	NOT ALLOWED	NOT ALLOWED	
ALIGNMENT FITTING	G	H	NOT ALLOWED	NOT ALLOWED	
SCUFF PLATE		К	К		

NOTES

- REFINISH REWORKED AREAS PER AMM 51-20
- REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- CONDUCTIVE COATING ON ALL DOOR PANELS. FOR ALLOWABLE DAMAGE TO CONDUCTIVE COATING REFER TO AMM 51-20.
- TYPICAL DAMAGE TO A PANEL EDGEBAND MAY CONSIST OF EDGE CRUSHING, CRACKS OR DELAMI-NATION. DAMAGE AROUND HOLES MAY CONSIST OF OVALIZATION, FASTENER PULL-THROUGH OR CRACKS OUT OF HOLE. DAMAGE MAY REDUCE THE EFFECTIVE CROSS SECTIONAL AREA OF AN EDGE-BAND. DAMAGE TO EDGES SHOULD BE BLENDED OUT TO LIMITATIONS GIVEN FOR COMPONENT
- A PROTECT DAMAGE FROM ENTRANCE OF WATER, SUNLIGHT OR OTHER FOREIGN MATTER BY SEAL-ING WITH ALUMINUM FOIL TAPE (SPEED TAPE) 3M-Y436 OR EQUIVALENT. RECORD LOCATION AND INSPECT AT AIRPLANE "A" CHECK. REPLACE ALUMINUM FOIL TAPE IF ANY PEELING OR DETERIORATION OF TAPE IS EVIDENT. REPAIR DAMAGE PER SRM 51-70 NO LATER THAN THE NEXT "C" CHECK.
- B 0.50 MAX LENGTH IN HONEYCOMB AREA IS ALLOWED PER SQUARE FOOT OF AREA AND A MINIMUM OF 6 INCHES FROM ANY OTHER CRACK. EDGE CRACKS MUST BE REMOVED PER DETAILS III AND V. A
- C DAMAGE ALLOWED ON SURFACE RESIN ONLY. DAMAGE TO FIBERS NOT ALLOWED. CLEAN\_UP EDGE DAMAGE PER DETAILS III AND V. A
- D DENTS GENERALLY RESULT IN FIBER DAMAGE OR DELAMINATION. HOWEVER, IF THERE IS NO FIBER DAMAGE OR DELAMINATION, DENTS UP TO 1.10 DIA MAX ARE ALLOWED, ONE DENT PER

SQUARE FOOT OF AREA ALLOWED WHICH MUST BE A MINIMUM OF 6 INCHES FROM ANY OTHER DAMAGE, FASTENER HOLE, OR PANEL EDGE. SEE OR F IF FIBER DAMAGE OR DELAMINATION IS PRESENT

- E 0.50 MAX DIA IN HONEYCOMB AREA ONLY PRO-VIDED DAMAGE IS MIN OF 2.5 D FROM OTHER DAMAGE, NEAREST HOLE, OR MATERIAL EDGE. DO NOT CLEAN UP DAMAGE EXCEPT TO REMOVE RESIN BURRS EXTENDING INTO SURFACE CONTOUR. A
- F 0.50 MAX DIA IN HONEYCOMB AREA AND NOT TO EXCEED 25% OF HONEYCOMB CORE LENGTH PER SIDE. A MAXIMUM OF 0.03 DELAMINATION FROM EDGE IS ALLOWED. REPAIR DELAMINATION IN HONEYCOMB AREA PER SRM 51-70 AND NO LATER THAN THE NEXT AIRPLANE "C" CHECK. PROTECT EDGE DAMAGE PER A.
- G CLEAN UP EDGE CRACKS PER DETAILS III AND VI. CLEAN UP CORNER CRACKS PER DETAIL VII. OTHER CRACKS NOT ALLOWED. SEE DETAILS I AND II FOR APPLICABLE SHOT PEEN REQUIREMENTS.
- H CLEAN UP EDGE DAMAGE PER DETAILS III, IV AND V. CLEAN UP CORNER DAMAGE PER DETAIL VII. CLEAN UP LUG DAMAGE PER DETAIL VIII. CLEAN UP OTHER DAMAGE PER DETAIL IV. DAMAGE NOT ALLOWED IN VICINITY OF BUSHINGS. SEE DETAILS I AND II FOR APPLICABLE SHOT PEEN REQUIREMENTS.
- I SHOT PEEN REWORKED AREAS PER SRM 51-20-06. SHOT PEEN INTENSITIES WILL VARY WITH THE THICKNESS REMAINING AFTER REWORK
- J CRITICAL AREA (SHADED). ALLOWABLE DAMAGE SAME AS ON REST OF PANEL, EXCEPT INSPECT EVERY "A" CHECK AND REPAIR WITHIN 90 DAYS

Allowable Damage - Nose Landing Gear Door Figure 101 (Sheet 2 of 5)



Page 102 Jan 20/2005




NOTES (CONTINUED)

- K A MISSING SCUFF PLATE IS PERMITTED. REMOVE AND DISCARD A DAMAGED OR LOOSE SCUFF PLATE AS GIVEN IN SRM 52-80-02, REPAIR 4, FLAGNOTE E. CHECK FOR DAMAGE IN THE DOOR PANEL IN THE AREA WHERE THE SCUFF PLATE WAS REMOVED.
- L FOR CUM LINE NUMBERS: 805 THRU 869

Allowable Damage - Nose Landing Gear Door Figure 101 (Sheet 3 of 5)














Allowable Damage - Nose Landing Gear Door Figure 101 (Sheet 5 of 5)

DAMAGE CLEANUP AND SEALING OF EDGE EROSION DETAIL IX

EXISTING PLIES


2 PLIES MAXIMUM

DAMAGE ALLOWED





#### ALLOWABLE DAMAGE 3 - MAIN LANDING GEAR STRUT DOOR



Allowable Damage - Main Landing Gear Strut Door Figure 101 (Sheet 1 of 5)



Page 101 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL

DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES	DELAMI- NATION	EDGE EROSION
DOOR PANEL	В	C	D	E	F	SEE DETAIL IX
PLATE SERRATED	G	Н	SEE DETAIL IV	NOT ALLOWED		
ATTACHMENT FITTINGS	Ι	J	NOT ALLOWED	NOT ALLOWED		
CENTER FITTINGS	I	J	NOT ALLOWED	NOT ALLOWED		
BEAM FITTING	К	L	NOT ALLOWED	NOT ALLOWED		
FWD FITTING	K	L	NOT ALLOWED	NOT ALLOWED		
STIFFENER FITTINGS	К	L	NOT ALLOWED	NOT ALLOWED		

#### NOTES

- REFINISH REWORKED AREAS PER AMM 51-20
- REFER TO SRM 51-10-01 FOR AERODYNAMIC ٠ SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- REFER TO SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- DAMAGE TO PANEL EDGES MAY BE CONFINED TO DELAMINATION OR MAY TAKE A FORM WHICH RESULTS IN DAMAGE TO FIBERS AND A LOSS OF EFFECTIVE CROSS-SECTIONAL AREA. THIS TYPE OF DAMAGE SHOULD BE REMOVED AND THE LIMITATIONS GIVEN FOR CRACKS APPLIED
- A REMOVE MOISTURE FROM DAMAGE AREA. USE VACUUM AND HEAT (MAX OF 125°F (52°C)) TO REMOVE MOISTURE FROM HONEYCOMB CELLS IS RECOMMENDED. PROTECT DAMAGE FROM ENTRANCE OF WATER, SUNLIGHT OR OTHER FOREIGN MATTER BY SEALING WITH ALUMINUM FOIL TAPE (SPEED TAPE) 3M-Y436 OR EQUIVALENT. RECORD LOCATION AND INSPECT AT AIRPLANE "A" CHECK. REPLACE ALUMINUM FOIL TAPE IF ANY PEELING OR DETERIORATION OF TAPE IS EVIDENT. REPAIR DAMAGE PER SRM 51-70 NO LATER THAN THE NEXT "C" CHECK

- B 2.0 INCHES (50 mm) MAX LENGTH ALLOWED IN HONEYCOMB AREA PER SQUARE FOOT (930 SQUARE cm) OF AREA AND A MINIMUM OF 6 INCHES (150 MM) FROM ANY OTHER CRACK. CLEAN UP EDGE CRACKS PER DETAILS II AND IV. CRACKS THROUGH CONSECUTIVE FASTENERS OR THROUGH THE PANEL EDGEBAND ARE ALLOWED PROVIDED DAMAGE DOES NOT EXCEED 10% OF EDGEBAND LENGTH PER SIDE A
- C DAMAGE ALLOWED ON SURFACE RESIN ONLY. DAMAGE TO FIBERS NOT ALLOWED. CLEAN UP EDGE DAMAGE PER DETAILS II AND VI A

Allowable Damage - Main Landing Gear Strut Door Figure 101 (Sheet 2 of 5)



Page 102 Jan 20/2005




- D DENTS GENERALLY RESULT IN FIBER DAMAGE OR DELAMINATION. HOWEVER, PROVIDED THAT THERE IS NO FIBER DAMAGE OR DELAMINATION, DENTS UP TO 1.00 DIA MAX ARE ALLOWED. ONE DENT PER SQUARE FOOT OF AREA ALLOWED WHICH MUST BE A MINIMUM OF 6 INCHES FROM ANY OTHER DAMAGE, FASTENER HOLE, OR PANEL EDGE. SEE E OR F IF FIBER DAMAGE OR DELAMINATION IS PRESENT
- E 1.00 MAX DIA ALLOWED PROVIDED DAMAGE IS MIN OF 3.0 D FROM OTHER DAMAGE, NEAREST HOLE, OR MATERIAL EDGE. DO NOT CLEAN UP DAMAGE EXCEPT TO REMOVE RESIN BURRS EXTENDING INTO SURFACE CONTOUR A
- F 1.00 INCH MAX DIA IS ALLOWED IN HONEYCOMB AREA. A MAXIMUM OF 0.10 INCH DELAMINATION FROM EDGE IS ALLOWED. REPAIR DELAMINATION IN HONEYCOMB AREA PER 51-70 NO LATER THAN THE NEXT "C" CHECK. PROTECT EDGE DAMAGE PER A
- G CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAILS II AND VI
- H REMOVE DAMAGE PER DETAILS II, III AND V
- I CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAIL VIII
- J FOR EDGE DAMAGE SEE DETAIL VIII. FOR LUG DAMAGE SEE DETAIL VII. FOR OTHER DAMAGE SEE DETAIL III. DAMAGE NOT ALLOWED IN VICINITY OF BUSHINGS
- K CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAIL VIII. SEE DETAIL I FOR APPLICABLE SHOT PEEN REQUIREMENTS
- L FOR EDGE DAMAGE SEE DETAIL VIII. FOR LUG DAMAGE SEE DETAIL VII. FOR OTHER DAMAGE SEE DETAIL III. DAMAGE NOT ALLOWED IN VICINITY OF BUSHINGS. SEE DETAIL I FOR APPLICABLE SHOT PEEN REQUIREMENTS
- M SHOT PEEN REWORKED AREA PER 51-20-06. SHOT PEEN INTENSITIES WILL VARY WITH THE THICKNESS REMAINING AFTER REWORK

Allowable Damage - Main Landing Gear Strut Door Figure 101 (Sheet 3 of 5)








ALLOWABLE DAMAGE 3 **52-80-02** Page 104 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL




Allowable Damage - Main Landing Gear Strut Door Figure 101 (Sheet 5 of 5)





#### ALLOWABLE DAMAGE 4 - TRUNNION FAIRING DOOR



DESCRIPTION	CRACKS	NICKS, GOUGES AND CORROSION	DENTS	HOLES AND PUNCTURES	DELAMI- NATION	EDGE EROSION
TRUNNION DOOR PANEL	В	C	D	E	F	SEE DETAIL II
HINGE	Ι	G	NOT ALLOWED	NOT ALLOWED		
SUPPORT FITTING	I	G	NOT ALLOWED	NOT ALLOWED		

Allowable Damage - Trunnion Fairing Door Figure 101 (Sheet 1 of 4)








#### NOTES

- REFINISH REWORKED AREAS PER AMM 51-20 OF THE MAINTENANCE MANUAL
- REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED
- REFER TO SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE
- TYPICAL DAMAGE TO A PANEL EDGEBAND MAY CONSIST OF EDGE CRUSHING, CRACKS OR DELAMINATION. DAMAGE AROUND HOLES MAY CONSIST OF OVALIZATION, FASTENER PULL-THROUGH OR CRACKS OUT OF HOLE. DAMAGE MAY REDUCE THE EFFECTIVE CROSS-SECTIONAL AREA OF AN EDGEBAND. DAMAGE TO EDGES SHOULD BE BLENDED OUT TO LIMITATIONS GIVEN FOR COMPONENT
- A REMOVE MOISTURE FROM DAMAGE AREA. USE OF VACUUM AND HEAT (MAX OF 125°F (52°C)) TO REMOVE MOISTURE FROM HONEYCOMB CELLS IS RECOMMENDED. PROTECT DAMAGE FROM ENTRANCE OF WATER, SUNLIGHT OR OTHER FOREIGN MATTER BY SEALING WITH ALUMINUM FOIL TAPE (SPEED TAPE). RECORD LOCATION AND INSPECT AT AIRPLANE "A" CHECK. REPLACE ALUMINUM FOIL TAPE IF ANY PEELING OR DETERIORATION OF TAPE IS EVIDENT. REPAIR DAMAGE PER SRM 51-70 NO LATER THAN THE NEXT "C" CHECK
- B 0.50 (12.7 mm) MAX LENGTH IN HONEYCOMB AREA ALLOWED PER SQUARE FOOT OF AREA AND A MINIMUM OF 6 INCHES (150 mm) FROM ANY OTHER DAMAGE. CLEAN UP EDGE CRACKS PER DETAIL VI. CRACKS THROUGH CONSECUTIVE FASTENERS OR THROUGH THE PANEL EDGEBAND ARE ALLOWED PROVIDED DAMAGE DOES NOT EXCEED 10% OF EDGEBAND LENGTH PER SIDE A
- C DAMAGE ALLOWED ON SURFACE RESIN ONLY. DAMAGE TO FIBERS NOT ALLOWED. CLEAN UP EDGE DAMAGE PER DETAILS III, VI A
- D DENTS GENERALLY RESULT IN FIBER DAMAGE OR DELAMINATION. HOWEVER, IF THERE IS NO FIBER DAMAGE OR DELAMINATION, DENTS UP TO 2.25 SQUARE INCH (14.5 SQUARE cm) AREA ARE ALLOWED. ONE DENT PER SQUARE FOOT (930 SQUARE cm) OF AREA ALLOWED WHICH MUST BE A MINIMUM OF 6 INCHES (150 mm) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR PANEL EDGE. SEE [] OR[] IF FIBER DAMAGE OR DELAMINATION IS PRESENT

- E 0.50 INCH (12.7 mm) MAX DIA ALLOWED PROVIDED DAMAGE IS MIN OF 3.0D FROM OTHER DAMAGE, NEAREST HOLE, OR MATERIAL EDGE. DO NOT CLEAN UP DAMAGE EXCEPT TO REMOVE RESIN BURRS EXTENDING INTO SURFACE CONTOUR A
- F 0.50 INCH (12.7 mm) MAX DIA IS ALLOWED IN HONEYCOMB AREA. A MAXIMUM OF 0.03 INCH (0.75 mm) DELAMINATION FROM EDGE IS ALLOWED. REPAIR DELAMINATION IN HONEYCOMB AREA PER SRM 51-70 NO LATER THAN THE NEXT "C" CHECK. PROTECT EDGE DAMAGE PER A
- G FOR EDGE DAMAGE SEE DETAIL VI. FOR LUG DAMAGE SEE DETAIL IV. FOR OTHER DAMAGE SEE DETAIL V. DAMAGE NOT ALLOWED IN VICINITY OF BUSHINGS. SEE DETAIL I FOR APPLICABLE SHOT PEEN REQUIREMENTS
- H SHOT PEEN REWORKED AREAS PER SRM 51-20-06. SHOT PEEN INTENSITIES WILL VARY WITH THE THICKNESS REMAINING AFTER REWORK
- I CRACKS NOT ALLOWED EXCEPT FOR EDGE CRACKS WHICH MUST BE REMOVED PER DETAIL V



## OF EDGE EROSION

DETAIL II


Allowable Damage - Trunnion Fairing Door Figure 101 (Sheet 2 of 4)








757-200 STRUCTURAL REPAIR MANUAL



X = DEPTH OF CLEANUP = 0.10 MAX


REMOVAL OF NICK OR CRACK DAMAGE OF AN EDGE DETAIL III








757-200 STRUCTURAL REPAIR MANUAL







DAMAGE CLEANUP OF EDGES WHERE

FASTENER EDGE MARGINS DO NOT OVERLAP

DAMAGE CLEANUP OF EDGES WHERE FASTENER EDGE MARGINS OVERLAP

BOUNDARY OF CLEANED

OF REWORKED PORTION

DETERMINED BY DEPTH

OF DAMAGE R = 1.0 MIN

(REF)

FASTENER EDGE

MARGIN BOUNDARY

UP FLANGE. RADIUS


DETAIL VI

Allowable Damage - Trunnion Fairing Door Figure 101 (Sheet 4 of 4)





#### **REPAIR 1 - MAIN LANDING GEAR STRUT DOOR**



Main Landing Gear Strut Door Figure 201 (Sheet 1 of 2)



REPAIR 1 Page 201 Jan 20/2005



	INTERIM REPAIRS B	PERMANENT REPAIRS			
DAMAGE	WET LAYUP ROOM TEMP (SRM 51-70-03)	WET LAYUP 150°F (66°C)CURE (SRM 51-70-03)	WET LAYUP 200°F (93°C)CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-05)	
CRACKS	UP TO 3.0 INCHES (75 mm) LONG, REPAIR WITH PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE	
HOLES	3.0 INCHES (75 mm) MAX DIA NOT TO EXCEED 30% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N.A	6.0 INCHES (150 mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH FACESHEET REPAIRED C	12.0 INCHES (300 mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH FACESHEET REPAIRED C	NO SIZE LIMIT	
EDGE EROSION		IN SRM 51-70-03, PAR. 5	THAN 35% OF EDGEBAND THI 5.0. FOR LARGER DAMAGE, SRM 51-70-17, PAR. 4.G.		
DELAMI- NATION	CUT OUT AND REPAIR AS A HOLE				
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE				
DENTS	UP TO 2.0 INCHES (50 mm) DIA WITH NO FIBER DAMAGE OR DELAMINATION, FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.L.C OVER 2.0 INCHES (50 mm) DIA OR WITH FIBER DAMAGE OR DELAMINATION, REPAIR AS A HOLE				

# REPAIR DATA FOR 250°F (121°C) CURE HONEYCOMB PANELS TABLE I

#### NOTES

- WHEN YOU USE THIS REPAIR, REFER TO:
  - AMM 51-21-01 FOR APPLICATION OF FINISHES
  - SRM 51-10-01, FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE IS MORE THAN THE LIMITS GIVEN IN SRM 51-10-01, THOUGHT SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE THAT MAY OCCUR.
- A LIMITED TO REPAIR OF DAMAGE TO ONE FACESHEET SKIN AND HONEYCOMB CORE. ONE REPAIR FOR EACH SQUARE FOOT (930 SQUARE cm) OF AREA AND MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR EDGE OF PANEL
- B INSPECT INTERIM REPAIR USING INSTRUMENTED NDT METHODS OR "TAP" TEST EVERY AIRPLANE "2A" CHECK. FOR "TAP" TEST, USE A SOLID METAL DISK AND TAP THE REPAIR AREA LIGHTLY BUT FIRMLY. VOID AREAS WILL GIVE A DULL SOUND INSTEAD OF A SHARP RING THAT YOU WILL HEAR ON A SOLID BONDED AREA. PERMANENT REPAIR IS REQUIRED IF ANY DETERIORATION IS FOUND. REFER TO SRM 51-70-03, PAR. 4.I. AND THE NONDESTRUCTIVE TEST MANUAL
- C ONE REPAIR FOR EACH SQUARE FOOT (930 SQUARE cm) OF AREA AND A MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, EDGE OF PANEL, OR A MINIMUM OF 2.0 INCHES (50 mm) FROM TAPERED EDGE OF HONEYCOMB CORE

Main Landing Gear Strut Door Figure 201 (Sheet 2 of 2)




REPAIR 1 Page 202 Jan 20/2005






#### **REPAIR 2 - TRUNNION FAIRING DOOR**



REF DWG 113N1800



#### DETAIL I

Trunnion Fairing Door Figure 201 (Sheet 1 of 2)



REPAIR 2 Page 201 Jan 20/2005





	INTERIM REPAIRS B	PERMANENT REPAIRS			
DAMAGE	WET LAYUP ROOM TEMP (SRM 51-70-03)	WET LAYUP 150°F (66°C)CURE (SRM 51-70-03)	WET LAYUP 200°F (93°C)CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-05)	
CRACKS	UP TO 3.0 INCHES (75 mm) LONG, REPAIR WITH PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE	
HOLES	3.0 INCHES (75 mm) MAX DIA NOT TO EXCEED 30% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N.A	6.0 INCHES (150 mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH FACESHEET REPAIRED C	DIMENSION ACROSS	NO SIZE LIMIT	
EDGE EROSION		IN SRM 51-70-03, PAR. 5	HAN 35% OF EDGEBAND THIC .O. FOR LARGER DAMAGE, SRM 51-70-17, PAR. 4.G.		
DELAMI- NATION	CUT OUT AND REPAIR AS A HOLE				
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF YOU FIND FIBER DAMAGE OR DELAMINATION, THEN REPAIR AS A HOLE				
DENTS	UP TO 2.0 INCHES (50 mm) DIA WITH NO FIBER DAMAGE OR DELAMINATION, FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.L.C OVER 2.0 INCHES (50 mm) DIA OR WITH FIBER DAMAGE OR DELAMINATION, REPAIR AS A HOLE				

## REPAIR DATA FOR 250°F (121°C) CURE HONEYCOMB PANELS TABLE I

#### NOTES

- WHEN YOU USE THIS REPAIR, REFER TO:
  - AMM 51-21-01 FOR APPLICATION OF FINISHES
  - SRM 51-10-01, FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE IS MORE THAN THE LIMITS GIVEN IN SRM 51-10-01, THOUGHT SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE THAT MAY OCCUR.
- A LIMITED TO REPAIR OF DAMAGE TO ONE FACESHEET SKIN AND HONEYCOMB CORE. ONE REPAIR FOR EACH SQUARE FOOT (930 SQUARE cm) OF AREA AND MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR EDGE OF PANEL
- B INSPECT INTERIM REPAIR USING INSTRUMENTED NDT METHODS OR "TAP" TEST EVERY AIRPLANE "2A" CHECK. FOR "TAP" TEST, USE A SOLID METAL DISK AND TAP THE REPAIR AREA LIGHTLY BUT FIRMLY. VOID AREAS WILL GIVE A DULL SOUND INSTEAD OF A SHARP RING THAT YOU WILL HEAR ON A SOLID BONDED AREA. PERMANENT REPAIR IS REQUIRED IF ANY DETERIORATION IS EVIDENT. REFER TO SRM 51-70-03, PAR. 4.I. AND THE NONDESTRUCTIVE TEST MANUAL
- C ONE REPAIR FOR EACH SQUARE FOOT (930 SQUARE cm) OF AREA AND A MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, EDGE OF PANEL, OR A MINIMUM OF 2.0 INCHES (50 mm) FROM TAPERED EDGE OF HONEYCOMB CORE


Trunnion Fairing Door Figure 201 (Sheet 2 of 2)



REPAIR 2 Page 202 Jan 20/2005




#### **REPAIR 3 - MAIN LANDING GEAR DOOR**






REPAIR 3 Page 201 Jan 20/2005



REPAIR 3 Page 202 Jan 20/2005

52-80-02



Main Landing Gear Doors Figure 201 (Sheet 3 of 8)




REPAIR 3 Page 203 Jan 20/2005

D634N201



757-200 STRUCTURAL REPAIR MANUAL






REPAIR 3 Page 204 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL




Main Landing Gear Doors Figure 201 (Sheet 5 of 8)



REPAIR 3 Page 205 Jan 20/2005



757-200 STRUCTURAL REPAIR MANUAL



SECTION THRU COLD WRAPPED FIBERGLASS EDGE (TYPICAL)

#### REPAIR OF FIBERGLASS WRAPPED EDGE

- 1. Remove plies in the damaged area.
- 2. Remove water and debris using vacuum and oil-free compressed air.
- 3. Clean damaged area with MIBK, MEK, or acetone.
- Taper sand existing fiberglass edge plies allowing 0.50-inch overlap for each repair ply.
- Apply one ply of BMS 9-3, Type H fiberglass for each damaged ply using BMS 8-201, Type II resin.
- 6. Cure repair as given in SRM 51-70-06.
- 7. Lightly sand the edge of the topmost repair ply to fair the edge.
- Restore original finish as given in Chapter 51 of the Maintenance Manual.

DETAIL VI

Main Landing Gear Doors Figure 201 (Sheet 6 of 8)




REPAIR 3 Page 206 Jan 20/2005



	INTERIM REPAIRS B D	PERMANENT REPAIRS			
DAMAGE	WET LAYUP 150°F (66°C)CURE (SRM 51-70-03)	WET LAYUP 200°F (93°C)CURE (SRM 51-70-17)D	250°F (121°C) CURE (SRM 51-70-05) D	350°F (177°C) CURE (SRM 51-70-04)	
CRACKS	UP TO 3.0 INCHES (75 mm) LONG, REPAIR WITH PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N.A	CLEAN UP DAMAGE AND REPAIR AS HOLE.	CLEAN UP DAMAGE AND REPAIR AS HOLE.	CLEAN UP DAMAGE AND REPAIR AS HOLE.	
HOLES	3.0 INCHES (75 mm) MAX DIA NOT TO EXCEED 30% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N. A	12.0 INCHES (300 mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH FACESHEET REPAIRED C	6.0 INCHES (150 mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH FACESHEET REPAIRED C	NO SIZE LIMIT	
DELAMI- NATION	CUT OUT AND REPAIR AS HOLE.				
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES PER SRM 51-70-03. IF FIBER DAMAGE OR DELAMINATION EXISTS, REPAIR AS A HOLE.				
DENTS	UP TO 2.0 INCH (50 mm) DIA WITH NO FIBER DAMAGE OR DELAMINATION, FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.L. C OVER 2.0 INCHES (50 mm) DIA OR WITH FIBER DAMAGE OR DELAMINATION, REPAIR AS A HOLE				

#### REPAIR DATA FOR 350°F ( 177°C) CURE HONEYCOMB PANELS TABLE I

Main Landing Gear Doors Figure 201 (Sheet 7 of 8)



**REPAIR 3** 



#### NOTES

- REFINISH REWORKED AREAS AS GIVEN IN 51-20 OF THE MAINTENANCE MANUAL.
- REFER TO SRM 51-10-02 FOR INSPECTION AND REMOVAL OF DAMAGE.
- REFER TO SRM 51-10-01 FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE EXCEEDS THE LIMITS SHOWN IN SRM 51-10-01, CONSIDERATION SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE INVOLVED.
- REFER TO SRM 51-70-06 FOR GLASS FABRIC REINFORCED EPOXY LAMINATE AND NONMETALLIC HONEYCOMB SANDWICH REAIRS.
- A LIMITED TO REPAIR OF DAMAGE TO ONE FACE-SHEET SKIN AND HONEYCOMB CORE. ONE REPAIR PER SQUARE FOOT (930 SQUARE cm) OF AREA AND MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR EDGE OF PANEL.
- B INSPECT INTERIM REPAIR USING INSTRUMENTED NDI METHODS OR "TAP" TEST EVERY AIRPLANE "2A" CHECK. FOR "TAP" TEST, USE A SOLID METAL DISK AND TAP THE REPAIR AREA LIGHTLY BUT FIRMLY. VOID AREAS WILL PRODUCE A DULL SOUND AS OPPOSED TO A SHARP RING ON A SOLID BONDED AREA. PERMANENT REPAIR IS REQUIRED IF ANY DETERIORATION IS EVIDENT. REFER TO SRM 51-70-03, PAR. 4.I. AND THE NONDESTRUCTIVE TEST MANUAL, D634N301.
- C ONE REPAIR PER SQUARE FOOT (930 cm) OF AREA AND A MINIMUM OF 6.0 INCHES (150 cm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR EDGE OF PANEL.
- CONTACT THE BOEING COMPANY FOR REPAIR INFORMATION IN CRITICAL AREAS. INTERIM, 200°F (93°C), AND 250°F (121°C) CURE REPAIRS ARE NOT ALLOWED IN CRITICAL AREAS UNLESS SPECIFICALLY APPROVED BY THE BOEING COMPANY.
- E HEAT SHIELD ON THE RH DOOR IS CENTERED AT RBL 53.75.
- F FOR CUM LINE NUMBERS: 1 THRU 36
- G FOR CUM LINE NUMBERS: 37 AND ON
- H FOR ONE-PIECE DOOR AND TANG. SEE DETAIL I.
- I FOR TWO-PIECE DOOR AND TANG. SEE DETAIL IV.


Main Landing Gear Doors Figure 201 (Sheet 8 of 8)



REPAIR 3 Page 208 Jan 20/2005



#### **REPAIR 4 - NOSE LANDING GEAR DOORS**



BOEING PROPRIETARY - Copyright () Unpublished Work - See title page for details



	INTERIM REPAIRS B	PERMANENT REPAIRS			
DAMAGE	WET LAYUP ROOM TEMP (SRM 51-70-03)	WET LAYUP 150°F (66°C)CURE (SRM 51-70-03)	WET LAYUP 200°F (93°C)CURE (SRM 51-70-17)	250°F (121°C) CURE (SRM 51-70-05)	
CRACKS	UP TO 3.0 INCHES (75 mm) LONG, REPAIR WITH PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N.A	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE	CLEAN UP DAMAGE AND REPAIR AS A HOLE	
HOLES	3.0 INCHES (75 mm) MAX DIA NOT TO EXCEED 30% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.N.A	6.0 INCHES (150 mm) MAXIMUM DIA NOT TO EXCEED 50% OF SMALLEST DIMENSION ACROSS HONEYCOMB PANEL AT THE DAMAGE LOCATION. USE TWO EXTRA PLIES FOR EACH FACESHEET REPAIRED C	DIMENSION ACROSS	NO SIZE LIMIT	
EDGE EROSION		FOR DAMAGE NOT THAT IS LARGER THAN 35% OF EDGEBAND THICKNESS, REPAIR AS GIVEN IN SRM 51-70-03, PAR. 5.0. FOR LARGER DAMAGE, REPAIR AS GIVEN IN: SRM 51-70-03, PAR. 5.G. SRM 51-70-17, PAR. 4.G. SRM 51-70-05, PAR. 5.G.			
DELAMI- NATION	CUT OUT AND REPAIR AS A HOLE D				
NICKS AND GOUGES	IF THERE IS NO FIBER DAMAGE OR DELAMINATION, FILL NICKS OR GOUGES AS GIVEN IN SRM 51-70-03 IF FIBER DAMAGE OR DELAMINATION EXISTS, REPAIR AS A HOLE				
DENTS	UP TO 2.0 INCHES (50 mm) DIA WITH NO FIBER DAMAGE OR DELAMINATION, FILL WITH BMS 5-28, TYPE 7 POTTING COMPOUND AND PATCH AS GIVEN IN SRM 51-70-03, PAR. 5.L.C OVER 2.0 INCHES (50 mm) DIA OR WITH FIBER DAMAGE OR DELAMINATION, REPAIR AS A HOLE				

#### REPAIR DATA FOR 250°F (121°C) CURE HONEYCOMB PANELS TABLE I

#### NOTES

- WHEN YOU USE THIS REPAIR, REFER TO:
  - AMM 51-21-01 FOR APPLICATION OF FINISHES
  - SRM 51-10-01, FOR AERODYNAMIC SMOOTHNESS REQUIREMENTS. WHERE THE DAMAGE IS MORE THAN THE LIMITS GIVEN IN SRM 51-10-01, THOUGHT SHOULD BE GIVEN TO THE LOSS OF PERFORMANCE THAT MAY OCCUR.
- A LIMITED TO REPAIR OF DAMAGE TO ONE FACESHEET SKIN AND HONEYCOMB CORE. ONE REPAIR FOR EACH SQUARE FOOT (930 SQUARE cm) OF AREA AND MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, OR EDGE OF PANEL
- B INSPECT INTERIM REPAIR USING INSTRUMENTED NDT METHODS OR "TAP" TEST EVERY AIRPLANE "2A" CHECK. FOR "TAP" TEST, USE A SOLID METAL DISK AND TAP THE REPAIR AREA LIGHTLY BUT FIRMLY. VOID AREAS WILL GIVE A DULL SOUND INSTEAD OF A SHARP RING THAT YOU WILL HEAR ON A SOLID BONDED AREA. PERMANENT REPAIR IS REQUIRED IF ANY DETERIORATION IS EVIDENT. REFER TO SRM 51-70-03, PAR. 4.I. AND THE NONDESTRUCTIVE TEST MANUAL
- C ONE REPAIR FOR EACH SQUARE FOOT (930 SQUARE cm) OF AREA AND A MINIMUM OF 6.0 INCHES (150 mm) (EDGE TO EDGE) FROM ANY OTHER DAMAGE, FASTENER HOLE, EDGE OF PANEL, OR A MINIMUM OF 2.0 INCHES (50 mm) FROM TAPERED EDGE OF HONEYCOMB CORE
- D REFER TO (REPAIR 5) FOR REPAIR OF DELAMINATED ARAMID SKIN PLIES

Nose Landing Gear Doors Figure 201 (Sheet 2 of 3)

52-80-02

REPAIR 4 Page 202 Jan 20/2005





NOTES (CONTINUED)

E THERE ARE NO REPAIRS FOR THE SCUFF PLATE.

- <u>CAUTION</u>: USE CARE WHEN REMOVING THE SCUFF PLATE. DAMAGE TO THE FLOOR PANEL CAN RESULT.
- 1. REMOVE AND DISCARD A DAMAGED OR LOOSE SCUFF PLATE.
  - A. USE A PLASTIC SCRAPER TO CUT THE ADHESIVE BOND AT A CORNER OF THE SCUFF PLATE TO GET ACCESS UNDER THE PLATE.
  - B. BEND THE CORNER OF THE PLATE BACK WITH PLIERS.
  - C. GRADUALLY CUT AND PEEL THE PLATE AWAY FROM THE DOOR PANEL.
  - D. USE CARE WHEN SCRAPING OFF ADHESIVE WITH VOIDS OR AIR BUBBLES REMAINING ON THE DOOR PANELS.
  - E. WHEN THERE IS A THIN LAYER OF ADHESIVE, USE MPK TO CLEAN THE SUR-FACE OF THE DOOR PANEL.
  - F. APPLY A FINISH AND PAINT AS NECESSARY.
- NOTE: REFER TO SRM 52-80-02, ALLOWABLE DAMAGE 2 FLAGNOTE K.
- F FOR CUMLINE NUMBERS: 805 THRU 869

Nose Landing Gear Doors Figure 201 (Sheet 3 of 3)



REPAIR 4 Page 203 Jan 20/2005



#### **REPAIR 5 - REPAIR OF DELAMINATED ARAMID SKIN PLIES - NOSE LANDING GEAR DOOR**

#### REPAIR INSTRUCTIONS

- Remove the damaged area of the aramid ply or remove the entire ply.
- 2. Prepare the surface where the aramid ply has been removed as necessary.
  - A. Contaminated surfaces:
    - Solvent clean by brushing with a stiff bristle brush and methyl ethyl ketone (MEK), methyl isobutyl ketone (MIBK), or acetone.
    - (2) Blot with clean wipers to remove contaminated solvent.
    - (3) Repeat as necessary to ensure a contamination-free surface.
  - B. Uncontaminated surfaces where the aramid ply has just been removed do not require additional surface preparation.
- Spray apply Dexter Laminar X-500 Surfacer, 8-W-5 as given in the manufacturer's instructions.
- 4. Allow surfacer to dry as shown in Detail I.
- 5. After the surfacer has cured, sand to a smooth finish with 200 or finer grit abrasive paper.
- 6. Solvent clean with MEK, MIBK, or acetone.
- Apply BMS 10-79, type II primer and BMS 10-60, type II enamel as given in AMM 51-21. Use color as required by the airline.

Repair of Delaminated Aramid Skin Plies - Nose Landing Gear Door Figure 201 (Sheet 1 of 2)




REPAIR 5 Page 201 Jan 20/2005





757-200 STRUCTURAL REPAIR MANUAL



DRYING TIMES FOR LAMINAR X-500 SURFACER DETAIL I

Repair of Delaminated Aramid Skin Plies - Nose Landing Gear Door Figure 201 (Sheet 2 of 2)



REPAIR 5 Page 202 Jan 20/2005

