

GPA Group plc

PAGE	DATE	CODE	PAGE	DATE	CODE	PAGE	DATE	CODE
CHAPTER 2	23 TAB		23-FAULT R 7 R 8	CODE INDEX MAY 20/09 MAY 20/09	CONT. 30.101 25.101	23–32–00 101 102	SEP 20/92 DEC 20/93	11 11
COMMUNICA	ATIONS		R 9 R 10	MAY 20/09 MAY 20/09	28.101 25.101	102 103 104	SEP 20/92 BLANK	11
EFFECTIVE SEE LAST NUMBER OF	PAGE OF LIST F	OR	R 11 R 12 R 13 R 14	MAY 20/09 MAY 20/09 SEP 20/08	25.101 27.101 32.101	23-34-00 101 102	SEP 20/92	14 16
27			R 15	SEP 20/08 SEP 20/08	33.101 32.101	103	SEP 20/92 SEP 20/92	11
23-CONTEN	JAN 28/00	GUI	R 16 R 17	SEP 20/08 SEP 20/08	31.101 33.101	104 105	SEP 20/92 SEP 20/92	10 09
2 3	MAY 28/04 JAN 28/00	GUI GUI	R 18 R 19	MAY 20/09 SEP 20/08	40.101 28.101	106 107	SEP 20/92 SEP 20/92	09 02
4	SEP 28/99	GUI	R 20	SEP 20/08	29.101	108	BLANK	02
	USE THE FIM		R 21 22	SEP 20/08 BLANK	23.101	23-41-00		
1 2	SEP 20/98 SEP 20/98	01 01	 23-BITE	NDFX		101 102	SEP 20/90 SEP 20/90	05 05
3	SEP 28/99	01	1	SEP 28/99	01	1	22. 20, 70	
4 5	SEP 20/98 SEP 20/98	01 01	2 3	SEP 28/99 SEP 28/99	01 01	23–42–00 101	MAR 20/94	12
6	SEP 20/98	01	4	BLANK		102 103	MAR 20/94 MAR 20/94	01 18
23-INDEX			23-11-00			104	MAR 20/94	15
1 2	JAN 28/00 SEP 20/94	26 28	101 102	DEC 20/93 DEC 20/93	16 16	105 106	JAN 28/03 MAY 28/04	02 02
3 4	SEP 20/94 SEP 20/94	18 02	103	DEC 20/93	14	107 108	MAY 28/04	01
1		UZ	104 105	DEC 20/93 DEC 20/95	08 01		BLANK	
23-FAULT	CODE DIAGRAM MAR 20/93	21	106 107	MAY 28/03 MAY 28/03	01 01	23-43-00 101	MAR 20/94	01
2	JAN 20/99	03	108	BLANK	•	102	MAR 20/94	01
4	SEP 20/91 JUN 20/91	23 24	23-12-00			103 104	MAR 20/97 MAR 20/97	09 09
3 4 5 6 7	MAY 20/98 SEP 20/98	06 23	101 102	DEC 20/93 DEC 20/95	15 06	23-51-00		
	MAR 20/95	25	103	DEC 20/93	18	101	DEC 20/91	01
8 9	MAY 28/01 JAN 20/99	28 08	104 105	DEC 20/93 DEC 20/93	15 09	102 103	DEC 20/91 DEC 20/91	13 20
10	DEC 20/87	15	106	SEP 28/02	13	104	SEP 20/93	14
11 12	MAY 20/98 SEP 20/98	10 13	107 108	MAY 28/03 MAY 28/03	07 01	105 106	SEP 20/93 SEP 20/93	04 01
13 14	JAN 28/01 JUN 20/96	11 09	109 110	MAY 28/03 BLANK	01	23-61-00		
15	DEC 20/92	17		DLAIN		101	SEP 20/93	01
16 17	DEC 20/96 JUN 20/92	06 18	23-21-00 101	MAR 20/94	17	102 103	SEP 20/90 SEP 20/93	01 01
18	JAN 20/98	12	102	MAR 20/94	19	104	SEP 20/90	01
19 20	DEC 20/87 JAN 28/00	05 23	23-31-00			105 106	SEP 20/90 BLANK	01
I	CODE INDEX		101 102	DEC 20/92 DEC 20/92	27 23	23-71-00	CONFIG 1	
1	SEP 20/08	02	103	DEC 20/92	25	101	MAR 20/93	02
R 3	SEP 20/08 MAY 20/09	21 19 . 101	104 105	DEC 20/92 DEC 20/92	10 24	102 103	MAR 20/93 MAR 20/93	02 02
R 4	MAY 20/09	25.1	106	DEC 20/92	06	104	MAR 20/93	02
R 5 R 6	MAY 20/09 SEP 20/08	26.101 17.101				105 106	MAR 20/93 MAR 20/93	02 02

R = REVISED, A = ADDED OR D = DELETED 632 MAY 20/09 D633N632

CHAPTER 23 **EFFECTIVE PAGES** PAGE CONTINUED



GPA Group plc

PAGE	DATE	CODE	PAGE	DATE	CODE	PAGE	DATE	CODE
23-71-00 107 108	CONFIG 1 MAR 20/93 BLANK	CONT. 02						
l 107	MAR 20/93	02 02 02 02 02 02 02 02 02						

R = REVISED, A = ADDED OR D = DELETED 632 MAY 20/09 D633N632

CHAPTER 23 **EFFECTIVE PAGES** PAGE 2 LAST PAGE



TABLE OF CONTENTS

<u>Subject</u>	Chapter Section Subject	<u>Page</u>	Effectivity
HOW TO USE THE FIM	23-HOW TO USE THE FI		ALL
INDEX	23-INDEX	1	ALL
EICAS MESSAGES	23-EICAS MESSAGES	1	ALL
FAULT CODE DIAGRAMS	23-FAULT CODE DIAGR		ALL
FAULT CODE INDEX	23-FAULT CODE INDEX	1	ALL
BITE INDEX	23-BITE INDEX	1	ALL
COMMUNICATIONS	23-00-00		
SPEECH COMMUNICATION SYSTEM HF COMMUNICATION SYSTEM Component Location Component Index Component Location	23–10–00 23–11–00	101	ALL
Fault Isolation High Frequency Communications System BITE Procedure (Fig. 103)		104	
VHF COMMUNICATION SYSTEM Component Location Component Index Component Location Fault Isolation	23-12-00	101	ALL
VHF Communications Transceiver BITE Procedure (Fig. 103)		105	
DATA TRANSMISSION AND AUTOMATIC CALLING	23-20-00		
SELCAL SYSTEM Component Location Component Index Component Location	23-21-00	101	ALL

23-CONTENTS

GUI

Page 1 Jan 28/00



TABLE OF CONTENTS

<u>Subject</u>	Chapter Section Subject	<u>Page</u>	<u>Effectivity</u>
PASSENGER ADDRESS AND ENTERTAINMENT PASSENGER ADDRESS SYSTEM Component Location Component Index Component Location	23–30–00 23–31–00	101	ALL
Fault Isolation Passenger Address Amplifier BITE Procedure (Fig. 103)	27. 72. 00	105	
PASSENGER ENTERTAINMENT (VIDEO) SYSTEM Component Location Component Index Component Location [*] GUI 115	23–32–00	101	[*]
PASSENGER ENTERTAINMENT SYSTEM Component Location Component Index Component Location	23-34-00	101	ALL
Fault Isolation Passenger Entertainment System (PES) BITE Procedure (Fig. 103)		105	
INTERPHONE SERVICE INTERPHONE SYSTEM Component Location Component Index Component Location	23–40–00 23–41–00	101	ALL
CABIN INTERPHONE SYSTEM Component Location Component Index Component Location	23-42-00	101	ALL
Fault Isolation Cabin Chime and Call Light/Attendant Call from Pilit 407		105	
(Fig. 103) Pilot Call Chime and Light Problem (Fig. 104)		106	

23-CONTENTS

GUI

Page 2 May 28/04



TABLE OF CONTENTS

Subject	Chapter Section Subject	<u>Page</u>	<u>Effectivity</u>
GROUND CREW CALL SYSTEM Component Location Component Index Component Location Fault Isolation	23-43-00	101	ALL
Ground Crew Call Horn Fails to Sound. EQPT CLG FLOW or EQPT CLG SENSOR EICAS Status Message(s) Displayed. (Fig. 103)		103	
Ground Crew Call Horn Fails to Sound. IRS Mode Select Switch (L, C, or R) On. L and R DC Power Off (Fig. 104)		104	
AUDIO INTEGRATING FLIGHT INTERPHONE SYSTEM Component Location Component Index Component Location	23–50–00 23–51–00	101	ALL
STATIC DISCHARGING STATIC DISCHARGING Component Location Component Index Component Location	23–60–00 23–61–00	101	ALL

23-CONTENTS



TABLE OF CONTENTS

Chapter Section Subject **Effectivity** <u>Subject</u> <u>Page</u> 23-70-00 AUDIO AND VIDEO MONITORING 23-71-00 **VOICE RECORDER SYSTEM** 101 CONFIG 1 [*] Component Location Component Index Component Location Fault Isolation Voice Recorder BITE Procedure 103 (Fig. 103) Voice Recorder System Fault 104 Isolation (Fig. 104) [*] GUI 009,115 101 CONFIG 2 [*] Component Location Component Index Component Location Fault Isolation Voice Recorder BITE Procedure 103 (Fig. 103) Voice Recorder System Fault 104 Isolation (Fig. 104)

[*] GUI 001-008,010-013

23-CONTENTS



These are the possible types of faults: YOU FIND A FAULT WITH 1. EICAS Message AN AIRPLANE SYSTEM 2. Observed Fault Use the EICAS message, fault code, or fault description to find the corrective action or fault isolation procedure in the FIM. DO THE CORRECTIVE For details, see Figure 3 -ACTION OR GO TO THE FAULT ISOLATION PROCEDURE IN THE FIM If you do not have a fault code or an EICAS message and if the system has BITE, then you can use the system BITE to get more information: Use the BITE Index to find if the system has BITE and to find the BITE procedures in the FIM. For details, see Figure 2 -The fault isolation procedure FOLLOW THE STEPS IN explains how to find and repair the THE FAULT ISOLATION the cause of the fault. **PROCEDURE** For details, see Figure 4 —

> Basic Fault Isolation Process Figure 1


ALL ALL

23-HOW TO USE THE FIM

01

Page 1 Sep 20/98






How to Get Fault Information from BITE Figure 2

23-HOW TO USE THE FIM

01

Page 2 Sep 20/98 IF YOU HAVE:

THEN DO THIS TO FIND THE CORRECTIVE ACTION OR FAULT ISOLATION PROCEDURE IN THE FIM:



- The first two digits of the fault code are the FIM chapter that you need. Go to the Fault Code Index in that chapter and find the fault code.
- 2. Find the Fault Isolation Reference for the fault code and do the corrective action. If there is a FIM reference, then go to that fault isolation procedure in the FIM and do the steps in the procedure (see Figure 4).



If you know the chapter of the EICAS message, then go to the EICAS Messages section in that chapter and find the EICAS message.

If you do not know the chapter of the EICAS message, then do these steps:

A. Go to FIM EICAS MESSAGE LIST and find the EICAS message in the table.

NOTE: The list follows the INTRODUCTION to the FIM.

- B. Find the chapter number on the same line as the EICAS message. Go to the EICAS Messages section in that chapter and find the EICAS message.
- 2. Do the corrective action in the "Procedure" column for the EICAS message. If there is a FIM reference, then go to that fault isolation procedure in the FIM and do the steps in the procedure (see Figure 4).



- Go to the Fault Code Diagram for the problem in the applicable chapter.
- 2. Do the fault analysis on the diagram and find the fault code.
- 3. The first two digits of the fault code are the FIM chapter that you need. Go to the Fault Code Index in that chapter and find the fault code.
- 4. Find the Fault Isolation Reference for the fault code and do the corrective action. If there is a FIM reference, then go to that fault isolation procedure in the FIM and do the steps in the procedure (see Figure 4).

How to Find the Corrective Action or Fault Isolation Procedure in the FIM Figure 3

EFFECTIVITY-

23-HOW TO USE THE FIM

ALL

Page 3 Sep 28/99



ASSUMED CONDITIONS AT START OF TASK

- External electrical power is OFF
- Hydraulic power and pneumatic power are OFF
- Engines are shut down
- Circuit breakers for the system are closed
- No equipment in the system is deactivated

PREREQUISITES

- This box gives the steps to get the airplane from the normal shutdown condition to the configuration necessary to do the fault isolation procedure.
- The Prerequisites give procedure references, circuit breakers, and special tools and equipment requirements.

FAULT ISOLATION BLOCKS


- Start the fault isolation procedure at block 1 unless specified differently.
- Do the check to get an answer to the question in the box. Follow the arrow that applies to your answer. This will go to the next check.
- When you get to a box in the column at the right of the page, you have isolated that fault. Do the steps in that box to repair the cause of the fault.
- Make sure that fault is corrected to complete the procedure.

Do the Fault Isolation Procedure Figure 4

EFFECTIVITY-

23-HOW TO USE THE FIM






Subjects in Each FIM Chapter Figure 5 (Sheet 1)

ALL

O1 Page 5
Sep 20/98

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.



Subjects in Each FIM Chapter Figure 5 (Sheet 2)

EFFECTIVITY-

23-HOW TO USE THE FIM

01

ALL

Page 6 Sep 20/98



<u>TITLE</u>	CHAP/SEC
ATTENDANT	
CALL FROM ATTENDANT	2342
CALL FROM LAV	
CALL FROM PILOT	
CALL FROM SEATS	
AUDIO SELECTOR PANEL (ASP)	
BOARDING MUSIC AND PRERECORDED	2001
ANNOUNCEMENTS	2331
CABIN	
CHIME	2331
HANDSET	2342
INTERPHONE	2342
SPEAKER	2331
COCKPIT	
CALL	
CHIME	2342
HEADSET	
MIC	
SPEAKER	
EICAS MESSAGES	
FLIGHT INTERPHONE	
GROUND CALL	
HF COMM	
PASSENGER ADDRESS	
PUSH TO TALK (PTT)	
READING LIGHTS	
SELCAL	
SERVICE INTERPHONE	
VHF COMM	2312
VIDEO	
CONTROL UNIT	
SOUND TRACK	
TAPE REPRODUCER	
VIDEO MONITOR	
VOICE DECODDED	2771

COMMUNICATIONS - INDEX Figure 1 (Sheet 1)


 23-INDEX

26


Page 1 Jan 28/00




FAULT ISOLATION/MAINT MANUAL




BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.






A47188





AFT STOWAGE BIN

COMMUNICATIONS - INDEX Figure 1 (Sheet 3)












PILOTS' CALL PANEL





INERTIAL REFERENCE MODE PANEL (IRMP)



PILOTS' CENTER INSTRUMENT **PANEL**

<u>IIILE</u> <u>C</u>	HAP/SEC
GROUND CALL HORN	2343
PILOTS CALL PANEL	2342
INERTIAL REFERENCE MODE PANEL	3421
E/E COOLING MODULE	2158
EICAS DISPLAY UNIT	3141

GROUND CALL HORN - INDEX (GROUND) Figure 2

EFFECTIVITY-ALL


89620

23-INDEX

02

Page 4 Sep 20/94





VHF COMM LEFT 11c3 11G29 CAPT FLT AMPL 11C25 CAPT FLT AMPL 11G30 F/O OBS

11C26 F/O OBS VHF COMM RIGHT 11G31

VHF COMM - FAULT CODES

EFFECTIVITY-ALL

23-FAULT CODE DIAGRAM


21

Page 1 Mar 20/93

872262



FAULT ISOLATION/MAINT MANUAL



APPLICABLE CIRCUIT BREAKERS AS INSTALLED

11C25	CAPT (-S/O) FLT AMPL (DUAL PWR)
11026	F/O (OBS, OBSR) (DUAL PWR)
11G29	CAPT (-S/O) FLT AMPL (DUAL PWR)
	F/O (OBS, OBSR) (DUAL PWR)

ASP, COCKPIT MIC, HEADSET, SPEAKER - FAULT CODES

EFFECTIVITY-


ALL

23-FAULT CODE DIAGRAM

03

Page 2 Jan 20/99





PUSH TO TALK (PTT) - FAULT CODES

EFFECTIVITY-ALL

23-FAULT CODE DIAGRAM


23

Page 3 Sep 20/91

872264



FAULT ISOLATION/MAINT MANUAL



PASSENGER ADDRESS SYSTEM - FAULT CODES


ALL ALL

23-FAULT CODE DIAGRAM

24

Page 4 Jun 20/91





CABIN HANDSETS AND SPEAKERS - FAULT CODES

ALL


138921

23-FAULT CODE DIAGRAM

06

Page 5 May 20/98





APPLICABLE CIRCUIT BREAKERS

11C22 PASS ADRS AMPL

BOARDING MUSIC - FAULT CODES


ALL

23-FAULT CODE DIAGRAM

23

Page 6 Sep 20/98





1> IF INSTALLED

APPLICABLE CIRCUIT BREAKERS

11H30 VIDEO SYSTEM DC

PASSENGER ENTERTAINMENT - FAULT CODES

ALL ALL


23-FAULT CODE DIAGRAM

25

Page 7 Mar 20/95



FAULT ISOLATION/MAINT MANUAL



ATTENDANT CALL FROM LAVATORY - FAULT CODES


EFFECTIVITY-ALL

23-FAULT CODE DIAGRAM

28

Page 8 May 28/01





ATTENDANT CALL FROM SEATS - FAULT CODES


EFFECTIVITY-ALL

23-FAULT CODE DIAGRAM

80

Page 9 Jan 20/99





CABIN CHIME, CALL FROM PILOT, ALERT CALL
& PASS SIGNS - FAULT CODES

EFFECTIVITY-


23-FAULT CODE DIAGRAM

15

ALL

Page 10 Dec 20/87






SERVICE INTERPHONE - FAULT CODES

23-FAULT CODE DIAGRAM





CABIN INPH - FAULT CODES


ALL

23-FAULT CODE DIAGRAM

13

Page 12 Sep 20/98





CABIN AND COCKPIT CHIME/CALL LIGHTS FROM ATTENDANT & NOSE WHEEL WELL - FAULT CODES


EFFECTIVITY—

23-FAULT CODE DIAGRAM

ALL

Page 13 Jan 28/01





APPLICABLE CIRCUIT BREAKERS AS INSTALLED

11C25	CAPT (-S/O) FLT AMPL (DUAL PWR)
11C26	F/O (OBS, OBSR) (DUAL PWR)
11G29	CAPT (-S/O) FLT AMPL (DUAL PWR)
11G30	F/O (OBS, OBSR) (DUAL PWR)

FLIGHT INTERPHONE - FAULT CODES


ALL

23-FAULT CODE DIAGRAM

09

Page 14 Jun 20/96





VOICE RECORDER - FAULT CODES


EFFECTIVITY ALL

23-FAULT CODE DIAGRAM

17

Page 15 Dec 20/92





APPLICABLE CIRCUIT BREAKERS AS INSTALLED

11c3	VHF COMM (LEFT, L)	11G8	HF COMM (LEFT, L)
11G3	SELCAL	11G31	VHF COMM (RIGHT, R)
11G4	VHF COMM (CENTER, C)	11G34	HF COMM (RIGHT, R)

SELCAL - FAULT CODES


ALL

23-FAULT CODE DIAGRAM

06

Page 16 Dec 20/96






HF COMM - FAULT CODES

23-FAULT CODE DIAGRAM

18

Page 17 Jun 20/92






VIDEO SYSTEM - FAULT CODES

23-FAULT CODE DIAGRAM

12 Page 18





GROUND CREW CALL SYSTEM - FAULT CODES (GROUND)

ALL

23-FAULT CODE DIAGRAM

05

Page 19 Dec 20/87



	EICAS		ULT COD	E/
	WAS MSG DISPLAYED?	NO.	T APPLY	00
NO NO			NORMAL	₩
DATAL	INK LOST		23 23 01	00
DATAL	INK SYS	 	23 23 02	00
SATCO	OM DATALINK		23 15 01	00
	OM VOICE		23 15 02	00
	COM VOICE		23 15 03	00
	COM VOICE	 	23 15 04	00
SATCO		 	23 15 05	00
HF DA	TALINK		23 23 05	00
; 		 		
── REPORT AN	NY FAULT SYMPTOM OR PATTERN NOT SHOWN ABOVE		23 15 XA	00

EICAS MESSAGE - FAULT CODES

ALL

23-FAULT CODE DIAGRAM

23

Page 20 Jan 28/00



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 11 XA	Report HF comm symptoms or patterns along with fault code.	SSM 23-11-01
23 12 XA	Report VHF comm symptoms or patterns along with fault code.	SSM 23-12-01, SSM 23-12-02
23 15 XA 00	Report EICAS message symptoms or patterns along with fault code.	SSM 23-15-01
23 21 XA	Report SELCAL symptoms or patterns along with fault code.	SSM 23-21-01
23 31 XA	Report passenger address system symptoms or patterns along with fault codes.	WDM 23-31-01
23 31 XB	Report cabin handset and speaker symptoms or patterns along with fault code.	SSM 23-31-01
23 31 XC 00	Report boarding music and prerecorded announcements symptoms or patterns along with fault code.	WDM 23-31-01, WDM 23-34-01
23 32 XA 00	Report video system symptoms or patterns along with fault code.	WDM 23-32-01
23 34 XA	Report passenger entertainment symptoms or patterns along with fault code.	WDM 23-34-01
23 41 XA	Report service interphone symptoms or patterns along with fault code.	WDM 23-41-01
23 42 XA	Report cabin chime, call from captain, alert call and pass signs, symptoms or patterns along with fault code.	WDM 23-42-01
23 42 XB	Report cabin interphone symptoms or patterns along with fault code.	WDM 23-42-01

23-FAULT CODE INDEX

02



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 42 XC	Report cabin cockpit chime/call lights from attendant and nose wheel well symptoms or patterns along with fault code.	WDM 23-42-01
23 51 XA	Report Push-To-Talk (PTT) symptoms or patterns along with fault codes.	WDM 23-51-01
23 51 XB	Report Flight Interphone symptoms or patterns along with fault code.	WDM 23-51-01
23 51 XC	Report ASP, cockpit mic, headset, speaker symptoms or patterns along with fault code.	WDM 23-51-01
23 71 XA 00	Report voice recorder symptoms or patterns along with fault code.	WDM 23-71-01
23 11 01	Reception on (L,R) HF (describe problem: inop, weak, intermittent, etc.) at (03=Capt, 04=F/0,05=1st Obs,06=2nd Obs) station. Other crew stations normal.	Replace the audio selector panel, M70 (M71,M98,M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 11 02	Reception on (01=L,02=R) HF (describe problem: inop, weak, intermittent, etc.) at all stations.	Replace the L(R) HF comm transceiver, M152 (M153) (AMM 23-11-03/401).
23 11 03	Transmission on (L,R) HF (describe problem: inop, weak, intermittent, no sidetone, etc.) at (03=Capt,04=F/0,05=1st Obs, 06=2nd Obs) station. Other crew stations normal.	Replace the audio selector panel, M70 (M71,M98,M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401). If the problem continues, do a check of, or replace the boom and the hand microphone jacks at the positions where the problem occurs (WDM 23-51-11, WDM 23-51-21, WDM 23-51-41, WDM 23-51-51).

23-FAULT CODE INDEX



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 11 04	Transmission on (01=L,02=R) HF (describe problem: inop, weak, intermittent, no sidetone, etc.) at all stations.	Replace the L (R) HF comm transceiver, M152 (M153) (AMM 23-11-03/401).
23 11 05	Transmission and reception on (L,R) HF (describe problem: inop, weak, intermittent,etc.) at (03=Capt,04=F/0,05=1st Obs, 06=2nd Obs) station. Other crew stations are normal.	Replace the audio selector panel, M70 (M71,M98,M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 11 06	Transmission and reception on (01=L,02=R) HF at MHz (describe problem: inop, weak, intermittent, etc.).	FIM 23-11-00/101, Fig. 103, Block 1
23 11 07	Transmission and reception on (01=L, 02=R) HF (describe problem: inop, weak, intermittent, etc.).	FIM 23-11-00/101, Fig. 103, Block 1
23 11 08	(01=L,02=R) HF freq control inop on (L,R) HF (describe).	Replace the L(R) HF control panel, M82 (M83) (AMM 23-11-02/401).
23 11 09	(01=L,02=R) HF freq incorrect onMHz.	Replace the L(R) HF control panel, M82 (M83) (AMM 23-11-02/401). If the problem continues, refer to FIM 23-11-00/101, Fig. 103, Block 1.
23 11 10	(01=L,02=R) HF frequency indicator has missing segment.	Replace the L (R) HF control panel, M82 (M83) (AMM 23-11-02/401).

23-FAULT CODE INDEX

ALL

19.101

Page 3 May 20/09



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 11 17	Transmission on an HF system (L or R) is defective at cruise or high altitudes, but is satisfactory on the ground or at low altitudes.	Replace the antenna coupler for the affected system (L = M241, R = M242) (AMM 23-11-01/401).
23 12 01	(01=L,02=R,03=C) VHF transfer lgt inop for (L,R) selected frequency.	Replace the L (R,C) VHF control panel, M78 (M79,M80) (AMM 23-12-02/401).
23 12 02	(01=L,02=R,03=C) VHF freq control (inop, stuck, knob missing) for (L,R) frequency.	Replace the L (R,C) VHF control panel, M78 (M79,M80) (AMM 23-12-02/401).
23 12 03	Reception on (L,R,C,All) VHF (describe problem: inop, weak, intermittent, etc.) at (04=Capt, 05=F/0,06=1st Obs,07=2nd Obs) station. Other crew stations are normal.	Replace the audio selector panel, M70 (M71,M98,M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 12 04	(01=L,02=R,03=C) VHF comm reception (describe problem: inop, weak, intermittent, etc.) at all crew stations.	Replace the L (R C) VHF comm transceiver, M188 (M189,M190) (AMM 23-12-01/401).
23 12 05	(L,R,C) VHF xmission (inop, weak, intermittent, no sidetone, etc.) at (04=Capt,05=F/0,06=1st Obs,07=2nd Obs) station. Other crew stations normal.	Replace the audio selector panel, M70 (M71,M98,M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 12 06	(01=L,02=R,03=C) VHF xmission (inop, weak, intermittent, no sidetone, etc.) at all crew stations.	Replace the L(R,C) VHF comm transceiver, M188 (M189,M190) (AMM 23-12-01/401).
23 12 07	(01=L,02=R,03=C) VHF xmission and reception (inop, weak, intermittent, etc.) on (specific freq) when using (L,R) side of VHF comm panel.	Replace the L(R,C) VHF control panel, M78 (M79) (AMM 23-12-02/401).
23 12 08	(01=L,02=R,03=C) VHF xmission and reception (inop, weak, intermittent, etc.) on (specify freq).	FIM 23-12-00/101, Fig. 103, Block 1

23-FAULT CODE INDEX

ALL

25.1 Page 4 May 20/09



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 12 09	Transmission and reception on (L,R,C) VHF (inop, weak, intermittent, etc.) at (04=Capt, 05=F/0,06=1st Obs,07=2nd Obs) station.	Replace the audio selector panel, M70 (M71,M98,M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 12 10	(01=L,02=R,03=C) VHF xmission and reception (inop, weak, intermittent, etc.) at all crew stations (specify freq).	FIM 23-12-00/101, Fig. 103, Block 1
23 12 11	(01=L,02=R,03=C) VHF freq indication incorrect (describe).	Replace the L(R,C) VHF control panel, M78 (M79,M80) (AMM 23-12-02/401).
23 12 12	(01=L,02=R,03=C) VHF will not transfer to (L,R) side.	Replace the L(R,C) VHF control panel, M78 (M79,M80) (AMM 23-12-02/401).
23 15 05 00	EICAS message SATCOM displayed.	FIM 23-12-00/101, Fig. 103, Block 1
23 21 01	(01=L VHF,02=R VHF,03=C VHF, 04=L HF,05=R HF) Call switch fails to reset SELCAL. PTT resets SELCAL.	Replace the pilots' call panel, M51 (AMM 23-42-02/401).
23 21 02	(01=L VHF,02=R VHF,03=C VHF, 04=L HF,05=R HF) SELCAL is not reset by PTT. Call switch resets SELCAL.	Replace the pilots' call panel, M51 (AMM 23-42-02/401).
23 21 03	(01=L VHF,02=R VHF,03=C VHF, 04=L HF,05=R HF) Call switch and PTT fail to reset SELCAL.	Replace the SELCAL decoder, M180 (AMM 23-21-01/401).
23 21 04	Calls on (01=L VHF,02=R VHF, 03=C VHF,04=L HF,05=R HF) fail to turn on SELCAL lgt.	Replace the SELCAL switchlight (WDM 23-21-11). If the problem continues, replace the SELCAL decoder, M180 (AMM 23-21-01/401).
23 21 05	Calls on (01=L VHF,02=R VHF, 03=C VHF,04=L HF,05=R HF) fail to sound chime. Call lgt on.	Replace the SELCAL decoder, M180 (WDM 23-21-01/401). If the problem continues, replace the bell chime card, M1000 (AMM 31-51-04/401).

23-FAULT CODE INDEX

ALL

26.101

Page 5 May 20/09



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 21 06	Calls on (01=L VHF,02=R VHF, 03=C VHF,04=L HF,05=R HF) fail to turn on SELCAL lgt and sound chime. SELCAL on another radio normal.	(01=L VHF,02=R VHF,03=C VHF) FIM 23-12-00/101, Fig. 103, Block 1. If the problem continues, replace the SELCAL decoder, M180 (AMM 23-21-01/401). (04=L HF,05=R HF) FIM 23-11-00/101, Fig. 103, Block 1. If the problem continues, replace the SELCAL decoder, M180 (AMM 23-21-01/401).
23 21 07 00	Calls on any radio fail to turn on SELCAL lgt and sound chime.	Replace the SELCAL decoder, M180 (AMM 23-21-01/401).
23 23 01 00	EICAS message DATALINK LOST displayed.	Total loss of datalink capability due to active ACARS being in NO COMM condition. The NO COMM condition is a normal condition if the airplane is not out of range of an ACARS ground station, or if the ACARS ground network is not operational. If ACARS operates correctly on other airplanes at the same location, do this fault isolation procedure: FIM 23-22-00/101, Fig. 103, Block 1.
23 23 02 00	EICAS message DATALINK SYS displayed.	Total loss of datalink capability due to ACARS MU failure (FIM 23-22-00/101).
23 23 05 00	EICAS message HF DATALINK displayed.	Replace the ACARS Management Unit (AMM 23-22-01/401). If the fault continues, replace the HF Transciever (AMM 23-11-03/401).
23 31 01 00	All lav, pass, and PSU speakers are describe problem: noisy, inop (etc.) when PA is used.	Do the passenger address amplifier BITE procedure (FIM 23-31-00/101, Fig. 103, Block 1).

23-FAULT CODE INDEX

ALL

17.101 Page 6 Sep 20/08



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 31 05 00	The aft attnd speakers are, describe problem: noisy, inop (etc.), when PA is used.	Replace the PA amplifier, M177 (AMM 23-31-01/401). If the problem continues, replace the aft galley speaker, M10346 (AMM 23-31-04/401).
23 31 06	PA is, describe problem: noisy, weak, inop, too loud (etc.), when using (O1=Capt,O2=F/O, O3=1st Obs,O4=2nd Obs) audio selector panel.	Replace the audio selector panel, M70 (M71,M98,M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 31 07 00	PA is, describe problem: noisy, weak, inop, too loud (etc.), when using handsets. PA is normal when using audio select panel.	Do the passenger address amplifier BITE procedure (FIM 23-31-00/101, Fig. 103, Block 1).
23 31 08 00	PA is, describe problem: noisy, weak, inop, too loud (etc.), when using attend handsets or audio selector panels.	Do the passenger address amplifier BITE procedure (FIM 23-31-00, Fig. 103, Block 1).
23 31 09	(01=Fwd Attnd,02=Mid Attnd, 03=Aft Attnd,04=Fwd Galley, 05=Aft Galley,06=Lav,07=PSU, 08=Pass) Speaker, describe problem: noisy, inop (etc.).	Do the passenger address amplifier BITE procedure (FIM 23-31-00/101, Fig. 103, Block 1).
23 31 10	(01=Fwd Attnd, 02=Mid Attnd, 03=Aft Attnd) handset (describe problem: unable to talk, unable to hear, unable to key).	Install a handset from a different location. If the problem goes away, replace the bad handset. If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 31 11 00	Boarding music volume too low with engines on.	Replace the PA amplifier, M177 (AMM 23-31-01/401).

23-FAULT CODE INDEX

ALL

30.101 Page 7 May 20/09



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 31 12 00	Boarding music too low at max volume.	Replace the boarding music tape reproducer, M10748 (AMM 23-31-06/201). If the problem continues, replace the PA amplifier, M177 (AMM 23-31-01/401). NOTE: Low boarding music volume may be caused by a low recording level when the tape was produced. Equipment failure may not be the cause of the problem.
23 31 14 00	Boarding music is (describe problem: noisy, inop, etc.). PA is normal.	Replace the tape cassette in the boarding music tape reproducer, M10748. If the problem continues, replace the tape reproducer, M10748 (AMM 23-31-06/201).
23 31 15 00	Boarding music and PA are (describe problem: noisy, inop, etc.).	Do the passenger address amplifier BITE procedure (FIM 23-31-00/101, Fig. 103, Block 1).
23 31 16	PA has no sidetone when using (O1=Capt, O2=F/O, O3=1st Obs, O4=2nd Obs) audio selector panel.	Replace the audio selector panel, M70 (M71, M98, M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 31 17 00	PA has no sidetone when using any audio selector panel.	Replace the PA amplifier, M177 (AMM 23-31-01/401).
23 31 22	PA has background noise (whistle) when using (05=Fwd, 06=Mid L, 07=Mid R, 08=Aft L) handset.	Replace the audio accessory unit, M108 (AMM 23-42-01/401). If the problem continues, replace the muting relay (WDM 23-31-42).
23 31 23	PA has cockpit feedback during PA announcement using (05=Fwd, 06=Mid L, 07=Mid R, 08=Aft L) handset.	Replace the handset, B61 with a new model that corrects this problem (P/N 285NO412-1 or newer model).
23 31 26 00	Boarding music plays too (fast, slow).	Replace the tape reproducer, M10748 (AMM 23-31-06/201).

23-FAULT CODE INDEX

ALL

25.101 Page 8 May 20/09



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 31 27 00	Boarding music channel select not normal.	Replace the tape reproducer, M10748 (AMM 23-31-06/201). If the problem continues, replace the boarding music remote control switch, S10179 (WDM 23-31-17) on the forward attendant panel, P21.
23 31 28 00	Boarding music channel is (describe problem: noisy, inop, etc.).	Replace the tape reproducer, M10748 (AMM 23-34-03/201). If the problem continues, replace the boarding music remote control switch, S10179 (WDM 23-34-16) on the forward attendant panel, P21.
23 31 30 00	All boarding music and pass entmt channels are (describe problem: noisy, inop, etc.).	Replace the tape reproducer, M10748 (AMM 23-34-03/201).
23 32 01	(01=1, 02=2, 03=3, 04=4, 05=5, 06=6, 07=7, 08=8) VIDEO MONITOR inop.	Replace the video monitor 1 (AMM 23-32-01/401) or the video monitor 2, 3, 4, 5, 6, 7 or 8 (AMM 23-32-02/401) as necessary.
23 32 02	(01=1, 02=2, 03=3, 04=4, 05=5, 06=6, 07=7, 08=8) VIDEO MONITOR picdture not normal (describe).	Adjust the tuning controls on the side of the video monitor (remove the shroud for access). If the problem continues, replace the video monitor 1 (AMM 23-32-01/401) or the video monitor 2, 3, 4, 5, 6, 7 or 8 (AMM 23-32-02/401) as necessary.
23 32 03	(01=1, 02=2, 03=3, 04=4, 05=5, 06=6, 07=7, 08=8) VIDEO MONITOR (PIX, BRT, COLOR, HUE, V HOLD) control not normal (describe).	Replace the video monitor 1 (AMM 23-32-01/401) or the video monitor 2, 3, 4, 5, 6, 7 or 8 (AMM 23-32-02/401) as necessary.
23 32 04 00	Video sound tracks are (describe problem: noisy, too low, etc.) at all seats. They are normal on PA.	Replace the main multiplexer, M10733 (AMM 23-34-01/401).

23-FAULT CODE INDEX

ALL

28.101

Page 9 May 20/09



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 32 05 00	Video sound tracks are (describe problem: noisy, too low, etc.) at all seats and on PA.	Replace the video tape. If the problem continues, replace the video tape reproducer (AMM 23-32-04/401). If the problem continues, replace the system control unit (AMM 23-32-03/401).
23 32 06	(01=1, 02=2) VTR is inop.	Replace the video tape reproducer (AMM 23-32-04/401). If the problem continues, replace the system control unit (AMM 23-32-03/401).
23 32 07 00	Entertainment tape plays too (fast, slow).	Replace the video tape. If the problem continues, replace the video tape reproducer (AMM 23-32-04/401).
23 32 08 00	Video sound track not normal on PA (describe).	FIM 23-32-00/101, Fig. 103, Block 1
23 32 09	Zone (09=A, 10=B, 11=C, 12=All) VIDEO MONITOR(s) not normal (describe).	(09=A, 10=B) Replace the video monitor 1 (AMM 23-32-01/401) or the video monitor 2 (AMM 23-32-02/401). If the problem continues, replace the system control unit (AMM 23-32-03/401). (11=C) Replace the forward interface box, M10684. If the problem continues, replace the system control unit (AMM 23-32-03/401).
23 32 10	(REW, PLAY, FF, STOP) Control on (O1=1, O2=2) VTR is inop.	Replace the video tape reproducer (AMM 23-32-04/401).
23 34 01 00	Pass entmt volume control (describe problem: unable to adjust volume, too sensitive, etc.) at seat	Do the passenger entertainment system BITE procedure (FIM 23-34-00/101, Fig. 103, Block 1).
23 34 02 00	Pass entmt channel select (describe problem: unable to change channels, digit dspy, etc.) at seat	Do the passenger entertainment system BITE procedure (FIM 23-34-00/101, Fig. 103, Block 1).

23-FAULT CODE INDEX

ALL

25.101

Page 10 May 20/09



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 34 03 00	Pass entmt channel sel (describe problem: unable to change channels, etc.) at row	Do the passenger entertainment system BITE procedure (FIM 23-34-00/101, Fig. 103, Block 1).
23 34 04 00	Pass entmt (describe problem: noisy, inop, etc.) at seat	Do the passenger entertainment system BITE procedure (FIM 23-34-00/101, Fig. 103, Block 1).
23 34 05 00	Pass entmt (describe problem: noisy, inop, etc.) at row	Do the passenger entertainment system BITE procedure (FIM 23-34-00/101, Fig. 103, Block 1).
23 34 06 00	Pass entmt (describe problem: noisy, inop, etc.) aft of row	Do the passenger entertainment system BITE procedure (FIM 23-34-00/101, Fig. 103, Block 1).
23 34 07	(01=L, 02=R) side of cabin pass entmt (describe problem: noisy, inop, etc.).	Do the passenger entertainment system BITE procedure (FIM 23-34-00/101, Fig. 103, Block 1).
23 34 08 00	Passenger entmt channel (describe problem: noisy, inop, etc.).	Do the passenger entertainment system BITE procedure (FIM 23-34-00/101, Fig. 103, Block 1). If the problem continues, replace the entertainment tape reproducer, M130 (AMM 23-34-03/401).
23 34 09 00	All pass entmt channels (describe problem: noisy, inop, etc.) at all seats. Boarding music normal on PA.	Do the passenger entertainment system BITE procedure (FIM 23-34-00/101, Fig. 103, Block 1).
23 34 21 00	Passenger entertainment system test circuit not normal (describe).	Do the passenger entertainment system BITE procedure (FIM 23-34-00/101, Fig. 103, Block 1).

23-FAULT CODE INDEX

ALL

25.101



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 41 01	(04=Aft Equip Ctr, 05=Main E/E, 06=Nose W/W, 07=Fueling, 08=Horiz Stab, 09=APU, 10=R W/W, 11=E5 Equip Rack) service jack (describe problem: noisy, inop, etc.).	Replace the jack where the problem occurs (WDM 23-41-12).
23 41 02	Comm on service inph (describe noisy, inop, no sidetone, etc.) from (O1=Capt, O2=F/O, O3=1st Obs) audio selector panel. Normal from other crew pos.	Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 41 03 00	Comm from service inph jacks (describe problem: noisy, inop, no sidetone, etc.) using any audio selector panel.	Make sure that no service interphone jack case is loose or shorted to ground (WDM 23-41-12). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 41 04 00	Unable to receive transmission from service inph external jacks. Service Inph switch is ON.	Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 02	(01=Fwd, 03=Mid Fwd, 04=Mid Aft, 05=Aft, 07=All) Attendant's pink call lights inop. Chime does sound.	(01=Fwd, 03=Mid Fwd, 04=Mid Aft, 05=Aft) Replace the attendant's pink call light (FIM 33-25-00/101, Fig. 103, Block 1). (07=All) Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 03	Alert call from (01=Fwd, 03=Mid Fwd, 04=Mid Aft, 05=Aft, 06=Cockpit, 07=All) station(s) fails to sound chime. Attendant's pink call lgts come on.	Replace the passenger address amplifier, M177 (AMM 23-31-01/401). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401).

23-FAULT CODE INDEX

ALL

27.101 Page 12 May 20/09



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 42 04	Alert call from (01=Fwd, 03=Mid Fwd, 04=Mid Aft, 05=Aft, 06=Cockpit, 07=All) station(s) fails to sound chime and illum attendant's pink call lgts.	(01=Fwd, 03=Mid Fwd, 04=Mid Aft 05=Aft) Replace the handset, B61 that you used to place the call (WDM 23-42-11). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401). (06=Cockpit) Replace the pilots' call panel, M51 (AMM 23-42-02/401). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401). (07=All) Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 05	(01=Fwd, 02=Mid, 05=Aft) Attendant call from cockpit overhead cabin call button fails to sound chime. Attendant's pink call lgts are normal. Chime sounds when fasten seat belt switch is turned on.	Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 06	(01=Fwd, 02=Mid, 05=Aft) Attendant call from cockpit overhead cabin call button fails to sound chime. Attendant's pink call lgts are normal. Fasten seat belt switch also fails to sound chime.	Replace the passenger address amplifier, M177 (AMM 23-31-01/401).
23 42 07	(01=Fwd, 02=Mid, 05=Aft) Attendant call from cockpit overhead cabin call button fails to sound chime and illuminate attendant's pink call lights.	FIM 23-42-00/101, Fig. 103, Block 1
23 42 08	Cabin inph (describe problem: noisy, inop, no sidetone, etc.) when using (01=Capt, 02=F/0, 03=1st Obs) audio selector panel. Cabin inph normal using handsets.	Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401).

23-FAULT CODE INDEX

ALL

32.101

Page 13 Sep 20/08



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 42 09 00	Cabin inph (describe problem: noisy, inop, no sidetone, etc.) when using audio selector panels. Cabin inph normal when using handsets.	Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 10	Cabin inph (describe problem: noisy, inop, etc.) when using (04=Fwd, 05=Mid Fwd, 06=Mid Aft, 07=Aft) handset.	Replace the handset, B61 at the position where the problem occurs (WDM 23-42-11). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 11 00	Cabin inph (describe problem: noisy, inop, etc.) when using any handset.	Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 12	Call from corresponding attendants station(s) fail(s) to come on (01=Fwd, 02=Mid, 05=Aft, 06=Alert, 07=All) CABIN CALL light. Cockpit chime normal.	(01=Fwd, 02=Mid, 05=Aft, 06=Alert) Replace the CABIN CALL switchlight (WDM 23-42-11). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401). (07=All) Replace the audio accessory unit, M108 (AMM 23-42-01/401). If the problem continues, replace the pilots' call panel, M51 (AMM 23-42-02/401).
23 42 13	Call from (01=Fwd, 03=Mid Fwd, 04=Mid Aft, 05=Aft, 07=All) attendants station(s) fail(s) to sound cockpit chime. Corresponding CABIN CALL lgt(s) are normal.	Replace the audio accessory unit, M108 (AMM 23-42-01/401). If the problem continues, replace the bell chime module, M1000 (AMM 31-51-04/401).
23 42 14	Call from (01=Fwd, 03=Mid Fwd, 04=Mid Aft, 05=Aft, 07=All) attendants station(s) fail(s) to sound cockpit chime or illum corresponding CABIN CALL lgt(s).	(01=Fwd, 03=Mid Fwd, 04=Mid Aft, 05=Aft) Replace the handset, B61 at the position where the problem occurs (WDM 23-42-11). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401). (07=All) Replace the audio accessory unit, M108 (AMM 23-42-01/401).

23-FAULT CODE INDEX

ALL

33.101 Page 14 Sep 20/08



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 42 15 00	Cabin chime inop when calling from handsets. Call lgts do come on.	Replace the passenger address amplifier, M177 (AMM 23-31-01/401). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 15	(01=Fwd, 03=Mid Fwd, 04=Mid Aft, 05=Aft, 07=All) cabin chime(s) inop when calling from handsets. Call lgts do come on.	(01=Fwd, 03=Mid Fwd, 04=Mid Aft, 05=Aft) FIM 23-31-00/101, Fig. 103, Block 1. (07=All) Replace the passenger address amplifier, M177 (AMM 23-31-01/401). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 16	(01=Fwd, 02=Mid, 03=Mid Fwd, 04=Mid Aft, 05=Aft, 07=All) Attendants pink call lgt(s) inop when calling from handsets. Chime does sound.	(01=Fwd, 02=Mid, 03=Mid Fwd, 04=Mid Aft, 05=Aft) Replace the attendant's pink call light (FIM 33-25-00/101, Fig. 103, Block 1). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401). (07=All) Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 17 00	Cabin chime and call lgts inop when calling from handsets.	Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 17	(01=Fwd, 02=Mid, 03=Mid Fwd, 04=Mid Aft, 05=Aft, 07=All) Cabin chime(s) and pink call lgts inop when calling from handsets.	(01=Fwd, 02=Mid, 03=Mid Fwd, 04=Mid Aft, 05=Aft) FIM 23-42-00/101, Fig. 103, Block 1. (07=All) Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 18 00	Cabin chime sound is weak.	Replace the passenger address amplifier, M177 (AMM 23-31-01/401). If the problem continues, replace the accessory unit, M108 (AMM 23-42-01/401).

23-FAULT CODE INDEX

ALL

32.101

Page 15 Sep 20/08



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 43 01 00	Call from nose W/W fails to come on GND CALL lgt. Cockpit chime normal.	Replace the GND CALL switchlight (WDM 23-43-11). If the problem continues, replace the pilots' call panel, M51 (AMM 23-42-02/401).
23 43 02 00	Call from nose W/W fails to sound cockpit chime. GND CALL lgt ON.	Replace the pilots' call panel, M51 (AMM 23-42-02/401). If the problem continues, replace the bell chime module, M1000 (AMM 31-51-04/401).
23 43 03 00	Call from nose W/W fails to come on GND CALL lgt and sound cockpit chime.	Replace the pilots' call panel, M51 (AMM 23-42-02/401). If the problem continues, replace the FLT DECK CALL switch on the P62 panel (WDM 23-43-11).
23 51 01	(01=Capt, 02=F/0) Speaker (describe problem: low, noisy, etc.).	Replace the interphone speaker, B1 (B2) (AMM 23-51-02/401). If the problem continues, replace the audio selector panel, M70 (M71) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 02	(01=Capt, 02=F/0, 03=1st Obs, 04=2nd Obs) Headset (describe problem: noisy, unable to hear, etc.).	Replace the headset (WDM 23-51-11, WDM 23-51-21, WDM 23-51-41). If the problem continues, examine and replace the bad headset jack.
23 51 03	(01=Capt, 02=F/0, 03=1st Obs, 04=2nd Obs) Hand mic unsatisfactory.	Replace the hand microphone (WDM 23-51-11, WDM 23-51-21, WDM 23-51-51). If the problem continues, examine and replace the bad hand microphone jack.
23 51 04	(01=Capt, 02=F/0, 03=1st Obs, 04=2nd Obs) Boom mic unsatisfactory.	Replace the boom microphone (WDM 23-51-11, WDM 23-51-21, WDM 23-51-51). If the problem continues, examine and replace the bad boom microphone jack.

23-FAULT CODE INDEX

ALL

31.101

Page 16 Sep 20/08



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 51 05	(01=Capt, 02=F/0, 03=1st Obs, 04=2nd Obs) Oxygen mask mic unsatisfactory.	Replace the oxygen mask (WDM 23-51-11, WDM 23-51-21, WDM 23-51-51). If the problem continues, examine and replace the oxygen mask microphone connector.
23 51 06	Transmission is (describe problem: inop, intermittent, etc.) using (07=Capt, 08=F/0, 09=1st Obs, 10=2nd Obs) ASP push to talk sw.	Replace the audio selector panel, M70 (M71, M98, M10216) at the flight crew position when the problem occurs (AMM 23-51-01/401).
23 51 07	Transmission is (describe problem: inop, intermittent, etc.) using (07=Capt, 08=F/0) control wheel PTT sw in INT position.	Replace the control wheel PTT switch, S549 (S551) (AMM 23-51-03/401). If the problem continues, replace the audio selector panel, M70 (M71) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 08	Transmission is (describe problem: inop, intermittent, etc.) using (07=Capt, 08=F/0) control wheel PTT sw in MIC position. Corresponding ASP PTT is normal.	Replace the control wheel PTT switch, S550 (S552) (AMM 23-51-03/401).
23 51 09	Transmission is (describe problem: inop, intermittent, etc.) using (07=Capt, 08=F/0) ASP or control wheel PTT sw in MIC position. Other crewmember PTT is normal.	Replace the audio selector panel, M70 (M71) at the flight crew position where the problem occurs (AMM 23-51-01/401).

23-FAULT CODE INDEX

ALL

33.101 Page 17 Sep 20/08



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 51 10	All control wheel MIC and audio select push-to-talks are not normal for (01=L VHF, 02=R VHF, 03=C VHF, 04=L HF, 05=R HF, 06=INPH, 07=Capt, 08=F/0, 09=1st Obs, 10=2nd Obs).	(01=L VHF, 02=R VHF, 03=C VHF) Replace the VHF comm transceiver, M188 (M189, M190) (AMM 23-12-01/401). (04=L HF, 05=R HF) Replace the HF comm transceiver, M152 (M153)(AMM 23-11-03/401). (06=INPH) Replace the audio accessory unit, M108 (AMM 23-42-01/401). (07=Capt, 08=F/0, 09=1st 0bs, 10=2nd 0bs) Replace the audio selector panel, M70 (M71, M98, M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 11 00	Transmission from nose W/W on flt inph (describe problem: noisy, inop, etc.).	Replace the FLIGHT INPH jack on the P62 panel (WDM 23-51-13).
23 51 12 00	Reception at nose W/W on flt inph (describe problem: noisy, inop, etc.).	Replace the FLIGHT INPH jack on the P62 panel (WDM 23-51-13).
23 51 13	Flight inph reception at (01=Capt, 02=F/0, 03=1st Obs, 04=2nd Obs) audio selector panel (describe problem: noisy, inop, etc.). Other stations normal.	Replace the audio selector panel, M70 (M71, M98, M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 14	Flight inph transmission at (01=Capt, 02=F/0, 03=1st Obs, 04=2nd Obs) audio selector panel (describe problem: noisy, inop, etc.). Other stations normal.	Replace the audio selector panel, M70 (M71, M98, M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 15 00	Flight inph abnormal at all crew stations.	Replace the audio accessory unit, M108 (AMM 23-42-01/401).

23-FAULT CODE INDEX

ALL

40.101

Page 18 May 20/09



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 51 17	(01=Capt, 02=F/0, 03=1st Obs, 04=2nd Obs) Audio selector panel has bleed through (describe).	Replace the audio selector panel, M70 (M71, M98, M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401). If the problem continues, do an inspection of the contrahelical cable and include the shield wire connections at burndy block GD1757-ST for (Capt, F/O), GD1758-ST (1st Obs, 2nd Obs). Do an inspection of the load resistors R10233, R10234. Repair or relace the components as necessary (WDM 23-51-11, WDM 23-51-14, WDM 23-51-21, WDM 23-51-41, WDM 23-51-51).
23 51 18	(01=Capt, 02=F/0, 03=1st Obs, 04=2nd Obs) Audio selector panel lighting faulty (volume control, etc.).	
23 51 19	(01=Capt, 02=F/0, 03=1st Obs, 04=2nd Obs) Audio selector panel volume control (inop, knobs broken, loose, etc.).	Replace the audio selector panel, M70 (M71, M98, M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 20	Cockpit speaker will not mute with (01=Capt, 02=F/O) Audio selector panel in OXY position, using hand mic.	Replace the audio selector panel, M70 (M71) at the flight crew position where the problem occurs (AMM 23-51-01/401). If the problem continues, replace the interphone speaker, B1 (B2) (AMM 23-51-02/401).

23-FAULT CODE INDEX

ALL

28.101

Page 19 Sep 20/08



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 51 21	Unable to transmit, transmission weak, etc., using mic select sw position on (01=Capt, 02=F/0, 03=1st Obs, 04=2nd Obs) audio selector panel.	Replace the audio selector panel, M70 (M71, M98, M10216) at the flight crew position where problem occurs (AMM 23-51-01/401). If the problem continues, do a check of and replace the boom or the hand microphone jack at the position where the problem occurs (WDM 23-51-11, WDM 23-51-21, WDM 23-51-41).
23 51 22	Unable to receive, reception weak, intermittent, etc., using mic select sw position on (01=Capt, 02=F/0, 03=1st 0bs, 04=2nd 0bs) audio selector panel.	Replace the audio selector panel, M70 (M71, M98, M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 26	Sidetone (missing, weak, intermittent, etc.) using (O1=Capt, O2=F/O, O3=1st Obs, O4=2nd Obs) audio selector panel.	Replace the audio selector panel, M70 (M71, M98, M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 27	(Identify sw) mic select sw (will not stay engaged, sticks, etc.) on (01=Capt, 02=F/0, 03=1st Obs, 04=2nd Obs) ASP.	Replace the audio selector panel, M70 (M71, M98, M10216) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 28	(07=Capt, 08=F/0) Control wheel PTT sw (will not stay engaged, sticks, etc.) in INT position.	Clean the rocker and the switch with a contact cleaner. If the problem continues, replace the control wheel PTT switch, S549 (S551) (AMM 23-51-03/401).
23 51 29	(07-Capt, 08=F/O) Control wheel PTT sw (sticks, etc.) in MIC position.	Clean the rocker and the switch with a contact cleaner. If the problem continues, replace the control wheel PTT switch, S550 (S552) (AMM 23-51-03/401).
23 51 30 00	Sidetone (missing, weak, intermittent, etc.) all audio selector panels.	Replace the audio accessory unit, M108 (AMM 23-42-01/401).

23-FAULT CODE INDEX

ALL

29.101 Page 20 Sep 20/08



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
23 71 01 00	Voice recorder signal is (describe problem: noisy, missing, etc.) at monitor jack.	FIM 23-71-00/101, Fig. 103, Block 1
23 71 02 00	Voice recorder monitor response to test is, describe problem: low, high, etc.	FIM 23-71-00/101, Fig. 103, Block 1

23-FAULT CODE INDEX

ALL

23.101

Page 21 Sep 20/08



BITE Index

1. General

- A. Use this index to find the BITE procedure for the applicable LRU/System.
- B. The BITE procedure will provide the fault isolation instructions for the fault indications/LRU maintenance messages.

LRU/System Name	<u>Acronym</u>	FIM Reference
Air Data Computer	ADC	34-12
Air Data Inertial Reference Unit	ADIRU	34-26
Air Traffic Control Transponder	ATC	34-53
Airborne Vibration Monitor Signal Conditioner	AVM	77-31
Antiskid/Autobrake Control Unit		32-42
APU Fire Detection System		26-15
Automatic Direction Finder Receiver	ADF	34-57
APU Control Unit	ECU	49-11
Brake Temperature Monitor Unit		32-46
Bus Power Control Unit	BPCU	24-20
Cabin Pressure Controller		21-30
Digital Flight Data Acquisition Unit	DFDAU	31-31
Distance Measuring Equipment Interrogator	DME	34-55
Duct Leak (Wing and Body)		26-18
E/E Cooling Control Card (If cards installed)		21-58
ECS Bleed Configuration Card		36-10
Electronic Engine Control (RR Engines)	EEC	73-21
Electronic Engine Control Monitor Unit (PW Engines)	EECM	71-EPCS Message Index
Electronic Flight Instrument System	EFIS	34-22
Electronic Propulsion Control System (PW Engines)	EPCS	71-EPCS Message Index
Engine Fire/Overheat Detection System		26-11
Engine Indication and Crew Alerting System Computer	EICAS	31-41

Bite Index Figure 1 (Sheet 1)

EFFECTIVITY

23-BITE INDEX



LRU/System Name	Acronym	FIM Reference
Engine Turbine Cooling Overheat Detection System (RR Engines)		26-13
Enhanced Ground Proximity Warning Computer	EGPWC	34-46
Flap/Slat Accessory Module	FSAM	27-51
Flap/Slat Electronic Unit	FSEU	27-51
Flight Management Computer	FMC	34-61
Fuel Quantity Indicating System Processor	FQIS	28-41
Ground Proximity Warning Computer	GPWC	34-46
HF (High Frequency) Communication		23-11
Inertial Reference Unit	IRU	34-21
Instrument Comparator Unit	ICU	34-25
Instrument Landing System Receiver	ILS	34-31
Lower Cargo Compartment Smoke Detection System		26-16
Maintenance Control Display Panel	MCDP	22-00
PA (Passenger Address) Amplifier		23-31
Pack Standby Temperature Controller		21-51
Pack Temperature Controller		21-51
Passenger Entertainment System	PES	23-34
Power Supply Module (Control System Electronics Units)	PSM	27-09
Propulsion Discrete Interface Unit (PW Engines)	PDIU	73-21
Proximity Switch Electronics Unit	PSEU	32-09
Radio Altimeter Transmitter/Receiver	RA	34-33
Rudder Ratio Changer Module	RRCM	27-09
Spoiler Control Module	SCM	27-09
Stabilizer Position Module	SPM	27-48
Stabilizer Trim/Elevator Asymmetry Limit Module	SAM	27-09
Stall Warning Computer/Module (in Warning Electronic Unit)	SWC	27–32
Strut Overheat Detection System (RR Engines)		26–12

Bite Index Figure 1 (Sheet 2)

EFFECTIVITY-

23-BITE INDEX

ALL

01 Page 2 Sep 28/99



<u>LRU/System Name</u>	<u>Acronym</u>	FIM Reference
Thrust Management Computer/Autothrottle	TMC	22-00
Traffic Alert and Collision Avoidance Computer	TCAS	34-45
VHF (Very High Frequency) Communication		23–12
VOR/Marker Beacon Receiver	VOR/MKR	34-51
Warning Electronic Unit BITE Module (Stall Warning)	WEU	27–32
Weather Radar Transceiver	WXR	34-43
Wheel Well Fire Detection		26-17
Window Heat Control Unit	WHCU	30-41
Yaw Damper Module	YDM	22-21
Yaw Damper/Stabilizer Trim Module	YSM	27-09
Zone Temperature Controller		21-60

Bite Index Figure 1 (Sheet 3)

23-BITE INDEX

01

Page 3 Sep 28/99



HF COMMUNICATIONS SYSTEM

COMPONENT		QTY	ACCESS/AREA	AMM REFERENCE
ANTENNA - HF, M244	2	1	322CL, VERTICAL FIN	23-11-00
CIRCUIT BREAKER -	2		FLT COMPT, P11	
HF COMM LEFT, C3005		1	11G8	*
HF COMM RIGHT, C3006		1	11G34	*
COUPLER - L HF COMM ANTENNA, M241	2	1	322CL, VERTICAL FIN	23-11-01
COUPLER - R HF COMM ANTENNA, M242	2	1	322CL, VERTICAL FIN	23-11-01
PANEL - L HF COMM CONT, M82 _	2	1	FLT COMPT, P5	23-11-02
PANEL - R HF COMM CONT, M83 1	2	1	FLT COMPT, P5	23-11-02
TRANSCEIVER - L HF COMM, M152	1	1	119BL, MAIN EQUIP CTR, E4-3	23-11-03
TRANSCEIVER - R HF COMM, M153 1	1	1	119BL, MAIN EQUIP CTR, E3-2	23-11-03

^{*} SEE THE WDM EQUIPMENT LIST

1>> GUI 001-099


HF Communications System - Component Index Figure 101

ALL

003636

23-11-00






RIGHT HF
COMMUNICATION
TRANSCEIVER,
M153 (E3-2)
SEE A

LEFT HF
COMMUNICATION
TRANSCEIVER,
M152 (E4-3)
SEE A

MAIN EQUIPMENT
CENTER ACCESS
DOOR, 119BL

AFT EQUIPMENT CENTER 2

MAIN EQUIPMENT CENTER 1



LEFT OR RIGHT COMMUNICATION TRANSCEIVER, M152 OR M153



1 GUI 001-099 2 GUI 101-999

HF Communications System - Component Location Figure 102 (Sheet 1)

ALL

23-11-00


16

Page 102 Dec 20/93

A77048



FAULT ISOLATION/MAINT MANUAL



EFFECTIVITY ALL

984873

23-11-00


14

Page 103 Dec 20/93



PREREQUISITES MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 11G8; 1>> 11G34 MAKE SURE THE AIRPLANE IS IN THE CONFIGURATION THAT HIGH FREQUENCY COM-FOLLOWS: MUNICATIONS SYSTEM ELECTRICAL POWER IS ON (MM 24-22-00/201) BITE PROCEDURE YES SET THE MODE SELECTOR TO 10 PUSH THE "SQL/LAMP TEST" 20 REPLACE THE LEFT (RIGHT) "AM" ON THE LEFT (RIGHT) HF SWITCH ON THE TRANSCEIVER HF COMM TRANSCEIVER M152 COMM CONTROL PANEL ON P5. SET FRONT PANEL. (M153)(MM 23-11-03/401). THE FREQUENCY SELECTORS TO THE DO ONE OR MORE OF THE APPLICABLE AM FREQUENCY. STATUS LIGHTS COME ON? IS THE INTERNAL BLOWER NO MOTOR ON THE LEFT (RIGHT) HF COMM TRANSCEIVER ON? 21 REPLACE THE LEFT (RIGHT) HF COMM TRANSCEIVER M152 (M153)(MM 23-11-03/401). IF THE PROBLEM CONTINUES, REPLACE THE LEFT (RIGHT) HF COMM CONTROL PANEL M82 (M83) (MM 23-11-02/401). NO 2 PUSH THE "SQL/LAMP TEST" 22 REPLACE THE LEFT (RIGHT) SWITCH ON THE LEFT (RIGHT) HF HF COMM TRANSCEIVER M152 COMM TRANSCEIVER FRONT PANEL. (M153)(MM 23-11-03/401). DO ALL OF THESE STATUS LIGHTS COME ON? "LRU FAIL" "KEY INTERLOCK" "CONTROL INPUT FAIL" N0 3 RELEASE THE "SQL/LAMP 23 DO THE CORRECTION PRO-TEST" SWITCH ON THE LEFT CEDURE FOR THE LIGHT THAT IS (RIGHT) TRANSCEIVER FRONT ON. REFER TO TABLE 101. PANEL. DO ALL THE STATUS LIGHTS GO OFF? YFS NO 4 CONNECT THE HEADSET TO THE 24 REPLACE THE LEFT (RIGHT) "PHONE" JACK ON THE TRANS-HF COMM TRANSCEIVER M152 CEIVER FRONT PANEL. LISTEN ON (M153)(MM 23-11-03/401). THE HEADSET. MOMENTARILY PUSH AND RELEASE THE "SQL/LAMP NOTE: BITE DOES A TEST OF THESE SYSTEM COMPONENTS: TEST" SWITCH. DOES THE RECEIVER NOISE HF COMM TRANSCEIVER MOMENTARILY INCREASE AND THEN HF COMM CONTROL PANEL DECREASE TO A SATISFACTORY HF ANTENNA COUPLER BITE DOES NOT DO A TEST OF THESE SYSTEM COMPONENTS: LEVEL? HF ANTENNA YES SEE SHEET 2 (BLOCK 5) 1 AIRPLANES WITH DUAL HE SYSTEMS.


High Frequency Communications System BITE Procedure Figure 103 (Sheet 1)



STATUS LIGHT ON	CORRECTIVE ACTION
LRU FAIL	REPLACE THE LEFT (RIGHT) HF COMM TRANSCEIVER, M152 (M153) (AMM 23-11-03/401).
KEY INTERLOCK	1. REPLACE THE LEFT (RIGHT) HF COMM ANTENNA COUPLER, M241 (M242) (AMM 23-11-01/401). 2. IF THE PROBLEM CONTINUES, REPLACE THE LEFT (RIGHT) HF COMM TRANSCEIVER, M152 (M153)(AMM 23-11-03/401). 3. IF THE PROBLEM CONTINUES, DO THE TIME DOMAIN REFLECTOMETRY CHECK OF THE ANTENNA SYSTEM (AMM 20-10-32/201). REPAIR THE COAXIAL CABLE AS NECESSARY (WDM 23-11-11,-21).
CONTROL INPUT FAIL	1. REPLACE THE LEFT (RIGHT) HF COMM CONTROL PANEL, M82 (M83) (AMM 23-11-02/401). 2. IF THE PROBLEM CONTINUES, REPLACE THE LEFT (RIGHT) HF COMM TRANS- CEIVER, M152 (M153)(AMM 23-11-03/401).

TABLE 101

High Frequency Communications System BITE Procedure Figure 103 (Sheet 2)





1. Fault Isolation - Tips

- A. HF Communication System faults can be caused by Flight Interphone System faults. If HF failures continue after the replacement of HF equipment, then replace suspected Flight Interphone System equipment (FIM 23-51-00/101).
 - (1) The equipment that follows are possible causes of HF audio input or keyline circuitry faults:
 - (a) audio selector panel or audio control panel
 - (b) audio management unit, if installed (only on airplanes with audio control panels)
 - (c) headsets, boom microphone headsets
 - (d) hand microphones
 - (e) control wheel push-to-talk switch
 - (f) flight interphone jacks for headsets and microphones
 - (g) wiring between the Flight Interphone System and HF Communication System.

2. ARINC Data Bus Charts

A. General

<u>CAUTION</u>: DO NOT DIRECTLY TOUCH THE CONNECTORS. USE A BREAKOUT BOX OR YOU CAN CAUSE DAMAGE TO THE CONNECTORS.

(1) The ARINC 429 data bus charts give data necessary to make an analysis of ARINC 429 transmitters, receivers, and data buses. For the test, use a breakout box at the available terminal or at the LRU connectors.

B. Equipment

- (1) Standard multi-meter
- (2) 429EBP Data Bus Analyzer (recommended) JcAIR Instrumentation 400 Industrial Parkway Industrial Airport, KS 66031

429-2 Data Bus Analyzer (alternative) Interface Technology 150 E. Arrow Highway San Dimas, CA 91773

(3) A34011-1 Breakout Box (recommended)
A34011-112 Breakout Box (alternative)

HF PNL									
DIGITAL OUTPUT BUS CHART									
BUS NAME	CON	PIN	S	BUS	BIT	DATA			
SOURCE	TYPE	BUS				FORMAT	RATE	BUS	
HFPNL (L R)	Α	1		09	10	429	LO	FREQ FUNC SELECT	

ALL ALL

23-11-00



HF PNL ID=B9								
OCTAL LABELS CHART								
SIGNAL	TYPE	LABEL	FORMAT	MIN UPDATE RATE	SDI	BINARY RANGE	POSITIVE SENSE	UNITS
HF FREQ SELECT	Α	037	BCD	5		2.8-24	N/A	MHZ

23-11-00



VHF COMMUNICATIONS SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
ANTENNA - C VHF COMM, M247 ANTENNA - L VHF COMM, M245 ANTENNA - R VHF COMM, M246 CIRCUIT BREAKER -	1 1 1 2	1 1 1	BOTTOM FUSELAGE, AFT TOP FUSELAGE, FWD BOTTOM FUSELAGE, FWD FLT COMPT, P11	23-12-03 23-12-03 23-12-03
VHF COMM CENTER, C546 VHF COMM LEFT, C544 VHF COMM RIGHT, C545 PANEL - (FIM 23-51-00/101) CAPT AUDIO SELECTOR, M70 F/O AUDIO SELECTOR, M71 OBS AUDIO SELECTOR, M98		1 1 1	11G4 11C3 11G31	* *
PANEL - C VHF CONTROL, M80 PANEL - L VHF CONTROL, M78 PANEL - R VHF CONTROL, M79 RELAY - (FIM 31-01-36/101) AIR/GROUND, K10388 RELAY - (FIM 31-01-37/101) AIR/GROUND, K200	2 2 2	1 1 1	FLT COMPT, P8 FLT COMPT, P8 FLT COMPT, P8	23-12-02 23-12-02 23-12-02
AIR/GROUND, K201 TRANSCEIVER - C VHF COMM, M190 TRANSCEIVER - L VHF COMM, M188 TRANSCEIVER - R VHF COMM, M189 UNIT - (FIM 31-31-00/101) FLT DATA ACQUISITION, M138	2 2 2	1 1 1	119BL, MAIN EQUIP CTR, E4-3 119BL, MAIN EQUIP CTR, E4-3 119BL, MAIN EQUIP CTR, E4-3	23-12-01 23-12-01 23-12-01

^{*} SEE THE WDM EQUIPMENT LIST

1>> GUI 001-099


2 GUI 001-008,010-099


VHF Communications System - Component Location Figure 101

EFFECTIVITY-ALL 23-12-00

D03746







1 AIRPLANES WITH A CENTER VHF COMMUNICATION ANTENNA INSTALLED

B06877

VHF Communication System - Component Location Figure 102 (Sheet 1)


23-12-00


06

Page 102 Dec 20/95



FAULT ISOLATION/MAINT MANUAL







FLIGHT COMPARTMENT

LEFT, RIGHT, OR CENTER VHF COMMUNICATION CONTROL PANEL, M78, M79, OR M80







LEFT, RIGHT OR CENTER VHF COMMUNICATION TRANSCEIVER, M188,M189, OR M190

VHF Communications System - Component Location Figure 102 (Sheet 2)


EFFECTIVITY-GUI 001-008, 010-099 23-12-00


18

Page 103 Dec 20/93




FAULT ISOLATION/MAINT MANUAL






MAIN EQUIPMENT CENTER

FLIGHT COMPARTMENT



LEFT OR RIGHT VHF COMMUNICATION CONTROL PANEL,
M78 OR M79



VHF Communications System - Component Location Figure 102 (Sheet 3)

GUI 009, 101-999

23-12-00

15

Page 104 Dec 20/93

A77201




PREREQUISITES

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 11C3,11G31,11G4

MAKE SURE THE AIRPLANE IS IN THE CONFIGURATION THAT FOLLOWS:

ELECTRICAL POWER IS ON (MM 24-22-00/201)

VHF COMMUNICATIONS TRANSCEIVER BITE PROCEDURE




VHF Communications Transceiver BITE Procedure Figure 103 (Sheet 1)

23-12-00

09

Page 105 Dec 20/93



NOTE: BITE DOES A TEST OF THESE SYSTEM COMPONENTS:

- VHF COMM TRANSCEIVER
- VHF COMM CONTROL PANEL
- VHF COMM ANTENNA
- VHF COMM ANTENNA CABLE.

VHF Communications Transceiver BITE Procedure Figure 103 (Sheet 2)




VHF COMMUNICATIONS TRANSCEIVER BITE PROCEDURE

PREREQUISITES

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 11C3, 11G31

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (MM 24-22-00/201)



NOTE: BITE DOES A TEST OF THESE SYSTEM COMPONENTS:

- VHF COMM TRANSCEIVER
 - VHF COMM CONTROL PANEL

BITE DOES NOT DO A TEST OF THESE SYSTEM COMPONENTS:

- VHF COMM ANTENNA
- VHF COMM ANTENNA CABLE

STATUS LIGHT ON	CORRECTION PROCEDURE
RED COMM LIGHT	REPLACE THE LEFT (RIGHT) VHF COMM TRANSCEIVER M188 (M189) (AMM 23-12-01/401).
RED DATA IN LIGHT	REPLACE THE LEFT (RIGHT) VHF COMM CONTROL PANEL M78 (M79) (AMM 23-12-02/401). IF THE PROBLEM CONTINUES, REPLACE THE LEFT (RIGHT) VHF COMM TRANSCEIVER M188 (M189)(AMM 23-12-01/401).

TABLE A

VHF Communications Transceiver BITE Procedure Figure 103 (Sheet 3)

GUI 009, 101-999

23-12-00

07

Page 107 May 28/03



1. Fault Isolation - Tips

- A. VHF Communication System faults can be caused by Flight Interphone System faults. If VHF failures continue after the replacement of VHF equipment, then replace suspected Flight Interphone System equipment (FIM 23-51-00/101).
 - (1) The equipment that follows are possible causes of VHF audio input or keyline circuitry faults:
 - (a) audio selector panel or audio control panel
 - (b) audio management unit, if installed (only on airplanes with audio control panels)
 - (c) headsets, boom microphone headsets
 - (d) hand microphones
 - (e) control wheel push-to-talk switch
 - (f) flight interphone jacks for headsets and microphones
 - (g) wiring between the Flight Interphone System and VHF Communication System.

2. ARINC Data Bus Charts

A. General

<u>CAUTION</u>: DO NOT DIRECTLY TOUCH THE CONNECTORS. USE A BREAKOUT BOX OR YOU CAN CAUSE DAMAGE TO THE CONNECTORS.

(1) The ARINC 429 data bus charts give data necessary to make an analysis of ARINC 429 transmitters, receivers, and data buses. For the test, use a breakout box at the available terminal or at the LRU connectors.

B. Equipment

- (1) Standard multi-meter
- (2) 429EBP Data Bus Analyzer (recommended) JcAIR Instrumentation 400 Industrial Parkway Industrial Airport, KS 66031

429-2 Data Bus Analyzer (alternative) Interface Technology 150 E. Arrow Highway San Dimas, CA 91773

(3) A34011-1 Breakout Box (recommended) A34011-112 Breakout Box (alternative)

VHF PNL								
DIGITAL OUTPUT BUS CHART								
BUS NAME				PINS	BUS	BIT	DATA	
SOURCE	TYPE	BUS			FORMAT	RATE	BUS	
VHFPNL (L C R)	Α	1		17 18	429	LO	FREQ FUNC SELECT	

EFFECTIVITY-

ALL

23-12-00



VHF PNL ID = B6								
OCTAL LABELS CHART								
SIGNAL	TYPE	LABEL	FORMAT	MIN UPDATE RATE	SDI	BINARY RANGE	POSITIVE SENSE	UNITS
FREQ/FUNCTION SEL	Α	030	BCD	5		118-136.97	N/A	MHZ

 23-12-00



SELCAL SYSTEM

	FIG. 102			
COMPONENT	SHT	QTY	ACCESS/AREA	REFERENCE
CIRCUIT BREAKER - SELCAL, C539		1	FLT COMPT, P11 11G3	
DECODER - SELCAL, M180 MODULE - (31-51-00/101) AURAL WARNING BELL, M1000 PANEL - (23-42-00/101) PILOTS' CALL, M51		1	119BL, MAIN EQUIP CTR, E4-3	23-21-01
RECEPTACLE - SELCAL SHORTING, M974		1	119BL, MAIN EQUIP CTR, BACK OF E4-3	*
SWITCHES - (23-42-00/101)		1		
C VHF COMM, S2 L HF COMM, S4		1		
L VHF COMM, S1		1		
R HF COMM, S5		i		
R VHF COMM, S3		1		
L HF COMM, S4				
L VHF COMM, S1				
K Hr COMM, 33				
R VHF COMM, S2 J				
TRANSCEIVERS - (23-11-00/101)				
L HF COMM, M152				
R HF COMM, M153 TRANSCEIVERS - (23-12-00/101)				
C VHF COMM, M190 1				
L VHF COMM, M188				
R VHF COMM, M189				

^{*} SEE THE WDM EQUIPMENT LIST

ALL EXCEPT GUI XA-MMX

GOING THE STATE OF TH

Selcal System - Component Index Figure 101


23-21-00

17


Page 101 Mar 20/94




FAULT ISOLATION/MAINT MANUAL



FLIGHT COMPARTMENT





RIGHT

(S2)

SWITCH,

LEFT

(S4)

SWITCH,

VHF COMM HF COMM

SELCAL

RIGHT

(S5)

HF COMM

SWITCH,

LEFT

(S1)

VHF COMM

SWITCH,

PILOTS' CALL PANEL, M51 (REF)

1 >> ALL EXCEPT GUI XA-MMX

> GUI XA-MMX

A69850

Selcal System - Component Location Figure 102

EFFECTIVITY-ALL

23-21-00

19

Page 102 Mar 20/94



PASSENGER ADDRESS SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
AMPLIFIER - PASSENGER ADDRESS, M177	1	1	119BL, MAIN EQUIP CTR, E4-3	23-31-01
CIRCUIT BREAKER -	1		FLT COMPT, P11	
PASS ADRS AMPL, C548		1	11022	*
TAPE REPRO DC, C4027		1	11H34	*
CIRCUIT BREAKER -	1		119BL, MAIN EQUIP CTR, P37	
TAPE RPDR AC, C4028		1	37E2	*
DIODE		*	119BL, MAIN EQUIP CTR, E4-3, TB141A	*
RELAYS -				
ANNOUNCEMENT CONTROL, K10637	1	1	119BL, MAIN EQUIP CTR, P36	*
MUTING, K10270	2,3	1	PASS. CABIN, ATTND CEILING PANEL	*
MUTING, K10498	2,3	1	PASS. CABIN, AFT L CEILING PANEL	*
MUTING, K10500	2,3	1	PASS. CABIN, FWD R CEILING PANEL	*
MUTING, K10503	2,3	1	PASS. CABIN, MID L CEILING PANEL	*
RELAYS - (31-01-34/101)				
FASTEN SEAT BELT, K10028				
NO SMOKING, K10029				
RELAY - (31-01-36/101)				
LEFT ENG START TO STOP, K10212				
RELAYS - (31-01-37/101)				
OXYGEN DEPLOY INDICATION, K10038				
RIGHT ENG START TO STOP, K10224				
REPRODUCER - BOARDING MUSIC TAPE, M10031 2	3	1	119B1, MAIN EQUIP CTR, E4-4	23-31-06
REPRODUCER - BOARDING MUSIC TAPE, M10748 1	2	1	PASS. CABIN, LEFT FWD LAV WALL	23–31–06
LAVATORY, LAV A, M10012	2,3	1	PASS. CABIN, LEFT FWD LAV	23-31-05
LAVATORY, LAV C, M10014	2,3	1	PASS. CABIN, LEFT MID LAV	23-31-05
LAVATORY, LAV D, M10015	2,3	1	PASS. CABIN, RIGHT MID LAV	23-31-05
LAVATORY, LAV F, M10013 2	3	1	PASS. CABIN, LEFT FWD MID LAV	23-31-05
LAVATORY, LAV S, M10654 1>	2	1	PASS. CABIN, LEFT MID LAV	23-31-05
PA, B10110	2,3	1	PASS. CABIN, AFT L CEILING PANEL	23-31-08
PA, B10111	2,3	1	PASS. CABIN, FWD R CEILING PANEL	23-31-08
PA, B10112	2,3	1	PASS. CABIN, FWD L CEILING PANEL	23-31-08
PA, B10114	2,3	1	PASS. CABIN, MID R CEILING PANEL	23-31-08
PA, B10116	2,3	1	PASS. CABIN, MID L CEILING PANEL	23-31-08
PA, B10140	2,3	1	PASS. CABIN, AFT R CEILING PANEL	23-31-08
PSÚ, M10342	2,3	*	PASS. CABIN, PSU MODULES	23-31-02
PSU, M10343	2,3	2	PASS. CABIN, MID ATTND STA	23-31-02
SWITCH - (33-22-00/101)			_	
BOARDING MUSIC REMOTE CONTROL, \$10179				
UNIT - (23-42-00/101)				
AUDIO ACCESSORY, M108				

*	SEE	THE	WDM	EQUIPMENT	LIST

1 GUI 001-014 2 GUI 115

Passenger Address System - Component Index Figure 101

EFFECTIVITY-

ALL


23-31-00

27

Page 101 Dec 20/92



FAULT ISOLATION/MAINT MANUAL



Passenger Address System - Component Location Figure 102 (Sheet 1)

ALL


ALL

23 Page 102


Dec 20/92

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.





HANDSET AND SPEAKER LOCATIONS



Passenger Address System - Component Location Figure 102 (Sheet 2)

GUI 001-014

23-31-00

25


Page 103

Dec 20/92

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.



FAULT ISOLATION/MAINT MANUAL



Passenger Address System - Component Location Figure 102 (Sheet 3)

EFFECTIVITY-23-31-00 **GUI 115** 10 Page 104 Dec 20/92 BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.




PREREQUISITES

MAKE SURE THIS CIRCUIT BREAKER IS CLOSED: 11C22 PASSENGER ADDRESS

AMPLIFIER BITE

MAKE SURE THE AIRPLANE IS IN THE CONFIGURATION THAT FOLLOWS:

ELECTRICAL POWER IS ON (MM 24-22-00/201)



Passenger Address Amplifier BITE Procedure Figure 103 (Sheet 1)






TABLE 101								
SPEAKER LOCATION	SPEAKER EQUIP NO.	MM REFERENCE	MUTING RELAY EQUIP NO. (WDM 23-31-42)					
LAV A	M10012	23-31-05						
LAV C	M10014	23-31-05						
LAV D	M10015	23-31-05						
LAV F 2	M10013	23-31-05						
LAV S 1	M10654	23-31-05						
PA - AFT L	B10110	23-31-08	K10498					
PA - AFT R	B10140	23-31-08	K10498					
PA - FWD R	B10111	23-31-08	K10500					
PA - FWD L	B10112	23-31-08	K10500					
PA - FWD MID L	B10116	23-31-08	K10503					
PA - FWD MID R	B10114	23-31-08	K10503					
PA - MID L	M10343	23-31-02	K10270					
PA - MID R	M10343	23-31-02	K10270					
PSU	M10342	23-31-02						

- SPEAKERS, RELAYS AND WIRING.

BITE DOES NOT DO A TEST OF THESE SYSTEM COMPONENTS:

- AUDIO ACCESSORY UNIT
- ENTERTAINMENT MUSIC TAPE REPRODUCER.

> GUI 001-014

Passenger Address Amplifier BITE Procedure Figure 103 (Sheet 2)

EFFECTIVITY-

23-31-00

ALL

06

Page 106 Dec 20/92



PASSENGER ENTERTAINMENT (VIDEO) SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
AMPLIFIER - (23-31-00/101)				
PASSENGER ADDRESS, M177				
BOX - AFT INTERFACE, M10685	1	1	PASS. CABIN	*
BOX - FWD INTERFACE, M10684	1	1	PASS. CABIN	*
BOX - JUNCTION, M10668		1	PASS. CABIN, VIDEO CONTROL CTR	*
CIRCUIT BREAKERS -	1		119BL, MAIN EQUIP CTR, P37	
VIDEO SYSTEM (MAIN BUS) MONITOR AFT, C4441		1	37A7	*
VIDEO SYSTEM (MAIN BUS) MONITOR FWD, C4440		1	37A6	*
VIDEO SYSTEM (MAIN BUS) SYSTEM AC, C4442		1	37A8	*
VIDEO SYSTEM (UTIL BUS) MONITOR AFT, C4362		1	3707	*
VIDEO SYSTEM (UTIL BUS) MONITOR FWD, C4361		1	3706	*
VIDEO SYSTEM (UTIL BUS) SYSTEM AC, C4363	_	1	3708	*
CIRCUIT BREAKER -	1		FLT COMPT, P11	*
VIDEO SYSTEM DC, C4364	1	1	11H30	*
MONITORS -	1	1	PASS. CABIN	23-32-01
NO. 1, M10669 NO. 2, M10670			PASS. CABIN	23-32-01
NO. 3, M10671			PASS. CABIN	23-32-02
NO. 4, M10672			PASS. CABIN	23-32-02
NO. 5, M10673			PASS. CABIN	23-32-02
NO. 6, M10674		1	PASS. CABIN	23-32-02
NO. 7, M10675		i	PASS. CABIN	23-32-02
RELAYS - (31-01-37/101)		'		== == ==
BUS SWITCHING, K10642				
SYS NO. 2 AIR/GND, K10239				
REPRODUCER - VIDEO TAPE	2	1	PASS. CABIN, VIDEO CONTROL CTR	23-32-04
UNIT - SYSTEM CONTROL	2	1	PASS. CABIN, VIDEO CONTROL CTR	23-32-03


^{*} SEE THE WDM EQUIPMENT LIST

Passenger Entertainment (Video) System - Component Index Figure 101

EFFECTIVITY—GUI 115

23-32-00





Passenger Entertainment (Video) System - Component Location Figure 102 (Sheet 1)


EFFECTIVITY
GUI 115

23-32-00

11 Page 102
Dec 20/93


BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.





SYSTEM CONTROL UNIT (SCU)





VIDEO TAPE REPRODUCER (VTR)



Passenger Entertainment (Video) System - Component Location Figure 102 (Sheet 2)

A46063

23-32-00

11

Page 103 Sep 20/92



PASSENGER ENTERTAINMENT SYSTEM (PES)

COMPONENT	FIG. 102 SHT	OTV	ACCESS / ADEA	DEFEDENCE
COMPONENT	эпі	QTY	ACCESS/AREA	REFERENCE
AMPLIFIER - (23-31-00/101) PASSENGER ADDRESS, M177,M10782				
BOX - SEAT ELECTRONICS	2,3	1	EACH PASS. SEAT GROUP	
CIRCUIT BREAKERS -	1		FLT COMPT, P11	
ENTMT DC, C4434		1	11H34	*
PASSENGER ADDRESS, C548		1	11022	*
CIRCUIT BREAKERS -	1		119BL, MAIN EQUIP CTR, P37	
ENT TAPE RPDR, C4426 1		1	37B7	*
MULTIPLEXER, C4403		1	37B8	*
TAPE RPDR, C4028 2>		1	37E2	*
CONTROL - (33-22-00/101) 2				
BOARDING MUSIC, S10179		_		
MULTIPLEXER - MAIN, M10733	1	1	119BL, MAIN EQUIP CTR, E4-4	23-34-01
PANEL - (33-22-00/101)				
FWD ATTENDANT, P21				
DELAYO (74 04 7//404)				
RELAYS - (31-01-36/101)				
AUDIO PRIORITY CONTROL, K10641				
MUX PWR, K10599				
TAPE REP PWR, K10600 2 REPRODUCER - ENTERTAINMENT TAPE, M130	1	1	119BL, MAIN EQUIP CTR, E4-4	23-34-03
SWITCH - ENTERTAINMENT CONTROL, S10479	2,3		PASS. CABIN P21 PANEL	23-34-03
UNIT - PASSENGER CONTROL	2,3		EACH PASSENGER SEAT	23-34-05
UNIT - (23-42-00/101) 1>	-,5	'	LACII I ASSENDEN SEAT	25 54 05
AUDIO ACCESSORY, M108				
ADDIO AGGEOGORI, MICO	1			1

^{*} SEE THE WDM EQUIPMENT LIST

1 GUI 009-099


Passenger Entertainment System (PES) - Component Index Figure 101

 23-34-00


14

Page 101 Sep 20/92





FLIGHT COMPARTMENT



Passenger Entertainment System - Component Location Figure 102 (Sheet 1)


ALL

23-34-00


16

Page 102 Sep 20/92






SEAT ARRANGEMENT (EXAMPLE)



FORWARD ATTENDANT'S PANEL, P21





PASSENGER CONTROL UNIT (PCU)



Passenger Entertainment System - Component Location Figure 102 (Sheet 2)

GUI 001-099


A71381

23-34-00


11

Page 103 Sep 20/92






FORWARD ENTRY DOOR AREA



SEAT ARRANGEMENT (EXAMPLE)



ENTERTAINMENT CONTROL SWITCH, \$10479

FORWARD ATTENDANT'S PANEL, P21



PASSENGER CONTROL UNIT (PCU)



Passenger Entertainment System - Component Location Figure 102 (Sheet 3)

GUI 115

(0)

23-34-00

10

Page 104 Sep 20/92

A71384



PREREQUISITES

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 11C22,37B8

MAKE SURE THE AIRPLANE IS IN THE CONFIGURATION THAT FOLLOWS:

ELECTRICAL POWER IS ON (MM 24-22-00/201)

PASSENGER ENTER-TAINMENT SYSTEM (PES) BITE PROCEDURE

YES 1 | TURN THE "PES" SWITCH TO 20 DOES ONE PCU SHOW A FAULT? 40 REPLACE THE PCU THE "TEST" POSITION ON THE 1>> (MM 23-34-05/401). FORWARD ATTENDANT PANEL P21. IF THE PROBLEM CONTINUES, NO REPLACE THE SEAT ELECTRONICS IS THE CENTER HORIZONTAL BAR OF THE RIGHT NUMBER ON, BOX (SEB)(MM 23-34-06/401). IF THE PROBLEM CONTINUES, AND ALL OTHER SEGMENTS OF THE DISPLAY OFF, AT EACH PASSENGER CONTROL UNIT (PCU)? REPAIR OR REPLACE THE SEB TO PCU CABLE. 2 YES 21 DOES MORE THAN ONE PCU AT TURN THE "PES" SWITCH TO 41 REPLACE THE SEAT THE "OFF" POSITION. A SEAT GROUP SHOW A FAULT? ELECTRONICS BOX (SEB) THE SYSTEM IS OK. 1>> (MM 23-34-06/401). IF THE PROBLEM CONTINUES, NO REPAIR OR REPLACE THE SEB TO PCU CABLE. 2 YFS 42 REPLACE THE MAIN 22 DO ALL PCU'S IN ONE OR MORE COLUMNS SHOW "E"? MULTIPLEXER M10733 (MM 23-34-01/401).NO SEE SHEET 2

(BLOCK 23)

1 A FAULT IS SHOWN BY A PCU WITH:

- 1. E SHOWN (AUDIO FAULT).
- 2. DISPLAY OFF (POWER FAULT).
- ANYTHING OTHER THAN E OR CENTER HORIZONTAL BAR (PCU MICRO-PROCESSOR FAULT).
- TURN THE PES SWITCH OFF WHEN
 THE SEAT ELECTRONICS BOX CABLES
 ARE DISCONNECTED OR CONNECTED.

 $\underline{\mathtt{NOTE}} \colon \mathsf{BITE} \ \mathsf{DOES} \ \mathsf{A} \ \mathsf{TEST} \ \mathsf{OF} \ \mathsf{THESE} \ \mathsf{SYSTEM} \ \mathsf{COMPONENTS} \colon$

PES TEST PANEL
MAIN MULTIPLEXER
ZONE MULTIPLEXER
SEAT ELECTRONICS BOX
PASSENGER CONTROL UNIT
SEAT TO SEAT CABLES

BITE DOES A TEST OF THESE SYSTEM COMPONENTS:

AMPLIFIER

ENTERTAINMENT TAPE REPRODUCER


Passenger Entertainment System (PES) BITE Procedure Figure 103 (Sheet 1)

23-34-00

09

Page 105 Sep 20/92






Passenger Entertainment System (PES) BITE Procedure Figure 103 (Sheet 2)

ALL

O9
Page 106
Sep 20/92

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.



835850

23-34-00

02

Page 107 Sep 20/92



SERVICE INTERPHONE SYSTEM

COMPONENT	FIG. 102 SHT	OTV	ACCECC/ADEA	DEFEDENCE
COMPONENT	эпі	QTY	ACCESS/AREA	REFERENCE
CIRCUIT BREAKER			FLT COMPT, P11	
INTERPHONE CABIN SERVICE, C551		1	11023	*
JACK - SERVICE INTPH, DOO413		1	315AL,316AR, APU SHROUD	*
JACK - SERVICE INTPH, DOO415		1	822, AFT CARGO DOOR, AFT EQUIP- MENT CENTER	*
JACK - SERVICE INTPH, DOO417		1	R WING FUELING PANEL, P28	*
JACK - SERVICE INTPH, DOO423		1	119BL, MAIN EQUIP CTR	*
JACK - SERVICE INTPH, DOO425		1	NOSE LANDING GEAR, P62	*
JACK - SERVICE INTPH, DOO427		1	R MAIN WHEEL WELL	*
JACK - SERVICE INTPH, D00429		1	FUSELAGE, HORIZONTAL STAB ACCESS PANEL	*
JACK - SERVICE INTPH, D00843		1	821, FWD CARGO DOOR, E5, EQUIP RACK	*
PANEL - (REF 31-31-00, FIG. 101) FLIGHT RECORDER CONTROL, M33				
SWITCH - SERVICE INTPH, (S2)		1	FLT COMPT, P61, FLT RCDR CONT PNL, M33	*
UNIT - (REF 23-42-00, FIG. 101) AUDIO ACCESSORY, M108				

^{*} SEE THE WDM EQUIPMENT LIST

Service Interphone System - Component Index Figure 101


23-41-00

05


Page 101 Sep 20/90




FAULT ISOLATION/MAINT MANUAL



FLIGHT COMPARTMENT



FLIGHT RECORDER CONTROL PANEL, M33 (REF)



SERVICE INTERPHONE JACK LOCATIONS

Service Interphone System - Component Location Figure 102

ALL

23-41-00

05

Page 102 Sep 20/90



CABIN INTERPHONE SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
AMPLIFIER - (FIM 23-31-00/101) PASSENGER ADDRESS, M177 CIRCUIT BREAKER - INTERPHONE CABIN SERVICE, C551 HANDSET - ATTENDANT, B61 LIGHT - (FIM 33-25-00/101) FWD ATTEND CALL, L324 MODULE - (FIM 31-51-00/101) BELL CHIME AURAL WARNING, M1000 MODULE - (FIM 33-25-00/101) EMER EXIT LOCATOR, M10253 THRU M10255 EMER EXIT LOCATOR, M10253, M10680, M10255	2 2	1 4	FLT COMPT, P11 11C23 PASSENGER CABIN	* *
PANEL - PILOTS' CALL, M51 UNIT - AUDIO ACCESSORY, M108 * SEE THE WDM EQUIPMENT LIST	1	1 1	FLT COMPT, P5 119BL, MAIN EQUIP CTR, E4-3	23-42-02 23-42-01

1 ALL EXCEPT GUI 115

Cabin Interphone System - Component Index Figure 101


EFFECTIVITY-


23-42-00

ALL

12 Page 101 Mar 20/94







MAIN EQUIPMENT CENTER



Cabin Interphone System - Component Location Figure 102 (Sheet 1)


EFFECTIVITY-ALL

23-42-00


01

Page 102 Mar 20/94






FLIGHT COMPARTMENT



PILOTS' CALL PANEL, M51





PILOTS' CALL PANEL, M51




>> ALL EXCEPT GUI 115 2>> GUI 115

> Cabin Interphone System - Component Location Figure 102 (Sheet 2)

EFFECTIVITY-ALL

23-42-00







HANDSET, B61 (EXAMPLE)



ALL EXCEPT GUI 115 - GUI 115

> Cabin Interphone System - Component Location Figure 102 (Sheet 3)

EFFECTIVITY-ALL

23-42-00

15

Page 104 Mar 20/94




CABIN CHIME AND CALL LIGHT/ATTENDANT CALL FROM PILOT OR

PREREQUISITES

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 11C22, 11C23

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



Cabin Chime and Call Light/Attendant Call from Pilot or Attendant Problem Figure 103

23-42-00



PREREQUISITES

MAKE SURE THESE SYSTEMS WILL OPERATE: EICAS (AMM 31-41-00/201) WARNING ELECTRONICS (AMM 31-51-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 11B16, 11B18, 11C23, 11H35, 11J2, 11J3, 11J29, 11J30, 11J31, 11J32, 11J33

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)


PILOT CALL CHIME AND CALL LIGHT **PROBLEM**

1 MAKE A "PILOT" OR "ALERT" 11 MAKE A "PILOT" OR "ALERT" 21 REPLACE THE PILOTS CALL PANEL, M51. CALL FROM ANY ATTENDANT CALL FROM A DIFFERENT IF THE PROBLEM CONTINUES, STATION. ATTENDANT STATION. DOES THE CORRECT CABIN DOES THE CORRECT CABIN TROUBLESHOOT THE WIRING FROM CALL LIGHT (FWD, MID, AFT, CALL LIGHT (FWD, MID, AFT, THE AUDIO ACCESSORY UNIT, ALERT) ON THE PILOTS CALL ALERT) ON THE PILOTS CALL M108, TO THE PILOTS CALL PANEL, M51 (WDM 23-42-11). PANEL, M51, COME ON? PANEL, M51, COME ON? YES YFS 22 REPLACE THE AUDIO ACCESSORY UNIT, M108 SEE SHEET 2 (BLOCK 2) (AMM 23-42-01/401). IF THE PROBLEM CONTINUES, TROUBLESHOOT THE WIRING FROM THE AUDIO ACCESSORY UNIT, M108, TO THE PILOTS CALL PANEL, M51 (WDM 23-42-11).

> Pilot Call Chime and Light Problem Figure 104 (Sheet 1)

EFFECTIVITY-ALL

23-42-00





GROUND CREW CALL SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
CIRCUIT BREAKER - GND CALL, C560 HORN - GROUND CREW CALL, B60 MODULE - (FIM 31-51-00/101) BELL CHIME AURAL WARNING, M1000 PANEL - (FIM 23-42-00/101) PILOTS' CALL, M51 RELAY - (FIM 21-58-00/101) HORN, K10080		1 1	FLT COMPT, P11 11H31 714, NOSE WHEEL WELL	* 23-43-01
SWITCH - FLIGHT DECK CALL, S426		1	NOSE LANDING GEAR, NOSE GEAR INTPH PANEL, P62	*


^{*} SEE THE WDM EQUIPMENT LIST

Ground Crew Call System - Component Index Figure 101

EFFECTIVITY ALL

23-43-00





Ground Crew Call System - Component Location Figure 102

EFFECTIVITY-ALL

55739

23-43-00

В


GROUND CREW CALL
HORN FAILS TO SOUND.
"EQPT CLG FLOW" OR
"EQPT CLG SENSOR"
EICAS STATUS
MESSAGE(S)
DISPLAYED. 1

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (MM 31-41-00/501)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6D6,11H31; 2 11N13; 3 11N17

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (MM 24-22-00/201)



IF AN EQUIPMENT COOLING FAILURE IS REPAIRED BEFORE THIS PROCEDURE, AN EQUIPMENT COOLING FAILURE WILL HAVE TO BE MADE (MM 21-58-00/501) TO PERMIT THE GROUND CREW CALL HORN TO OPERATE.

2 ALL EXCEPT GUI XA-MMX

|3≫ GUI XA-MMX

Ground Crew Call Horn Fails to Sound. EQPT CLG FLOW or EQPT CLG SENSOR EICAS
Status Message(s) Displayed.

Figure 103

23-43-00

09

Page 103 Mar 20/97

GROUND CREW CALL PREREQUISITES HORN FAILS TO SOUND. MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: IRS MODE SELECT 6D6,11H31 SWITCH (L, C, OR R) MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: L AND R DC POWER ON. ELECTRICAL POWER IS ON (MM 24-22-00/201) OFF 1 OPEN THE "EQUIP COOLING LOW FLOW DET" CIRCUIT BREAKER, 11N13 1 2; 11N17 1 21 REPLACE THE GROUND CREW CALL HORN, B60 (MM 23-43-01/ 401). IF THE PROBLEM CONTINUES, PUSH THE GND CALL SWITCH REPLACE THE PILOTS' CALL ON THE PILOTS' CALL PANEL, PANEL, M51 (MM 23-42-02/401). M51, ON THE P5 PANEL. CLOSE THE CIRCUIT BREAKER, IS THERE A HORN SOUND? 11N13 | 2 > ; 11N17 | 3 > .YES 2 REMOVE THE HORN RELAY, 11 DO A CHECK FOR A GROUND AT 22 REPLACE THE HORN RELAY, K10080, IN THE P36 PANEL (WDM 21-58-11). K10080, IN THE P36 PANEL PIN 3 OF THE RELAY RECEPTACLE, (WDM 21-58-11). D1572. IS PIN 3 AT GROUND? IF THE PROBLEM CONTINUES. DO A CHECK FOR 28V DC AT PIN 7 OF THE RELAY RECEPTACLE, REPLACE THE PILOTS' CALL NO PANEL, M51 (MM 23-42-02/401). D1572. IS THERE 28V DC? CLOSE THE CIRCUIT BREAKER, 11N13 2>; 11N17 3>. NO 23 REPLACE THE POWER XFR RELAY, K10079, IN THE P36 PANEL (WDM 21-58-11). INSTALL THE HORN RELAY, K10080, IN THE P36 PANEL (WDM 21-58-11). CLOSE THE CIRCUIT BREAKER, 11N13 2>; 11N17 3>. YES 3 INSTALL THE HORN RELAY, 24 REPLACE THE AIR/GND RELAY, K10080, IN THE P36 PANEL K124 (MM 32-09-02/201). (WDM 21-58-11). CLOSE THE CIRCUIT BREAKER, REMOVE THE AIR/GND RELAY, 11N13 2>; 11N17 3>. K124 (MM 32-09-02/201). DO A CHECK FOR 28V DC AT PIN 7 OF THE RELAY RECEP-TACLE, D582. IS THERE 28V DC? NO 25 | INSTALL THE AIR/GND RELAY, K124 (MM 32-09-02/201). REPLACE THE POWER XFR 1> THE EQUIPMENT COOLING LOW FLOW DETECTION SYSTEM WILL NOT RELAY, K10079, IN THE P36 PANEL (WDM 21-58-11). OPERATE WHILE THE CIRCUIT BREAKER, 11N13 2>; 11N17 3>, IS OPEN. THE EQUIPMENT COOLING SYSTEM SHOULD BE MONITORED CLOSE THE CIRCUIT BREAKER, FOR CORRECT OPERATION WHILE THE CIRCUIT BREAKER IS OPEN. 11N13 | 2>> ; 11N17 | 3>> . 2 ALL EXCEPT GUI XA-MMX 3 GUI XA-MMX

Ground Crew Call Horn Fails to Sound. IRS Mode Select Switch (L, C, or R) On.
L and R DC Power Off
Figure 104

ALL

O9

Page 104

Mar 20/97



FLIGHT INTERPHONE SYSTEM - TROUBLE SHOOTING

 23-51-00

01

Page 101 Dec 20/91



FLIGHT INTERPHONE SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
AMPLIFIER - (REF 23-31-00, FIG. 101) PASSENGER ADDRESS, M177 CIRCUIT BREAKERS - INTERPHONE - CAPT FLT AMPL, C552,C554 INTERPHONE - F/O OBS FLT AMP, C553,C557 DIODE - R58 R59 R60 R61 INTERROGATOR - (REF 34-55-00, FIG. 101) LEFT DME, M123 RIGHT DME, M124 JACK - CAPT BOOM MIC, D543 CAPT HAND MIC, D539 CAPT HEADSET, D541 F/O BOOM MIC, D533 F/O HAND MIC, D529 F/O HEADSET, D531 OBS BOOM MIC, D525 OBS HAND MIC, D521 OBS HAND MIC, D521 OBS HADSET, D521	1 1	2 2 1 1 1 1 1 1 1 1 1 1 1	FLT COMPT, P11 11c25,11G29 11c26,11G30 FLT COMPT,TB113, BEHIND P5 A10 A7 A9 A8 FLT COMPT P13 P13 P13 P14 P14 P14 P17 P17	* * * * * * * * * * * * * * * * * * *
SEC OBS HEADSET, D551 JACK - FLT INTPH, D435	2	1 1	P61 NOSE LANDING GEAR, NOSE GEAR	*
PANEL - CAPT AUDIO SELECTOR, M70 PANEL - F/O AUDIO SELECTOR, M71 PANEL - OBS AUDIO SELECTOR, M98 PANEL - (REF 34-51-00, FIG. 101) LEFT DME/VOR, M91 RIGHT DME/VOR, M92 RECEIVER - (REF 34-31-00, FIG. 101) CENTER ILS, M157 LEFT ILS, M156 RIGHT ILS, M158 RECEIVER - (REF 34-51-00, FIG. 101) LEFT VOR, M186 RIGHT VOR, M187 RECEIVER - (REF 34-57-00, FIG. 101) LEFT ADF, M215 RIGHT ADF, M216	1 1 1	1 1 1	INTPH PNL, P62 FLT COMPT, P8 FLT COMPT, P8 FLT COMPT, P17	23-51-01 23-51-01 23-51-01

^{*} SEE THE WDM EQUIPMENT LIST

196615

Flight Interphone System - Component Index Figure 101 (Sheet 1)

EFFECTIVITY-ALL 23-51-00



COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
RESISTOR - R10233 R10234 SPEAKER - CAPT COCKPIT, B1 SPEAKER - F/O COCKPIT, B2 SWITCH - CAPT PTT INTPH CONT, S549 SWITCH - CAPT RT/PTT MIC CONT, S550 UNIT - (REF 23-42-00, FIG. 101) AUDIO ACCESSORY, M108 XCVR - (REF 23-11-00, FIG. 101) LEFT HF, M152 RIGHT HF, M153 XCVR - (REF 23-12-00, FIG. 101) CENTER VHF, M190 LEFT VHF, M188 RIGHT VHF, M188	2 1 1 1 1 1 1	1 1 1 1 1 1	MAIN EQUIP CTR, E4-3, TB141 FLT COMPT FLT COMPT FLT COMPT, CAPT CONTROL WHEEL FLT COMPT, CAPT CONTROL WHEEL	* 23-51-02 23-51-02 23-51-03 23-51-03

^{*} SEE THE WDM EQUIPMENT LIST


Flight Interphone System - Component Index Figure 101 (Sheet 2)

23-51-00


20

Page 103 Dec 20/91





FLIGHT COMPARTMENT



AUDIO SELECTOR PANEL, M70,M71,M98

Flight Interphone System - Component Location Figure 102 (Sheet 1)


ALL

23-51-00

14


Page 104 Sep 20/93





CAPTAIN'S AND FIRST OFFICER'S JACK PANEL (EXAMPLE)





FIRST OBSERVER'S JACK PANEL (EXAMPLE)





SECOND OBSERVER'S HEADSET JACK, D551 (EXAMPLE)

(D)


Flight Interphone System - Component Location (Details from Sht 1)
Figure 102 (Sheet 2)


23-51-00


04

Page 105 Sep 20/93









Page 106

Flight Interphone System - Component Location Figure 102 (Sheet 3)

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

EFFECTIVITY-23-51-00 ALL 01 Sep 20/93

FLIGHT INTERPHONE



STATIC DISCHARGERS

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
ADAPTER - ALUMINUM STATIC DISCHARGER BASE,	1	2	ELEVATORS	23-61-00
ASSY	2	1	RUDDER	23-61-00
ADAPTER - TITANIUM STATIC DISCHARGER BASE,	1	4	ELEVATORS	23-61-00
ASSY	2	2	RUDDER	23-61-00
BASE - ALUMINUM STATIC DISCHARGER,	1	4	ELEVATORS	23-61-01
TRAILING EDGE TYPE	2	3	RUDDER	23-61-01
	2	2	WINGTIPS	23-61-01
BASE - FLAT SURFACE STATIC DISCHARGER, TIP TYPE	1	2	HORIZ STABILIZER TIPS	23-61-01
BASE - LARGE RADIUS SURFACE STATIC	2	1	VERTICAL STABILIZER TIP	23-61-01
DISCHARGER, TIP TYPE	2	4	WINGTIPS	23-61-01
BASE - SMALL RADIUS SURFACE STATIC	2	1	VERTICAL STABILIZER TIP	23-61-01
DISCHARGER, TIP TYPE	1	2	HORIZ STABILIZER TIPS	23-61-01
BASE - TITANIUM STATIC DISCHARGER,	2	10	OUTBD AILERONS	23-61-01
TRAILING EDGE TYPE	1	4	ELEVATORS	23-61-01
	2	2	RUDDER	23-61-01
DISCHARGER - TIP TYPE STATIC	1	4	HORIZ STABILIZER TIPS	23-61-01
	2	1	RUDDER	23-61-01
	2	1	VERTICAL STABILIZER TIP	23-61-01
	2	4	WINGTIPS	23-61-01
DISCHARGER - TRAILING EDGE TYPE STATIC	2	10	OUTBD AILERONS	23-61-01
	1	8	ELEVATORS	23-61-01
	2	5	RUDDER	23-61-01
	2	2	WINGTIPS	23-61-01

Static Dischargers - Component Index Figure 101

EFFECTIVITY-


94626


23-61-00

01

Page 101 Sep 20/93







HORIZONTAL STABILIZER AND ELEVATOR STATIC DISCHARGERS (EXAMPLE)




Static Dischargers - Component Location Figure 102 (Sheet 1)

ALL

O1 Page 102
Sep 20/90


BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.





WING TIP AND AILERON STATIC DISCHARGERS (EXAMPLE)





VERTICAL FIN TIP AND RUDDER STATIC DISCHARGERS



Static Dischargers - Component Location (Details from Sht 1) Figure 102 (Sheet 2)

EFFECTIVITY-ALL


98727


23-61-00

01

Page 103 Sep 20/93







TIP TYPE STATIC DISCHARGER BASE (ALUMINUM - FLAT OR CURVED SURFACE)




Static Dischargers - Component Location Figure 102 (Sheet 3)

23-61-00


01

Page 104 Sep 20/90






TRAILING EDGE TYPE STATIC DISCHARGER



TRAILING EDGE TYPE STATIC DISCHARGER BASE (TITANIUM)



STATIC DISCHARGER BASE ADAPTER ASSEMBLY
(ALUMINUM OR TITANIUM)

Static Dischargers - Component Location Figure 102 (Sheet 4)

ALL

23-61-00

01

Page 105 Sep 20/90



VOICE RECORDER SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
BEACON - UNDERWATER LOCATOR CIRCUIT BREAKER		1	AFT PASSENGER CABIN CEILING FLT COMPT, P11	23-71-03
VOICE RECORDER, C532 PANEL - (REF 23-51-00, FIG. 101) CAPT AUDIO SELECTOR, M70 F/O AUDIO SELECTOR, M71 1ST OBS AUDIO SELECTOR, M98		1	11H33	*
PANEL - VOICE RECORDER CÓNTROL, M50 RECORDER - VOICE, M201 RELAY - (REF 31-01-36, FIG. 101) AIR/GND, K135 PARKING BRAKE, K419		1 1	FLT COMPT, P5 AFT PASS CABIN CEILING	23-71-02 23-71-01

^{*} SEE THE WDM EQUIPMENT LIST


Voice Recorder System - Component Index Figure 101

832817

23-71-00



FAULT ISOLATION/MAINT MANUAL



Voice Recorder System - Component Location Figure 102




PREREQUISITES

MAKE SURE THIS CIRCUIT BREAKER IS CLOSED: 11H33

MAKE SURE THE AIRPLANE IS IN THE CONFIGURATION THAT FOLLOWS:

ELECTRICAL POWER IS ON (MM 24-22-00/201)

VOICE RECORDER BITE PROCEDURE



NOTE: BITE DOES A TEST OF THESE SYSTEM COMPONENTS:

VOICE RECORDER

VOICE RECORDER CONTROL PANEL

BITE DOES NOT DO A TEST OF THESE SYSTEM COMPONENTS:

AUDIO SELECTOR PANEL

UNDERWATER LOCATOR BEACON

Voice Recorder BITE Procedure Figure 103

EFFECTIVITY
GUI 009,115

23-71-00

CONFIG 1

02 Page 103

Mar 20/93



PREREQUISITES


MAKE SURE THESE SYSTEMS WILL OPERATE: FLIGHT INTERPHONE (MM 23-51-00/501) NORMAL PARKING (MM 10-11-01/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6F4,11C25,11C26,11C30,11G29,11G30,11H33,11S15

MAKE SURE THE AIRPLANE IS IN THE CONFIGURATION THAT FOLLOWS:

ELECTRICAL POWER IS ON (MM 24-22-00/201)

VOICE RECORDER SYSTEM FAULT ISOLATION



Voice Recorder System Fault Isolation Figure 104 (Sheet 1)

GUI 009,115


23-71-00

CONFIG 1

Page 104


Mar 20/93

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.



Voice Recorder System Fault Isolation Figure 104 (Sheet 2)





Voice Recorder System Fault Isolation Figure 104 (Sheet 3)

EFFECTIVITY
GUI 009,115

23-71-00

CONFIG 1

Page 106

Mar 20/93

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

FROM SHEET 3
(BLOCK 8)

YES

9 CLOSE THE "PARKING BRAKE VLV" CIRCUIT BREAKER, 6F4.

WARNING

DO THE DEACTIVATION PROCEDURE FOR THE SPOILERS OR MOVE ALL PERSONS AND EQUIPMENT AWAY FROM THE SPOILERS. THE SPOILERS CAN RETRACT QUICKLY AND CAUSE INJURY TO PERSONS OR DAMAGE TO EQUIPMENT.

DO THE DEACTIVATION PROCEDURE FOR THE SPOILERS (MM 27-61-00/201) OR MOVE ALL PERSONS AND EQUIPMENT AWAY FROM THE SPOILERS.

WARNING

MAKE SURE YOU DO THE FLIGHT MODE SIMULATION CORRECTLY. IF THE PROCEDURE IS NOT DONE CORRECTLY, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

DO THE FLIGHT MODE SIMULATION PROCEDURE FOR THE NO. 1 (NO. 2) AIR/GROUND SYSTEM (MM 32-09-02/201). OPEN THE "LDG GEAR POS SYS 1" CIRCUIT BREAKER, 11C3O. PUSH THE "ERASE" SWITCH ON THE VOICE RECORDER CONTROL PANEL FOR 2 SECONDS.

DO YOU HEAR THE 400-Hz TONE SOUND IN THE HEADPHONE?

NO

10 CLOSE THE "LDG GEAR POS SYS 1" CIRCUIT BREAKER, 11C30. PUT THE AIRPLANE BACK TO GROUND MODE (MM 32-09-02/ 201).

DO THE ACTIVATION PROCEDURE FOR THE SPOILERS IF YOU DID THE DEACTIVATION PROCEDURE (MM 27-61-00/201). DISCONNECT THE HEADPHONE FROM THE VOICE RECORDER CONTROL PANEL. THE SYSTEM IS OK.

35 REPLACE THE AIR/GROUND RELAY, K135 (MM 32-09-02/401). PUT THE AIRPLANE BACK TO THE GROUND MODE (MM 32-09-02/401).

Voice Recorder System Fault Isolation Figure 104 (Sheet 4)

GUI 009,115

23-71-00



VOICE RECORDER SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
BEACON - UNDERWATER LOCATOR CIRCUIT BREAKER		1	AFT PASSENGER CABIN CEILING FLT COMPT, P11	23-71-03
VOICE RECORDER, C532 PANEL - (REF 23-51-00, FIG. 101) CAPT AUDIO SELECTOR, M70 F/O AUDIO SELECTOR, M71 1ST OBS AUDIO SELECTOR, M98		1	11H33	*
PANEL - VOICE RECORDER CÓNTROL, M50 RECORDER - VOICE, M201 RELAY - (REF 31-01-36, FIG. 101) AIR/GND, K135 PARKING BRAKE, K419		1 1	FLT COMPT, P5 AFT PASS CABIN CEILING	23-71-02 23-71-01


^{*} SEE THE WDM EQUIPMENT LIST


Voice Recorder System - Component Index Figure 101

832796

23-71-00








FLIGHT COMPARTMENT

VOICE RECORDER CONTROL PANEL, M50



02

Voice Recorder System - Component Location Figure 102

23-71-00 CONFIG 2 Page 102 Mar 20/93




PREREQUISITES

MAKE SURE THIS CIRCUIT BREAKER IS CLOSED: 11H33

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (MM 24-22-00/201)

VOICE RECORDER BITE PROCEDURE



NOTE: BITE DOES A TEST OF THESE SYSTEM COMPONENTS:

- VOICE RECORDER
- VOICE RECORDER CONTROL PANEL.

BITE DOES NOT DO A TEST OF THESE SYSTEM COMPONENTS:

- AUDIO SELECTOR PANEL
- UNDERWATER LOCATOR BEACON.

Voice Recorder BITE Procedure Figure 103

23-71-00




PREREQUISITES

MAKE SURE THESE SYSTEMS WILL OPERATE: FLIGHT INTERPHONE (MM 23-51-00/501) NORMAL PARKING (MM 10-11-01/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6F4,11C25,11C26,11C30,11G29,11G30,11H33,11S15,

MAKE SURE THE AIRPLANE IS IN THIS CONFIFURATION: ELECTRICAL POWER IS ON (MM 24-22-00/201) PARKING BRAKE IS ENGAGED




Voice Recorder System Fault Isolation Figure 104 (Sheet 1)

EFFECTIVITY-GUI 001-008,010-013


VOICE RECORDER


SYSTEM FAULT

23-71-00 CONFIG



Voice Recorder System Fault Isolation Figure 104 (Sheet 2)





Voice Recorder System Fault Isolation Figure 104 (Sheet 3)


EFFECTIVITY—GUI 001-008,010-013

23-71-00

CONFIG 2

Page 106

Mar 20/93



Voice Recorder System Fault Isolation Figure 104 (Sheet 4)

EFFECTIVITY—GUI 001-008,010-013

23-71-00

CONFIG 2

Page 107

Mar 20/93

FROM SHEET 4 (BLOCK 8)

NO

YES

9 CLOSE THE "PARKING BRAKE VLV" CIRCUIT BREAKER, 6F4.

WARNING

DO THE DEACTIVATION PROCEDURE FOR THE SPOILERS OR MOVE ALL PERSONS AND EQUIPMENT AWAY FROM THE SPOILERS. THE SPOILERS CAN RETRACT QUICKLY AND CAUSE INJURY TO PERSONS OR DAMAGE TO EQUIPMENT.

DO THE DEACTIVATION PROCEDURE FOR THE SPOILERS (MM 27-61-00/201) OR MOVE ALL PERSONS AND EQUIPMENT AWAY FROM THE SPOILERS.

WARNING

MAKE SURE YOU DO THE FLIGHT MODE SIMULATION CORRECTLY. IF THE PROCEDURE IS NOT DONE CORRECTLY, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

DO THE FLIGHT MODE SIMULATION PROCEDURE FOR THE NO. 1 (NO. 2) AIR/GROUND SYSTEM (MM 32-09-02/201). OPEN THE "LDG GEAR POS SYS 1" CIRCUIT BREAKER, 11C3O. PUSH THE "ERASE" SWITCH ON THE VOICE RECORDER CONTROL PANEL FOR 2 SECONDS.

DO YOU HEAR THE 400-Hz TONE SOUND IN THE HEADPHONE?

NO

10 CLOSE THE "LDG GEAR POS SYS 1" CIRCUIT BREAKER, 11C30. PUT THE AIRPLANE BACK TO GROUND MODE (MM 32-09-02/ 201).

DO THE ACTIVATION PROCEDURE FOR THE SPOILERS IF YOU DID THE DEACTIVATION PROCEDURE (MM 27-61-00/201). DISCONNECT THE HEADPHONE FROM THE VOICE RECORDER CONTROL PANEL. THE SYSTEM IS OK.

37 REPLACE THE AIR/GROUND RELAY, K135 (MM 32-09-02/401).
PUT THE AIRPLANE BACK TO THE GROUND MODE (MM 32-09-02/401).

Voice Recorder System Fault Isolation Figure 104 (Sheet 5)

GUI 001-008,010-013

23-71-00

CONFIG

02

Page 108 Mar 20/93