

GPA Group plc

PAGE	DATE	CODE	PAGE	DATE	CODE	PAGE	DATE	CODE
CHARTER (C. T	·AD		49-11-00	CONFIG 1		49-11-00	CONFIG 1	CONT.
CHAPTER 49 T	AB		101	SEP 20/94 SEP 20/94	01	159	SEP 28/03	09 10
A TODODNE ALIV	ILIARY POWER		102 103	MAR 20/96	01 05	160 161	JAN 28/02 JAN 28/02	09
AIRDORNE AUX	ILIAKI PUWEK		103	SEP 20/94	01	162	JAN 28/02	07
EFFECTIVE PA	GES		105	SEP 28/02	01	163	JAN 28/02	07
SEE LAST PAG	E OF LIST FOR		106	SEP 20/94	04	164	JAN 28/02	08
NUMBER OF PA	GES		107	SEP 20/98	01	165	SEP 28/03	10
1			108	MAY 28/00	01	166	SEP 28/03	09
			109	SEP 28/01	01	167	SEP 28/03	07
49-CONTENTS	ED 28/00	04	110	MAR 20/96 MAR 20/96	01	168	SEP 28/03	07
	EP 28/99 AN 28/02	O1 GUI	111 112	MAR 20/96	01 01	169 170	SEP 28/03 SEP 28/03	07 07
	IAY 28/07	GUI	113	MAY 28/00	01	171	SEP 28/03	08
	AN 28/05	GUI	114	MAY 28/00	05	172	SEP 28/03	07
1 5 J	AN 28/05	GUI	115	MAY 28/00	02	173	SEP 28/03	08
[6 J	AN 28/00	GUI	116	MAY 28/00	02	174	SEP 28/03	10
] 7 J	AN 28/00	GUI	117	MAY 28/00	01	175	SEP 28/03	08
8	BLANK		118	MAY 28/00	01	176	SEP 28/03	09
	- THE		119	MAY 28/00	01	177	SEP 28/03	08
49-HOW TO US		04	120	MAY 28/00	01	178	SEP 28/03	07
	EP 20/98 EP 20/98	01 01	121 122	MAY 28/00 MAY 28/03	01 01	179 180	SEP 28/03 SEP 28/03	08 09
7 3	EP 28/99	01	123	MAY 28/00	01	180	3EF 20/03	09
	EP 20/98	01	124	MAY 28/00		49-11-00	CONFIG 2	
	EP 20/98	01	125	SEP 28/01	01	101	SEP 20/94	01
6 S	EP 20/98	01	126	MAY 28/00	01	102	SEP 20/94	01
			127	MAY 28/00	01	103	MAY 28/00	06
49-INDEX			128	MAY 28/03	01	104	MAY 28/04	01
	EC 20/90	02	129	MAY 28/00	01	105	SEP 28/02	04
2 D	EC 20/90	04	130	MAY 28/00	01	106	SEP 20/98	01
49-EICAS MES	CACEC		131 132	MAY 28/00 MAY 28/00	01 01	107 108	MAY 28/00 MAY 28/04	01 01
	EC 20/90	01	132	MAY 28/00	05	108	SEP 28/01	01
2 0	EC 20/90	01	134	MAY 28/00	01	110	MAR 20/96	01
3 3	AN 28/05	02	135	JAN 28/05	01	111	DEC 20/94	01
4	BLANK		136	MAY 28/00	01	112	DEC 20/94	01
			137	MAY 28/00	04	113	MAY 28/00	01
49-FAULT COD			138	MAY 28/00	05	114	MAY 28/00	01
] 1 J	AN 28/01	02	139	MAY 28/00	08	115	MAY 28/00	01
2 M	IAY 28/02 IAN 28/01	03	140 141	MAY 28/00	05 06	116	MAY 28/00 MAY 28/00	02
	EP 15/84	01 02	141	MAY 28/00 MAY 28/00	06 09	117 118	MAY 28/00	01 01
5 J	AN 28/01	02	143	MAY 28/00	07	119	MAY 28/00	01
	AN 28/01	01	144	MAY 28/00	07	120	JAN 28/06	01
1		- -	145	MAY 28/00	08	121	MAY 28/03	01
49-FAULT COD	E INDEX		146	MAY 28/00	07	122	MAY 28/07	01
	EP 20/08	01	147	MAY 28/00	07	123	SEP 28/01	01
	EP 20/08	02	148	MAY 28/00	08	124	MAY 28/00	05
1 , .	EP 20/08	80	149	JAN 28/02	08	125	MAY 28/00	01
4 S	EP 20/08	09	150 151	JAN 28/U2 JAN 28/02	07 06	126 127	MAY 28/00 MAY 28/00	01 01
49-BITE INDE	X		152	JAN 28/02 JAN 28/05	09	128	MAY 28/00	01
	EP 28/99	01	153	JAN 28/02	07	129	MAY 28/07	05
	EP 28/99	01	154	JAN 28/02	06	130	MAY 28/07	01
] 3 s	EP 28/99	01	155	JAN 28/02	07	131	MAY 28/07	01
4	BLANK		156	JAN 28/02	07	132	MAY 28/00	01
			157	JAN 28/02	09	133	MAY 28/00	03
			158	JAN 28/05	80	134	MAY 28/00	08

R = REVISED, A = ADDED OR D = DELETED 632 JAN 20/09 D633N632

CHAPTER 49 **EFFECTIVE PAGES** PAGE CONTINUED



GPA Group plc

PAGE	DATE	CODE	PAGE	DATE	CODE	PAGE	DATE	CODE
49-11-00 135	CONFIG 2 MAY 28/00	CONT. 04	49-11-00 180M	CONFIG 2 JAN 28/05	CONT. 07	49-71-00 101	SEP 20/94	01
136	MAY 28/00	04	180N	JAN 28/05	11	102	SEP 20/94	01
137	MAY 28/00	07	1800	JAN 28/05	10		02. 20///	.
138	MAY 28/00	05	180P	JAN 28/05	11	49-72-00		
139	JAN 28/05	04	180Q	JAN 28/05	12	101	DEC 20/93	01
140	JAN 28/05	05	180R	JAN 28/05	09	102	DEC 20/95	01
141	JAN 28/05	05 05	180s	JAN 28/05	12	/0.84.00		
142 143	MAY 28/05 SEP 28/06	05 05	180T	BLANK		49-81-00 101	SEP 20/94	01
144	JAN 28/05	05	49-13-00			102	SEP 20/94	01
145	JAN 28/05	05	101	SEP 20/94	01	102	3L1 20774	01
146	JAN 28/05	05	102	SEP 20/94	01	49-94-00		
147	JAN 28/05	06	1			101	DEC 20/95	07
148	JAN 28/05	05	49-15-00			102	DEC 20/93	07
149	JAN 28/05	08	101	DEC 20/91	01			
150	JAN 28/05	05 05	102	DEC 20/91	01			
151 152	JAN 28/05 JAN 28/05	05 06	49-16-00					
153	JAN 28/05	08	101	DEC 20/91	06			
154	JAN 28/05	04	102	DEC 20/91	01			
155	JAN 28/05	09	103	SEP 20/95	04	1		
156	JAN 28/05	06	104	BLANK				
157	JAN 28/05	07	İ			İ		
158	JAN 28/05	08	49-27-00			I		
159	JAN 28/05	06	101	SEP 20/92	10			
160	JAN 28/05	05 05	102	DEC 20/91	01			
161 162	JAN 28/05 JAN 28/05	05 07	103 104	DEC 20/91 DEC 20/91	01 03			
163	JAN 28/05	06	104	SEP 20/92	09			
164	JAN 28/05	09	106	BLANK	07	•		
165	JAN 28/05	06						
166	JAN 28/05	07	49-31-00			İ		
167	JAN 28/05	04	101	DEC 20/91	01	I		
168	JAN 28/05	06	102	DEC 20/91	01			
169	JAN 28/05	07 05	103	DEC 20/91	01			
170 171	JAN 28/05 JAN 28/05	05 05	104	BLANK				
172	JAN 28/05	08	49-41-00					
173	JAN 28/05	06	101	DEC 20/91	08			
174	JAN 28/05	07	102	DEC 20/91	01	1		
175	JAN 28/05	07	1			I		
176	JAN 28/05	06	49-51-00		0.4	I		
177	JAN 28/05	07	101	SEP 20/98	01	1		
178 179	JAN 28/05 JAN 28/05	06	102	SEP 20/98	01	1		
179	JAN 28/05 JAN 28/05	08 10	49-52-00			1		
180A	JAN 28/05	09	101	SEP 20/94	01			
180B	JAN 28/05	10	102	SEP 20/94	01	1		
180c	JAN 28/05	10	1		-			
180D	JAN 28/05	06	49-53-00					
180E	JAN 28/07	06	101	SEP 20/94	02			
180F	JAN 28/05	08	102	SEP 28/04	02			
180G	JAN 28/05	08	40_41_00					
180H 180I	JAN 28/05 JAN 28/05	06 07	49-61-00 101	DEC 20/91	03	1		
1801 180J	JAN 28/05	07 08	101	DEC 20/91 DEC 20/94	03 01	1		
180K	JAN 28/05	09	103	DEC 20/94	01	1		
180L	JAN 28/05	06	104	BLANK		1		

R = REVISED, A = ADDED OR D = DELETED 632 JAN 20/09 D633N632

CHAPTER 49 **EFFECTIVE PAGES** PAGE 2 LAST PAGE



TABLE OF CONTENTS

<u>Subject</u>	Chapter Section Subject	<u>Page</u>	<u>Effectivity</u>
HOW TO USE THE FIM	49-HOW TO USE THE FI	1 M	ALL
INDEX	49-INDEX	1	ALL
EICAS MESSAGES	49-EICAS MESSAGES	1	ALL
FAULT CODE DIAGRAMS	49-FAULT CODE DIAGR	1 AM	ALL
FAULT CODE INDEX	49-FAULT CODE INDEX	1	ALL
BITE INDEX	49-BITE INDEX	1	ALL



TABLE OF CONTENTS

<u>Subject</u>	Chapter Section <u>Subject</u>	<u>Page</u>	<u>Effectivity</u>
AIRBORNE AUXILIARY POWER	49-00-00		
POWER PLANT AUXILIARY POWER UNIT (APU) Component Location Component Index Component Location Fault Isolation	49–10–00 49–11–00	101	CONFIG 1 [*]
Auto Shutdown - FAILED SENSOR		151	
on BITE (Fig. 114) Auto Shutdown - GEN FILTER on		147	
BITE (Fig. 112) Auto Shutdown - HOT on BITE		143	
(Fig. 110) Auto Shutdown - LOP on BITE		138	
(Fig. 109) Auto Shutdown - NO ACCEL on BITE (Fig. 105)		120	
Auto Shutdown - NO FLAME on BITE (Fig. 107)		132	
Auto Shutdown - OVER SPEED on BITE (Fig. 111)		146	
Auto Shutdown - OVER TEMP on BITE (Fig. 113)		148	
Auto Shutdown - SLOW START on BITE (Fig. 106)		126	
Auto Shutdown During Governed Speed - REVERSE FLOW on BITE (Fig. 108)		136	
APU BITE Procedure (Fig. 103) APU Starting Problems (Fig. 104)		103 114	
APU Will Not Carry Pneumatic and Electrical Load Associated with RPM Drop (Fig. 117)		155	
EICAS Msg APU OIL QTY Displayed (Fig. 116)		153	
Faulty Unit - STARTER CIRCUIT on BITE (Fig. 106A)		130	
Fluctuating Duct Pressure (Fig. 119)		160	

49-CONTENTS

GUI

Page 2 Jan 28/02



TABLE OF CONTENTS

<u>Subject</u>	Chapter Section Subject	<u>Page</u>	<u>Effectivity</u>
Fluctuating Duct Pressure		161	
(Fig. 119) Fluids Coming from Drain Mast		179	
(Fig. 121) Fumes and/or Smoke in the		180	
Cabin (Fig. 122) High Oil Consumption (Fig. 115)		152	
Low Duct Pressure (Fig. 120) Low Duct Pressure in All Operational Modes: ECS, MES and Duct Pressurization (Fig. 120C)		165 170	
Low Duct Pressure in Duct Pressurization Mode (3–25 PSIG) (Fig. 120B)		168	
Low Duct Pressure in MES Mode Only (Fig. 120E)		177	
Low Duct Pressure During One or Two ECS Pack Operation Only (Fig. 120D)		175	
No Duct Pressure in Any Mode (0-2 PSIG) (Fig. 118)		156	
[*] AIRPLANES WITH THE APU CONTROL UNI	T -18 AND BE	FORE	
Component Location Component Index Component Location Fault Isolation		101	CONFIG 2 [*]
Auto Shutdown - DC PWR LOSS on BITE (Fig. 138)		180s	
Auto Shutdown - GEN FILTER on		144	
BITE (Fig. 112) Auto Shutdown - HOT on BITE		139	
(Fig. 110) Auto Shutdown - LOP on BITE		134	
(Fig. 109) Auto Shutdown – NO LIGHT OFF		129	
on BITE (Fig. 107) Auto Shutdown – NORMAL STOP		180L	
SIG on BITE (Fig. 133) Auto Shutdown - OVER SPEED on BITE (Fig. 111)		143	

49-CONTENTS

GUI

Page 3 May 28/07



TABLE OF CONTENTS

Chapter Section

	Section		
<u>Subject</u>	<u>Subject</u>	<u>Page</u>	Effectivity
Auto Shutdown - OVER TEMP on BITE (Fig. 113)		146	
Auto Shutdown - START ABORTED on BITE (Fig. 105)		120	
Auto Shutdown - UNDER SPEED on BITE (Fig. 106)		124	
Auto Shutdown During Governed Speed - REVERSE FLOW on BITE (Fig. 108)		132	
APU BITE Procedure (Fig. 103)		103	
APU Starting Problems (Fig.		114	
104)			
APU Will Not Carry Pneumatic and Electrical Load Associated with RPM Droop		154	
(Fig. 117)			
EICAS Msg APU OIL QTY		152	
Displayed (Fig. 116)			
Faulty LRU - #1 SPD SENSOR on		1800	
BITE (Fig. 136) Faulty LRU - #2 SPD SENSOR on		180Q	
BITE (Fig. 137)		1004	
Faulty LRU - APU STARTER on		180c	
BITE (Fig. 129)			
Faulty LRU - Delta P SENSOR on BITE (Fig. 125)		177	
Faulty LRU - ECU on BITE (Fig. 131)		180F	
Faulty LRU - EGT #1 CIRCUIT on BITE (Fig. 134)		180M	
Faulty LRU - EGT #2 CIRCUIT on BITE (Fig. 135)		180N	
Faulty LRU - FUEL CONTROL on		178	
BITE (Fig. 126)			
Faulty LRU - FUEL SOL on BITE (Fig. 123)		175	
Faulty LRU - IGN UNIT on BITE		180B	
(Fig. 128)			
Faulty LRU - IGV ACT on BITE (Fig. 127)		179	
_		4.0014	
Faulty LRU - INLET DOOR RLY on BITE (Fig. 132)		180K	

49-CONTENTS



TABLE OF CONTENTS

Chapter Section Subject Subject <u>Page</u> **Effectivity** Faulty LRU - PT SENSOR on BITE 176 (Fig. 124) Faulty LRU - P2 SENSOR on BITE 180E (Fig. 130) Faulty Unit - STARTER CIRCUIT 127 on BITE (Fig. 106A) Figure Not Used 149 Fluctuating Duct Pressure 157 (Fig. 119) Fluids Coming from Drain Mast 173 (Fig. 121) Fumes and/or Smoke in the 174 Cabin (Fig. 122) High Oil Consumption (Fig. 150 115) 160 Low Duct Pressure (Fig. 120) Low Duct Pressure in All 166 Operational Modes: ECS, MES and Duct Pressurization (Fig. 120c) Low Duct Pressure in Duct 164 Pressurization Mode (3-25 PSIG) (Fig. 120B) Low Duct Pressure in MES Mode 172 Only (Fig. 120E) Low Duct Pressure During One 170 or Two ECS Pack Operation Only (Fig. 120D) No Duct Pressure (0-2 PSIG) 155 (Fig. 118) Surge Control System Test 163 (Fig. 120A) [*] AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT APU MOUNTS 49-13-00 Component Location 101 ALL Component Index Component Location APU AIR INTAKE SYSTEM 49-15-00 Component Location 101 ALL Component Index

49-CONTENTS

GUI

Page 5 Jan 28/05

Component Location



TABLE OF CONTENTS

Subject	Chapter Section <u>Subject</u>	<u>Page</u>	Effectivity
APU DRAINS AND VENTS Component Location Component Index Component Location	49–16–00	101	ALL
ENGINE APU AND GENERATOR LUBRICATION SYSTEM Component Location Component Index Component Location Fault Isolation	49-20-00 49-27-00	101	ALL
ENGINE FUEL AND CONTROL APU ENGINE FUEL SYSTEM Component Location Component Index Component Location	49–30–00 49–31–00	101	ALL
IGNITION/STARTING APU IGNITION/STARTING SYSTEM Component Location Component Index Component Location	49-40-00 49-41-00	101	ALL
AIR APU COOLING AIR SYSTEM Component Location Component Index Component Location	49–50–00 49–51–00	101	ALL
APU BLEED AIR SYSTEM Component Location Component Index	49-52-00	101	ALL
Component Location APU SURGE BLEED SYSTEM Component Location Component Index Component Location	49-53-00	101	ALL

49-CONTENTS



TABLE OF CONTENTS

Subject	Chapter Section Subject	<u>Page</u>	<u>Effectivity</u>
ENGINE CONTROLS APU CONTROL SYSTEM Component Location Component Index Component Location	49–60–00 49–61–00	101	ALL
INDICATING	49-70-00		
APU EXHAUST GAS TEMPERATURE INDICATING SYSTEM Component Location Component Index Component Location	49-71-00	101	ALL
APU TIME TOTALIZER Component Location Component Index Component Location	49-72-00	101	ALL
<u>EXHAUST</u>	49-80-00		
APU EXHAUST SYSTEM Component Location Component Index Component Location	49-81-00	101	ALL
OIL APU OIL INDICATING SYSTEM Component Location Component Index Component Location	49–90–00 49–94–00	101	ALL

49-CONTENTS



These are the possible types of faults: YOU FIND A FAULT WITH 1. EICAS Message AN AIRPLANE SYSTEM 2. Observed Fault Use the EICAS message, fault code, or fault description to find the corrective action or fault isolation procedure in the FIM. DO THE CORRECTIVE For details, see Figure 3 -ACTION OR GO TO THE FAULT ISOLATION PROCEDURE IN THE FIM If you do not have a fault code or an EICAS message and if the system has BITE, then you can use the system BITE to get more information: Use the BITE Index to find if the system has BITE and to find the BITE procedures in the FIM. For details, see Figure 2 -The fault isolation procedure FOLLOW THE STEPS IN explains how to find and repair the THE FAULT ISOLATION the cause of the fault. **PROCEDURE**

> Basic Fault Isolation Process Figure 1

ALL ALL


49-HOW TO USE THE FIM

For details, see Figure 4 —

01

Page 1 Sep 20/98






How to Get Fault Information from BITE Figure 2

49-HOW TO USE THE FIM


O1 Page 2

IF YOU HAVE:

THEN DO THIS TO FIND THE CORRECTIVE ACTION OR FAULT ISOLATION PROCEDURE IN THE FIM:



- 1. The first two digits of the fault code are the FIM chapter that you need. Go to the Fault Code Index in that chapter and find the fault code.
- 2. Find the Fault Isolation Reference for the fault code and do the corrective action. If there is a FIM reference, then go to that fault isolation procedure in the FIM and do the steps in the procedure (see Figure 4).



1. If you know the chapter of the EICAS message, then go to the EICAS Messages section in that chapter and find the EICAS message.

If you do not know the chapter of the EICAS message, then do these steps:

A. Go to FIM EICAS MESSAGE LIST and find the EICAS message in the table.

 $\underline{\mathtt{NOTE}} \colon$ The list follows the INTRODUCTION to the FIM.

- B. Find the chapter number on the same line as the EICAS message. Go to the EICAS Messages section in that chapter and find the EICAS message.
- 2. Do the corrective action in the "Procedure" column for the EICAS message. If there is a FIM reference, then go to that fault isolation procedure in the FIM and do the steps in the procedure (see Figure 4).



- 1. Go to the Fault Code Diagram for the problem in the applicable chapter.
- 2. Do the fault analysis on the diagram and find the fault code.
- 3. The first two digits of the fault code are the FIM chapter that you need. Go to the Fault Code Index in that chapter and find the fault code.
- 4. Find the Fault Isolation Reference for the fault code and do the corrective action. If there is a FIM reference, then go to that fault isolation procedure in the FIM and do the steps in the procedure (see Figure 4).

How to Find the Corrective Action or Fault Isolation
Procedure in the FIM
Figure 3

EFFECTIVITY-

49-HOW TO USE THE FIM



ASSUMED CONDITIONS AT START OF TASK

- External electrical power is OFF
- Hydraulic power and pneumatic power are OFF
- Engines are shut down
- Circuit breakers for the system are closed
- No equipment in the system is deactivated

PREREQUISITES

- This box gives the steps to get the airplane from the normal shutdown condition to the configuration necessary to do the fault isolation procedure.
- The Prerequisites give procedure references, circuit breakers, and special tools and equipment requirements.

FAULT ISOLATION BLOCKS


- Start the fault isolation procedure at block 1 unless specified differently.
- Do the check to get an answer to the question in the box. Follow the arrow that applies to your answer. This will go to the next check.
- When you get to a box in the column at the right of the page, you have isolated that fault. Do the steps in that box to repair the cause of the fault.
- Make sure that fault is corrected to complete the procedure.

Do the Fault Isolation Procedure Figure 4

EFFECTIVITY-

49-HOW TO USE THE FIM






Subjects in Each FIM Chapter Figure 5 (Sheet 1)

ALL

ALL

O1 Page 5
Sep 20/98

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.



Subjects in Each FIM Chapter Figure 5 (Sheet 2)

EFFECTIVITY-

49-HOW TO USE THE FIM

ALL

O1 Page 6 Sep 20/98



 IIILE	CHAP/SI	<u>= C</u>		
CHART APU OVERTEMPERATURE. CHECK APU SLOW/ACCEL/HUNG START. OVERSPEED	4911			
AUTO SHUTDOWNBLEED VALVE		74		
DOOR		30		
FIRE BTL DISCH LIGHT		26		
FIRE SWITCH				
FUEL FEED				
GENERATOR				
OIL QTY	4911			
PNEUMATIC SUPPLY	. CHAPTER	36,	CHAPTER	71
SHUTDOWN	4911			
START	4911			
FAULT LIGHT				
AUTO SHUTDOWN				
DURING SHUTDOWN				
DURING START	4911			
RUN LIGHT				
DURING SHUTDOWN.				
DURING START.				
SMOKE, FUMES FROM APU	4911			

APU - INDEX


ALL ALL


116196

49-INDEX

02

Page 1 Dec 20/90







OVERHEAD PANEL

AFT ELECTRONIC CONTROL PANEL

EICAS STATUS





APU - INDEX



AIRBORNE AUXILIARY POWER - EICAS MESSAGE LIST

1. General

- A. This procedure shows the EICAS message locations and gives a list of procedures to find the solution for each message.
 - (1) EICAS Message Locations (Fig. 1)
 - (a) Figure 1 shows the location of the EICAS display units and the area where the messages show on the display units.
 - (b) Each message level has a different location. The location and color of each message level is also shown.
 - (2) The EICAS MESSAGE LIST gives the message, level, and procedure for each message.
 - (a) The EICAS MESSAGE column lists the messages alphabetically. Messages which start with L, R, or C are put together and alphabetized at L.
 - (b) The LEVEL column gives all levels for each message as follows:
 - A Warning messages
 - B Caution messages
 - C Advisory messages
 - S Status messages
 - M Maintenance messages
 - (c) The PROCEDURE column gives the steps that are necessary to remove the message and includes one or more of the procedures that follow:
 - 1) A Fault Isolation Manual procedure reference
 - 2) A Maintenance Manual procedure and reference
 - 3) Wiring checks and a Wiring Diagram Manual reference
 - 4) A reference to an EICAS message list in a different chapter.
 - 5) A reference to a FAULT CODE INDEX and specified fault codes
 - 6) A step to change the airplane configuration


EFFECTIVITY—


49-EICAS MESSAGES

01




FAULT ISOLATION/MAINT MANUAL






ENGINE PRIMARY PAGE OR COMPACTED PAGE (TOP DISPLAY UNIT)



ECS/MSG PAGE
(BOTTOM DISPLAY UNIT)



STATUS PAGE
(BOTTOM DISPLAY UNIT)

LE	VEL	COLOR		
A-WAR	NING	RED		
B-CAU	TION	YELLOW		
C-ADV	ISORY	YELLOW		
S-STA	TUS	WHITE		
M-MAI	NTENANCE	WHITE		

EICAS Message Locations Figure 1

ALL

49-EICAS MESSAGES

01

Page 2 Dec 20/90



EICAS MESSAGE LIST					
EICAS MESSAGE	LEVEL	PROCEDURE			
APU BAT CHGR	S, M	Go To 24-EICAS MESSAGES			
APU BAT DISCH	С	Go To 24-EICAS MESSAGES			
APU BAT NO STBY	S, M	M Go To 24-EICAS MESSAGES			
APU BITE	М	FIM 49-11-00/101, Fig. 103, Block 1			
APU BLEED VAL	С	Go To 36-EICAS MESSAGES			
APU DOOR	S, M	FIM 49-11-00/101, Fig. 104, Block 23			
APU FAULT	С	FIM 49-11-00/101, Fig. 103, Block 1			
APU FUEL VAL	С	Go To 28-EICAS MESSAGES			
APU GEN OFF	С	Go To 24-EICAS MESSAGES			
APU OIL QTY	S, M	M FIM 49-11-00/101, Fig. 116, Block 1			


49-EICAS MESSAGES

02

Page 3 Jan 28/05

ALL






APU START - FAULT CODES

49-FAULT CODE DIAGRAM

02 Page 1

Jan 28/01





APPLICABLE CIRCUIT BREAKERS AS INSTALLED

6E3	APU FUEL VALVES	11c33	DC PUMP APU	11D32	DISAGREE ENABLE APU
6H12	APU START TRU CONT	11c33	DC PUMP PWR	11D32	DISAGREE ENBL APU
11B34	APU ALTN CONT			11D35	DC PUMP CONT

APU AUTO SHUTDOWN/APU OIL QTY - FAULT CODES


ALL ALL

49-FAULT CODE DIAGRAM

03

Page 2 May 28/02





NOTE: CLOSING THE APU BLEED VALVE REDUCES WORKLOAD ON THE APU AND PERMITS APU COOLING BEFORE SHUTDOWN. APU RUN LIGHT WILL EXTIN BEFORE 60 SEC IF APU BLEED VALVE IS CLOSED BEFORE APU SLCTR SW IS PLACED TO OFF.

APPLICABLE CIRCUIT BREAKERS AS INSTALLED

		_		
6E3	APU FUEL VALVES	11D32	DISAGREE ENAB	SLE APU
11B34	APU ALTN CONT	11D32	DISAGREE ENBL	. APU
11B34	APU MN BAT CONT	11D35	DC PUMP CONT	
11c33	DC PUMP APU	•		
11c33	DC PUMP PWR			


APU SHUTDOWN - FAULT CODES

49-FAULT CODE DIAGRAM

O1 Page 3
Jan 28/01

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.





SMOKE, FUMES FROM APU - FAULT CODES

EFFECTIVITY ALL


49-FAULT CODE DIAGRAM

02

Page 4 Sep 15/84



CHART 1



APU WILL SHUT DOWN AND FAULT LGT ILLUMINATE WITH EICAS MSG "APU FAULT" DISPLAYED, IF THE NORMAL LIMIT IS EXCEEDED FOR .5 SEC OR THE REDUNDANT LIMIT FOR .1 SEC.

CHARTS

EFFECTIVITY ALL

49-FAULT CODE DIAGRAM

02

Page 5 Jan 28/01



CHECK 1

APU SLOW ACCEL/HUNG START CHECK

APU WILL SHUT DOWN AND FAULT LGT ILLUMINATE WITH EICAS MSG "APU FAULT" DISPLAYED IF THESE ACCELERATION LIMITS ARE NOT MET.

RPM %	TIME (SEC)				
NO ACCEL	5				
7	30				
20	50				
50	70 (ON	GRD	OR IN	FLT BELOW	30,000')
50	100 (IN	FLT	ABOVE	30,000')	-

CHECK 2

OVERSPEED LIMIT

APU WILL SHUT DOWN AND FAULT LGT ILLUMINATE WITH EICAS MSG "APU FAULT" DISPLAYED IF 107% RPM LIMIT IS EXCEEDED.

CHECKS

EFFECTIVITY-

206765

ALL

49-FAULT CODE DIAGRAM

Ω1

Page 6 Jan 28/01



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
49 11 XA 00	An APU start problem was encountered by the flight crew which is not covered by the fault code diagrams.	SSM 49-41-01
49 11 XB 00	An APU auto shutdown or oil quantity problem was encountered by the flight crew which is not covered by the fault code diagrams.	SSM 49-61-01
49 11 XC 00	An APU shutdown problem was encountered by the flight crew which is not covered by the fault code diagrams.	SSM 49-61-01
49 11 XD 00	An APU smoke, fumes from APU problem was encountered by the flight crew which is not covered by the fault code diagrams.	FIM 49-11-00/101, Fig. 122, Block 1
49 11 01 00	APU slow to start, sec elapsed before RUN light turned on.	FIM 49-11-00/101, Fig. 104, Block 1
49 11 02 00	APU failed to start. FAULT light on and EICAS message APU FAULT displayed. APU selector positioned OFF then ON, light and message remained.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 03 00	APU failed to start. RUN light off, FAULT light on and EICAS APU FAULT message displayed. (describe additional indications such as: RPM, EGT, etc.).	FIM 49-11-00/101, Fig. 103, Block 1
49 11 04 00	APU failed to start. FAULT light on and EICAS message APU FAULT displayed. APU started normal on next attempt.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 05 00	APU failed to start. FAULT light on and EICAS message APU FAULT displayed. Additional start attempts unsuccessful.	FIM 49-11-00/101, Fig. 103, Block 1

49-FAULT CODE INDEX

ALL



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
49 11 05 00	APU failed to start. FAULT light on and EICAS message APU FAULT displayed. Second attempt indicates no RPM rise.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 07 00	APU failed to start. FAULT light on and EICAS message APU FAULT displayed. Second attempt indicates slow accel, hung start.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 08 00	APU failed to start. FAULT light on and EICAS message APU FAULT displayed. Second attempt indicates no EGT rise.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 09 00	APU failed to start. FAULT light on and EICAS message APU FAULT displayed. Second attempt indicates EGT high.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 10 00	APU failed to start. FAULT light on and EICAS message APU FAULT displayed. Second attempt indicates APU overspeed.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 11 00	APU failed to start. FAULT light on and EICAS message APU FAULT displayed. Second start norm, EGT & RPM norm.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 12 00	APU failed to start. FAULT light on and EICAS message APU FAULT displayed. Second attempt shows norm EGT & RPM, but APU quit.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 15 00	APU failed to start. EICAS megs APU DOOR & APU FAULT displayed & FAULT lgt on when sw placed to START.	
49 11 16 00	APU shutdown, FAULT light on and EICAS APU FAULT message displayed.	FIM 49-11-00/101, Fig. 103, Block 1

49-FAULT CODE INDEX

ALL



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
49 11 17 00	APU had auto shutdown, FAULT light on and EICAS message APU FAULT displayed. Next start attempt normal.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 18 00	APU had auto shutdown after eng start. FAULT light on and EICAS message EICAS msg APU FAULT displayed. Next start attempt normal.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 19 00	APU had auto shutdown during eng start, packs on, etc. FAULT light on and EICAS message APU FAULT displayed. Next start attempt normal.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 22 00	EICAS message APU OIL QTY displayed.	FIM 49-11-00/101, Fig. 116, Block 1
49 11 23 00	EICAS message APU DOOR remains displayed after APU shutdown.	FIM 49-11-00/101, Fig. 104, Block 23
49 11 24 00	APU fault during shutdown. FAULT light on and EICAS APU FAULT message displayed.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 25 00	APU shut down prior to 60-second cool down period. FAULT light on and EICAS APU FAULT message displayed.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 26 00	(Smoke, Fumes) Coming into cabin from APU.	FIM 49-11-00/101, Fig. 122, Block 1
49 11 27 00	EICAS APU BITE message displayed.	FIM 49-11-00/101, Fig. 103, Block 1
49 11 28 00	EICAS message APU DOOR displayed.	FIM 49-11-00/101, Fig. 104, Block 23
49 11 29 00	EICAS APU OIL QTY msg displayed.	FIM 49-11-00/101, Fig. 116, Block 1
49 11 30	(01=L,02=R) Engine slow to start using APU air. Duct press low, psi.	FIM 49-11-00/101, Fig. 120, Block 1

49-FAULT CODE INDEX

80

Page 3 Sep 20/08



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
49 11 31	(01=L,02=R) Engine N3 failed to rotate with start selector in GND, duct press was low, psi with start vlv open. APU was press source.	FIM 49-11-00/101, Fig. 120, Block 1
49 11 32	(01=L,02=R) Engine low max N3 motoring speed during start, duct press was low with start vlv open.	FIM 49-11-00/101, Fig. 120, Block 1
49 11 33 00	L and R duct pressure zero with APU running, APU bleed air switch ON, and VALVE light off.	FIM 49-11-00/101, Fig. 118, Block 1
49 11 34 00	L and R duct press low with APU suppling pneumatic system.	FIM 49-11-00/101, Fig. 120, Block 1
49 11 35 00	L and R duct press fluctuates with APU supplying pneumatic system.	FIM 49-11-00/101, Fig. 119, Block 1
49 11 36 00	APU generator OFF light off and EICAS message APU GEN OFF displayed when packs operated engine started.	Replace the inlet pressure (P2) sensor YBMTS4 (AMM 49-61-04/201). If the problem continues, replace the fuel control unit YBMM4 (AMM 49-31-01/401).
49 11 39 00	APU shutdown after eng start, FAULT light on and EICAS APU FAULT message displayed. Next start attempt abnormal.	FIM 49-11-00/101, Fig. 103, Block 1
49 72 01 00	APU hours indicator does not advance normally with APU operating.	Replace the APU hourmeter (WDM 49-72-11). If the problem continues, examine circuit from the E6 rack APU TOTALIZER circuit breaker to the hourmeter terminals. Repair any problems that you find.

49-FAULT CODE INDEX



BITE Index

1. General

- A. Use this index to find the BITE procedure for the applicable LRU/System.
- B. The BITE procedure will provide the fault isolation instructions for the fault indications/LRU maintenance messages.

LRU/System Name	<u>Acronym</u>	FIM Reference
Air Data Computer	ADC	34–12
Air Data Inertial Reference Unit	ADIRU	34-26
Air Traffic Control Transponder	ATC	34-53
Airborne Vibration Monitor Signal Conditioner	AVM	77–31
Antiskid/Autobrake Control Unit		32-42
APU Fire Detection System		26-15
Automatic Direction Finder Receiver	ADF	34-57
APU Control Unit	ECU	49–11
Brake Temperature Monitor Unit		32-46
Bus Power Control Unit	BPCU	24-20
Cabin Pressure Controller		21-30
Digital Flight Data Acquisition Unit	DFDAU	31-31
Distance Measuring Equipment Interrogator	DME	34-55
Duct Leak (Wing and Body)		26-18
E/E Cooling Control Card (If cards installed)		21-58
ECS Bleed Configuration Card		36–10
Electronic Engine Control (RR Engines)	EEC	73–21
Electronic Engine Control Monitor Unit (PW Engines)	EECM	71-EPCS Message Index
Electronic Flight Instrument System	EFIS	34-22
Electronic Propulsion Control System (PW Engines)	EPCS	71-EPCS Message Index
Engine Fire/Overheat Detection System		26–11
Engine Indication and Crew Alerting System Computer	EICAS	31-41

Bite Index Figure 1 (Sheet 1)

EFFECTIVITY-

49-BITE INDEX



LRU/System Name	Acronym	FIM Reference
Engine Turbine Cooling Overheat Detection System (RR Engines)		26-13
Enhanced Ground Proximity Warning Computer	EGPWC	34-46
Flap/Slat Accessory Module	FSAM	27-51
Flap/Slat Electronic Unit	FSEU	27-51
Flight Management Computer	FMC	34-61
Fuel Quantity Indicating System Processor	FQIS	28-41
Ground Proximity Warning Computer	GPWC	34-46
HF (High Frequency) Communication		23-11
Inertial Reference Unit	IRU	34-21
Instrument Comparator Unit	ICU	34-25
Instrument Landing System Receiver	ILS	34-31
Lower Cargo Compartment Smoke Detection System		26-16
Maintenance Control Display Panel	MCDP	22-00
PA (Passenger Address) Amplifier		23-31
Pack Standby Temperature Controller		21-51
Pack Temperature Controller		21-51
Passenger Entertainment System	PES	23-34
Power Supply Module (Control System Electronics Units)	PSM	27-09
Propulsion Discrete Interface Unit (PW Engines)	PDIU	73-21
Proximity Switch Electronics Unit	PSEU	32-09
Radio Altimeter Transmitter/Receiver	RA	34-33
Rudder Ratio Changer Module	RRCM	27-09
Spoiler Control Module	SCM	27-09
Stabilizer Position Module	SPM	27-48
Stabilizer Trim/Elevator Asymmetry Limit Module	SAM	27-09
Stall Warning Computer/Module (in Warning Electronic Unit)	SWC	27-32
Strut Overheat Detection System (RR Engines)		26–12

Bite Index Figure 1 (Sheet 2)

EFFECTIVITY-

49-BITE INDEX

ALL

01 Page 2 Sep 28/99



<u>LRU/System Name</u>	<u>Acronym</u>	FIM Reference
Thrust Management Computer/Autothrottle	TMC	22-00
Traffic Alert and Collision Avoidance Computer	TCAS	34-45
VHF (Very High Frequency) Communication		23-12
VOR/Marker Beacon Receiver	VOR/MKR	34-51
Warning Electronic Unit BITE Module (Stall Warning)	WEU	27-32
Weather Radar Transceiver	WXR	34-43
Wheel Well Fire Detection		26–17
Window Heat Control Unit	WHCU	30-41
Yaw Damper Module	YDM	22-21
Yaw Damper/Stabilizer Trim Module	YSM	27-09
Zone Temperature Controller		21-60

Bite Index Figure 1 (Sheet 3)

49-BITE INDEX

01

Page 3 Sep 28/99



AUXILIARY POWER UNIT

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
AUXILIARY POWER UNIT		1	316AR,315AL, APU COMPT	49-11-01


Auxiliary Power Unit - Component Index Figure 101


49-11-00 config 1

01

Page 101 Sep 20/94







AUXILIARY POWER UNIT

Auxiliary Power Unit - Component Location Figure 102

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

49-11-00 CONFIG 1 Page 102 Sep 20/94

01



PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

APU BITE PROCEDURE

PUT THE APU MASTER CONTROL SWITCH ON P5 TO "OFF".

MAKE SURE THE APU SPEED IS BELOW 7%.

MOVE THE TEST SWITCH ON THE APU CONTROL UNIT (ECU), M206, IN THE AFT EQUIPMENT CENTER TO "LAMP TEST".

DO ALL LIGHTS IN THE FIVE COLUMNS OF INDICATORS COME ON, COLUMN BY COLUMN, FROM LEFT TO RIGHT?

NOTE: IF YOU HOLD THE SWITCH IN POSITION DURING THE LAMP TEST AND FOR 10 SECONDS AFTER, THE ECU WILL SHOW MINIFLAGS. THE MINI-FLAG NUMBERS WILL SHOW ON THE LAMPS ON THE ECU FRONT PANEL.

> TURN YOUR HEAD CLOCK-WISE 90 DEGREES TO READ THE MINIFLAGS. THE MINIFLAGS ARE FOR INFORMATION ONLY. DO NOT USE THE MINIFLAG DATA AS AN ALTERNATIVE TO THE FAULT ISOLATION PROCEDURES. THE MINI-FLAG DESCRIPTIONS ARE IN TABLE C.

> THE LAMPS THAT COME ON AFTER THE MINIFLAGS ARE USED BY THE APU MANUFACTURER ONLY.

> > YES

SEE SHEET 2 (BLOCK 2)

21 IF ALL OF THE LIGHTS DO NOT COME ON, REPLACE THE ECU, M206 (AMM 49-61-05/201). IF ONE OR TWO LIGHTS DO


NOT COME ON, COMPLETE THE BITE PROCEDURE (FIG. 103, BLOCK 2) TO GET THE HISTORY DATA, THEN REPLACE THE ECU, M206 (AMM 49-61-05/201).

IF THE PROBLEM CONTINUES, EXAMINE THE CIRCUITS FROM THE ECU, CONNECTOR D1796C, PIN 9 (GND, PIN 11), TO CIRCUIT BREAKERS "APU ALTN CONT" (11B34) AND "APU CONT" ON THE E6 RACK (WDM 49-61-11).

REPAIR THE PROBLEMS THAT YOU FIND.

APU BITE Procedure Figure 103 (Sheet 1)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE



APU BITE Procedure Figure 103 (Sheet 2)

EFFECTIVITY

AIRPLANES WITH THE APU


CONTROL UNIT -18 AND BEFORE

49-11-00 CONFIG 1 Page 104

Sep 20/94

01





MESSAGE	CORRECTIVE ACTION
ECU	REPLACE THE ECU, M206 (AMM 49-61-05/201).
NO ACCEL	FIG. 105.
SLOW START	FIG. 106.
NO FLAME	FIG. 107.
REVERSE FLOW	FOR AN APU START SHUTDOWN, TIGHTEN THE INLET TEMPERATURE SENSOR FOR THE LOAD COMPRESSOR (LCIT), YBMTS5 CONNECTIONS. IF THE PROBLEM CONTINUES, REPLACE THE SURGE VALVE, YBMM5 (AMM 49-53-01/401).
	FOR AN APU GOVERNED SPEED SHUTDOWN, DO THIS PROCEDURE: AUTO SHUTDOWN DURING GOVERNED SPEED - "REVERSE FLOW" ON BITE (FIG. 108).
DC PWR LOSS	FIG. 104, BLOCK 22.
LOP	FIG. 109.
INLET DOOR	FIG. 104, BLOCK 23.
S/D CIRCUIT	REPLACE THE ECU, M206 (AMM 49-61-05/201). IF THE PROBLEM CONTINUES, REPLACE THE FUEL CONTROL UNIT, YBMM4 (AMM 49-31-01/401).
нот	FIG. 110.
OVER SPEED	FIG. 111.
GEN FILTER	FIG. 112.
FIRE EMERG	LOOK AT THE AIRPLANE LOG BOOK AND THE APU COMPARTMENT FOR SIGNS OF A REPORTED
	FIRE. IF FIRE DAMAGE SHOWS, REPAIR OR REPLACE THE DAMAGED COMPONENTS. MAKE SURE
	THAT THE APU CONTROL SWITCH ON THE P5 PANEL IS "OFF" AND MOVE THE MAIN BATTERY
	SWITCH ON THE P5 PANEL "ON" THEN "OFF. IF THERE IS NO LOG BOOK REPORT OR SIGNS OF
	FIRE DAMAGE, DO THE BITE PROCEDURE FOR THE APU FIRE DETECTION SYSTEM (FIM 26-15-00/
OVER TEMP	101, FIG. 103).
OVER TEMP	FIG. 113.
FAILED SENSOR	FIG. 114.

FAULT DISPLAY REFERENCE TABLE A

APU BITE Procedure Figure 103 (Sheet 3)

EFFECTIVITY

AIRPLANES WITH THE APU

CONTROL UNIT -18 AND BEFORE

49–11–00

CONFIG 1 1 Page 105 Sep 28/02

01



MESSAGE	CORRECTIVE ACTION	IF PROBLEM CONTINUES
LCIT SENSOR	REPLACE THE LCIT SENSOR, YBMTS5 (AMM 49-61-03/401).	EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PINS E6 AND E7, TO THE INLET TEMPERATURE SENSOR (WDM 49-14-11). REPAIR
FUEL SOL	REPLACE THE FUEL SOLENOID VALVE, YBMV1 (AMM 49-31-02/401).	THE PROBLEMS THAT YOU FIND. EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PINS F6 AND F7, TO THE VALVE CONNECTOR, PINS 1,2 (WDM 49-14-11). REPAIR
PT SENSOR	REPLACE THE FLOW SENSING MODULE (AMM 49-53-08/401).	THE PROBLEMS THAT YOU FIND. EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PINS A1,A2,A3, AND A4, TO THE PT TRANSDUCER CONNECTOR, PINS 1,2,3, AND 4 (WDM 49-14-11). REPAIR THE PROBLEMS
ΔP SENSOR	REPLACE THE FLOW SENSING MODULE (AMM 49-53-08/401).	THAT YOU FIND. EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796B, PINS A1,A2,B3, AND B4, TO THE AP TRANSDUCER CONNECTOR, PINS 1,2,3, AND 4 (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
NO. 1 SPD SENSOR	REPLACE THE RIGHT MONOPOLE, YBMTS8 (AMM 49-61-02/401).	EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PINS A10 AND A11, TO THE MONOPOLE CONNECTOR, PINS 1,2 (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
NO. 2 SPD SENSOR	REPLACE THE LEFT MONOPOLE, YBMTS9 (AMM 49-61-02/401).	EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PINS B5 AND B6, TO THE MONO- POLE CONNECTOR, PINS 1 AND 2 (WDM 49-14-11). REPAIR THE PROBLEMS THAT
LOP SWITCH	REPLACE THE LOP SWITCH, YBMS2 (AMM 49-94-02/401).	YOU FIND. EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PIN C5, TO THE LOP SWITCH CONNECTOR, PIN 1. EXAMINE THE CIRCUIT FROM THE LOP SWITCH CONNECTOR, PIN 2, TO GROUND (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
FUEL CONTROL	REPLACE THE FUEL CONTROL UNIT (THE TORQUE MOTOR, YBMM4, HAS A PROBLEM) (AMM 49-31-01/401).	EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PINS H10 AND H11, TO THE TORQUE MOTOR CONNECTOR, PINS 1 AND 2 (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
SURGE VALVE	REPLACE THE SURGE VALVE, YBMM5 (AMM 49-53-01/401).	EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PINS G6 AND G7, TO THE TORQUE MOTOR CONNECTOR, PINS 1 AND 2 (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
NO. 1 T/C RAKE	REPLACE THE LEFT SIDE THERMOCOUPLES, YBMTS6 (AMM 49-71-01/201).	EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PINS A6 AND A7, TO THE THERMOCOUPLE RAKE NO. 1 (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
NO. 2 T/C RAKE	REPLACE THE RIGHT SIDE THERMOCOUPLES, YBMTS7 (AMM 49-71-01/201).	EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PINS A8 AND A9, TO THE THERMOCOUPLE RAKE NO. 2 (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.

FAULTY UNIT REFERENCE TABLE B

ERASE THE "APU BITE" MESSAGE IF IT SHOWS (FIM 31-41-00/101, FIG. 109).

APU BITE Procedure Figure 103 (Sheet 4)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

49-11-00

04

CONFIG 1 Page 106 Sep 20/94



MESSAGE	CORRECTIVE ACTION	IF PROBLEM CONTINUES
IGV ACT	REPLACE THE IGV ACTUATOR, YBMM6 (AMM 49-52-02/401).	EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PINS G8,G9,F9,F10,F11, AND F8, TO THE ACTUATOR CONNECTOR, PINS 1,2,3, 4,5, AND 6 (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
IGN UNIT	REPLACE THE IGNITION UNIT, YBMM1 (AMM 49-41-03/401).	EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796C, PINS 4 AND 6, TO THE IGNITION UNIT CONNECTOR, PINS 1 AND 2 (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
DEOIL SOL	REPLACE THE DEOIL SOLENOID VALVE, YBMM3 (AMM 49-27-08/401).	EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PINS J4 AND J5, TO THE SOLE- NOID CONNECTOR, PINS 1 AND 2. EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796B, PIN J10, TO THE OIL TEMP SWITCH, YBMS5, CON- NECTOR, PIN 1 (WDM 49-14-11). REPAIR THE
FLOW DIV SOL	REPLACE THE FUEL FLOW DIVIDER SOLENOID VALVE, YBMM2 (AMM 49-31-03/401).	PROBLEMS THAT YOU FIND. EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PINS J7 AND J8, TO THE SOLE- NOID CONNECTOR, PINS 1 AND 2 (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
ECS CONTROL	REPLACE THE ZONE TEMPERATURE CONTROL, M195 (AMM 21-61-03/401).	
APU STARTER	REPLACE THE APU STARTER MOTOR, M893 (AMM 49-41-01/201).	
STARTER CIRCUIT	SEE FIG. 106A.	
HOT SENSOR	REPLACE THE OIL TEMPERATURE (HOT) SEN- SOR, YBMTS1 (AMM 49-94-01/401).	EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PINS E4 AND E5, TO THE HOT SENSOR CONNECTOR, PINS A AND B (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
P2 SENSOR	REPLACE THE INLET PRESSURE (P2) SENSOR, YBMTS4 (AMM 49-61-04/201).	EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PINS A1,A2,C8, AND C9, TO THE P2 SENSOR CONNECTOR, PINS 1,2,3, AND 4 (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
ECU	REPLACE THE APU CONTROL UNIT (ECU), M206 (AMM 49-61-05/201).	EXAMINE THE CIRCUIT FROM THE ECU, CON- NECTOR D1796B, PIN J10, TO THE OIL TEMP SWITCH, YBMS5, CONNECTOR, PIN 1 (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.

FAULTY UNIT REFERENCE TABLE B

APU BITE Procedure Figure 103 (Sheet 5)

49-11-00



MESSAGE	CORRECTIVE ACTION	IF PROBLEM CONTINUES
FAN VALVE	APU WITHOUT THE FAN ISOLATION VALVE (POST-ALLIEDSIGNAL-SB 49-7391); IGNORE THIS MESSAGE, IT IS A NUISANCE MESSAGE. 1 APU WITH THE FAN ISOLATION VALVE (PRE-ALLIEDSIGNAL-SB 49-7391); REPLACE THE FAN ISOLATION VALVE, YBMS4 (AMM 49-51-02/401).	APU WITH THE FAN ISOLATION VALVE CONNECTED TO THE FIRST-STAGE COMPRESSOR (PRE-ALLIEDSIGNAL-SB 49-7391; POST-ALLIEDSIGNAL-SB 49-7192); EXAMINE THE CONDITION OF THE LINE FROM THE FAN ISOLATION VALVE TO THE FIRST-STAGE COMPRESSOR. REPAIR THE LINE IF IT IS NECESSARY. 1 APU WITH THE FAN ISOLATION VALVE CONNECTED TO THE SURGE VALVE (PRE-ALLIEDSIGNAL-SB 49-7391; PRE-ALLIEDSIGNAL-SB 49-7192); EXAMINE THE CONDITION OF THE LINE FROM THE FAN ISOLATION VALVE TO THE SURGE VALVE. REPAIR THE LINE IF IT IS NECESSARY. 1 IF THE PROBLEM CONTINUES, REPLACE THE SURGE CONTROL VALVE FILTER (AMM 49-53-06/201). EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D408B, PIN B10, TO THE FAN VALVE SWITCH CONNECTOR, PIN 1. EXAMINE THE CIRCUIT FROM THE SWITCH CONNECTOR, PIN 2, TO GROUND (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND. IF THERE WAS A HEAT PROBLEM, EXAMINE THE FAN INLET DUCT FOR DAMAGE. REPAIR THE PROBLEMS THAT YOU FIND.
FILTER SWITCH	REPLACE THE GENERATOR ΔP SWITCH, YBMS1 (AMM 49-27-15/401).	EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796B, PIN D11, TO THE FILTER SWITCH CONNECTOR, PIN 1. EXAMINE THE CIRCUIT FROM THE SWITCH CONNECTOR, PIN 2, TO GROUND (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
A/C RELAY	REPLACE RELAY, K175 (WDM 49-61-11).	REPLACE RELAY, K176 (WDM 49-61-11).

FAULTY UNIT REFERENCE TABLE B

APU BITE Procedure Figure 103 (Sheet 6)

EFFECTIVITY

AIRPLANES WITH THE APU

CONTROL UNIT -18 AND BEFORE

49-11-00 config 1



NOTE: THE MINIFLAGS ARE FOR INFORMATION ONLY. DO NOT USE THE MINIFLAG DATA AS AN ALTERNATIVE TO THE FAULT ISOLATION PROCEDURES.

NUMBER	DESCRIPTION
1	SPEED SIGNAL NO. 1 IS NOT FUNCTIONING. THE SPEED SENSOR NO. 1 OR WIRING IS NOT PROVIDING PROPER INPUT AT SPEEDS GREATER THAN 50%.
2	SPEED SIGNAL NO. 2 IS NOT FUNCTIONING. THE SPEED SENSOR NO. 2 OR WIRING IS NOT PROVIDING PROPER INPUT AT SPEEDS GREATER THAN 50%.
3	ECU SPEED CONVERTER CIRCUIT IS FAILED. THE ECU SPEED CONVERTER CIRCUIT DOES NOT INTERPRET THE SPEED SIGNAL PROPERLY WHEN THE APU IS OPERATING AT SPEEDS GREATER THAN 50%.
4	FAILED ECU N/DC CONVERTER NO. 1 CIRCUIT. THE ECU CIRCUIT THAT CONVERTS THE NO. 1 SPEED SIGNAL TO A DC VOLTAGE IS NOT FUNCTIONING PROPERLY.
5	FAILED ECU N/DC CONVERTER NO. 2 CIRCUIT. THE ECU CIRCUIT THAT CONVERTS THE NO. 2 SPEED SIGNAL TO A DC VOLTAGE IS NOT FUNCTIONING PROPERLY.
6	FAILED ECU N/DC CONVERTER NO. 3 CIRCUIT. THE ECU REDUNDANT CIRCUIT THAT CONVERTS THE HIGHEST SPEED SIGNAL TO A DC VOLTAGE IS NOT FUNCTIONING PROPERLY.
9	LCIT SENSOR SIGNAL OUT OF RANGE. THE LCIT SENSOR CIRCUIT READS LESS THAN -100°F.
10	OIL TEMPERATURE SENSOR RESISTANCE OUT OF RANGE. THE OIL TEMPERATURE RESISTANCE IS NOT WITHIN THE RANGE OF 65 TO 208 OHMS (-110 TO +482°F).
11	FAILED EGT THERMOCOUPLE CIRCUIT NO. 1 SIGNAL OUT OF RANGE. THE THERMOCOUPLE CIRCUIT READS LESS THAN -100°F ABSOLUTE OR EGT THERMOCOUPLE NO. 2 READS +150°F MORE THAN EGT NO. 1. SEVERE POWER SECTION DISTRESS CAN ALSO CAUSE A LARGE VARIATION IN EGT NO. 1 AND NO. 2 READINGS.
12	FAILED EGT THERMOCOUPLE CIRCUIT NO. 2 SIGNAL OUT OF RANGE. THE THERMOCOUPLE CIRCUIT READS LESS THAN -100°F ABSOLUTE OR EGT THERMOCOUPLE NO. 1 READS +150°F MORE THAN EGT NO. 2. SEVERE POWER SECTION DISTRESS CAN ALSO CAUSE A LARGE VARIATION IN EGT NO. 1 AND NO. 2 READINGS.
14	FAILED TOTAL PRESSURE SENSOR/CIRCUIT. THE PT VALUE IS OUT OF ITS NORMAL OPERATING RANGE OR DIFFERS BY MORE THAN 3 PSIG FROM THE P2 SENSOR READING ON THE GROUND AT SPEEDS LESS THAN 12%. A MODERATELY SHIFTED P2 SENSOR OUTPUT COULD ALSO CAUSE THIS MINIFLAG.
15	FAILED DIFFERENTIAL PRESSURE SENSOR/CIRCUIT. THE DP VALUE IS OUT OF ITS NORMAL OPERATING RANGE.
16	FAILED AMBIENT PRESSURE (P2) SENSOR/CIRCUIT. THE P2 VALUE IS OUT OF ITS NORMAL OPERATING RANGE.
17	GENERATOR OIL FILTER SWITCH FAILED OPEN. THE NORMALLY CLOSED GENERATOR OIL FILTER SWITCH IS OPEN PRIOR TO APU OPERATION.
18	COOLING FAN ISOLATION VALVE FAILED. THE NORMALLY OPEN COOLING FAN ISOLATION VALVE SWITCH IS CLOSED PRIOR TO OPERATION OR OPEN DURING APU OPERATION.
19	LOP SWITCH CIRCUIT FAILED CLOSED. THE LOP SWITCH CIRCUIT IS CLOSED (SHORTED) PRIOR TO START.
21	ECU FLOW DIVIDER DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
22	CLOGGED GENERATOR FILTER.
23	ECS DEMAND SIGNAL OUT OF RANGE. THE ECS DEMAND SIGNAL IS LESS THAN -0.3V DC OR GREATER THAN 9.9V DC DURING APU OPERATION IN ECS MODE.
25	FUEL SOLENOID CIRCUIT FAILED. THE FUEL SOLENOID CIRCUIT IS OPEN OR SHORTED.
26	DEOIL SOLENOID CIRCUIT FAILED. THE DEOIL SOLENOID CIRCUIT IS OPEN OR SHORTED.

ECU MINIFLAG DESCRIPTION TABLE C

APU BITE Procedure Figure 103 (Sheet 7)

49–11–00

CONFIG 1 01 Page 109 Sep 28/01



NUMBER	DESCRIPTION
27	FLOW DIVIDER SOLENOID CIRCUIT FAILED. THE FLOW DIVIDER SOLENOID CIRCUIT IS OPEN OR SHORTED.
28	IGNITION UNIT CIRCUIT FAILED. THE IGNITION UNIT CIRCUIT IS OPEN OR SHORTED.
29	ECU DEOIL SOLENOID DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
30	ECU FUEL SOLENOID DRIVER OPEN. INTERNAL ECU FAILURE WAS FOUND.
32	ECU IGNITION UNIT DRIVER OPEN. INTERNAL ECU FAILURE WAS FOUND.
33	ECU STARTER CIRCUIT DRIVER OPEN. INTERNAL ECU FAILURE WAS FOUND.
34	AIRPLANE STARTER CIRCUIT FAILED. VOLTAGE WAS FOUND AT THE START MOTOR AT GREATER THAN 95% SPEED OR NO START MOTOR VOLTAGE IS FOUND DURING START CYCLE.
35	START MOTOR FAILED. VOLTAGE EXISTS ON THE START MOTOR BUT NO APU ROTATION IS FOUND AFTER 30 SECONDS.
36	ECU SCV DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
37	ECU FUEL CONTROL TORQUE MOTOR DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
38	ECU IGV ACTUATOR DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER WAS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
39	ECU FUEL CONTROL TORQUE MOTOR DRIVER OPEN. INTERNAL ECU FAILURE WAS FOUND.
41	FUEL CONTROL TORQUE MOTOR FAILED. THE FUEL CONTROL TORQUE MOTOR CIRCUIT IS OPEN OR SHORTED.
42	IGV ACTUATOR FAILED. THE IGV TORQUE MOTOR OR LVDT IS SHORTED OR OPEN OR COMMANDED IGV POSITION DOES NOT AGREE WITH ACTUAL IGV POSITION BY 10 DEGREES FOR MORE THAN 6 SECONDS (SEE MINIFLAGS 106,126, AND 127 FIRST IF PRESENT).
43	SURGE CONTROL VALVE TORQUE MOTOR FAILED. THE SURGE CONTROL VALVE TORQUE MOTOR CIRCUIT IS OPEN OR SHORTED.
44	ECU EGT NO. 1 SIGNAL CONDITIONER FAILED. INTERNAL ECU FAILURE WAS FOUND.
45	ECU EGT NO. 2 SIGNAL CONDITIONER FAILED. INTERNAL ECU FAILURE WAS FOUND.
46	ECU OVERTEMPERATURE TEST FAILURE. INTERNAL ECU FAILURE WAS FOUND DURING APU SHUTDOWN.
47	INLET DOOR RELAY FAILED. AN OVERCURRENT WAS FOUND ON THE INLET DOOR RELAY CIRCUIT.
48	ECU FAILED. THIS MINIFLAG INDICATES INTERNAL ECU FAILURES AND IS SET BY MINIFLAGS 3-6,21, 29-33,39,44,45,46,65,83-89,92-100,105,107,112,116-119,121-124 OR 128. IT CAN ALSO BE SET BY MINIFLAGS 36,37, OR 38.
65	ECU HI-WINS SPEED CIRCUIT FAILURE. INTERNAL ECU FAILURE WAS FOUND.
75	AIRPLANE MAINTENANCE LAMP CIRCUIT OVERCURRENT
76	AIRPLANE BLEED AIR RELAY OVERCURRENT
77	AIRPLANE GENERATOR AVAILABLE RELAY OVERCURRENT
78	AIRPLANE FAULT RELAY OVERCURRENT

ECU MINIFLAG DESCRIPTION TABLE C

APU BITE Procedure Figure 103 (Sheet 8)

49-11-00 config 1



80 81	LOP LAMP OVERCURRENT
81	HOT LAMB OVERGUIDENT
01	HOT LAMP OVERCURRENT
83	ECU LCIT CONDITIONER FAILED. INTERNAL ECU FAILURE WAS FOUND.
84	ECU DEOIL SOLENOID DRIVER FAILED OPEN. INTERNAL ECU FAILURE WAS FOUND.
86	ECU AIRPLANE BLEED RELAY OPEN. INTERNAL ECU FAILURE WAS FOUND.
89	ECU FUEL SOLENOID DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
92	ECU IGNITION UNIT DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
94	ECU BLEED AIR DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
95	ECU FLOW DIVIDER DRIVER OPEN. INTERNAL ECU FAILURE WAS FOUND.
97	ECU STARTER RELAY DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
99	ECU BLEED AIR DRIVER OPEN. INTERNAL ECU FAILURE WAS FOUND.
100	ECU BLEED AIR DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
102	FAILED FUEL D/A CONVERTER. INTERNAL ECU FAILURE WAS FOUND.
103	FAILED IGV D/A CONVERTER. INTERNAL ECU FAILURE WAS FOUND.
104	FAILED SCV D/A CONVERTER. INTERNAL ECU FAILURE WAS FOUND.
105	ECU IGV ACTUATOR DRIVER FAILED OPEN. INTERNAL ECU FAILURE WAS FOUND.
106	IGV ACTUATOR TORQUE MOTOR FAILED. THE IGV ACTUATOR TORQUE MOTOR IS FAILED OPEN OR SHORT CIRCUIT.
107	ECU SCV DRIVER FAILED OPEN. INTERNAL ECU FAILURE WAS FOUND.
109	FAILED FUEL TORQUE MOTOR DRIVER WRAP AROUND. INTERNAL ECU FAILURE WAS FOUND.
110	FAILED IGV ACTUATOR DRIVER WRAP AROUND. INTERNAL ECU FAILURE WAS FOUND.
111	FAILED SCV TORQUE MOTOR DRIVER WRAP AROUND. INTERNAL ECU FAILURE WAS FOUND.
112	ECU MAGNETIC RELAY FAILED. THE ECU MAGNETIC LATCH WAS FOUND FAILED DURING SHUTDOWN.
114	FAILED STOP TIMER (N > 7% 120 SECONDS AFTER STOP OR SHUTDOWN).
116	ECU FAILED +15V DC POWER SUPPLY. INTERNAL ECU FAILURE WAS FOUND.
117	ECU FAILED -10V DC POWER SUPPLY. INTERNAL ECU FAILURE WAS FOUND.
118	ECU FAILED -15V DC POWER SUPPLY. INTERNAL ECU FAILURE WAS FOUND.
119	ECU FAILED +5V DC POWER SUPPLY. INTERNAL ECU FAILURE WAS FOUND.
120	ECU PRESSURE REFERENCE POWER SUPPLY FAILED LOW. OV DC WAS FOUND ON THE REFERENCE POWER SUPPLY. THERE IS A POSSIBLE ECU FAILURE OR AN EXTERNAL SHORT.

ECU MINIFLAG DESCRIPTION TABLE C

APU BITE Procedure Figure 103 (Sheet 9)

EFFECTIVITY

AIRPLANES WITH THE APU

CONTROL UNIT -18 AND BEFORE

49-11-00

CONFIG 1 Page 111




NUMBER	DESCRIPTION
121	ECU +10V A/D CONVERTER POWER SUPPLY FAILED LOW. INTERNAL ECU FAILURE WAS FOUND.
122	ECU +10V A/D CONVERTER POWER SUPPLY FAILED HIGH. INTERNAL ECU FAILURE WAS FOUND.
123	ECU OV A/D CONVERTER REFERENCE FAILED LOW. INTERNAL ECU FAILURE WAS FOUND.
124	ECU OV A/D CONVERTER REFERENCE FAILED HIGH. INTERNAL ECU FAILURE WAS FOUND.
126	IGV ACTUATOR LVDT VOLTAGE OUT OF RANGE. THE IGV ACTUATOR LVDT VOLTAGE IS OUT OF ITS EXPECTED RANGE.
127	IGV ACTUATOR LVDT SECONDARY VOLTAGE OUT RANGE. THE IGV ACTUATOR LVDT SECONDARY VOLTAGE IS OUT OF ITS EXPECTED RANGE.
128	IGV ACTUATOR LVDT PRIMARY VOLTAGE OUT OF RANGE. THE IGV ACTUATOR LVDT PRIMARY VOLTAGE IS OUT OF ITS EXPECTED RANGE.
	APU CONTROL UNIT -18 AND BEFORE; THERE ARE NO DIAGNOSTIC MINIFLAGS THAT ARE ACTIVE DURING APU OPERATION.

ECU MINIFLAG DESCRIPTION TABLE C


APU BITE Procedure Figure 103 (Sheet 10)

49-11-00 config 1





MINIFLAG "128" (EXAMPLE OF A MINIFLAG DISPLAY ON ECU)



MINIFLAG "OK" (EXAMPLE OF A MINIFLAG DISPLAY ON ECU)

APU BITE Procedure Figure 103 (Sheet 11)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE

49-11-00

CONFIG Page 113 May 28/00




PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

APU STARTING PROBLEMS




WHEN YOU START THE APU, LOOK AT THE APU BATTERY VOLTAGE AND THE CURRENT ON THE EICAS "ELEC/HYD" DISPLAY. LOOK AT THE APU RPM AND THE EGT ON THE EICAS "PERF/APU" DISPLAY.

PUSH THE "ECS/MSG" SWITCH ON THE EICAS PANEL, P61, AND MAKE SURE "APU DOOR" MESSAGE DOES NOT

APU Starting Problems Figure 104 (Sheet 1)

49-11-00






APU Starting Problems Figure 104 (Sheet 2)

49-11-00

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.




APU Starting Problems Figure 104 (Sheet 3)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

49-11-00

02

CONFIG 1 Page 116 May 28/00




APU Starting Problems Figure 104 (Sheet 4)

EFFECTIVITY—
AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

49-11-00


01

CONFIG 1 Page 117 May 28/00



APU Starting Problems Figure 104 (Sheet 5)

49-11-00



BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

CONFIG

Page 119 May 28/00

01

CONTROL UNIT -18 AND BEFORE




PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3,6H12,6H23,11B34,11C33,11D32,11D34,APU CONT,
APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER,
E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

AUTO SHUTDOWN - "NO ACCEL" ON BITE



AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

IF TWO APU STARTER MOTORS ARE REPLACED IN LESS THAN 30 DAYS, REPLACE THE APU STARTER MOTOR, M893 (AMM 49-41-01/201), AND THE APU STARTER CLUTCH (AMM 49-41-06/201).


Auto Shutdown - NO ACCEL on BITE Figure 105 (Sheet 1)

49-11-00

01

CONFIG 1 Page 120 May 28/00






Auto Shutdown - NO ACCEL on BITE Figure 105 (Sheet 2)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

CONFIG 1
Page 121
May 28/00






Auto Shutdown - NO ACCEL on BITE Figure 105 (Sheet 3)

> Page 122 May 28/03

EFFECTIVITY-49-11-00 AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE CONFIG 01






Auto Shutdown - NO ACCEL on BITE Figure 105 (Sheet 4)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

CONFIG 1
Page 123
May 28/00

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.




Auto Shutdown - NO ACCEL on BITE Figure 105 (Sheet 5)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

CONFIG 1
Page 124
May 28/00





Auto Shutdown - NO ACCEL on BITE Figure 105 (Sheet 6)

EFFECTIVITY
AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

49-11-00 CONFIG 1

01

Page 125 Sep 28/01




PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,
APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER
E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

AUTO SHUTDOWN - "SLOW START" ON BITE 3>>



AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

2 IF TWO APU STARTER MOTORS ARE REPLACED IN LESS THAN 30 DAYS, REPLACE THE APU STARTER MOTOR, M893 (AMM 49-41-01/201), AND THE APU STARTER CLUTCH (AMM 49-41-06/201).

IF THE SLOW START CONTINUES, THE PROBLEM MAY BE AN APU LOW OUTPUT DEFECT. EXAMINE THE TRU FOR SIGNS THAT IT HAS BECOME TOO HOT.

Auto Shutdown - SLOW START on BITE Figure 106 (Sheet 1)


49-11-00

CONFIG


01

Page 126 May 28/00







Auto Shutdown - SLOW START on BITE Figure 106 (Sheet 2)



Auto Shutdown - SLOW START on BITE Figure 106 (Sheet 3)





Auto Shutdown - SLOW START on BITE Figure 106 (Sheet 4)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

CONFIG 1
Page 129
May 28/00




PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,APU
START,APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

FAULTY UNIT -"STARTER CIRCUIT" ON BITE CAUTION: MAKE SURE YOU OBEY THE STARTER DUTY CYCLE IN THE APU OPERATION LIMITS (AMM 49-11-00/201). IF YOU DO NOT OBEY THESE INSTRUCTIONS, YOU CAN CAUSE DAMAGE TO THE APU.



AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

IF TWO APU STARTER MOTORS ARE REPLACED IN LESS THAN 30 DAYS, REPLACE THE APU STARTER MOTOR, M893 (AMM 49-41-01/201), AND THE APU STARTER CLUTCH (AMM 49-41-06/201).


Faulty Unit - STARTER CIRCUIT on BITE Figure 106A (Sheet 1)

49-11-00

01

Page 130 May 28/00





Faulty Unit - STARTER CIRCUIT on BITE Figure 106A (Sheet 2)

EFFECTIVITY—
AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

CONFIG 1
Page 131
May 28/00

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.




PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

AUTO SHUTDOWN - "NO FLAME" ON BITE



AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.


Auto Shutdown - NO FLAME on BITE Figure 107 (Sheet 1)

49-11-00

CONFIG

01

Page 132 May 28/00




1 AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

> Auto Shutdown - NO FLAME on BITE Figure 107 (Sheet 2)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE

49-11-00

CONFIG



AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.


Auto Shutdown - NO FLAME on BITE Figure 107 (Sheet 3)

49-11-00

01

Page 134 May 28/00





AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER YOU CORRECT THE PROBLEM, PUSH THE "PERF/APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. HOLD THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS GONE.

Auto Shutdown - NO FLAME on BITE Figure 107 (Sheet 4)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

CONFIG 1
Page 135
Jan 28/05


PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

AUTO SHUTDOWN DURING GOVERNED SPEED -"REVERSE FLOW" ON BITE




1 AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

> Auto Shutdown During Governed Speed - REVERSE FLOW on BITE Figure 108 (Sheet 1)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE

CONFIG





Auto Shutdown During Governed Speed - REVERSE FLOW on BITE Figure 108 (Sheet 2)

49-11-00 config 1



PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,
APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER,
E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

NOTE: AIRPLANES WITH AN \$351T020-18 APU CONTROL UNIT (ECU);

THE "LOP" LIGHT ON THE ECU WILL FLASH WHEN AN "LOP" SHUTDOWN OCCURS ON THE THIRD TRY TO START THE APU WITH THE AIRPLANE ON THE GROUND. THE "LOP" LIGHT WILL ONLY FLASH IF THE ECU MEMORY WAS NOT ERASED AFTER THE FIRST TWO "LOP" SHUTDOWNS.

AIRPLANES WITH A -18 APU CONTROL UNIT WITH AIRESEARCH SB 2117342-49-2195; IF THE APU IS INITIALLY STARTED WITH LOW OIL PRESSURE, THE APU WILL SHUTDOWN 15.5 SECONDS AFTER IT GETS TO 95% RPM (OR ONE SECOND IF THE APU OIL TEMPERATURE IS GREATER THAN 20°F). THE SUBSEQUENT START WITH LOW OIL PRESSURE WILL CAUSE A SHUTDOWN ONE SECOND AFTER THE APU GETS TO 95% RPM. THE APU WILL THEN NOT START IF THERE IS LOW OIL PRESSURE.

> AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

Auto Shutdown - LOP on BITE Figure 109 (Sheet 1)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

49-11-00


CONFIG

05

Page 138 May 28/00



AUTO SHUTDOWN - "LOP" ON BITE




AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

Auto Shutdown - LOP on BITE Figure 109 (Sheet 2)

49-11-00

08

CONFIG 1 Page 139 May 28/00



AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

Auto Shutdown - LOP on BITE Figure 109 (Sheet 3)

49-11-00

05

CONFIG 1 Page 140 May 28/00 FROM SHEET 3 (BLOCK 15)

N0 29 THERE IS A PERFORMANCE 16 IT IS POSSIBLE THAT THERE PROBLEM IN THE OIL SYSTEM. IS OIL FILTER BLOCKAGE. REPLACE THE APU OIL PUMP EXAMINE THE OIL PRESSURE FILTER AND THE GENERATOR (AMM 49-27-01/401). 1> SCAVENGE FILTER FOR CONTAMIN-NOTE: IF THE DRIVE SHAFT FOR ATION (AMM 49-27-03/201)(IF THE OIL PUMP IS BROKEN, YOU DID NOT EXAMINE IT MAKE SURE YOU REMOVE IT BEFORE). 1> FROM THE DRIVE GEAR. IF THE PROBLEM CONTINUES, CONNECT A PRESSURE GAGE IF THE PROBLEM CONTINUES, REMOVE THE DE-OIL SOLENOID (0-150 PSIG) TO THE OIL PRES-SURE TEST PORT (SEE SHEET 5). VALVE (AMM 49-27-08/401) TO SEE IF IT IS STUCK OPEN. 1 START THE APU (AMM 49-11-00/201). OPERATE IF THE PROBLEM CONTINUES, EXAMINE THE OIL COOLER, THE THE APU IN THE ECS MODE. IS THE OIL PRESSURE LINES AND THE CHECK VALVES FOR BLOCKAGE. 1> GREATER THAN 40 PSIG? IF THE PROBLEM CONTINUES, THE APU HAS AN INTERNAL LEAK. REPLACE THE APU (AMM 49-11-01/401). 30 | IT IS POSSIBLE THAT THERE 17 IS THE OIL PRESSURE LESS THAN 60 PSI? IS A PERFORMANCE PROBLEM IN THE OIL SYSTEM. REPLACE THE NO APU OIL PUMP (AMM 49-27-01/ 401). 1 18 THERE IS AN INDICATION NOTE: IF THE DRIVE SHAFT FOR PROBLEM. IT IS POSSIBLE THAT THE OIL PUMP IS BROKEN, THERE IS A CALIBRATION SHIFT MAKE SURE YOU REMOVE IT IN THE OIL PRESSURE (LOP) FROM THE DRIVE GEAR. SWITCH. REPLACE THE OIL PRESSURE (LOP) SWITCH, YBMS2 IF THE PROBLEM CONTINUES, (AMM 49-94-02/201). 1> REMOVE THE DE-OIL SOLENOID IF THE PROBLEM CONTINUES, VALVE (AMM 49-27-08/401) TO SEE IF IT IS STUCK OPEN. 1> EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796B, PIN C5, IF THE PROBLEM CONTINUES, EXAMINE THE OIL COOLER, THE TO THE LOW OIL PRESSURE SWITCH, YBMS2, CONNECTOR P6, LINES AND THE CHECK VALVES FOR PIN 1 (GROUND, PIN 2) BLOCKAGE. 1> IF THE PROBLEM CONTINUES, (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND. $\fbox{1}$ THE APU HAS AN INTERNAL LEAK. REPLACE THE APU (AMM 49-11-01/ IF THE PROBLEM CONTINUES, 401). 1> REPLACE THE ECU, M206 IF THE PROBLEM CONTINUES, (AMM 49-61-05/201). 1> THERE IS AN INDICATION PROBLEM. EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796B, PIN C5 TO THE LOW OIL PRESSURESWITCH, YBMS2, CONNEC-TOR P6, PIN 1 (GROUND, PIN 2) (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND. 1

Auto Shutdown - LOP on BITE Figure 109 (Sheet 4)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

49-11-00


IF THE PROBLEM CONTINUES,


REPLACE THE ECU, M206 (AMM 49-61-05/201). 1

06

CONFIG 1 Page 141 May 28/00







Auto Shutdown - LOP on BITE Figure 109 (Sheet 5)

49-11-00

09


Page 142 May 28/00



MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

AUTO SHUTDOWN -"HOT" ON BITE

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)




1 AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

> Auto Shutdown - HOT on BITE Figure 110 (Sheet 1)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE

49-11-00 CONFIG Page 143



AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.


Auto Shutdown - HOT on BITE Figure 110 (Sheet 2)

49-11-00

07

CONFIG 1 Page 144 May 28/00





AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

Auto Shutdown - HOT on BITE Figure 110 (Sheet 3)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

CONFIG 1

Page 145


May 28/00



AUTO SHUTDOWN - "OVER SPEED" ON BITE

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

Auto Shutdown - OVER SPEED on BITE Figure 111


AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

CONFIG 1

Page 146

May 28/00





AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

Auto Shutdown - GEN FILTER on BITE Figure 112

49-11-00

07

CONFIG 1 Page 147 May 28/00




MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,
APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER,
F6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

AUTO SHUTDOWN - "OVER TEMP" ON BITE

NOTE: IF THE APU HAS A START PROBLEM ("NO FLAME", "SLOW START", OR "NO ACCEL") AND THE AUTOMATIC SHUTDOWN "OVER TEMP", THERE IS A DEFECT IN THE FLOW DIVIDER OR THE PRIMARY FUEL NOZZLE.



AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.


Auto Shutdown - OVER TEMP on BITE Figure 113 (Sheet 1)

49-11-00

CONFIG

80

Page 148 May 28/00




Auto Shutdown - OVER TEMP on BITE Figure 113 (Sheet 2)

EFFECTIVITY

AIRPLANES WITH THE APU

CONTROL UNIT -18 AND BEFORE

49-11-00 CONFIG 1 Page 149



Auto Shutdown - OVER TEMP on BITE Figure 113 (Sheet 3)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE

M38841

49-11-00 CONFIG

Page 150


Jan 28/02



AUTO SHUTDOWN - "FAILED SENSOR" ON BITE

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

Auto Shutdown - FAILED SENSOR on BITE Figure 114

EFFECTIVITY

AIRPLANES WITH THE APU

CONTROL UNIT -18 AND BEFORE

49-11-00


CONFIG 1

Page 151

06

Page 151 Jan 28/02





High Oil Consumption Figure 115

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.



PREREQUISITES MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201) MAKE SURE THIS CIRCUIT BREAKER IS CLOSED: 11A33 EICAS MSG "APU OIL MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: QTY" DISPLAYED ELECTRICAL POWER IS ON (AMM 24-22-00/201) NO 1 START THE APU 20 | THE SYSTEM IS OK. DO THE APU SHUTDOWN PROCE-(AMM 49-11-00/201.OPERATE THE APU FOR 5 MIN-DURE (AMM 49-11-00/201). UTES. DO THIS PROCEDURE: MAINTENANCE MESSAGE ERASE PRO-CEDURE (FIM 31-41-00/101, FIG. 109). DOES THE "APU OIL QTY" MESSAGE SHOW IMMEDIATELY? YES NO 2 DO THE APU SHUTDOWN PROCE-10 1>; 21 REPLACE THE OIL LEVEL SWITCH, YBMS3 (AMM 49-94-03/ 201). GO TO BLOCK 21. DURE (AMM 49-11-00/201). REMOVE FILL CAP AND CHECK OIL LEVEL IN RESERVOIR BY ADD-REMOVE THE CONNECTOR FROM REPLACE THE OIL QUANTITY ING APPROVED OIL UNTIL IT IS THE OIL QUANTITY TRANSMITTER, TRANSMITTER, YBMS3 FULL (OVERFLOWS)(AMM 12-13-04/ (AMM 49-94-04/201). 2 YBMS3. CLEAN THE CONNECTOR

AND THE TRANSMITTER. REMOVE

ALL CONTAMINATION SUCH AS OIL

OR GREASE. REPLACE THE CON-

NECTOR ON THE TRANSMITTER.

OPERATE THE APU FOR

5 MINUTES. DO THIS PROCEDURE:

MAINTENANCE MESSAGE ERASE PRO-CEDURE (FIM 31-41-00/101,

DOES THE "APU OIL QTY" MESSAGE SHOW IMMEDIATELY?

START THE APU (AMM 49-11-00/201).

FIG. 109).

.

GUI 115

> GUI 001-114,116-999

DID THE APU NEED MORE THAN

YES

SEE SHEET 2

(BLOCK 3)

2 QUARTS OF OIL TO BE FULL?

301).

EICAS Msg APU OIL QTY Displayed Figure 116 (Sheet 1)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

49-11-00

DO THIS PROCEDURE: MAIN-

TENANCE MESSAGE ERASE PROCE-


DURE (FIM 31-41-00/101,

21A THE SYSTEM IS OK.

DURE (AMM 49-11-00/201).

DO THE APU SHUTDOWN PROCE-

FIG. 109).



EICAS Msg APU OIL QTY Displayed Figure 116 (Sheet 2)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE

CONFIG

06 Page 154



APU WILL NOT CARRY PNEUMATIC AND **ELECTRICAL LOAD** ASSOCIATED WITH RPM DROOP

PREREQUISITES	
NONE	

REPLACE THE P2 SENSOR (AMM 49-61-04/201). IF THE PROBLEM CONTINUES, REPLACE THE ECU, M206 (AMM 49-61-05/201). IF THE PROBLEM CONTINUES, REPLACE THE FUEL CONTROL UNIT, YBMM4 (AMM 49-31-01/401). IF THE PROBLEM CONTINUES, REPLACE THE FUEL FLOW DIVIDER (AMM 49-31-02/401). IF THE PROBLEM CONTINUES, REPLACE THE SECONDARY FUEL MANIFOLDS AND NOZZLES (AMM 49-31-06/401).

APU Will Not Carry Pneumatic and Electrical Load Associated with RPM Droop Figure 117

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE




MAKE SURE THIS SYSTEM WILL OPERATE: APU START NORMAL

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

NO DUCT PRESSURE IN ANY MODE (0-2 PSIG)


MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



No Duct Pressure in Any Mode (0-2 PSIG) Figure 118 (Sheet 1)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE CONFIG






No Duct Pressure in Any Mode (0-2 PSIG) Figure 118 (Sheet 2)

EFFECTIVITY

AIRPLANES WITH THE APU

CONTROL UNIT -18 AND BEFORE

49-11-00 CONFIG 1 Page 157




No Duct Pressure in Any Mode (0-2 PSIG) Figure 118 (Sheet 3)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE

CONFIG Page 158 Jan 28/05





No Duct Pressure in Any Mode (0-2 PSIG) Figure 118 (Sheet 4)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE

CONFIG Page 159 Sep 28/03



MAKE SURE THESE SYSTEMS WILL OPERATE: EICAS (AMM 31-41-00/201) APU START NORMAL

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35, APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

FLUCTUATING DUCT PRESSURE

NOTE: IF YOU LOSE ELECTRICAL POWER WHEN YOU TRANSFER FROM ONE GENERATOR TO ANOTHER, THE DUCT PRESSURE WILL MOMENTARILY BE IRREGULAR.




Fluctuating Duct Pressure Figure 119 (Sheet 1)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

49-11-00






Fluctuating Duct Pressure Figure 119 (Sheet 2)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE


CONFIG Page 161 Jan 28/02



Fluctuating Duct Pressure Figure 119 (Sheet 3)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE 07 Jan 28/02

CONFIG Page 162




Fluctuating Duct Pressure Figure 119 (Sheet 4)

EFFECTIVITY

AIRPLANES WITH THE APU

CONTROL UNIT -18 AND BEFORE

49-11-00



Fluctuating Duct Pressure Figure 119 (Sheet 5)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

49-11-00 CONFIG 1

80

Page 164 Jan 28/02




MAKE SURE THIS SYSTEM WILL OPERATE:
APU START NORMAL (AMM 49-11-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35, APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)


LOW DUCT PRESSURE



Low Duct Pressure Figure 120 (Sheet 1)

49–11–00





Low Duct Pressure Figure 120 (Sheet 2)

49-11-00 CONFIG 1 Page 166

Sep 28/03

09



Not Used Figure 120A

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE

07

CONFIG Page 167 Sep 28/03



MAKE SURE THIS SYSTEM WILL OPERATE:
APU START NORMAL (AMM 49-11-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35, APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

LOW DUCT PRESSURE IN DUCT PRESSURIZATION MODE (3-25 PSIG)

1 DOES THE SURGE CONTROL 11 DO A CHECK OF THE PRESSURE 21 REMOVE THE BLOCKAGE OF VALVE HAVE A PRESSURE SUPPLY SUPPLY TUBE FOR THE SURGE MOISTURE, ICE OR UNWANTED TUBE WITH A 0.030 INCH CONTROL VALVE FOR BLOCKAGE OF MATERIALS AND/OR REPAIR THE (0.76 mm) DRAIN HOLE MOISTURE, ICE OR UNWANTED PROBLEMS THAT YOU FIND. (HONEYWELL POST-SB MATERIALS AND DAMAGE THAT CAN GTCP331-49-7496 OR HONEYWELL CAUSE A DECREASE IN AIRFLOW. POST-SB GTCP331-49-7707)? IS THERE BLOCKAGE OF 22 THE PRESSURE SUPPLY TUBE MOISTURE, ICE OR UNWANTED FOR THE SURGE CONTROL VALVE IS MATERIALS OR DAMAGE TO THE OK. PRESSURE SUPPLY TUBE? GO TO BLOCK 2. YES START THE APU 23 THERE IS A LEAK IN A (AMM 49-11-00/201). DOWNSTREAM SOURCE. PUSH THE TWO BLEED AIR EXAMINE ALL DUCTS AND L (R) ENG SWITCHES ON THE P5 CLAMPS TO MAKE SURE THERE ARE PANEL TO THE "OFF" POSITION. NO PROBLEMS. LOOK AT THE POSITION PUSH THE BLEED AIR ISOLATION VALVE SWITCH TO THE INDICATORS ON THE LEFT AND OPEN POSITION. RIGHT FLOW CONTROL VALVES. PUSH THE BLEED AIR APU MAKE SURE THE TWO CONTROL VALVE SWITCH TO THE OPEN VALVES ARE FULLY CLOSED. POSITION. SELECT THE LEFT AND RIGHT ECS PACKS ON. LOOK AT THE POSITION INDICATOR ON THE SURGE CONTROL VALVE ON THE APU. IS THE VALVE IN THE CLOSED OR APPROXIMATE CLOSED POSITION? NO SEE SHEET 2 (BLOCK 3)

Low Duct Pressure in Duct Pressurization Mode (3-25 PSIG) Figure 120B (Sheet 1)

EFFECTIVITY

AIRPLANES WITH THE APU

CONTROL UNIT -18 AND BEFORE

49-11-00

07

CONFIG 1 Page 168 Sep 28/03

FROM SHEET 1 (BLOCK 2) YES THERE MAY BE A PROBLEM 24 THERE IS A SURGE CONTROL WITH THE CONTROL AIR PRESSURE VALVE PROBLEM. FOR THE SURGE VALVE. SHUTDOWN THE APU PUSH THE LEFT AND RIGHT (AMM 49-11-00/201). ECS PACKS "OFF". REPLACE THE SURGE CONTROL VALVE (AMM 49-53-01/401). CAUTION: THERE IS HOT AIR NEAR THE SURGE VALVE. FEEL FOR AIR LEAKS AT THE QUICK DUMP FOR THE SURGE VALVE. NO 25 DO THE APU SHUTDOWN ARE THERE AIR LEAKS? PROCEDURE (AMM 49-11-00/201). APUS WITH THE FAN ISOLATION VALVE CONNECTED TO THE FIRST STAGE COMPRESSOR; EXAMINE THE PLUMBING AND CONNECTIONS FOR PCD2 CONTROL PRESSURE FROM THE HEAT SHIELD TO THE SCV. TIGHTEN THE CONNECTIONS OR REPLACE THE TUBES OR COMPONENTS IF PROBLEMS OR LEAKS ARE FOUND. APUS WITH THE FAN ISOLATION VALVE CONNECTED TO THE SURGE VALVE; EXAMINE THE PLUMBING AND CONNECTIONS FOR THESE SCV CONTROL PRESSURES: PCD2 FROM HEAT SHIELD TO SCV, AND COOLING FAN ISOLATION VALVE MUSCLE AIR AT BOTH ENDS. EXAMINE THE DIAPHRAGM VENT ON THE FAN ISOLATION VALVE FOR AIR LEAKAGE (DAMAGED DIAPHRAGM). TIGHTEN THE CONNECTIONS OR REPLACE THE TUBES OR COMPONENTS IF PROBLEMS OR LEAKS ARE FOUND.

Low Duct Pressure in Duct Pressurization Mode (3-25 PSIG) Figure 120B (Sheet 2)

49-11-00

CONFIG


07

Page 169 Sep 28/03

MAKE SURE THIS SYSTEM WILL OPERATE:
APU START NORMAL (AMM 49-11-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35, APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



Low Duct Pressure in All Operational Modes: ECS, MES and Duct Pressurization Figure 120C (Sheet 1)

EFFECTIVITY

AIRPLANES WITH THE APU

CONTROL UNIT -18 AND BEFORE

LOW DUCT PRESSURE

MODES:


AND DUCT

IN ALL OPERATIONAL

ECS, MES

49-11-00






Low Duct Pressure in All Operational Modes: ECS, MES and Duct Pressurization Figure 120C (Sheet 2)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE


49-11-00 CONFIG Page 171 Sep 28/03



Low Duct Pressure in All Operational Modes: ECS, MES and Duct Pressurization Figure 120C (Sheet 3)

49-11-00 CONFIG 1 Page 172 Sep 28/03

07



Low Duct Pressure in All Operational Modes: ECS, MES and Duct Pressurization Figure 120C (Sheet 4)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -18 AND BEFORE

CONFIG

FROM SHEET 4 (BLOCK 18)

NO

YES

19 EXAMINE FOR CONTROL PRES-SURE LEAKAGE AT THE SURGE CONTROL VALVE.

APUS WITH THE FAN
ISOLATION VALVE CONNECTED TO
THE FIRST STAGE COMPRESSOR;
LOOK AT THE CONNECTIONS TO THE
PCD.

ARE THERE POSSIBLE LEAKS?
APUS WITH THE FAN
ISOLATION VALVE CONNECTED TO
THE SURGE VALVE;
LOOK AT THE CONNECTIONS TO THE
PCD AND THE FAN ISOLATION
VALVE.

ARE THERE POSSIBLE LEAKS?

NO

52 APUS WITH THE FAN
ISOLATION VALVE CONNECTED TO
THE FIRST STAGE COMPRESSOR;
EXAMINE THE PLUMBING AND
CONNECTIONS FOR PCD2 CONTROL
PRESSURE FROM THE HEAT SHIELD
TO THE SCV.

TIGHTEN THE CONNECTIONS OR REPLACE THE TUBES OR COMPONENTS IF PROBLEMS OR LEAKS ARE FOUND.

APUS WITH THE FAN
ISOLATION VALVE CONNECTED TO
THE SURGE VALVE;
EXAMINE THE PLUMBING AND
CONNECTIONS FOR THESE SCV
CONTROL PRESSURES: PCD2 FROM
HEAT SHIELD TO SCV, AND FAN
ISOLATION VALVE MUSCLE AIR AT
BOTH ENDS.

EXAMINE THE DIAPHRAGM VENT ON THE FAN ISOLATION VALVE FOR AIR LEAKAGE (DAMAGED DIAPHRAGM).

TIGHTEN THE CONNECTIONS
OR REPLACE THE TUBES OR
COMPONENTS IF PROBLEMS OR
LEAKS ARE FOUND.

MODULE (AMM 49-53-08/401).

IF THE PROBLEM CONTINUES,
REPLACE THE SURGE VALVE,
YBMM5 (AMM 49-53-01/401).

IF THE PROBLEM CONTINUES,

EXAMINE ALL DUCTS, CLAMPS, APU CHECK VALVE, FOR LEAKS AND DISCONNECTED FITTINGS, AND THE APU SURGE VALVE FILTER ELEMENT FOR CORRECT INSTALL— ATION.

Low Duct Pressure in All Operational Modes: ECS, MES and Duct Pressurization Figure 120C (Sheet 5)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

49-11-00

CONFIG

10

Page 174 Sep 28/03



MAKE SURE THIS SYSTEM WILL OPERATE: APU START NORMAL (AMM 49-11-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35,
APU CONT, APU START, APU INLET DR ACT
(AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)


LOW DUCT PRESSURE DURING ONE OR TWO ECS PACK OPERATION ONLY

DOES THE SURGE CONTROL 11 DO A CHECK OF THE PRESSURE 21 REMOVE THE BLOCKAGE OF VALVE HAVE A PRESSURE SUPPLY SUPPLY TUBE FOR THE SURGE MOISTURE, ICE OR UNWANTED TUBE WITH A 0.030 INCH CONTROL VALVE FOR BLOCKAGE OF MATERIALS AND/OR REPAIR THE (0.76 mm) DRAIN HOLE MOISTURE, ICE OR UNWANTED PROBLEMS THAT YOU FIND. (HONEYWELL POST-SB MATERIALS AND DAMAGE THAT CAN GTCP331-49-7496 OR HONEYWELL CAUSE A DECREASE IN AIRFLOW. POST-SB GTCP331-49-7707)? IS THERE BLOCKAGE OF 22 THE PRESSURE SUPPLY TUBE MOISTURE, ICE OR UNWANTED FOR THE SURGE CONTROL VALVE IS MATERIALS OR DAMAGE TO THE PRESSURE SUPPLY TUBE? GO TO BLOCK 2. NO START THE APU 23 A PROBLEM EXISTS WITH (AMM 49-11-00/201). EITHER THE ZONE TEMPERATURE PUSH THE TWO BLEED AIR CONTROLLER OR THE TEMPERATURE L (R) ENG SWITCHES ON THE P5 CONTROL AIR VALVE. PANEL TO THE "OFF" POSITION. REMOVE PNEUMATIC PRESSURE PUSH THE ISOLATION VALVE FROM THE SYSTEM. DO THIS PROCEDURE: ZONE TO THE OPEN POSITION. PUSH THE THE TRIM AIR TEMPERATURE CONTROL BITE SWITCH TO THE "OFF" POSITION. PROCEDURE (FIM 21-60-00/101, SET THE L PACK TO STBY "C" FIG. 104). AND WRITE THE PRESSURE FROM THE EICAS ECS PAGE. SET THE L PACK TO STBY ''W''. ARE THE DUCT PRESSURES UNDER THE TWO CONDITIONS WITHIN 2 PSI? YES SEE SHEET 2 (BLOCK 3)

Low Duct Pressure During One or Two ECS Pack Operation Only Figure 120D (Sheet 1)

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

49-11-00



Low Duct Pressure During One or Two ECS Pack Operation Only Figure 120D (Sheet 2)

49-11-UL CONFIG 1 Page 176 Sep 28/03

09



MAKE SURE THIS SYSTEM WILL OPERATE:
APU START NORMAL (AMM 49-11-00/201)


MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35, APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

LOW DUCT PRESSURE

IN "MES" MODE ONLY

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:


ELECTRICAL POWER IS ON (AMM 24-22-00/201)



Low Duct Pressure in MES Mode Only Figure 120E (Sheet 1)

49-11-00






Low Duct Pressure in MES Mode Only Figure 120E (Sheet 2)

49-11-00

07 Page 178 Sep 28/03





Fluids Coming from Drain Mast Figure 121

AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE


CONFIG 1

08 Page 179
Sep 28/03



FUMES AND/OR SMOKE IN THE CABIN

PREREQUISITES
NONE



Fumes and/or Smoke in the Cabin Figure 122

EFFECTIVITY
AIRPLANES WITH THE APU
CONTROL UNIT -18 AND BEFORE

49-11-00



AUXILIARY POWER UNIT

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
AUXILIARY POWER UNIT		1	316AR,315AL, APU COMPT	49-11-01

Auxiliary Power Unit - Component Index Figure 101


AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT


49-11-00 config 2

01

Page 101 Sep 20/94







AUXILIARY POWER UNIT

Auxiliary Power Unit - Component Location Figure 102

AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

49-11-UC CONFIG 2 Page 102

Sep 20/94



MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

APU BITE PROCEDURE

MOVE THE TEST SWITCH ON THE APU CONTROL UNIT (ECU), M206, IN THE AFT EQUIPMENT CENTER TO "LAMP TEST".

DO ALL LIGHTS IN THE FIVE COLUMNS OF INDICATORS COME ON, COLUMN BY COLUMN, FROM LEFT TO RIGHT?

THE MINIFLAG SUMMARY WILL SHOW IMMEDIATELY AFTER THE LAST COLUMN OF INDICATOR LIGHTS GO OUT IN THE LAMP TEST.

TURN YOUR HEAD CLOCKWISE 90 DEGREES TO READ THE MINIFLAG NUMBERS.

WRITE ALL OF THE MINIFLAGS THAT SHOW.

NOTE: THE LAMPS THAT COME ON AFTER THE MINIFLAGS ARE USED BY THE APU MANUFACTURER ONLY.

> YES SEE SHEET 2 (BLOCK 2)


21 IF ONE OR MORE LIGHTS DO NOT COME ON, COMPLETE THE BITE PROCEDURE (FIG. 103, BLOCK 2) TO GET THE HISTORY DATA, THEN REPLACE THE ECU, M206 (AMM 49-61-05/201).

IF NONE OF THE LIGHTS COME ON, EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796C, PIN 9 (GND, PIN 11), TO CIRCUIT BREAKERS "APU ALTN CONT" (11B34) AND "APU CONT" ON THE E6 RACK (WDM 49-61-11). REPAIR THE PROBLEMS THAT YOU FIND.

MAKE SURE THE APU CONTROL UNIT, CONNECTOR D1796B, PIN A5, IS NOT GROUNDED (WDM 49-61-11).

APU BITE Procedure Figure 103 (Sheet 1)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT




APU BITE Procedure Figure 103 (Sheet 2)

49-11-00

01

CONFIG 2 Page 104 May 28/04





MESSAGE	CORRECTIVE ACTION	IF THE PROBLEM CONTINUES
INLET DOOR RLY LCIT SENSOR	FIG. 132 REPLACE THE LCIT SENSOR, YBMTS5 (AMM 49-61-03/401). 1	EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796B, PINS E6 AND E7, TO THE INLET TEMPERATURE SENSOR (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
FUEL SOL PT SENSOR AP SENSOR #1 SPD SENSOR #2 SPD SENSOR	FIG. 123 FIG. 124 FIG. 125 FIG. 136	NEL YEAR THE TROSELING THAT THE TENER
LOP SWITCH	REPLACE THE LOP SWITCH, YBMS2 (AMM 49-94-02/401).	MAKE SURE THE ECU, CONNECTOR D1796B, PIN C5, IS NOT GROUNDED. 2 REPAIR THE PROBLEMS THAT YOU FIND.
FUEL CONTROL	FIG. 126	

FAULTY LRU - REFERENCE TABLE A

1 ERASE THE "APU BITE" MESSAGE ON EICAS IF IT SHOWS (FIM 31-41-00/101, FIG. 109).

DO THE SELF-TEST (FIG. 103, BLOCK 3) TO MAKE SURE THE PROBLEM IS REPAIRED.

3 OPERATE THE APU (AMM 49-11-00/201) AND DO THE APU BITE PROCEDURE (FIG. 103) AGAIN TO MAKE SURE THE PROBLEM IS REPAIRED.

APU BITE Procedure Figure 103 (Sheet 3)

49–11–00



MESSAGE	CORRECTIVE ACTION	IF THE PROBLEM CONTINUES
SURGE VALVE	REPLACE THE SURGE VALVE, YBMM5 (AMM 49-53-01/401).	EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796B, PINS G6 AND G7, TO THE TORQUE MOTOR CONNECTOR, PINS 1 AND 2 (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
EGT #1 CIRCUIT	FIG. 134	
EGT #2 CIRCUIT	FIG. 135	
IGV ACT	FIG. 127	
IGN UNIT	FIG. 128	
DEOIL SOL	REPLACE THE DEOIL SOLENOID VALVE, YBMM3 (AMM 49-27-08/401). 1	EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796B, PINS J4 AND J5, TO THE SOLENOID CONNECTOR, PINS 1 AND 2. EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796B, PIN J10, TO THE OIL TEMP SWITCH, YBMS5, CONNECTOR, PIN 1 (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
FLOW DIV SOL	REPLACE THE FUEL FLOW DIVIDER SOLENOID VALVE, YBMM2 (AMM 49-31-03/401).	EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796B, PINS J7 AND J8, TO THE SOLENOID CONNECTOR, PINS 1 AND 2 (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
ECS CONTROL	REPLACE THE ZONE TEMPERATURE CONTROL, M195 (AMM 21-61-03/401).	EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796B, PINS D8 AND D9, TO THE ZONE TEMPERATURE CONTROL, M195, CONNECTOR D2558B, PINS C1 AND C2 (WDM 21-61-51). REPAIR THE PROBLEMS THAT YOU FIND.
APU STARTER	IF #1 SPD SENSOR AND #2 SPD SENSOR LIGHTS COME ON, DO THE CORRECTIVE ACTION FOR THEM. IF #1 SPD SENSOR AND #2 SPD SENSOR LIGHTS DO NOT COME ON, GO TO FIG. 129.	
A/C STRT CIRCUIT	FIG. 106A	

FAULTY LRU - REFERENCE TABLE A

APU BITE Procedure Figure 103 (Sheet 4)

49-11-00 CONFIG 2 Page 106

Sep 20/98

01



MESSAGE	CORRECTIVE ACTION	IF THE PROBLEM CONTINUES
HOT SENSOR	REPLACE THE OIL TEMPERATURE (HOT) SENSOR, YBMTS1 (AMM 49-94-01/401).	EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796B, PINS E4 AND E5, TO THE HOT SENSOR CONNECTOR, PINS A AND B (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
P2 SENSOR ECU FAN VALVE	FIG. 130 FIG. 131 APU WITHOUT THE FAN ISOLATION VALVE (POST-ALLIEDSIGNAL-SB 49-7391); IGNORE THIS MESSAGE, IT IS A NUISANCE MESSAGE. APU WITH THE FAN ISOLATION VALVE (PRE-ALLIEDSIGNAL-SB 49-7391); REPLACE THE FAN ISOLATION VALVE, YBMS4 (AMM 49-51-02/401). 2	APU WITH THE FAN ISOLATION VALVE CONNECTED TO THE FIRST-STAGE COMPRESSOR (PRE-ALLIEDSIGNAL SB-49-7391, POST-ALLIEDSIGNAL SB-49-7192); EXAMINE THE CONDITION OF THE LINE FROM THE FAN ISOLATION VALVE TO THE FIRST STAGE COMPRESSOR. REPAIR THE LINE IF IT IS NECESSARY. 1 2 APU WITH THE FAN ISOLATION VALVE CONNECTED TO THE SURGE VALVE (PRE-ALLIEDSIGNAL-SB 49-7391, PRE-ALLIEDSIGNAL-SB 49-7192); EXAMINE THE CONDITION OF THE LINE FROM THE FAN ISOLATION VALVE TO THE SURGE VALVE. REPAIR THE LINE IF IT IS NECESSARY. 1 IF THE PROBLEM CONTINUES, REPLACE THE SURGE CONTROL VALVE FILTER (AMM 49-53-06/201). EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D408B, PIN B10, TO THE FAN VALVE SWITCH CONNECTOR, PIN 1. EXAMINE THE CIRCUIT FROM THE SWITCH CONNECTOR, PIN 2, TO GROUND (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND. IF THERE WAS A HEAT PROBLEM, EXAMINE
		THE FAN INLET DUCT FOR DAMAGE. REPAIR THE PROBLEMS THAT YOU FIND.
FILTER SW (GEN)	REPLACE THE GENERATOR ΔP SWITCH, YBMS1 (AMM 49-27-15/401). 1 2	EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796B, PIN D11, TO THE FILTER SWITCH CONNECTOR, PIN 1. EXAMINE THE CIRCUIT FROM THE SWITCH CONNECTOR, PIN 2, TO GROUND (WDM 49-14-11). REPAIR THE PROBLEMS THAT YOU FIND.
SEE MNT MANUAL	SEE TABLE B	

FAULTY LRU - REFERENCE TABLE A

APU BITE Procedure Figure 103 (Sheet 5)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

CONFIG



MESSAGE	CORRECTIVE ACTION FOR THE "SEE MNT MANUAL" FAULTY LRU MESSAGE OR "NO DATA" STATUS MESSAGE
NORMAL STOP SIG CONTROL FAILURE UNDER SPEED START ABORTED NO LIGHT OFF REVERSE FLOW EGT OVERTEMP	FIG. 133 REPLACE THE ECU, M206 (AMM 49-61-05/201). FIG. 106 FIG. 105 FIG. 107 FIG. 108 FIG. 113
DC PWR LOSS LOW OIL PRESSURE GEN FILTER DOOR SYSTEM	FIG. 138 FIG. 109 FIG. 112 FIG. 104, BLOCK 23
FIRE EMERG	LOOK AT THE AIRPLANE LOG BOOK AND THE APU COMPARTMENT FOR SIGNS OF A REPORTED FIRE. IF FIRE DAMAGE SHOWS, REPAIR OR REPLACE THE DAMAGED COMPONENTS. MAKE SURE THAT THE APU CONTROL SWITCH ON THE P5 PANEL IS "OFF" AND MOVE THE MAIN BATTERY SWITCH ON THE P5 PANEL "ON" THEN "OFF. IF THERE IS NO LOG BOOK REPORT OR SIGNS OF FIRE DAMAGE, DO THE BITE PROCEDURE FOR THE APU FIRE DETECTION SYSTEM (FIM 26-15-00/101, FIG. 103). IF THE PROBLEM CONTINUES, REPLACE THE EXTERNAL SHUTDOWN RELAY, K421 (WDM 26-15-11).
O/S TEST CIRCUIT	REPLACE THE ECU, M206 (AMM 49-61-05/201). IF THE PROBLEM CONTINUES AND "FUEL SOL" COMES ON, REPLACE THE FUEL SOLENOID VALVE, YBMV1 (AMM 49-31-02/401).
HIGH OIL TEMP OVER SPEED	FIG. 110 FIG. 111

REASON APU NOT OPERATING - REFERENCE TABLE B

APU BITE Procedure Figure 103 (Sheet 6)

49-11-00 CONFIG 2



NOTE: THE MINIFLAGS ARE FOR INFORMATION ONLY. DO NOT USE THE MINIFLAG DATA AS AN ALTERNATIVE TO THE FAULT ISOLATION PROCEDURES.

NUMBER	DESCRIPTION
1	SPEED SIGNAL NO. 1 IS NOT FUNCTIONING. THE SPEED SENSOR NO. 1 OR WIRING IS NOT PROVIDING PROPER INPUT AT SPEEDS GREATER THAN 50%.
2	SPEED SIGNAL NO. 2 IS NOT FUNCTIONING. THE SPEED SENSOR NO. 2 OR WIRING IS NOT PROVIDING PROPER INPUT AT SPEEDS GREATER THAN 50%.
3	ECU SPEED CONVERTER CIRCUIT IS FAILED. THE ECU SPEED CONVERTER CIRCUIT DOES NOT INTERPRET THE SPEED SIGNAL PROPERLY WHEN THE APU IS OPERATING AT SPEEDS GREATER THAN 50%.
4	FAILED ECU N/DC CONVERTER NO. 1 CIRCUIT. THE ECU CIRCUIT THAT CONVERTS THE NO. 1 SPEED SIGNAL TO A DC VOLTAGE IS NOT FUNCTIONING PROPERLY.
5	FAILED ECU N/DC CONVERTER NO. 2 CIRCUIT. THE ECU CIRCUIT THAT CONVERTS THE NO. 2 SPEED SIGNAL TO A DC VOLTAGE IS NOT FUNCTIONING PROPERLY.
6	FAILED ECU N/DC CONVERTER NO. 3 CIRCUIT. THE ECU REDUNDANT CIRCUIT THAT CONVERTS THE HIGHEST SPEED SIGNAL TO A DC VOLTAGE IS NOT FUNCTIONING PROPERLY.
7	THIS MINIFLAG IS DISPLAYED ONLY IN THE "SUMMARY" ROTARY SELECT SWITCH POSITION AND INDICATES AIRPLANE FAULTS PER MINIFLAGS 75-78.
9	LCIT SENSOR SIGNAL OUT OF RANGE. THE LCIT SENSOR CIRCUIT READS LESS THAN -100°F.
10	OIL TEMPERATURE SENSOR RESISTANCE OUT OF RANGE. THE OIL TEMPERATURE RESISTANCE IS NOT WITHIN THE RANGE OF 65 TO 208 OHMS (-110 TO +482°F).
11	FAILED EGT THERMOCOUPLE CIRCUIT NO. 1 SIGNAL OUT OF RANGE. THE THERMOCOUPLE CIRCUIT READS LESS THAN -100°F ABSOLUTE OR EGT THERMOCOUPLE NO. 2 READS +150°F MORE THAN EGT NO. 1. SEVERE POWER SECTION DISTRESS CAN ALSO CAUSE A LARGE VARIATION IN EGT NO. 1 AND NO. 2 READINGS.
12	FAILED EGT THERMOCOUPLE CIRCUIT NO. 2 SIGNAL OUT OF RANGE. THE THERMOCOUPLE CIRCUIT READS LESS THAN -100°F ABSOLUTE OR EGT THERMOCOUPLE NO. 1 READS +150°F MORE THAN EGT NO. 2. SEVERE POWER SECTION DISTRESS CAN ALSO CAUSE A LARGE VARIATION IN EGT NO. 1 AND NO. 2 READINGS.
14	FAILED TOTAL PRESSURE SENSOR/CIRCUIT. THE PT VALUE IS OUT OF ITS NORMAL OPERATING RANGE OR DIFFERS BY MORE THAN 3 PSIG FROM THE P2 SENSOR READING ON THE GROUND AT SPEEDS LESS THAN 12%. A MODERATELY SHIFTED P2 SENSOR OUTPUT COULD ALSO CAUSE THIS MINIFLAG. THIS MINIFLAG CAN BE SET BY MINIFLAG 120.
15	FAILED DIFFERENTIAL PRESSURE SENSOR/CIRCUIT. THE DP VALUE IS OUT OF ITS NORMAL OPERATING RANGE OR HAS AN OUTPUT OF LESS THAN 0.25 PSIG WHEN THE IGV POSITION IS 60 DEGREES (MOSTLY OPEN). THIS MINIFLAG CAN BE SET BY MINIFLAG 120.
16	FAILED AMBIENT PRESSURE (P2) SENSOR/CIRCUIT. THE P2 VALUE IS OUT OF ITS NORMAL OPERATING RANGE OR LESS THAN 8 PSIG ON THE GROUND. THIS MINIFLAG CAN BE SET BY MINIFLAG 120.
17	GENERATOR OIL FILTER SWITCH FAILED OPEN. THE NORMALLY CLOSED GENERATOR OIL FILTER SWITCH IS OPEN PRIOR TO APU OPERATION.
18	COOLING FAN ISOLATION VALVE FAILED. THE NORMALLY OPEN COOLING FAN ISOLATION VALVE SWITCH IS CLOSED PRIOR TO OPERATION OR OPEN DURING APU OPERATION.
19	LOP SWITCH CIRCUIT FAILED CLOSED. THE LOP SWITCH CIRCUIT IS CLOSED (SHORTED) PRIOR TO START.
21	ECU FLOW DIVIDER DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
23	ECS DEMAND SIGNAL OUT OF RANGE. THE ECS DEMAND SIGNAL IS LESS THAN -0.3V DC OR GREATER THAN 9.9V DC DURING APU OPERATION IN ECS MODE (MINIFLAG 133).
25	FUEL SOLENOID CIRCUIT FAILED. THE FUEL SOLENOID CIRCUIT IS OPEN OR SHORTED.
26	DEOIL SOLENOID CIRCUIT FAILED. THE DEOIL SOLENOID CIRCUIT IS OPEN OR SHORTED.

ECU MINIFLAG DESCRIPTION TABLE C

APU BITE Procedure Figure 103 (Sheet 7)

AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

49–11–00



NUMBER	DESCRIPTION
27	FLOW DIVIDER SOLENOID CIRCUIT FAILED. THE FLOW DIVIDER SOLENOID CIRCUIT IS OPEN OR SHORTED.
28	IGNITION UNIT CIRCUIT FAILED. THE IGNITION UNIT CIRCUIT IS OPEN OR SHORTED.
29	ECU DEOIL SOLENOID DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
30	ECU FUEL SOLENOID DRIVER OPEN. INTERNAL ECU FAILURE WAS FOUND.
32	ECU IGNITION UNIT DRIVER OPEN. INTERNAL ECU FAILURE WAS FOUND.
33	ECU STARTER CIRCUIT DRIVER OPEN. INTERNAL ECU FAILURE WAS FOUND.
34	AIRPLANE STARTER CIRCUIT FAILED. VOLTAGE WAS FOUND AT THE START MOTOR AT GREATER THAN 95% SPEED OR NO START MOTOR VOLTAGE IS FOUND DURING START CYCLE.
35	START MOTOR FAILED. VOLTAGE EXISTS ON THE START MOTOR BUT NO APU ROTATION IS FOUND AFTER 14.5 SECONDS.
36	ECU SCV DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
37	ECU FUEL CONTROL TORQUE MOTOR DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
38	ECU IGV ACTUATOR DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER WAS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
39	ECU FUEL CONTROL TORQUE MOTOR DRIVER OPEN. INTERNAL ECU FAILURE WAS FOUND.
41	FUEL CONTROL TORQUE MOTOR FAILED. THE FUEL CONTROL TORQUE MOTOR CIRCUIT IS OPEN OR SHORTED.
42	IGV ACTUATOR FAILED. THE IGV TORQUE MOTOR OR LVDT IS SHORTED OR OPEN OR COMMANDED IGV POSITION DOES NOT AGREE WITH ACTUAL IGV POSITION BY 10 DEGREES FOR MORE THAN 6 SECONDS (SEE MINIFLAGS 66,106,126, AND 127 FIRST IF PRESENT).
43	SURGE CONTROL VALVE TORQUE MOTOR FAILED. THE SURGE CONTROL VALVE TORQUE MOTOR CIRCUIT IS OPEN OR SHORTED.
44	ECU EGT NO. 1 SIGNAL CONDITIONER FAILED. INTERNAL ECU FAILURE WAS FOUND.
45	ECU EGT NO. 2 SIGNAL CONDITIONER FAILED. INTERNAL ECU FAILURE WAS FOUND.
46	ECU OVERTEMPERATURE TEST FAILURE. INTERNAL ECU FAILURE WAS FOUND DURING APU SHUTDOWN.
47	INLET DOOR RELAY FAILED. AN OVERCURRENT WAS FOUND ON THE INLET DOOR RELAY CIRCUIT.
48	ECU FAILED. THIS MINIFLAG INDICATES INTERNAL ECU FAILURES AND IS SET BY MINIFLAGS 3-6,21, 29-33,37,39,44,45,46,65,82-89,92-100,105,107,112-119,121-125 OR 128. IT CAN ALSO BE SET BY MINIFLAGS 36 OR 38.
65	ECU HI-WINS SPEED CIRCUIT FAILURE. INTERNAL ECU FAILURE WAS FOUND.
66	IGV POSITION DOES NOT MATCH COMMAND. COMMANDED IGV POSITION DOES NOT AGREE WITH ACTUAL IGV POSITION BY 10 DEGREES FOR MORE THAN 6 SECONDS DURING APU OPERATION.
75	AIRPLANE MAINTENANCE LAMP CIRCUIT OVERCURRENT
76	AIRPLANE BLEED AIR RELAY OVERCURRENT
77	AIRPLANE GENERATOR AVAILABLE RELAY OVERCURRENT
78	AIRPLANE FAULT RELAY OVERCURRENT
82	FUEL TORQUE MOTOR OVERCURRENT. THE FUEL CONTROL TORQUE MOTOR CIRCUIT IS SHORTED.
83	ECU LCIT CONDITIONER FAILED. INTERNAL ECU FAILURE WAS FOUND.

ECU MINIFLAG DESCRIPTION TABLE C

APU BITE Procedure Figure 103 (Sheet 8)

49-11-00



NUMBER	DESCRIPTION
84	ECU DEOIL SOLENOID DRIVER FAILED OPEN. INTERNAL ECU FAILURE WAS FOUND.
86	ECU AIRPLANE BLEED RELAY OPEN. INTERNAL ECU FALURE WAS FOUND.
89	ECU FUEL SOLENOID DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
90	FUEL SOLENOID CIRCUIT OPEN. THIS MINIFLAG SETS MINIFLAG 25.
91	IGNITION UNIT CIRCUIT FAILED OPEN. THIS MINIFLAG SETS MINIFLAG 28.
92	ECU IGNITION UNIT DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
94	ECU BLEED AIR DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
95	ECU FLOW DIVIDER DRIVER OPEN. INTERNAL ECU FAILURE WAS FOUND.
97	ECU STARTER RELAY DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
99	ECU BLEED AIR DRIVER OPEN. INTERNAL ECU FAILURE WAS FOUND.
100	ECU BLEED AIR DRIVER SHORTED. +28V DC WAS FOUND ON THE ECU DRIVER WHEN THE DRIVER IS IN THE OFF POSITION. THERE IS A POSSIBLE ECU FAILURE OR A +28V DC EXTERNAL SHORT TO THE DRIVER.
101	FUEL CONTROL TORQUE MOTOR FAILED OPEN. THE FUEL CONTROL TORQUE MOTOR CIRCUIT IS OPEN CIRCUIT. THIS MINIFLAG SETS MINIFLAG 41.
105	ECU IGV ACTUATOR DRIVER FAILED OPEN. INTERNAL ECU FAILURE WAS FOUND.
106	IGV ACTUATOR TORQUE MOTOR FAILED. THE IGV ACTUATOR TORQUE MOTOR IS FAILED OPEN OR SHORT CIRCUIT.
107	ECU SCV DRIVER FAILED OPEN. INTERNAL ECU FAILURE WAS FOUND.
108	FUEL SOLENOID MECHANICALLY STUCK. THE APU DID NOT SHUTDOWN WHEN THE SOLENOID WAS COMMANDED OFF.
112	ECU MAGNETIC RELAY FAILED. THE ECU MAGNETIC LATCH WAS FOUND FAILED DURING SHUTDOWN.
116	ECU FAILED +15V DC POWER SUPPLY. INTERNAL ECU FAILURE WAS FOUND.
117	ECU FAILED -10V DC POWER SUPPLY. INTERNAL ECU FAILURE WAS FOUND.
118	ECU FAILED -15V DC POWER SUPPLY. INTERNAL ECU FAILURE WAS FOUND.
119	ECU FAILED +5V DC POWER SUPPLY. INTERNAL ECU FAILURE WAS FOUND.
120	ECU PRESSURE REFERENCE POWER SUPPLY FAILED LOW. INTERNAL ECU FAILURE WAS FOUND.
121	ECU +10V A/D CONVERTER POWER SUPPLY FAILED LOW. INTERNAL ECU FAILURE WAS FOUND.
122	ECU +10V A/D CONVERTER POWER SUPPLY FAILED HIGH. INTERNAL ECU FAILURE WAS FOUND.
123	ECU OV A/D CONVERTER REFERENCE FAILED LOW. INTERNAL ECU FAILURE WAS FOUND.
124	ECU OV A/D CONVERTER REFERENCE FAILED HIGH. INTERNAL ECU FAILURE WAS FOUND.
125	ECU PRESSURE REFERENCE POWER SUPPLY FAILED HIGH. INTERNAL ECU FAILURE WAS FOUND.

ECU MINIFLAG DESCRIPTION TABLE C

APU BITE Procedure Figure 103 (Sheet 9)

49-11-00 CONFIG 2 Page 111



NUMBER	DESCRIPTION
126	IGV ACTUATOR LVDT VOLTAGE OUT OF RANGE. THE IGV ACTUATOR LVDT VOLTAGE IS OUT OF ITS EXPECTED RANGE.
127	IGV ACTUATOR LVDT SECONDARY VOLTAGE OUT RANGE. THE IGV ACTUATOR LVDT SECONDARY VOLTAGE IS OUT OF ITS EXPECTED RANGE.
128	IGV ACTUATOR LVDT PRIMARY VOLTAGE OUT OF RANGE. THE IGV ACTUATOR LVDT PRIMARY VOLTAGE IS OUT OF ITS EXPECTED RANGE.
	DIAGNOSTIC MINIFLAGS ACTIVE DURING APU OPERATION
130	DUCT PRESSURIZATION MODE ACTIVE. THE APU IS CURRENTLY OPERATING IN DUCT PRESSURIZATION MODE.
131	ADP MODE ACTIVE. THE APU IS CURRENTLY OPERATING IN AIR DRIVEN PUMP MODE.
132	INFLIGHT OPERATION MODE ACTIVE. THE APU IS CURRENTLY OPERATING IN IN-FLIGHT OPERATION MODE.
133	ECS MODE ACTIVE. THE APU IS CURRENTLY OPERATING IN ECS MODE.
134	MES MODE ACTIVE. THE APU IS CURRENTLY OPERATING IN MAIN ENGINE START MODE.
140	SCV IS COMMANDED CLOSED. THE SURGE CONTROL VALVE TORQUE MOTOR COMMAND IS GREATER THAN 95 MILLIAMPS.
141	SCV IS COMMANDED OPEN. THE SURGE CONTROL VALVE TORQUE MOTOR COMMAND IS LESS THAN 10 MILLIAMPS.
142	IGV POSITION DOES NOT AGREE WITH COMMANDED POSITION. THE ACTUAL IGV POSITION IS CURRENTLY AT LEAST 5 DEGREES DIFFERENT THAN THE COMMANDED POSITION.
143	APU IS OPERATING ON EGT TEMPERATURE TRIM. THE APU IS OPERATING ON EGT TEMPERATURE TRIM WHICH INDICATES A DETERIORATED POWER SECTION WHICH CAN RESULT IN REDUCED PNEUMATIC OUTPUT.

ECU MINIFLAG DESCRIPTION TABLE C


APU BITE Procedure Figure 103 (Sheet 10)

49-11-UC CONFIG 2 Page 112


Dec 20/94

01





MINIFLAG "128" (EXAMPLE OF A MINIFLAG DISPLAY ON ECU)



MINIFLAG "OK" (EXAMPLE OF A MINIFLAG DISPLAY ON ECU)

APU BITE Procedure Figure 103 (Sheet 11)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

CONFIG Page 113




MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,APU
START,APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

APU STARTING PROBLEMS



WHEN YOU START THE APU, LOOK AT THE APU BATTERY VOLTAGE AND THE CURRENT ON THE EICAS "ELEC/HYD" DISPLAY. LOOK AT THE APU RPM AND THE EGT ON THE EICAS "PERF/APU" DISPLAY.

2 PUSH THE "ECS/MSG" SWITCH ON THE EICAS PANEL, P61, AND MAKE SURE "APU DOOR" MESSAGE DOES NOT SHOW.

OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.


APU Starting Problems Figure 104 (Sheet 1)

49-11-00

CONFIG


E49112





APU Starting Problems Figure 104 (Sheet 2)

49-11-00




APU Starting Problems Figure 104 (Sheet 3)

49-11-00

02

CONFIG 2 Page 116 May 28/00




APU Starting Problems Figure 104 (Sheet 4)

AIRPLANES WITH THE APU CONTROL
UNIT -19 AND SUBSEQUENT

49–11–00

01

CONFIG 2 Page 117 May 28/00




APU Starting Problems Figure 104 (Sheet 5)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

49-11-00 CONFIG Page 118





APU Starting Problems Figure 104 (Sheet 6)

49-11-00 config 2


01

Page 119 May 28/00

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35, APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF/APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

IF TWO APU STARTER MOTORS ARE REPLACED IN LESS THAN 30 DAYS, REPLACE THE APU STARTER MOTOR, M893 (AMM 49-41-01/401), AND THE APU STARTER CLUTCH (AMM 49-41-06/401).

Auto Shutdown - START ABORTED on BITE Figure 105 (Sheet 1)

AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

AUTO SHUTDOWN -

BITE

"START ABORTED" ON

49-11-00


44 DO THE "CORRECTIVE ACTION"

IN FIG. 103, TABLE B.

01

CONFIG 2 Page 120 Jan 28/06





Auto Shutdown - START ABORTED on BITE Figure 105 (Sheet 2)


AIRPLANES WITH THE APU CONTROL
UNIT -19 AND SUBSEQUENT

CONFIG 2

O1 Page 121

May 28/03

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.




Auto Shutdown START ABORTED on BITE Figure 105 (Sheet 3)

AIRPLANES WITH THE APU CONTROL
UNIT -19 AND SUBSEQUENT

49-11-00 CONFIG 2 Page 122 May 28/07

01



Auto Shutdown START ABORTED on BITE Figure 105 (Sheet 4)

AIRPLANES WITH THE APU CONTROL
UNIT -19 AND SUBSEQUENT

CONFIG 2

Page 123
Sep 28/01

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.



MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,
APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER,
E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

"UNDER SPEED" ON BITE

AUTO SHUTDOWN -

YES 41 IF THE "LOW OIL PRESSURE" 1 DO THIS PROCEDURE: BITE PROCEDURE (FIG. 103)(IF LIGHT IS ON, DO THIS PROCE-DURE: AUTO SHUTDOWN - LOW OIL YOU HAVE NOT DONE IT BEFORE). DOES THE "LOW OIL PRESSURE ON BITE (FIG. 109). PRESSURE" OR THE "HIGH OIL IF THE "HIGH OIL TEMP" TEMP" LIGHT COME ON IN THE LIGHT IS ON, DO THIS PROCE-"RECORD SELECT" SWITCH DURE: AUTO SHUTDOWN - HIGH POSITIONS 2 THRU 4? OIL TEMP ON BITE (FIG. 110). YES 42 REPLACE THE OIL PRESSURE REMOVE THE MAGNETIC CHIP WARNING DETECTOR FROM THE GENERATOR ELEMENT AND THE SCAVENGE IF YOU THINK THERE IS A FAIL-FILTER ELEMENT (AMM 49-27-03/ SCAVENGE PORT. URE IN THE GENERATOR SCAVENGE DOES MORE THAN 1 PINT OF 401). SYSTEM, DO NOT STAND NEAR THE OIL DRAIN FROM THE PORT, OR IS REPLACE THE SCAVENGE OIL APU WHEN IT IS STARTED. IF THE POP-UP BUTTON FOR THE DIF-PUMP FOR THE GENERATOR YOU DO NOT OBEY THESE INSTRUC-(AMM 49-27-02/401). FERENTIAL PRESSURE INDICATOR TIONS, AN INJURY CAN OCCUR. FOR THE GENERATOR EXTENDED? REPLACE THE APU GENERATOR (AMM 24-21-01/401). VISUALLY EXAMINE THE NO GENERATOR FOR A FAILURE. CHANGE THE APU OIL (AMM 49-27-00/301). 1>> DOES THE GENERATOR HAVE A SEE SHEET 2 (BLOCK 3) YES 43 REPLACE THE APU (AMM 49-11-01/401). 1>>

AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF/APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

2 IF TWO APU STARTER MOTORS ARE REPLACED IN LESS THAN 30 DAYS, REPLACE THE APU STARTER MOTOR, M893 (AMM 49-41-01/401), AND THE APU STARTER CLUTCH (AMM 49-41-06/401).

OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

Auto Shutdown - UNDER SPEED on BITE Figure 106 (Sheet 1)

AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT


49-11-00

CONFIG


05


Page 124 May 28/00





Auto Shutdown - UNDER SPEED on BITE Figure 106 (Sheet 2)





Auto Shutdown - UNDER SPEED on BITE Figure 106 (Sheet 3)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

CONFIG Page 126

May 28/00

01




MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,APU
START,APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

FAULTY UNIT -"STARTER CIRCUIT" ON BITE CAUTION: MAKE SURE YOU OBEY THE STARTER DUTY CYCLE IN THE APU OPERATION LIMITS (AMM 49-11-00/201). IF YOU DO NOT OBEY THESE INSTRUCTIONS, YOU CAN CAUSE DAMAGE TO THE APU.



AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.


2 IF TWO APU STARTER MOTORS ARE REPLACED IN LESS THAN 30 DAYS, REPLACE THE APU STARTER MOTOR, M893 (AMM 49-41-01/201), AND THE APU STARTER CLUTCH (AMM 49-41-06/201).

Faulty Unit - STARTER CIRCUIT on BITE Figure 106A (Sheet 1)

49-11-00

CONFIG





Faulty Unit - STARTER CIRCUIT on BITE Figure 106A (Sheet 2)

49-11-00

01

Page 128 May 28/00



MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,
APU START (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

AUTO SHUTDOWN - "NO LIGHT OFF " ON BITE

1 DO THIS PROCEDURE: APU
BITE PROCEDURE (FIG. 103)(IF
YOU HAVE NOT DONE IT BEFORE).
START THE APU
(AMM 49-11-00/201).
DO NOT DISCONNECT THE
PRIMARY LEAD, ABOVE 7% RPM
(AMM 49-11-00/201).
CAN YOU HEAR THE IGNITER
PLUG?

YES

SEE SHEET 2
(BLOCK 2)

11 MAKE SURE THESE CIRCUIT BREAKERS ARE OPEN:

11B34, "APU ALTN CONT" P11 OVERHEAD PANEL "APU CONT" E6 RACK, AFT

EQUIPMENT CENTER

WARNING: DO NOT TOUCH THE IGNITION COMPONENTS UNTIL YOU DO THESE STEPS. THESE STEPS WILL RELEASE THE HIGH VOLTAGE FROM THE IGNITION UNIT. IF YOU DO NOT OBEY THESE STEPS, INJURY TO PERSONS CAN OCCUR.

RELEASE THE HIGH VOLTAGE FROM THE IGNITION UNIT:

- STOP FOR A MINIMUM OF 5 MINUTES
- DISCONNECT THE IGNITION CABLE FROM THE IGNITER PLUG
- GROUND THE IGNITION CABLE TERMINAL TO THE APU ENGINE.

EXAMINE THE IGNITION LEAD CONNECTION TO THE IGNITER PLUG (AMM 49-41-04/201).

IS THE CONNECTION BAD?

NO

YES 21 REPLACE THE IGNITER PLUG, YBMM7 (AMM 49-41-02/201) AND THE IGNITION LEAD (AMM 49-41-04/201).

AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.


OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) AGAIN TO MAKE SURE THE PROBLEM IS REPAIRED.

Auto Shutdown - NO LIGHT OFF on BITE Figure 107 (Sheet 1)

49-11-00

CONFIG 2 05 Page 129 May 28/07





AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.


Auto Shutdown - NO LIGHT OFF on BITE Figure 107 (Sheet 2)

49-11-00

01

Page 130 May 28/07





AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER YOU CORRECT THE PROBLEM, PUSH THE "PERF/APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

Auto Shutdown - NO LIGHT OFF on BITE Figure 107 (Sheet 3)

EFFECTIVITY
AIRPLANES WITH THE APU CONTROL
UNIT -19 AND SUBSEQUENT


49-11-00

CONFIG 2 1 Page 131

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,
APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER,
E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

Auto Shutdown During Governed Speed - REVERSE FLOW on BITE Figure 108 (Sheet 1)

AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

AUTO SHUTDOWN DURING


GOVERNED SPEED - "REVERSE FLOW"

49-11-00

IF THE PROBLEM CONTINUES, REPLACE THE ECU (AMM 49-61-05/

201). 1





Auto Shutdown During Governed Speed - REVERSE FLOW on BITE Figure 108 (Sheet 2)

AIRPLANES WITH THE APU CONTROL
UNIT -19 AND SUBSEQUENT

CONFIG 2
Page 133
May 28/00



MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

"LOP" SHUTDOWNS.

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

NOTE: THE "LOP" LIGHT ON THE ECU WILL FLASH WHEN AN "LOP" SHUTDOWN OCCURS ON THE THIRD TRY TO START THE APU WITH THE AIRPLANE ON THE GROUND. THE "LOP" LIGHT WILL ONLY FLASH IF THE ECU MEMORY WAS NOT ERASED AFTER THE FIRST TWO

> IF THE APU IS INITIALLY STARTED WITH LOW OIL PRESSURE, THE APU WILL SHUTDOWN 15.5 SECONDS AFTER IT GETS TO 95% RPM (OR ONE SECOND IF THE APU OIL TEMPERATURE IS GREATER THAN 20°F). THE SUBSEQUENT START WITH LOW OIL PRESSURE WILL CAUSE A SHUTDOWN ONE SECOND AFTER THE APU GETS TO 95% RPM. THE APU WILL THEN NOT START IF THERE IS LOW OIL PRESSURE.

1>	AN AUTOMATIC	SHUTDOWN	WILL CA	JSE THE	EICAS TO	WRITE	AN A	UTO-EVE	NT FOR	THE S	HUTDOWN.	AFT	ER THE
	PROBLEM IS C	ORRECTED,	PUSH TH	"PERF-	-APU" AND	THE "	'AUTO-	-EVENT R	EAD" S	MITCHE	S ON THE	P61	PANEL.
	PHISH THE "ER	ASE" SWIT	CH FOR 3	SECONDS	S MAKE	SLIRE T	THE "Δ	DII-FAIII	ו פז ייד	FRASED	1		

Auto Shutdown - LOP on BITE Figure 109 (Sheet 1)


EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

CONFIG

² OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) AGAIN TO MAKE SURE THE PROBLEM IS REPAIRED.



AUTO SHUTDOWN - "LOP" ON BITE




AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

Auto Shutdown - LOP on BITE Figure 109 (Sheet 2)

49-11-00

04

Page 135 May 28/00



> AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

> Auto Shutdown - LOP on BITE Figure 109 (Sheet 3)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

49-11-00

CONFIG Page 136 May 28/00

FROM SHEET 3 (BLOCK 15)

29 THERE IS A PERFORMANCE 16 IT IS POSSIBLE THAT THERE IS OIL FILTER BLOCKAGE. PROBLEM IN THE OIL SYSTEM. REPLACE THE APU OIL PUMP EXAMINE THE OIL PRESSURE (AMM 49-27-01/401). 1>2 FILTER AND THE GENERATOR SCAVENGE FILTER FOR CONTAMI-NOTE: IF THE DRIVE SHAFT FOR NATION (AMM 49-27-03/201), IF THE OIL PUMP IS BROKEN, YOU DID NOT EXAMINE THEM BEFORE. 1 2 MAKE SURE YOU REMOVE IT FROM THE DRIVE GEAR. IF THE PROBLEM CONTINUES, CONNECT A PRESSURE GAGE IF THE PROBLEM CONTINUES, REMOVE THE DE-OIL SOLENOID (0-150 PSIG) TO THE OIL PRESSURE TEST PORT (SEE VALVE (AMM 49-27-08/401) TO SEE IF IT IS STUCK OPEN. 1> SHEET 6). START THE APU (AMM 49-11-00/201). IF THE PROBLEM CONTINUES, OPERATE THE APU IN THE ECS EXAMINE THE OIL COOLER, THE LINES AND THE CHECK VALVES IS THE OIL PRESSURE FOR BLOCKAGE. 1 2 IF THE PROBLEM CONTINUES, GREATER THAN 40 PSIG? THE APU HAS AN INTERNAL LEAK. YES REPLACE THE APU (AMM 49-11-01/ 401). 30 IT IS POSSIBLE THAT THERE 17 IS THE OIL PRESSURE LESS THAN 60 PSI? IS A PERFORMANCE PROBLEM IN THE OIL SYSTEM. REPLACE THE NO APU OIL PUMP (AMM 49-27-01/ 401). 1>2> 18 THERE IS AN INDICATION NOTE: IF THE DRIVE SHAFT FOR PROBLEM. IT IS POSSIBLE THAT THE OIL PUMP IS BROKEN, THERE IS A CALIBRATION SHIFT MAKE SURE YOU REMOVE IT IN THE OIL PRESSURE (LOP) FROM THE DRIVE GEAR. SWITCH. REPLACE THE OIL PRESSURE (LOP) SWITCH, YBMS2 (AMM 49-94-02/201). IF THE PROBLEM CONTINUES, REMOVE THE DE-OIL SOLENOID VALVE (AMM 49-27-08/401) TO IF THE PROBLEM CONTINUES, EXAMINE THE CIRCUIT FROM THE SEE IF IT IS STUCK OPEN. 1> ECU, CONNECTOR D1796B, PIN C5, IF THE PROBLEM CONTINUES, TO THE LOW OIL PRESSURE SWITCH, YBMS2, CONNECTOR P6, EXAMINE THE OIL COOLER, THE PIN 1 (GROUND, PIN 2) LINES AND THE CHECK VALVES FOR BLOCKAGE. 1 2 (WDM 49-14-11). REPAIR THE PROBLEMS THAT IF THE PROBLEM CONTINUES, YOU FIND. 1>2> THE APU HAS AN INTERNAL LEAK. REPLACE THE APU (AMM 49-11-01/401). 1 2 IF THE PROBLEM CONTINUES, REPLACE THE ECU, M206 (AMM 49-61-05/201). 1>IF THE PROBLEM CONTINUES, THERE IS AN INDICATION PROBLEM. EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1796B, PIN C5, TO THE LOW OIL PRESSURE SWITCH, YBMS2, CON-NECTOR P6, PIN 1 (GROUND, PIN 2)(WDM 49-14-11). REPAIR THE PROBLEMS THAT

Auto Shutdown - LOW OIL PRESURE on BITE Figure 109 (Sheet 4)

AIRPLANES WITH THE APU CONTROL
UNIT -19 AND SUBSEQUENT

49-11-00

CONFIG

IF THE PROBLEM CONTINUES,


07

YOU FIND. 1 2

REPLACE THE ECU, M206 (AMM 49-61-05/201).

Page 137 May 28/00





Auto Shutdown - LOP on BITE Figure 109 (Sheet 5)

AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

49-11-00

05

CONFIG 2 Page 138 May 28/00



MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

"HOT" ON BITE

1 DO THIS PROCEDURE: APU
BITE PROCEDURE (FIG. 103) (1

AUTO SHUTDOWN -


YES 51 DO THIS PROCEDURE: AUTO SHUTDOWN - LOW OIL PRESSURE ON BITE (FIG. 109). BITE PROCEDURE (FIG. 103) (IF YOU HAVE NOT DONE IT BEFORE). MAKE SURE THE HIGH OIL TEMP (HOT) LIGHT IS SHOWN ON "REASON APU NOT OPERATING". DO A CHECK OF PREVIOUS SHUTDOWN MESSAGES AND THEN PUSH THE "ERASE MEMORY" SWITCH TO ERASE THE BITE MEMORY. DID YOU FIND ANY PREVIOUS LOW OIL PRESSURE (LOP) SHUTDOWNS? NO YES ARE THERE SIGNS OF OIL 52 REPLACE THE COOLING FAN ON THE APU FIREWALL? (AMM 49-51-03/401).REPLACE OR CLEAN THE OIL (AMM 49-27-09/401). 1>YES VISUALLY EXAMINE THE FAN 53 REPLACE OR REPAIR THE FAN INLET AND OUTLET DUCTS FOR INLET AND OUTLET DUCTS AS DAMAGE AND ATTACHMENT. NECESSARY. IS THERE A PROBLEM WITH THE DUCTS? NO SEE SHEET 2 (BLOCK 4)

AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

Auto Shutdown - HOT on BITE Figure 110 (Sheet 1)


AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

49–11–00




Auto Shutdown - HOT on BITE Figure 110 (Sheet 2)

AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT



Auto Shutdown - HOT on BITE Figure 110 (Sheet 3)





Auto Shutdown - HOT on BITE Figure 110 (Sheet 4)

49-11-00

05

Page 142 May 28/05



AUTO SHUTDOWN -"OVER SPEED" ON BITE

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

YES DO THIS PROCEDURE: APU 11 REMOVE THE BLOCKAGE OR BITE PROCEDURE (FIG. 103)(IF REPLACE THE TUBES. 1 2 YOU HAVE NOT DONE IT BEFORE). IF THE PROBLEM CONTINUES, REPLACE THE APU FUEL GO TO BLOCK 12. CONTROL UNIT (AMM 49-31-01/401). |1> |2>IF THE PROBLEM CONTINUES, EXAMINE THE TUBES FOR THE INLET PRESSURE (P2) SENSOR FORBLOCKAGE. NOTE: IF THE P2 SENSOR HAS A DEFECT, OR IF THE TUBES FOR THE P2 SENSOR ARE CLOGGED, AN OVERSPEED SHUTDOWN CAN OCCUR DURING A FLIGHT. ARE THE TUBES CLOGGED? NO 12 REPLACE THE P2 SENSOR, YBMTŞ4 (AMM 49-61-04/201). 1>>|2> IF THE PROBLEM CONTINUES, REPLACE THE ECU, M206 (AMM 49-61-05/201).

AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) AGAIN TO MAKE SURE THE PROBLEM IS REPAIRED.

Auto Shutdown - OVER SPEED on BITE Figure 111

49-11-UL CONFIG 2 Page 143


Sep 28/06

05

AUTO SHUTDOWN -"GEN FILTER" ON BITE

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)




AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

Auto Shutdown - GEN FILTER on BITE Figure 112 (Sheet 1)

EFFECTIVITY—AIRPLANES WITH THE APU CONTROL
UNIT -19 AND SUBSEQUENT

CONFIG 2
Page 144
Jan 28/05





Auto Shutdown - GEN FILTER on BITE Figure 112 (Sheet 2)

49-11-00

05

Page 145 Jan 28/05


MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER,

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

AUTO SHUTDOWN -"OVER TEMP" ON BITE

NOTE: IF THE APU HAS A START PROBLEM ("NO FLAME", "SLOW START", OR "NO ACCEL") AND THE AUTOMATIC SHUTDOWN "OVER TEMP", THERE IS A DEFECT IN THE FLOW DIVIDER OR THE PRIMARY FUEL NOZZLE.




1 AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF-APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

2 OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

> Auto Shutdown - OVER TEMP on BITE Figure 113 (Sheet 1)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

CONFIG




Auto Shutdown - OVER TEMP on BITE Figure 113 (Sheet 2)

49-11-00

06

Page 147 Jan 28/05



Auto Shutdown - OVER TEMP on BITE Figure 113 (Sheet 3)

49-11-00

05


CONFIG 2 Page 148 Jan 28/05



Not Used Figure 114

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT






High Oil Consumption Figure 115 (Sheet 1)

49-11-00 config 2





High Oil Consumption
Figure 115 (Sheet 2)

49-11-00 CONFIG 2 Page 151 Jan 28/05

05



MAKE SURE THIS SYSTEM WILL OPERATE:

PREREQUISITES

EICAS (AMM 31-41-00/201) MAKE SURE THIS CIRCUIT BREAKER IS CLOSED: 11A33 EICAS MSG "APU OIL MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: QTY" DISPLAYED ELECTRICAL POWER IS ON (AMM 24-22-00/201) NO 1 DO THIS PROCEDURE: APU 20 | THE SYSTEM IS OK. DO THE APU SHUTDOWN PROCE-BITE PROCEDURE (FIG. 103)(IF YOU HAVE NOT DONE IT BEFORE). DURE (AMM 49-11-00/201). START THE APU (AMM 49-11-00/201. OPERATE THE APU FOR 5 MIN-UTES. DO THIS PROCEDURE: MAINTENANCE MESSAGE ERASE PRO-CEDURE (FIM 31-41-00/101, FIG. 109). DOES THE "APU OIL QTY" MESSAGE SHOW IMMEDIATELY? YES 2 DO THE APU SHUTDOWN PROCE-10 1>; 21 REPLACE THE OIL LEVEL SWITCH, YBMS3 (AMM 49-94-03/ 201). 1 DURE (AMM 49-11-00/201). GO TO BLOCK 21. REMOVE FILL CAP AND CHECK 2>; REMOVE THE CONNECTOR FROM OIL LEVEL IN RESERVOIR BY ADD-REPLACE THE OIL QUANTITY ING APPROVED OIL UNTIL IT IS THE OIL QUANTITY TRANSMITTER, TRANSMITTER, YBMS3 (AMM 49-94-04/201). 2 FULL (OVERFLOWS)(AMM 12-13-04/ YBMS3. CLEAN THE CONNECTOR AND THE TRANSMITTER. REMOVE 301). DO THIS PROCEDURE: MAIN-DID THE APU NEED MORE THAN ALL CONTAMINATION SUCH AS OIL TENANCE MESSAGE ERASE PROCE-2 QUARTS OF OIL TO BE FULL? OR GREASE. REPLACE THE CON-DURE (FIM 31-41-00/101, NECTOR ON THE TRANSMITTER. FIG. 109). YES START THE APU (AMM 49-11-00/201). OPERATE THE APU FOR SEE SHEET 2 5 MINUTES. DO THIS PROCEDURE: (BLOCK 3) MAINTENANCE MESSAGE ERASE PRO-CEDURE (FIM 31-41-00/101, FIG. 109). DOES THE "APU OIL QTY" MESSAGE SHOW IMMEDIATELY? 21A THE SYSTEM IS OK.

EICAS Msg APU OIL QTY Displayed Figure 116 (Sheet 1)

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT


GUI 001-114,116-999

GUI 115

49-11-00

DO THE APU SHUTDOWN PROCE-

DURE (AMM 49-11-00/201).




EICAS Msg APU OIL QTY Displayed Figure 116 (Sheet 2)

APU WILL NOT CARRY PNEUMATIC AND ELECTRICAL LOAD ASSOCIATED WITH RPM DROOP

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201) APU START NORMAL (AMM 49-11-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



1> OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) AGAIN TO MAKE SURE THE PROBLEM IS REPAIRED.

APU Will Not Carry Pneumatic and Electrical Load Associated with RPM Droop Figure 117

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

49-11-00

CONFIG



MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201) APU START NORMAL

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)


NO DUCT PRESSURE (0-2 PSIG)

YES 11 PNEUMATIC COMPONENT IS 21 UNLOCK THE APU SHUTOFF DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103)(IF CAUSE OF NO DUCT PRESSURE VALVE UNLESS IT IS LOCKED FOR OTHER CAUSES. YOU HAVE NOT DONE IT BEFORE). PROBLEM. EITHER APU COMPONENT OR LOOK AT THE POSITION PNEUMATIC SYSTEM COMPONENT MAY INDICATION ON THE APU SHUTOFF BE AT FAULT. START THE APU IS THE APU SHUTOFF VALVE (AMM 49-11-00/201).CLOSED AND LOCKED? PUSH THE TWO BLEED AIR L (R) ENG SWITCHES ON THE P5 PANEL TO THE "OFF" POSITION. 22 DO THIS PROCEDURE: EICAS 12 MAKE SURE THE TWO BLEED PUSH THE BLEED AIR ISOLA-MESSAGE "APU BLEED VAL" TION VALVE SWITCH TO THE AIR L (R) ENG SWITCHES ON THE OPEN POSITION. P5 PANEL ARE SET TO THE "OFF" DISPLAYED. "VALVE" LIGHT ILLUMINATED (FIM 36-10-00/101, PUSH THE BLEED AIR APU POSITION. VALVE SWITCH TO THE OPEN IS THE BLEED AIR, L (R) FIG. 114). POSITION. ENG, "OFF" SWITCH LIGHT ON? IDENTIFY IF THE APU SHUT-OFF VALVE OPENED: DID THE 23 DO THIS PROCEDURE: L (R) "BLEED AIR, APU, VALVE" LIGHT COME ON, THEN GO OFF IN LESS ENG BLEED AIR OFF LIGHT DID THAN 10 SECONDS? NOT ILLUMINATE WITH SWITCH ON AND ENGINES NOT RUNNING YES (FIM 36-10-00/101, FIG. 103). SEE SHEET 2 (BLOCK 2)

> No Duct Pressure (0-2 PSIG) Figure 118 (Sheet 1)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

Page 155



No Duct Pressure (0-2 PSIG) Figure 118 (Sheet 2)




MAKE SURE THESE SYSTEMS WILL OPERATE:
EICAS (AMM 31-41-00/201)
APU START NORMAL
APU BATTERY CHARGER OPERATES NORMAL
(ELECTROMAGNETIC INTERFERENCE CAN CAUSE INCORRECT
SIGNALS TO AND FROM THE ECU)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35, APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)


FLUCTUATING DUCT PRESSURE

NOTE: IF YOU LOSE ELECTRICAL POWER WHEN YOU TRANSFER FROM ONE GENERATOR TO ANOTHER, THE DUCT PRESSURE WILL MOMENTARILY BE IRREGULAR.



Fluctuating Duct Pressure Figure 119 (Sheet 1)


49-11-00 config 2



OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) AGAIN TO MAKE SURE THE PROBLEM IS REPAIRED.

Fluctuating Duct Pressure Figure 119 (Sheet 2)

49-11-00 config 2



Fluctuating Duct Pressure Figure 119 (Sheet 3)




MAKE SURE THIS SYSTEM WILL OPERATE:
APU START NORMAL (AMM 49-11-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35, APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)


LOW DUCT PRESSURE



Low Duct Pressure Figure 120 (Sheet 1)


AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT





Low Duct Pressure Figure 120 (Sheet 2)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT



Low Duct Pressure Figure 120 (Sheet 3)

49-11-00

07

CONFIG 2 Page 162 Jan 28/05



Not Used Figure 120A

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

06

Page 163 Jan 28/05



MAKE SURE THIS SYSTEM WILL OPERATE:
APU START NORMAL (AMM 49-11-00/201)


MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35, APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

LOW DUCT PRESSURE
IN DUCT
PRESSURIZATION MODE
(3-25 PSIG)

1 DOES THE SURGE CONTROL 11 DO A CHECK OF THE PRESSURE 21 REMOVE THE BLOCKAGE OF VALVE HAVE A PRESSURE SUPPLY SUPPLY TUBE FOR THE SURGE MOISTURE, ICE OR UNWANTED TUBE WITH A 0.030 INCH CONTROL VALVE FOR BLOCKAGE OF MATERIALS AND/OR REPAIR THE (0.76 mm) DRAIN HOLE MOISTURE, ICE OR UNWANTED PROBLEMS THAT YOU FIND. (HONEYWELL POST-SB MATERIALS AND DAMAGE THAT CAN GTCP331-49-7496 OR HONEYWELL CAUSE A DECREASE IN AIRFLOW. POST-SB GTCP331-49-7707)? IS THERE BLOCKAGE OF 22 THE PRESSURE SUPPLY TUBE MOISTURE, ICE OR UNWANTED FOR THE SURGE CONTROL VALVE IS MATERIALS OR DAMAGE TO THE OK. PRESSURE SUPPLY TUBE? GO TO BLOCK 2. YES START THE APU 23 THERE IS A LEAK IN A (AMM 49-11-00/201). DOWNSTREAM SOURCE. EXAMINE ALL DUCTS AND PUSH THE TWO BLEED AIR L (R) ENG SWITCHES ON THE P5 CLAMPS TO MAKE SURE THERE ARE PANEL TO THE "OFF" POSITION. NO PROBLEMS. LOOK AT THE POSITION PUSH THE BLEED AIR ISOLATION VALVE SWITCH TO THE INDICATORS ON THE LEFT AND OPEN POSITION. RIGHT FLOW CONTROL VALVES. PUSH THE BLEED AIR APU MAKE SURE THE TWO CONTROL VALVE SWITCH TO THE OPEN VALVES ARE FULLY CLOSED. POSITION. SELECT THE LEFT AND RIGHT ECS PACKS ON. LOOK AT THE POSITION INDICATOR ON THE SURGE CONTROL VALVE ON THE APU. IS THE VALVE IN THE CLOSED OR APPROXIMATE CLOSED POSITION? NO SEE SHEET 2 (BLOCK 3)

Low Duct Pressure in Duct Pressurization Mode (3-25 PSIG) Figure 120B (Sheet 1)




Low Duct Pressure in Duct Pressurization Mode (3-25 PSIG) Figure 120B (Sheet 2)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

MAKE SURE THIS SYSTEM WILL OPERATE:
APU START NORMAL (AMM 49-11-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35, APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



Low Duct Pressure in All Operational Modes: ECS, MES and Duct Pressurization Figure 120C (Sheet 1)

LOW DUCT PRESSURE


MODES:

AND DUCT

IN ALL OPERATIONAL

ECS, MES

49-11-00 CONFIG 2 Page 166



OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) AGAIN TO MAKE SURE THE PROBLEM IS REPAIRED.

Low Duct Pressure in All Operational Modes: ECS, MES and Duct Pressurization Figure 120C (Sheet 2)

EFFECTIVITY


AIRPLANES WITH THE APU CONTROL

UNIT -19 AND SUBSEQUENT

49-11-00

04

Page 167 Jan 28/05



Low Duct Pressure in All Operational Modes: ECS, MES and Duct Pressurization Figure 120C (Sheet 3)

49-11-00 CONFIG 2 Page 168

Jan 28/05

06

FROM SHEET 3 (BLOCK 15)

NO 16 EXAMINE FOR CONTROL PRES-49 APUS WITH THE FAN SURE LEAKAGE AT THE SURGE ISOLATION VALVE CONNECTED TO CONTROL VALVE. THE FIRST STAGE COMPRESSOR; APUS WITH THE FAN EXAMINE THE PLUMBING AND ISOLATION VALVE CONNECTED TO CONNECTIONS FOR PCD2 CONTROL THE FIRST STAGE COMPRESSOR; PRESSURE FROM THE HEAT SHIELD LOOK AT THE CONNECTIONS TO THE TO THE SCV. TIGHTEN THE CONNECTIONS OR PCD. ARE THERE POSSIBLE LEAKS? REPLACE THE TUBES OR COMPONENTS IF PROBLEMS OR APUS WITH THE FAN ISOLATION VALVE CONNECTED TO LEAKS ARE FOUND. THE SURGE VALVE; APUS WITH THE FAN LOOK AT THE CONNECTIONS TO THE ISOLATION VALVE CONNECTED TO PCD AND THE FAN ISOLATION THE SURGE VALVE; EXAMINE THE PLUMBING AND VALVE. ARE THERE POSSIBLE LEAKS? CONNECTIONS FOR THESE SCV CONTROL PRESSURES: PCD2 FROM HEAT SHIELD TO SCV, AND FAN ISOLATION VALVE MUSCLE AIR AT BOTH ENDS. EXAMINE THE DIAPHRAGM VENT ON THE FAN ISOLATION VALVE FOR AIR LEAKAGE (DAMAGED DIAPHRAGM). TIGHTEN THE CONNECTIONS OR REPLACE THE TUBES OR COMPONENTS IF PROBLEMS OR LEAKS ARE FOUND. 50 REPLACE THE FLOW SENSING MODULE (AMM 49-53-08/401). IF THE PROBLEM CONTINUES. REPLACE THE SURGE VALVE, YBMM5 (AMM 49-53-01/401).

Low Duct Pressure in All Operational Modes: ECS, MES and Duct Pressurization Figure 120C (Sheet 4)

AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

49-11-00 config 2

IF THE PROBLEM CONTINUES, EXAMINE ALL DUCTS, CLAMPS, APU CHECK VALVE, FOR LEAKS AND DISCONNECTED FITTINGS, AND THE APU SURGE VALVE FILTER ELEMENT FOR CORRECT INSTALL—

ATION.



MAKE SURE THIS SYSTEM WILL OPERATE: APU START NORMAL (AMM 49-11-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35, APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)


LOW DUCT PRESSURE DURING ONE OR TWO ECS PACK OPERATION ONLY

1 DOES THE SURGE CONTROL 11 DO A CHECK OF THE PRESSURE 21 REMOVE THE BLOCKAGE OF VALVE HAVE A PRESSURE SUPPLY SUPPLY TUBE FOR THE SURGE MOISTURE, ICE OR UNWANTED TUBE WITH A 0.030 INCH CONTROL VALVE FOR BLOCKAGE OF MATERIALS AND/OR REPAIR THE (0.76 mm) DRAIN HOLE MOISTURE, ICE OR UNWANTED PROBLEMS THAT YOU FIND. (HONEYWELL POST-SB MATERIALS AND DAMAGE THAT CAN GTCP331-49-7496 OR HONEYWELL CAUSE A DECREASE IN AIRFLOW. POST-SB GTCP331-49-7707)? IS THERE BLOCKAGE OF 22 THE PRESSURE SUPPLY TUBE MOISTURE, ICE OR UNWANTED FOR THE SURGE CONTROL VALVE IS MATERIALS OR DAMAGE TO THE OK. PRESSURE SUPPLY TUBE? GO TO BLOCK 2. NO START THE APU 23 A PROBLEM EXISTS WITH (AMM 49-11-00/201). EITHER THE ZONE TEMPERATURE PUSH THE TWO BLEED AIR CONTROLLER OR THE TEMPERATURE L (R) ENG SWITCHES ON THE P5 CONTROL AIR VALVE. PANEL TO THE "OFF" POSITION. REMOVE PNEUMATIC PRESSURE PUSH THE ISOLATION VALVE FROM THE SYSTEM. TO THE OPEN POSITION. DO THIS PROCEDURE: ZONE TEMPERATURE CONTROL BITE PUSH THE THE TRIM AIR SWITCH TO THE "OFF" POSITION. PROCEDURE (FIM 21-60-00/101, SET THE L PACK TO STBY "C" FIG. 104). AND WRITE THE PRESSURE FROM THE EICAS ECS PAGE. SET THE L PACK TO STBY ARE THE DUCT PRESSURES UNDER THE TWO CONDITIONS WITHIN 2 PSI? YES SEE SHEET 2 (BLOCK 3)

> Low Duct Pressure During One or Two ECS Pack Operation Only Figure 120D (Sheet 1)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

CONFIG



Low Duct Pressure During One or Two ECS Pack Operation Only Figure 120D (Sheet 2)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

CONFIG Page 171




MAKE SURE THIS SYSTEM WILL OPERATE: APU START NORMAL (AMM 49-11-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35, APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

LOW DUCT PRESSURE IN "MES" MODE ONLY

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



Low Duct Pressure in MES Mode Only Figure 120E

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

49-11-00 CONFIG



FLUIDS COMING FROM MAKE SURE THIS SYSTEM WILL OPERATE: DRAIN MAST APU START NORMAL (AMM 49-11-00/201) 1 IF YOU DO NOT KNOW WHICH IS THE FLUID OIL? 11 DO THE APU SHUTDOWN PROCE-DRAIN MAST TUBE THE FLUID DURE (AMM 49-11-00/201). COMES FROM, START THE APU REPLACE THE FUEL CONTROL NO (AMM 49-11-00/201). UNIT, YBMM4 (AMM 49-31-01/ DOES FLUID COME OUT OF THE 401). DRAIN FOR THE FUEL CONTROL, OIL PUMP, AND IGV ACTUATOR? 12 DO THE APU SHUTDOWN PROCE-DISCONNECT THE DRAIN LINE NO FROM THE IGV ACTUATOR. START DURE (AMM 49-11-00/201). AND OPERATE THE APU REPLACE THE IGV ACTUATOR, (AMM 49-11-00/201). YBMM6 (AMM 49-52-02/401). DOES MORE THAN ONE DROP OF FUEL COME OUT OF THE IGV ACTUATOR IN A MINUTE? 13 DO THE APU SHUTDOWN PROCE-DURE (AMM 49-11-00/201). REPLACE THE FUEL CONTROL UNIT, YBMM4 (AMM 49-31-01/ 401). YES DO YOU SEE MORE THAN ONE 14 REPLACE THE FUEL FLOW DROP OF FUEL COME OUT OF THE DIVIDER, YBMM2 (AMM 49-31-03/ DRAIN FOR THE FUEL FLOW DIVI-401). DER AND HEAT SHIELD IN ONE MINUTE? NOTE: FUEL CAN DRAIN FROM THIS LOCATION DURING A SHUTDOWN OR AN UNSATIS-FACTORY START. FUEL MUST NOT DRAIN WHEN YOU OPERATE THE APU. NO YES DOES OIL COME OUT OF THE 15 NO CORRECTIVE STEPS ARE DRAIN FOR THE BEARING CAVITY NECESSARY, PROVIDED THE APU SEAL OR THE DRAIN FOR THE OIL CONSUMPTION RATE IS NOT TURBINE PLENUM? MORE THAN THE LIMIT (AMM 49-11-00/201).NO IF THE RATE IS MORE THAN THE LIMIT, REPLACE THE APU (AMM 49-11-01/401). 16 WHEN FUEL COMES OUT OF THE TURBINE PLENUM DRAIN DURING A SHUTDOWN OR AN UNSATISFACTORY START, THE COMBUSTOR DRAIN VALVE IS CLOGGED. REPLACE THE VALVE (AMM 49-16-01/201).

Fluids Coming from Drain Mast Figure 121


AIRPLANES WITH THE APU CONTROL
UNIT -19 AND SUBSEQUENT

CONFIG 2
Page 173
Jan 28/05



FUMES AND/OR SMOKE IN THE CABIN

PREREQUISITES
NONE



Fumes and/or Smoke in the Cabin Figure 122


49-11-UC CONFIG 2 Page 174



MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

> Faulty LRU - FUEL SOL on BITE Figure 123

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

FAULTY LRU - "FUEL

SOL" ON BITE

CONFIG

401).

24 REPLACE THE ECU, M206 (AMM 49-61-05/201).



MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

NO DO THIS PROCEDURE: 20 THE SYSTEM IS OK. BITE PROCEDURE (FIG. 103)(IF YOU HAVE NOT DONE IT BEFORE). REPLACE THE FLOW SENSING MODULE (AMM 49-53-08/401). 1> DOES THE PROBLEM CONTINUE? YES YES DID THE MINIFLAG 120 COME 21 AN INTERNAL ECU FAILURE ON? WAS FOUND. REPLACE THE ECU, M206 NO (AMM 49-61-05/201). YES YES DID THE MINIFLAG 14 COME 10 THE PT VALUE IS NOT IN ITS 22 A MODERATELY SHIFTED OUT-ON? CORRECT RANGE OR DIFFERS BY PUT FROM THE INLET PRESSURE MORE THAN 3 PSIG FROM THE P2 (P2) SENSOR CAN ALSO CAUSE NO SENSOR VALUE ON THE GROUND AT THIS MINIFLAG. SPEEDS LESS THAN 12%. REPLACE THE INLET PRESSURE REPAIR THE OPEN CIRCUIT (P2) SENSOR, YBMTS4 (AMM 49-61-04/201). FROM THE ECU, CONNECTOR D1796B, PINS A1, A2, A3 AND A4, TO THE PT SENSOR, YBMTS2, CON-NECTOR P12, PINS 1,2,3 AND 4 (WDM 49-14-11). 1 DOES THE PROBLEM CONTINUE? NO 23 THE SYSTEM IS OK. 24 REPLACE THE ECU, M206

OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

Faulty LRU - PT SENSOR on BITE Figure 124

AIRPLANES WITH THE APU CONTROL
UNIT -19 AND SUBSEQUENT

FAULTY LRU - "PT SENSOR" ON BITE

49-11-00

06

(AMM 49-61-05/201).

CONFIG 2 Page 176 Jan 28/05


BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.



MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

Faulty LRU - Delta P SENSOR on BITE Figure 125

FAULTY LRU - "AP

49-11-00

07

Page 177 Jan 28/05




MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

FAULTY LRU - "FUEL CONTROL" ON BITE

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



 $|1\rangle$ OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

> Faulty LRU - FUEL CONTROL on BITE Figure 126

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

CONFIG

06

Page 178 Jan 28/05




MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/501)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35,
APU CONT, APU START, APU INLET DR ACT
(AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)


FAULTY LRU - "IGV ACT" ON BITE



> OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

Faulty LRU - IGV ACT on BITE Figure 127 (Sheet 1)

49-11-00




Faulty LRU - IGV ACT on BITE Figure 127 (Sheet 2)

AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

49-11-00 config 2





Faulty LRU - IGV ACT on BITE Figure 127 (Sheet 3)

49-11-00




MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

FAULTY LRU - "IGN UNIT" ON BITE



> OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

> Faulty LRU - IGN UNIT on BITE Figure 128


EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT



MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

FAULTY LRU - "APU MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)




OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

> IF TWO APU STARTER MOTORS ARE REPLACED IN LESS THAN 30 DAYS, REPLACE THE APU STARTER MOTOR, M893 (AMM 49-41-01/401), AND THE APU STARTER CLUTCH (AMM 49-41-06/401).

Faulty LRU - APU STARTER on BITE Figure 129 (Sheet 1)

49-11-00





Faulty LRU - APU STARTER on BITE Figure 129 (Sheet 2)

AIRPLANES WITH THE APU CONTROL
UNIT -19 AND SUBSEQUENT

49-11-00 CONFIG 2

06 Page 180D Jan 28/05

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3, 6H12, 6H23, 11B34, 11C33, 11D32, 11D35,
APU CONT, APU START, APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

ELECTRICAL POWER IS ON (AMM 24-22-00/201) YES 1 DO THIS PROCEDURE: APU 11 DID THE MINIFLAG 120 COME 21 AN INTERNAL ECU FAILURE BITE PROCEDURE (FIG. 103)(IF ON? WAS FOUND. YOU HAVE NOT DONE IT BEFORE). REPLACE THE ECU, M206 NO (AMM 49-61-05/201). REPLACE THE INLET PRESSURE (P2) SENSOR, YBMTS4 (AMM 49-61-04/201). 2 >12 DID THE MINIFLAG 16 COME 22 REPLACE THE ECU, M206 DOES THE PROBLEM CONTINUE? (AMM 49-61-05/201). 1 YES THE SYSTEM IS OK. YES 13 THE INLET PRESSURE (P2) 23 REPLACE THE ECU, M206 (AMM 49-61-05/201). 1 VALUE IS NOT IN ITS CORRECT RANGE OR IS LESS THAN 8 PSIG ON THE GROUND. REPAIR THE OPEN CIRCUITS FROM THE ECU, CONNECTOR 24 THE SYSTEM IS OK. D1796B, PINS A1, A2, C8 AND C9, TO THE P2 SENSOR, YBMTS4, CONNECTOR P14, PINS 1, 2, 3 AND 4 (WDM 49-14-11). 1 THE AIR/GROUND RELAY, K214, CAN BE IN THE STUCK CLOSED (GROUND) POSITION WHILE THE AIRCRAFT IS IN THE AIR MODE OR THERE IS A GROUND WIRING PROBLEM FROM THE ECU TO THE RELAY. REPLACE THE AIR/GROUND RELAY, K214 (AMM 32-09-02/201) OR IF THE PROBLEM CONTINUES, EXAMINE THE CIRCUIT FROM THE ECU, CONNECTOR D1786B, PIN D6, TO THE AIR/GROUND RELAY, K214,

ERASE THE "APU BITE" MESSAGE ON EICAS IF IT SHOWS (FIM 31-41-00/101, FIG. 109).

DO THE SELF-TEST (FIG. 103, BLOCK 3) TO MAKE SURE THE PROBLEM IS REPAIRED.

YOU FIND.

Faulty LRU - P2 SENSOR on BITE Figure 130

CONNECTOR D636, PIN 8 (WDM 49-61-11) 1.

REPAIR THE PROBLEMS THAT

DOES THE PROBLEM CONTINUE?


FAULTY LRU - "P2 SENSOR" ON BITE

49–11–00

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

FAULTY LRU - "ECU" ON BITE MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



DO THE SELF-TEST (FIG. 103, BLOCK 3) TO MAKE SURE THE PROBLEM IS REPAIRED.


Faulty LRU - ECU on BITE Figure 131 (Sheet 1)

49-11-00

80

CONFIG 2 Page 180F Jan 28/05






Faulty LRU - ECU on BITE Figure 131 (Sheet 2)

49–11–00






Faulty LRU - ECU on BITE Figure 131 (Sheet 3)

49-11-00

06

CONFIG 2 Page 180H Jan 28/05






Faulty LRU - ECU on BITE Figure 131 (Sheet 4)

EFFECTIVITY-AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT





Faulty LRU - ECU on BITE Figure 131 (Sheet 5)

AIRPLANES WITH THE APU CONTROL
UNIT -19 AND SUBSEQUENT

49-11-00

80

CONFIG 2 Page 180J Jan 28/05




MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,
APU START,APU INLET DR ACT (AFT EQUIPMENT
CENTER, E6)

FAULTY LRU - "INLET DOOR RLY" ON BITE

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

Faulty LRU - INLET DOOR RLY on BITE Figure 132


49-11-00

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

AUTO SHUTDOWN "NORMAL STOP SIG" ON BITE



Auto Shutdown - NORMAL STOP SIG on BITE Figure 133

AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

49-11-00

OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF/APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.



MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

FAULTY LRU - "EGT #1 CIRCUIT" ON BITE

DO THIS PROCEDURE: APU
BITE PROCEDURE (FIG. 103)(IF
YOU HAVE NOT DONE IT BEFORE).
THE EGT VALUE IS LESS THAN
-100°F ABSOLUTE, OR THE EGT #2
VALUE IS +150°F MORE THAN
EGT #1.
REPLACE THE LEET SIDE

NO

REPLACE THE LEFT SIDE
THERMOCOUPLES, YBMTS6
(AMM 49-71-01/201). 2
DOES THE PROBLEM CONTINUE?

NOTE: THE ECU MONITORS BOTH
OF THE THERMOCOUPLE
RAKES. BOTH RAKES MUST
HAVE A FAILURE TO CAUSE
AN AUTOMATIC SHUTDOWN.

10 DISCONNECT THE APU 21 REPAIR THE PROBLEMS THAT HARNESS, CONNECTOR D40200P, AT YOU FIND. 1> THE FIREWALL. MEASURE THE LOOP RESIS-TANCE FROM PIN 10 TO 24 (WDM 49-14-11). THE RESIS-TANCE MUST BE LESS THAN 5.0 OHMS. IS THE RESISTANCE WITHIN THE LIMITS? YES 11 EXAMINE THE CIRCUIT FROM 22 THE SYSTEM IS OK. 1 THE FIREWALL, CONNECTOR D40200J, PINS 10 AND 24, TO THE ECU, M206, CONNECTOR D1796B, PINS A6 AND A7 (WDM 49-14-11). REPAIR THE OPEN OR GROUNDED CIRCUITS. 2 DOES THE PROBLEM CONTINUE? YES 23 REPLACE THE FUEL MANIFOLDS (AMM 49-31-06/401). 1> 2> IF THE PROBLEM CONTINUES,

IF THE PROBLEM CONTINUES,
REPLACE THE ECU, M206
(AMM 49-61-05/201). 2

NOTE: A DAMAGED POWER SECTION
CAN CAUSE A LARGE

20 THE SYSTEM IS OK. 1>

DIFFERENCE IN EGT #1
AND EGT #2 VALUES.

IF THE PROBLEM CONTINUES,

REPLACE THE APU (AMM 49-11-01/401).

1> ERASE THE "APU BITE" MESSAGE ON EICAS IF IT SHOWS (FIM 31-41-00/101, FIG. 109).

> OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

Faulty LRU - EGT #1 CIRCUIT on BITE Figure 134

AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

49-11-00

07

CONFIG 2 Page 180M Jan 28/05



MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,
APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

FAULTY LRU - "EGT #2 CIRCUIT" ON BITE

DO THIS PROCEDURE: APU
BITE PROCEDURE (FIG. 103)(IF
YOU HAVE NOT DONE IT BEFORE).
THE EGT VALUE IS LESS THAN
-100°F ABSOLUTE, OR THE EGT #1
VALUE IS +150°F MORE THAN
EGT #2.
REPLACE THE RIGHT SIDE

NO

THERMOCOUPLES, YBMTS7
(AMM 49-71-01/201). 2
DOES THE PROBLEM CONTINUE?

NOTE: THE ECU MONITORS BOTH
OF THE THERMOCOUPLE
RAKES. BOTH RAKES MUST
HAVE A FAILURE TO CAUSE
AN AUTOMATIC SHUTDOWN.

THE FIREWALL.

MEASURE THE LOOP RESISTANCE WITHIN THE LIMITS?

NO

21 REPAIR THE PROBLEMS THAT YOU FIND.

YOU FIND.

1 REPAIR THE PROBLEMS THAT YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

YOU FIND.

THE FIREWALL, CONNECTOR
D40200J, PINS 11 AND 25, TO
THE ECU, M206, CONNECTOR
D1796B, PINS A8 AND A9
(WDM 49-14-11).
REPAIR THE OPEN OR
GROUNDED CIRCUITS. 2
DOES THE PROBLEM CONTINUE?

YES

23 REPLACE THE FUEL MANIFOLDS

(AMM 49-31-06/401). 1 2

IF THE PROBLEM CONTINUES,
REPLACE THE ECU, M206
(AMM 49-61-05/201). 2

22 THE SYSTEM IS OK. 1

20 THE SYSTEM IS OK. 1>

NOTE: A DAMAGED POWER SECTION
CAN CAUSE A LARGE
DIFFERENCE IN EGT #1
AND EGT #2 VALUES.

IF THE PROBLEM CONTINUES,

REPLACE THE APU (AMM 49-11-01/401).

1> ERASE THE "APU BITE" MESSAGE ON EICAS IF IT SHOWS (FIM 31-41-00/101, FIG. 109).

OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

Faulty LRU - EGT #2 CIRCUIT on BITE Figure 135

AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

49-11-00


CONFIG 2 11 Page 180N Jan 28/05

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,
APU START,APU INLET DR ACT (AFT EQUIPMENT
CENTER, E6)

FAULTY LRU - "#1 SPD SENSOR" ON BITE

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



1> ERASE THE "APU BITE" MESSAGE ON EICAS IF IT SHOWS (FIM 31-41-00/101, FIG. 109).


OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

Faulty LRU - #1 SPD SENSOR on BITE Figure 136 (Sheet 1)

AIRPLANES WITH THE APU CONTROL
UNIT -19 AND SUBSEQUENT

49–11–00





Faulty LRU - #1 SPD SENSOR on BITE Figure 136 (Sheet 2)

49-11-00

E68674




CENTER, E6)

PREQUISITES MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201) MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT,

FAULTY LRU - "#2 SPD SENSOR" ON BITE

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

APU START, APU INLET DR ACT (AFT EQUIPMENT




1 ERASE THE "APU BITE" MESSAGE ON EICAS IF IT SHOWS (FIM 31-41-00/101, FIG. 109).

OPERATE THE APU (AMM 49-11-00/201) AND DO THIS PROCEDURE: APU BITE PROCEDURE (FIG. 103) TO MAKE SURE THE PROBLEM IS REPAIRED.

Faulty LRU - #2 SPD SENSOR on BITE Figure 137 (Sheet 1)

49–11–00





Faulty LRU - #2 SPD SENSOR on BITE Figure 137 (Sheet 2)

AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

49-11-00

09


CONFIG 2 Page 180R Jan 28/05



MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E3,6H12,6H23,11B34,11C33,11D32,11D35,APU CONT, APU START,APU INLET DR ACT (AFT EQUIPMENT CENTER, E6)

AUTO SHUTDOWN - "DC MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



AN AUTOMATIC SHUTDOWN WILL CAUSE THE EICAS TO WRITE AN AUTO-EVENT FOR THE SHUTDOWN. AFTER THE PROBLEM IS CORRECTED, PUSH THE "PERF/APU" AND THE "AUTO-EVENT READ" SWITCHES ON THE P61 PANEL. PUSH THE "ERASE" SWITCH FOR 3 SECONDS. MAKE SURE THE "APU-FAULT" IS ERASED.

DO THE SELF-TEST (FIG. 103, BLOCK 3) TO MAKE SURE THE PROBLEM IS REPAIRED.

Auto Shutdown - DC PWR LOSS on BITE Figure 138

49–11–00



APU MOUNTS


COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
BRACKET - APU MOUNTING SUPPORT AND VIBRATION		3	316AR,315AL, APU COMPT	49-13-03
ISOLATOR MOUNT - APU AFT SUPPORT AND VIBRATION		2	316AR,315AL APU COMPT	49-13-02
ISOLATOR MOUNTS - APU FORWARD		1	316AR,315AL APU COMPT	49-13-01


APU Mounts - Component Index Figure 101

EFFECTIVITY-ALL

49-13-00







APU Mounts - Component Location Figure 102

EFFECTIVITY-ALL

49-13-00

01

Page 102 Sep 20/94



APU AIR INTAKE

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
ACTUATOR - DOOR, M406		1	311AL, STABILIZER COMPT, AUXILIARY POWER UNIT	49-15-06
DOOR		1	311AL, STABILIZER COMPT, APU AIR INTAKE DOOR	49-15-05
DUCT		2	AUXILIARY POWER UNIT	49-15-01
HOUSING		1	311AL, STABILIZER COMPT, APU AIR INTAKE DOOR	49-15-08
PLENUM		1	313AL,315AL,316AR, APU COMPT, AUXILIARY POWER UNIT	49-15-03
RELAY - (31-01-06/101) APU INLET DOOR RELAY, K176				
SEAL - DOOR		1	311AL, STABILIZER COMPT, APU AIR INTAKE DOOR	49-15-07
SEAL - PLENUM FLANGE		1	315AL,316AR, APU COMPT, APU AIR INTAKE PLENUM	49-15-04
SWITCH - DOOR, \$10031		1	311AL, STABILIZER COMPT, APU AIR INTAKE DOOR	49-15-02
UNIT - (49-61-00/101) APU CONTROL, M206				


APU Air Intake - Component Index Figure 101


49-15-00


01

Page 101 Dec 20/91









APU Air Intake - Component Location Figure 102

ALL

O1 Page 102

Dec 20/91

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.



APU DRAINS AND VENTS

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
DRAIN - AIR INTAKE HOUSING AND DUCT	1	1	311AL, STABILIZER COMPT	49-15-00
DRAIN - APU INLET PLENUM	2	1	315AL,316AR, APU COMPT, BOTTOM OF INLET PLENUM	49–16–00
DRAIN - APU PLENUM	1	1	315AL,316AR, APU COMPT, LEFT FORWARD CORNER	49-16-03
DRAIN - BEARING SEAL CAVITY	2	1	315AL,316AR, APU COMPT, DRAIN	49-16-00
DRAIN - FORWARD BEARING SEAL CAVITY - TELL TALE	2	1	315AL,316AR, APU COMPT, BOTTOM OF INLET PLENUM	49-16-00
DRAIN - FUEL CONTROL UNIT/OIL PUMP/IGV ACTUATOR	2	1	315AL,316AR, APU COMPT, DRAIN	49-16-00
DRAIN - FUEL CONTROL UNIT/OIL PUMP - TELL TALE	2	1	315AL,316AR, APU COMPT, BOTTOM OF INLET PLENUM	49-16-00
DRAIN - FUEL FLOW DIVIDER	2	1	315AL,316AR, APU COMPT, BOTTOM OF COMBUSTOR	49-16-00
DRAIN - HEAT SHIELD	2	1	315AL,316AR, APU COMPT, DRAIN	49-16-00
DRAIN - IGV ACTUATOR - TELL TALE	2	1	315AL,316AR, APU COMPT, BOTTOM OF INLET PLENUM	49-16-00
DRAIN - MID-BEARING SEAL CAVITY - TELL TALE	2	2	315AL,316AR, APU COMPT, BOTTOM OF INLET PLENUM	49-16-00
DRAIN - OIL SCUPPER	1	1	315AL,316AR, APU COMPT, LOWER LEFT SIDE OF APU	49-27-00
DRAIN - TURBINE PLENUM	2	1	315AL,316AR, APU COMPT, DRAIN	49-16-00
LINE - INFLIGHT PRESSURE	2	1	315AL,316AR, APU COMPT, BOTTOM OF COMBUSTOR	49-16-00
MAST - APU DRAIN	2	1	315AL,316AR, APU COMPT, DRAIN	49-16-00
TANK - APU DRAIN	2	1	315AL,316AR, APU COMPT, BOTTOM OF COMBUSTOR	49-16-00

APU Drains and Vents - Component Index Figure 101

EFFECTIVITY-


ALL


49-16-00

06

Page 101 Dec 20/91







APU Drains and Vents - Component Location Figure 102 (Sheet 1)

EFFECTIVITY-ALL


49-16-00


01


Page 102 Dec 20/91



FAULT ISOLATION/MAINT MANUAL







(VIEW IN THE FORWARD DIRECTION)

E

APU Drains and Vents - Component Location Figure 102 (Sheet 2)

ALL

318369

49-16-00

04

Page 103 Sep 20/95



APU AND GENERATOR LUBRICATION SYSTEM

	FIG.			
	102			
COMPONENT	SHT	QTY	ACCESS/AREA	REFERENCE
COOLER - OIL	1	1	315AL,316AR, APU COMPT, UPPER COMPRESSOR SECTION	49-27-09
DETECTOR - COMPRESSOR BEARING MAGNETIC CHIP	4	1	315AL,316AR, APU COMPT, LEFT SIDE OF GEARBOX	49-27-04
DETECTOR - GEARBOX MAGNETIC CHIP	4	1	315AL,316AR, APU COMPT, BOTTOM OF GEARBOX	49-27-04
DETECTOR - GENERATOR SCAVENGE MAGNETIC CHIP	4	1	315AL,316AR, APU COMPT, BOTTOM OF GEARBOX	49-27-04
DETECTOR - TURBINE BEARING MAGNETIC CHIP	4	1	315AL,316AR, APU COMPT, RIGHT SIDE OF APU	49-27-04
ELEMENTS - OIL PRESSURE AND GENERATOR SCAVENGE FILTER	2	2	315AL,316AR, APU COMPT, GEARBOX ACCESSORIES	49-27-03
INDICATOR - GENERATOR OIL FILTER DIFFERENTIAL PRESSURE	2	1	315AL,316AR, APU COMPT, FRONT	49-27-16
INDICATOR - OIL FILTER DIFFERENTIAL PRESSURE	2	1	315AL,316AR, APU COMPT, GEARBOX ACCESSORIES	49-27-07
PLUG - DRAIN	4	1	315AL,316AR, APU COMPT, BOTTOM OF GEARBOX	49-27-04
PUMP - GENERATOR SCAVENGE OIL	2	1	315AL,316AR, APU COMPT, FRONT OF APU	49-27-02
PUMP - OIL	2	1	315AL,316AR, APU COMPT, GEARBOX ACCESSORIES	49-27-01
REGULATOR - OIL PRESSURE	2	1	315AL,316AR, APU COMPT, GEARBOX ACCESSORIES	49-27-05
SEAL PLATE - APU GENERATOR	3	1	315AL,316AR, APU COMPT, FRONT OF GEARBOX	49-27-06
SENSOR - (49-94-00/101) OIL TEMPERATURE, YBMTS1 SWITCHES - (49-94-00/101) LOW OIL LEVEL, YBMS3 1 LOW OIL PRESSURE, YBMS2				
SWITCH - GENERATOR OIL FILTER DIFFERENTIAL PRESSURE, YBMS1	2	1	315AL,316AR, APU COMPT, FRONT OF APU	49-27-15
SWITCH - LOW OIL TEMPERATURE, YBMS5	4	1	315AL,316AR, APU COMPT, BOTTOM OF GEARBOX	49-27-14
TRANSMITTER - (49-94-00/101) OIL QUANITY, YBMS3 2				
VALVE - DE-OIL SOLENOID, YBMM3	3	1	315AL,316AR, APU COMPT, FRONT OF GEARBOX	49-27-08
VALVE - GEARBOX PRESSURE REGULATING	3	1	315AL,316AR, APU COMPT, FRONT OF GEARBOX	49-27-12
VALVE - GEARBOX SHUTOFF	3	1	315AL,316AR, APU COMPT, RIGHT SIDE INLET PLENUM	49-27-11
VALVE - OIL COOLER BYPASS	1	1	315AL,316AR, APU COMPT, UPPER COMPRESSOR SECTION	49-27-10
VALVE - SHUTTLE	3	1	315AL,316AR, APU COMPT, RIGHT SIDE INLET PLENUM	49-27-13
UNIT - (49-61-00/101) APU CONTROL, M206				

* SEE THE WDM EQUIPMENT LIST

> GUI 001-114,116-999 GUI 115

> APU and Generator Lubrication System - Component Index Figure 101


EFFECTIVITY-

49-27-00


ALL

10 Page 101 Sep 20/92





AUXILIARY POWER UNIT



UPPER COMPRESSOR SECTION



APU and Generator Lubrication System - Component Location Figure 102 (Sheet 1)


ALL

49-27-00

01


Page 102 Dec 20/91





GEARBOX ACCESSORIES





APU and Generator Lubrication System - Component Location (Details from Sht 1) Figure 102 (Sheet 2)

ALL ALL


274773

49-27-00


01

Page 103 Dec 20/91





RIGHT SIDE OF THE INLET PLENUM



FRONT OF THE GEARBOX




APU and Generator Lubrication System - Component Location (Details from Sht 2) Figure 102 (Sheet 3)

EFFECTIVITY-ALL 49-27-00

03


Page 104 Dec 20/91






BOTTOM OF THE GEARBOX







RIGHT SIDE OF THE LOAD COMPRESSOR

(H)

LEFT SIDE OF THE LOAD COMPRESSOR

(I)

3 GUI 001-114,116-999

4 > GUI 115

APU and Generator Lubrication System - Component Location (Details from Sht 2) Figure 102 (Sheet 4)

49-27-00

09

Page 105 Sep 20/92



APU ENGINE FUEL SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
ELEMENT - FUEL FILTER	2	1	316AR,315AL, APU COMP, FRONT OF APU	49-31-04
ELEMENT - FUEL FLOW DIVIDER FILTER	1	1	316AR,315AL, APU COMP, LEFT SIDE OF COMBUSTOR	49-31-08
FILTER - FUEL HIGH PRESSURE	2	1	316AR,315AL, APU COMP, FRONT OF APU	49-31-07
HOSES - FUEL MANIFOLD	1	2	316AR,315AL, APU COMP, LEFT SIDE OF COMBUSTOR	49-31-09
MANIFOLDS AND NOZZLES	1	12	316AR,315AL, APU COMP, LEFT SIDE OF COMBUSTOR	49-31-06
MONOPOLE - (49-61-00/101) YBMTS8,YBMTS9				
SENSORS - (49-61-00/101) APU INLET PRESSURE, YBMTS4 APU INLET TEMPERATURE, YBMTS5				
THERMOCOUPLE ASSEMBLY - (49-71-00/101) YBMTS6,YBMTS7 UNIT - (49-61-00/101)				
APU CONTROL, M206				
UNIT - FUEL CONTROL	2	1	316AR,315AL, APU COMP, FRONT OF APU	49-31-01
VALVE - FUEL CONTROL SOLENOID, YBMV1	2	1	316AR,315AL, APU COMP, FRONT OF APU	49-31-02
VALVE - FUEL FILTER BYPASS	2	1	316AR,315AL, APU COMP, FRONT OF APU	49-31-05
VALVE - FUEL FLOW DIVIDER AND SOLENOID, YBMM2	1	1	316AR,315AL, APU COMP, LEFT SIDE OF COMBUSTOR	49-31-03


APU Engine Fuel System - Component Index Figure 101

EFFECTIVITY-

24242

49-31-00





APU Engine Fuel System - Component Location Figure 102 (Sheet 1)

ALL


ALL

O1 Page 102

Dec 20/91


BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.





FRONT OF THE APU





BYPASS VALVE



APU Engine Fuel System - Component Location Figure 102 (Sheet 2)

55313

49-31-00

01

Page 103 Dec 20/91



APU IGNITION/STARTING SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
BATTERY - (24-31-00/101)			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
APU, M208				
CIRCUIT BREAKER -			FLT COMPT, P6	
APU START TRU CONT, C865		1	6H12	*
CIRCUIT BREAKERS -			822, AFT EQUIP CTR, E6 RACK	
APU CONT, C1382		1		*
APU START, C2O APU START TRU FAN, C89		1 1		*
CIRCUIT BREAKER -		'	FLT COMPT, P11	_ ^
APU ALTN CONT, C1390		1	11B34	*
CIRCUIT BREAKER -		-	119BL, MAIN EQUIP CTR, P32	
APU START TRU POWER, C3000		1	32A6	*
CLUTCH - STARTER		1	316AR,315AL, APU COMP, FRONT OF APU	49-41-06
CONTACTOR - APU CRANK, K117		1	822, AFT EQUIP CTR, E6 RACK	*
LEAD - IGNITION		1	316AR,315AL, APU COMP, RIGHT SIDE OF COMBUSTOR	49-41-04
MOTOR - STARTER, M893		1	316AR,315AL, APU COMP, FRONT OF APU	49-41-01
PANEL - (49-61-00/101) APU START, M10324				
PLUG - IGNITER, YBMM7		1	316AR,315AL, APU COMP, RIGHT SIDE OF COMBUSTOR	49-41-02
RELAYS - (31-01-86/101) APU FAULT, K10033 APU START, K197 APU START CONTROL, K10030 APU START ENABLE, K10163 APU START TRU FAN CONT, K619 APU START TRU OVERHEAT, K616 APU TRU START, K10010 SWITCH - (24-33-00/101) BATTERY (S2) SWITCH - (26-22-00/101) APU FIRE, S39 SWITCH - (49-15-00/101) APU INLET DOOR, S10031 UNIT - (24-32-00/101) APU START TRANSFORMER RECTIFIER, T189 UNIT - (49-61-00/101)				
APU CONTROL, M206 UNIT - IGNITION, M1		1	316AR,315AL, APU COMP, RIGHT SIDE OF COMBUSTOR	49-41-03

^{*} SEE THE WDM EQUIPMENT LIST


APU Ignition/Starting System - Component Index Figure 101

EFFECTIVITY-ALL 49-41-00

319098



FAULT ISOLATION/MAINT MANUAL



APU Ignition/Starting System - Component Location Figure 102

ALL

ALL

O1 Page 102
Dec 20/91



APU COOLING AIR SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
DUCT - OIL COOLING		1	315AL,316AR, APU COMPT, LEFT SIDE PLENUM	49-51-01
FAN - COOLING		1	315AL,316AR, APU COMPT, AUXILIARY POWER UNIT	49-51-03
VALVE - FAN ISOLATION 1		1	315AL,316AR, APU COMPT, UPPER COMPRESSOR	49-51-02

1 APUS PRE-ALLIED SIGNAL -SB 49-7391


APU Cooling Air System - Component Index Figure 101

49-51-00

01

Page 101 Sep 20/98





BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

01

Page 102 Sep 20/98

ALL



APU BLEED AIR SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
ACTUATOR - INLET GUIDE VANE		1	316AR,315AL, APU COMP, LEFT SIDE COMPRESSOR	49-52-02


APU Bleed Air System - Component Index Figure 101


ALL


49-52-00

E48353









LEFT SIDE OF THE COMPRESSOR



APU Bleed Air System - Component Location Figure 102

54551

49-52-00

01

Page 102 Sep 20/94



APU SURGE BLEED SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
ELEMENT - SURGE VALVE FILTER		1	315AL,316AR, APU COMPT, SURGE	49-53-06
MODULE - FLOW SENSING		1	315AL,316AR, APU COMPT, BOTTOM OF GEARBOX	49-53-08
VALVE - SURGE		1	315AL,316AR, APU COMPT, SURGE DUCT	49-53-01


APU Surge Bleed System - Component Index Figure 101

ALL

49-53-00

E48368





APU Surge Bleed System - Component Location Figure 102

ALL 02 Page 102 Sep 28/04

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.



APU CONTROL SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
CIRCUIT BREAKERS -			FLT COMPT, P11	
APU ALTN CONT, C1390	-	1	11B34	*
APU CONT, C1382	_	1	822,E6, AFT EQUIP CENTER	*
MONOPOLE - APU	-	2	316AR,315AL	49-61-02
PANEL - APU CONTROL, M1	-	1	FLT COMPT, P5	*
SENSOR - APU INLET PRESSURE, YBMTS4	-	1	316AR,315AL, APU COMPT	49-61-04
SENSOR - APU INLET TEMPERATURE, YBMTS5	-	1	316AR,315AL, APU COMPT	49-61-03
UNIT - APU CONTROL, M206	-	1	822,E6, AFT EQUIP CENTER	49-61-05

^{*} SEE THE WDM EQUIPMENT LIST

APU Control System - Component Index Figure 101


 49-61-00


03


Page 101 Dec 20/91





FAULT ISOLATION/MAINT MANUAL













APU CONTROL PANEL, M1



AFT EQUIPMENT CENTER, E6





APU CONTROL UNIT, M206



APU Control System - Component Location Figure 102 (Sheet 1)


EFFECTIVITY-ALL

49-61-00

01

Page 102 Dec 20/94





APU CONTROL UNIT, M206



2 AIRPLANES WITH THE APU CONTROL UNIT -19 AND SUBSEQUENT

APU Control System - Component Location Figure 102 (Sheet 2)

49-61-00

01

Page 103 Dec 20/94



APU EXHAUST GAS TEMPERATURE INDICATING SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
ASSEMBLY - APU EGT THERMOCOUPLE, YBMTS6,YBMTS7 UNIT - (FIM 49-61-00/101) AUXILIARY POWER CONTROL, M206		2	316AR,315AL, APU COMPT	49-71-01


APU Exhaust Gas Temperature Indicating System - Component Index Figure 101


 49-71-00


01

Page 101 Sep 20/94









VIEW IN THE FORWARD DIRECTION



APU Exhaust Gas Temperature Indicating System - Component Location Figure 102

ALL

49-71-00

01

Page 102 Sep 20/94



APU TIME TOTALIZER AND CYCLEMETER

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
CYCLEMETER, N10032 HOURMETER, N10017		1	822, E6 AFT EQUIP CENTER 822, E6 AFT EQUIP CENTER	*

^{*} SEE THE WDM EQUIPMENT LIST


APU Time Totalizer and Cyclemeter - Component Index Figure 101


ALL

49-72-00

01


Page 101 Dec 20/93






ELECTRONIC EQUIPMENT RACK, E6

(AFT EQUIPMENT CENTER)



HOURMETER, N10017



CYCLEMETER, N10032

APU Time Totalizer and Cyclemeter - Component Location Figure 102

49-72-00

01

Page 102 Dec 20/95



APU EXHAUST SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
DUCT - EXHAUST INSULATION BLANKET - EXHAUST DUCT SUPPORT - EXHAUST DUCT	 	1 1 1	316AR,315AL, APU ACCESS DOORS 316AR,315AL, APU ACCESS DOORS 316AR,315AL, APU ACCESS DOORS	49-81-01 49-81-02 49-81-03

APU Exhaust System - Component Index Figure 101

ALL


E48399


49-81-00

01

Page 101 Sep 20/94







APU Exhaust System - Component Location Figure 102

ALL

ALL

O1 Page 102

Sep 20/94

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.



APU OIL INDICATING SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
SENSOR - OIL TEMPERATURE, YBMTS1		1	315AL,316AR, APU COMPT, RIGHT SIDE LOAD COMPRESSOR	49-94-01
SWITCH - LOW OIL LEVEL, YBMS3		1	315AL,316AR, APU COMPT, BOTTOM OF GEARBOX	49-94-03
SWITCH - LOW OIL PRESSURE, YBMS2	 	1	315AL,316AR, APU COMPT, RIGHT SIDE LOAD COMPRESSOR	49-94-02
TRANSMITTER - OIL QUANTITY, YBMS3 2		1	315AL,316AR, APU COMPT, BOTTOM OF GEARBOX	49-94-04

> GUI 001-114,116-999


APU Oil Indicating System - Component Index Figure 101


EFFECTIVITY-ALL

D04893

49-94-00







> GUI 001-114,116-999

A70467

APU Oil Indicating System - Component Location Figure 102

EFFECTIVITY-ALL

49-94-00

07

Page 102 Dec 20/93