



BOEING
767
FAULT ISOLATION/MAINT MANUAL

Scandinavian Airlines System

PAGE	DATE	CODE	PAGE	DATE	CODE	PAGE	DATE	CODE
CHAPTER 23 TAB			23-FAULT CODE DIAGRAM			CONT.		
COMMUNICATIONS			21	FEB 10/97	20	23-12-00		
EFFECTIVE PAGES			22	AUG 10/89	09	101	FEB 10/94	14
SEE LAST PAGE OF LIST FOR			23	FEB 10/97	13	102	FEB 10/94	04
NUMBER OF PAGES			24	DEC 22/05	12	103	APR 22/99	31
			25	DEC 22/01	13	104	APR 22/02	10
			26	DEC 22/01	12	105	MAY 10/96	05
			23-FAULT CODE INDEX			106	AUG 22/02	01
			1	DEC 22/01	16	107	AUG 22/02	04
23-CONTENTS			2	APR 22/01	24	108	BLANK	
1	DEC 22/08	SAS	3	AUG 22/01	19	23-21-00		
2	DEC 22/08	SAS	4	AUG 22/00	23	101	MAY 10/93	01
3	APR 22/09	SAS	R 5	AUG 22/09	16.1	102	MAY 10/93	13
4	DEC 22/99	SAS	R 6	MAY 10/96	24.101	23-22-00		
5	DEC 22/99	SAS	7	DEC 22/00	18	101	DEC 10/98	SAS
6	BLANK		8	DEC 22/01	23	102	DEC 10/98	SAS
23-HOW TO USE THE FIM			9	DEC 22/01	23	103	DEC 10/98	04
1	AUG 22/99	01	10	DEC 22/01	22	104	DEC 10/98	04
2	AUG 22/99	01	11	DEC 22/01	26	105	DEC 10/98	05
3	AUG 22/99	01	12	DEC 22/01	27	106	DEC 10/98	04
4	AUG 22/99	01	13	DEC 22/01	26	107	DEC 10/98	06
5	AUG 22/99	01	14	DEC 22/01	27	108	BLANK	
6	AUG 22/99	01	15	DEC 22/01	27	23-24-00		
23-INDEX			16	DEC 22/01	28	101	MAY 10/94	01
1	DEC 22/01	20	17	DEC 22/01	26	102	MAY 10/94	01
2	NOV 10/91	28	18	DEC 22/01	27	103	MAY 10/94	01
3	DEC 22/01	20	19	DEC 22/01	27	104	DEC 22/00	01
4	DEC 22/01	04	20	DEC 22/01	24	23-25-00		
23-EICAS MESSAGES			21	MAY 10/96	28	101	MAY 10/96	01
1	APR 22/99	01	22	AUG 22/00	30	102	MAY 10/96	01
2	DEC 22/01	06	23	AUG 22/00	30	103	MAY 10/96	01
3	APR 22/09	14	24	APR 22/03	30	104	BLANK	
4	DEC 22/05	04	25	MAY 10/96	18	23-31-00		
23-FAULT CODE DIAGRAM			26	DEC 22/01	25	101	NOV 10/90	28
1	AUG 10/89	24	27	DEC 22/01	07	102	NOV 10/90	28
2	FEB 10/97	07	28	MAY 10/96	13	103	NOV 10/90	27
3	MAY 10/89	24	29	MAY 10/96	10	104	FEB 10/96	11
4	AUG 10/89	25	30	DEC 22/99	10	105	DEC 22/01	07
5	AUG 10/89	10	31	DEC 22/99	07	106	DEC 22/01	10
6	AUG 10/89	11	32	BLANK		107	AUG 10/98	06
7	MAY 10/93	26	23-BITE INDEX			108	BLANK	
8	MAY 10/92	06	1	AUG 22/99	01	23-32-00 CONFIG 1		
9	AUG 10/91	26	2	AUG 22/99	01	101	DEC 22/06	01
10	AUG 10/91	31	3	AUG 22/99	01	102	NOV 10/90	01
11	AUG 10/89	27	4	BLANK		103	NOV 10/90	01
12	AUG 22/00	06	23-11-00			104	NOV 10/90	01
13	AUG 22/00	11	101	AUG 10/90	07	105	NOV 10/90	01
14	DEC 22/99	04	102	AUG 10/90	07	106	NOV 10/90	01
15	AUG 10/89	27	103	AUG 10/90	08	23-32-00 CONFIG 2		
16	NOV 10/91	22	104	AUG 22/05	04	101	DEC 22/06	01
17	APR 10/98	14	105	AUG 22/00	04	102	NOV 10/92	01
18	MAY 10/92	21	106	AUG 10/97	04	103	AUG 22/01	01
19	AUG 22/00	24	107	AUG 10/97	05	104	AUG 22/01	01
20	AUG 22/05	13	108	AUG 10/97	06			
			109	AUG 22/02	05			
			110	AUG 10/97	05			

R = REVISED, A = ADDED OR D = DELETED
F = FOLDOUT PAGE
33
AUG 22/09

D633T633

CHAPTER 23
EFFECTIVE PAGES
PAGE 1
CONTINUED



BOEING
767
FAULT ISOLATION/MAINT MANUAL

Scandinavian Airlines System

PAGE	DATE	CODE	PAGE	DATE	CODE	PAGE	DATE	CODE
23-32-00	CONFIG 2	CONT.	23-51-00					
105	AUG 22/01	01	101	AUG 10/90	17			
106	AUG 22/01	01	102	AUG 10/90	16			
107	NOV 10/92	01	103	AUG 10/90	18			
108	NOV 10/92	01	104	AUG 10/90	18			
109	NOV 10/92	01						
110	BLANK		23-61-00					
23-34-00			101	APR 22/01	01			
101	NOV 10/92	21	102	APR 22/01	01			
102	NOV 10/92	21	103	AUG 22/99	01			
103	NOV 10/92	28	104	AUG 22/99	01			
104	NOV 10/92	22	105	AUG 22/99	01			
105	NOV 10/92	15	106	AUG 22/99	01			
106	NOV 10/92	15	23-71-00					
107	NOV 10/92	17	101	FEB 10/88	03			
108	NOV 10/92	15	102	NOV 10/88	10			
109	APR 22/07	14	103	APR 22/05	13			
110	NOV 10/92	10	104	APR 22/05	13			
111	APR 22/07	08	105	DEC 10/98	02			
112	NOV 10/92	06	106	NOV 10/91	01			
113	NOV 10/92	04	107	DEC 10/98	01			
114	BLANK		108	BLANK				
23-41-00								
101	DEC 22/06	01						
102	FEB 10/94	01						
103	FEB 10/94	01						
104	BLANK							
23-42-00	CONFIG 1							
101	MAY 10/94	01						
102	AUG 10/90	01						
103	FEB 10/91	01						
104	MAY 10/94	01						
105	MAY 10/94	01						
106	MAY 10/94	01						
107	MAY 10/94	01						
108	BLANK							
23-42-00	CONFIG 2							
101	MAY 10/94	01						
102	MAY 10/94	01						
103	MAY 10/94	01						
104	MAY 10/94	01						
105	MAY 10/94	01						
106	BLANK							
23-43-00								
101	MAY 10/94	01						
102	MAY 10/94	01						
103	MAY 10/94	01						
104	MAY 10/94	01						
105	MAY 10/94	01						
106	BLANK							

R = REVISED, A = ADDED OR D = DELETED
 F = FOLDOUT PAGE
 33
 AUG 22/09

D633T633

CHAPTER 23
 EFFECTIVE PAGES
 PAGE 2
 LAST PAGE



BOEING
767
FAULT ISOLATION/MAINT MANUAL

CHAPTER 23 - COMMUNICATIONS

TABLE OF CONTENTS

<u>Subject</u>	Chapter Section <u>Subject</u>	<u>Page</u>	<u>Effectivity</u>
HOW TO USE THE FIM	23-HOW TO USE THE FIM	1	ALL
INDEX	23-INDEX	1	ALL
EICAS MESSAGES	23-EICAS MESSAGES	1	ALL
FAULT CODE DIAGRAMS	23-FAULT CODE DIAGRAM	1	ALL
FAULT CODE INDEX	23-FAULT CODE INDEX	1	ALL
BITE INDEX	23-BITE INDEX	1	ALL
<u>COMMUNICATIONS</u>	23-00-00		
<u>SPEECH COMMUNICATIONS</u>	23-10-00		
HF COMMUNICATION SYSTEM	23-11-00		
Component Location		101	ALL
Component Index			
Component Location			
Fault Isolation			
High Frequency Communication System - BITE Procedure (Figure 103)		104	
VHF COMMUNICATION SYSTEM	23-12-00		
Component Location		101	ALL
Component Index			
Component Location			
Fault Isolation			
VHF Communications Transceiver BITE Procedure (Fig. 103)		104	
<u>DATA TRANSMISSION AND AUTOMATIC CALLING</u>	23-20-00		
SELCAL SYSTEM	23-21-00		
Component Location		101	ALL
Component Index			
Component Location			

23-CONTENTS

SAS

Page 1
Dec 22/08



767
FAULT ISOLATION/MAINT MANUAL

CHAPTER 23 - COMMUNICATIONS

TABLE OF CONTENTS

<u>Subject</u>	<u>Chapter Section Subject</u>	<u>Page</u>	<u>Effectivity</u>
ACARS	23-22-00		
Component Location		101	[*]
Component Index			
Component Location			
Fault Isolation			
ACARS Management Unit (MU)		104	
BITE Procedure (Fig. 103)			
SAS [*] SAS 150, 152-157, 162-167 MTH			
SAS 275-278, 280-281			
EMERGENCY LOCATOR TRANSMITTER	23-24-00		
Component Location		101	[*]
Component Index			
Component Location			
Fault Isolation			
Emergency Locator Transmitter		104	
(ELT) Fault Isolation (Fig. 103)			
[*] SAS 050-274			
SATELLITE COMMUNICATION (SATCOM) SYSTEM	23-25-00		
Component Location		101	[*]
Component Index			
Component Location			
[*] SAS 150,153-157,162-167 AFTER PROJECT: MT0-230591,230592,230593			
<u>PASSENGER ADDRESS AND ENTERTAINMENT</u>	23-30-00		
PASSENGER ADDRESS SYSTEM	23-31-00		
Component Location		101	ALL
Component Index			
Component Location			
Fault Isolation			
Passenger Address Amplifier		107	
BITE Procedure (Fig. 103)			



BOEING
767
FAULT ISOLATION/MAINT MANUAL

CHAPTER 23 - COMMUNICATIONS

TABLE OF CONTENTS

<u>Subject</u>	Chapter Section <u>Subject</u>	<u>Page</u>	<u>Effectivity</u>
PASSENGER ENTERTAINMENT (VIDEO PROJECTION)	23-32-00		
Component Location		101	CONFIG 1 [*]
Component Index			
Component Location			
[*] ALL SAS AIRPLANES			
Component Location		101	CONFIG 2 [*]
Component Index			
Component Location			
[*] ALL MTH AIRPLANES			
PASSENGER ENTERTAINMENT/PASSENGER SERVICE SYSTEM	23-34-00		
Component Location		101	ALL
Component Index			
Component Location			
Fault Isolation			
Cabin Chime Sounds		109	
Intermittently (Fig. 103)			
Passenger		111	
Entertainment/Passenger			
Service System BITE Procedure (Fig. 104)			
<u>INTERPHONE</u>	23-40-00		
SERVICE INTERPHONE SYSTEM	23-41-00		
Component Location		101	ALL
Component Index			
Component Location			



BOEING
767
FAULT ISOLATION/MAINT MANUAL

CHAPTER 23 - COMMUNICATIONS

TABLE OF CONTENTS

<u>Subject</u>	Chapter Section <u>Subject</u>	<u>Page</u>	<u>Effectivity</u>
CABIN INTERPHONE SYSTEM	23-42-00		
Component Location		101	CONFIG 1 [*]
Component Index			
Component Location			
Fault Isolation			
Cabin Chime and Call		107	
Light/Attendant Call from			
Pilot or Attendant Problem			
(Fig. 103)			
[*] ALL SAS AIRPLANES			
Component Location		101	CONFIG 2 [*]
Component Index			
Component Location			
Fault Isolation			
Cabin Chime and Call		105	
Light/Attendant Call from			
Pilot or Attendant Problem			
(Fig. 103)			
[*] ALL MTH AIRPLANES			
GROUND CREW CALL SYSTEM	23-43-00		
Component Location		101	ALL
Component Index			
Component Location			
Fault Isolation			
Ground Crew Call Horn Fails to		104	
Sound. Equipment Cooling			
Failure Indicators On. (Fig.			
104)			
Ground Crew Call Horn Fails to		105	
Sound. IRS Mode Select Switch			
(L,C, or R) On. L and R DC			
Power Off. (Fig. 105)			
Ground Crew Call Horn Sounds		103	
Continuously (Fig. 103)			
<u>AUDIO INTEGRATING</u>	23-50-00		
FLIGHT INTERPHONE SYSTEM	23-51-00		
Component Location		101	ALL
Component Index			
Component Location			

23-CONTENTS

SAS

Page 4
Dec 22/99




BOEING
767
FAULT ISOLATION/MAINT MANUAL

CHAPTER 23 - COMMUNICATIONS

TABLE OF CONTENTS

<u>Subject</u>	Chapter Section <u>Subject</u>	<u>Page</u>	<u>Effectivity</u>
<u>STATIC DISCHARGING</u>	23-60-00		
STATIC DISCHARGERS	23-61-00		
Component Location		101	ALL
Component Index			
Component Location			
<u>AUDIO AND VIDEO MONITORING</u>	23-70-00		
VOICE RECORDER SYSTEM	23-71-00		
Component Location		101	ALL
Component Index			
Component Location			
Fault Isolation			
Voice Recorder BITE Procedure (Fig. 103)		103	
Voice Recorder System Fault Isolation (Fig. 104)		104	



Basic Fault Isolation Process
Figure 1


EFFECTIVITY

ALL

23-HOW TO USE THE FIM

01

Page 1
Aug 22/99



How to Get Fault Information from BITE
Figure 2


EFFECTIVITY

ALL

23-HOW TO USE THE FIM

01

Page 2
Aug 22/99



How to Find the Corrective Action or Fault Isolation Procedure in the FIM

Figure 3

EFFECTIVITY

ALL

23-HOW TO USE THE FIM

01

Page 3
Aug 22/99

ASSUMED CONDITIONS AT START OF TASK

- External electrical power is OFF
- Hydraulic power and pneumatic power are OFF
- Engines are shut down
- Circuit breakers for the system are closed
- No equipment in the system is deactivated

PREREQUISITES

- This box gives the steps to get the airplane from the normal shutdown condition to the configuration necessary to do the fault isolation procedure.
- The Prerequisites give procedure references, circuit breakers, and special tools and equipment requirements.

FAULT ISOLATION BLOCKS

- Start the fault isolation procedure at block 1 unless specified differently.
- Do the check to get an answer to the question in the box. Follow the arrow that applies to your answer. This will go to the next check.
- When you get to a box in the column at the right of the page, you have isolated that fault. Do the steps in that box to repair the cause of the fault.
- Make sure that fault is corrected to complete the procedure.

Do the Fault Isolation Procedure
Figure 4


EFFECTIVITY

ALL

23-HOW TO USE THE FIM

01


Page 4
Aug 22/99



Subjects in Each FIM Chapter
Figure 5 (Sheet 1)

EFFECTIVITY ALL	<h1 style="margin: 0;">23-HOW TO USE THE FIM</h1> <p align="right">01 Page 5 Aug 22/99</p>
------------------------	---

K37638



Alphabetical list of the EICAS messages. Gives the procedure to repair the cause of the message or a reference to a fault isolation procedure.

Failure analysis diagrams for the airplane systems to find the correct fault code for the fault.

Numerical list of fault codes. Gives the procedure to repair the cause of the fault or a reference to a fault isolation procedure.

EFFECTIVITY	ALL	21-EICAS MESSAGES	Page 1 Apr 22/99
-------------	-----	-------------------	---------------------

EFFECTIVITY	ALL	21-FAULT CODE DIAGRAMS	Page 1 Apr 22/99
-------------	-----	------------------------	---------------------

EFFECTIVITY	ALL	21-FAULT CODE INDEX	Page 1 Apr 22/99
-------------	-----	---------------------	---------------------

EFFECTIVITY	ALL	21-BITE INDEX	Page 1 Apr 22/99
-------------	-----	---------------	---------------------

EFFECTIVITY	ALL	21-11-00	Page 101 Apr 22/99
-------------	-----	----------	-----------------------

Alphabetical list of all the LRUs/systems that have BITE. Gives the chapter/section for the BITE procedure.

Component index, component location, and fault isolation procedures for the systems in the chapter.

Subjects in Each FIM Chapter
Figure 5 (Sheet 2)

EFFECTIVITY	ALL
-------------	-----

23-HOW TO USE THE FIM

<u>TITLE</u>	<u>CHAP/SEC</u>
ACARS	2322
ATTENDANT	
CALL FROM ATTENDANT	2342
CALL FROM LAV	3325
CALL FROM PILOT	2342
CALL FROM SEATS	2334
AUDIO SELECTOR PANEL (ASP)	2351
BOARDING MUSIC	2331
CABIN	
CHIME	2342
HANDSET	2342
INTERPHONE	2342
SPEAKER	2331
COCKPIT	
CALL	2342
CHIME	2342
HANDSET	2342
HEADSET	2351
MIC	2351
SPEAKER	2351
EMERGENCY LOCATOR TRANSMITTER	2324
FLIGHT INTERPHONE	2351
GROUND CALL	2343
HF COMM	2311
PASSENGER ADDRESS	2331
PASSENGER ENTERTAINMENT	2334
PRERECORDED ANNOUNCEMENTS	2331
PRINTER	3135
PUSH TO TALK (PTT)	2351
READING LIGHTS	2334
SELCAL	2321
SERVICE INTERPHONE	2341
VHF COMM	2312
VIDEO	
CONTROL UNIT	2332
SOUND TRACK	2332
TAPE REPRODUCER	2332
VOICE RECORDER	2371

COMMUNICATIONS – INDEX





EFFECTIVITY

ALL

23-INDEX




BOEING

767 FAULT ISOLATION/MAINT MANUAL



OVERHEAD PANEL 2342 2343 2351



OVERHEAD PANEL



2351 2312 2312 2342, 2351 2311

2341
ACCESSORY PANEL

OVERHEAD PANEL



AFT ELECTRONIC & ACCESSORY PANEL CHAPTER 34

FWD ATTND PANEL

2334

- 1 IF INSTALLED
- 2 AS INSTALLED













COMMUNICATIONS - INDEX

EFFECTIVITY	ALL
-------------	-----

23-INDEX

BOEING

767 FAULT ISOLATION/MAINT MANUAL



AS INSTALLED

COMMUNICATIONS - INDEX

EFFECTIVITY	ALL
-------------	-----


23-INDEX

589874

BOEING


767

FAULT ISOLATION/MAINT MANUAL



AFT ELECTRONICS PANEL

2322




AFT ELECTRONICS PANEL

3135

1


2331




PURSER'S STATION

2331

2331



OR



1 AS INSTALLED

COMMUNICATIONS - INDEX

EFFECTIVITY

ALL

23-INDEX

04

Page 4
Dec 22/01

COMMUNICATIONS – EICAS MESSAGE LIST

1. General

A. This procedure shows the EICAS message list of procedures.

(1) The EICAS MESSAGE LIST gives the message, level, and procedure for each message.

(a) The EICAS MESSAGE column lists the messages alphabetically. Messages which start with L, R, or C are put together and alphabetized at L.

(b) The LEVEL column gives all levels for each message as follows:

A – Warning messages

B – Caution messages

C – Advisory messages

E – Communications messages (with aural chime)

F – Communications messages

S – Status messages

M – Maintenance messages

(c) The PROCEDURE column gives the steps that are necessary to remove the message and includes one or more of the procedures that follow:

1) A Fault Isolation Manual procedure reference

2) A Maintenance Manual procedure and reference

3) Wiring checks and a Wiring Diagram Manual reference

4) A reference to an EICAS message list in a different chapter.

5) A reference to a FAULT CODE INDEX and specified fault codes

6) A step to change the airplane configuration

EFFECTIVITY

ALL

23-EICAS MESSAGES

01

Page 1
Apr 22/99


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

EICAS MESSAGE LIST		
EICAS MESSAGE	LEVEL	PROCEDURE
ACARS	E	A company medium priority uplink message has been received by ACARS. This message requires crew action.
ACARS	F	A company low priority uplink message has been received by ACARS. This message requires crew action.
CABIN ALERT	E	<p>An alert call is received over the cabin interphone. Push the ALERT switch-light on the Pilot's call panel to reset the system.</p> <p>AIRPLANES WITH -1001 EICAS COMPUTERS; This message can be a nuisance message. To do a check for a nuisance message, put the EICAS computer select switch to an alternative position. If the message does not show, it was a nuisance message. Open and close the circuit breakers for the EICAS computer that had the message.</p>
CABIN CALL	E	An interphone call is received from the cabin. Push the FWD, MID or AFT switch-light on the Pilot's call panel to reset.
DATALINK AVAIL	F	ACARS Datalink is active after being in a NO COMM condition.
DATALINK LOST	C	Total loss of datalink capability due to the ACARS being in "NO COMM" condition. The "NO COMM" condition is a normal condition if the airplane is out of range of an ACARS ground station, or if the ACARS ground network is not operational. If ACARS operates correctly on other airplanes at the same location, do this fault isolation procedure: FIM 23-22-00/101, Figure 103, block 1.
DATALINK SYS	C	Total loss of datalink capability due to ACARS MU Failure (FIM 23-22-00/101).
ELT ON	C	Emergency locator transmitter (ELT) is on. Reset with switch on pilots call panel (FIM 23-24-00/101).

EFFECTIVITY

ALL

23-EICAS MESSAGES

06

Page 2
Dec 22/01



BOEING
767
FAULT ISOLATION/MAINT MANUAL

EICAS MESSAGE LIST		
EICAS MESSAGE	LEVEL	PROCEDURE
GROUND CALL	E	An interphone call is received from the nose landing gear. EICAS message goes off after 30 seconds.
HF DATALINK	C	Total failure of L and R data function. This message inhibited by DATALINK SYS.
PRINTER	E, F	A message is available on the printer.
RADIO TRANSMIT	C	HF or VHF communication system in continuous transmit mode. Do a check of the PTT switches and PTT wiring (FIM 23-12-00/101, Fig. 103). AIRPLANES WITH -1001 EICAS COMPUTERS; This message can be a nuisance message. To do a check for a nuisance message, put the EICAS computer select switch to an alternative position. If the message does not show, it was a nuisance message. Open and close the circuit breakers for the EICAS computer that had the message.
SATCOM	C	Loss of both satellite voice and data capability due to SATCOM system failure (FIM 23-25-00/101)
SATCOM DATA	S,M	Interface failure between ACARS and SATCOM (FIM 23-22-00/101 and FIM 23-25-00/101).
SATCOM DATALINK	C	Interface failure between ACARS and SATCOM (FIM 23-22-00/101 and FIM 23-25-00/101).
SATCOM HIGH GAIN	S,M	SATCOM high gain or intermediate gain antenna subsystem failure (FIM 23-25-00/101).
SATCOM LOW GAIN	S,M	SATCOM low gain antenna subsystem failure (FIM 23-25-00/101)
SATCOM MESSAGE	E	A failure or status message for an air-to-ground call is displayed on the SATCOM Main Menu page (on the CDU). (FIM 23-25-00/101).

EFFECTIVITY

ALL

23-EICAS MESSAGES

14

Page 3
Apr 22/09


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

EICAS MESSAGE LIST		
EICAS MESSAGE	LEVEL	PROCEDURE
SATCOM VOICE	C	Total loss of voice capability due to equipment failure (FIM 23-25-00/101).
L SATCOM VOICE	C	
R SATCOM VOICE	C	
SATVOICE AVAIL	F	Satellite voice communication is re-established after a log-off or temporary use of the low gain system. No fault isolation is necessary.
SATVOICE LOST	C	The SATCOM system lost the voice link capability temporarily, due to SATCOM log-off or temporary revision to the low gain antenna. No fault isolation is necessary.
SELCAL	E	<p>A call has been received on VHF, HF or SATCOM. Push the switch-light on the Pilot's call panel to reset, or select the appropriate microphone transmitter on the ACP, and push the PTT switch.</p> <p>AIRPLANES WITH -1001 EICAS COMPUTERS; This message can be a nuisance message. To do a check for a nuisance message, put the EICAS computer select switch to an alternative position. If the message does not show, it was a nuisance message. Open and close the circuit breakers for the EICAS computer that had the message.</p>
VHF DATA OFF	F	VHF radio is selected to voice rather than data mode and ACARS can not communicate via VHF.

EFFECTIVITY _____


ALL

23-EICAS MESSAGES

BOEING

767

FAULT ISOLATION/MAINT MANUAL



1 CAPT OR F/O MIC WILL MUTE OPPOSITE SPEAKER.

APPLICABLE CIRCUIT BREAKERS AS INSTALLED

11C25	CAPT/OBS (FLT AMPL) OR CAPT (SUP-NUM) FLT AMPL DUAL PWR
11C26	F/O (OBS DUAL PWR)

11G29	CAPT/OBS (FLT AMPL) OR CAPT (SUP-NUM) FLT AMPL DUAL PWR
11G30	F/O (OBS DUAL PWR)

ASP, COCKPIT MIC, HEADSET, HANDSET, SPEAKER - FAULT CODES

EFFECTIVITY


ALL

23-FAULT CODE DIAGRAM

07

Page 2
Feb 10/97

BOEING
767
FAULT ISOLATION/MAINT MANUAL



APPLICABLE CIRCUIT BREAKERS

11C3	VHF COMM L	11G29	CAPT/OBS FLT AMPL
11C25	CAPT/OBS FLT AMPL	11G30	F/O
11C26	F/O	11G31	VHF COMM R
11G4	VHF COMM CTR	11G33	RIGHT HF COMM
11G8	LEFT HF COMM		

PUSH TO TALK (PTT) – FAULT CODES

EFFECTIVITY


ALL

23-FAULT CODE DIAGRAM

BOEING

767

FAULT ISOLATION/MAINT MANUAL



1 IF ONE HANDSET INOP, SEE "CABIN HANDSETS AND SPEAKERS" OR "ASP, COCKPIT MIC, HEADSET, HANDSET, SPEAKER" FAULT CODES.

2 IF ONE SPEAKER INOP, SEE "CABIN HANDSETS AND SPEAKERS". 3 IF INSTALLED

APPLICABLE CIRCUIT BREAKERS

11C22 PASS ADRS	11C26 F/O	11G29 CAPT/OBS FLT AMPL	
11C23 CABIN SERVICE	11C25 CAPT/OBS FLT AMPL	11G30 F/O	


PASSENGER ADDRESS SYSTEM - FAULT CODES

EFFECTIVITY

ALL

23-FAULT CODE DIAGRAM

589891



APPLICABLE CIRCUIT BREAKERS

- | | |
|-------|---------------|
| 11C22 | PASS ADRS |
| 11C23 | CABIN SERVICE |



CABIN HANDSETS AND SPEAKERS – FAULT CODES

EFFECTIVITY


ALL

23-FAULT CODE DIAGRAM

GALLEY, LAV,
PSU SPEAKERS



FAULT CODE/
LOCATION



1 IF INSTALLED
APPLICABLE CIRCUIT BREAKERS


11C22 PASS ADRS

BOARDING MUSIC AND PRERECORDED ANNOUNCEMENTS – FAULT CODES

EFFECTIVITY

ALL


23-FAULT CODE DIAGRAM



ATTENDANT CALL FROM SEATS - FAULT CODES

EFFECTIVITY
ALL SAS AIRPLANES

23-FAULT CODE DIAGRAM



ATTENDANT CALL FROM SEATS - FAULT CODES

EFFECTIVITY
ALL MTH AIRPLANES


23-FAULT CODE DIAGRAM

672727

BOEING

767

FAULT ISOLATION/MAINT MANUAL



REPORT ANY FAULT SYMPTOM OR PATTERN NOT SHOWN ABOVE

1 LAVATORY/MASTER CALL LGT LOCATIONS. 2 -300 AIRPLANES



NORMAL

33 25 08

33 25 09

33 25 10

33 25 11

33 25 13

33 25 12

33 25 XB

APPLICABLE CIRCUIT BREAKERS

11C22 PASS ADRS 11P34 LAV CALL/SMOKE DET SYS

ATTENDANT CALL FROM LAVATORY - FAULT CODES



EFFECTIVITY
ALL SAS AIRPLANES

23-FAULT CODE DIAGRAM

BOEING

767

FAULT ISOLATION/MAINT MANUAL



APPLICABLE CIRCUIT BREAKERS

11C22 PASS ADRS 11P34 LAV CALL/SMOKE DET SYS

ATTENDANT CALL FROM LAVATORY – FAULT CODES

EFFECTIVITY
ALL MTH AIRPLANES


23-FAULT CODE DIAGRAM

672736

BOEING

767

FAULT ISOLATION/MAINT MANUAL



1 IF HANDSET IS FAULTY, SEE "COCKPIT MIC, HEADSET, HANDSET SPEAKER" OR "CABIN HANDSET & SPEAKERS" FAULT CODES.

2 SYSTEM MAY RESET BY CYCLING CABIN SERVICE CB.

APPLICABLE CIRCUIT BREAKERS

11C22 PASS ADRS


11C23 CABIN SERVICE

CABIN CHIME, CALL FROM PILOT, ALERT CALL & PASS SIGNS - FAULT CODES

EFFECTIVITY

ALL

23-FAULT CODE DIAGRAM



APPLICABLE CIRCUIT BREAKERS AS INSTALLED

11C23	(INTERPHONE) CABIN SERVICE	11G30	(INTERPHONE) F/O (SEC)(OBS)(DUAL PWR)
11C25	CAPT SEC-OBS FLT AMPL		
11C25	(INTERPHONE) CAPT(/OBS, OBS)(SUP NUM)(FLT AMPL)(DUAL PWR)		
11C26	(INTERPHONE) F/O (SEC)(OBS)(DUAL PWR)		
11G29	CAPT SEC-OBS FLT AMPL		
11G29	(INTERPHONE) CAPT(/OBS, OBS)(SUP NUM)(FLT AMPL)(DUAL PWR)		

SERVICE INTERPHONE - FAULT CODES

EFFECTIVITY


ALL

23-FAULT CODE DIAGRAM

BOEING

767

FAULT ISOLATION/MAINT MANUAL



- 1 ▷ FLT INT SWITCH MUST BE ON TO CONNECT FLT INPH TO CABIN AND SERVICE INPH SYSTEMS.
- 2 ▷ AS INSTALLED

APPLICABLE CIRCUIT BREAKERS AS INSTALLED

11C23	(INTERPHONE) CABIN SERVICE
11C25	(INTERPHONE) CAPT(/OBS, OBS)(SEC-OBS)(FLT AMPL)(DUAL PWR)
11C26	(INTERPHONE) F/O (SEC)(OBS)(DUAL PWR)
11G29	(INTERPHONE) CAPT(/OBS, OBS)(SEC-OBS)(FLT AMPL)(DUAL PWR)
11G30	(INTERPHONE) F/O (SEC)(OBS)(DUAL PWR)

CABIN INTERPHONE - FAULT CODES

EFFECTIVITY


ALL

23-FAULT CODE DIAGRAM

BOEING

767

FAULT ISOLATION/MAINT MANUAL



1 AS INSTALLED

APPLICABLE CIRCUIT BREAKERS AS INSTALLED

11B16	AURAL WARN SPKR L	11H32	GND CALL
11B18	WARN ELEX B	11H35	AURAL WARN SPKR R
11C23	(INTERPHONE) CABIN SERVICE	11J34	WARN ELEX A
11C24	CABIN SERVICE		

CABIN AND COCKPIT CHIME, CALL LIGHTS FROM ATTENDANT & NOSE WHEEL WELL - FAULT CODES

EFFECTIVITY


ALL

23-FAULT CODE DIAGRAM

BOEING

767

FAULT ISOLATION/MAINT MANUAL



APPLICABLE CIRCUIT BREAKERS


11C25	CAPT/OBS FLT AMPL
11C26	F/O
11G29	CAPT/OBS FLT AMPL
11G30	F/O

FLIGHT INTERPHONE - FAULT CODES

EFFECTIVITY

ALL

23-FAULT CODE DIAGRAM



- 1 PUSH FOR APPROX 4 SEC, MONITOR LGT SHOULD FLASH 2 TIMES.
- 2 TEST TONE SHOULD BE HEARD.
- 3 AS INSTALLED

APPLICABLE CIRCUIT BREAKERS

11H34 VOICE RECORDER


VOICE RECORDER - FAULT CODES

EFFECTIVITY

ALL

23-FAULT CODE DIAGRAM

BOEING
767
FAULT ISOLATION/MAINT MANUAL



1 IF INOP CHECK PES & PSS SWS AT FWD ATTND PNL ARE ON.

2 IF INSTALLED

APPLICABLE CIRCUIT BREAKERS

- 11C22 PASS ADRS
- 11T8 PASS ENTMT/SERVICE CONT

PASSENGER ENTERTAINMENT (SHEET 1) - FAULT CODES

EFFECTIVITY


ALL

23-FAULT CODE DIAGRAM

BOEING

767

FAULT ISOLATION/MAINT MANUAL




11C22 PASS ADRS 11C23 CABIN SERVICE 11T8 PASS ENTMT/SERVICE CONT

PASSENGER ENTERTAINMENT (SHEET 2) - FAULT CODES

EFFECTIVITY
ALL SAS AIRPLANES

23-FAULT CODE DIAGRAM



PASSENGER ENTERTAINMENT (SHEET 3) - FAULT CODES

EFFECTIVITY


ALL

23-FAULT CODE DIAGRAM

BOEING

767

FAULT ISOLATION/MAINT MANUAL



APPLICABLE CIRCUIT BREAKERS AS INSTALLED


11C25	CAPT(/OBS)(FLT AMPL)(DUAL PWR)	11G29	ASP PWR 1
11C25	ALTN ASP PWR 1	11G29	CAPT(/OBS)(FLT AMPL)(DUAL PWR)
11C26	F/O (OBS)(DUAL PWR)	11G30	F/O (OBS)(DUAL PWR)
11C26	ALTN ASP PWR 2	11G30	ASP PWR 2
11G8	(LEFT, L) HF COMM	11G35	(RIGHT, R) HF COMM

HF COMM - FAULT CODES

EFFECTIVITY

ALL

23-FAULT CODE DIAGRAM



1 As installed
APPLICABLE CIRCUIT BREAKERS AS INSTALLED


11C3	VHF COMM L
11G3	SELCAL
11G4	VHF COMM (CTR, C)
11G8	(LEFT, L) HF COMM
11G31	VHF COMM R
11G35	(RIGHT, R) HF COMM

SELCAL - FAULT CODES

EFFECTIVITY

ALL

23-FAULT CODE DIAGRAM




APPLICABLE CIRCUIT BREAKERS
NONE

EMERGENCY LOCATOR TRANSMITTER – FAULT CODES

EFFECTIVITY

ALL

23-FAULT CODE DIAGRAM



— REPORT ANY FAULT SYMPTOM OR PATTERN NOT SHOWN ABOVE —————> 23 43 XB 00

APPLICABLE CIRCUIT BREAKERS


11H32 GND CALL

GROUND CREW CALL SYSTEM - FAULT CODES (GROUND)

EFFECTIVITY

ALL

23-FAULT CODE DIAGRAM




EICAS MESSAGE – FAULT CODES

EFFECTIVITY

ALL


23-FAULT CODE DIAGRAM

FWD ELECTRONICS PANEL



**FAULT CODE/
LOCATION**

L 01
R 02
BOTH 03



1 REFER TO "NAVIGATION" CHAPTER FOR FMC CDU FAULTS.

APPLICABLE CIRCUIT BREAKERS

6G5	ACARS DC PWR	11E29	RIGHT FMCS CDU
11E8	LEFT FMCS CDU	11G6	ACARS MGMT UNIT AC


FMC CDU-ACARS INTERFACE - FAULT CODES

EFFECTIVITY


ALL

23-FAULT CODE DIAGRAM

AFT ELECTRONICS PANEL



FAULT CODE/
LOCATION



APPLICABLE CIRCUIT BREAKERS

NONE

ACARS PRINTER – FAULT CODES

EFFECTIVITY

ALL

23-FAULT CODE DIAGRAM



767
FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 11 XA --	1. Report HF comm symptoms or patterns along with the fault code. 2. SSM 23-11-01, SSM 23-11-02.
23 12 XA --	1. Report VHF comm symptoms or patterns along with fault code. 2. FIM 23-12-00/101, Fig. 103.
23 21 XA --	1. Report SELCAL symptoms or patterns along with fault code. 2. SSM 23-21-01.
23 22 XB --	1. Report ACARS printer symptoms or patterns along with fault code. 2. SSM 23-21-01.
23 24 XA 00	1. Report emergency locator transmitter symptoms or patterns along with fault code. 2. SSM 23-24-01.
23 25 XA 00	1. Report EICAS message symptoms or patterns along with fault code. 2. SSM 23-25-01.
23 31 XA --	1. Report passenger address system symptoms or patterns along with fault codes. 2. SSM 23-31-01.
23 31 XB --	1. Report cabin handset and speaker symptoms or patterns along with fault code. 2. SSM 23-31-01, SSM 23-42-01.
23 31 XC 00	1. Report boarding music symptoms or patterns along with fault code. 2. SSM 23-31-01, SSM 23-31-02, SSM 23-34-01.
23 32 XA --	1. Report passenger entertainment symptoms or patterns along with fault code. 2. SSM 23-32-01.

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 32 XB --	1. Report passenger entertainment symptoms or patterns along with fault code. 2. SSM 23-32-01.
23 34 XA --	1. Report attendant call from seat symptoms or patterns along with fault code. 2. SSM 23-34-01.
23 34 XB --	1. Report passenger entertainment symptoms or patterns along with fault code. 2. SSM 23-34-01, SSM 23-34-02.
23 34 XC --	1. A reading light problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref Chapter 33 for fault code diagram). 2. SSM 23-34-01, SSM 23-34-02.
23 34 XD --	1. An attendant call from seat problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref fault code diagram for flight crew actions). 2. SSM 23-34-01, SSM 23-34-02.
23 41 XA --	1. Report service interphone symptoms or patterns along with the fault code. 2. SSM 23-41-01.
23 42 XA --	1. A cabin chime, passenger signs, call from pilot, other attendant, and alert problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref fault code diagram for flight crew actions). 2. SSM 23-42-01.

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 42 XB --	1. Report cabin interphone symptoms or patterns along with fault code. 2. SSM 23-42-01.
23 42 XC --	1. Report cabin and cockpit chime/call light from attendant and nose wheel well symptoms or patterns along with the fault code. 2. SSM 23-42-01, SSM 23-43-01.
23 43 XA 00	1. An equipment cooling/IRU: ground crew call warning system problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref fault code diagram for ground crew actions). 2. SSM 23-43-01.
23 43 XB 00	1. A ground crew call system problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref fault code diagram for ground crew actions). 2. SSM 23-43-01.
23 51 XA --	1. Report push to talk (PTT) symptoms or patterns along with fault codes. 2. SSM 23-51-01.
23 51 XB --	1. Report Flight Interphone symptoms or patterns along with fault code. 2. SSM 23-51-01.
23 51 XC --	1. Report ASP, cockpit mic, headset, speaker symptoms along with the fault code. 2. SSM 23-51-01.

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 71 XA 00	1. Report voice recorder symptoms or patterns along with fault code. 2. SSM 23-71-01.
23 11 01 --	1. Reception on (L, R, single) HF (describe problem: inop, weak, intermittent, etc.) at (04=Capt, 05=F/O, 06=1st Obs, 07=2nd Obs) station. Other crew stations normal. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 11 02 ___	1. Reception on (01=L, 02=R, 03=single) HF (describe problem: inop, weak, intermittent, etc.) at all stations. 2. Replace the HF comm transceiver, M153 (AMM 23-11-03/401).
23 11 03 --	1. Transmission on (L, R, single) HF (describe problem: inop, weak, intermittent, no sidetone, etc.) at (04=Capt, 05=F/O, 06=1st Obs, 07=2nd Obs) station. Other crew stations normal. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 11 04 ___	1. Transmission on (01=L, 02=R, 03=single) HF (describe problem: inop, weak, intermittent, no sidetone, etc.) at all stations. 2. Replace the HF comm transceiver, M153 (AMM 23-11-03/401).
23 11 05 --	1. Transmission and reception on (L, R, single) HF (describe problem: inop, etc.) at (04=Capt, 05=F/O, 06=1st Obs, 07=2nd Obs) station. Other crew stations are normal. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 11 06 ___	1. Transmission and reception on (01=L, 02=R, 03=single) HF at _____ MHz (describe problem: inop, etc.). 2. FIM 23-11-00/101, Fig. 103, Block 1.
23 11 07 --	1. Transmission and reception on (01=L, 02=R, 03=single) HF (describe problem: inop, etc.). 2. FIM 23-11-00/101, Fig. 103, Block 1.
23 11 08 --	1. (01=L, 02=R, 03=single) HF freq control inop. (Describe). 2. Replace the L (R) HF comm control panel, M82 (M83) (AMM 23-11-02/401).
23 11 09 --	1. (01=L, 02=R, 03=single) HF freq incorrect on _____ MHz. 2. FIM 23-11-00/101, Fig. 103, Block 1.
23 11 10 --	1. (01=L, 02=R, 03=single) HF freq indicator has missing segment. 2. Replace the L (R) HF comm control panel, M82 (M83) (AMM 23-11-02/401).
23 11 20 --	1. Tuning or transmission on (01=L, 02=R) HF causes invalid EICAS message or causes faults in autothrottle or other systems (describe problem). 2. Inspect the coaxial cable connector for each HF system at the unpressurized side of the aft pressure bulkhead for corrosion (WDM 23-11-11, sheet 2 and WDM 23-11-12, sheet 2). If corrosion is present, replace the coaxial cable. 3. FIM 23-11-00/101, Fig. 103, Block 1.
23 11 21 --	1. Transmission on an HF system (01=L, 02=R) is defective at high altitudes or cruise, but is satisfactory on the ground or at low altitudes. 2. Replace the antenna coupler for the affected system (L = M241, R = M242) (AMM 23-11-01/401).
23 12 01 --	1. (01=L, 02=R, 03=C) VHF transfer lgt inop for (L, R) selected frequency. 2. Replace the L (R, C) VHF comm control panel, M78 (M79, M80) (AMM 23-12-02/401).
23 12 02 --	1. (01=L, 02=R, 03=C) VHF freq control (describe problem: inop, stuck, knob missing, etc) for (L, R) frequency. 2. Replace the L (R, C) VHF comm control panel, M78 (M79, M80) (AMM 23-12-02/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX

16.1

Page 5
Aug 22/09


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 12 03 --	1. Reception on (L, R, C, All) VHF (describe problem: inop, weak, intermittent, etc.) at (04=Capt, 05=F/O, 06=1st Obs) station. Other crew stations are norm. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 12 04 --	1. (01=L, 02=R, 03=C) VHF reception (describe problem: inop, weak, intermittent, radar interference, etc.) at all crew stations. 2. Replace the VHF comm transceiver, M188 (M189, M190) (AMM 23-12-01/401).
23 12 05 --	1. (L, R, C) VHF xmission, (describe problem: inop, weak, intermittent, no sidetone, etc.) at (04=Capt, 05=F/O, 06=1st Obs) station. Other crew stations normal. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 12 06 --	1. (01=L, 02=R, 03=C) VHF xmission (describe problem: inop, weak, intermittent, no sidetone, etc.) at all crew stations. 2. Replace the VHF comm transceiver, M188 (M189, M190) (AMM 23-12-01/401).
23 12 07 --	1. (01=L, 02=R, 03=C) VHF xmission and reception inop when using (L, R) selected frequency (specify freq). 2. Replace the L (R, C) VHF comm control panel, M78 (M79, M80) (AMM 23-12-02/401).
23 12 08 --	1. (01=L, 02=R, 03=C) VHF xmission and reception (describe problem: inop, weak, intermittent, etc.) on (specify freq). 2. FIM 23-12-00/101, Fig. 103, Block 1.
23 12 09 --	1. Xmission and reception on (L, R, C) VHF (describe problem: inop, weak, intermittent, etc.) at (04=Capt, 05=F/O, 06=1st Obs) station. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX

24.101

Page 6
May 10/96

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 12 10 --	1. (01=L, 02=R, 03=C) VHF xmission and reception (describe problem: inop, weak, intermittent, etc.) at all crew stations on all freq. 2. Do the VHF comm transceiver BITE procedure (FIM 23-12-00/101, Fig. 103, Block 1). If the problem continues, do the time domain reflectometry check of the antenna system (AMM 20-10-32/201). Repair the coaxial cable (WDM 23-12-11, WDM 23-12-21, WDM 23-12-31) or replace the VHF comm antenna, M245 (M246, M247) (AMM 23-12-03/401), as necessary.
23 12 11 --	1. (01=L, 02=R, 03=C) VHF comm test (describe problem: weak, inop, button stuck, etc.). 2. FIM 23-12-00/101, Fig. 103, Block 1.
23 12 13 --	1. (01=L, 02=R, 03=C) VHF freq indication incorrect. (Describe problem). 2. Replace the L (R, C) VHF comm control panel, M78 (M79, M80) (AMM 23-12-02/401).
23 12 14 --	1. (01=L, 02=R, 03=C) VHF freq indicator has segment missing. 2. Replace the L (R, C) VHF comm control panel, M78 (M79, M80) (AMM 23-12-02/401).
23 12 15 --	1. (01=L, 02=R, 03=C) VHF will not transfer to (L, R) side. 2. Replace the L (R, C) VHF comm control panel, M78 (M79, M80) (AMM 23-12-02/401).
23 21 01 --	1. (01=L VHF, 02=C VHF, 03=R VHF, 04=L HF, 05=R HF, 06=HF) call switch fails to reset SELCAL. PTT resets SELCAL. 2. Replace the pilots' call panel, M51 (AMM 23-42-02/401).
23 21 02 --	1. (01=L VHF, 02=C VHF, 03=R VHF, 04=L HF, 05=R HF, 06=HF) SELCAL is not reset by PTT. Call switch resets SELCAL. 2. (01=L VHF, 02=C VHF, 03=R VHF) replace the pilot's call panel, M51 (AMM 23-42-02/401). If the problem continues, replace the VHF comm transceiver, M188 (M189, M190) (AMM 23-12-01/401). (04=L HF, 05=R HF) replace the pilot's call panel, M51 (AMM 23-42-02/401). If the problem continues, replace the HF comm transceiver, M152 (M153) (AMM 23-11-03/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 21 03 --	1. (01=L VHF, 02=C VHF, 03=R VHF, 04=L HF, 05=R HF, 06=HF) call switch and PTT fail to reset SELCAL. 2. Replace the SELCAL decoder, M180 (AMM 23-21-01/401).
23 21 04 --	1. Calls on (01=L VHF, 02=C VHF, 03=R VHF, 04=L HF, 05=R HF, 06=HF) fail to illum SELCAL lgt. 2. Replace the SELCAL decoder, M180 (AMM 23-21-01/401).
23 21 05 --	1. Calls on (01=L VHF, 02=C VHF, 03=R VHF, 04=L HF, 05=R HF, 06=HF) fail to sound chime. SELCAL call lgt illum. 2. Replace the bell chime aural warning module, M1000 (AMM 31-51-04/401). If the problem continues, replace the SELCAL decoder, M180 (AMM 23-21-01/401).
23 21 06 --	1. Calls on (01=L VHF, 02=C VHF, 03=R VHF, 04=L HF, 05=R HF, 06=HF) fail to illum SELCAL lgt and sound chime. SELCAL on another radio norm. 2. (01=L VHF, 02=C VHF, 03=R VHF) FIM 23-12-00/101, Fig. 103, Block 1. If the problem continues, replace the SELCAL decoder, M180 (AMM 23-21-01/401). (04=L HF, 05=R HF, 06=HF) FIM 23-11-00/101, Fig. 103, Block 1. If the problem continues, replace the SELCAL decoder, M180 (AMM 23-21-01/401).
23 21 07 00	1. Calls on any radio fail to illum SELCAL lgt and sound chime. 2. Replace the SELCAL decoder, M180 (AMM 23-21-01/401).
23 22 33 00	1. Printer MSG light illuminated. 2. Push the MSG switchlamp once. If the MSG switchlamp goes out and the message prints out on the printer, the system is O.K. If the MSG lamp stays on, replace the printer (AMM 31-35-06/401).
23 22 40 --	1. ACARS item selections do not respond to line item selection keys on (01=L, 02=R, 03=Both) CDU(s). 2. Replace the ACARS Management Unit, M172 (AMM 23-22-01/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 22 78 00	1. ACARS printer FAULT lgt illum. 2. Replace the ACARS printer, M939 (AMM 23-22-03/401).
23 22 81 00	1. ACARS printer SELF TEST inoperative. 2. Replace the Multi-Input printer (AMM 31-35-06/401).
23 22 98 --	1. ACARS voice mode inop using (01=L, 02=R, 03=Both) CDU(s). 2. Replace the center VHF comm transceiver, M190 (AMM 23-12-01/401).
23 23 01 00	1. EICAS msg DATALINK SYS displayed. 2. ACARS Datalink is active after being in a NO COMM condition, no corrective action required.
23 23 04 00	1. EICAS msg HF DATALINK displayed. 2. Replace the HF Transceiver (AMM 23-11-03/401). If the fault continues, replace the ACARS Management Unit (AMM 23-22-01/401).
23 23 07 00	1. EICAS msg DATALINK LOST displayed. 2. Total loss of datalink capability due to active ACARS being in "NO COMM" condition. The "NO COMM" condition is a normal condition if the airplane is out of range of an ACARS ground station, or if the ACARS ground network is not operationsl. If ACARS operates correctly on other airplanes at the same location, do this fault isolation procedure: FIM 23-22-00/101, Figure 103, block 1.
23 23 09 00	1. EICAS msg >DATALINK LOST displayed. 2. No corrective action is necessary.
23 23 10 00	1. EICAS msg >DATALINK SYS displayed. 2. FIM 23-22-00/101 Fig. 103, Block 1.
23 24 01 00	1. Emergency locator signal being transmitted when not selected. 2. Push the RESET switch on the front panel of the emergency locator transmitter. If the problem continues, replace the emergency locator transmitter, M1597 (AMM 23-24-01/201).
23 24 02 00	1. Emergency locator system did not test properly. 2. FIM 23-24-00/101, Fig. 103, Block 1.
23 25 01 00	1. EICAS message SATCOM displayed. 2. FIM 23-25-00/101.

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 25 02 00	1. EICAS message SATCOM DATALINK displayed. 2. FIM 23-22-00/101, Fig. 103, Block 1 or FIM 23-25-00/101.
23 25 03 00	1. EICAS message SATCOM VOICE displayed. 2. FIM 23-25-00/101.
23 25 04 00	1. EICAS message L SATCOM VOICE displayed. 2. FIM 23-25-00/101.
23 25 05 00	1. EICAS message R SATCOM VOICE displayed. 2. FIM 23-25-00/101.
23 31 01 00	1. One speaker (describe location) is (describe problem: noisy, inop, too loud, etc.) when PA is used. 2. FIM 23-31-00/101, Fig. 103, Block 1.
23 31 02 00	1. All speakers are (describe problem: noisy, inop, too loud, etc.) when PA is used. 2. Replace the PA amplifier, M177 (AMM 23-31-01/401).
23 31 03 --	1. PA has background noise when using (01=Capt, 04=Purser, 05=Fwd L, 06=Fwd R, 07=Mid, 08=Aft L, 09=Aft R) handset. Handset is normal. 2. Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 31 04 --	1. PA is (describe problem: noisy, inop, too loud, weak, etc.) when using (01=Capt, 02=F/O, 03=1st Obs, 04=2nd Obs) audio select panel. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).##
23 31 05 00	1. PA is (describe problem: noisy, inop, too loud, etc.) when using handsets. PA is normal when using audio select panel. 2. Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 31 06 00	1. PA is (describe problem: noisy, inop, too loud, etc.) when using handsets or audio selector panels. 2. FIM 23-31-00/101, Fig. 103, Block 1.
23 31 07 --	1. (01=Fwd L, 02=Fwd R, 03=Aft L, 04=Aft R, 05=Mid, 07=___ Galley, 08=___ Lav, 09=___ PSU) speaker (describe problem: noisy, inop, etc.). 2. FIM 23-31-00/101, Fig. 103, Block 1.

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 31 08 --	1. (01=Fwd L, 02=Fwd R, 03=Aft L, 04=Aft R, 05=Mid, 06=Purser) attendant handset (describe problem: unable to talk, unable to hear, unable to key). 2. Put the handset at a different position. If the problem follows, replace the handset, B61. If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 31 09 00	1. Boarding music channel select not normal. 2. Replace the PA tape deck, M1523 (AMM 23-31-10/401).
23 31 10 00	1. Boarding music volume too low with engines on. 2. Replace the passenger address amplifier, M177 (AMM 23-31-01/401). If the problem continues, do a check of the circuit wiring (WDM 23-31-11, WDM 23-31-12, WDM 23-31-13, WDM 23-31-14, WDM 23-31-15, WDM 23-31-16, WDM 23-31-17).
23 31 11 00	1. Boarding music too low at max volume. 2. Replace the PA tape deck, M1523 (AMM 23-31-10/401). If the problem continues, replace the PA amplifier, M177 (AMM 23-31-01/401).
23 31 12 00	1. Boarding music volume control inop. 2. Replace the PA tape deck, M1523 (AMM 23-31-10/401). If the problem continues, replace the PA amplifier, M177 (AMM 23-31-01/401).
23 31 13 00	1. Boarding music channel _____ is (describe problem: noisy inop, etc.). 2. Replace the cassette tape in the PA tape deck. If the problem continues, replace the PA tape deck, M1523 (AMM 23-31-10/401).
23 31 14 00	1. All boarding music channels are (describe problem: noisy, inop, etc.). Pass entmt channels are normal. 2. Replace the PA amplifier, M177 (AMM 23-31-01/401). If the problem continues, replace the BRD MUSIC VOLUME switch, YBHS24 (WDM 23-31-12) on the forward attendant panel, P21 (AMM 33-22-05/401).
23 31 15 00	1. All boarding music and pass entmt channels are (describe problem: noisy, inop, etc.). 2. Replace the entertainment tape reproducer, M170 (AMM 23-34-03/201).

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 31 18 00	1. The (enter announcement) announcement is (describe problem: noisy, inop, etc.). 2. Replace the cassette tape in the PA tape deck. If the problem continues, replace the PA tape deck, M1523 (AMM 23-31-10/401).
23 31 19 00	1. All pre-recorded announcements are (describe problem: noisy, inop, etc.). 2. Replace the PA tape deck, M1523 (AMM 23-31-10/401). If the problem continues, replace the PA amplifier, M177 (AMM 23-31-01/401).
23 31 20 00	1. Boarding music plays too (fast, slow). 2. Clean the tape deck pinch rollers and the tape heads. If the problem continues, replace the cassette tape in the PA tape deck. If the problem continues, replace the PA tape deck, M1523 (AMM 23-31-10/401).
23 31 21 --	1. PA has no sidetone when using (01=Capt, 02=F/O, 03=1st Obs) audio selector panel. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 31 22 00	1. PA has no sidetone when using any audio selector panel. 2. Replace the PA amplifier, M177 (AMM 23-31-01/401).
23 31 31 00	1. Purser PA microphone is inop. 2. Replace the purser PA microphone. If the problem continues, replace the PA switching card, M1635 (AMM 23-31-11/401).
23 31 32 00	1. Purser PA control is inoperative when selecting individual cabin sections. 2. Replace the PA switching cards, M1634 and M1635 (AMM 23-31-11/401). If the problem continues, replace the zone select switch on the purser panel (WDM 23-31-13).
23 31 33 00	1. Purser PA control is inoperative when selecting all cabin sections. 2. Replace the zone select switch on the purser panel (WDM 23-31-13). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 32 04 --	1. (01=VTR 1, 02=VTR 2, 03=VTR 3, 10=All) video sound tracks are (describe problem: noisy, too low, bleed thru, etc.) all seats and on PA. Proj normal. 2. (01=VTR 1, 02=VTR 2, 03=VTR 3) replace the video cassette tape. If the problem continues, replace the video tape reproducer, M1108 (M1059, M1613) (AMM 23-32-01/401). If the problem continues, replace the control distribution unit, M815 (AMM 23-32-03/401). (10=All) replace the control distribution unit, M815 (AMM 23-32-03/401).
23 32 06 --	1. (01=VTR 1, 02=VTR 2, 03=VTR 3, 10=All) video sound tracks are (describe problem: noisy, too low, bleed thru, etc.) all seats. They are normal on PA. 2. Replace the control distribution unit, M815 (AMM 23-32-03/401).
23 32 07 --	1. (04=Proj, 05=Monitor 1, 06=Monitor 2, 07=Monitor 3, 08=Monitor 4, 09=Monitor 5) zone video picture is blank. Sound is normal. 2. Tell "TRANSCOM" about the problem.
23 32 08 --	1. (04=Proj, 05=Monitor 1, 06=Monitor 2, 07=Monitor 3, 08=Monitor 4, 09=Monitor 5) zone video picture is out of focus. 2. Tell "TRANSCOM" about the problem.
23 32 09 --	1. (04=Proj, 05=Monitor 1, 06=Monitor 2, 07=Monitor 3, 08=Monitor 4, 09=Monitor 5) zone video picture tint not normal (Describe). 2. Tell "TRANSCOM" about the problem.
23 32 10 --	1. (04=Proj, 05=Monitor 1, 06=Monitor 2, 07=Monitor 3, 08=Monitor 4, 09=Monitor 5) zone video picture is too (dark, light). 2. Tell "TRANSCOM" about the problem.
23 32 11 --	1. (04=Proj, 05=Monitor 1, 06=Monitor 2, 07=Monitor 3, 08=Monitor 4, 09=Monitor 5) zone video picture(s) (has horiz hold problem, rolls, flickers). 2. Tell "TRANSCOM" about the problem.
23 32 12 --	1. (01=VTR 1, 02=VTR 2, 03=VTR 3) Video sound channel (inop, garbled, etc.) on PA. 2. Replace the video tape reproducer, M1108 (M1059, M1613) (AMM 23-32-01/401). If the problem continues, replace the control distribution unit, M815 (AMM 23-32-03/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 32 13 --	1. (01=VTR 1, 02=VTR 2, 03=VTR 3, 10=All) Video sound channel(s) (too low, high, garbled, inop, etc.) on PA. 2. (01=VTR 1, 02=VTR 2, 03=VTR 3) replace the video tape reproducer, M1108 (M0159, M1613) (AMM 23-32-01/401). If the problem continues, replace the control distribution unit, M815 (AMM 23-32-03/401). (10=All) replace the control distribution unit, M815 (AMM 23-32-03/401). If the problem continues, replace the PA amplifier, M177 (AMM 23-31-01/401).
23 32 15 --	1. (01=VTR 1, 02=VTR 2, 03=VTR 3) video tape reproducer will not play tape. 2. Make sure the cassette tape is correctly wound. If the problem continues, replace the video cassette. If the problem continues, replace the video tape reproducer, M1108 (M1059, M1613) (AMM 23-32-01/401).
23 32 16 --	1. (01=VTR 1, 02=VTR 2, 03=VTR 3) video tape reproducer tape stops during movie. 2. Replace the video cassette tape. If the problem continues, replace the video tape reproducer, M1108 (M1059, M1613) (AMM 23-32-01/401).
23 32 17 --	1. (01=VTR 1, 02=VTR 2, 03=VTR 3) video tape reproducer stuck in fast forward. 2. Replace the video tape reproducer, M1108 (M1059, M1613) (AMM 23-32-01/401).
23 32 18 --	1. (01=VTR 1, 02=VTR 2, 03=VTR 3) video tape reproducer will not eject tape. 2. Replace the video tape reproducer, M1108 (M1059, M1613) (AMM 23-32-01/401).
23 32 19 --	1. Unable to get power on (01=VTR 1, 02=VTR 2, 03=VTR 3). VIDEO ON lgt did not illum. 2. Tell "TRANSCOM" about the problem.
23 32 20 --	1. Lgt bulb inop on (01=VTR 1, 02=VTR 2, 03=VTR 3) control. 2. Tell "TRANSCOM" about the problem.
23 32 42 00	1. Passenger Flight Information Display System is inop. 2. Replace the digital interface unit, M1457 (AMM 23-32-07/401).
23 32 43 00	1. (Identify location). Video picture is blank. 2. Tell "TRANSCOM" about the problem.

EFFECTIVITY

ALL

23-FAULT CODE INDEX



BOEING
767
FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 32 44 --	1. (01=Fwd, 02=Mid, 03=Aft, 06=All) area video pictures are blank. 2. Replace the system control unit, M815 (AMM 23-32-03/401).
23 32 45 00	1. (Identify location). Video picture is out of focus. 2. Tell "TRANSCOM" about the problem.
23 32 46 00	1. (Identify location). Video picture is too (dark, light). 2. Tell "TRANSCOM" about the problem.
23 32 47 00	1. (Identify location) video picture tint not normal. 2.
23 32 48 00	1. Video control unit class key inop. 2. Replace the system control unit, M815 (AMM 23-32-03/401).
23 32 49 --	1. (04=VTR 1, 05=VTR 2) video tape reproducer area (F,C,M) using (primary, secondary) audio channel (inop, garbled, etc.) on PA. 2. Replace the video tape reproducer, M1108 (M1059) (AMM 23-32-01/401). If the problem continues, replace the system control unit, M815 (AMM 23-32-03/401).
23 32 50 --	1. (04=VTR 1, 05=VTR 2) video tape reproducer both audio channels (too low, high, garbled, inop, etc.) on PA. 2.
23 32 51 00	1. Preview monitor inop when viewing VTR's with preview key. 2. Replace the system control unit, M815 (AMM 23-32-03/401).
23 32 52 00	1. Video control unit status key inop. 2. Replace the system control unit, M815 (AMM 23-32-03/401).
23 32 53 00	1. Tape reproducer selection inop. 2. Replace the system control unit, M815 (AMM 23-32-03/401).
23 32 54 --	1. (04=VTR 1, 05=VTR 2) will not play tape. 2. Replace the video tape reproducer, M1108 (M1059) (AMM 23-32-01/401).
23 32 55 --	1. (04=VTR 1, 05=VTR 2) has no power. 2. Replace the video tape reproducer, M1108 (M1059) (AMM 23-32-01/401). If the problem continues, replace the system control unit, M815 (AMM 23-32-02/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX

27

Page 15
Dec 22/01


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 32 56 --	1. (04=VTR 1, 05=VTR 2) tracking inop. 2. Replace the video tape reproducer, M1108 (M1059) (AMM 23-32-01/401).
23 32 57 --	1. (04=VTR 1, 05=VTR 2) will not eject tape. 2. Replace the video tape reproducer, M1108 (M1059) (AMM 23-32-01/401).
23 32 58 --	1. (04=VTR 1, 05=VTR 2) programming inop. 2. Replace the video tape reproducer, M1108 (M1059) (AMM 23-32-01/401).
23 32 59 --	1. (04=VTR 1, 05=VTR 2) (FF, REW) stuck or inop. 2. Replace the video tape reproducer, M1108 (M1059) (AMM 23-32-01/401).
23 32 60 --	1. (04=VTR 1, 05=VTR 2) video sound channels are (describe problem: noisy, too low, inop, etc.) all seats. Normal on PA. 2. Replace the system control unit, M815 (AMM 23-32-03/401).
23 32 61 --	1. (04=VTR 1, 05=VTR 2) video sound channels (describe problem: noisy, too low, inop, etc.) all seats and on PA. 2. Replace the video cassette tape. If the problem continues, replace the video tape reproducer, M1108 (M1059) (AMM 23-32-01/401). If the problem continues, replace the system control unit, M815 (AMM 23-32-03/401).
23 32 62 00	1. Master power sw inop on video system control unit. 2. Replace the system control unit, M815 (AMM 23-32-03/401).
23 34 01 --	1. (01=Fwd, 13=Aft) master attendant call reset not normal. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 02 00	1. Attendant call lgt will not reset at seat ____. 2. Replace the passenger control unit at the affected seat (AMM 23-34-05/401). If the problem continues, replace the seat electronics box, M915 (AMM 23-34-04/401).
23 34 03 --	1. (02=Fwd L, 04=Fwd R, 09=Mid Fwd L, 10=Mid Fwd R, 11=Mid Aft L, 12=Mid Aft R, 14=Aft Fwd L, 15=Aft Fwd R, 16=Aft Mid L, 17=Aft Mid R, 18=Aft L, 20=Aft R) BLUE call lgts inop. 2. FIM 23-34-00/101, Fig. 104, Block 1.

EFFECTIVITY

ALL

23-FAULT CODE INDEX



BOEING
767
FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 34 04 --	1. (02=Fwd L, 04=Fwd R, 06=Mid L, 08=Mid R, 18=Aft L, 20=Aft R) attendant call lgts blink. Chime sounds without moving switch. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 07 00	1. Pass entmt volume control (describe problem: unable to adjust volume, too sensitive, etc.) at seat _____. 2. Replace the PCU (AMM 23-34-05/401).
23 34 08 --	1. (02=Fwd L, 03= Fwd C, 06=Mid L, 08=Mid R, 18=Aft L, 20=Aft R) attendant call chime(s) inop when calling from seat _____. Call lgts are normal. 2. (02=Fwd L, 03=Fwd C) replace the electronic chime, B139 (B144) at the position where the problem occurs (AMM 23-42-04/401). If the problem continues, replace the Fwd column timer decoder, M1319 (AMM 23-34-07/401). (06=Mid L, 08=Mid R) replace the electronic chime, B145 (B146) at the position where the problem occurs (AMM 23-42-04/401). If the problem continues, replace the Mid column timer decoder, M1320 (AMM 23-34-07/401). (18=Aft L, 20=Aft R) replace the electronic chime, B147 (B148) at the position where the problem occurs (AMM 23-42-04/401). If the problem continues, replace the Aft column timer decoder, M1306 (AMM 23-34-07/401).
23 34 10 --	1. (02=Fwd L, 04=Fwd R, 06=Mid L, 08=Mid R, 18=Aft L, 20=Aft R) attendant call lgts blink. Chime doesn't sound. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 11 00	1. Attendant call lgt & chime inop from seat _____. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 12 --	1. In (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Mid L, 07=Mid C, 08=Mid R, 18=Aft L, 19=Aft C, 20=Aft R) column, attendant call from row _____ inop. Chime fails to sound. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 13 --	1. In (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Mid L, 07=Mid C, 08=Mid R, 18=Aft L, 19=Aft C, 20=Aft R) column, attendant call lgt for row _____ and aft inop. Chime fails to sound. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 14 --	1. (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Mid L, 07=Mid C, 08=Mid R, 18=Aft L, 19=Aft C, 20=Aft R) column attendant call lgts inop. Chime fails to sound. 2. FIM 23-34-00/101, Fig. 104, Block 1.

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 34 15 --	1. (01=Fwd, 05=Mid, 13=Aft) section attendant call lgts inop. Chime fails to sound. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 16 00	1. Cabin chime sounds intermittently. 2. FIM 23-34-00/101, Fig. 103, Block 1.
23 34 17 00	1. Pass entmt channel select (describe problem: unable to change channels, etc.) at seat ____. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 18 00	1. Pass entmt channel sel (describe problem: unable to change channels, etc.) at row ____. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 19 00	1. Pass entmt (describe problem: noisy, inop, etc.) at seat ____. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 20 00	1. Pass entmt (describe problem: noisy, inop, etc.) at row ____. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 21 --	1. Pass entmt (describe problem: noisy, inop, etc.) aft of row ____ in (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Mid L, 07=Mid C, 08=Mid R, 10=Aft L, 11=Aft C, 12=Aft R, 13=All) sections. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 22 --	1. (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Mid L, 07=Mid C, 08=Mid R, 10=Aft L, 11=Aft C, 12=Aft R, 13=All) column pass entmt sections (describe problem: noisy, inop, etc.). 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 23 --	1. (01=Fwd, 05=Mid, 09=Aft) section pass entmt (describe problem: noisy, inop, etc.). 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 24 00	1. Pass entmt channel ____ (describe problem: noisy, inop, etc.). 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 25 00	1. All pass entmt channels (describe problem: noisy, inop, etc.) at all seats. Boarding music normal on PA. 2. FIM 23-34-00/101, Fig. 104, Block 1.

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 34 26 00	1. All pass entmt channels (describe problem: noisy, inop, etc.) at all seats. Boarding music on PA also, (Describe problem noisy, inop, etc.). 2. Replace the entertainment tape reproducer, M170 (AMM 23-34-03/201).
23 34 27 --	1. (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Aft C, 08=Aft R) column reading lgts blink (Ref Chapter 33 for fault code diagrams). 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 28 --	1. Master reading lgt switch fails to illum lgts in (01=Fwd, 05=Aft) section (Ref Chapter 33 for fault code diagrams). 2. Replace the Fwd (Aft) column timer decoder, M297 (M298) (AMM 23-34-07/401).
23 34 29 00	1. Master reading lgt switch fails to illum lgts in both sections (Ref Chapter 33 for fault code diagrams). 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 30 00	1. Reading lgt at seat ____ inop with seat switch. Master switch is normal (Ref Chapter 33 for fault code diagrams). 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 31 00	1. Reading lgt at seat ____ inop with both seat switch and master switch (Ref Chapter 33 for fault code diagrams). 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 32 --	1. In (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Aft L, 07=Aft C, 08=Aft R) column, reading lgts in row ____ inop with seat switches. Master switch is normal (Ref Chapter 33 for fault code diagrams). 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 33 --	1. In (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Aft L, 07=Aft C, 08=Aft R) column, reading lgts in row ____ inop with seat switches and master switch (Ref Chapter 33 for fault code diagrams). 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 34 --	1. In (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Aft L, 07=Aft C, 08=Aft R) column, reading lgts in row ____ and aft inop with seat switches. Master switch is normal (Ref Chapter 33 for fault code diagram). 2. FIM 23-34-00/101, Fig. 104, Block 1.

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 34 35 --	1. In (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Aft L, 07=Aft C, 08=Aft R) column, reading lgts in row ____ and aft inop with seat switches and master switch (Ref Chapter 33 for fault code diagram). 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 36 --	1. In (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Aft L, 07=Aft C, 08=Aft R) column, all reading lgts inop with seat switches. Master switch is normal (Ref Chapter 33 for fault code diagram). 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 37 --	1. In (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Aft L, 07=Aft C, 08=Aft R) column, all reading lgts inop with seat switches and master switch (Ref Chapter 33 for fault code diagram). 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 38 --	1. Reading lgts in (01=Fwd, 05=Aft) section inop with seat switches. Master switch is normal (Ref Chapter 33 for fault code diagram). 2. Replace the Fwd (Aft) column timer decoder, M297 (M298) (AMM 23-34-07/401).
23 34 39 --	1. Reading lgts in (01=Fwd, 05=Aft) section inop with seat switches and master switch (Ref Chapter 33 for fault code diagram). 2. Replace the Fwd (Aft) column timer decoder, M297 (M298) (AMM 23-34-07/401).
23 34 41 00	1. Attendant call lgt in PSU inop at seat ____. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 42 --	1. (02=Fwd L, 04=Fwd R, 05=Mid L, 08=Mid R, 18=Aft L, 20=Aft R) blue call lgts remain illum with no call lgts illum in PSU. MSTR call reset will reset lgts. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 43 00	1. Entertainment tape plays too (fast, slow). 2. Replace the entertainment tape reproducer, M170 (AMM 23-34-03/201).
23 34 46 --	1. (01=Fwd, 15=Aft) master attendant call reset not normal. 2. FIM 23-34-00/101, Fig. 104, Block 1.

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 34 47 --	1. (02=Fwd L, 04=Fwd R, 09=Mid Fwd L, 10=Mid Fwd R, 11=Mid Ctr L, 12=Mid Ctr R, 13=Mid Aft L, 14=Mid Aft R, 16=Aft L, 17=Aft R) attendant call lgts blink. Chime sounds. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 48 --	1. (02=Fwd L, 04=Fwd R, 09=Mid Fwd L, 10=Mid Fwd R, 11=Mid Ctr L, 12=Mid Ctr R, 13=Mid Aft L, 14=Mid Aft R, 16=Aft L, 17=Aft R) attendant call lgts blink. Chime doesn't sound. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 49 --	1. (02=Fwd L, 04=Fwd R, 09=Mid Fwd L, 10=Mid Fwd R, 11=Mid Ctr L, 12=Mid Ctr R, 13=Mid Aft L, 14=Mid Aft R, 16=Aft L, 17=Aft R) blue call lgt(s) inop. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 50 --	1. (01=Fwd, 05=Mid, 15=Aft) blue call lgts remain illum with no call lgts illum in PSU. MSTR call reset will reset lgts. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 51 --	1. (02=Fwd L, 03=Fwd C, 06=Mid L, 08=Mid R, 16=Aft L, 18=Aft R) attendant call chime(s) inop when calling from seat _____. Call lgts are normal. 2. (02=Fwd L, 03=Fwd C) replace the electronic chime, B139 (B144) at the position where the problem occurs (AMM 23-42-04/401). If the problem continues, replace the Fwd column timer decoder, M1319 (AMM 23-34-07/401). (06=Mid L, 08=Mid R) replace the electronic chime, B145 (B146) at the position where the problem occurs (AMM 23-42-04/401). If the problem continues, replace the Mid column timer decoder, M1320 (AMM 23-34-07/401). (16=Aft L, 18=Aft R) replace the electronic chime, B147 (B148) at the position where the problem occurs (AMM 23-42-04/401). If the problem continues, replace the Aft column timer decoder, M1306 (AMM 23-34-07/401).
23 34 52 --	1. (02=Fwd L, 03=Fwd C, 06=Mid L, 08=Mid R, 16=Aft L, 18=Aft R) cabin chime sounds intermittently. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 53 --	1. In (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Mid L, 07=Mid C, 08=Mid R, 16=Aft L, 17=Aft C, 18=Aft R) column, attendant call lgt for row ___ and aft inop. Chime fails to sound. 2. FIM 23-34-00/101, Fig. 104, Block 1.

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 34 54 --	1. (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Mid L, 07=Mid C, 08=Mid R, 16=Aft L, 17=Aft C, 18=Aft R) column attendant call lgts inop. Chime fails to sound. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 55 --	1. (01=Fwd, 05=Mid, 15=Aft) section attendant call lgts inop. Chime fails to sound. 2. FIM 23-34-00/101, Fig. 104, Block 1.
23 34 56 --	1. In (02=Fwd L, 03=Fwd C, 04=Fwd R, 06=Mid L, 07=Mid C, 08=Mid R, 16=Aft L, 17=Aft C, 18=Aft R) column, attendant call lgt for row ___ inop. Chime fails to sound. 2. Replace the seat electronic box, M915 (AMM 23-34-04/401) in the seat row where the problem occurs.
23 41 01 --	1. (05=Aft Cargo, 06=Main E/E Headset, 07=Main E/E Phone, 08=Main E/E Mic, 09=Fwd Cargo, 10=Weather Radar, 11=Nose W/W, 12=Fueling, 13=Jackscrew, 14=APU Shroud, 15=R W/W) service jack (describe problem: noisy, inop, etc.). 2. Replace the jack at the position where the problem occurs (WDM 23-41-11).
23 41 02 00	1. Comm from service inph jacks (describe problem: noisy, inop, no sidetone, etc.) using any audio selector panel. 2. Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 41 03 00	1. Unable to receive transmission from service inph external jacks. SERV INTPH switch is ON. 2. Replace the audio accessory unit, M108 (AMM 23-42-01/401). If the problem continues, replace the flight recorder control panel, M33 (bad service interphone switch) (AMM 31-31-04/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX



BOEING
767
FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 41 04 --	<ol style="list-style-type: none"> Comm on service inph (describe problem: noisy, inop, no sidetone, etc.) from (01=Capt, 02=F/O, 03=1st Obs) audio selector panel. Norm from other crew pos. Replace the audio selector panel, M70 (M71, M8, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 42 02 --	<ol style="list-style-type: none"> (01=Fwd, 08=Mid, 12=Aft, 19=All) attendant's pink call lights inop. Chime does sound. (01=Fwd, 08=Mid, 12=Aft) replace the attendant's pink call light (FIM 33-25-00/101, Fig. 103, Block 1). (19=All) replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 03 --	<ol style="list-style-type: none"> Alert call from (02=Fwd L, 04=Fwd R, 08=Mid, 09=Mid L, 15=Aft L, 16=Aft R, 17=Purser, 18=Cockpit, 19=All) station(s) fails to sound chime. Attendant's pink call lgts illum. Replace the passenger address amplifier, M177 (AMM 23-31-01/401). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 04 --	<ol style="list-style-type: none"> Alert call from (02=Fwd L, 04=Fwd R, 08=Mid, 09=Mid L, 15=Aft L, 16=Aft R, 17=Purser, 18=Cockpit, 19=All) station(s) fails to sound chime and illum attendant's pink call lgts. Replace the audio accessory unit, M108 (AMM 23-42-01/401). If the problem continues, replace the handset, B61 at the position where the problem occurs (WDM 23-42-11).
23 42 05 --	<ol style="list-style-type: none"> (01=Fwd, 08=Mid, 12=Aft) attendant call from cockpit overhead cabin call button fails to sound chime. Attendant's pink call lgts are normal. Replace the electronic chime, B139 (B144-148) at the position where the problem occurs (AMM 23-42-04/401). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 07 --	<ol style="list-style-type: none"> (01=Fwd, 08=Mid, 12=Aft) attendant call from cockpit overhead cabin call button fails to sound chime and illum attendant's pink call lights. FIM 23-42-00/101, Fig. 103, Block 1.

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 42 08 --	1. Cabin inph (describe problem: noisy, inop, etc.) when using (01=Capt, 02=F/O, 03=1st Obs, 04=2nd Obs) audio selector panel. Cabin inph normal using handsets. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 42 09 00	1. Cabin inph (describe problem: noisy, inop, etc.) when using audio selector panels. Cabin inph normal when using handsets. 2. Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 10 --	1. Cabin inph (describe problem: noisy, inop, etc.) when using (01=Capt, 04=Fwd L, 05=Fwd R, 06=Mid L, 07=Aft L, 08=Aft R, 09=Purser) handset. 2. Put the handset at a different position. If the problem follows, replace the defective handset, B61 (WDM 23-42-11). If the problem does not follow, replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 11 00	1. Cabin inph (describe problem: noisy, inop, etc.) when using any handset. 2. Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 12 --	1. Call from corresponding attendants station(s) fail(s) to illum (01=Fwd, 08=Mid, 12=Aft, 18=Alert, 19=All) CABIN CALL lgt. Cockpit chime normal. 2. (01=Fwd, 08=Mid, 12=Aft, 18=Alert) replace the CABIN CALL switchlight (WDM 23-42-11). If the problem continues, replace the pilots' call panel, M51 (AMM 23-42-02/401). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401). (19=All) replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 13 --	1. Call from (02=Fwd L, 05=Fwd R, 08=Mid, 09=Mid L, 15=Aft L, 16=Aft R, 17=Purser, 19=All) attendant(s) station(s) fail(s) to sound cockpit chime. Corresponding CABIN CALL lgt(s) are normal. 2. Replace the bell chime aural warning module, M1000 (AMM 31-51-04/401). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 42 14 --	1. Call from (02=Fwd L, 05=Fwd R, 08=Mid, 09=Mid L, 15=Aft L, 16=Aft R, 17=Purser, 19=All) attendants station(s) fail(s) to sound cockpit chime or illum corresponding CABIN CALL lgt(s). 2. (02=Fwd L, 05=Fwd R, 08=Mid, 09=Mid L, 15=Aft L, 16=Aft R, 17=Purser) replace the handset, B61 that you used to make the call (WDM 23-42-11). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401). (19=All) replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 15 00	1. Cockpit handset (describe problem: noisy, unable to talk, etc.). 2. Replace the handset, B61 (WDM 23-42-11).
23 42 16 --	1. (02=Fwd L, 03=Fwd C, 04=Fwd Ctr R, 05=Fwd R, 06=Fwd Aft L, 07=Fwd Aft R, 09=Mid L, 10=Mid C, 11=Mid R, 13=Aft Fwd L, 14=Aft Fwd R, 15=Aft L, 16=Aft R, 17=Purser, 19=All) attendant pink call lgt(s) inop when calling from handsets. Chime does sound. 2. Replace the attendant's pink call light at the position where the problem occurs (FIM 33-25-00/101, Fig. 103, Block 1). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401). (19=All) replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 17 --	1. (02=Fwd L, 03=Fwd C, 09=Mid L, 11=Mid R, 15=Aft L, 16=Aft R, 17=Purser, 19=All) cabin chime(s) and call lgts inop when calling from handsets. 2. (02=Fwd L, 03=Fwd C, 09=Mid L, 11=Mid R, 15=Aft L, 16=Aft R, 17=Purser) FIM 23-42-00/101, Fig. 103, Block 1. (19=All) replace the audio accessory unit, M108 (AMM 23-42-01/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 42 19 --	1. (01=Fwd, 02=Fwd L, 03=Fwd C, 08=Mid, 09=Mid L, 11=Mid R, 12=Aft, 15=Aft L, 16=Aft R, 17=Purser, 19=All) cabin chime(s) sound is weak. 2. (01=Fwd, 02=Fwd L, 03=Fwd C, 08=Mid, 09=Mid L, 11=Mid R, 12=Aft, 15=Aft L, 16=Aft R, 17=Purser) replace the electronic chime, B139 (B144-148, B376) at the position where the problem occurs (AMM 23-42-04/401). (19=All) replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 42 21 --	1. (02=Fwd L, 03=Fwd C, 04=Fwd R, 05=Fwd Ctr R, 06=Fwd Aft L, 07=Fwd Aft R, 09=Mid L, 10=Mid C, 11=Mid R, 13=Aft Fwd L, 14=Aft Fwd R, 15=Aft L, 16=Aft R, 17=Purser) attendant's pink call lgt inop. 2. Replace the attendant's pink call light at the position where the problem occurs (FIM 33-25-00/101, Fig. 103, Block 1).
23 42 22 00	1. Cabin chime sounds intermittently for no reason. Call lgts did not illum and chime would not reset. 2. Replace the audio accessory unit, M108 (AMM 23-42-01/401). If the problem continues, replace the electronic chime, B139 (B144-148) (AMM 23-42-04/401).
23 42 23 --	1. (02=Fwd L, 03=Fwd C, 09=Mid L, 11=Mid R, 15=Aft L, 16=Aft R, 17=Purser, 19=All) cabin chime(s) inop when calling from handsets. Call lgts do illum. 2. (02=Fwd L, 03=Fwd C, 09=Mid L, 11=Mid R, 15=Aft L, 16=Aft R, 17=Purser) replace the electronic chime, B139 (B144-148, B376) at the position where the problem occurs (AMM 23-42-04/401). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401). (19=All) replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 43 01 00	1. Call from Nose W/W fails to sound cockpit chime. GND CALL lgt ON. 2. Replace the bell chime aural warning module, M1000 (AMM 31-51-04/401). If the problem continues, replace the audio accessory unit, M108 (AMM 23-42-01/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 43 02 00	1. Call from Nose W/W fails to illum GND CALL lgt and sound cockpit chime. 2. Replace the FLIGHT DECK CALL switch, S426 on the APU remote control panel (WDM 23-43-11). If the problem continues, replace the pilots' call panel, M51 (AMM 23-42-02/401).
23 43 03 00	1. Call from Nose W/W fails to illum GND CALL lgt. Cockpit chime normal. 2. Replace the GND CALL switchlight on the pilots' call panel, M51 (WDM 23-43-11). If the problem continues, replace the pilots' call panel, M51 (AMM 23-42-02/401).
23 43 04 00	1. Ground crew call horn sounds continuously. Related systems in normal configuration. 2. FIM 23-43-00/101, Fig. 104, Block 1.
23 43 05 00	1. Equipment cooling failure indicated by EICAS display. Ground crew call horn fails to sound. 2. FIM 23-43-00/101, Fig. 105, Block 1.
23 43 06 00	1. Ground crew call horn fails to sound when GND CALL switch is depressed. 2. Replace the ground crew call horn, B60 (AMM 23-43-01/401). If the problem continues, replace the pilots' call panel, M51 (AMM 23-42-02/401).
23 43 07 00	1. Ground crew call horn sounding. L and R main DC buses not powered. Inertial reference mode panel switches (L, Ctr, or R) not set to OFF. 2. Put all the inertial reference mode panel switches on the P5 panel to the OFF position.
23 43 08 00	1. Ground crew call horn fails to sound. L and R main DC buses not powered. Inertial reference mode panel switches (L, Ctr or R) not set to OFF. 2. FIM 23-43-00/101, Fig. 105, Block 1.
23 43 09 00	1. GND CALL switch on pilots' call panel stuck in depressed position. 2. Replace the pilots' call panel, M51 (AMM 23-42-02/401).
23 51 01 --	1. (01=Capt, 02=F/O) speaker (describe problem: low, noisy, etc.). 2. Replace the interphone speaker, B1 (B2) at the flight crew position where the problem occurs (AMM 23-51-02/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX

07

Page 27
Dec 22/01


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 51 03 --	1. (01=Capt, 02=F/O, 03=1st Obs, 04=2nd Obs) headset (describe problem: noisy, unable to hear, etc.). 2. Replace the headset (WDM 23-51-11, WDM 23-51-21, WDM 23-51-41)
23 51 04 --	1. (01=Capt, 02=F/O, 03=1st Obs) hand mic unsatisfactory. 2. Replace the hand mic (WDM 23-51-11, WDM 23-51-21, WDM 23-51-41).
23 51 05 --	1. (01=Capt, 02=F/O, 03=1st Obs) boom mic unsatisfactory. 2. Replace the boom mic (WDM 23-51-11, WDM 23-51-21, WDM 23-51-41).
23 51 06 --	1. (01=Capt, 02=F/O, 03=1st Obs) oxy mask mic unsatisfactory. 2. Replace the oxygen mask (WDM 23-51-11, WDM 23-51-21, WDM 23-51-41).
23 51 09 08	1. Xmission is (inop, weak, intermittent, etc.) using 1st Obs PTT. 2. Replace the 1st Obs audio selector panel, M98 (AMM 23-51-01/401).
23 51 10 --	1. Xmission is (inop, weak, intermittent, etc.) using (06=Capt, 07=F/O) control wheel PTT sw. Other pilot PTT sw norm. 2. Replace the audio selector panel, M70 (M71) at the flight crew position where the problem occurs (AMM 23-51-01/401). If the problem continues, replace the Capt (F/O) control wheel PTT switch, S550 (S552) (AMM 23-51-03/401).
23 51 12 --	1. Xmission from any crew position on (01=L VHF, 02=R VHF, 03=C VHF, 04=L HF, 05=R HF) comm not norm. (Describe). 2. (01=L VHF, 02=R VHF, 03=C VHF) replace the VHF comm transceiver, M188 (M189, M190) (AMM 23-12-01/401). (04=L HF, 05=R HF) replace the HF comm transceiver, M152 (M153) (AMM 23-11-03/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 51 15 00	1. Xmission from Nose W/W on flt inph (describe problem: noisy, inop, etc.). 2. Replace the flight interphone jack, D8545 (WDM 23-51-11).
23 51 16 00	1. Reception at Nose W/W on flt inph (describe problem: noisy, inop, etc.). 2. Replace the flight interphone jack, D8545 (WDM 23-51-11).
23 51 17 --	1. Flt inph reception at (01=Capt, 02=F/O, 03=1st Obs) audio selector panel (describe problem: noisy, inop, etc.). Other stations normal. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 18 --	1. Flt inph xmission at (01=Capt, 02=F/O, 03=1st Obs) audio selector panel (describe problem: noisy, inop, etc.). Other stations normal. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 19 00	1. Flt inph abnormal at all crew stations. 2. Replace the audio accessory unit, M108 (AMM 23-42-01/401).
23 51 20 --	1. Cockpit speaker will not mute with (01=Capt, 02=F/O) audio selector panel in OXY position, using hand mic. 2. Replace the audio selector panel, M70 (M71) at the flight crew position where the problem occurs (AMM 23-51-01/401). If the problem continues, replace the interphone speaker, B1 (B2) (AMM 23-51-02/401).
23 51 21 --	1. (01=Capt, 02=F/O, 03=1st Obs) audio selector panel has bleed thru (describe). 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401). If the problem continues, do an inspection of the contrahelical cable and include the shield wire connections at the grounding stud, GDX3-S. Repair or replace as necessary (WDM 23-51-11, WDM 23-51-14, WDM 23-51-21, WDM 23-51-41).
23 51 22 --	1. (01=Capt, 02=F/O, 03=1st Obs) audio selector panel lighting faulty (volume control, etc.). 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).

EFFECTIVITY

ALL

23-FAULT CODE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 51 23 --	1. (01=Capt, 02=F/O, 03=1st Obs) audio selector panel volume control (inop, knobs broken, loose, etc.). 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 24 --	1. (Identify radio) mic select sw (will not stay engaged, sticks, etc.) on (01=Capt, 02=F/O, 03=1st Obs) ASP. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 26 --	1. (06=Capt, 07=F/O) control wheel PTT sw (sticks, etc.). 2. Clean the rocker and the switch with a contact cleaner. If the problem continues, replace the Capt (F/O) control wheel mic PTT switch, S550 (S552) (AMM 23-51-03/401).
23 51 30 --	1. (Unable to transmit, transmission weak, etc.) using mic select sw position on (01=Capt, 02=F/O, 03=1st Obs) audio selector panel. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 31 --	1. (Unable to receive, reception weak, intermittent, etc.) using mic select sw position on (01=Capt, 02=F/O, 03=1st Obs) audio selector panel. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 51 32 --	1. Sidetone (missing, weak, intermittent, etc.) using (01=Capt, 02=F/O, 03=1st Obs) audio selector panel. 2. Replace the audio selector panel, M70 (M71, M98) at the flight crew position where the problem occurs (AMM 23-51-01/401).
23 71 01 00	1. Voice recorder signal is (noisy, missing, etc.) at monitor jack. 2. FIM 23-71-00/101, Fig. 103, Block 2.

EFFECTIVITY

ALL

23-FAULT CODE INDEX

 **BOEING**
767
FAULT ISOLATION/MAINT MANUAL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
23 71 02 00	1. Voice recorder monitor response to test is (describe problem: low, high, etc.). 2. FIM 23-71-00/101, Fig. 103, Block 1.

EFFECTIVITY

ALL

23-FAULT CODE INDEX

07

Page 31
Dec 22/99


BITE Index

1. General

- A. Use this index to find the BITE procedure for the applicable LRU/System.
- B. The BITE procedure will provide the fault isolation instructions for the fault indications/LRU maintenance messages.

<u>LRU/System Name</u>	<u>Acronym</u>	<u>FIM Reference</u>
ACARS Management Unit		23-22
Air Data Computer	ADC	34-12
Air Data Inertial Reference Unit	ADIRU	34-26
Air Supply Control and Test Unit	ASCTU	36-20
Air Traffic Control Transponder	ATC	34-53
Airborne Vibration Monitor Signal Conditioner	AVM	77-31
Antiskid/Autobrake Control Unit	AACU	32-42
APU Fire Detection System		26-15
Automatic Direction Finder Receiver	ADF	34-57
APU Control Unit (or Electronic Control Unit)	ECU	49-11
Autopilot/Flight Director	AFDS	22-00
Auxiliary Zone Temperature Controller	AZTC	2160/21-61
Brake Temperature Monitor Unit	BTMU	32-46
Bus Power Control Unit	BPCU	24-20
Cabin Pressure Controller	CPC	21-30/21-31
Cabin Temperature Controller	CTC	21-61
Digital Flight Data Acquisition Unit	DFDAU	31-31
Distance Measuring Equipment Interrogator	DME	34-55
Duct Leak (Wing and Body)		26-18
E/E Cooling Control Card (If cards installed)		21-58
ECS Bleed Configuration Card		36-10
Electronic Control Unit	ECU	49-11
Electronic Engine Control Monitor Unit (Non-FADEC Engines)	EECM	71-EECM Message Index
Electronic Flight Instrument System	EFIS	34-22

Bite Index
Figure 1 (Sheet 1)




23-BITE INDEX


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

<u>LRU/System Name</u>	<u>Acronym</u>	<u>FIM Reference</u>
Engine Fire/Overheat Detection System		26-11
Engine Indication and Crew Alerting System Computer	EICAS	31-41
Enhanced Ground Proximity Warning Computer	EGPWC	34-46
Equipment Cooling System Controller		21-58
Equipment Cooling Temperature Controller		21-58
Flap/Slat Electronic Unit	FSEU	27-51
Flap/Stabilizer Position Module	FSPM	27-58
Flight Management Computer	FMC	34-61
Fuel Quantity Indicating System Processor	FQIS	28-41
Ground Proximity Warning Computer	GPWC	34-46
HF (High Frequency) Communication		23-11
In-Flight Entertainment Equipment Cooling Card		21-58
Inertial Reference Unit	IRU	34-21
Instrument Comparator Unit	ICU	34-25
Instrument Landing System Receiver	ILS	34-31
Large Format Display System	LFDS	31-63
Lower Cargo Compartment Smoke Detection System		26-16
Maintenance Control Display Panel	MCDP	22-00
Multi-Mode Receiver	MMR	34-31
PA (Passenger Address) Amplifier		23-31
Pack Standby Temperature Controller	PSTC	21-51
Pack Temperature Controller	PTC	21-51
Passenger Entertainment System	PES	23-34
Power Supply Module (Control System Electronics Units)	PSM	27-09
Propulsion Interface and Monitor Unit (FADEC Engines)	PIMU	71-PIMU Message Index
Proximity Switch Electronics Unit	PSEU	32-09

Bite Index
Figure 1 (Sheet 2)



23-BITE INDEX

01

Page 2
Aug 22/99




767

FAULT ISOLATION/MAINT MANUAL

<u>LRU/System Name</u>	<u>Acronym</u>	<u>FIM Reference</u>
Radio Altimeter Transmitter/Receiver	RA	34-33
Rudder Ratio Changer Module	RRCM	27-09
Satellite Data Unit	SDU	23-25
Spoiler Control Module	SCM	27-09
Stabilizer Trim/Elevator Asymmetry Limit Module	SAM	27-09
Stall Warning Computer/Module (in Warning Electronic Unit)	SWC	27-32
Strut Overheat Detection System (RR Engines)		26-12
Thrust Management Computer/Autothrottle	TMC	22-00
Traffic Alert and Collision Avoidance Computer	TCAS	34-45
VHF (Very High Frequency) Communication		23-12
VOR/Marker Beacon Receiver	VOR/MKR	34-51
Warning Electronic Unit BITE Module (Stall Warning)	WEU	27-32
Weather Radar Transceiver	WXR	34-43
Wheel Well Fire Detection		26-17
Window Heat Control Unit	WHCU	30-41
Yaw Damper Module	YDM	22-21
Yaw Damper/Stabilizer Trim Module	YSM	27-09
Zone Temperature Controller	ZTC	21-60/21-61

Bite Index
Figure 1 (Sheet 3)



23-BITE INDEX

01

Page 3
Aug 22/99


BOEING
767
FAULT ISOLATION/MAINT MANUAL

HF COMMUNICATIONS SYSTEM



COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
ANTENNA - HF COMM, M244	1	1	322BL, VERTICAL FIN	*
CIRCUIT BREAKER	2		FLT COMPT, P11	
LEFT HF COMM, C340		1	11G8	*
RIGHT HF COMM, C341		1	11G35	*
COUPLER - L, R HF COMM, M241,M242	1	2	322BL, VERTICAL FIN	23-11-01
DECODER - (REF 23-21-00, FIG. 101)				
SELCAL, M180				
PANEL - (REF 23-42-00, FIG. 101)				
PILOTS' CALL, M51				
PANEL - (REF 23-51-00, FIG. 101)				
AUDIO SELECTOR, M70,M71,M98				
PANEL - L, R HF COMM CONTROL, M82,M83	2	2	FLT COMPT, P5	23-11-02
TRANSCIVER - L, R HF COMM, M152,M153	2	2	119AL, MAIN EQUIP CTR, E2-6	23-11-03
UNIT - (REF 31-31-00, FIG. 101)				
DIGITAL FLIGHT DATA ACQUISITION, M138				

* SEE THE WDM EQUIPMENT LIST

HF Communications System - Component Index
Figure 101



23-11-00




LEFT OR RIGHT HF COMMUNICATIONS COUPLER,
M241 OR M242
(B)

HF Communications System - Component Location
Figure 102 (Sheet 1)


EFFECTIVITY	
ALL	

23-11-00


BOEING
767
FAULT ISOLATION/MAINT MANUAL



MAIN EQUIPMENT CENTER




FLIGHT COMPARTMENT



LEFT OR RIGHT HF COMMUNICATIONS TRANSCEIVER, M152 OR M153

(C)



LEFT OR RIGHT HF COMMUNICATIONS CONTROL PANEL, M82 OR M83

(D)

HF Communications System - Component Location
Figure 102 (Sheet 2)

EFFECTIVITY

ALL

23-11-00

08


Page 103
Aug 10/90

HIGH FREQUENCY COMMUNICATIONS SYSTEM BITE PROCEDURE

PREREQUISITES

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
11G8,11G35

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:
ELECTRICAL POWER IS ON (AMM 24-22-00/201)




High Frequency Communications System BITE Procedure
Figure 103 (Sheet 1)

EFFECTIVITY	ALL

23-11-00

BOEING
767
FAULT ISOLATION/MAINT MANUAL



High Frequency Communications System BITE Procedure
Figure 103 (Sheet 2)

EFFECTIVITY

ALL


23-11-00

04

Page 105
Aug 22/00

652172

BOEING
767
FAULT ISOLATION/MAINT MANUAL




High Frequency Communications System BITE Procedure
Figure 103 (Sheet 3)

EFFECTIVITY

ALL

23-11-00

FROM SHEET 3
(BLOCK 5)



High Frequency Communications System BITE Procedure
Figure 103 (Sheet 4)

EFFECTIVITY	ALL
-------------	-----

23-11-00

G73064

FROM SHEET 4
(BLOCK 6)



High Frequency Communications System BITE Procedure
Figure 103 (Sheet 5)

EFFECTIVITY _____
ALL

23-11-00

1. Fault Isolation - Tips

- A. HF Communication System faults can be caused by Flight Interphone System faults. If HF failures continue after the replacement of HF equipment, then replace suspected Flight Interphone System equipment (FIM 23-51-00/101).
 - (1) The equipment that follows are possible causes of HF audio input or keyline circuitry faults:
 - (a) audio selector panel or audio control panel
 - (b) audio management unit, if installed (only on airplanes with audio control panels)
 - (c) headsets, boom microphone headsets
 - (d) hand microphones
 - (e) control wheel push-to-talk switch
 - (f) flight interphone jacks for headsets and microphones
 - (g) wiring between the Flight Interphone System and HF Communication System.
- B. ARINC 429 data bus charts give data necessary to make an analysis of ARINC 429 transmitters, receivers, and data buses. A breakout box is used at the available terminal blocks or at the LRU connectors to do the tests.

CAUTION: DO NOT DIRECTLY TOUCH THE CONNECTORS. USE A BREAKOUT BOX OR YOU CAN CAUSE DAMAGE TO THE CONNECTORS.

2. Equipment

- A. Standard multi-meter
- B. Data Bus Analyzer - 429EB; JcAIR Instrumentation (preferred)
400 Industrial Parkway,
Industrial Airport, KS 66031

- 429-2; Interface Technology (optional)
150 E. Arrow Highway,
San Dimas, CA 91773
- C. Breakout box A34011-1 (preferred)
A34011-112 (optional)

EFFECTIVITY

ALL

23-11-00

05

Page 109
Aug 22/02


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

HF PNL							
DIGITAL OUTPUT BUS CHART							
BUS NAME	TYPE	BUS	CON	PINS	BUS FORMAT	BIT RATE	DATA BUS
SOURCE							
HFPNL (L R)	A	1		09 10	429	LO	FREQ/FUNC SELECT

HF PNL ID = B9								
OCTAL LABELS CHART								
SIGNAL	TYPE	LABEL	FORMAT	MIN UPDATE RATE	SDI	BINARY RANGE	POSITIVE SENSE	UNITS
HF FREQ SELECT	A	037	BCD	5		2.8-24	N/A	MHZ

EFFECTIVITY

ALL

23-11-00


 **BOEING**
767
FAULT ISOLATION/MAINT MANUAL

VHF COMMUNICATIONS SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
ANTENNA - C VHF COMM, M247	1	1	BOTTOM FUSELAGE, AFT	23-12-03
ANTENNA - L VHF COMM, M245	1	1	TOP FUSELAGE, FWD	23-12-03
ANTENNA - R VHF COMM, M246	1	1	BOTTOM FUSELAGE, FWD	23-12-03
CIRCUIT BREAKER -	2		FLT COMPT, P11	
VHF COMM C, C556		1	11G4	*
VHF COMM L, C544		1	11C3	*
VHF COMM R, C545		1	11G31	*
PANEL - (FIM 23-42-00/101)				
PILOTS' CALL, M51				
PANEL - (FIM 23-51-00/101)				
AUDIO SELECTOR, M70				
AUDIO SELECTOR, M71				
AUDIO SELECTOR, M98				
PANEL - C VHF CONTROL, M80	2	1	FLT COMPT, P8	23-12-02
PANEL - L VHF CONTROL, M78	2	1	FLT COMPT, P8	23-12-02
PANEL - R VHF CONTROL, M79	2	1	FLT COMPT, P8	23-12-02
RELAY - (FIM 32-09-00/101)				
SYS NO. 1 AIR/GROUND, K199				
SYS NO. 2 AIR/GROUND, K203				
TRANSCEIVER - C VHF COMM, M190	2	1	119AL, MAIN EQUIP CTR, E2-5	23-12-01
TRANSCEIVER - L VHF COMM, M188	2	1	119AL, MAIN EQUIP CTR, E2-5	23-12-01
TRANSCEIVER - R VHF COMM, M189	2	1	119AL, MAIN EQUIP CTR, E2-5	23-12-01
UNIT - (FIM 23-21-00/101)				
SELCAL DECODER, M180				
UNIT - (FIM 31-31-00/101)				
FLT DATA ACQUISITION, M138				



* SEE THE WDM EQUIPMENT LIST

VHF Communications System - Component Index
Figure 101



23-12-00

BOEING
 767
 FAULT ISOLATION/MAINT MANUAL



VHF COMMUNICATION ANTENNA LOCATIONS

VHF Communications System - Component Location
 Figure 102 (Sheet 1)



EFFECTIVITY	ALL
-------------	-----

23-12-00



04

Page 102
 Feb 10/94

315926



SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS




SAS
SAS
SAS

VHF Communications System - Component Location
Figure 102 (Sheet 2)

EFFECTIVITY	ALL
-------------	-----

**VHF COMMUNICATIONS
TRANSCIEVER BITE
PROCEDURE**


PREREQUISITES
ELECTRICAL POWER (MM 24-22-00/201)
CB'S: 11C3,11G4,11G31



VHF Communications Transceiver BITE Procedure
Figure 103 (Sheet 1)

EFFECTIVITY
AIRPLANES WITH COLLINS VHF-700/700A
TRANSCIEVERS

23-12-00



VHF Communications Transceiver BITE Procedure
Figure 103 (Sheet 2)

EFFECTIVITY
COLLINS VHF-700/700A
TRANSCEIVERS INSTALLED

23-12-00


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

1. Fault Isolation - Tips

- A. VHF Communication System faults can be caused by Flight Interphone System faults. If VHF failures continue after the replacement of VHF equipment, then replace suspected Flight Interphone System equipment (FIM 23-51-00/101).
 - (1) The equipment that follows are possible causes of VHF audio input or keyline circuitry faults:
 - (a) audio selector panel or audio control panel
 - (b) audio management unit, if installed (only on airplanes with audio control panels)
 - (c) headsets, boom microphone headsets
 - (d) hand microphones
 - (e) control wheel push-to-talk switch
 - (f) flight interphone jacks for headsets and microphones
 - (g) wiring between the Flight Interphone System and VHF Communication System.
- B. ARINC 429 data bus charts give data necessary to make an analysis of ARINC 429 transmitters, receivers, and data buses. A breakout box is used at the available terminal blocks or at the LRU connectors to do the tests.

CAUTION: DO NOT DIRECTLY TOUCH THE CONNECTORS. USE A BREAKOUT BOX OR YOU CAN CAUSE DAMAGE TO THE CONNECTORS.

2. Equipment

- A. Standard multi-meter
- B. Interface Technology model 429-2 Data Bus Analyzer.
- C. Breakout box A34011-1 (preferred) A34011-112 (optional)

VHF PNL							
DIGITAL OUTPUT BUS CHART							
BUS NAME		BUS	CON	PINS	BUS FORMAT	BIT RATE	DATA BUS
SOURCE	TYPE	BUS	CON	PINS	BUS FORMAT	BIT RATE	DATA BUS
VHF PNL (L C R)	A	1		17 18	429	LO	FREQ/FUNC SELECT

EFFECTIVITY _____
 ALL

23-12-00


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

VHF PNL ID = B6								
OCTAL LABELS CHART								
SIGNAL	TYPE	LABEL	FORMAT	MIN UPDATE RATE	SDI	BINARY RANGE	POSITIVE SENSE	UNITS
FREQ/FUNCTION SEL	A	030	BCD	5		118-136.97	N/A	MHZ

EFFECTIVITY _____

ALL

23-12-00



BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

SELCAL SYSTEM




COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
CIRCUIT BREAKER SELCAL, C539	--	1	FLT COMPT, P11 1163	*
DECODER - SELCAL, M180	--	1	119AL, MAIN EQUIP CTR, E2-5	23-21-01
MODULE - (REF 31-51-00, FIG. 101)				
BELL CHIME AURAL WARNING, M1000				
PANEL - (REF 23-42-00, FIG. 101)				
PILOTS' CALL, M51				
RECEPTACLE - SELCAL CODING, M974	--	1	119AL, MAIN EQUIP CTR, E2-5	*
SWITCH - (REF 23-42-00, FIG. 101)				
L VHF COMM, (S1)	--	1		
R VHF COMM, (S3)	--	1		
C VHF COMM, (S2)	--	1		
L HF COMM, (S4)	--	1		
R HF COMM, (S5)	--	1		
TRANSCEIVER - (REF 23-12-00, FIG. 101)				
C VHF COMM, M190				
L VHF COMM, M188				
R VHF COMM, M189				
TRANSCEIVER - (REF 23-11-00, FIG. 101)				
L HF COMM, M152				
R HF COMM, M153				

* SEE THE WDM EQUIPMENT LIST

Selcal System - Component Index
Figure 101




23-21-00



PILOTS' CALL PANEL, M51 (REF)

(A)



SELCAL System - Component Location
Figure 102

EFFECTIVITY	ALL
-------------	-----

23-21-00

 **BOEING**
767
FAULT ISOLATION/MAINT MANUAL

ACARS

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
CIRCUIT BREAKER - ACARS DC PWR, C538	1	1	FLT COMPT, P6 6G5	*
CIRCUIT BREAKER - ACARS MGMT UNIT AC, C559	1	1	FLT COMPT, P11 11G6	*
COMPUTER - (FIM 31-41-00/101) L EICAS, M10181 R EICAS, M10182				
COMPUTER - (FIM 34-61-00/101) L FLIGHT MANAGEMENT, M134 R FLIGHT MANAGEMENT, M135				
DECODER - (FIM 23-21-00/101) SELCAL, M180				
DIODE - SELCAL LT ISOLATION, R76 MODULE - (FIM 31-41-00/101) EICAS LOWER DISPLAY SWITCHING, M10418 MODULE - (FIM 31-51-00/101) BELL/CHIME AURAL WARNING, M1000		1	119AL, MAIN EQUIP CTR, E2-5	*
PANEL - (FIM 23-12-00/101) C VHF CONTROL, M80				
PANEL - (FIM 23-22-00/101) VOICE/DATA SWITCH, TM1953	1	1	FLT COMPT, P8	23-22-02
PANEL - (FIM 23-22-00/101) VOICE/DATA SWITCH, M1953	1	1	FLT COMPT, P8	23-22-02
PANEL - (FIM 23-42-00/101) PILOTS' CALL, M51				
RECEPTACLE - REGISTRATION I/D CODING, M975	2	1	119AL, MAIN EQUIP CTR, E2-5 DISCONNECT BRACKET	*
TRANSCEIVER - (FIM 23-12-00/101) C VHF COMM, M190				
UNIT - (FIM 31-35-00/101) DATA MANAGEMENT, M1200				
UNIT - (FIM 34-61-00/101) L FLIGHT MANAGEMENT COMPUTER CONTROL/DISPLAY, M76 R FLIGHT MANAGEMENT COMPUTER CONTROL/DISPLAY, M77				
UNIT - L ACARS MANAGEMENT, M172	2	1	119AL, MAIN EQUIP CTR, E2-5	23-22-01

SAS
SAS
MTH
MTH

* SEE THE WDM EQUIPMENT LIST

ACARS - Component Index
Figure 101


EFFECTIVITY
SAS 150, 152-157, 162-167
MTH 275-278, 280-281

23-22-00

BOEING




767

FAULT ISOLATION/MAINT MANUAL




SAS
SAS
SAS
SAS
SAS
SAS
SAS

SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS



LEFT (RIGHT) FLIGHT MANAGEMENT COMPUTER CONTROL/DISPLAY UNIT, M76 (M77)(REF)

(A)



(C)

1 SAS 150,152-157, 162-167


2 MTH 275-278,280,281

**ACARS - Component Location
Figure 102 (Sheet 1)**


EFFECTIVITY
SAS 150, 152-157, 162-167
MTH 275-278, 280-281

23-22-00

BOEING
767
FAULT ISOLATION/MAINT MANUAL




SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS
SAS



ACARS MANAGEMENT UNIT (MU), M172

(D) 1



ACARS MANAGEMENT UNIT (MU), M172

(D) 2

ACARS - Component Location
Figure 102 (Sheet 2)


EFFECTIVITY

SAS 150, 152-157, 162-167
MTH 275-278, 280-281

23-22-00

**ACARS MANAGEMENT
 UNIT (MU) BITE
 PROCEDURE**

PREREQUISITES
 ELECTRICAL POWER (MM 24-22-00/201)
 CB'S: 6G5,11E8,11E9,11E29,11E30,11G6



ACARS Management Unit (MU) BITE Procedure
 Figure 103

EFFECTIVITY
 SAS 150, 152-157, 162-167
 MTH 275-278, 280-281

23-22-00

 **BOEING**
767
FAULT ISOLATION/MAINT MANUAL

1. ARINC Data Bus Charts

A. General

CAUTION: DO NOT DIRECTLY TOUCH THE CONNECTORS. USE A BREAKOUT BOX OR YOU CAN CAUSE DAMAGE TO THE CONNECTORS.

- (1) The ARINC 429 data bus charts give data necessary to make an analysis of ARINC 429 transmitters, receivers, and ata buses. For the test, use a breakout box at the available terminal or at the LRU connector.

B. Equipment

- (1) Standard multi-meter
- (2) 429EBP Data Bus Analyzer (recommended)
JcAIR Instrumentation
400 Industrial Parkway
Industrial Airport, KS 66031
- 429-2 Data Bus Analyzer (alternative)
Interface Technology
150 E. Arrow Highway
San Dimas, CA 91773
- (3) A34011-1 Breakout Box (recommended)
A34011-112 Breakout Box (alternative)

EFFECTIVITY
SAS 150, 152-157, 162-167
MTH 275-278, 280-281

23-22-00


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

ACR MU							
DIGITAL OUTPUT BUS CHART							
BUS NAME	TYPE	BUS	CON	PINS	BUS FORMAT	BIT RATE	DATA BUS
SOURCE							
ACRMU (L)	A	1	B	G07 H07	429	LO	DATA TO DFDAU
ACRMU (L)	B	2	A	H13 J13	429	LO	DATA TO FMC-L
ACRMU (L)	B	3	B	C15 D15	429	LO	DATA TO FMC-R
ACRMU (L)	D	5	A	A09 B09	429	LO	DATA TO XCVR
ACRMU (L)	E	6	A	A07 B07	429	LO	FREQ. SELECT

ACR MU ID = 024								
OCTAL LABELS CHART								
SIGNAL	TYPE	LABEL	FORMAT	MIN UPDATE RATE	SDI	BINARY RANGE	POSITIVE SENSE	UNITS
DATA TO DFDAU	A	N/A	BNR	N/A		N/A	N/A	N/A
DATA TO FMC-L	B	N/A	BNR	N/A		N/A	N/A	N/A
DATA TO FMC-R	B	N/A	BNR	N/A		N/A	N/A	N/A
DATA TO XCVR	D	N/A	BNR	N/A		N/A	N/A	N/A
FREQ SELECT	E	030	BCD	5		118-135.97	N/A	MHZ

ACR PNL							
DIGITAL OUTPUT BUS CHART							
BUS NAME	TYPE	BUS	CON	PINS	BUS FORMAT	BIT RATE	DATA BUS
SOURCE							
ACRPNL (L)	A	1		T U	429	LO	CU DATA TO MU

EFFECTIVITY
 SAS 150, 152-157, 162-167
 MTH 275-278, 280-281

23-22-00


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

ACR PNL ID=024								
OCTAL LABELS CHART								
SIGNAL	TYPE	LABEL	FORMAT	MIN UPDATE RATE	SDI	BINARY RANGE	POSITIVE SENSE	UNITS
CU DATA TO MU	A	N/A	BNR	N/A		N/A	N/A	N/A

EFFECTIVITY
 SAS 150, 152-157, 162-167
 MTH 275-278, 280-281

23-22-00



767
FAULT ISOLATION/MAINT MANUAL

EMERGENCY LOCATOR TRANSMITTER (ELT)

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
ANTENNA - EMERGENCY LOCATOR TRANSMITTER, M1596	2	1	FUSELAGE	23-24-02
SWITCH - EMERGENCY LOCATOR TRANSMITTER REMOTE CONTROL, YDGS1	1	1	FLIGHT COMPARTMENT, P5 PANEL	*
TRANSMITTER - EMERGENCY LOCATOR, M1597	2	1	AFT PASSENGER CABIN CEILING, ABOVE E7 RACK	23-24-01

* SEE THE WDM EQUIPMENT LIST

Emergency Locator Transmitter (ELT) - Component Index
Figure 101



EFFECTIVITY
SAS 050-274

23-24-00

01

Page 101
May 10/94


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL




Emergency Locator Transmitter (ELT) - Component Location
Figure 102 (Sheet 1)


EFFECTIVITY
SAS 050-274

23-24-00


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL



ELT ANTENNA LOCATION




Emergency Locator Transmitter (ELT) - Component Location
Figure 102 (Sheet 2)

EFFECTIVITY
 SAS 050-274

23-24-00

EMERGENCY LOCATOR TRANSMITTER (ELT) FAULT ISOLATION

PREREQUISITES
 MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
 11C3, 11C26, 11G30
 MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:
 ELECTRICAL POWER IS ON (AMM 24-22-00/201)



¹ THE ELT FRONT PANEL SWITCH MUST BE IN THE "ARM" POSITION IMMEDIATELY AFTER THIS STEP. THE ELT POWER SUPPLY IS A NON-RECHARGEABLE BATTERY PACK THAT MUST BE REPLACED AFTER IT OPERATES FOR A TOTAL OF ONE HOUR.

Emergency Locator Transmitter (ELT) Fault Isolation
Figure 103


EFFECTIVITY
SAS 050-274

23-24-00

612306

 **BOEING**
767
FAULT ISOLATION/MAINT MANUAL

PASSENGER ADDRESS SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
AMPLIFIER - PASSENGER ADDRESS, M177	1	1	119AL, MAIN EQUIP CTR, E2-5	23-31-01
CIRCUIT BREAKER - PASS ADRS, C548	2	1	FLT COMPT, P11 11C22	*
CIRCUIT BREAKER - PRE-RECD ANNCT, C534		1	119AL, MAIN EQUIP CTR, P36	*
DIODE - R409-R418, R431-R438,  R475, R655		20	37J7 119AL, MAIN EQUIP CTR E2-5	*
HANDSET - (REF 23-42-00, FIG. 101) ATTENDANTS, B61 PILOTS', B61				
MULTIPLEXER - (REF 23-34-00, FIG. 101) AFT ZONE, M1307 FWD ZONE, M642 MID ZONE, M1321				
RELAY - (REF 31-01-19, FIG. 101) OXYGEN DEPLOYED INDICATION, K8 OXYGEN MANUAL DEPLOYED INDICATION, K42 PASSENGER SIGNS, K383, K384				
RELAY - (REF 31-01-36, FIG. 101) FLIGHT RECORDER CONTROL, K163				
RELAY - (REF 31-01-37, FIG. 101) FLIGHT RECORDER CONTROL, K164				
REPRODUCER - BOARDING MUSIC TAPE, M1708	2	1	PURSER STATION	23-31-10
REPRODUCER - (REF 23-34-00, FIG. 101) ENTERTAINMENT TAPE, M170				
SPEAKER - CEILING AFT L, B235	1	1	PASS CABIN	23-31-08
SPEAKER - CEILING, FWD L, B289	1	1	PASS CABIN	23-31-08
SPEAKER - CEILING, FWD L, B293	1	1	PASS CABIN	23-31-08
SPEAKER - CEILING, FWD R, B292	1	1	PASS CABIN	23-31-08
SPEAKER - CEILING MID, B243	1	1	PASS CABIN	23-31-08
SPEAKER - GALLEY, AFT L, B229	1	1	PASS CABIN	23-31-04
SPEAKER - GALLEY, AFT R, B230	1	1	PASS CABIN	23-31-04
SPEAKER - GALLEY, FWD, B70	1	1	PASS CABIN	23-31-04
SPEAKER - LAVATORY, FWD, M289	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, MID-CTR AFT, M1588	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, MID-CTR FWD, M1585	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, MID L AFT, M1587	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, MID L FWD, M1584	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, MID R AFT, M1589	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, MID R FWD, M1586	1	1	PASS CABIN	23-31-05
SPEAKER - PSU, B69	1			
SWITCHING CARDS - PASSENGER ADDRESS, M1634, M1635	2	2	119AL, MAIN EQUIP CTR E2-5	23-31-11
VOLUME LEVEL INDICATOR CARD - PASSENGER ADDRESS, M1633	2	1	119AL, MAIN EQUIP CTR E2-5	23-31-11
UNIT - (REF 23-42-00, FIG. 101) AUDIO ACCESSORY, M108			PASS CABIN	23-31-02

* SEE THE WDM EQUIPMENT LIST

 SAS 153-999

Passenger Address System - Component Index
Figure 101 (Sheet 1)

EFFECTIVITY
ALL SAS 767-300 AIRPLANES

23-31-00

 **BOEING**
767
FAULT ISOLATION/MAINT MANUAL

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
AMPLIFIER - PASSENGER ADDRESS, M177	1	1	119AL, MAIN EQUIP CTR, E2-5	23-31-01
CIRCUIT BREAKER - PASS ADRS, C548	2	1	FLT COMPT, P11 11C22	*
CIRCUIT BREAKER - PRE-RECD ANNCT, C534		1	119AL, MAIN EQUIP CTR, P36 37J7	*
DIODE - R409-R418, R431-R438, R475, R655		20	119AL, MAIN EQUIP CTR E2-5	
HANDSET - (REF 23-42-00, FIG. 101) ATTENDANTS, B61 PILOTS', B61				
MULTIPLEXER - (REF 23-34-00, FIG. 101) AFT ZONE, M1307 FWD ZONE, M642 MID ZONE, M1321				*
RELAY - (REF 31-01-19, FIG. 101) OXYGEN DEPLOYED INDICATION, K8 OXYGEN MANUAL DEPLOYED INDICATION, K42 PASSENGER SIGNS, K383, K384				
RELAY - (REF 31-01-36, FIG. 101) FLIGHT RECORDER CONTROL, K163				
RELAY - (REF 31-01-37, FIG. 101) FLIGHT RECORDER CONTROL, K164				
REPRODUCER - BOARDING MUSIC TAPE, M1708	2	1	PURSER STATION	23-31-10
REPRODUCER - (REF 23-34-00, FIG. 101) ENTERTAINMENT TAPE, M170				
SPEAKER - ATTENDANT, AFT L, B76	1	1	PASS CABIN	23-31-03
SPEAKER - ATTENDANT, AFT R, B77	1	1	PASS CABIN	23-31-03
SPEAKER - ATTENDANT, FWD L, B72	1	1	PASS CABIN	23-31-03
SPEAKER - ATTENDANT, FWD R, B73	1	1	PASS CABIN	23-31-03
SPEAKER - ATTENDANT, MID L, B74	1	1	PASS CABIN	23-31-03
SPEAKER - ATTENDANT, MID R, B75	1	1	PASS CABIN	23-31-03
SPEAKER - CEILING, FWD L, B289	1	1	PASS CABIN	23-31-08
SPEAKER - CEILING, FWD R, B292	1	1	PASS CABIN	23-31-08
SPEAKER - GALLEY, AFT L, B229	1	1	PASS CABIN	23-31-04
SPEAKER - GALLEY, AFT R, B230	1	1	PASS CABIN	23-31-04
SPEAKER - GALLEY, FWD, B70	1	1	PASS CABIN	23-31-04
SPEAKER - LAVATORY, FWD, M289	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, MID-CTR FWD, M1585	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, MID L AFT, M1587	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, MID L FWD, M1584	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, MID R AFT, M1589	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, MID R FWD, M1586	1	1	PASS CABIN	23-31-05
SPEAKER - PSU, B69	1			
SWITCHING CARDS - PASSENGER ADDRESS, M1634, M1635	2	2	119AL, MAIN EQUIP CTR E2-5	23-31-11
VOLUME LEVEL INDICATOR CARD - PASSENGER ADDRESS, M1633	2	1	119AL, MAIN EQUIP CTR E2-5	23-31-11
UNIT - (REF 23-42-00, FIG. 101) AUDIO ACCESSORY, M108			PASS CABIN	23-31-02

* SEE THE WDM EQUIPMENT LIST

Passenger Address System - Component Index
Figure 101 (Sheet 2)

EFFECTIVITY
ALL SAS 767-200 AIRPLANES

23-31-00

 **BOEING**
767
FAULT ISOLATION/MAINT MANUAL




COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
AMPLIFIER - PASSENGER ADDRESS, M177	1	1	119AL, MAIN EQUIP CTR, E2-5	23-31-01
CIRCUIT BREAKER - PASS ADRS, C548	2	1	FLT COMPT, P11 11C22	*
CIRCUIT BREAKER - PRE RECD ANNCT, C534	1	1	119AL, MAIN EQUIP CTR, P36 36J7	*
DECK - PA TAPE, M1523	4	1	PASS CABIN, FWD CLOSET	23-31-10
DIODE - R126	2	1	119AL, MAIN EQUIP CTR E2-5	*
HANDSET - (REF 23-42-00, FIG. 101) ATTENDANTS, B61 PILOTS ¹ , B61				
MULTIPLEXER - (REF 23-34-00, FIG. 101) AFT ZONE, M1307 FWD ZONE, M642 MID ZONE, M1321				
RELAY - (REF 31-01-19, FIG. 101) OXYGEN DEPLOYED INDICATION, K8 OXYGEN MANUAL DEPLOYED INDICATION, K42 PASSENGER SIGNS, K383, K384				
RELAY - (REF 31-01-36, FIG. 101) FLIGHT RECORDER CONTROL, K163				
RELAY - (REF 31-01-37, FIG. 101) FLIGHT RECORDER CONTROL, K164				
RELAY - VIDEO ANNCT, K671	2	1	119AL, MAIN EQUIP CTR, E2-5	*
REPRODUCER - (REF 23-34-00, FIG. 101) ENTERTAINMENT TAPE, M170				
SPEAKER - CEILING AFT, B235	1	1	PASS CABIN	23-31-08
SPEAKER - CEILING, FWD L, B246	1	1	PASS CABIN	23-31-08
SPEAKER - CEILING, FWD L, B289	1	1	PASS CABIN	23-31-08
SPEAKER - CEILING MID, B243	1	1	PASS CABIN	23-31-08
SPEAKER - GALLEY, AFT L, B229	1	1	PASS CABIN	23-31-04
SPEAKER - GALLEY, AFT R, B230	1	1	PASS CABIN	23-31-04
SPEAKER - GALLEY, FWD, B70	1	1	PASS CABIN	23-31-04
SPEAKER - LAVATORY, AFT L, M1186	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, AFT R, M1188	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, FWD, M289	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, MID CTR, M1312	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, MID L, M1156	1	1	PASS CABIN	23-31-05
SPEAKER - LAVATORY, MID R, M1157	1	1	PASS CABIN	23-31-05
SPEAKER - PSU, B69	1			*
UNIT - (REF 23-42-00, FIG. 101) AUDIO ACCESSORY, M108			PASS CABIN	23-31-02

* SEE THE WDM EQUIPMENT LIST


Passenger Address System - Component Index
Figure 101 (Sheet 3)

EFFECTIVITY
ALL MTH AIRPLANES

23-31-00




PA AMPLIFIER, M177
(B)




PA ACCESSORY BOX
(FRONT COVER SHOWN REMOVED)
(C)

1 SAS ALL


Passenger Address System - Component Location
Figure 102 (Sheet 1)



23-31-00



FWD ←
PURSER STATION
SEE (D)
FORWARD ENTRY DOOR AREA



PARTIAL VIEW OF PURSER STATION
(D)

Passenger Address System - Component Location
Figure 102 (Sheet 2)





EFFECTIVITY
SAS ALL

F52307

23-31-00

07

Page 105
Dec 22/01



- 2 MTH 275-278,281-999
- 3 MTH 279,280

Passenger Address System - Component Location
Figure 102 (Sheet 3)

EFFECTIVITY
MTH ALL


23-31-00

**PASSENGER ADDRESS
AMPLIFIER BITE
PROCEDURE**

PREREQUISITES

MAKE SURE THIS CIRCUIT BREAKER IS CLOSED:
11C22

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:
ELECTRICAL POWER IS ON (AMM 24-22-00/201)



NOTE: BITE DOES A TEST OF THESE SYSTEM COMPONENTS:

- PA AMPLIFIER
- SPEAKERS
- SPEAKER WIRING.


BITE DOES NOT DO A TEST OF THESE SYSTEM COMPONENTS:

- AUDIO ACCESSORY UNIT
- ZONE MULTIPLEXER.

SPEAKER LOCATION	AMM REFERENCE
PSU	23-31-02/401
ATTENDANT	23-31-03/401
GALLEY	23-31-04/401
LAVATORY	23-31-05/401
CEILING	23-31-08/401

TABLE 101

Passenger Address Amplifier BITE Procedure
Figure 103



23-31-00

 **BOEING**
767
FAULT ISOLATION/MAINT MANUAL

PASSENGER ENTERTAINMENT (VIDEO PROJECTION)

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
AMPLIFIER - (REF 23-31-00, FIG. 101) PASS ADRS, M177				
CIRCUIT BREAKERS VIDEO PROJECTION, C540	1	1	FLT COMPT, P11 11T34	*
CIRCUIT BREAKERS AFT VIDEO PROJECTOR, C555	1	1	119AL, MAIN EQUIP CTR, P37 37K7	*
FWD VIDEO PROJECTOR, C549		1	37K5	*
MID VIDEO PROJECTOR, C550		1	37K6	*
COUPLER - VIDEO ANTENNA, M820	1	1	VERT STAB, 322 BL	23-32-04
COMPUTER - (REF 34-12-00, FIG. 101) RIGHT AIR DATA, M101				
COMPUTER - (REF 34-61-00, FIG. 101) LEFT FLIGHT MANAGEMENT, M134				
DRIVER - (REF 23-34-00, FIG. 101) ZONE, M1308, M1710				
MONITOR - PASSENGER VIDEO, M1432 ² , M1562, M1563, M1611, M1612 ² , M1659 ¹	1	5	PASS CABIN	*
MULTIPLEXER - (REF 23-34-00, FIG. 101) AFT ZONE, M1307 FWD ZONE, M642 MID ZONE, M1321				
PANEL - ENTERTAINMENT, M1111	1	1	FLT COMPT, P5	*
PROJECTOR - VIDEO, M819	1	1	PASS CABIN	23-32-02
RELAY - (REF 31-01-19, FIG. 101) OXY DEPLOYED IND, K8 OXY MAN DEPLOYED IND, K42				
REPRODUCER - VIDEO TAPE, M1108, M1059, M1613	3	3	PASS CABIN, VIDEO CONTROL CTR	23-32-01
SPLITTER - COAX SIGNAL, M1526, M1527 ² , M1615 ²		3	PASS CABIN, ABOVE CEILING	*
SWITCH - MODE SELECTOR, M1614	2	1	PASS CABIN, VIDEO CONTROL CTR	*
TRANSFORMER - VIDEO, T232	3	1	119AL, MAIN EQUIP CTR, E1-4	*
TUNER - TV, M1113	1	1	PASS CABIN, VIDEO CONTROL CTR	23-32-06
UNIT - CONTROL DISTRIBUTION, M815	3	1	PASS CABIN, VIDEO CONTROL CTR	23-32-03
UNIT - DIGITAL INTERFACE, M1457	3	1	119AL, MAIN EQUIP CTR, E1-4	23-32-07
UNIT - LEFT HI BAND VIDEO MATCHING, M847	1	1	VERT STAB	*
UNIT - LEFT LO BAND VIDEO MATCHING, M970	1	1	VERT STAB	*
UNIT - RIGHT HI BAND VIDEO MATCHING, M846	1	1	VERT STAB	*
UNIT - RIGHT LO BAND VIDEO MATCHING, M969	1	1	VERT STAB	*

* SEE THE WDM EQUIPMENT LIST

- ¹ 767-200 AIRPLANES
- ² 767-300 AIRPLANES


Passenger Entertainment (Video Projection) - Component Index
Figure 101

EFFECTIVITY
ALL SAS AIRPLANES


23-32-00
CONFIG 1
Page 101
Dec 22/06

01

BOEING
767
FAULT ISOLATION/MAINT MANUAL



767-200 AIRPLANES



767-300 AIRPLANES


Passenger Entertainment (Video Projection) - Component Location
Figure 102 (Sheet 1)

EFFECTIVITY
ALL SAS AIRPLANES

23-32-00

CONFIG 1
Page 102
Nov 10/90

01



Passenger Entertainment (Video Projection) -
Component Location (Detail from Sheet 1)
Figure 102 (Sheet 2)


EFFECTIVITY
ALL SAS AIRPLANES

724260

23-32-00


CONFIG 1
Page 103
Nov 10/90

01




MODE SELECTOR SWITCH, M1614

B




TRANS COM VIDEO SYSTEM CONTROL DISTRIBUTION UNIT, M815

C



TV TUNER, M1113

D



VIDEO TAPE REPRODUCER, M1108, M1059, M1613

E

Passenger Entertainment (Video Projection) -
Component Location (Details from Sht 2)
Figure 102 (Sheet 3)



EFFECTIVITY
ALL SAS AIRPLANES

23-32-00

CONFIG 1
Page 104
Nov 10/90

01

BOEING
767
FAULT ISOLATION/MAINT MANUAL



Passenger Entertainment (Video Projection) - Component Location
Figure 102 (Sheet 4)

EFFECTIVITY
ALL SAS AIRPLANES


23-32-00

CONFIG 1


01

Page 105

Nov 10/90



VERTICAL STABILIZER



VIDEO ANTENNA COUPLER, M820

(H)

Passenger Entertainment (Video Projection) - Component Location
Figure 102 (Sheet 5)

EFFECTIVITY
ALL SAS AIRPLANES

614216

23-32-00

CONFIG 1
Page 106
Nov 10/90

01



767

FAULT ISOLATION/MAINT MANUAL

PASSENGER ENTERTAINMENT (VIDEO PROJECTION)

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
AMPLIFIER - (23-31-00/101) PASS. ADRS, M177				
CIRCUIT BREAKER - VIDEO PROJ, C540	6	1	FLT COMPT, P11 11T34	*
CIRCUIT BREAKERS - VIDEO AC CONT CTR, C1550	6	1	119AL, MAIN EQUIP CTR, P37 37K6	*
VIDEO AC 1, C1551		1	37L1	*
VIDEO AC 2, C1552		1	37L2	*
VIDEO AC 3, C1553		1	37L3	*
VIDEO AC 4, C1554		1	37L4	*
COUPLER - VIDEO ANTENNA, M820	7	1	VERT STAB, 322 BL	23-32-04
COMPUTER - (34-12-00/101) RIGHT AIR DATA, M101				
COMPUTER - (34-61-00/101) LEFT FLIGHT MANAGEMENT, M134				
MONITOR-1 - VIDEO, M1659	1,3	1	PASS. CABIN	23-32-10
MONITOR-2 - VIDEO, M1660	1,3	1	PASS. CABIN	23-32-10
MONITOR-3 - VIDEO, M1662	1,3	1	PASS. CABIN	23-32-10
MONITOR-4 - VIDEO, M1663	1,3	1	PASS. CABIN	23-32-10
MONITOR-5 - VIDEO, M1665 (PROV)	1,3	1	PASS. CABIN	23-32-10
MONITOR-6 - VIDEO, M1666	1,3	1	PASS. CABIN	23-32-10
MONITOR-7 - VIDEO, M1668	1,3	1	PASS. CABIN	23-32-10
MONITOR-8 - VIDEO, M1669 (PROV)	1,3	1	PASS. CABIN	23-32-10
MONITOR-9 - VIDEO, M1671 (PROV)	1,3	1	PASS. CABIN	23-32-10
MONITOR-10 - VIDEO, M1672 (PROV)	1,3	1	PASS. CABIN	23-32-10
MONITOR-11 - VIDEO, M1674 (PROV)	1,3	1	PASS. CABIN	23-32-10
MONITOR-12 - VIDEO, M1675 (PROV)	1,3	1	PASS. CABIN	23-32-10
MONITOR-13 - VIDEO, M1677 (PROV)	1,3	1	PASS. CABIN	23-32-10
MONITOR-14 - VIDEO, M1908	3	1	PASS. CABIN	23-32-10
MONITOR-15 - VIDEO, M1680	1,3	1	PASS. CABIN	23-32-10
MONITOR-16 - VIDEO, M1681	1,3	1	PASS. CABIN	23-32-10
MONITOR-17 - VIDEO, M1683	1,3	1	PASS. CABIN	23-32-10
MONITOR-18 - VIDEO, M1684	1,3	1	PASS. CABIN	23-32-10
MONITOR-19 - VIDEO, M1686	1,3	1	PASS. CABIN	23-32-10
MONITOR-20 - VIDEO, M1687	1,3	1	PASS. CABIN	23-32-10
MONITOR-21 - VIDEO, M1689	3	1	PASS. CABIN	23-32-10
MONITOR-22 - VIDEO, M1690	3	1	PASS. CABIN	23-32-10
MONITOR-23 - VIDEO, M1692	1,3	1	PASS. CABIN	23-32-10
MONITOR-24 - VIDEO, M1693	1,3	1	PASS. CABIN	23-32-10
MONITOR-25 - VIDEO, M1695	1,3	1	PASS. CABIN	23-32-10
MONITOR-26 - VIDEO, M1696	1,3	1	PASS. CABIN	23-32-10
MONITOR-27 - VIDEO, M1775 (PROV)	3	1	PASS. CABIN	23-32-10
MONITOR-28 - VIDEO, M1776	3	1	PASS. CABIN	23-32-10
MULTIPLEXERS - (23-34-00/101) AFT ZONE, M1307 FWD ZONE, M642 MID ZONE, M1321				
PANEL - ENTERTAINMENT, M1111	6	1	FLT COMPT, P5	*
PLUG - TERMINATION, M1697, M1698	1,3	2	PASS. CABIN, ABOVE CEILING	*
RELAY - (23-31-00/101) VIDEO ANNCT, K671				
RELAYS - (31-01-19/101) OXY DEPLOYED IND, K8 OXY MAN DEPLOYED IND, K42				

* SEE THE WDM EQUIPMENT LIST

MTH 275-278
 MTH 279-299

MTH 275-276
 MTH 277-299

Passenger Entertainment (Video Projection) - Component Index
Figure 101 (Sheet 1)

EFFECTIVITY
ALL MTH AIRPLANES

23-32-00

CONFIG 2

01






Page 101

Dec 22/06

671045

 **BOEING**
767
FAULT ISOLATION/MAINT MANUAL

PASSENGER ENTERTAINMENT (VIDEO PROJECTION)

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
REPRODUCER-1 - VIDEO TAPE (VTR-1), M1108	2,4	1	PASS. CABIN, VIDEO CONTROL CTR, FWD CLOSET	23-32-01
REPRODUCER-2 - VIDEO TAPE (VTR-2), M1059	2,4	1	PASS. CABIN, VIDEO CONTROL CTR, FWD CLOSET	23-32-01
REPRODUCER-3 - VIDEO TAPE (VTR-3), M1613 (PROV) 				
SWITCH - MODE SELECTOR, M1614 	5	1	PASS. CABIN, VIDEO CONTROL CTR, FWD CLOSET	*
TRANSFORMER - VIDEO, T232	6	1	119AL, MAIN EQUIP CTR, E1-4 IN DIU TRAY	*
UNIT - CABIN CONTROL (CCU), M1614 	2	1	PASS. CABIN, VIDEO CONTROL CTR, FWD CLOSET	23-32-09
UNIT - CONTROL DISTRIBUTION (CDU), M815	2,4	1	PASS. CABIN, VIDEO CONTROL CTR, FWD CLOSET	23-32-03
UNIT - DIGITAL INTERFACE (DIU), M1457	6	1	119AL, MAIN EQUIP CTR, E1-4	23-32-07
UNIT - LEFT HI BAND VIDEO MATCHING, M847	--	1	VERT STAB	*
UNIT - LEFT LO BAND VIDEO MATCHING, M970	--	1	VERT STAB	*
UNIT - RIGHT HI BAND VIDEO MATCHING, M846	--	1	VERT STAB	*
UNIT - RIGHT LO BAND VIDEO MATCHING, M969	--	1	VERT STAB	*
UNIT-1 - VIDEO DISTRIBUTION (VDU-1), M1658	1,3	1	PASS. CABIN, ABOVE CEILING	23-32-08
UNIT-2 - VIDEO DISTRIBUTION (VDU-2), M1661	1,3	1	PASS. CABIN, ABOVE CEILING	23-32-08
UNIT-3 - VIDEO DISTRIBUTION (VDU-3), M1664	1,3	1	PASS. CABIN, ABOVE CEILING	23-32-08
UNIT-4 - VIDEO DISTRIBUTION (VDU-4), M1667	1,3	1	PASS. CABIN, ABOVE CEILING	23-32-08
UNIT-5 - VIDEO DISTRIBUTION (VDU-5), M1670	1,3	1	PASS. CABIN, ABOVE CEILING	23-32-08
UNIT-6 - VIDEO DISTRIBUTION (VDU-6), M1673	1,3	1	PASS. CABIN, ABOVE CEILING	23-32-08
UNIT-7 - VIDEO DISTRIBUTION (VDU-7), M1676	1,3	1	PASS. CABIN, ABOVE CEILING	23-32-08
UNIT-8 - VIDEO DISTRIBUTION (VDU-8), M1711	3	1	PASS. CABIN, ABOVE CEILING	23-32-08
				
UNIT-9 - VIDEO DISTRIBUTION (VDU-9), M1679	1,3	1	PASS. CABIN, ABOVE CEILING	23-32-08
UNIT-10 - VIDEO DISTRIBUTION (VDU-10), M1682	1,3	1	PASS. CABIN, ABOVE CEILING	23-32-08
UNIT-11 - VIDEO DISTRIBUTION (VDU-11), M1685	1,3	1	PASS. CABIN, ABOVE CEILING	23-32-08
UNIT-12 - VIDEO DISTRIBUTION (VDU-12), M1688	3	1	PASS. CABIN, ABOVE CEILING	23-32-08
				
UNIT-13 - VIDEO DISTRIBUTION (VDU-13), M1691	1,3	1	PASS. CABIN, ABOVE CEILING	23-32-08
UNIT-14 - VIDEO DISTRIBUTION (VDU-14), M1694	1,3	1	PASS. CABIN, ABOVE CEILING	23-32-08

* SEE THE WDM EQUIPMENT LIST

Passenger Entertainment (Video Projection) - Component Index
Figure 101 (Sheet 2)

EFFECTIVITY
ALL MTH AIRPLANES


23-32-00
CONFIG 2
Page 102
Nov 10/92

01

BOEING

767

FAULT ISOLATION/MAINT MANUAL



Passenger Entertainment (Video Projection) - Component Location
Figure 102 (Sheet 1)

EFFECTIVITY
ALL MTH AIRPLANES


23-32-00

CONFIG 2

01

Page 103

Aug 22/01



- 1 MTH 275,276
- 2 MTH 277,278

Passenger Entertainment (Video Projection) - Component Location (Detail from Sht 1)
Figure 102 (Sheet 2)

EFFECTIVITY
ALL MTH AIRPLANES

A93998

23-32-00


CONFIG 2
Page 104
Aug 22/01

01

BOEING

767

FAULT ISOLATION/MAINT MANUAL



Passenger Entertainment (Video Projection) - Component Location
Figure 102 (Sheet 3)

EFFECTIVITY
ALL MTH AIRPLANES


23-32-00

CONFIG 2

01

Page 105

Aug 22/01



Passenger Entertainment (Video Projection) - Component Location (Detail from Sht 3)
Figure 102 (Sheet 4)

EFFECTIVITY
ALL MTH AIRPLANES


A93999

23-32-00

CONFIG 2
Page 106
Aug 22/01


01

BOEING
767
FAULT ISOLATION/MAINT MANUAL




MODE SELECTOR SWITCH, M1614

(C) 1



CONTROL DISTRIBUTION UNIT (CDU), M815

(D)



VIDEO TAPE REPRODUCER-1,-2 (VTR-1,VTR-2), M1108,M1059

(E)

1 MTH 275,276

Passenger Entertainment (Video Projection) - Component Location
(Details from Shts 2 and 4)
Figure 102 (Sheet 5)

EFFECTIVITY
ALL MTH AIRPLANES

670126

23-32-00



CONFIG 2

01

Page 107

Nov 10/92

BOEING
767
FAULT ISOLATION/MAINT MANUAL



Passenger Entertainment (Video Projection) - Component Location
Figure 102 (Sheet 6)

EFFECTIVITY
ALL MTH AIRPLANES


23-32-00

CONFIG 2


Page 108

Nov 10/92

01




VERTICAL STABILIZER



VIDEO DISTRIBUTION UNIT (VDU)
(EXAMPLE)

(H) FROM SHTS 1 AND 3



VIDEO ANTENNA COUPLER, M820

(I)

Passenger Entertainment (Video Projection) - Component Location
Figure 102 (Sheet 7)

EFFECTIVITY
ALL MTH AIRPLANES

23-32-00

CONFIG 2

Page 109

Nov 10/92

01

BOEING

767

FAULT ISOLATION/MAINT MANUAL

PASSENGER ENTERTAINMENT/PASSENGER SERVICE SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
AMPLIFIER - (23-31-00/101) PASSENGER ADDRESS, M177				
BOX - SEAT ELECTRONIC (SEB), M915	2	*	PASS. CABIN	23-34-04
BOX - SEAT ELECTRONIC (SEB), CREW REST, M1756	--	1	PASS. CABIN, CREW REST AREA	23-34-04
CARDS - (23-31-00/101) PA SWITCHING, M1634, M1635				
PA VOLUME LEVEL INDICATOR, M1633				
CHIMES - (23-42-00/101) AFT L ATTENDANT'S, B148				
AFT R ATTENDANT'S, B147				
FWD CTR ATTENDANT'S, B139				
FWD L ATTENDANT'S, B144				
MID L ATTENDANT'S, B146				
MID R ATTENDANT'S, B145				
CIRCUIT BREAKER - PASS ENTMT/SERVICE CONT, C547	2		FLT COMPT, P11	
CIRCUIT BREAKERS - AFT C PSUD, C536	1	1	11T8	*
FWD C PSUD, C531		1	119AL, MAIN EQUIP CTR, P33	
MID C PSUD, C507		1	33A3	*
CIRCUIT BREAKERS - L AFT PSUD, C535	1	1	33A4	*
L FWD PSUD, C530		1	33A5	*
MUX/TAPE REPRO, C546		1	119AL, MAIN EQUIP CTR, P36	
R AFT PSUD, C541		1	36J4	*
R FWD PSUD, C533		1	36J3	*
CIRCUIT BREAKERS - AFT CTD, C543	1	1	36J5	*
FWD CTD, C542		1	36J2	*
DECODER - AFT COLUMN TIMER, M1306	1	1	36J1	*
DECODER - FWD COLUMN TIMER, M1319	1	1	119AL, MAIN EQUIP CTR, P37	
DECODER - MID COLUMN TIMER, M1320	1	1	37K2	*
DECODERS - PASSENGER SERVICE UNIT (PSUD), M914, M1056	2	*	37K1	*
DECODER - PASSENGER SERVICE UNIT (PSUD), CREW REST, M1755	--	1	821, MID EQUIP CTR, E5	23-34-07
DIODES - (23-42-00/101) CHIME ISLN R86, R87, R88, R89, R285, R286, R287 			119AL, MAIN EQUIP CTR	23-34-07
DIODE - (31-01-33/101) K458 RELAY, R23			119AL, MAIN EQUIP CTR	23-34-07
DIODES - MASTER CALL ISLN, R312, R313	--	2	PASS. CABIN	23-34-08
DRIVERS - ZONE, M1308; M1710	1	2	PASS. CABIN, CREW REST AREA	23-34-08
			119AL, MAIN EQUIP CTR, E2-5, TB139	*
			119AL, MAIN EQUIP CTR, E3	23-34-10

* SEE THE WDM EQUIPMENT LIST

- | | |
|---|--|
| ALL SAS AIRPLANES
SAS 050-149
SAS 150-999
SAS 050-149, 162-999 | ALL MTH AIRPLANES
MTH 279-999
ALL EXCEPT SAS 050-149
ALL EXCEPT SAS 150-999 |
|---|--|

Passenger Entertainment/Passenger Service System - Component Index
Figure 101 (Sheet 1)

EFFECTIVITY


























ALL

23-34-00

BOEING

767

FAULT ISOLATION/MAINT MANUAL

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
LIGHT - AFT B/C L MASTER CALL, L581 	3	1	PASS. CABIN	*
LIGHT - AFT B/C R MASTER CALL, L582 	3	1	PASS. CABIN	*
LIGHT - AFT CTR MASTER CALL, L637 	3	1	PASS. CABIN	*
LIGHT - AFT L MASTER CALL, L583	3	1	PASS. CABIN	*
LIGHT - AFT R MASTER CALL, L584	3	1	PASS. CABIN	*
LIGHT - CTR T/C L MASTER CALL, L409 	3	1	PASS. CABIN	*
LIGHT - CTR T/C R MASTER CALL, L410 	--	1	PASS. CABIN	*
LIGHT - CREW REST LOWER BUNK READING, L1184 	--	1	PASS. CABIN, CREW REST AREA	23-34-09
LIGHT - CREW REST UPPER BUNK READING, L1183 	3	1	PASS. CABIN, CREW REST AREA	23-34-09
LIGHT - FWD B/C L MASTER CALL, L731 	3	1	PASS. CABIN	*
LIGHT - FWD B/C R MASTER CALL, L732 	3	1	PASS. CABIN	*
LIGHT - FWD MASTER CALL, L864 	3	1	PASS. CABIN	*
LIGHT - FWD L MASTER CALL, L579	3	1	PASS. CABIN	*
LIGHTS - FWD R MASTER CALL, L580; L864 	3	2	PASS. CABIN	*
LIGHTS - MID AFT L MASTER CALL, L1133 	3	2	PASS. CABIN	*
L687 	3	2	PASS. CABIN	*
LIGHTS - MID AFT R MASTER CALL, L1134 	3	2	PASS. CABIN	*
L688 	3	1	PASS. CABIN	*
LIGHT - MID CTR L MASTER CALL, L409 	3	1	PASS. CABIN	*
LIGHT - MID CTR R MASTER CALL, L410 	3	1	PASS. CABIN	*
LIGHTS - MID FWD L MASTER CALL, L731 	3	2	PASS. CABIN	*
L685 	3	2	PASS. CABIN	*
LIGHTS - MID FWD R MASTER CALL, L732 	3	2	PASS. CABIN	*
L686 	3	1	PASS. CABIN	*
LIGHT - MID L MASTER CALL, L581 	3	1	PASS. CABIN	*
LIGHT - MID R MASTER CALL, L582 	3	1	PASS. CABIN	*
LIGHT - MID T/C L MASTER CALL, L1133 	3	1	PASS. CABIN	*
LIGHT - MID T/C R MASTER CALL, L1134 	3	1	PASS. CABIN	*
LIGHT - PASSENGER SERVICE UNIT READING	2	*	PASS. CABIN	23-34-09
MULTIPLEXER - AFT ZONE, M1307	1	1	821, MID EQUIP CTR, E5	23-34-02
MULTIPLEXER - FWD ZONE, M642	1	1	119AL, MAIN EQUIP CTR	23-34-02
MULTIPLEXER - MAIN, M171	1	1	119AL, MAIN EQUIP CTR, E2-5	23-34-01
MULTIPLEXER - MID ZONE, M1321	1	1	119AL, MAIN EQUIP CTR	23-34-02

* SEE THE WDM EQUIPMENT LIST

Passenger Entertainment/Passenger Service System - Component Index
Figure 101 (Sheet 2)

EFFECTIVITY

ALL

23-34-00

 **BOEING**
767
FAULT ISOLATION/MAINT MANUAL

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
PANEL - (33-22-00/101) FWD ATTENDANT'S, P21				
PLUG - 50 OHM TERMINATION, M1307T	--	1	821, MID EQUIP CTR	*
PLUG - PSUD TERMINATION, M914T	--	*	PASS. CABIN	*
PLUG - PSUD TERMINATION, M1755T 4	--	1	PASS. CABIN, CREW REST AREA	*
PLUG - SEB TERMINATION, M915T	--	*	PASS. CABIN	*
RELAYS - (31-01-33/101) AFT PSS PWR, K459 FWD PSS PWR, K458 MID PSS PWR, K1305 6 PES PWR, K460 PES/PSS TEST, K928				
RELAY - CALL LIGHT, K1262 2	--	1	119AL, MAIN EQUIP CTR, E2-5	*
RELAYS - CHIME OFF, K1258, K1259 5	--	2	119AL, MAIN EQUIP CTR, E2-5	*
REPRODUCER - (23-31-00/101) BOARDING MUSIC TAPE, M1708 1				
REPRODUCER - ENTERTAINMENT TAPE, M170	1	1	119AL, MAIN EQUIP CTR, E2-5	23-34-03
RESISTOR, R658 4	--	1	PASS. CABIN, CREW REST AREA	*
SWITCH - PES/PSS TEST, YBHS31	2	1	PASS. CABIN, FWD ATTENDANT'S PANEL, P21	*
SWITCH - READING LIGHTS, YBHS6	2	1	PASS. CABIN, FWD ATTENDANT'S PANEL, P21	*
SWITCH/LIGHT - AFT MASTER CALL RESET, YBHS19	2	1	PASS. CABIN, FWD ATTENDANT'S PANEL, P21	*
SWITCH/LIGHT - CHIME SHUT-OFF, YBHS20 5	2	1	PASS. CABIN, FWD ATTENDANT'S PANEL, P21	*
SWITCH/LIGHT - FWD MASTER CALL RESET, YBHS14	2	1	PASS. CABIN, FWD ATTENDANT'S PANEL, P21	*
SWITCH/LIGHT - PES PWR, YBHS16	2	1	PASS. CABIN, FWD ATTENDANT'S PANEL, P21	*
SWITCH/LIGHT - PSS PWR, YBHS15	2	1	PASS. CABIN, FWD ATTENDANT'S PANEL, P21	*
UNIT - (23-32-00/101) VIDEO CONTROL DISTRIBUTION, M815				
UNIT - (23-42-00/101) AUDIO ACCESSORY, M108				
UNIT - PASSENGER CONTROL (PCU)	2	*	PASS. CABIN SEAT ARMRESTS	23-34-05
UNIT - PASSENGER CONTROL (PCU), CREW REST LOWER BUNK, M1757 4	--	1	PASS. CABIN, CREW REST AREA	23-34-05
UNIT - PASSENGER CONTROL (PCU), CREW REST UPPER BUNK, M1758 4	--	1	PASS. CABIN, CREW REST AREA	23-34-05

* SEE THE WDM EQUIPMENT LIST


Passenger Entertainment/Passenger Service System - Component Index
Figure 101 (Sheet 3)

EFFECTIVITY

ALL


23-34-00

BOEING
767
FAULT ISOLATION/MAINT MANUAL



MAIN EQUIPMENT CENTER
ACCESS DOOR, 119AL

SEE (A)




FWD

FORWARD CARGO
DOOR, 821

RIGHT SIDE

SEE (C)



CEILING AREA
FORWARD OF E2 RACK

SEE (B)

P37
PANEL

P33
PANEL

MAIN
MULTIPLEXER,
M171 (E2-5)

ENTERTAINMENT
TAPE REPRODUCER,
M170 (E2-5)

E3 RACK

ZONE DRIVERS,
M1308;
M1710


119AL

P36
PANEL

FWD

MAIN EQUIPMENT CENTER

(A)



FORWARD ZONE
MULTIPLEXER,
M642


MID ZONE
MULTIPLEXER,
M1321

FORWARD
COLUMN
TIMER
DECODER,
M1319

MID
COLUMN
TIMER
DECODER,
M1320

FWD INBD

E2 RACK
(REF)



AFT
COLUMN
TIMER
DECODER,
M1306

821

AFT ZONE
MULTIPLEXER,
M1307

MID EQUIPMENT CENTER, E5

(C)

CEILING AREA FORWARD OF E2 RACK





(B)

1 ALL SAS AIRPLANES

Passenger Entertainment/Passenger Service System - Component Location
Figure 102 (Sheet 1)

EFFECTIVITY	ALL
-------------	-----

23-34-00




Passenger Entertainment System - Component Location
Figure 102 (Sheet 2)



EFFECTIVITY	ALL
-------------	-----

23-34-00

613918



FORWARD ATTENDANT PANEL, P21



FORWARD ATTENDANT PANEL, P21



Passenger Entertainment System - Component Location (Detail from Sht 2)
Figure 102 (Sheet 3)

EFFECTIVITY


ALL

23-34-00


BOEING

767


FAULT ISOLATION/MAINT MANUAL



ALL SAS 767-300 AIRPLANES



ALL MTH AIRPLANES






ALL SAS 767-200 AIRPLANES

Passenger Entertainment System - Component Location
Figure 102 (Sheet 4)

EFFECTIVITY	ALL
-------------	-----

23-34-00



Passenger Entertainment System - Component Location (Details from Sht 4)
 Figure 102 (Sheet 5)

EFFECTIVITY	ALL
-------------	-----


23-34-00

CABIN CHIME SOUNDS INTERMITTENTLY

PREREQUISITES

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
11C22, 11C23, 11T8, 36J1, 36J2, 36J3, 36J4, 36J5, 37K1, 37K2; 2 33A3, 33A4; 1 37K3, 37K4

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:
ELECTRICAL POWER IS ON (AMM 24-22-00/201)
THE PASSENGER ADDRESS SYSTEM IS ON (AMM 23-31-00/501)
UTILITY BUS-R SWITCH IS ON (AMM 24-51-00/001) 3




- 1 767-200 AIRPLANES
- 2 767-300 AIRPLANES
- 3 POST-SB 24-0152, SAS 162-167, 276-278, 280


Cabin Chime Sounds Intermittently
Figure 103 (Sheet 1)

EFFECTIVITY	ALL
-------------	-----

23-34-00



Cabin Chime Sounds Intermittently
Figure 103 (Sheet 2)




23-34-00

PASSENGER ENTERTAINMENT PASSENGER SERVICE SYSTEM BITE PROCEDURE

PREREQUISITES

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
11C22, 11C23, 11T8, 36J1, 36J2, 36J3, 36J4, 36J5, 37K1, 37K2; **6** 33A3, 33A4; **5** 37K3, 37K4

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:
ELECTRICAL POWER IS ON (AMM 24-22-00/201)
THE PASSENGER ADDRESS SYSTEM IS ON (AMM 23-31-00/501)
UTILITY BUS-R SWITCH IS ON (AMM 24-51-00/001) **7**



NOTE: BITE DOES A TEST OF THESE SYSTEM COMPONENTS:
FORWARD COLUMN TIMER DECODER
AFT COLUMN TIMER DECODER
PASSENGER SERVICE UNIT DECODER
SEAT ELECTRONIC BOX
MASTER CALL LIGHTS
ATTENDANT CALL LIGHTS
MAIN MUX
FORWARD ZONE MUX
AFT ZONE MUX
PASSENGER CONTROL UNIT
MID ZONE MUX
MID COLUMN TIMER DECODER
BITE DOES NOT DO A TEST OF THESE SYSTEM COMPONENTS:
ENTERTAINMENT TAPE REPRODUCER
FORWARD ATTENDANT PANEL
ZONE DRIVER


- 1** IF THE FWD AND AFT MSTR CALL RESET LIGHTS DO NOT COME ON, CYCLE THE PASS ENT SYST TEST SWITCH FROM NORMAL TO MASTER TEST UP TO THREE TIMES BEFORE YOU DO THE SUBSEQUENT BLOCK
- 2** THE CHIME WILL OPERATE AT THE END OF THE TEST
- 3** AFTER THE REPAIR IS MADE, DO BLOCK 1 (MASTER TEST) AGAIN

- 4** SEE NOTE B
- 5** 767-200 AIRPLANES
- 6** 767-300 AIRPLANES
- 7** POST-SB 24-0152, SAS 162-167, 276-278, 280

Passenger Entertainment/Passenger Service System BITE Procedure
Figure 104 (Sheet 1)

EFFECTIVITY	ALL
-------------	-----

23-34-00




Passenger Entertainment/Passenger Service System BITE Procedure
Figure 104 (Sheet 2)

EFFECTIVITY

ALL

23-34-00

 **BOEING**
767
FAULT ISOLATION/MAINT MANUAL



NOTE A: A SHORTED COAXIAL CABLE CAN CAUSE PES/PSS FAILURES NOT IDENTIFIABLE BY THE BITE. IF THERE IS A FAILURE THAT THE BITE DOES NOT REMOVE, DO THE STEPS THAT FOLLOW:

1. FOR AUDIO, READING LIGHT OR ATTENDANT CALL LIGHT FAILURES, MAKE SURE THE SEB TERMINATION PLUG M915T HAS THE RESISTOR AND SHORTING WIRE INSTALLED CORRECTLY (REF SCH MAN 23-34-01,-02) AND THAT THE TERMINATION PLUG IS CORRECTLY ATTACHED TO THE SEB. 3
IF THE PROBLEM CONTINUES, MOVE THE SEB TERMINATION PLUG FORWARD IN THE COLUMN UNTIL THE FAILURE IS REMOVED. REPLACE THE LAST SEB TO SEB CABLE THAT YOU DISCONNECTED (WDM 23-34-13). INSTALL THE TERMINATION PLUG ON THE AFT SEB IN THE COLUMN. 3
2. FOR READING OR ATTENDANT CALL LIGHT FAILURES (AUDIO NORMAL), MAKE SURE THE PSUD TERMINATION PLUG M914T HAS THE SHORTING WIRE INSTALLED CORRECTLY AND THAT THE TERMINATION PLUG IS CORRECTLY ATTACHED TO THE PSUD. 3
IF THE PROBLEM CONTINUES, MOVE THE PSUD TERMINATION PLUG FORWARD IN THE COLUMN UNTIL THE FAILURE IS REMOVED. REPLACE THE LAST CABLE THAT YOU DISCONNECTED (WDM 23-34-13). INSTALL THE TERMINATION PLUG ON THE AFT PSUD IN THE COLUMN. 3

NOTE B: BEFORE YOU REPLACE THE COLUMN TIMER DECODER (CTD) LOOK FOR OPEN CIRCUITS BETWEEN PIN 4 AND 5 OF CONNECTORS J3, J4 AND J6 ON THE CTD REMOVED FROM THE AIRPLANE. IF THERE IS AN OPEN CIRCUIT AT ONE OR MORE OF THESE POINTS, AN INTERNAL FUSE HAS BLOWN WHICH IS A PROBLEM IN THE SEAT ELECTRONICS BOX (SEB)-TO-SEB WIRING. EXAMINE AND REPAIR THE SEB-TO-SEB WIRING (WDM 23-34,13,-14,-15) IN THE APPLICABLE COLUMN (J3-LEFT, J4-RIGHT, J6-CENTER) BEFORE YOU INSTALL NEW COLUMN TIMER DECODER.

Passenger Entertainment/Passenger Service System BITE Procedure
Figure 104 (Sheet 3)

EFFECTIVITY

ALL

23-34-00

04

Page 113
Nov 10/92

615715


BOEING
767
FAULT ISOLATION/MAINT MANUAL

SERVICE INTERPHONE SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
CIRCUIT BREAKER - INTERPHONE CABIN/SERVICE, C551	2	1	FLT COMPT, P11 11C23	*
JACK - SERVICE INTPH, D8503	2	1	312AR, JACKSCREW SERVICE	*
JACK - SERVICE INTPH, D8505	2	1	316AR (315AL), APU SHROUD	*
JACK - SERVICE INTPH, D8539	2	1	119AL, MAIN EQUIP CTR	*
JACK - SERVICE INTPH, D8541	2	1	113AL, WEATHER RADAR MOUNT	*
JACK - SERVICE INTPH, D8543	2	1	NOSE WHL GEAR, APU SHUTDOWN PNL, P40	*
JACK - SERVICE INTPH, D8547	2	1	821, FWD COMPT CARGO HDLG ACCESS PNL, P35	*
JACK - SERVICE INTPH, D8549	2	1	L WING FUELING PNL, P28	*
JACK - SERVICE INTPH, D8553	2	1	R W/W SERVICE PNL, P56	*
JACK - SERVICE INTPH, D8555	2	1	822, AFT COMPT CARGO HDLG ACCESS PNL, P39	*
PANEL - (FIM 31-31-00/101) FLIGHT RECORDER CONTROL, M33	2	1	FLT COMPT, P61, FT RCDR CONT PNL, M33	*
SWITCH - SERVICE INTPH, YDSS2	2	1		*
UNIT - (FIM 23-42-00/101) AUDIO ACCESSORY, M108	2	1		*

* SEE THE WDM EQUIPMENT LIST

Service Interphone System - Component Index
Figure 101





23-41-00

01

Page 101
Dec 22/06

D20776



Service Interphone System - Component Location
 Figure 102 (Sheet 1)


EFFECTIVITY	ALL
-------------	-----

23-41-00


BOEING

767

FAULT ISOLATION/MAINT MANUAL



FLIGHT COMPARTMENT




(A) FROM SHT 1

SERVICE INTERPHONE SWITCH, YDSS2

FLIGHT RECORDER CONTROL PANEL, M33 (REF)

(B)

JACK	LOCATION
D8503	JACKSCREW SERVICE
D8505	APU SHROUD
D8539	MAIN EQUIPMENT CENTER
D8541	WEATHER RADAR MOUNT
D8543	P40 CONTROL PANEL
D8547	FORWARD COMPARTMENT CARGO HANDLING ACCESS PANEL, P35
D8549	LEFT WING FUELING PANEL, P28
D8553	RIGHT WHEEL WELL SERVICE PANEL, P56
D8555	AFT COMPARTMENT CARGO HANDLING ACCESS PANEL, P39



SERVICE INTERPHONE JACK LOCATIONS

Service Interphone System - Component Location
Figure 102 (Sheet 2)

EFFECTIVITY

ALL














23-41-00

01

Page 103
Feb 10/94

 **BOEING**
767
FAULT ISOLATION/MAINT MANUAL

CABIN INTERPHONE SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
AMPLIFIER - (FIM 23-31-00/101) PASSENGER ADDRESS, M177				
CHIME - AFT L ATTENDANT, B148 	5	1	PASS. CABIN	23-42-04
CHIME - AFT R ATTENDANT, B147 	5	1	PASS. CABIN	23-42-04
CHIME - CREW REST AREA, B420 	5	1	PASS. CABIN, CREW REST AREA	*
CHIME - FWD C ATTENDANT, B139 	5	1	PASS. CABIN	23-42-04
CHIME - FWD L ATTENDANT, B144 	5	1	PASS. CABIN	23-42-04
CHIME - MID L ATTENDANT, B146 	5	1	PASS. CABIN	23-42-04
CHIME - MID R ATTENDANT, B145 	5	1	PASS. CABIN	23-42-04
CHIME - PURSER'S, B376 	5	1	PASS. CABIN, PURSER'S STATION	23-42-04
CIRCUIT BREAKER - INTERPHONE CABIN/SERVICE, C551	2	1	FLT COMPT, P11 11C23	*
HANDSET - ATTENDANT, B61	2	5	PASS. CABIN	*
HANDSET - CREW REST AREA, B61 	2	1	PASS. CABIN, CREW REST AREA	*
HANDSET - PILOTS', B61	2	1	FLT COMPT, P8	*
HANDSET - PURSER'S, B61	2	1	PASS. CABIN, PURSER'S STATION	*
LIGHT - ATTENDANT CALL	5		PASS. CABIN	*
MODULE - (FIM 31-51-00/101) BELL CHIME AURAL WARNING, M1000				
PANEL - (FIM 33-21-00/101) PURSER'S, P78				
PANEL - CREW REST CONTROL 	3,4	1	PASS. CABIN, CREW REST AREA	*
PANEL - PILOTS' CALL, M51	2	1	FLT COMPT, P5	23-42-02
RELAY - TIME DELAY, B418,B419 	3,4	2	PASS. CABIN, CREW REST AREA	*
SWITCH-LIGHT, CALL, B416,B417 	4	2	PASS. CABIN, CREW REST AREA, CREW REST CONTROL PANEL	*
UNIT - AUDIO ACCESSORY, M108	1	1	119AL, MAIN EQUIP CTR, E2-5	23-42-01

* SEE THE WDM EQUIPMENT LIST

-  SAS 150-999
-  SAS 050-149,162-999
-  FOR THE QUANTITY, LOCATION, AND EQUIPMENT NUMBERS, REFER TO THE WDM 23-42-11.


Cabin Interphone System - Component Index
Figure 101

EFFECTIVITY
ALL SAS AIRPLANES


23-42-00
CONFIG 1
Page 101
May 10/94

01

BOEING
 767
 FAULT ISOLATION/MAINT MANUAL



MAIN EQUIPMENT CENTER
 ACCESS PANEL, 119AL
 SEE (A)



MAIN EQUIPMENT CENTER
 (A)


Cabin Interphone System - Component Location
 Figure 102 (Sheet 1)

EFFECTIVITY
 ALL SAS AIRPLANES


23-42-00

CONFIG 1
 Page 102
 Aug 10/90

01




FLIGHT COMPARTMENT




HANDSET, B61
(EXAMPLE)

(C)



PILOTS' CALL PANEL, M51

(B) 1



PILOTS' CALL PANEL, M51

(B) 2

- 1 SAS 050-149,162-999
- 2 SAS 150-161

Cabin Interphone System - Component Location
Figure 102 (Sheet 2)

EFFECTIVITY
ALL SAS AIRPLANES

23-42-00

CONFIG 1

01


Page 103

Feb 10/91

BOEING

767

FAULT ISOLATION/MAINT MANUAL



Cabin Interphone System - Component Location
Figure 102 (Sheet 3)

EFFECTIVITY
ALL SAS AIRPLANES


23-42-00

CONFIG 1


Page 104

May 10/94

01



ATTENDANT'S CALL LIGHT
(EXAMPLE)



ELECTRONIC CHIME
(EXAMPLE)

(D) FROM SHT 3

Cabin Interphone System - Component Location
Figure 102 (Sheet 4)

EFFECTIVITY
ALL SAS AIRPLANES


23-42-00

CONFIG 1

Page 105


May 10/94

01



PURSER'S PANEL, P78 (REF)

(E) FROM SHT 3



CREW REST CONTROL PANEL 1

(F) FROM SHT 3

6 SAS 050-051,
150-155,
162-165

7 SAS 052-149,
156-161,
166-999

Cabin Interphone System - Component Location
Figure 102 (Sheet 5)

EFFECTIVITY
ALL SAS AIRPLANES


23-42-00

CONFIG 1
Page 106
May 10/94

01

CABIN CHIME AND CALL LIGHT/ATTENDANT CALL FROM PILOT OR ATTENDANT PROBLEM

PREREQUISITES:
 MAKE SURE THIS CIRCUIT BREAKER IS CLOSED:
 11C23
 MAKE SURE THE AIRPLANE IS IN THE CONFIGURATION THAT FOLLOWS:
 ELECTRICAL POWER IS ON (MM 24-22-00/201)



Cabin Chime and Call Light/Attendant Call from Pilot or Attendant Problem
Figure 103

EFFECTIVITY
ALL SAS AIRPLANES

23-42-00
 CONFIG 1
 Page 107
 May 10/94

01

BOEING
767
FAULT ISOLATION/MAINT MANUAL

CABIN INTERPHONE SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
AMPLIFIER - (FIM 23-31-00/101) PASSENGER ADDRESS, M177				
CHIME - AFT L ATTENDANT, B148	3	1	PASS. CABIN	23-42-04
CHIME - AFT R ATTENDANT, B147	3	1	PASS. CABIN	23-42-04
CHIME - FWD L ATTENDANT, B144	3	1	PASS. CABIN	23-42-04
CHIME - FWD R ATTENDANT, B139	3	1	PASS. CABIN	23-42-04
CHIME - MID L ATTENDANT, B146	3	1	PASS. CABIN	23-42-04
CHIME - MID R ATTENDANT, B145	3	1	PASS. CABIN	23-42-04
CIRCUIT BREAKER - INTERPHONE CABIN/SERVICE, C551	2	1	FLT COMPT, P11 11C23	*
HANDSET - ATTENDANT, B61	3	5	PASS. CABIN	*
HANDSET - PILOTS', B61	2	1	FLT COMPT, P8	*
LIGHT -ATTENDANT CALL	3	1	PASS. CABIN	*
MODULE - (FIM 31-51-00/101) BELL CHIME AURAL WARNING, M1000				
PANEL - PILOTS' CALL, M51	2	1	FLT COMPT, P5	23-42-02
UNIT - AUDIO ACCESSORY, M108	1	1	119AL, MAIN EQUIP CTR, E2-5	23-42-01

* SEE THE WDM EQUIPMENT LIST



1 FOR THE QUANTITY LOCATION, AND EQUIPMENT NUMBERS, REFER TO THE WDM 23-42-11.

Cabin Interphone System - Component Index
Figure 101

EFFECTIVITY
ALL MTH AIRPLANES

23-42-00
CONFIG 2
Page 101
May 10/94

01



MAIN EQUIPMENT CENTER
 (A)

Cabin Interphone System - Component Location
 Figure 102 (Sheet 1)

EFFECTIVITY
 ALL MTH AIRPLANES


23-42-00
 CONFIG 2
 Page 102
 May 10/94

01


BOEING

767

FAULT ISOLATION/MAINT MANUAL




FLIGHT COMPARTMENT



PILOTS' CALL PANEL, M51

(B)



HANDSET, B61 (EXAMPLE)

(C)

Cabin Interphone System - Component Location
Figure 102 (Sheet 2)

EFFECTIVITY
ALL MTH AIRPLANES

666187

01

23-42-00

CONFIG 2


Page 103

May 10/94


BOEING

767


FAULT ISOLATION/MAINT MANUAL



HANDSET AND CHIME LOCATIONS



ATTENDANT'S CALL LIGHT (EXAMPLE)



ELECTRONIC CHIME B139, B144-148

(D)

**Cabin Interphone System - Component Location
Figure 102 (Sheet 3)**

EFFECTIVITY
ALL MTH AIRPLANES

23-42-00

CONFIG 2

Page 104


May 10/94

01

666181

CABIN CHIME AND CALL LIGHT/ATTENDANT CALL FROM PILOT OR ATTENDANT PROBLEM

PREREQUISITES:
 MAKE SURE THIS CIRCUIT BREAKER IS CLOSED:
 11C23
 MAKE SURE THE AIRPLANE IS IN THE CONFIGURATION THAT FOLLOWS:
 ELECTRICAL POWER IS ON (MM 24-22-00/201)



Cabin Chime and Call Light/Attendant Call from Pilot or Attendant Problem
Figure 103

EFFECTIVITY
ALL MTH AIRPLANES

23-42-00
CONFIG 2
Page 105
May 10/94

01


BOEING
767
FAULT ISOLATION/MAINT MANUAL

GROUND CREW CALL SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
CARD - (FIM 21-58-00/101) EQUIP COOLING IND, M867				
CIRCUIT BREAKER - EQUIP COOL GND WARN, C711	--	1	FLT COMPT, P6 6D6	*
CIRCUIT BREAKER - GND CALL, C560	--	1	FLT COMPT, P11 11H32	*
DIODE - SUPPRESSOR, R252	--	1	119AL, MAIN EQUIP CTR, E2-5	*
HORN - GROUND CREW CALL, B60	--	1	714, NOSE WHEEL WELL	23-43-01
MODULE - (FIM 31-51-00/101) BELL CHIME AURAL WARNING, M1000				
PANEL - (FIM 23-42-00/101) PILOTS' CALL, M51				
PANEL - (FIM 26-15-00/101) APU SHUTDOWN (REMOTE CONTROL), P40				
SWITCH - FLT DECK CALL, S426	--	1	NOSE LANDING GEAR, APU SHUTDOWN PANEL, P40	*
SWITCH-LIGHT - GND CALL, YDCS10	--	1	FLT COMPT, P5, PILOTS' CALL PANEL, M51	*

* SEE THE WDM EQUIPMENT LIST

Ground Crew Call System - Component Index
Figure 101







23-43-00

01

Page 101
May 10/94

E19428



GND CALL SWITCH-LIGHT, YDCS10
(B)


Ground Crew Call System - Component Location
Figure 102

EFFECTIVITY	
	ALL

23-43-00

GROUND CREW CALL
HORN SOUNDS
CONTINUOUSLY

PREREQUISITES
 MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
 6D6,11H32,11P22
 MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:
 ELECTRICAL POWER IS ON (AMM 24-22-00/201)




Ground Crew Call Horn Sounds Continuously
Figure 103

EFFECTIVITY	ALL
-------------	-----

23-43-00

GROUND CREW CALL
HORN FAILS TO SOUND.
EQUIPMENT COOLING
FAILURE INDICATORS
ON.

PREREQUISITES
MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6D6,11H32,11P22
MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:
ELECTRICAL POWER IS ON (AMM 24-22-00/201)




Ground Crew Call Horn Fails to Sound. Equipment Cooling Failure Indicators On.
Figure 104

EFFECTIVITY	ALL
-------------	-----

23-43-00

GROUND CREW CALL
HORN FAILS TO SOUND.
IRS MODE SELECT
SWITCH (L,C, OR R)
ON. L AND R DC
POWER OFF.

PREREQUISITES
MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
6D6,11H32
MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:
ELECTRICAL POWER IS ON (MM 24-22-00/201)



Ground Crew Call Horn Fails to Sound. IRS Mode Select Switch (L,C, or R) On.
L and R DC Power Off.

Figure 105

EFFECTIVITY	ALL
-------------	-----

23-43-00

 **BOEING**
767
FAULT ISOLATION/MAINT MANUAL

FLIGHT INTERPHONE SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
AMPLIFIER - (REF 23-31-00, FIG. 101) PASSENGER ADDRESS, M177				
CIRCUIT BREAKER - INTERPHONE - DUAL PWR CAPT/OBS FLT AMPL, C644,C645	1	2	FLT COMPT, P11 11C25,11G29	*
INTERPHONE - DUAL PWR F/O, C646,C647		2	11C26,11G30	*
DIODE - R58,R59,R60,R61	1	4	FLT COMPT, BEHIND P11	*
DIODE - ISOLATION, R472,R473,R474 1		3	MAIN EQUIP CENTER, E2-5	*
INTERROGATOR - (REF 34-55-00, FIG. 101) LEFT DME, M123 RIGHT DME, M124				
JACK - CAPT HAND MIC, D861	1	1	FLT COMPT, P13	*
JACK - F/O HAND MIC, D863	1	1	FLT COMPT, P14	*
JACK - FLT INTPH, D8545	2	1	APU GROUND CONT PNL, P40	*
MIC - CAPT OXY MASK, M933	1	1	FLT COMPT	*
MIC - F/O OXY MASK, M934	1	1	FLT COMPT	*
MIC - F/OBS OXY MASK, M936	1	1	FLT COMPT	*
PANEL - (REF 34-51-00, FIG. 101) LEFT VOR CONT, M91 RIGHT VOR CONT, M92				
PANEL - CAPT AUDIO SELECTOR, M70	1	1	FLT COMPT, P8	23-51-01
PANEL - CAPT JACK, M889	1	1	FLT COMPT, P15	*
PANEL - F/O AUDIO SELECTOR, M71	1	1	FLT COMPT, P8	23-51-01
PANEL - F/O JACK, M890	1	1	FLT COMPT, P16	*
PANEL - F/OBS AUDIO SELECTOR, M98	1	1	FLT COMPT, P61	23-51-01
PANEL - F/OBS JACK, M133	1	1	FLT COMPT, P61	*
PANEL - SEC/OBS JACK, M892	1	1	FLT COMPT, P63	*
RECEIVER - (REF 34-31-00, FIG. 101) CENTER ILS, M157 LEFT ILS, M156 RIGHT ILS, M158				
RECEIVER - (REF 34-51-00, FIG. 101) LEFT VOR/MKR, M186 RIGHT VOR/MKR, M187				
RECEIVER - (REF 34-57-00, FIG. 101) LEFT ADF, M215 RIGHT ADF, M216				
RECORDER - (REF 23-71-00, FIG. 101) VOICE, M201				
SPEAKER - CAPT COCKPIT, B1	1	1	FLT COMPT	23-51-02
SPEAKER - F/O COCKPIT, B2	1	1	FLT COMPT	23-51-02

* SEE THE WDM EQUIPMENT LIST

1 SAS 150-152 WITH SB 23-32, SAS 050-149,153-999 AND ALL MTH AIRPLANES.

Flight Interphone System - Component Index
Figure 101 (Sheet 1)

EFFECTIVITY

ALL


23-51-00


BOEING
 767
 FAULT ISOLATION/MAINT MANUAL

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
STOWAGE - CAPT OXY MASK, M933	1	1	FLT COMPT	*
STOWAGE - F/O OXY MASK, M934	1	1	FLT COMPT	*
STOWAGE - F/OBS OXY MASK, M936	1	1	FLT COMPT	*
SUPPRESSOR BLOCK - PTT, R538-R542	1	5	119AL, MAIN EQUIP CTR, E2-5	*
SWITCH - CAPT PTT INTPH, S549	1	1	FLT COMPT, CAPT CONT WHEEL	23-51-03
SWITCH - CAPT R/T PTT, S550	1	1	FLT COMPT, CAPT CONT WHEEL	23-51-03
SWITCH - F/O PTT INTPH, S551	1	1	FLT COMPT, F/O CONT WHEEL	23-51-03
SWITCH - F/O R/T PTT, S552	1	1	FLT COMPT, F/O CONT WHEEL	23-51-03
UNIT - (REF 23-42-00, FIG. 101) AUDIO ACCESSORY, M108				
XCVER - (REF 23-11-00, FIG. 101) LEFT HF COMM, M152				
RIGHT HF COMM, M153				
XCVER - (REF 23-12-00, FIG. 101) CENTER VHF COMM, M190				
LEFT VHF COMM, M188				
RIGHT VHF COMM, M189				

* SEE THE WDM EQUIPMENT LIST

Flight Interphone System - Component Index
 Figure 101 (Sheet 2)





23-51-00

BOEING

767

FAULT ISOLATION/MAINT MANUAL



- 1 ALL SAS 767-300 AIRPLANES
- 2 ALL MTH AIRPLANES
- 3 ALL SAS 767-200 AIRPLANES

Flight Interphone System - Component Location
Figure 102 (Sheet 1)


EFFECTIVITY	
ALL	

23-51-00

BOEING


767

FAULT ISOLATION/MAINT MANUAL




CAPTAIN, FIRST OFFICER OR FIRST OBSERVER
AUDIO SELECTOR PANEL, M70, M71, OR M98

(B) FROM SHT 1




CAPTAIN **1**, FIRST OFFICER **1**, OR
FIRST OBSERVER **3** JACK PANEL
M889 **1**, M890 **1**, OR M133 **3**

(C) FROM SHT 1




FIRST OBSERVER JACK PANEL, M133

(D) **1** FROM SHT 1




SECOND OBSERVER JACK PANEL, M892

(E) FROM SHT 1




NOSE LANDING GEAR



CAPTAIN, FIRST OFFICER OR
FIRST OBSERVER JACK PANEL
M889, M890, M133

(F) FROM SHT 1
2

FLIGHT INTERPHONE JACK, D8545



APU SHUTDOWN PANEL, P40

(G)

- 1** ALL SAS 767-300 AIRPLANES
- 2** ALL MTH AIRPLANES
- 3** ALL SAS 767-200 AIRPLANES

Flight Interphone System - Component Location
Figure 102 (Sheet 2)

EFFECTIVITY

ALL

23-51-00

BOEING
767
FAULT ISOLATION/MAINT MANUAL

STATIC DISCHARGERS

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
BASE - ALUMINUM STATIC DISCHARGER, TRAILING EDGE TYPE	3	6	HORIZ STABILIZER OUTBOARD TRAILING EDGES	23-61-01
	3	2	HORIZ STABILIZER TIPS	23-61-01
	2	4	OUTBOARD AILERONS	23-61-01
	3	3	RUDDER	23-61-01
	2	2	WINGTIPS	23-61-01
BASE - STATIC DISCHARGER, TIP TYPE	3	4	HORIZ STABILIZER TIPS	23-61-01
	3	2	VERTICAL STABILIZER TIP	23-61-01
	2	4	WINGTIPS	23-61-01
BASE - TITANIUM STATIC DISCHARGER, TRAILING EDGE TYPE	2	8	OUTBOARD AILERONS	23-61-01
	3	2	OUTBOARD ELEVATORS	23-61-01
	3	2	RUDDER	23-61-01
DISCHARGER - TIP TYPE STATIC	3	4	HORIZ STABILIZER TIPS	23-61-01
	3	2	VERTICAL STABILIZER TIP	23-61-01
	2	4	WINGTIPS	23-61-01
DISCHARGER - TRAILING EDGE TYPE STATIC	3	6	HORIZ STABILIZER OUTBOARD TRAILING EDGES	23-61-01
	3	2	HORIZ STABILIZER TIPS	23-61-01
	2	12	OUTBOARD AILERONS	23-61-01
	3	2	OUTBOARD ELEVATORS	23-61-01
	3	5	RUDDER	23-61-01
	2	2	WINGTIPS	23-61-01
	3	6	HORIZ STABILIZER OUTBOARD TRAILING EDGES	23-61-01
	3	1	RUDDER	23-61-01
	3	2	OUTBOARD ELEVATORS	23-61-01
	3	2	RUDDER	23-61-01
MOUNTING PLATE - ALUMINUM STATIC DISCHARGER BASE	3	6	HORIZ STABILIZER OUTBOARD TRAILING EDGES	23-61-01
	3	1	RUDDER	23-61-01
MOUNTING PLATE - TITANIUM STATIC DISCHARGER BASE	3	2	OUTBOARD ELEVATORS	23-61-01
	3	2	RUDDER	23-61-01
	2	8	OUTBOARD AILERONS	23-61-01

Static Dischargers - Component Index
Figure 101

EFFECTIVITY


ALL

23-61-00

01

Page 101
Apr 22/01

111547




Static Dischargers - Component Location
Figure 102 (Sheet 1)

EFFECTIVITY	ALL
-------------	-----

23-61-00

111733




WING TIP AND AILERON STATIC DISCHARGERS (EXAMPLE)

(A)

Static Dischargers - Component Location (Detail from Sht 1)
Figure 102 (Sheet 2)


EFFECTIVITY	ALL
-------------	-----

23-61-00



HORIZONTAL STABILIZER AND ELEVATOR STATIC DISCHARGERS (EXAMPLE)

(B)




VERTICAL FIN TIP AND RUDDER STATIC DISCHARGERS

(C)

Static Dischargers - Component Location (Details from Sht 1)
Figure 102 (Sheet 3)


EFFECTIVITY	ALL
-------------	-----

23-61-00




TIP TYPE STATIC DISCHARGER

(D)



TIP TYPE STATIC DISCHARGER BASE
(ALUMINUM - FLAT OR CURVED SURFACE)


(E)




TRAILING EDGE TYPE STATIC DISCHARGER

(F)

Static Dischargers - Component Location (Details from Sht 2 and 3)
Figure 102 (Sheet 4)




23-61-00




**TRAILING EDGE TYPE STATIC
 DISCHARGER BASE
 (ALUMINUM)**

G




**TRAILING EDGE TYPE STATIC
 DISCHARGER BASE
 (TITANIUM)**


H



I



J



K

**STATIC DISCHARGER BASE MOUNTING PLATE
 (ALUMINUM OR TITANIUM)**

**Static Discharger - Component Location (Details from Sht 2, 3 and 4)
 Figure 102 (Sheet 5)**

EFFECTIVITY	ALL
-------------	-----

23-61-00

01

Page 106
Aug 22/99


BOEING
767
FAULT ISOLATION/MAINT MANUAL

VOICE RECORDER SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
BEACON - UNDERWATER LOCATOR	--	1	AFT PASSENGER CABIN CEILING, E7	23-71-03
CIRCUIT BREAKER	--	1	FLT COMPT, P11	*
VOICE RECORDER, C532	--	1	11H34	*
PANEL - (FIM 23-51-00/101)				
CAPT AUDIO SELECTOR, M70				
F/O AUDIO SELECTOR, M71				
1ST OBS AUDIO SELECTOR, M98				
PANEL - VOICE RECORDER CONTROL, M50	--	1	FLT COMPT, P5	23-71-02
RECORDER - VOICE, M201	--	1	AFT PASSENGER CABIN CEILING, E7	23-71-01
RELAY - (FIM 31-01-36/101)				
SYS NO. 1 AIR/GROUND, K178				
PARK BRAKE CLOSE SENSE, K419				

* SEE THE WDM EQUIPMENT LIST

Voice Recorder System - Component Index
Figure 101



23-71-00

03

Page 101
Feb 10/88


293551

BOEING


767

FAULT ISOLATION/MAINT MANUAL


VOICE RECORDER
CONTROL PANEL, M50
SEE (A)



AFT GALLEY
COMPLEX




E7 RACK
(ABOVE GALLEY)
SEE (B)




VOICE RECORDER CONTROL PANEL, M50

(A)



(B)



VOICE RECORDER, M201

(C)

Component Location
Figure 102

EFFECTIVITY

ALL

23-71-00

10

Page 102
Nov 10/88


587012

**VOICE RECORDER
BITE PROCEDURE**

PREREQUISITES

MAKE SURE THIS CIRCUIT BREAKER IS CLOSED:
11H34

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:
ELECTRICAL POWER IS ON (AMM 24-22-00/201)



Voice Recorder BITE Procedure
Figure 103

EFFECTIVITY

ALL

23-71-00


**VOICE RECORDER
SYSTEM FAULT
ISOLATION**

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE:
 FLIGHT INTERPHONE SYSTEM (AMM 23-51-00/501)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:
 6F4, 11C25, 11C26, 11G29, 11G30, 11H34, 11U15


MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:
 ELECTRICAL POWER IS ON (AMM 24-22-00/201)



Voice Recorder System Fault Isolation
Figure 104 (Sheet 1)

EFFECTIVITY	ALL
-------------	-----


23-71-00



Voice Recorder System Fault Isolation
Figure 104 (Sheet 2)

EFFECTIVITY
 AIRPLANES WITH TAPE BASED
 LORAL/FAIRCHILD VOICE RECORDER

23-71-00




Voice Recorder System Fault Isolation
Figure 104 (Sheet 3)

EFFECTIVITY

ALL

23-71-00



Voice Recorder System Fault Isolation
Figure 104 (Sheet 4)

EFFECTIVITY
 AIRPLANES WITH TAPE BASED
 LORAL/FAIRCHILD VOICE RECORDER

23-71-00