/ PW4000 SERIES **ENGINES**

Scandinavian Airlines System

PAGE	DATE	CODE	PAGE	DATE	CODE	PAGE	DATE	CODE
	_		73-21-00		CONT.	73-21-00		CONT.
CHAPTER 7	3 TAB		116	APR 22/99	NO1	174	APR 22/99	N07
ENGTHE FI	IEL AND CONTRO		117	AUG 22/99	NO1	175	APR 22/99	N07
1	EL AND CONTRO)L	118 119	APR 22/99 APR 22/99	NO1 NO1	176 177	AUG 22/99 APR 22/99	N06 N08
(PW4000)			120	APR 22/99	NO1	178	APR 22/99	NO7
EFFECTIVE	PAGES		121	AUG 22/99	NO1	179	AUG 22/99	NO3
	PAGE OF LIST	FOR	122	AUG 22/07	NO1	180	DEC 22/04	N06
NUMBER OF			123	APR 22/99	NO1	180A	AUG 22/99	NO2
İ			124	APR 22/99	NO1	180B	AUG 22/99	NO4
I			125	AUG 22/99	N03	180c	APR 22/99	N05
73-CONTEN			126	APR 22/99	NO3	180D	AUG 22/99	NO4
1	AUG 22/99	NSAS	127	AUG 22/99	NO1	180E	APR 22/99	N06
2 7	DEC 22/99 DEC 22/99	NSAS NSAS	128 129	APR 22/99 APR 22/99	NO1 NO1	180F 180G	AUG 22/99 APR 22/99	NO3 NO3
3 4	BLANK	NOAO	130	AUG 22/99	NO3	180H	AUG 22/99	NO3
1 7	DEANK		131	APR 22/99	NO1	1801	APR 22/99	NO4
73-FAULT	CODE INDEX		132	AUG 22/99	NO1	180J	BLANK	
1	MAY 10/96	N02	133	AUG 22/07	NO1	1		
2	MAY 10/96	N02	134	AUG 22/99	NO1	73-31-00		
3	AUG 22/04	N09	135	APR 22/99	NO1	101	FEB 10/95	NO1
4	AUG 22/04	N06	136	APR 22/99	NO1	102	FEB 10/95	NO1
5	DEC 22/00	NO1	137	DEC 22/04 AUG 22/99	NO1	77 77 00		
6 7	DEC 22/00 DEC 22/00	NO1 NO1	138 139	APR 22/99	N06 N08	73–33–00 101	FEB 10/95	NO1
8	APR 22/99	NO1	140	APR 22/99	NO5	101	FEB 10/95	NO1
9	MAY 10/96	NO1	141	APR 22/99	N06	103	AUG 22/00	NO1
10	MAY 10/96	NO1	142	APR 22/99	N06	104	AUG 22/00	NO1
11	APR 22/99	NO5	143	APR 22/99	N08	105	MAY 10/95	NO1
12	DEC 22/00	NO4	144	APR 22/99	N05	106	MAY 10/95	NO1
13	DEC 22/00	N05	145	APR 22/09	NO5			
14	APR 22/04	NO1	146	APR 22/99	NO5	73-34-00	FFD 40/0F	NO4
15 16	DEC 22/00 APR 22/99	NO1 NO4	147 148	APR 22/99 APR 22/99	N07 N07	101 102	FEB 10/95 FEB 10/95	NO1 NO1
10	AFR 22/77	NO4	149	APR 22/99	NO8	103	APR 22/99	NO1
73-11-00			150	APR 22/99	N07	104	BLANK	1101
101	FEB 10/97	NO1	151	APR 22/99	N07			
102	AUG 10/91	NO1	152	APR 22/99	N07	İ		
103	AUG 10/91	NO1	153	APR 22/99	N07	I		
104	APR 22/99	NO1	154	APR 22/99	N07	I		
105	AUG 22/99	NO1	155	AUG 22/99	NO5	1		
106	AUG 22/99	N02	156 157	APR 22/99 APR 22/99	N05 N07	ł		
73-21-00			158	APR 22/99	NO5	ł		
101	FEB 10/97	NO1	159	APR 22/99	N08	1		
102	AUG 10/91	NO1	160	APR 22/99	N06	1		
103	APR 10/98	NO1	161	APR 22/99	N06	I		
104	AUG 10/91	NO1	162	APR 22/09	NO5	I		
105	AUG 10/91	NO1	163	APR 22/99	NO5	1		
106 107	AUG 10/91 AUG 10/91	NO1	164 165	APR 22/99 APR 22/99	N06 N06	1		
107	AUG 10/91 AUG 22/99	NO1 NO1	166	APR 22/99 APR 22/99	NU6 NO5	1		
109	APR 22/99	NO1	167	APR 22/99	NO5	1		
110	AUG 22/99	NO1	168	APR 22/99	NO7	1		
111	APR 22/99	NO1	169	APR 22/99	N07	I		
112	APR 22/99	NO1	170	APR 22/99	N06	I		
113	AUG 22/99	NO1	171	APR 22/99	N06	I		
114	APR 22/99	NO1	172	AUG 22/99	N06	1		
115	AUG 22/99	NO1	173	APR 22/99	N07	L		

R = REVISED, A = ADDED OR D = DELETED F = FOLDOUT PAGE 33 AUG 22/09 D633T633

CHAPTER 73 **EFFECTIVE PAGES** PAGE LAST PAGE

CHAPTER 73 - ENGINE FUEL AND CONTROL

TABLE OF CONTENTS

Chapter Section

<u>Subject</u> <u>Subject</u> <u>Page</u> <u>Effectivity</u>

FAULT ISOLATION 73-FAULT 1 ALL

CODE INDEX

ENGINE FUEL AND CONTROL 73-00-00

DISTRIBUTION 73-10-00

ENGINE FUEL AND CONTROL 73-11-00

Component Location 101 ALL

Component Index
Component Location

Fault Isolation

High Fuel Flow, Other Engine 105

Parameters Normal (Fig. 104)

No Engine Lightoff (No Fuel 104

Flow) (Fig. 103)

73-CONTENTS

NSAS

Page 1 Aug 22/99

CHAPTER 73 - ENGINE FUEL AND CONTROL

TABLE OF CONTENTS

Chapter Section Subject Subject <u>Page</u> **Effectivity** CONTROLLING 73-20-00 FUEL CONTROL SYSTEM 73-21-00 Component Location 101 ALL Component Index Component Location Fault Isolation Engine did not reach Target 115 EPR (Engine parameters not Normal for EPR Obtained) (Fig. 104B) Engine did not reach Target 113 EPR (Engine Parameters Normal for EPR Obtained) (Fig. 104A) Engine did not reach Target 117 EPR (No engine parameters available) (Fig. 104C) Engine Auto Acceleration (Fig. 108 103) Engine Auto Decel (Fig. 104) 110 Engine Flameout (Fuel Flow is 180H OK) (Fig. 119) Engine Flameout (No or Low 121 Fuel Flow) (Fig. 105) Engine Flameout (Reason for 132 Unsuccessful Restart Unknown) (Fig. 109) Engine Power Fluctuates (Fig. 179 114) EICAS Message IDLE DISAGREE or 138 L (R) ENG LOW IDLE is Shown (Fig. 111) EICAS Message IDLE DISAGREE or 155 L (R) ENG LOW IDLE is Shown (Fig. 111A) EICAS Message L (R) ENG EEC C1 180A Displayed (Fig. 115) EICAS Message L (R) ENG EEC C2 180B Displayed (Fig. 116) EICAS Msg L (R) ENG CONTROL 172 Displayed (Fig. 112) 176 EICAS Msq L (R) ENG EEC MODE

73-CONTENTS

NSAS Page 2 Dec 22/99

Displayed (Fig. 113)

CHAPTER 73 - ENGINE FUEL AND CONTROL

TABLE OF CONTENTS

<u>Subject</u>	Chapter Section <u>Subject</u>	<u>Page</u>	<u>Effectivity</u>
Hung Start or Slow Acceleration to Idle (Fig.		134	
110) Idle RPM is too High or too Low (Engine Related) (Fig. 117)		180c	
No Engine Lightoff (Fuel Flow is Low) (Fig. 118)		180F	
No Engine Lightoff With Ignition Selector in Single or Both (Fuel Flow was Available) (Fig. 106)		123	
No Engine Response to Thrust Lever Movement, Engine Parameters Normal (Fig. 108)		127	
Slow Engine Response to Thrust Lever Movement, Engine Parameters Normal (Fig. 108A)		130	
Thrust Levers Misaligned (Fig. 107)		124	
INDICATING FUEL FLOW INDICATING SYSTEM Component Location Component Index	73–30–00 73–31–00	101	ALL
Component Location FUEL PRESSURE INDICATING SYSTEM Component Location Component Index Component Location	73–33–00	101	ALL
Fault Isolation Engine fuel Pump Interstage Pressure Indication Problems (Fig. 103)		105	
FUEL FILTER BYPASS WARNING SYSTEM Component Location Component Index Component Location Fault Isolation	73–34–00	101	ALL
EICAS Msg L (R) ENG FUEL FILT Shown (Fig. 103)		103	

73-CONTENTS

NSAS

Page 3 Dec 22/99

//	///////////////////////////////////////	//
/	PW4000 SERIES	/
/	ENGINES	/
11	///////////////////////////////////////	//

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
73 03 XA	 A (01=L, 02=R) electronic engine control problem was enountered by the flight crew which is not covered in the fault code diagrams (Ref Chapter 71 fault code diagram for flight crew actions). SSM 73-00-00 thru SSM 73-21-08
73 03 XB	 A (01=L, 02=R) eng idle rpm low/high problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref Chapter 71 fault code diagrams for flight crew actions). SSM 73-21-02, SSM 73-21-04
73 03 XC	 A (01=L, 02=R) eng flameout problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref Chapter 71 fault code diagrams for flight crew actions). SSM 73-00-00 thru SSM 73-21-08
73 03 XD	 A (01=L, 02=R) eng power fluctuates problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref Chapter 71 fault code diagram for flight crew actions). SSM 73-00-00 thru SSM 73-21-08
73 03 XE	 A (01=L, 02=R) takeoff thrust low problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref Chapter 71 fault code diagrams for flight crew actions). SSM 73-00-00 thru SSM 73-21-08
73 03 XF	 A (01=L, 02=R) eng thrust loss (auto decel) problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref Chapter 71 fault code diagram for flight crew actions). SSM 73-00-00 thru SSM 73-21-08
73 03 XG	 A (01=L, 02=R) eng high fuel flow problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref Chapter 71 fault code diagram for flight crew actions). SSM 73-00-00

EFFECTIVITY-

73-FAULT CODE INDEX

///	///////////////////////////////////////	//
/	PW4000 SERIES	/
/	ENGINES	/
11	///////////////////////////////////////	//

FAULT 1. LOG BOOK REPORT CODE 2. FAULT ISOLATION REFERENCE 1. A (01=L, 02=R) eng fuel indication problem was encountered by 73 03 XH -the flight crew which is not covered in the fault code diagrams (Ref Chapter 71 fault code diagrams for flight crew action). 2. SSM 73-31-01 73 O3 XI --1. A (01=L, 02=R) starting problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref Chapter 71 fault code diagrams for flight crew action). 2. SSM 73-00-00, SSM 74-31-01 and SSM 80-11-01 73 03 XJ --1. A (01=L, 02=R) eng no light/wet start problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref Chapter 71 fault code diagram for flight crew actions). 2. SSM 73-00-00 thru SSM 73-21-08 73 03 XK --1. A (O1=L, O2=R) eng slow accel to idle problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref Chapter 71 fault code diagrams for flight crew actions). 2. SSM 73-00-00 thru SSM 73-21-08 73 03 XL --1. A (01=L, 02=R) eng hung start problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref Chapter 71 fault code diagrams for flight crew actions). 2. SSM 73-00-00 thru SSM 73-21-08 73 O3 XM --1. A (01=L, 02=R) eng auto accel problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref Chapter 71 fault code diagrams for flight crew actions). 2. SSM 73-00-00 thru SSM 73-21-08 73 03 XN --1. A (01=L, 02=R) eng response to thrust lever movement problem was encountered by the flight crew which is not covered in the fault code diagrams (Ref Chapter 71 fault code diagram for flight crew action).

EFFECTIVITY-

73-FAULT CODE INDEX

2. SSM 73-00-00 thru SSM 73-21-08

ENGINES

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
73 03 01 00	Not Used
73 03 02 00	 EICAS msg IDLE DISAGREE displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 111, Block 1 or FIM 73-21-00/101, Fig. 111A, Block 1
73 03 03 00	 EICAS msg L ENG CONTROL displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 112, Block 1
73 03 04 00	 EICAS msg L ENG EEC C1 displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 115, Block 1
73 03 05 00	 EICAS msg L ENG EEC C2 displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 116, Block 1
73 03 06 00	73 03 06 00 thru 73 03 07 00 Not Used
73 03 08 00	 EICAS msg L ENG EEC MODE displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 113, Block 1
73 03 09 00	 EICAS msg L ENG FUEL FILT displayed (Ref Chapter 31 for fault code diagram). FIM 73-34-00/101, Fig. 103, Block 1
73 03 10 00	Not Used
73 03 11 00	 EICAS msg L ENG LOW IDLE displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 111, Block 1 or FIM 73-21-00/101, Fig. 111A, Block 1
73 03 12 00	Not Used

EFFECTIVITY-

73-FAULT CODE INDEX

ALL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
73 03 13 00	 EICAS msg R ENG CONTROL displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 112, Block 1
73 03 14 00	 EICAS msg R ENG EEC C1 displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 115, Block 1
73 03 15 00	 EICAS msg R ENG EEC C2 displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 116, Block 1
73 03 16 00	73 03 16 00 thru 73 03 17 00 Not Used
73 03 18 00	 EICAS msg R ENG EEC MODE displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 113, Block 1
73 03 19 00	 EICAS msg R ENG FUEL FILT displayed (Ref Chapter 31 for fault code diagram). FIM 73-34-00/101, Fig. 103, Block 1
73 03 20 00	Not Used
73 03 21 00	 EICAS msg R ENG LOW IDLE displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 111, Block 1 or FIM 73-21-00/101, Fig. 111A, Block 1
73 03 22 00	Not Used
73 03 23	 EICAS msg (01=L, 02=R) ENG EEC MODE displayed (Ref Chapter 71 for fault code diagrams). FIM 73-21-00/101, Fig. 113, Block 1
73 03 24	 EICAS msg (01=L, 02=R) ENG CONTROL displayed (Ref Chapter 71 for fault code diagrams). FIM 73-21-00/101, Fig. 112, Block 1
73 03 25	 Eng thrust levers misaligned in NORM mode. Thrust levers split knobs apart. (01=L, 02=R) thrust lever lags. alignment was norm in ALTN mode. Eng parameters were norm (Ref Chapter 71 Fault Code Diagram). FIM 73-21-00/101, Fig. 107, Block 1

EFFECTIVITY-

73-FAULT CODE INDEX

ALL

//	///////////////////////////////////////	//
/	PW4000 SERIES	/
/	ENGINES	/
11	///////////////////////////////////////	//

	FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
73	03 26	 Eng thrust levers misaligned in ALTN mode. Thrust levers split knobs apart. (01=L, 02=R) thrust lever lags. Eng parameters were norm (Ref Chapter 71 Fault Code Diagram). FIM 73-21-00/101, Fig. 107, Block 1
73	03 27	 Eng thrust levers misaligned in NORM mode. Thrust levers split knobs apart. (01=L, 02=R) thrust lever lags. Alignment was not checked in ALTN mode. Eng parameters were norm (Ref Chapter 71 Fault Code Diagram). FIM 73-21-00/101, Fig. 107, Block 1
73	03 28	 (01=L, 02=R) eng min idle rpm low%N2 (Ref Chapter 71 for fault code diagrams). Do the PIMU BITE procedure (71-PIMU MESSAGE INDEX). Look for the PIMU messages that follow:
		EEC CH-A/B N2 CROSS-CK FAIL (353-15) EEC CH-A/B N1 CROSS-CK FAIL (353-14) EEC CH-A/B N1 RANGE FAIL (352-14) EEC CH-A/B N2 RANGE FAIL (352-15) EEC CH-A/B P-SENSR DISAGREE (350-20) EEC A/B-CHAN FAIL (350-14) EEC CH-A/B UNIT FAIL (350-15)
		Refer to PIMU Table 101 for corrective action for any of the above PIMU messages shown.
		If none of the PIMU messages are shown, refer to FIM 73-21-00/101, Fig. 117, Block 1
73	03 29	 (01=L, 02=R) eng min idle rpm high%N2 (Ref Chapter 71 for fault code diagrams). Do the PIMU BITE procedure (71-PIMU MESSAGE INDEX). Look for the PIMU messages that follow:
		EEC CH-A/B FMU T/M W/A FAIL EEC CH-A/B FMU TR-CK FAIL EEC CH-A/B FMU FD-BK FAIL
		Refer to PIMU Table 101 for corrective action for any of the above PIMU messages shown.

EFFECTIVITY-

73-FAULT CODE INDEX

ALL

N01

If none of the above PIMU messages are shown, refer to FIM 73-21-00/101, Fig. 117, Block 1

///	///////////////////////////////////////	//
/	PW4000 SERIES	/
/	ENGINES	/
///	///////////////////////////////////////	//

FAULT CODE

- 1. LOG BOOK REPORT
- 2. FAULT ISOLATION REFERENCE

73 03 30 --

- 1. (O1=L, O2=R) eng appr idle rpm high _____%N2 (Ref Chapter 71 for fault code diagrams).
- 2. Do the PIMU BITE procedure (71-PIMU MESSAGE INDEX). Look for the PIMU messages that follow:

EEC CH-A/B FMU T/M W/A FAIL

EEC CH-A/B FMU TR-CK FAIL

EEC CH-A/B FMU FD-BK FAIL

Refer to PIMU Table 101 for corrective action for any of the above PIMU messages shown.

If none of the above PIMU messages are shown, refer to FIM 73-21-00/101, Fig. 117, Block 1

73 03 31 --

- 1. (O1=L, O2=R) eng appr idle rpm low _____%N2 with ldg flaps selected (Ref Chapter 71 for fault code diagrams).
- 2. Do the PIMU BITE procedure (71-PIMU MESSAGE INDEX). Look for the PIMU messages that follow:

EEC CH-A/B XTRN DIS DISAGREE (350-23)

EEC CH-A/B N1 CROSS-CK FAIL (353-14)

EEC CH-A/B N2 CROSS-CK FAIL (353-15)

EEC CH-A/B P-SENSR DISAGREE (350-20)

EEC CH-A/B N2 RANGE FAIL (352-15)

EEC A/B-CHAN FAIL (350-14)

EEC CH-A/B UNIT FAIL (350-15)

Refer to PIMU Table 101 for corrective action for any of the above PIMU messages shown.

If none of the above PIMU messages are shown, refer to FIM 73-21-00/101, Fig. 117, Block 1

EFFECTIVITY-

73-FAULT CODE INDEX

ALL

N01 Page 6 Dec 22/00

///	///////////////////////////////////////	///
/	PW4000 SERIES	/
/	ENGINES	/
11	///////////////////////////////////////	///

			LOG BOOK REPORT FAULT ISOLATION REFERENCE
73	03 32		(O1=L, O2=R) eng appr idle rpm low%N2 with eng anti-ice on (Ref Chapter 71 for fault code diagrams). Do the PIMU BITE procedure (71-PIMU MESSAGE INDEX). Look for the PIMU messages that follow:
			EEC CH-A/B XTRN DIS DISAGREE (350-23) EEC CH-A/B N1 CROSS-CK FAIL (353-14) EEC CH-A/B N2 CROSS-CK FAIL (353-15) EEC CH-A/B P-SENSR DISAGREE (350-20) EEC CH-A/B N2 RANGE FAIL (352-15) EEC A/B-CHAN FAIL (350-14) EEC CH-A/B UNIT FAIL (350-15)
			Refer to PIMU Table 101 for corrective action for any of the above PIMU messages shown.
			If none of the PIMU messages are shown, refer to FIM 73-21-00/101, Fig. 117, Block 1
73	03 33		(01=L, 02=R) eng appr idle rpm low%N2, with ldg flap selected and eng anti-ice on (Ref Chapter 71 for fault code diagrams). Do the PIMU BITE procedure (71-PIMU MESSAGE INDEX). Look for the PIMU messages that follow:
			EEC CH-A/B XTRN DIS DISAGREE (350-23) EEC CH-A/B N1 CROSS-CK FAIL (353-14) EEC CH-A/B N2 CROSS-CK FAIL (353-15) EEC CH-A/B P-SENSR DISAGREE (350-20) EEC CH-A/B N2 RANGE FAIL (352-15) EEC A/B-CHAN FAIL (350-14) EEC CH-A/B UNIT FAIL (350-15)
			Refer to PIMU Table 101 for corrective action for any of the above PIMU messages shown.
			If none of the PIMU messages are shown, refer to FIM 73-21-00/101, Fig. 110 , Block 1
73	03 34	1.	(O1=L, O2=R) eng flameout, operated norm after restart (Ref

EFFECTIVITY-

73-FAULT CODE INDEX

ALL

NO1

Page 7 Dec 22/00

Chapter 71 for fault code diagrams). 2. FIM 73-21-00/101, Fig. 119, Block 1

//	///////////////////////////////////////	/
/	PW4000 SERIES	/
/	ENGINES	/
//	///////////////////////////////////////	/

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
73 03 35	 (01=L, 02=R) eng flameout. Restart was not successful due to zero F/F (Ref Chapter 71 for fault code diagrams). FIM 73-21-00/101, Fig. 105, Block 1
73 03 36	 (01=L, 02=R) eng flameout. Restart was not successful due to low F/F (Ref Chapter 71 for fault code diagrams). FIM 73-21-00/101, Fig. 105, Block 3
73 03 37	 (01=L, 02=R) eng flameout. Restarting not (attempted, successful). (Note reason for no restart) (Ref Chapter 71 for fault code diagrams). FIM 73-21-00/101, Fig. 109, Block 1 and FIM 73-21-00/101, Fig. 119, Block 1
73 03 38	 (01=L, 02=R) eng power fluctuates at a constant thrust setting (Ref Chapter 71 fault code diagrams). FIM 73-21-00/101, Fig. 114, Block 1
73 03 39	 (01=L, 02=R) eng did not reach target EPR. Eng parameters were normal for EPR obtained (Ref Chapter 71 for fault code diagrams). FIM 73-21-00/101, Fig. 104A, Block 1
73 03 40	 (01=L, 02=R) eng Auto Decel. Eng parameter norm for thrust obtained (Ref Chapter 71 for fault code diagrams). 73-21-00/101, Fig. 104, Block 1
73 03 41	 (01=L, 02=R) eng high fuel flow. Other eng parameters norm. Fuel qty decrease confirms high fuel flow (Ref Chapter 71 for fault code diagrams). FIM 73-11-00/101, Fig. 104, Block 1
73 03 42	 (01=L, 02=R) eng high fuel flow. Other parameters norm. Fue qty decrease does not confirm high fuel flow (Ref Chapter 71 fault code diagrams). Replace the fuel flow transmitter (AMM 73-31-01/401).
73 03 43	 (01=L, 02=R) eng fuel used indicates low. Fuel flow indication normal (Ref Chapter 71 for fault code diagrams). Examine the fuel system from the engine strut to the fuel flow transmitter for fuel leaks. If leaks are found, repair or replace the defective component or fix the leak as it is necessary. If leaks are not found, examine and repair the simpleme fuel exercise as it is presented (AMM 28-11-00/201).

EFFECTIVITY-

73-FAULT CODE INDEX

airplane fuel system as it is necessary (AMM 28-11-00/201).

///	7//////////////////////////////////////	///
/	PW4000 SERIES	/
/	ENGINES	/
111	777777777777777777777777777777777777777	11

FAULT LOG BOOK REPORT

CODE 2. FAULT ISOLATION REFERENCE

73 03 44 --

- 1. (01=L, 02=R) eng fuel flow display was intermittent (Ref Chapter 71 for fault code diagrams).
- 2. Replace the fuel flow transmitter (AMM 73-31-01/401). If the problem continues, remove the L (R) EICAS computer, M10181 (M10182) (AMM 31-41-02/401). Examine and repair the circuit from the connector D11000, pins 1, 2, and 3 at the fuel flow transmitter, M7192, to the connectors D881A, pins J8, J9, and J7, connector D881D, pins J1, K1, and H1 at the left EICAS computer, M10181, and connectors D883D, pins J1, K1, and H1, and connector D883A, pins J7, J8, and J9 at the right EICAS computer, M10182 (WDM 73-31-11). Install the EICAS computer.

73 03 45 --

- 1. (01=L, 02=R) eng fuel flow display was zero. Fuel used was also low (Ref Chapter 71 for fault code diagrams).
- 2. Replace the fuel flow transmitter (AMM 73-31-01/401). If the problem continues, remove the L (R) EICAS computer, M10181 (M10182) (AMM 31-41-02/401). Examine and repair the circuit from the connector D11000, pins 1, 2, and 3 at the fuel flow transmitter, M7192, to the connectors D881A, pins J8, J9, and J7, connector D881D, pins J1, K1, and H1 at the left EICAS computer, M10181, and the connectors D883D, pins J1, K1, and H1, and the connector D883A, pins J7, J8, and J9 at the right EICAS computer, M10182 (WDM 73-31-11). Install the EICAS computer.

73 03 46 --

- 1. (O1=L, O2=R) eng F/F indicated zero during start, eng start was norm (Ref Chapter 71 for fault code diagrams).
- 2. Replace the fuel flow transmitter (AMM 73-31-01/401). If the probelm continues, remove the L (R) EICAS computers, M10181 (M10182) (AMM 31-41-02/401). Examine and repair the circuit from the connector D11000, pins 1, 2, and 3 at the fuel flow transmitter, M7192, to the connectors D881A, pins J8, J9, and J7, connector D881D, pins H1, K1, and J1 at the left EICAS computer, M10181, and the connectors D883D, pins J1, K1, and H1, and the connectors D883A, pins J7, J8, and J9 at the right EICAS computer, M10182 (WDM 73-31-11). Install the EICAS computers.

73 03 47 --

- 1. (01=L, 02=R) eng failed to light during start. F/F indicated zero with fuel control sw RUN (Ref Chapter 71 for fault code diagrams).
- 2. FIM 73-11-00/101, Fig. 103, Block 1

EFFECTIVITY-

73-FAULT CODE INDEX

ALL

N01

////	111111111111111111111111111111111111111	///
/	PW4000 SERIES	/
/	ENGINES	/
////	7//////////////////////////////////////	///

FAULT LOG BOOK REPORT

CODE 2. FAULT ISOLATION REFERENCE

73 03 48 --

- 1. (01=L, 02=R) eng F/F indicated low during start, eng start was norm (Ref Chapter 71 for fault code diagrams).
- 2. Replace the fuel flow transmitter (AMM 73-31-01/401). If the problem continues, remove the L (R) EICAS computers, M10181 (M10182) (AMM 31-41-02/401). Examine and repair the circuit from the connector D11000, pins 1, 2, and 3 at the fuel flow transmitter, M7192, to the connectors D881A, pins J8, J9, and J7, connector D881D, pins J1, K1, and H1 at the left EICAS computer, M10181, and the connectors D883D, pins J1, K1, and H1, and connector D883A, pins J7, J8, and J9 at the right EICAS computer, M10182 (WDM 73-31-11). Install the EICAS computers.

73 03 49 --

- 1. (01=L, 02=R) eng F/F indicated high during start, eng start was norm (Ref Chapter 71 for fault code diagrams).
- 2. Replace the fuel flow transmitter (AMM 73-31-01/401). If the problem continues, remove the L (R) EICAS computers, M10181 (M10182) (AMM 31-41-02/401). Examine and repair circuit from the connector D11000, pins 1, 2, and 3 at the fuel flow transmitter, M7192, to the connectors D881A, pins J8, J9, and J7, connector D881D, pins J1, K1, and H1 at the left EICAS computer, M10181, and the connectors D883D, pins J1, K1, and H1, and connector D883A, pins J7, J8, and J9 at the right EICAS computer, M10182 (WDM 73-31-11). Install the EICAS computers.

73 03 50 --

- 1. (01=L, 02=R) eng no lightoff during start attempt, F/F indicated zero. Eng and spar valve indicates norm operation (Ref Chapter 71 for fault code diagrams).
- 2. FIM 73-11-00/101, Fig. 103, Block 1

73 03 51 --

- 1. (01=L, 02=R) eng no lightoff during start attempt with ign selector in single or BOTH (Ref Chapter 71 for fault code diagrams).
- 2. FIM 73-21-00/101, Fig. 106, Block 1
- 73 03 52 --Not Used
- 73 03 53 --Not Used
- 73 03 54 --
- 1. (01=L, 02=R) eng hung start before starter cutout. EGT did not increase after N2 stabilization (Ref Chapter 71 for fault code diagrams).
- 2. FIM 73-21-00/101, Fig. 110, Block 1

EFFECTIVITY-

73-FAULT CODE INDEX

ALL

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
73 03 55	 (01=L, 02=R) eng auto accel. Eng was (approaching, exceeded) limits & was shut down (Ref Chapter 71 for fault code diagrams). FIM 73-21-00/101, Fig. 103, Block 1
73 03 56	 (01=L, 02=R) eng auto accel. Eng was (approaching, exceeded) limits & was not shut down (Ref Chapter 71 for fault code diagrams). FIM 73-21-00/101, Fig. 103, Block 1
73 03 57	 (01=L, 02=R) eng slow response to thrust lever movement (Ref Chapter 71 for fault code diagrams). FIM 73-21-00/101, Fig. 108A, Block 1
73 03 58	 (01=L, 02=R) eng no response to thrust lever movement (Ref Chapter 71 for fault code diagrams). FIM 73-21-00/101, Fig. 108, Block 1
73 03 59	 (01=L, 02=R) EICAS msg ENG CONTROL displayed and EICAS msg (01=L, 02=R) ENG EEC MODE displayed. FIM 73-21-00/101, Fig. 112, Block 1 and FIM 73-21-00/101, Fig. 113, Block 1
73 03 60	 EICAS msg (01=L, 02=R) ENG EEC C1 displayed (Ref Chapter 71 for fault code diagrams). FIM 73-21-00/101, Fig. 115, Block 1
73 03 61 00	 EICAS msg IDLE DISAGREE displayed. Both eng min and appr idle rpm normal (Ref Chapter 71 for fault code diagrams). FIM 73-21-00/101, Fig. 111, Block 1 or FIM 73-21-00/101, Fig. 111A, Block 1

EFFECTIVITY-

73-FAULT CODE INDEX

////	111111111111111111111111111111111111111	///
/	PW4000 SERIES	/
/	ENGINES	/
////	7//////////////////////////////////////	///

FAULT 1. LOG BOOK REPORT CODE 2. FAULT ISOLATION REFERENCE 1. EICAS msg IDLE DISAGREE displayed. (01=L, 02=R) eng min/appr 73 03 62 -idle rpm low (Ref Chapter 71 for fault code diagrams). 2. FIM 73-21-00/101, Fig. 111, Block 1 or FIM 73-21-00/101, Fig. 111A, Block 1 73 03 63 --1. EICAS msg (01=L, 02=R) REV POS displayed (Ref Chapter 71 for fault code diagrams). 2. Do the PIMU BITE procedure (71-PIMU MESSAGE INDEX). Look for the PIMU messages that follow: EEC CH-A/B REVERSER RNG FAIL (352-25) EEC CH-A/B REVR CR-CK FAIL (353-25) EEC A/B-CHAN FAIL (350-14) Refer to PIMU Table 101 for corrective action for any of the above PIMU messages shown. 73 03 64 --1. EICAS msg (01=L, 02=R) EEC TEST PWR displayed (Ref Chapter 71 for fault code diagrams). 2. Put the EEC MAINT L (R) ENG POWER switch on the pilot's right side panel, P61, to the NORM position. If the problem continues, replace the L (R) ENG POWER switch S1 (S3) on the EEC MAINT panel, M1390 (WDM 73-21-11). 73 03 65 ---1. EICAS msg (01=L, 02=R) ENG FUEL FILT displayed (Ref Chapter 71 for fault code diagrams). 2. FIM 73-34-00/101, Fig. 103, Block 1 73 03 66 00 Not Used.

EFFECTIVITY-

73-FAULT CODE INDEX

ENGINES

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
73 03 67 00	 EICAS msg L EEC TEST PWR displayed (Ref Chapter 31 for fault code diagram). Put the EEC MAINT L ENG POWER switch on the pilot's right side panel, P61, to the NORM position. If the problem continues, replace the L ENG POWER switch S1 on the EEC MAINT panel, M1390 (WDM 73-21-11).
73 03 68 00	 EICAS msg R EEC TEST PWR displayed (Ref Chapter 31 for fault code diagram). Put the EEC MAINT R ENG POWER switch on the pilot's right side panel, P61, to the NORM position. If the probelm continues, replace the R ENG POWER switch S3 on the EEC MAINT panel, M1390 (WDM 73-21-11).
73 03 69 00	 EICAS msg L ENG EEC C1 displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 115, Block 1
73 03 70 00	 EICAS msg R ENG EEC C1 displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 115, Block 1
73 03 71 00	 EICAS msg L ENG EEC C2 displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 116, Block 1
73 03 72 00	 EICAS msg R ENG EEC C2 displayed (Ref Chapter 31 for fault code diagram). FIM 73-21-00/101, Fig. 116, Block 1
73 03 73 00	 EICAS msg L ENG REV POS displayed (Ref Chapter 31 for fault code diagram). Do the PIMU BITE procedure (71-EPCS MESSAGE INDEX). Look for the PIMU messages that follow:
	EEC CH-A/B REVERSER RNG FAIL (352-25) EEC CH-A/B REVR CR-CK FAIL (353-25) EEC A/B-CHAN FAIL (350-14)
	Refer to PIMU Table 101 for corrective action for any of the above PIMU messages shown.

EFFECTIVITY-

73-FAULT CODE INDEX

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

///////////////////////////////////////	//
/ PW4000 SERIES	/
/ ENGINES	/
///////////////////////////////////////	//

FAULT 1. LOG BOOK REPORT CODE 2. FAULT ISOLATION REFERENCE 73 03 74 00 1. EICAS msg R ENG REV POS displayed (Ref Chapter 31 for fault code diagram). 2. Do the PIMU BITE procedure (71-PIMU MESSAGE INDEX). Look for the PIMU messages that follow: EEC CH-A/B REVERSER RNG FAIL (352-25) EEC CH-A/B REVR CR-CK FAIL (353-25) EEC A/B-CHAN FAIL (350-14) Refer to PIMU Table 101 for corrective action for any of the above PIMU messages shown. 73 03 75 --1. EICAS msg (01=L,02=R) ENG LIM PROT displayed (Ref Chapter 71 for fault code diagram). 2. There is no troubleshooting procedure for this EICAS message. This message is only set in conjunction with EICAS message (L,R) ENG EEC MODE (Refer to fault code 73 03 76 --) or EICAS message (L,R) ENG EEC C1 (Refer to fault code 73 03 77 --). 73 03 76 --1. EICAS msgs (01=L,02=R) ENG LIM PROT and (L,R) ENG EEC MODE displayed (Ref Chapter 71 for fault code diagram). 2. FIM 73-21-00/101, Fig. 113, Block 1 73 03 77 --1. EICAS msgs (01=L,02=R) ENG LIM PROT and (L,R) ENG EEC C1 displayed (Ref Chapter 71 for fault code diagram). 2. FIM 73-21-00/101, Fig. 115, Block 1 73 03 78 --Not Used

EFFECTIVITY-

73-FAULT CODE INDEX

///	///////////////////////////////////////	///
/	PW4000 SERIES	/
/	ENGINES	/
11	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	11

FAULT CODE	1. LOG BOOK REPORT 2. FAULT ISOLATION REFERENCE
73 03 79	 (O1=L,O2=R) eng did not reach target EPR. EICAS msg (L,R) ENG RPM LIM displayed (Ref Chapter 71 for fault code diagram). Do the PIMU BITE procedure (71-PIMU MESSAGE INDEX). Look for the PIMU messages that follow: EEC CH-A/B B25 T/M W/A FAIL (351-16)
	EEC CH-A/B FMU TR-CK FAIL (351-16) EEC CH-A/B B25 TR-CK FAIL 351-21) EEC CH-A/B B25 FD-BK FAIL (351-26) EEC CH-A/B N1 CROSS-CK FAIL (353-14) EEC CH-A/B N2 CROSS-CK FAIL (353-15) EEC CH-A/B STRT SOL W/A FAIL (354-15) EEC CH-A/B STAB SOL W/A FAIL (354-16) EEC CH-A/B PMA PWR SOL SHRT (354-24)
	Refer to PIMU Table 101 for corrective action for any of the above PIMU messages shown.
73 03 80	 (01=L, 02=R) eng slow accel to idle. F/F and duct press were normal (Ref Chapter 71 for fault code diagram). FIM 73-21-00/101, Fig. 110, Block 1
73 03 81	 (01=L, 02=R) eng slow accel to idle. F/F was abnormal (Ref Chapter 71 for fault code diagram). FIM 73-21-00/101, Fig. 110, Block 1
73 03 82	 (01=L, 02=R) eng did not reach target EPR. Eng parameters were not normal for EPR obtained (Ref Chapter 71 for fault code diagrams). FIM 73-21-00/101, Fig. 104B, Block 1
73 03 83	 (01=L, 02=R) eng did not reach target EPR. Eng parameters not reported. (Ref Chapter 71 for fault code diagram). FIM 73-21-00/101, Fig. 104C, Block 1

EFFECTIVITY-

73-FAULT CODE INDEX

ALL

NO1 Page 15 Dec 22/00



///////////////////////////////////////	///
/ PW4000 SERIES	/
/ ENGINES	/
///////////////////////////////////////	11

1. LOG BOOK REPORT **FAULT**

CODE 2. FAULT ISOLATION REFERENCE

73 03 84 --

1. (O1=L, O2=R) eng no lightoff during start attempt, F/F was low. (Ref Chapter 71 for fault code diagram).

2. FIM 73-21-00/101, Fig. 118, Block 1

EFFECTIVITY-

ALL

73-FAULT CODE INDEX

N04

Page 16 Apr 22/99

PW4000 SERIES **ENGINES**

FUEL DISTRIBUTION SYSTEM

SHT		ACCESS/AREA	AMM REFERENCE
CIRCUIT BREAKER - FUEL VALVE L SPAR, C1061 FUEL VALVE R SPAR, C1062 FUEL CONT VLV & EEC CHAN B RESET L, C1419 FUEL CONT VLV & EEC CHAN B RESET R, C1420 FILTER - LEFT ENGINE FUEL PUMP 2 FILTER - RIGHT ENGINE FUEL PUMP 2 INJECTORS AND SUPPORT - LEFT ENGINE FUEL 1 INJECTORS AND SUPPORT - RIGHT ENGINE FUEL 1 LINE - LEFT ENGINE MAIN FUEL SUPPLY LINE - RIGHT ENGINE MAIN FUEL SUPPLY PUMP - LEFT ENGINE FUEL PUMP - RIGHT ENGINE FUEL STRAINER - LEFT ENGINE FUEL STRAINER - LEFT ENGINE FUEL DISTRIBUTION VALVE STRAINER - RIGHT ENGINE FUEL DISTRIBUTION VALVE VALVE - LEFT ENGINE FUEL BYPASS VALVE - LEFT ENGINE FUEL BYPASS VALVE - RIGHT ENGINE FUEL DISTRIBUTION VALVE - RIGHT ENGINE FUEL DISTRIBUTION VALVE - RIGHT ENGINE FUEL DISTRIBUTION VALVE - RIGHT ENGINE FUEL DISTRIBUTION VALVE - RIGHT ENGINE FUEL DISTRIBUTION VALVE - RIGHT ENGINE FUEL DISTRIBUTION	1 1 1 1 1 24 24 1 1 1 1	FLT COMPT, P6,P11 6E1 6E2 11D25 11D26 416AR, THRUST REVERSER 426AR, THRUST REVERSER 415AL,416AR THRUST REVERSER 425AL,426AR THRUST REVERSER 426AR, THRUST REVERSER 426AR, THRUST REVERSER 426AR, THRUST REVERSER 426AR, THRUST REVERSER 426AR, THRUST REVERSER 426AR, THRUST REVERSER 426AR, THRUST REVERSER 426AR, THRUST REVERSER 426AR, THRUST REVERSER 426AR, THRUST REVERSER 426AR, THRUST REVERSER 426AR, THRUST REVERSER 426AR, THRUST REVERSER 426AR, THRUST REVERSER 426AR, THRUST REVERSER	* * * 73-11-02 73-11-05 73-11-05 73-11-08 73-11-01 73-11-01 73-11-04 73-11-04 73-11-07 73-11-07 73-11-03 73-11-03

^{*} SEE THE WDM EQUIPMENT LIST


Fuel Distribution System - Component Index Figure 101

EFFECTIVITY-

296735

73-11-00


PW4000 SERIES **ENGINES**



Fuel Distribution System - Component Location Figure 102 (Sheet 1)


EFFECTIVITY-73-11-00 ALL N01 Page 102 Aug 10/91 BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.






FUEL DISTRIBUTION VALVE







FUEL BYPASS VALVE

E

Fuel Distribution System - Component Location (Details from Sht 1)
Figure 102 (Sheet 2)

ALL

73-11-00

N01

Page 103 Aug 10/91

/ PW4000 SERIES **ENGINES**

NO ENGINE LIGHTOFF (NO FUEL FLOW)

PREREQUISITES


MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



POSSIBLE CAUSES:

- 1. FMU FUEL SHUTOFF SOLENOID PROBLEM (WDM 76-11-11)
- 2. FUEL PUMP IS NOT SATISFACTORY (AMM 73-11-01/401)
- 3. CONTAMINATION IN ENGINE FUEL METERING SYSTEM (FIM 71-08-00/101, FIG. 103)
- 4. AIRCRAFT FUEL SYSTEM OR FIRE PROTECTION SYSTEM PROBLEM (AMM 28 AND AMM 26).

FAULT ISOLATION:



NON-FREQUENT CAUSES OF THIS PROBLEM IN ALPHABETICAL ORDER	RECOMMENDED CORRECTIVE ACTION
MAINTENANCE	EXAMINE MAINTENANCE RECORD.

TABLE A

No Engine Lightoff (No Fuel Flow) Figure 103

EFFECTIVITY-73-11-00 ALL NO1 Page 104 Apr 22/99

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

///	11111111111111	///////
/	PW4000 SER	IES /
/	ENGINES	/
111	11111111111111	11111111

HIGH FUEL FLOW, OTHER ENGINE PARAMETERS NORMAL


PREREQUISITES	
NONE	



POSSIBLE CAUSES:

- 1. FOR AIRPLANES POST-SB 31-0114 OR PRR B12754, A FUEL FLOW INDICATION SPIKE DURING START IS NORMAL.
- 2. LEAK IN FUEL DISTRIBUTION SYSTEM
- 3. BAD FUEL METERING UNIT (AMM 73-21-01/401)
- 4. BAD FUEL FLOW TRANSMITTER (AMM 73-31-01/401).


FAULT ISOLATION:



High Fuel Flow, Other Engine Parameters Normal Figure 104 (Sheet 1)

EFFECTIVITY-73-11-00 ALL N01 Page 105 Aug 22/99

/ PW4000 SERIES **ENGINES**



High Fuel Flow, Other Engine Parameters Normal Figure 104 (Sheet 2)

EFFECTIVITY-73-11-00 ALL N02 Page 106 Aug 22/99

FUEL CONTROL SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
ALTERNATOR - LEFT EEC, T686 ALTERNATOR - RIGHT EEC, T686 CIRCUIT BREAKER -	6 6 3	1 1	415AL,416AR, THRUST REVERSERS 425AL,426AR, THRUST REVERSERS FLIGHT COMPT, P6,P11	73-21-05 73-21-05
AIR DATA CMPTR LEFT, C625		1	11A10	*
AIR DATA CMPTR RIGHT, C626		1	11F30	*
APU ENG START/ECS DISCRETES, C1512		1	11B36	*
FUEL CONT VLV & EEC CHAN B RESET L, C1419		1	11D25	*
FUEL CONT VLV & EEC CHAN B RESET R, C1420		1	11D26	*
FUEL VALVE LEFT SPAR, C1061		1	6E1	*
FUEL VALVE RIGHT SPAR, C1062		1	6E2	*
L ENGINE PERF SOL CHAN A, C1465		1	11L3	*
L ENGINE PERF SOL CHAN B, C1466		1	11L4	*
LEFT ENGINE EEC DISCRETES, C1404		1	11M5	*
LEFT ENGINE PROBE HEAT, C1122 R ENGINE PERF SOL CHAN A, C1467		1	6L25 11L30	*
R ENGINE PERF SOL CHAN B, C1467		1	11L31	*
RIGHT ENGINE EEC DISCRETES, C1405		1	11M32	*
RIGHT ENGINE PROBE HEAT, C1123		i	6K25	*
CONTROL - LEFT ELECTRONIC ENGINE, M7198	1	1	414AR, FAN COWL PANEL	73-21-04
CONTROL - RIGHT ELECTRONIC ENGINE, M7198	i	1	424AR, FAN COWL PANEL	73-21-04
HARNESS - LEFT ENGINE EEC WIRING	1	1	416AR, THRUST REVERSER	73-21-07
HARNESS - RIGHT ENGINE EEC WIRING	1	1	426AR, THRUST REVERSER	73-21-07
PLUG - LEFT ENGINE EEC DATA ENTRY	1	1	414AR, FAN COWL PANEL	73-21-08
PLUG - RIGHT ENGINE EEC DATA ENTRY	1	1	424AR, FAN COWL PANEL	73-21-08
PROBE - LEFT ENGINE EEC FUEL TEMPERATURE THERMOCOUPLE	6	1	416AR, THRUST REVERSER	73-21-09
PROBE - LEFT ENGINE EEC INLET TOTAL PRESSURE/ TEMPERATURE (PT2/TT2), T867	4	1	412AR, INLET PROBE ACCESS PANEL	73-21-03
PROBE - LEFT ENGINE EEC OIL TEMPERATURE THERMOCOUPLE	2	1	415AL,416AR, THRUST REVERSERS	73-21-10
PROBE - LEFT ENGINE EEC THERMOCOUPLE (TT3)	5	1	416AR, THRUST REVERSER	73-21-14
PROBE - RIGHT ENGINE EEC FUEL TEMPERATURE THERMOCOUPLE	6	1	426AR, THRUST REVERSER	73–21–09
PROBE - RIGHT ENGINE EEC INLET TOTAL PRESSURE TEMPERATURE (PT2/TT2), T867	4	1	422AR, INLET PROBE ACCESS PANEL	73–21–03
PROBE - RIGHT ENGINE EEC OIL TEMPERATURE THERMOCOUPLE	2	1	425AL,426AR, THRUST REVERSERS	73–21–10
PROBE - RIGHT ENGINE EEC THERMOCOUPLE (TT3)	5	1	426AR, THRUST REVERSER	73-21-14
RESOLVER - LEFT THRUST LEVER ANGLE (TLA), TS171	3	1	113AL, FORWARD EQUIPMENT COMPT ACCESS	
RESOLVER - RIGHT THRUST LEVER ANGLE (TLA), TS170	3	1	113AL, FORWARD EQUIPMENT COMPT ACCESS	
TRANSDUCER - LEFT ENGINE EEC SPEED (N1)	1	1	415AL,416AR, THRUST REVERSERS	73-21-06
TRANSDUCER - RIGHT ENGINE EEC SPEED (N1)	1	1	425AL,426AR, THRUST REVERSERS	73-21-06
UNIT - LEFT ENGINE FUEL METERING	6	1	415AL,416AR, THRUST REVERSERS	73-21-01
UNIT - RIGHT ENGINE FUEL METERING	6	1	425AL,426AR, THRUST REVERSERS	73-21-01

^{*} SEE THE WDM EQUIPMENT LIST

Fuel Control System - Component Index Figure 101

EFFECTIVITY-

296746


73-21-00

N01

Page 101 Feb 10/97








THRUST REVERSER
415AL (LEFT ENGINE OUTBOARD)
425AL (RIGHT ENGINE INBOARD)

LEFT OR RIGHT ELECTRONIC ENGINE CONTROL (EEC), M7198



LEFT OR RIGHT EEC SPEED TRANSDUCER (N1)



Fuel Control System - Component Location Figure 102 (Sheet 1)


ALL ALL

73-21-00

N01

Page 102 Aug 10/91





Fuel Control System - Component Location Figure 102 (Sheet 2)

EFFECTIVITY-ALL


> ENGINES PRE-PW-SB 73-84 ENGINES POST-PW-SB 73-84


73-21-00

N01


Page 103 Apr 10/98







FLIGHT COMPARTMENT



LEFT OR RIGHT THRUST LEVER ANGLE (TLA) RESOLVER, TS170 OR TS171



Fuel Control System - Component Location Figure 102 (Sheet 3)


ALL

NO1 Page 104
Aug 10/91

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.







LEFT OR RIGHT EEC INLET TOTAL PRESSURE/TEMPERATURE (PT2/TT2) PROBE, T867




Fuel Control System - Component Location Figure 102 (Sheet 4)


73-21-00

N01

Page 105 Aug 10/91







HIGH PRESSURE COMPRESSOR CASE, RIGHT SIDE



Fuel Control System - Component Location Figure 102 (Sheet 5)

EFFECTIVITY-ALL

73-21-00


N01

Page 106 Aug 10/91

299711


PW4000 SERIES **ENGINES**

LEFT OR RIGHT EEC FUEL TEMPERATURE



FUEL PUMP Н

L-A0224



Fuel Control System - Component Location (Details from Sht 5) Figure 102 (Sheet 6)

EFFECTIVITY-ALL

73-21-00

N01

Page 107 Aug 10/91

269662

///	///////////////////////////////////////	///
/	PW4000 SERIES	/
/	ENGINES	/
11	///////////////////////////////////////	111

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)


ENGINE AUTO ACCELERATION



DESCRIPTION:

THE ENGINE PARAMETERS (EPR, N1, N2, EGT AND FUEL FLOW) INCREASE WITHOUT THRUST LEVER MOVEMENT.

FAULT ISOLATION:



Engine Auto Acceleration Figure 103 (Sheet 1)

EFFECTIVITY-ALL

73-21-00

N01

Page 108 Aug 22/99

NON-FREQUENT CAUSES OF THIS PROBLEM IN ALPHABETICAL ORDER	RECOMMENDED CORRECTIVE ACTION
FUEL METERING UNIT	EXAMINE, REPAIR, OR REPLACE THE FUEL METERING UNIT (AMM 73-21-01/401).
N2 SIGNAL (PMA)	EXAMINE, REPAIR, OR REPLACE THE PERMANENT MAGNET ALTERNATOR (AMM 73-21-05/401).
PB MANIFOLD	DO VISUAL CHECK 4 - BURNER PRESSURE (PB) MANIFOLD CONDITION (FIM 71-07-00/101, FIG. 104).
	DO ENGINE CHECK 11 - BURNER PRESSURE (PB) MANIFOLD CHECK (FIM 71-08-00/101, FIG. 111).
P4.95 MANIFOLD	EXAMINE, REPAIR, OR REPLACE THE P4.95 COMPONENTS (AMM 72-00-00/701).
STATOR VANE ACTUATOR SYSTEM	MAKE SURE THE STATOR VANE ACTUATOR SYSTEM IS RIGGED PROPERLY.
THRUST LEVER ANGLE (TLA) RESOLVER	EXAMINE, REPAIR, OR REPLACE THE THRUST LEVER ANGLE (TLA) RESOLVER (AMM 73-21-11/401).
2.9 BLEED VALVE SYSTEM	DO ENGINE CHECK 4 - 2.9 BLEED VALVE SYSTEM CHECK (FIM 71-08-00/101, FIG. 104).
2.5 BLEED VALVE SYSTEM	DO ENGINE CHECK 10 - 2.5 BLEED VALVE SYSTEM CHECK (FIM 71-08-00/101, FIG. 110).
EEC (LESS-FREQUENT CAUSE)	EXAMINE OR REPLACE THE EEC (AMM 73-21-04/401).

TABLE A

Engine Auto Acceleration Figure 103 (Sheet 2)

EFFECTIVITY-ALL

73-21-00

//	///////////////////////////////////////	///
/	PW4000 SERIES	/
/	ENGINES	/
11	///////////////////////////////////////	1//

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

ENGINE AUTO DECEL




DESCRIPTION:

THE ENGINE PARAMETERS (EPR, N1, N2, EGT AND FUEL FLOW) DECREASE WITHOUT THRUST LEVER MOVEMENT.

POSSIBLE CAUSES:

- 1. LEAKS IN FUEL DISTRIBUTION SYSTEM
- 2. BAD BURNER PRESSURE SENSING LINE
- 3. BAD FUEL PUMP PRESSURE
- 4. FUEL SYSTEM CONTAMINATION
- 5. BAD FUEL METERING UNIT.

FAULT ISOLATION:




Engine Auto Decel Figure 104 (Sheet 1)

EFFECTIVITY-ALL


73-21-00

N01

Page 110 Aug 22/99



Engine Auto Decel Figure 104 (Sheet 2)



NON-FREQUENT CAUSES OF THIS PROBLEM IN ALPHABETICAL ORDER	RECOMMENDED CORRECTIVE ACTION
MAINTENANCE	EXAMINE THE MAINTENANCE HISTORY RECORDS. TAKE CORRECTIVE ACTION AS NECESSARY.
N1 SIGNAL	REPLACE THE N1 SPEED PROBE (AMM 73-21-06/401).
N2 SIGNAL (PMA/N2)	EXAMINE, REPAIR OR REPLACE THE PERMANENT MAGNET ALTERNATOR (AMM 73-21-05/401).
P2/T2 SIGNAL	EXAMINE, REPAIR OR REPLACE THE P2/T2 PROBE (AMM 73-21-03/401).
P4.95 SIGNAL	EXAMINE, REPAIR OR REPLACE THE P4.95 COMPONENTS (AMM 72-00-00/701).
THRUST REVERSER POSITION	EXAMINE, REPAIR OR REPLACE THE THRUST REVERSER COMPONENTS.
VARIABLE STATOR VANE SYSTEM	ENGINE CHECK 9 - VARIABLE STATOR VANE SYSTEM CHECK RIGGING (FIM 71-08-00/101, FIG. 109).
ELECTRONIC ENGINE CONTROL (EEC) (LESS FREQUENT)	EXAMINE AND REPLACE EEC (AMM 73-21-04/401).

TABLE A

Engine Auto Decel Figure 104 (Sheet 3)

EFFECTIVITY-73-21-00 ALL NO1 Page 112 Apr 22/99

ENGINE DID NOT REACH TARGET EPR (ENGINE PARAMETERS NORMAL FOR EPR OBTAINED)

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



POSSIBLE CAUSES:

- 1. LEAKS IN FUEL DISTRIBUTION SYSTEM
- 2. BAD BURNER PRESSURE SENSING LINE
- 3. BAD FUEL FILTER
- 4. BAD FUEL PUMP PRESSURE
- 5. BAD FUEL METERING UNIT


FAULT ISOLATION:

YES 1 DO THIS PROCEDURE: PIMU 41 REFER TO THE PIMU MESSAGE BITE PROCEDURE (FIM 71-PIMU TABLES (FIM 71-PIMU MESSAGE MESSAGE INDEX, FIG. 3). INDEX) AND DO THE CORRECTIVE ACTION FOR THE APPLICABLE LOOK FOR THE MESSAGES THAT MESSAGE(S) AS NECESSARY. FOLLOW: EEC A/B CHAN FAIL (350-14)EEC CH-A/B UNIT FAIL (350-15) EEC CH-A/B P-SENSR DISAGREE (350-20)EEC CH-A/B TMC DATA (350-25)EEC CH-A/B L ADC CHAN FAIL (350-27)EEC CH-A/B R ADC CHAN FAIL (350-28)EEC CH-A/B CHAN TMC I/F (350-29)EEC CH-A/B FMU TR-CK FAIL (351-19)EEC CH-A/B TRA RNG FAIL (352-26)EEC CH-A/B T2 CROSS-CK FAIL (353-18)EEC CH-A/B FMU CR-CK FAIL (353-24)EEC CH-A/B TRA CR-CK FAIL (353-26)EEC CH-A/B PO LINE FAIL (353-27)DOES ONE OR MORE OF THE ABOVE MESSAGES SHOW? NO SEE SHEET 2 (BLOCK 2)

Engine did not Reach Target EPR (Engine Parameters Normal for EPR Obtained) Figure 104A (Sheet 1)


EFFECTIVITY-ALL

73-21-00



NON-FREQUENT CAUSES FOR LOW TAKE-OFF POWER - ENGINE PARAMETERS NORMAL TABLE A

Engine did not Reach Target EPR (Engine Parameters Normal for EPR Obtained) Figure 104A (Sheet 2)



ENGINE DID NOT REACH TARGET EPR (ENGINE PARAMETERS NOT NORMAL FOR EPR OBTAINED)

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



POSSIBLE CAUSES:

- 1. LEAKS IN P4.95 SENSE LINE
- 2. BAD TT2 SIGNAL
- 3. BAD 2.5 BLEED VALVE SYSTEM
- 4. BAD 2.9 BLEED/START VALVE
- 5. BAD STATOR VANE ACTUATOR SYSTEM.

FAULT ISOLATION:

YES DO THIS PROCEDURE: PIMU 41 REFER TO THE PIMU MESSAGE BITE PROCEDURE (FIM 71-PIMU TABLES (FIM 71-PIMU MESSAGE INDEX) AND DO THE CORRECTIVE MESSAGE INDEX, FIG. 3). LOOK FOR THE MESSAGES THAT ACTION FOR THE APPLICABLE FOLLOW: MESSAGE(S) AS NECESSARY. EEC A/B CHAN FAIL (350-14) EEC CH-A/B UNIT FAIL (350-15) EEC CH-A/B P5 LINE FAULT (350-21) EEC CH-A/B B25 T/M W/A FAIL (351-16) EEC CH-A/B SVA TR-CK FAIL (351-20) EEC CH-A/B B25 TR-CK FAIL (351-21)EEC CH-A/B B25 FD-BK FAIL (351-26) EEC CH-A/B T2 CROSS-CK FAIL (353-18)EEC CH-A/B PO LINE FAIL (353-27)EEC CH-A/B STRT BLD OPEN (353-28)EEC CH-A/B STAB SOL W/A FAIL (354-16) EEC CH-A/B PMA PWR SOL SHRT (354-24)DOES ONE OR MORE OF THE ABOVE MESSAGES SHOW? NO SEE SHEET 2

Engine did not Reach Target EPR (Engine Parameters Normal for EPR Obtained) Figure 104B (Sheet 1)


EFFECTIVITY-ALL

(BLOCK 3)

73-21-00

N01

Page 115 Aug 22/99



NON-FREQUENT CAUSES OF THIS PROBLEM IN ALPHABETICAL ORDER	RECOMMENDED CORRECTIVE ACTION
INTERNAL EEC PRESSURE SENSOR LEAKAGE	REPLACE THE EEC (AMM 73-21-04/401).

NON-FREQUENT CAUSES FOR LOW TAKE-OFF POWER - ENGINE PARAMETERS NOT NORMAL TABLE A

Engine did not Reach Target EPR (Engine Parameters Normal for EPR Obtained) Figure 104B (Sheet 2)

EFFECTIVITY-73-21-00 ALL NO1 Page 116 Apr 22/99 BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

ENGINE DID NOT REACH TARGET EPR (ENGINE PARAMETERS NOT REPORTED)

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



POSSIBLE CAUSES:

- 1. LEAKS IN FUEL DISTRIBUTION SYSTEM
- 2. BAD P4.95 SENSE LINE
- 3. BAD BURNER PRESSURE SENSING LINE
- 4. BAD 2.5 BLEED VALVE SYSTEM
- 5. BAD FUEL FILTER
- 6. BAD 2.9 BLEED/START VALVE
- 7. BAD STATOR VANE ACTUATOR SYSTEM
- 8. BAD FUEL PUMP PRESSURE.

FAULT ISOLATION:

```
1 DO THIS PROCEDURE: PIMU BITE PROCEDURE (FIM 71-PIMU MESSAGE
                                                                           41 REFER TO THE PIMU MESSAGE
INDEX, FIG. 3).
                                                                           TABLES (FIM 71-PIMU MESSAGE
   LOOK FOR THE PIMU MESSAGES THAT FOLLOW:
                                                                           INDEX) AND DO THE CORRECTIVE
                                                                           ACTION FOR THE APPLICABLE
EEC A/B CHAN FAIL (350-14)
                                                                           MESSAGE(S) AS NECESSARY.
EEC CH-A/B UNIT FAIL (350-15)
EEC CH-A/B P-SENSOR DISAGREE (350-20)
EEC CH-A/B P5 LINE FAULT (350-21)
EEC CH-A/B TMC DATA (350-25)
EEC CH-A/B L ADC CHAN FAIL (350-27)
EEC CH-A/B R ADC CHAN FAIL (350-28)
EEC A/B-CHAN TMC I/F (350-29)
EEC CH-A/B B25 T/M W/A FAIL (351-16)
EEC CH-A/B FMU TR-CK FAIL (351-19)
EEC CH-A/B SVA TR-CK FAIL (351-20)
EEC CH-A/B B25 TR-CK FAIL (351-21)
EEC CH-A/B B25 FD-BK FAIL 351-26)
EEC CH-A/B TRA RNG FAIL (352-26)
EEC CH-A/B T2 CROSS-CK FAIL (353-18)
EEC CH-A/B FMU CR-CK FAIL (353-24)
    DOES ONE OR MORE OF THE ABOVE MESSAGES SHOW?
                NO
         SEE SHEET 2
          (BLOCK 2)
```


Engine did not Reach Target EPR (Engine Parameters Not Reported) Figure 104C (Sheet 1)

EFFECTIVITY-ALL


73-21-00

N01

Page 117 Aug 22/99




Engine did not Reach Target EPR (Engine Parameters Not Reported) Figure 104C (Sheet 2)



Engine did not Reach Target EPR (Engine Parameters Not Reported) Figure 104C (Sheet 3)





NON-FREQUENT CAUSES OF THIS PROBLEM IN ALPHABETICAL ORDER	RECOMMENDED CORRECTIVE ACTION
ENGINE OR AIRCRAFT FUEL SYSTEM RESTRICTIONS	TROUBLESHOOT APPROPRIATE SYSTEMS. REFER TO CHAPTER 28.
INCORRECT FUEL FILTER INSTALLED	CONFIRM CORRECT SIZE AND MODEL OF FILTER (AMM 73-11-02/601).
INTERNAL EEC PRESSURE SENSOR LEAKAGE	REPLACE EEC (AMM 73-21-04/401).

NON-FREQUENT CAUSES FOR LOW TARGET EPR - ENGINE PARAMETERS NOT REPORTED TABLE A

Engine did not Reach Target EPR (Engine Parameters Not Reported) Figure 104C (Sheet 4)

EFFECTIVITY-73-21-00 ALL N01 Page 120 Apr 22/99 BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

PREREQUISITES

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

ENGINE FLAMEOUT (NO OR LOW FUEL FLOW)


NOTE: IF AN INFLIGHT ENGINE SHUTDOWN HAS OCCURRED, DO THE ENGINE WINDMILLING INSPECTION (AMM 72-00-00/601).



POSSIBLE CAUSES:

- 1. FUEL CONTROL CIRCUIT PROBLEM
- 2. FUEL PUMP IS NOT SATISFACTORY (AMM 73-11-01/401)
- 3. CONTAMINATION IN FUEL SYSTEM
- 4. LEAK IN BURNER PRESSURE (PB) MANIFOLD
- 5. FUEL METERING VALVE IS NOT SATISFACTORY (AMM 73-21-01/401).

FAULT ISOLATION:



Engine Flameout (No or Low Fuel Flow) Figure 105 (Sheet 1)


EFFECTIVITY-ALL

73-21-00

N01

Page 121 Aug 22/99





NON-FREQUENT CAUSES OF THIS PROBLEM IN ALPHABETICAL ORDER	RECOMMENDED CORRECTIVE ACTION
AIRCRAFT FUEL SYSTEM RESTRICTION/INTERRUPTION	MAKE SURE THE AIRCRAFT FUEL SYSTEM (FIM 28-22-00/101) AND THE FIRE PROTECTION SYSTEM (WDM 28-21-11) OPERATES CORRECTLY.
ENGINE FUEL SHUTOFF (SPAR) VALVE	DO THIS PROCEDURE: ENGINE FUEL SHUTOFF (SPAR) VALVE SWITCHLIGHT DOES NOT INDICATE AGREEMENT (FIM 28-22-00/101, FIG. 104).
FUEL ICING (WATER IN FUEL)	REMOVE FUEL/OIL COOLER (FOC) (AMM 79-21-01/401). EXAMINE SOLENOID BYPASS VALVE AND COOLER.
MAINTENANCE	EXAMINE MAINTENANCE RECORD.

TABLE A

Engine Flameout (No or Low Fuel Flow) Figure 105 (Sheet 2)



////	///////////////////////////////////////	///////////////////////////////////////	////
/	PW4000	SERIES	/
/	ENGI	NES	/
111	111111111	///////////////////////////////////////	1111

NO ENGINE LIGHTOFF WITH IGNITION SELECTOR IN SINGLE OR BOTH (FUEL FLOW WAS AVAILABLE)


PREREQUISITES	
NONE	



POSSIBLE CAUSES:

- 1. CONTAMINATED OR DAMAGED FUEL DISTRIBUTION VALVE FILTER (AMM 73-11-04/401)
- 2. LEAK IN FUEL DISTRIBUTION SYSTEM
- 3. BAD IGNITION SELECT SWITCH (WDM 73-31-11, -21).

FAULT ISOLATION:



No Engine Lightoff With Ignition Selector in Single or Both (Fuel Flow was Available) Figure 106

EFFECTIVITY-ALL

73-21-00



//	///////////////////////////////////////	///
/	PW4000 SERIES	/
/	ENGINES	/
11	///////////////////////////////////////	///

PREREQUISITES

THRUST LEVERS MISALIGNED



MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

POSSIBLE CAUSES:

- 1. THRUST LEVERS NOT ADJUSTED CORRECTLY (AMM 76-11-00/601)
- 2. BAD THRUST LEVER ANGLE RESOLVER (AMM 73-21-11/401).

FAULT ISOLATION:

Thrust Levers Misaligned Figure 107 (Sheet 1)

73-21-00

NO1

Page 124 Apr 22/99

DO THIS PROCEDURE: PIMU BITE PROCEDURE (FIM 71-PIMU MESSAGE INDEX, FIG. 3). LOOK FOR THE MESSAGES THAT FOLLOW: EEC CH-A/B TRA RNG FAIL (352-26)EEC CH-A/B TRA CR-CK FAIL (353-26)EEC CH-A/B T2 RANGE FAIL (352-18)EEC CH-A/B T2 CROSS-CK FAIL (353-18)EEC CH-A/B LBL 353 BIT 27 EEC CH-A/B PO LINE FAIL (353-27)EEC CH-A/B P2 LINE FAULT (350-22)EEC CH-A/B P5 LINE FAULT (350-21)EEC CH-A/B TMC DATA (350-25) EEC A/B-CHAN TMC I/F (350-29) EEC CH-A/B L ADC CHANFAIL (350-27)EEC CH-A/B R ADC CHANFAIL (350-28)EEC CH-A/B DEM PLUG INVALID (350-26)EEC CH-A/B LBL 350 BIT 19 EEC CH-A/B A/C ID FAILSAFE (350-19)EEC CH-A/B P-SENSR DISAGREE (350-20)EEC CH-A/B XTRN DIS DISAGREE (350-23)EEC CH-A/B FMU FD-BK FAIL (351-24)EEC CH-A/B SVA TR-CK FAIL (351-20) EEC CH-A/B B25 TR-CK FAIL (351-21) EEC CH-A/B SVA FD-BK FAIL (351-25)EEC CH-A/B SVA T/M W/A FAIL (351-15) EEC CH-A/B B25 FD-BK FAIL (351-26)EEC CH-A/B B25 T/M W/A FAIL

20 REFER TO THE PIMU MESSAGE TABLES (FIM 71-PIMU MESSAGE INDEX) AND DO THE CORRECTIVE ACTION FOR THE APPLICABLE MESSAGE(S) AS NECESSARY.


Thrust Levers Misaligned Figure 107 (Sheet 2)

EFFECTIVITY-

(351-16)

CONTINUED ON SHEET 3

73-21-00



Thrust Levers Misaligned Figure 107 (Sheet 3)

EFFECTIVITY-ALL

73-21-00

N03

Page 126 Apr 22/99

PREREQUISITES

NO ENGINE RESPONSE TO THRUST LEVER MOVEMENT, ENGINE PARAMETERS NORMAL

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)


MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



POSSIBLE CAUSES:

- 1. THRUST LEVERS NOT ADJUSTED CORRECTLY (AMM 76-11-00/501)
- 2. BAD BURNER PRESSURE (PB) SENSING LINES
- 3. BAD THRUST REVERSER INDICATION
- 4. CONTAMINATION IN FUEL SYSTEM
- 5. BAD FUEL PUMP
- 6. BAD FUEL METERING UNIT.


FAULT ISOLATION:



No Engine Response to Thrust Lever Movement, Engine Parameters Normal Figure 108 (Sheet 1)

EFFECTIVITY-ALL

73-21-00



No Engine Response to Thrust Lever Movement, Engine Parameters Normal Figure 108 (Sheet 2)



//	///////////////////////////////////////	/
/	PW4000 SERIES	/
/	ENGINES	/
//	///////////////////////////////////////	/

NON-FREQUENT CAUSES OF THIS PROBLEM IN ALPHABETICAL ORDER	RECOMMENDED CORRECTIVE ACTION
AIRPLANE FUEL SYSTEM RESTRICTION	CHAPTER 28
EEC	EXAMINE/REPLACE THE EEC (AMM 73-21-04/401).
MAINTENANCE	EXAMINE THE MAINTENANCE HISTORY RECORD. TAKE CORRECTIVE ACTION AS NECESSARY.
P2/T2 PROBE	EXAMINE/REPAIR/REPLACE THE P2/T2 PROBE (AMM 73-21-03/401).
THRUST LEVER ANGLE (TLA) RESOLVER	EXAMINE/REPAIR/REPLACE THRUST LEVER ANGLE (TLA) RESOLVER (AMM 73-21-11/401).

TABLE A

No Engine Response to Thrust Lever Movement, Engine Parameters Normal Figure 108 (Sheet 3)

ALL

73-21-00

NO1

Page 129 Apr 22/99

///	///////////////////////////////////////	///
/	PW4000 SERIES	/
/	ENGINES	/
11	///////////////////////////////////////	11

SLOW ENGINE RESPONSE TO THRUST LEVER MOVEMENT, ENGINE PARAMETERS NORMAL

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



POSSIBLE CAUSES:

- 1. BAD BURNER PRESSURE (PB) SENSING LINES.
- 2. BAD FUEL PUMP.
- 3. BAD FUEL METERING UNIT.

FAULT ISOLATION:


YES 1 DO THIS PROCEDURE: PIMU 20 REFER TO THE PIMU MESSAGE TABLES (FIM 71-PIMU MESSAGE BITE PROCEDURE (FIM 71-PIMU MESSAGE INDEX, FIG. 3). INDEX) AND DO THE CORRECTIVE ACTION FOR THE APPLICABLE LOOK FOR THE MESSAGES THAT MESSAGE(S) AS NECESSARY. EEC CH-A/B FMU TR-CK FAIL (351-19) EEC CH-A/B P5 LINE FAULT (350-21)EEC CH-A/B P2 LINE FAULT (350-22)EEC CH-A/B LBL 353 BIT 27 EEC CH-A/B PO LINE FAIL (353-27)EEC CH-A/B FMU T/M W/A FAIL (351-14)EEC CH-A/B SVA TR-CK FAIL (351-20)DOES ONE OR MORE OF THE ABOVE MESSAGES SHOW? SEE SHEET 2 (BLOCK 2)

Slow Engine Response to Thrust Lever Movement, Engine Parameters Normal Figure 108A (Sheet 1)

EFFECTIVITY-ALL

73-21-00

773595



NON-FREQUENT CAUSES OF THIS PROBLEM IN ALPHABETICAL ORDER	RECOMMENDED CORRECTIVE ACTION
AIRPLANE FUEL SYSTEM RESTRICTION	CHAPTER 28
EEC	EXAMINE/REPLACE THE EEC (AMM 73-21-04/401).
ENGINE BLEED SYSTEM	DO ENGINE CHECK 10 - 2.5 BLEED VALVE SYSTEM CHECK AND ENGINE CHECK 4 - 2.9 BLEED VALVE SYSTEM CHECK (FIM 71-08-00/101).
FUEL SYSTEM CONTAMINATION	DO ENGINE CHECK 3 - FUEL SYSTEM CONTAMINATION CHECK (FIM 71-08-00/101, FIG. 103).
MAINTENANCE	EXAMINE THE MAINTENANCE HISTORY RECORD. TAKE CORRECTIVE ACTION AS NECESSARY.
VARIABLE STATOR VANE SYSTEM	DO ENGINE CHECK 9 - VARIABLE STATOR VANE SYSTEM CHECK (FIM 71-08-00/101, FIG. 109).

NON-FREQUENT CAUSES FOR SLOW ENGINE RESPONSE TO THRUST LEVER MOVEMENT TABLE A

Slow Engine Response to Thrust Lever Movement, Engine Parameters Normal Figure 108A (Sheet 2)

EFFECTIVITY-ALL

73-21-00

N01

Page 131 Apr 22/99

PREREQUISITES

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

ENGINE FLAMEOUT (REASON FOR UNSUCCESSFUL RESTART UNKNOWN)

NOTE: IF AN INFLIGHT ENGINE SHUTDOWN HAS OCCURRED, DO THE ENGINE WINDMILLING INSPECTION


(AMM 72-00-00/601).




POSSIBLE CAUSES:

- 1. FOD
- 2. FUEL PUMP OR FUEL METERING UNIT IS NOT SATISFACTORY (AMM 73-11-01/401 AND AMM 73-21-01/401)
- 3. CONTAMINATION IN FUEL SYSTEM (AMM 73-11-02/401).

FAULT ISOLATION:




Engine Flameout (Reason for Unsuccessful Restart Unknown) Figure 109 (Sheet 1)



/ PW4000 SERIES

ENGINES



Engine Flameout (Reason for Unsuccessful Restart Unknown) Figure 109 (Sheet 2)

//	///////////////////////////////////////	///
/	PW4000 SERIES	/
/	ENGINES	/
11	///////////////////////////////////////	///

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E1, 6E2, 11D25, 11D26

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

HUNG START OR SLOW ACCELERATION TO IDLE



POSSIBLE CAUSES:

- 1. BAD TT2 SIGNAL (FIM 71-08-00/101)
- 2. BAD OR DAMAGED BURNER PRESSURE MANIFOLD (FIM 71-08-00/101, FIG. 111)
- 3. BAD ENGINE CONTROL SYSTEM ACTUATOR (FIM 71-08-00/101)
- 4. TIGHT N2 ROTOR (AMM 72-00-00/601)
- 5. DAMAGED OR DETERIORATED HPC (AMM 72-00-00/601)
- 6. BAD FUEL METERING UNIT (AMM 73-11-01/401).

FAULT ISOLATION:

YES 1 DO THIS PROCEDURE: PIMU 30 REFER TO THE PIMU MESSAGE BITE PROCEDURE (FIM 71-PIMU TABLES (FIM 71-PIMU MESSAGE INDEX) AND DO THE CORRECTIVE MESSAGE INDEX, FIG. 3). LOOK FOR THE PIMU MESSAGES ACTION FOR THE APPLICABLE MESSAGE(S) AS NECESSARY. THAT FOLLOW: EEC CH-A/B FMU T/M W/A FAIL (351-14) EEC CH-A/B FMU FD-BK FAIL (351-24)EEC CH-A/B SVA T/M W/A FAIL (351-15) EEC CH-A/B SVA FD-BK FAIL (351-25) EEC CH-A/B FMU TR-CK FAIL (351-19)EEC CH-A/B SVA TR-CK FAIL (351-20) EEC CH-A/B B25 TR-CK FAIL (351-21)EEC CH-A/B STRT SOL W/A FAIL (354-15)EEC CH-A/B PMA PWR SOL SHRT (354-24)EEC CH-A/B OVS SOL W/A FAIL (354-14)EEC CH-A/B STAB SOL W/A FAIL (354-16)EEC CH-A/B XTRN DIS DISAGREE (350-23)EEC CH-A/B P-SENSR DISAGREE (350-20)EEC CH-A/B T3 RANGE FAIL (352-22)EEC CH-A/B T3 CROSS-CK FAIL (353-22)(CONTINUED)


> Hung Start or Slow Acceleration to Idle Figure 110 (Sheet 1)

EFFECTIVITY-ALL


73-21-00

NO1

Page 134 Aug 22/99



Hung Start or Slow Acceleration to Idle Figure 110 (Sheet 2)



Hung Start or Slow Acceleration to Idle Figure 110 (Sheet 3)

NON-FREQUENT CAUSES OF THIS PROBLEM IN ALPHABETICAL ORDER	RECOMMENDED CORRECTIVE ACTION
2.9 BLEED VALVE SYSTEM	DO ENGINE CHECK 4 - 2.9 BLEED VALVE SYSTEM CHECK (FIM 71-08-00/101, FIG. 104).
AIRPLANE/ENGINE BLEED SYSTEMS	REFER TO CHAPTER 21.
EEC IS POWERED IN CHANNEL A AND CHANNEL B BEFORE ENGINE START	LOOK FOR PROBLEMS IN THE EEC RESET AND CHANNEL INHIBIT CIRCUIT. LOOK AT THE CIRCUIT FOR THE K1036 AND K1037, RELAYS (LEFT ENGINE) AND K1039 AND K1038, RELAYS (RIGHT ENGINE). REPAIR OR REPLACE AS NECESSARY.
EXTERNAL RESET CLOSED	GO TO FIM 71-PIMU MESSAGE INDEX, LABEL-BIT 350-23, EEC CH-A/B XTRN DIS DISAGREE. ONLY DO THE STEPS FOR "EXTERNAL RESET".
FUEL SYSTEM RESTRICTIONS	REMOVE AND EXAMINE ENGINE FUEL FILTER FOR FOD, CLOGGING, CORRECT P/N (AMM 73-11-02/401). REMOVE AND EXAMINE DISTRIBUTION VALVE STRAINER FOR FOD, CLOGGING, CORRECT P/N (AMM 73-11-04/401).
GASPATH DAMAGE	EXAMINE THE INLET, EXHAUST, 2.5/2.9 BLEED OPENING FOR DAMAGE.
MAINTENANCE	EXAMINE THE MAINTENANCE HISTORY RECORDS. TAKE CORRECTIVE ACTION AS NECESSARY.
OVERSERVICED OR DETERIORATED IDG WHICH CAUSES A HIGH DRAG ON THE HPC	EXAMINE AND SERVICE IDG (AMM 12-13-07/301).
PREMATURE STARTER CUT-OUT OR LACK OF TORQUE PROVIDED BY THE STARTER	MAKE SURE THAT THE STARTER IS PROPERLY SERVICED AND ROTATES FREELY (AMM 80-11-00/501 AND AMM 72-00-00/601). OBSERVE STARTER OPERATION COMPARED TO ANOTHER ENGINE.
TT3 SIGNAL	EXAMINE/REPAIR THE EEC TT3 T/C PROBE AND WIRING (AMM 73-21-14/401).
WATER IN Pb TRAP	REMOVE WATER FROM TRAP (AMM 73-21-04/601).

NON-FREQUENT CAUSES FOR HUNG START TABLE A

Hung Start or Slow Acceleration to Idle Figure 110 (Sheet 4)

EFFECTIVITY-

73-21-00

///	///////////////////////////////////////	//
/	PW4000 SERIES	/
/	ENGINES	/
11	///////////////////////////////////////	11

EICAS MESSAGE "IDLE DISAGREE" OR "L (R) ENG LOW IDLE" IS SHOWN

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



POSSIBLE CAUSES:

- 1. L (R) IDLE SOLENOID RELAY (WDM 73-21-19)
- 2. L (R) FLAP/STAB POSITION MODULE (AMM 27-50-01/401)
- 3. AIR/GROUND RELAY (AMM 32-09-02/401)
- 4. L (R) ENGINE EEC DISCRETES CARD ASSEMBLY (AMM 73-21-12/401)
- 5. L (R) TAI IDLE RELAY (WDM 73-21-19)
- 6. ENGINE EEC (AMM 73-21-04/401)
- 7. BAD ELECTRICAL CIRCUIT.

FAULT ISOLATION:



> CONNECT THE ELECTRICAL CONNECTORS THAT HAVE BEEN DISCONNECTED.

> CLOSE THE CIRCUIT BREAKERS THAT HAVE BEEN OPENED.

> PUT THE AIRPLANE IN THE GROUND MODE (AMM 32-09-02/201).

EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 1)

EFFECTIVITY-MANUAL ANTI-ICE

H91508

73-21-00

FROM SHEET 1 (BLOCK 1) NO YES 2 LOOK AT THE FLIGHT LOG 102 GO TO SHEET 15, BLOCK 7. BOOK TO FIND OUT WHICH ENGINE HAS THE IDLE SPEED PROBLEM. MAKE SURE THAT THE "L (R) ENGINE ANTI-ICE VALVE" SWITCHES AND THE "L (R) ENGINE START" SWITCHES ARE IN THE "OFF" POSITION. WARNING MAKE SURE THAT PERSONS AND EQUIPMENT ARE AWAY FROM THE LE AND TE FLAPS AND FLAP DRIVE MECHANISM BEFORE YOU MOVE THE POSITION SELECTOR SWITCH. WITH HYDRAULIC POWER REMOVED, THE FLAPS WILL MOVE AUTOMATICALLY BY ELECTRICAL POWER WHEN THE POSITION SELECTOR IS CHANGED. PUT THE POSITION SELECTOR SWITCH FOR THE ALTERNATE FLAP/ STAB DRIVE IN THE 30-UNIT POSITION (FIM 27-51-00/101, FIG. 101). CAN THE ENGINE IDLE SPEED PROBLEM BE IDENTIFIED TO A SPECIFIC ENGINE? NO SEE SHEET 3 (BLOCK 3)


> EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 2)

EFFECTIVITY-MANUAL ANTI-ICE

73-21-00

80N


Page 139 Apr 22/99



EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 3)

EFFECTIVITY-MANUAL ANTI-ICE

73-21-00



EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 4)


EFFECTIVITY-MANUAL ANTI-ICE

73-21-00

N₀6

Page 141 Apr 22/99

H91529




EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 5)

EFFECTIVITY-MANUAL ANTI-ICE

73-21-00

N₀6

Page 142 Apr 22/99



EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 6)

EFFECTIVITY-MANUAL ANTI-ICE

73-21-00

80N

Page 143 Apr 22/99

FROM SHEET 5 (BLOCK 57) YES 59 DISCONNECT CONNECTOR D2160 112 REPLACE THE AIR/GROUND RELAY, K167 (K205) (D2162), FOR THE L (R) ENG EEC DISCRETES CARD ASSEMBLY, M590 (AMM 32-09-02/401). (M591), ON THE P50 PANEL IF THE PROBLEM CONTINUES, (WDM 73-21-19). EXAMINE THE CIRCUIT FROM THE LOOK FOR A GROUND AT PIN 2 AIR/GROUND RELAY, K167 (K205), ON CONNECTOR D2160 (D2162). TO THE L (R) ENGINE EEC IS PIN 2 GROUNDED? DISCRETES CARD ASSEMBLY, M590 (M591)(WDM 73-21-19). REPAIR THE PROBLEMS THAT YOU FIND. IF THE PROBLEM CONTINUES, EXAMINE THE CIRCUIT FROM THE AIR/GROUND RELAY, K167 (K205), TERMINAL BLOCK TB218, YC7 (TB224, YA29), AIR/GROUND RELAY, K141 (K207), L (R) IDLE SOLENOID RELAY, K434 (K433), L (R) ENG TAI IDLE RELAY, K785 (K786), TO L (R) FLAP/STAB POSITION MODULE, M838 (M840) (WDM 73-21-19). REPAIR THE PROBLEMS THAT YOU FIND. IF THE PROBLEM CONTINUES, DO THIS PROCEDURE: BITE PROCEDURE FOR THE PROXIMITY SWITCH ELECTRONICS UNIT (PSEU) (FIM_32-09-03/101, FIG. 103). 1>2>3> 113 REPLACE THE L (R) ENGINE EEC DISCRETES CARD ASSEMBLY, M590 (M591)(AMM 73-21-12/401).

EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 7)


EFFECTIVITY-MANUAL ANTI-ICE

73-21-00

N05

1>2>3>

Page 144 Apr 22/99



EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 8)

EFFECTIVITY-MANUAL ANTI-ICE


73-21-00

N05

Page 145 Apr 22/09

REPLACE THE ENGINE EEC, M7198

(AMM 73-21-04/401). 1>2>3>



EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 9)

EFFECTIVITY-MANUAL ANTI-ICE

73-21-00

N₀5

Page 146 Apr 22/99

FROM SHEET 9 (BLOCK 62) NO 63 EXAMINE THE CIRCUIT 117 OPEN THE CIRCUIT BREAKERS BREAKERS THAT FOLLOW: THAT FOLLOW: 11M6, LEFT ENGINE IDLE CONT 11M6, LEFT ENGINE IDLE CONT 11M33, RIGHT ENGINE IDLE CONT 11M33, RIGHT ENGINE IDLE CONT 34L1, ENG IDLE CONT 34L1, ENG IDLE CONT DID ANY CIRCUIT BREAKERS EXAMINE THE CIRCUIT FROM THE ENG IDLE CONT CIRCUIT OPEN? BREAKERS 34L1,11M6 (11M33), NO TO THE L (R) ENG EEC DISCRETES CARD ASSEMBLY, M590 (M591) (WDM 73-21-19). REPAIR THE PROBLEMS THAT YOU FIND. 1>2>3>

118 REPLACE THE L (R) ENGINE EEC DISCRETES CARD ASSEMBLY, M590 (M591)(AMM 73-21-12/401). IF THE PROBLEM CONTINUES, REPLACE THE AIR/GROUND RELAY, K167 (K205)(AMM 32-09-02/401). IF THE PROBLEM CONTINUES,

EXAMINE THE CIRCUIT FROM THE L (R) IDLE SOLENOID RELAY, K434 (K433), TO THE L (R) ENGINE EEC DISCRETES CARD ASSEMBLY, M590 (M591) (WDM 73-21-19).

REPAIR THE PROBLEMS THAT YOU FIND.

FOR THE LEFT ENGINE: CONNECTOR D3622, PIN X1, TO CONNECTOR D2160, PIN 35.

FOR THE RIGHT ENGINE: CONNECTOR D3752, PIN X1, TO CONNECTOR D2162, PIN 35.

IF THE PROBLEM CONTINUES, EXAMINE THE CIRCUIT FROM THE L (R) ENGINE EEC DISCRETES CARD ASSEMBLY, M590 (M591); AIR/GROUND RELAY, K167 (K205); TERMINAL BLOCK TB218, YC7 (TB274, YA29); THE L (R) ENG TAI IDLE RELAY, K785 (K786); TO THE L (R) FLAP/STAB POSITION MODULE, M838 (M840) (WDM 73-21-19).

REPAIR THE PROBLEMS THAT YOU FIND.

IF THE PROBLEM CONTINUES, DO THIS PROCEDURE: BITE PROCEDURE FOR THE PROXIMITY SWITCH ELECTRONIC UNIT (PSEU) (FIM 32-09-03/101, FIG. 103). 1>2>3>


EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 10)

EFFECTIVITY-MANUAL ANTI-ICE

73-21-00

N07

Page 147 Apr 22/99




EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 11)

EFFECTIVITY-MANUAL ANTI-ICE

73-21-00

N07

Page 148 Apr 22/99



EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 12)

73-21-00

80N

Page 149 Apr 22/99

FROM SHEET 12 (BLOCK 66)

NO

67 OPEN THE CIRCUIT BREAKERS THAT FOLLOW: 11M6, LEFT ENGINE IDLE CONT

11A16, ANTI-ICE ENG L 11M33, RIGHT ENGINE IDLE CONT 11T19, ANTI-ICE ENG R 34L1, ENG IDLE CONT 11D19, L CONT ENG START 11D2O, R CONT ENG START

DISCONNECT CONNECTOR D10550 (D10552) FROM THE L (R) ENG TAI IDLE RELAY, K785 (K786), ON THE P36 (P37) PANEL (WDM 73-21-19).

CLOSE THE CIRCUIT BREAKERS THAT FOLLOW:

11D19, L CONT ENG START 11D2O, R CONT ENG START

ON THE P36 (P37) PANEL, LOOK FOR 28V DC AT PIN 6 OF CONNECTOR D10550 (D10552). IS 28V DC FOUND?

YES

SEE SHEET 14 (BLOCK 68)

123 EXAMINE THE CIRCUIT FROM THE L (R) ENG TAI IDLE RELAY, K785 (K786), TO THE L (R) CONT ENG START CIRCUIT BREAKERS 11D19 (11D20)(WDM 80-11-11, -21; 73-21-19).

FOR THE LEFT ENGINE: CONNECTOR D10550, PIN 6 AND


FOR THE RIGHT ENGINE: CONNECTOR D10552, PIN 6 AND C1511.

EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 13)

EFFECTIVITY-MANUAL ANTI-ICE 73-21-00

N07

Page 150 Apr 22/99




EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 14)

EFFECTIVITY-MANUAL ANTI-ICE

73-21-00

N07

Page 151 Apr 22/99




EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 15)

EFFECTIVITY-MANUAL ANTI-ICE

H91523

73-21-00



EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 16)

EFFECTIVITY-MANUAL ANTI-ICE

73-21-00

N07

Page 153 Apr 22/99

FROM SHEET 16 (BLOCK 9)	FROM SHEET 16 (BLOCK 71)	
YES	NO	
		THE L (R) ENGINE EEC DISCRETES CARD ASSEMBLY, M590 (M591), TO THE ENG IDLE CONT CIRCUIT BREAKERS 34L1, 11M6 (11M33) (WDM 73-21-19). REPAIR THE PROBLEMS THAT YOU FIND. FOR THE LEFT ENGINE: CONNECTOR D2160, PIN 19, AND C1459,C1458. FOR THE RIGHT ENGINE: CONNECTOR D2162, PIN 19, AND C1459,C1457.
		132 REPLACE THE L (R) IDLE
		SOLENOID RELAY, K434 (K433) (WDM 73-21-19). IF THE PROBLEM CONTINUES, EXAMINE THE CIRCUIT FROM THE ENGINE EEC, M7198, TO THE L (R) IDLE SOLENOID RELAY, K434 (K433), ON THE P36 (P37) PANEL (WDM 73-21-19). REPAIR THE PROBLEMS THAT YOU FIND. FOR THE LEFT ENGINE: CONNECTOR D3622, PIN A1 AND PIN A2, TO CONNECTOR D11114, PIN J AND PIN C; CONNECTOR D3622, PIN A1 AND PIN A2, TO CONNECTOR D11686, PIN J AND PIN C. FOR THE RIGHT ENGINE: CONNECTOR D3752, PIN A1 AND PIN A2, TO CONNECTOR D11114, PIN J AND PIN C; CONNECTOR D3752, PIN A1 AND PIN A2, TO CONNECTOR D11686, PIN J AND PIN C. IF THE PROBLEM CONTINUES, REPLACE THE ENGINE EEC, M7198 (AMM 73-21-04/401).

EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111 (Sheet 17)

EFFECTIVITY-MANUAL ANTI-ICE

Н91526

73-21-00

N07

Page 154 Apr 22/99

///	///////////////////////////////////////	1//
/	PW4000 SERIES	/
/	ENGINES	/
///	///////////////////////////////////////	///

EICAS MESSAGE "IDLE DISAGREE" OR "L (R) ENG LOW IDLE" IS SHOWN

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



POSSIBLE CAUSES:

- 1. L (R) IDLE SOLENOID RELAY (WDM 73-21-19)
- 2. L (R) FLAP/STAB POSITION MODULE (AMM 27-50-01/401)
- 3. AIR/GROUND RELAY (AMM 32-09-02/401)
- 4. L (R) ENG EEC DISCRETES CARD ASSEMBLY (AMM 73-21-12/401)
- 5. L (R) ENG ANTI-ICE CMD RELAY (WDM 73-21-19)
- 6. L (R) ENG CONT IGN IDLE RELAY (WDM 73-21-19)
- 7. ENGINE EEC (AMM 73-21-04/401)
- 8. BAD ELECTRICAL CIRCUIT.

FAULT ISOLATION:



1 CONNECT THE ELECTRICAL CONNECTORS THAT HAVE BEEN DISCONNECTED.

2 CLOSE THE CIRCUIT BREAKERS THAT HAVE BEEN OPENED.

3> PUT THE AIRPLANE IN THE GROUND MODE (AMM 32-09-02/201).

EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 1)

73-21-00

FROM SHEET 1 (BLOCK 1) NO YES 2 LOOK AT THE FLIGHT LOG 102 GO TO SHEET 15, BLOCK 7. BOOK TO FIND OUT WHICH ENGINE HAS THE IDLE SPEED PROBLEM. MAKE SURE THAT THE "L (R) ENGINE ANTI-ICE VALVE" SWITCHES AND THE "L (R) ENGINE START" SWITCHES ARE IN THE "OFF" POSITION. WARNING MAKE SURE THAT PERSONS AND EQUIPMENT ARE AWAY FROM THE LE AND TE FLAPS AND FLAP DRIVE MECHANISM BEFORE YOU MOVE THE POSITION SELECTOR SWITCH. WITH HYDRAULIC POWER REMOVED, THE FLAPS WILL MOVE AUTOMATICALLY BY ELECTRICAL POWER WHEN THE POSITION SELECTOR IS CHANGED. PUT THE POSITION SELECTOR SWITCH FOR THE ALTERNATE FLAP/ STAB DRIVE IN THE 30-UNIT POSITION (FIM 27-51-00/101, FIG. 101). CAN THE ENGINE IDLE SPEED PROBLEM BE IDENTIFIED TO A SPECIFIC ENGINE? NO SEE SHEET 3 (BLOCK 3)

> EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 2)


EFFECTIVITY-AUTO ANTI-ICE

H91531

73-21-00

N₀5

Page 156 Apr 22/99



EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 3)


EFFECTIVITY-AUTO ANTI-ICE

73-21-00

N07

Page 157 Apr 22/99

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.



EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 4)


EFFECTIVITY-AUTO ANTI-ICE

73-21-00

N05

Page 158 Apr 22/99

H91535



EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 5)


EFFECTIVITY-AUTO ANTI-ICE

73-21-00

80N

Page 159 Apr 22/99

H91536



EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 6)

EFFECTIVITY-AUTO ANTI-ICE

73-21-00

N06

Page 160 Apr 22/99

FROM SHEET 5 (BLOCK 57) YES 59 DISCONNECT CONNECTOR D2160 112 REPLACE THE AIR/GROUND RELAY, K167 (K205) (D2162), FOR THE L (R) ENG EEC DISCRETES CARD ASSEMBLY, M590 (AMM 32-09-02/401). (M591), ON THE P50 PANEL IF THE PROBLEM CONTINUES, (WDM 73-21-19). EXAMINE THE CIRCUIT FROM THE LOOK FOR A GROUND AT PIN 2 AIR/GROUND RELAY, K167 (K205), ON CONNECTOR D2160 (D2162). TO THE L (R) ENGINE EEC DISCRETES CARD ASSEMBLY, M590 IS PIN 2 GROUNDED? (M591)(WDM 73-21-19). REPAIR THE PROBLEMS THAT YOU FIND. IF THE PROBLEM CONTINUES, EXAMINE THE CIRCUIT FROM THE AIR/GROUND RELAY, K167 (K205), TERMINAL BLOCK TB218, YC7 (TB224, YA29), AIR/GROUND RELAY, K141 (K207), L (R) IDLE SOLENOID RELAY, K434 (K433), L (R) ENG CONT IGN IDLE RELAY, K2232 (K2233); L (R) ENG ANTI-ICE CMD RELAY, K2103 (K2104); TO L (R) FLAP/STAB POSITION MODULE, M838 (M840) (WDM 73-21-19). REPAIR THE PROBLEMS THAT YOU FIND. IF THE PROBLEM CONTINUES, DO THIS PROCEDURE: BITE PROCEDURE FOR THE PROXIMITY SWITCH ELECTRONICS UNIT (PSEU) (FIM 32-09-03/101, FIG. 103). 1>2>3>

EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 7)

EFFECTIVITY-AUTO ANTI-ICE

73-21-00


113 REPLACE THE L (R) ENGINE EEC DISCRETES CARD ASSEMBLY, M590 (M591)(AMM 73-21-12/401).

1>2>3>

N₀6

Page 161 Apr 22/99





EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 8)

EFFECTIVITY-AUTO ANTI-ICE

H91539

73-21-00

FROM SHEET 8 (BLOCK 61) YES 62 CLOSE THE CIRCUIT BREAKERS 116 REPLACE THE L (R) IDLE SOLENOID RELAY, K434 (K433) THAT FOLLOW: (WDM 73-21-19). 11M6, LEFT ENGINE IDLE CONT IF THE PROBLEM CONTINUES, 11M33, RIGHT ENGINE IDLE CONT EXAMINE THE CIRCUIT FROM THE 34L1, ENG IDLE CONT ENGINE EEC, M7198, TO THE ON THE P36 (P37) PANEL, L (R) IDLE SOLENOID RELAY, LOOK FOR 28V DC AT PIN X1 ON K434 (K433), ON THE P36 (P37) CONNECTOR D3622 (D3752). PANEL (WDM 73-21-19). IS 28V DC FOUND? REPAIR THE PROBLEMS THAT YOU FIND. NO FOR THE LEFT ENGINE: CONNECTOR D3622, PIN A1 AND PIN A2, TO CONNECTOR D11114, SEE SHEET 10 PIN J AND PIN C; CONNECTOR (BLOCK 63) D3622, PIN A1 AND PIN A2, TO CONNECTOR D11686, PIN J AND PIN C. FOR THE RIGHT ENGINE: CONNECTOR D3752, PIN A1 AND PIN A2, TO CONNECTOR D11114, PIN J AND PIN C; CONNECTOR D3752, PIN A1 AND PIN A2, TO CONNECTOR D11686, PIN J AND IF THE PROBLEM CONTINUES, REPLACE THE ENGINE EEC, M7198 (AMM 73-21-04/401). 1>2>3>

EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 9)

EFFECTIVITY-AUTO ANTI-ICE 73-21-00

N₀5

Page 163 Apr 22/99

FROM SHEET 9 (BLOCK 62) NΩ YES 63 EXAMINE THE CIRCUIT 117 OPEN THE CIRCUIT BREAKERS BREAKERS THAT FOLLOW: THAT FOLLOW: 11M6, LEFT ENGINE IDLE CONT 11M6, LEFT ENGINE IDLE CONT 11M33, RIGHT ENGINE IDLE CONT 11M33, RIGHT ENGINE IDLE CONT 34L1, ENG IDLE CONT 34L1, ENG IDLE CONT DID ANY CIRCUIT BREAKERS EXAMINE THE CIRCUIT FROM OPEN? THE ENG IDLE CONT CIRCUIT BREAKERS 34L1,11M6 (11M33) NO TO THE L (R) ENG EEC DISCRETES CARD ASSEMBLY, M590 (M591)

(WDM 73-21-19).

YOU FIND. 1>2>3>

REPAIR THE PROBLEMS THAT

118 REPLACE THE L (R) ENGINE

EEC DISCRETES CARD ASSEMBLY, M590 (M591)(AMM 73-21-12/401). IF THE PROBLEM CONTINUES, REPLACE THE AIR/GROUND RELAY, K167 (K205)(AMM 32-09-02/401). IF THE PROBLEM CONTINUES, EXAMINE THE CIRCUIT FROM THE L (R) IDLE SOLENOID RELAY, K434 (K433), TO THE L (R) ENGINE EEC DISCRETES CARD ASSEMBLY, M590 (M591) (WDM 73-21-19). REPAIR THE PROBLEMS THAT YOU FIND. FOR THE LEFT ENGINE: CONNECTOR D3622, PIN X1, TO CONNECTOR D2160, PIN 35. FOR THE RIGHT ENGINE: CONNECTOR D3752, PIN X1, TO CONNECTOR D2162, PIN 35. IF THE PROBLEM CONTINUES, EXAMINE THE CIRCUIT FROM THE L (R) ENGINE EEC DISCRETES CARD ASSEMBLY, M590 (M591); AIR/GROUND RELAY, K167 (K205); TERMINAL BLOCK TB218, YC7 (TB274, YA29); THE L (R) ENG ANTI-ICE CMD RELAY, K2103 (K2104); L (R) ENG CONT IGN IDLE RELAY, K2232 (K2233); TO THE L (R) FLAP/STAB POSITION MODULE, M838 (M840)

REPAIR THE PROBLEMS THAT YOU FIND.

(WDM 73-21-19).

IF THE PROBLEM CONTINUES, DO THIS PROCEDURE: BITE PROCEDURE FOR THE PROXIMITY SWITCH ELECTRONIC UNIT (PSEU) (FIM 32-09-03/101, FIG. 103). 1>2>3>


EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 10)

EFFECTIVITY-AUTO ANTI-ICE

73-21-00

N06

Page 164 Apr 22/99




EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 11)

EFFECTIVITY-AUTO ANTI-ICE

73-21-00

N₀6

Page 165 Apr 22/99



EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 12)

EFFECTIVITY-AUTO ANTI-ICE N05

FROM SHEET 12 (BLOCK 66)

NO

67 OPEN THE CIRCUIT BREAKERS THAT FOLLOW:

11M6, LEFT ENGINE IDLE CONT 11A16,11C2, OR 11T10, ANTI-ICE ENG L

11M33, RIGHT ENGINE IDLE CONT 11C28,11B2, OR 11T19, ANTI-ICE ENG R

34L1, ENG IDLE CONT 11D19, L CONT ENG START 11D2O, R CONT ENG START

DISCONNECT CONNECTOR D10550 (D10552) FROM THE L (R) ENG TAI IDLE RELAY, K785 (K786), ON THE P36 (P37) PANEL (WDM 73-21-19).

CLOSE THE CIRCUIT BREAKERS THAT FOLLOW:

11D19, L CONT ENG START 11D2O, R CONT ENG START

ON THE P36 (P37) PANEL, LOOK FOR 28V DC AT PIN 6 OF CONNECTOR D10550 (D10552). IS 28V DC FOUND?

YES

SEE SHEET 14 (BLOCK 68)

123 EXAMINE THE CIRCUIT FROM THE L (R) ENG TAI IDLE RELAY, K785 (K786), TO THE L (R) CONT ENG START CIRCUIT BREAKERS 11D19 (11D20) (WDM 80-11-11, -21; 73-21-19).

FOR THE LEFT ENGINE: CONNECTOR D10550, PIN 6 AND


FOR THE RIGHT ENGINE: CONNECTOR D10552, PIN 6 AND C1511.

EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 13)

EFFECTIVITY-AUTO ANTI-ICE 73-21-00

N₀5

Page 167 Apr 22/99




EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 14)

EFFECTIVITY-AUTO ANTI-ICE

73-21-00

N07

Page 168 Apr 22/99




EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 15)

EFFECTIVITY-AUTO INTI-ICE

73-21-00

N07

Page 169 Apr 22/99




EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 16)

EFFECTIVITY-AUTO ANTI-ICE

73-21-00

N06

Page 170 Apr 22/99



EICAS Message IDLE DISAGREE or L (R) ENG LOW IDLE Is Shown Figure 111A (Sheet 17)

EFFECTIVITY-AUTO ANTI-ICE

73-21-00

N₀6

Page 171 Apr 22/99

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)


MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 33D4,33D5,34P2,34P3

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

NOTE: THE EICAS MESSAGE "L (R) ENG CONTROL" WILL NOT BE SHOWN WHEN THE ENGINE N2 ROTOR SPEED IS LESS THAN 15%. THE EICAS MESSAGE "L (R) ENG CONTROL" WILL BE SHOWN IF ALL OF THE CONDITIONS THAT FOLLOW OCCUR:

- THE FAILURE THAT CAUSED THE MESSAGE TO BE SHOWN IS NOT CORRECTED
- THE ENGINE N2 ROTOR SPEED IS MORE THAN 15% FOR 60 SECONDS.

EICAS MSG "L (R) ENG CONTROL" DISPLAYED



A LOGIC DIAGRAM (SHEETS 3 AND 4) SHOWS HOW THE EICAS MESSAGE "L (R) ENG CONTROL" IS SET. YOU CAN USE THE LOGIC DIAGRAM TO FIND THE EASIEST FAULT TO CORRECT SO THIS EICAS MESSAGE WILL NOT SHOW.


EICAS Msg L (R) ENG CONTROL Displayed
Figure 112 (Sheet 1)

ALL

73-21-00


N₀6


Page 172 Aug 22/99




EICAS Msg L (R) ENG CONTROL Displayed Figure 112 (Sheet 2)








EICAS Message L(R) ENG CONTROL Logic Diagram Figure 112 (Sheet 3)





EICAS Message L(R) ENG CONTROL Logic Diagram Figure 112 (Sheet 4)

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 33D4, 33D5, 34P2, 34P3

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

NOTE: THE EICAS MESSAGE "L (R) ENG EEC MODE" WILL BE SHOWN IF THE CONDITIONS THAT FOLLOW OCCUR:

- THE FAILURE THAT CAUSED THE MESSAGE TO BE SHOWN IS NOT CORRECTED.
- THE FUEL CONTROL SWITCHES ARE IN THE RUN POSITION FOR 3 MINUTES OR THE N2 ROTOR SPEED IS ABOVE 53% (IDLE).

EICAS MSG "L (R) ENG EEC MODE" **DISPLAYED**

1 DO THE PIMU BITE PROCEDURE (FIM 71-PIMU MESSAGE INDEX, MAKE A LIST OF THE MESSAGES THAT SHOW ON THE PIMU DISPLAY. LOOK FOR THE PIMU MESSAGES THAT FOLLOW: EEC CH-A P2 LINE FAULT (350-22)EEC CH-A LBL 350 BIT 24 (350-24)EEC CH-A T2/P2 PROBE HT (350-24)DOES THE PIMU MESSAGE FOR 350-22 AND 350-24 SHOW BY CHANNEL A ONLY? 1 NO SEE SHEET 2 (BLOCK 2)

10 LOOK FOR THE PIMU MESSAGES THAT FOLLOW: EEC B-CHAN FAIL (350-14)EEC CH-B DEM PLUG INVALID (350-26)EEC CH-B FMU T/M W/A FAIL (351-14)EEC CH-B SVA T/M W/A FAIL (351-15)EEC CH-B B25 T/M W/A FAIL (351-16)EEC CH-B TCC T/M W/A FAIL (351-17)EEC CH-B AOC T/M W/A FAIL (351-18)EEC CH-B FMU TR-CK FAIL (351-19)EEC CH-B SVA TR-CK FAIL (351-20)EEC CH-B B25 TR-CK FAIL (351-21)EEC CH-B TCC TR-CK FAIL (351-22)EEC CH-B AOC TR-CK FAIL (351-23)EEC CH-B LOST POWER (352-29)EEC CH-B LBL 353 BIT 16 (353-16)EEC CH-B PMA FAULT (353-16)CONTINUED ON SHEET 2

20 REFER TO THE PIMU MESSAGE TABLES (FIM 71-PIMU MESSAGE INDEX) AND DO THE CORRECTIVE ACTION FOR THE APPLICABLE MESSAGE(S) AS NECESSARY.

> IF THE PIMU MESSAGE FOR 350-22 AND 350-24 ARE SHOWN BY CHANNEL A ONLY, IT IS POSSIBLE THAT THESE ARE NUISANCE MESSAGES. FOR MORE DATA ON THE POSSIBLE NUISANCE CONDITION, REFER TO THE MAINTENANCE TIP 767 MT 73-4 OR TO THE SERVICE LETTER 767-SL-73-8.

> EICAS Msg L (R) ENG EEC MODE Displayed Figure 113 (Sheet 1)


EFFECTIVITY-ALL

73-21-00

N₀6

Page 176 Aug 22/99


773546



EICAS Msg L (R) ENG EEC MODE Displayed Figure 113 (Sheet 2)

EFFECTIVITY-ALL

73-21-00



EICAS Msg L (R) ENG EEC MODE Displayed Figure 113 (Sheet 3)

EFFECTIVITY-ALL

73-21-00

N07

Page 178 Apr 22/99

///	///////////////////////////////////////	///
/	PW4000 SERIES	/
/	ENGINES	/
11	///////////////////////////////////////	1//

PREREQUISITES

ENGINE POWER MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: **FLUCTUATES** ELECTRICAL POWER IS ON (AMM 24-22-00/201)



POSSIBLE CAUSES:

- 1. BAD 2.9 BLEED VALVE SOLENOID (AMM 75-32-04/401)
- 2. BAD 2.9 BLEED VALVE (AMM 75-32-03/401)
- 3. BAD 2.5 BLEED SYSTEM COMPONENTS
- 4. BAD FUEL METERING UNIT (AMM 73-21-01/401).

FAULT ISOLATION:


YES 1 DO THIS PROCEDURE: PIMU 20 REFER TO THE PIMU MESSAGE BITE PROCEDURE (FIM 71-PIMU TABLES (FIM 71-PIMU MESSAGE INDEX) AND DO THE CORRECTIVE MESSAGE INDEX, FIG. 3). LOOK FOR THE MESSAGES THAT ACTION FOR THE APPLICABLE FOLLOW: MESSAGE(S) AS NECESSARY. EEC CH-A/B FMU TR-CK FAIL (351-19) EEC CH-A/B SVA TR-CK FAIL (351-20) EEC CH-A/B B25 TR-CK FAIL (351-21)EEC CH-A/B FMU FD-BK FAIL (351-24) EEC CH-A/B SVA FD-BK FAIL (351-25)EEC CH-A/B B25 FD-BK FAIL (351-26)EEC CH-A/B STAB SOL W/A FAIL (354-16) EEC CH-A/B STRT SOL W/A FAIL (354-15) EEC CH-A/B PMA PWR SOL SHRT (354-24) EEC CH-A/B FMU T/M W/A FAIL (351-14) EEC CH-A/B SVA T/M W/A FAIL (351-15)EEC CH-A/B B25 T/M W/A FAIL (351-16) EEC A/B-CHAN FAIL (350-14) EEC CH-A/B UNIT FAIL (350-15) DOES ONE OR MORE OF THE ABOVE MESSAGES SHOW? NO SEE SHEET 2 (BLOCK 2)

> **Engine Power Fluctuates** Figure 114 (Sheet 1)

EFFECTIVITY-

73-21-00

N03 Page 179 Aug 22/99




Engine Power Fluctuates Figure 114 (Sheet 2)

EICAS MESSAGE "L (R) ENG EEC C1" DISPLAYED 1>

PREREQUISITES

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



1 > THE EICAS MESSAGE "L (R) ENG EEC C1" IS SET IF THE ENGINES ARE STARTED WHEN THE AIRPLANE IS POWERED BY THE BATTERY. THE PIMU MESSAGE "EEC CH-A/B 28V PERF SOL PWR" IS ALSO SET. NO CORRECTIVE ACTION IS NECESSARY IF THE MESSAGES ARE SET WHILE YOU DO AN ENGINE START WITH ATRPLANE BATTERY POWER.

> EICAS Message L (R) ENG EEC C1 Displayed Figure 115

EFFECTIVITY-ALL

73-21-00

N₀2


Page 180A Aug 22/99 **PREREQUISITES**

///	///////////////////////////////////////	//
/	PW4000 SERIES	/
/	ENGINES	/
11	///////////////////////////////////////	11

EICAS MESSAGE "L (R) ENG EEC C2" DISPLAYED

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)



EICAS Message L (R) ENG EEC C2 Displayed Figure 116

754928

73-21-00

NO4

Page 180B Aug 22/99

///	777777777777777777777777777777777777777	///
/	PW4000 SERIES	/
/	ENGINES	/
111	'//////////////////////////////////////	11

PREREQUISITES

MAKE SURE THESE SYSTEMS WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 6E1,6E2,6L19,6K25,11D7,11D8,111D25,11D26,11M1,11M2, 11M9,11M28,11M29,11M36

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

IDLE RPM IS TOO HIGH OR TOO LOW. (ENGINE RELATED)



DESCRIPTION:

UNUSUAL GROUND IDLE AND/OR FLIGHT IDLE SPEEDS THAT ARE CAUSED BY ENGINE RELATED PROBLEMS.

POSSIBLE CAUSES:

- 1. BAD OR DAMAGED TT2 SIGNAL (AMM 73-21-03/401)
- 2. BAD OR DAMAGED BURNER PRESSURE (PB) SIGNAL (FIM 71-07-00/101)
- 3. START/STABILITY BLEED SYSTEM MALFUNCTION (AMM 75-32-04/401)
- 4. FUEL SCHEDULING SYSTEM (FIM 71-08-00/101).

FAULT ISOLATION:



Idle RPM Is Too High or Too Low (Engine Related)
Figure 117 (Sheet 1)

73-21-00

N05

Page 180C Apr 22/99

FROM SHEET 1 (BLOCK 1) NO YES 2 PIMU BITE PROCEDURE (FIM 71-PIMU MESSAGE INDEX, FIG. 3). LOOK FOR THE PIMU MESSAGES THAT FOLLOW: EEC A/B-CHAN FAIL (350-14) EEC CH-A/B UNIT FAIL (350-15) EEC CH-A/B P-SENSR DISAGREE (350-20) EEC CH-A/B XTRN DIS DISAGREE (350-23)EEC CH-A/B DEM PLUG INVALID (350-26)EEC CH-A/B FMU T/M W/A FAIL (351-14) EEC CH-A/B FMU TR-CK FAIL (351-19)EEC CH-A/B SVA TR-CK FAIL (351-20) EEC CH-A/B B25 TR-CK FAIL (351-21) EEC CH-A/B FMU FD-BK FAIL (351-24)EEC CH-A/B N1 RANGE FAIL (352-14) EEC CH-A/B N2 RANGE FAIL (352-15) EEC CH-A/B T2 RANGE FAIL (352–18) EEC CH-A/B TFUEL HIGH (352-24) EEC CH-A/B N1 CROSS-CK FAIL (353-14)EEC CH-A/B N2 CROSS-CK FAIL (353-15)EEC CH-A/B LBL 353 BIT 27 (353-27) EEC CH-A/B LBL 353 BIT 28 (353-28)EEC CH-A/B OVS SOL W/A FAIL (354-14) EEC CH-A/B STAB SOL W/A FAIL (354-16) EEC CH-A/B PMA PWR SOL SHRT (354-24)

NO

SEE SHEET 3 (BLOCK 3)


32 REFER TO THE PIMU MESSAGE TABLES (FIM 71-PIMU MESSAGE INDEX) AND DO THE CORRECTIVE ACTION FOR THE APPLICABLE MESSAGE(S) AS NECESSARY.

Idle RPM Is Too High or Too Low (Engine Related) Figure 117 (Sheet 2)

EFFECTIVITY-ALL

73-21-00





NON-FREQUENT CAUSES OF THIS PROBLEM IN ALPHABETICAL ORDER	RECOMMENDED CORRECTIVE ACTION
AIRPLANE BLEED SYSTEM MALFUNCTION	REFER TO CHAPTER 21.
LANDING GEAR POSITION, OR FLAP SETTING IS OUT OF ALIGNMENT	REFER TO CHAPTER 27 AND CHAPTER 32. LOOK FOR EICAS RELATED MESSAGES.
MAINTENANCE HISTORY	EXAMINE MAINTENANCE HISTORY.
N2 SIGNAL (PMA)	EXAMINE/REPAIR/REPLACE PMA (AMM 73-21-05/401).

TABLE A

Idle RPM Is Too High or Too Low (Engine Related) Figure 117 (Sheet 3)

EFFECTIVITY-ALL

73-21-00

N₀6

Page 180E Apr 22/99

///	///////////////////////////////////////	///
/	PW4000 SERIES	/
/	ENGINES	/
///	(//////////////////////////////////////	///

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

NO ENGINE LIGHTOFF (FUEL FLOW IS LOW)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)




DESCRIPTION:

AFTER THE FUEL SWITCH IS TURNED ON, THERE IS NO EGT INCREASE IN 20 SECONDS. FUEL FLOW INDICATION IS LOWER THAN EXPECTED.

POSSIBLE CAUSES:

- 1. FUEL PUMP OUTPUT IS NOT SATISFACTORY (AMM 73-11-01/401).
- 2. CONTAMINATION IN ENGINE FUEL METERING SYSTEM (FIM 71-08-00/101, FIG. 103).
- 3. FUEL METERING UNIT IS NOT SATISFACTORY (AMM 73-21-01/401).

FAULT ISOLATION:




No Engine Lightoff (Fuel Flow is Low) Figure 118 (Sheet 1)

EFFECTIVITY-73-21-00 ALL N03 Page 180F Aug 22/99

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.





NON-FREQUENT CAUSES OF THIS PROBLEM IN ALPHABETICAL ORDER	RECOMMENDED CORRECTIVE ACTION
MAINTENANCE	EXAMINE MAINTENANCE RECORD

TABLE A

No Engine Lightoff (Fuel Flow is Low) Figure 118 (Sheet 2)

EFFECTIVITY-ALL

73-21-00

N03

Page 180G Apr 22/99

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)

ENGINE FLAMEOUT (FUEL FLOW IS OK)




DESCRIPTION:

ENGINE FLAMEOUT MAY OCCUR WITH A COMPRESSOR STALL. FUEL FLOW IS CORRECT FOR THE THRUST SETTING.

POSSIBLE CAUSES:

- 1. DAMAGED HPC COMPRESSOR BLADES (AMM 72-00-00/601)
- 2. BAD COMPRESSOR STATOR VANE CONTROL SYSTEM (AMM 75-31-00/601).

FAULT ISOLATION:




Engine Flameout (Fuel Flow Is Ok) Figure 119 (Sheet 1)

EFFECTIVITY-ALL

73-21-00

N03


Page 180H Aug 22/99



NON-FREQUENT CAUSES OF THIS PROBLEM IN ALPHABETICAL ORDER	RECOMMENDED CORRECTIVE ACTION		
FUEL CONTAMINATION	DO ENGINE CHECK 3 - FUEL SYSTEM CONTAMINATION CHECK (FIM 71-08-00/101, FIG. 103).		
MAINTENANCE	EXAMINE MAINTENANCE HISTORY RECORD.		
N2 SIGNAL (PMA/N2)	EXAMINE, REPAIR, OR REPLACE PERMANENT MAGNET ALTERNATOR (AMM 73-21-05/401).		
ELECTRONIC ENGINE CONTROL (EEC) (LESS FREQUENT)	EXAMINE AND REPLACE EEC (AMM 73-21-04/401).		

TABLE A

Engine Flameout (Fuel Flow Is Ok) Figure 119 (Sheet 2)



FUEL FLOW INDICATING SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
COMPUTER - (FIM 31-41-00/101) L EICAS, M10181 COMPUTER - (FIM 31-41-00/101) R ECIAS, M10182				
TRANSMITTER - L ENG FUEL FLOW, M7192		1	416AR, FAN DUCT COWL AND THRUST REVERSER, FUEL DISTRIBUTION VALVE (REF)	73–31–01
TRANSMITTER - R ENG FUEL FLOW, M7192		1	426AR, FAN DUCT COWL AND THRUST REVERSER, FUEL DISTRIBUTION VALVE (REF)	73–31–01

Fuel Flow Indicating System - Component Index Figure 101


EFFECTIVITY-ALL 73-31-00


N01

Page 101 Feb 10/95









Fuel Flow Indicating System - Component Location Figure 102

EFFECTIVITY-ALL

73-31-00

N01

Page 102 Feb 10/95

///	///////////////////////////////////////	//
/	PW4000 SERIES	/
/	ENGINES	/
11	///////////////////////////////////////	//

FUEL PRESSURE INDICATING SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
CIRCUIT BREAKER - L ENG FUEL PRESS, C1415 R ENG FUEL PRESS, C1416 COMPUTER - (FIM 31-41-00/101) L EICAS, M10181 R EICAS, M10182 TRANSMITTER -		1	FLIGHT COMPT, P11 11M7 11M34	*
L ENG FUEL PUMP INTERSTAGE PRESSURE, M7193 R ENG FUEL PUMP INTERSTAGE PRESSURE, M7193	2 2	1 1	416AR, THRUST REVERSER 426AR, THRUST REVERSER	73–33–01 73–33–01

^{*} SEE THE WDM EQUIPMENT LIST


Fuel Pressure Indicating System - Component Index Figure 101

 73-33-00

N01

Page 101 Feb 10/95






FLIGHT COMPARTMENT

Fuel Pressure Indicating System - Component Location Figure 102 (Sheet 1)

EFFECTIVITY-ALL 73-33-00

N01

Page 102 Feb 10/95



ENGINE FUEL PUMP INTERSTAGE PRESSURE TRANSMITTER, M7193



Fuel Pressure Indicating System - Component Location Figure 102 (Sheet 2)

> FWD

EFFECTIVITY
ENGINES PRE-SB 73-32


73-33-00


NO1

Page 103 Aug 22/00

FUEL PUMP (REF)







ENGINE FUEL PUMP INTERSTAGE PRESSURE TRANSMITTER, M7193



Fuel Pressure Indicating System - Component Location Figure 102 (Sheet 3)

EFFECTIVITY-ENGINES POST-SB 73-32 73-33-00

N01

Page 104 Aug 22/00

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED: 11M7,11M34

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IS ON (AMM 24-22-00/201)


ENGINE FUEL PUMP INTERSTAGE PRESSURE INDICATION PROBLEMS



POSSIBLE CAUSES:

- 1. INADEQUATE VOLTAGE FROM INTERSTAGE PRESSURE TRANSMITTER (WDM 73-33-11)
- 2. OPEN CIRCUIT BETWEEN INTERSTAGE PRESSURE TRANSMITTER AND EICAS (WDM 73-33-11)
- 3. BAD FUEL PUMP INTERSTAGE PRESSURE TRANSMITTER (AMM 73-33-01/401).

FAULT ISOLATION:




Engine Fuel Pump Interstage Pressure Indication Problems Figure 103 (Sheet 1)

EFFECTIVITY-ALL

73-33-00

N01

Page 105 May 10/95



Engine Fuel Pump Interstage Pressure Indication Problems Figure 103 (Sheet 2)

EFFECTIVITY-73-33-00 ALL N01 Page 106 May 10/95 BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.



FUEL FILTER BYPASS WARNING SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
COMPUTER - (FIM 31-41-00/101) LEFT EICAS, M10181 COMPUTER - (FIM 31-41-00/101) RIGHT EICAS, M1082 SWITCH - FUEL FILTER DIFFERENTIAL PRESSURE, S1585		2	416AR, 426AR FAN DUCT COWL AND THRUST REVERSER, FUEL PUMP	73-34-01


Fuel Filter Bypass Warning System - Component Index Figure 101


EFFECTIVITY-ALL 73-34-00

N01

Page 101 Feb 10/95







Fuel Filter Bypass Warning System - Component Location Figure 102

EFFECTIVITY-ALL

278859

73-34-00

NO1

Page 102 Feb 10/95

PREREQUISITES

MAKE SURE THIS SYSTEM WILL OPERATE: EICAS (AMM 31-41-00/201)

EICAS MSG "L (R) ENG FUEL FILT" SHOWN


MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION: ELECTRICAL POWER IN ON (AMM 24-22-00/201)



POSSIBLE CAUSES:

- 1. CONTAMINATION IN THE FUEL PUMP FILTER
- 2. UNSATISFACTORY ELECTRICAL CONNECTION AT THE DIFFERENTIAL PRESSURE SWITCH
- 3. BAD DIFFERENTIAL PRESSURE SWITCH

FAULT ISOLATION:



NON-FREQUENT CAUSES OF THIS PROBLEM IN ALPHABETICAL ORDER	RECOMMENDED CORRECTIVE ACTION
FUEL PUMP DISTRESS	EXAMINE/REPLACE FUEL PUMP (AMM 73-11-01/401).
INCORRECT FILTER INSTALLED	REPLACE WITH CORRECT FILTER (AMM 73-11-02/401).
MAINTENANCE	EXAMINE THE MAINTENANCE HISTORY RECORD. TAKE CORRECTIVE ACTION AS NECESSARY.

TABLE A

EICAS Msg L (R) ENG FUEL FILT Shown Figure 103

EFFECTIVITY-73-34-00 ALL N01 Page 103 Apr 22/99