STA	ATION								B0E	ING CARD NO.
TAIL NO.					BOE		G		75-R	
			SAS		767	,			AIRL	INE CARD NO.
DATE				-	TASK C					
SKILL	WORK ARE	EA	RELATED TASK		IN	TERVAL		PHASE	MPD REV	TASK CARD REVISION
ENGIN	ENGIN/S	TRUT							007	DEC 22/07
TAS	SK .		TI	TITLE			STRUCTURAL ILLUSTRATION RE	FERENCE	AP AIRPLAN	PLICABILITY E ENGINE
REPLA	CE	NACELLE	ZONE VENT	SHUTOFF	VALVE				AIN LAN	L LNGINE
									ALL	4000
	ZONES					•	ACCESS PANELS			
410			413AL	415AL						

MECH INSP

MPD ITEM NUMBER

REPLACE THE ENGINE 1 NACELLE ZONE VENTILATION SHUTOFF VALVE.

N75-23-02-4A

THIS CARD IS NOT A SCHEDULED MAINTENANCE TASK. IT IS A COMPONENT CHANGE CARD AND IT IS PROVIDED FOR OPERATOR CONVENIENCE DURING UNSCHEDULED MAINTENANCE ACTIVITIES. SEE APPENDIX A OF THE 767 MAINTENANCE PLANNING DATA (MPD) DOCUMENT, D622T001, FOR A DESCRIPTION OF THE COMPONENT CHANGE CARDS.

- 1. Remove the Nacelle Zone Ventilation Shutoff Valve
 - A. References
 - (1) AMM 36-00-00/201, Pneumatic Power
 - (2) AMM 71-11-04/201, Fan Cowl Panels
 - (3) AMM 71-11-06/201, Core Cowl Panels
 - (4) AMM 78-31-00/201, Thrust Reverser System
 - B. Prepare to Remove the Shutoff Valve
 - (1) For the left engine, open this circuit breaker on the overhead circuit breaker panel, P11, and attach a D0-N0T-CLOSE tag:
 - (a) 11K9, LEFT ENGINE NAC VENT VALVE
 - (2) Remove pneumatic power (AMM 36-00-00/201).
 - (3) Open the left fan cowl panel (AMM 71-11-04/201).

REPLACE NACELLE ZONE VENT SHUTOFF VALVE

N75-23-02-4A 75-R02 PAGE 1 OF 6 APR 22/01

75-R02

AIRLINE CARD NO.

SAS BOEING 767 TASK CARD

MECH INSP

WARNING: DO THE THRUST REVERSER DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE THRUST REVERSER. THE ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURY TO PERSONS OR DAMAGE TO EQUIPMENT.

- (4) Do this procedure: Thrust Reverser Deactivation for Ground Maintenance (AMM 78-31-00/201).
- (5) Open the left core cowl panel (AMM 71-11-06/201).

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 WHEN YOU OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.

- (6) Open the left thrust reverser (AMM 78-31-00/201).
- C. Remove the Shutoff Valve for the Nacelle Zone Ventilation (Fig. 401)
 - (1) Disconnect the electrical connector.
 - (a) Install the protection covers.
 - (2) Disconnect the pneumatic line from the shutoff valve.
 - (a) Install the protection covers.
 - (3) Remove the screws (3) and nut (4) to disconnect the bonding jumper.
 - (4) Remove the clamps (1) which attach the shutoff valve (2) to the ventilation duct for the nacelle zone.
 - (5) Remove the shutoff valve from the engine.
 - (a) Install the protection covers.
- 2. Install the Nacelle Zone Ventilation Shutoff Valve
 - A. Parts

N75-23-02-4A

75-R02

AIRLINE CARD NO.



MECH INSP

АММ			AIPC			
FIG	ITEM	NOMENCLATURE	SUBJECT	FIG	ITEM	
401	2	Valve - Shutoff	75-23-02	10	240	

- B. References
 - (1) AMM 20-10-21/601, Electrical Bonding
 - (2) AMM 36-00-00/201, Pneumatic Power
 - (3) AMM 71-11-04/201, Fan Cowl Panels
 - (4) AMM 71-11-06/201, Core Cowl Panels
 - (5) AMM 78-31-00/201, Thrust Reverser System
- C. Procedure (Fig. 401)
 - (1) Make sure the cotter pin holds the lockpin in the correct position.

NOTE: If you do not install the cotter pin, the lockpin will be pushed. With the lockpin pushed, the valve will be manually locked in the open position.

(2) Put the valve clamps (1) on the duct so that they are on the left and right sides of the installed valve (2).

CAUTION: PUT THE VALVE AS CLOSE TO THE INNER WALL OF THE LEFT THRUST REVERSER AS POSSIBLE. THERE MUST BE SUFFICIENT CLEARANCE BETWEEN THE VALVE AND THE GENERATOR FEEDER CABLES. IF THE VALVE TOUCHES THE GENERATOR FEEDER CABLES, THE CABLES CAN BE DAMAGED AND THE GENERATOR CAN TRIP OFF.

(3) Put the valve (2) as shown in View A.

EFFECTIVITY

REPLACE NACELL

NACELLE ZONE VENT SHUTOFF VALVE

N75-23-02-4A

75-R02

PAGE 3 OF 6 DEC 22/07

75-R02

SAS BOEING TASK CARD

MECH INSP

(a) Adjust the valve position.

Make sure the bottom of the valve is close to the inner wall of the left thrust reverser.

- (b) Point the clamps (1) with the T-bolt out and down.
- (c) Turn the clamp on the flange.
- (d) Tighten the clamp nuts.
- Remove the protection cover from the pneumatic line.
- (5) Connect the pneumatic line to the shutoff valve (2).
 - (a) Tighten the tube nut.
- (6) Remove the protection cover from the electrical connector.
- (7) Connect the electrical connector to the shutoff valve (2).
- (8) Make sure the manual override locking pin is not in the housing.
 - Make sure the cotter pin is installed to hold the manual override locking pin in the open position as shown.
- (9) Connect the bonding jumper from the inner wall of the thrust reverser to the shutoff valve (2) with the screw (3) and nut (4).
- (10) Examine the bonding resistance between the shutoff valve (2) and the inner wall (AMM 20-10-21/601).
 - (a) Make sure the bonding resistance is not more than 0.001 ohms.
- D. Put the Airplane Back to Its Usual Condition
 - (1) Supply pneumatic power (AMM 36-00-00/201).

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 WHEN YOU CLOSE THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.

(2) Close the left thrust reverser (AMM 78-31-00/201).

EFFECTIVITY

REPLACE

NACELLE ZONE VENT SHUTOFF VALVE

N75-23-02-4A

75-R02

PAGE 4 OF 6 DEC 22/04

75-R02

AIRLINE CARD NO.

			TASK CARD	
СН	INSP			
		(3)	Close the left core cowl panel (AMM 71-11-06/201).	
		(4)	Do the activation procedure for the thrust reversers (AMM $78-31-00/201$).	
		(5)	Close the left fan cowl panel (AMM 71-11-04/201).	
		(6)	For the left engine, remove the DO-NOT-CLOSE tag and close circuit breaker on the P11 panel:	se this
			(a) 11K9, LEFT ENGINE NAC VENT VALVE	
- 1				


EFFECTIVITY

SAS



75-R02

AIRLINE CARD NO.



EFFECTIVITY

REPLACE N75-23-02-4A

Nacelle Zone Ventilation Shutoff Valve Installation Figure 401

NACELLE ZONE VENT SHUTOFF VALVE

75-R02

PAGE 6 OF 6 DEC 22/04

ST	ATION							BOE	ING CARD NO.
TAIL NO.				S BO	EIN	G		75-R	03
			SAS &	7	' 67			AIR	LINE CARD NO.
DATE				TASK	CARD				
SKILL	WORK AREA R		RELATED TASK	ELATED TASK INTERVAL			PHASE	MPD REV	TASK CARD REVISION
ENGIN	ENGIN/S	TRUT						007	DEC 22/08
TASK		TITLE	TITLE STRUCTURAL ILLUSTRATION REFERENCE			FERENCE	AIRPLAN	PLICABILITY E ENGINE	
REPLACE INTERCOMP		MPRESSOR (2.5) BLEED ACT	UATOR			712111 27111		
							ALL	4000	
	ZONES					ACCESS PANELS			
410	420		413AL 41	5AL 423AL	425AL				

MECH INSP

MPD ITEM NUMBER

REPLACE THE INTERCOMPRESSOR (2.5) BLEED ACTUATOR.

N75-32-01-4A

THIS CARD IS NOT A SCHEDULED MAINTENANCE TASK. IT IS A COMPONENT CHANGE CARD AND IT IS PROVIDED FOR OPERATOR CONVENIENCE DURING UNSCHEDULED MAINTENANCE ACTIVITIES. SEE APPENDIX A OF THE 767 MAINTENANCE PLANNING DATA (MPD) DOCUMENT, D622T001, FOR A DESCRIPTION OF THE COMPONENT CHANGE CARDS.

- 1. Remove the 2.5 Bleed Valve Actuator
 - A. Equipment
 - (1) Container for fuel
 - B. References
 - (1) AMM 71-11-04/201, Fan Cowl Panels
 - (2) AMM 71-11-06/201, Core Cowl Panels
 - (3) AMM 72-34-03/401, Fan Exit Liner Segments
 - (4) AMM 78-31-00/201, Thrust Reverser System
 - C. Prepare to Remove the 2.5 Bleed-Valve Actuator
 - (1) For the left engine, open these circuit breakers on the overhead circuit breaker panel, P11, and attach the DO-NOT-CLOSE tags:
 - (a) 11L3, L ENG PERF SOL CHAN A
 - (b) 11L4, L ENG PERF SOL CHAN B
 - (2) For the right engine, open these circuit breakers on the overhead circuit breaker panel, P11, and attach the D0-NOT-CLOSE tags:

REPLACE INTERCOMPRESSOR (2.5) BLEED ACTUATOR

N75-32-01-4A 75-R03 PAGE 1 OF 10 NOV 10/97

75-R03

SAS BOEING TASK CARD

MECH	INSP
------	------

- (a) 11L30, R ENG PERF SOL CHAN A
- (b) 11L31, R ENG PERF SOL CHAN B
- (3) Open the left fan cowl panel (AMM 71-11-04/201).

WARNING: DO THE THRUST REVERSER DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE THRUST REVERSER. ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURY TO PERSONS OR DAMAGE TO EQUIPMENT.

- (4) Do this procedure: Thrust Reverser Deactivation for Ground Maintenance (AMM 78-31-00/201).
- (5) Open the left core cowl panel (AMM 71-11-06/201).

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00/201 WHEN YOU OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

- (6) Open the left thrust reverser (AMM 78-31-00/201).
- D. Procedure (Fig. 401)
 - (1) Remove the fan exit liner segment at the 6:30 o'clock position (AMM 72-34-03/401).
 - Remove the 2.5 bleed-valve actuator.
 - (a) Disconnect the EEC electrical connector.
 - Install protection caps on the EEC electrical connector and the receptacle on the 2.5 bleed-valve actuator.

WARNING: MAKE SURE ALL THE SOURCES OF HEAT OR FLAME ARE REMOVED OR EXTINGUISHED BEFORE YOU DISCONNECT THE PRESSURE, RETURN, AND DRAIN LINES.

DO NOT GET FUEL IN YOUR EYES OR ON YOUR SKIN. THE FUEL <u>WARNING</u>: CAN CAUSE INJURY TO YOU.

EFFECTIVITY

REPLACE

INTERCOMPRESSOR (2.5) BLEED ACTUATOR

N75-32-01-4A

75-R03

PAGE 2 OF 10 NOV 10/97

75-R03

AIRLINE CARD NO.

		TASK CARD
1ECH	INSP	<u>'</u>
		(b) Disconnect the drain tube (11), the return tube (10) and the supply tube (9) from the 2.5 bleed-valve actuator (1).
		1) Collect the remaining fuel with the container.
		NOTE: Approximately 1/2 pint (1/4 liter) of fuel will drain from the 2.5 bleed-valve actuator.
		(c) ENGINES POST-PW-SB 75-84;
		Remove the support bracket for the 2.5 bleed-valve actuator with the steps that follow:
		 ENGINES PRE-PW-SB 75-126; Remove the three bolts and nuts which attach the support bracket to the bracket on the Flange E.
		2) ENGINES POST-PW-SB 75-126; Remove the three bolts which attach the support bracket to the bracket on the Flange E.
		 Remove the two bolts which attach the support bracket to the 2.5 bleed-valve actuator.
		4) Remove the support bracket from the engine.
		(d) Remove the cotter pin (3) from the shoulder bolt (2).
		CAUTION: BE CAREFUL WHEN YOU REMOVE THE SHOULDER BOLT. THE SHOULDER BOLT HAS LEFT-HAND THREADS. DAMAGE TO THE SHOULDER BOLT OR THE 2.5 BLEED-VALVE ACTUATOR CAN OCCUR I YOU TURN THE BOLT IN THE INCORRECT DIRECTION.
		(e) Hold the piston shaft hex-head of the 2.5 bleed-valve actuator(1) and remove the shoulder bolt (2).
		(f) Remove the bolts (14) which attach the 2.5 bleed-valve actuato(1) to the intermediate case bulkhead.

EFFECTIVITY

75-R03

SAS BOEING TASK CARD

MECH INSP

MAKE SURE THE CRIMPED LOCKING CUP AND RETAINING NUT DO NOT CAUTION: LOOSEN FROM THE PISTON SHAFT WHEN YOU TURN THE PISTON SHAFT HEX-HEAD. IF THE RETAINING NUT CHANGES POSITION OR LOOSENS, THE INTERNAL ADJUSTMENT OF THE 2.5 BLEED-VALVE ACTUATOR CAN BE CHANGED WHICH CAN CAUSE DAMAGE TO THE 2.5 BLEED-VALVE OR THE ENGINE.

- Turn the hex head of the piston shaft counterclockwise to disengage the internal threads from the rod end clevis.
- Remove the 2.5 bleed-valve actuator (1), forward end first, down through the liner segment section.
- (3) If it is necessary to replace the 2.5 bleed-valve actuator (1), do the steps that follow:
 - (a) Remove the adapters (7, 8) from the supply and return ports.
 - 1) Discard the packings (5, 6).
- (4) Install protection caps to the openings in the 2.5 bleed-valve actuator (1) and to all open line-ends.
- Install the 2.5 Bleed Valve Actuator
 - A. Equipment
 - (1) PWA 85928 Adapter Torque, Pratt & Whitney, East Hartford, Conn.
 - (2) M303, M305, or M307 Bergen Mechanical Crimper Bergen Cable Technologies Inc 170 Gregg St P.O. Box 1300 Lodi, NJ 07644-9982
 - Consumable Materials
 - (1) Engine Oil Aircraft Turbine Engine, Synthetic Base, 475°F Minimum, (P03-001)
 - (2) Lockwire 0.032 inch (0.813 mm) Diameter (P05-289)
 - (3) Ferrule, Safety Cable F30B50, 0.032 in. (0.813 mm) (P05-292) (Optional)

EFFECTIVITY

REPLACE

INTERCOMPRESSOR (2.5) BLEED ACTUATOR

N75-32-01-4A

75-R03

PAGE 4 OF 10 DEC 22/08

	(BOEING
SAS	767
	TASK CARD

MECH INSP

- (4) GO2335 Cable Safety PO5-291 (Optional)
- (5) Paste Antiseize, Molykote P-37 (P06-054)

Parts C.

AMM			AIPC			
FIG	ITEM	NOMENCLATURE	SUBJECT	FIG	ITEM	
401	1 3 5 6	Actuator - 2.5 Bleed Valve Pin - Cotter Packing (0-ring) Packing (0-ring)	75–32–01	05	55 35 10 20	

References

- (1) AMM 70-00-00/201, Standard Practices Engine
- (2) AMM 70-24-05/201, Electrical Harnesses
- (3) AMM 71-11-04/201, Fan Cowl Panels
- (4) AMM 71-11-06/201, Core Cowl Panels
- (5) AMM 72-34-03/401, Fan Exit Liner Segments
- AMM 75-32-01/501, 2.5 Bleed Valve Actuator (6)
- (7) AMM 78-31-00/201, Thrust Reverser System
- Prepare to Install the 2.5 Bleed-Valve Actuator (Fig. 401)
 - Remove the protection caps from the openings in the 2.5 bleed-valve actuator (1) and all open line-ends.
 - (2) If it is necessary to install a new 2.5 bleed-valve actuator, do the steps that follow:
 - (a) Lubricate the new packings (5, 6) with engine oil.
 - (b) Install the new packings (5, 6) on the adapters (7, 8).

Ŀ١	Н	ы	E١	L	Ι.	L١	V.	I	ľ	ľ

75-R03

SAS BOEING TASK CARD

MECH	INSP
------	------

- (c) Install the adapter (7) in the supply port of the 2.5 bleed-valve actuator (1).
 - Tighten the adapter (7) to 110-120 pound-inches (12.4-13.6 newton-meters).
- Install the adapter (8) in the return port of the 2.5 bleed-valve actuator (1).
 - Tighten the adapter (8) to 150-170 pound-inches (16.9-19.2) newton-meters).

F. Procedure

- (1) Install the 2.5 bleed-valve actuator.
 - (a) Lubricate the outer threads of the rod end clevis as follows:
 - 1) ENGINES PRE-PW-SB 75-154; Lubricate the external (OD) threads of the rod end clevis with engine oil (P03-001).
 - 2) ENGINES POST-PW-SB 75-154; Lubricate the external threads of the rod end clevis with Antiseize paste (P06-054).
 - Apply the paste to the entire area of the external threads and to a maximum of 0.250 inch (6.350 mm) more than both ends of the threads.
 - (b) Lubricate the threads of the attaching bolts (13) of the 2.5 bleed-valve actuator (1) with engine oil.

DO NOT TURN THE ROD END CLEVIS. IF YOU TURN THE ROD END CAUTION: CLEVIS, YOU CAN CAUSE DAMAGE TO THE 2.5 BLEED-VALVE LINKAGE.

- (c) Move the piston shaft of the 2.5 bleed-valve actuator (1) in its position on the lubricated rod end clevis.
- Turn the hex head of the piston shaft clockwise until the 2.5 bleed-valve actuator (1) is in position against the intermediate case.

EFFECTIVITY

REPLACE

INTERCOMPRESSOR (2.5) BLEED ACTUATOR

N75-32-01-4A

75-R03

PAGE 6 OF 10 DEC 22/08

75-R03

AIRLINE CARD NO.

		TASK CARD
MECH	INSP	
		(e) Secure the 2.5 bleed-valve actuator (1) to the intermediate case with the bolts (13) and washers (14).
		CAUTION: YOU MUST ADJUST THE TORQUE WRENCH INDICATION FOR THE EFFECT OF THE TORQUE ADAPTER ON THE APPLIED TORQUE (AMM 70-50-00/201). IF TOO MUCH TORQUE IS APPLIED TO THE BOLT, DAMAGE TO THE THREADS OF THE BOLT CAN OCCUR.
		(f) Use the PWA 85928 torque adapter to tighten the bolts (13) to 180–200 pound-inches (20.4–22.6 newton-meters).
		(g) Install the support bracket for the 2.5 bleed-valve actuator with the steps that follow:
		 Lubricate the threads of the attaching bolts of the support bracket, with engine oil.
		2) Install the support bracket to the 2.5 bleed-valve actuator with the two bolts.
		a) Tighten the bolts with your hand.
		3) Align the three bolt holes in the support bracket with the three bolt holes in the bracket on the Flange E.
		4) ENGINES PRE-PW-SB 75-126; Attach the support bracket to the bracket on the Flange E with the three bolts and nuts.
		a) Tighten the nuts with your hand.
		5) ENGINES POST-PW-SB 75-126; Attach the support bracket to the bracket on the Flange E with the three bolts.
		a) Tighten the bolts with your hand.
		6) Tighten the bolts which attach the support bracket to the 2.5 bleed-valve actuator to 65-85 pound-inches (7.3-9.6 newton-meters).
		 a) Safety the bolts with lockwire or safety cable and safety cable ferrule.

EFFECTIVITY

75-R03

SAS BOEING TASK CARD

AIRLINE CARD NO.

MECH	INSP

- 7) Tighten the bolts which attach the support bracket to the bracket on the Flange E to 85-95 pound-inches (9.6-10.7 newton-meters).
- (h) Lubricate the threads of the tube nut of the drain tube (11) with engine oil.
- Connect the drain tube (11) to the 2.5 bleed-valve actuator (1).
 - 1) Hold the adapter and tighten the tube nut to 270-300 pound-inches (30.5-33.9 newton-meters).
- (j) Remove the protection caps from the EEC electrical connector and the receptacle on the 2.5 bleed-valve actuator.

CAUTION: USE THE CORRECT ASSEMBLY PROCEDURE, AND TOOLS, FOR THE HARNESS CONNECTOR INSTALLATION (AMM 70-24-05/201). IF YOU USE THE INCORRECT ASSEMBLY PROCEDURE, OR TOOLS, A DAMAGED OR LOOSE CONNECTOR CAN OCCUR. A LOOSE CONNECTOR PERMITS VIBRATION, WHICH CAUSES THE CONTACTS TO WEAR AND DECREASES THE LIGHTNING PROTECTION.

- (k) Install the W3P15 electrical connector to the 2.5 bleed-valve actuator (AMM 70-24-05/201).
- (2) Adjust the 2.5 bleed-valve actuator (AMM 75-32-01/501).
- (3) Install the fan exit liner segment at the 6:30 o'clock position (AMM 72-34-03/401).
- Return the Aircraft to Its Usual Condition

OBEY THE INSTRUCTIONS IN AMM 78-31-00/201 WHEN YOU CLOSE THE WARNING: THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.

- (1) Close the left thrust reverser (AMM 78-31-00/201).
- (2) Close the left core cowl panel (AMM 71-11-06/201).
- (3) Close the left fan cowl panel (AMM 71-11-04/201).

EFFECTIVITY

REPLACE

INTERCOMPRESSOR (2.5) BLEED ACTUATOR

N75-32-01-4A

75-R03

PAGE 8 OF 10 DEC 22/08

75-R03

AIRLINE CARD NO.

		TASK CARD
MECH INSP		
	(4)	Do the activation procedure for the thrust reversers (AMM 78-31-00/201).
	(5)	For the left engine, remove the DO-NOT-CLOSE tags and close these circuit breakers on the P11 panel:
		(a) 11L3, L ENG PERF SOL CHAN A
		(b) 11L4, L ENG PERF SOL CHAN B
	(6)	For the right engine, remove the DO-NOT-CLOSE tags and close these circuit breakers on the P11 panel:
		(a) 11L30, R ENG PERF SOL CHAN A
		(b) 11L31, R ENG PERF SOL CHAN B


EFFECTIVITY

SAS



75-R03

AIRLINE CARD NO.



BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

STA	ATION								B0E	ING CARD NO.
TAIL NO.				Ø 4	<i>30E</i>		Œ		75-R	05
			SAS		767		_		AIRL	INE CARD NO.
D	PATE		0710							
					TASK C	ARD				
SKILL	WORK ARE	EA	RELATED TASK		IN	TERVAL		PHASE	MPD REV	TASK CARD REVISION
ENGIN	ENGIN/S	TRUT							007	DEC 22/07
TAS	SK .	·	TIT	LE			STRUCTURAL ILLUSTRATION RE	FERENCE	AP AIRPLAN	PLICABILITY E ENGINE
REPLA	CE	NACELLE	ZONE VENT	SHUTOFF	VALVE				AIRPLAN	E ENGINE
									ALL	4000
	ZONES					•	ACCESS PANELS		•	
420			423AL	425AL						

MECH INSP

MPD ITEM NUMBER

REPLACE THE ENGINE 2 NACELLE ZONE VENTILATION SHUTOFF VALVE.

N75-23-02-4B

THIS CARD IS NOT A SCHEDULED MAINTENANCE TASK. IT IS A COMPONENT CHANGE CARD AND IT IS PROVIDED FOR OPERATOR CONVENIENCE DURING UNSCHEDULED MAINTENANCE ACTIVITIES. SEE APPENDIX A OF THE 767 MAINTENANCE PLANNING DATA (MPD) DOCUMENT, D622T001, FOR A DESCRIPTION OF THE COMPONENT CHANGE CARDS.

- 1. Remove the Nacelle Zone Ventilation Shutoff Valve
 - A. References
 - (1) AMM 36-00-00/201, Pneumatic Power
 - (2) AMM 71-11-04/201, Fan Cowl Panels
 - (3) AMM 71-11-06/201, Core Cowl Panels
 - (4) AMM 78-31-00/201, Thrust Reverser System
 - B. Prepare to Remove the Shutoff Valve
 - (1) For the right engine, open this circuit breaker on the overhead circuit breaker panel, P11, and attach a D0-NOT-CLOSE tag:
 - (a) 11L35, RIGHT ENGINE NAC VENT VALVE
 - (2) Remove pneumatic power (AMM 36-00-00/201).
 - (3) Open the left fan cowl panel (AMM 71-11-04/201).

REPLACE NACELLE ZONE VENT SHUTOFF VALVE

N75-23-02-4B 75-R05 PAGE 1 OF 6 APR 22/01

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

75-R05

AIRLINE CARD NO.

SAS BOEING 767 TASK CARD

MECH INSP

WARNING: DO THE THRUST REVERSER DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE THRUST REVERSER. THE ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURY TO PERSONS OR DAMAGE TO EQUIPMENT.

- (4) Do this procedure: Thrust Reverser Deactivation for Ground Maintenance (AMM 78-31-00/201).
- (5) Open the left core cowl panel (AMM 71-11-06/201).

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 WHEN YOU OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.

- (6) Open the left thrust reverser (AMM 78-31-00/201).
- C. Remove the Shutoff Valve for the Nacelle Zone Ventilation (Fig. 401)
 - (1) Disconnect the electrical connector.
 - (a) Install the protection covers.
 - (2) Disconnect the pneumatic line from the shutoff valve.
 - (a) Install the protection covers.
 - (3) Remove the screws (3) and nut (4) to disconnect the bonding jumper.
 - (4) Remove the clamps (1) which attach the shutoff valve (2) to the ventilation duct for the nacelle zone.
 - (5) Remove the shutoff valve from the engine.
 - (a) Install the protection covers.
- 2. Install the Nacelle Zone Ventilation Shutoff Valve
 - A. Parts

75-R05

SAS BOEING
767
TASK CARD

AIRLINE CARD NO.

MECH INSP

АММ			AIPC			
FIG	ITEM	NOMENCLATURE	SUBJECT	FIG	ITEM	
401	2	Valve - Shutoff	75-23-02	10	240	

- B. References
 - (1) AMM 20-10-21/601, Electrical Bonding
 - (2) AMM 36-00-00/201, Pneumatic Power
 - (3) AMM 71-11-04/201, Fan Cowl Panels
 - (4) AMM 71-11-06/201, Core Cowl Panels
 - (5) AMM 78-31-00/201, Thrust Reverser System
- C. Procedure (Fig. 401)
 - (1) Make sure the cotter pin holds the lockpin in the correct position.

NOTE: If you do not install the cotter pin, the lockpin will be pushed. With the lockpin pushed, the valve will be manually locked in the open position.

- (2) Put the valve clamps (1) on the duct so that they are on the left and right sides of the installed valve (2).
- CAUTION: PUT THE VALVE AS CLOSE TO THE INNER WALL OF THE LEFT THRUST REVERSER AS POSSIBLE. THERE MUST BE SUFFICIENT CLEARANCE BETWEEN THE VALVE AND THE GENERATOR FEEDER CABLES. IF THE VALVE TOUCHES THE GENERATOR FEEDER CABLES, THE CABLES CAN BE DAMAGED AND THE GENERATOR CAN TRIP OFF.
- (3) Put the valve (2) as shown in View A.

REPLACE NACELLE ZONE VENT SHUTOFF VALVE

N75-23-02-4B 75-R05 PAGE 3 OF 6 DEC 22/07

75-R05

AIRLINE CARD NO.

			TASK CARD
MECH	INSP		, and the second
			(a) Adjust the valve position.
			NOTE: Make sure the bottom of the valve is close to the inner wall of the left thrust reverser.
			(b) Point the clamps (1) with the T-bolt out and down.
			(c) Turn the clamp on the flange.
			(d) Tighten the clamp nuts.
		(4)	Remove the protection cover from the pneumatic line.
		(5)	Connect the pneumatic line to the shutoff valve (2).
			(a) Tighten the tube nut.
		(6)	Remove the protection cover from the electrical connector.
		(7)	Connect the electrical connector to the shutoff valve (2).
		(8)	Make sure the manual override locking pin is not in the housing.
			(a) Make sure the cotter pin is installed to hold the manual override locking pin in the open position as shown.
		(9)	Connect the bonding jumper from the inner wall of the thrust reverser to the shutoff valve (2) with the screw (3) and nut (4).
		(10)	Examine the bonding resistance between the shutoff valve (2) and the inner wall (AMM $20-10-21/601$).
			(a) Make sure the bonding resistance is not more than 0.001 ohms.
		D. Put	the Airplane Back to Its Usual Condition
		(1)	Supply pneumatic power (AMM 36-00-00/201).
		WARN	ING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 WHEN YOU CLOSE THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.
		(2)	Close the left thrust reverser (AMM 78-31-00/201).

EFFECTIVITY

75-R05

AIRLINE CARD NO.

_			TASK CARD								
ME	CH INSP										
		(3)	Close the left core cowl panel (AMM 71-11-06/201).								
		(4)	Do the activation procedure for the thrust reversers (AMM 78-31-00/201).								
		(5)	Close the left fan cowl panel (AMM 71-11-04/201).								
		(6)	(6) For the right engine, remove the DO-NOT-CLOSE tag and close this circuit breaker on the P11 panel:								
			(a) 11L35, RIGHT ENGINE NAV VENT VALVE								
F	FFECT]	 	DEDLACE NACELLE ZONE VENT SHUTOFE VALVE								
		-	FDEDIALE NATELLE /ONE VENI CHILIALE VALVE								


REPLACE

SAS



75-R05

AIRLINE CARD NO.



EFFECTIVITY

N75-23-02-4B

75-R05

REPLACE

Figure 401

NACELLE ZONE VENT SHUTOFF VALVE

PAGE 6 OF 6 DEC 22/04

STATION
TAIL NO.
DATE

WORK AREA



BOEING CARD NO. 75-404-01-1

AIRLINE CARD NO.

TASK CARD

RELATED TASK INTERVAL SKILL PHASE REV REVISION 005 02000 HRS DEC 22/07 ENGIN | ENGINE 1 10404 APPLICABILITY
ANF ENGINE STRUCTURAL ILLUSTRATION REFERENCE AIRPLANE

OPERATIONAL ENGINE 1 TURBINE CASE COOLING ALL 4000

ACCESS PANELS ZONES

411 415AL 416AR 417AL 418AR

MPD ITEM NUMBER MECH INSP

OPERATIONALLY CHECK THE ENGINE 1 TURBINE CASE COOLING SYSTEM COOLING AIR VALVES AND CONTROL CABLE.

N75-24-00-6A N75-24-00-A

- 1. Do an Inspection of the Linkage for the Turbine Cooling System
 - A. Equipment
 - (1) Positioning bolt Standard hex head bolt No. 8-32, 1.5 inch (38.1 mm) thread of minimum length, commercially available.
 - References В.
 - (1) AMM 71-11-04/201, Fan Cowl Panels
 - (2) AMM 71-11-06/201, Core Cowl Panels
 - (3) AMM 78-31-00/201, Thrust Reverser System
 - Prepare to Do the Inspection of the Linkage
 - (1) Open the fan cowl panels (AMM 71-11-04/201).

WARNING: DO THE THRUST REVERSER DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE THRUST REVERSER. ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURY TO YOU OR DAMAGE TO EQUIPMENT.

- (2) Do this procedure: Thrust Reverser Deactivation for Ground Maintenance (AMM 78-31-00/201).
- (3) Open the core cowl panels (AMM 71-11-06/201).

EFFECTIVITY OPERATIONAL ENGINE 1 TURBINE CASE COOLING N75-24-00-6A 75-404-01-1 PAGE 1 OF 9 DEC 22/07

75-404-01-1

SAS BOEING
767
TASK CARD

AIRLINE CARD NO.

MECH	INSP
------	------

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 WHEN YOU OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.

- (4) Open the thrust reversers (AMM 78-31-00/201).
- D. Do an Inspection of the Linkage for the Turbine Cooling System (Fig. 602)

<u>NOTE</u>: When you do the engine shutdown, the air shutoff valves are in the fully closed position.

- (1) Install the positioning bolt in the positioning bolt hole at the rear of the actuator.
 - (a) While you install the positioning bolt, look at the linkage to make sure it moves freely and each lever arm moves off the closed stop to the open position.
 - (b) Install the positioning bolt a minimum of one inch into the actuator.
- (2) Remove the positioning bolt from the actuator.
 - (a) While you remove the positioning bolt, look at the linkage to make sure it moves freely and the lever arms go back to the fully closed position.
- (3) If the linkage does not operate correctly, repair or replace the linkage as it is necessary.
- E. Put the airplane back to its initial condition

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 WHEN YOU CLOSE THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.

- (1) Close the thrust reversers (AMM 78-31-00/201).
- (2) Close the core cowl panels (AMM 71-11-06/201).
- (3) Close the fan cowl panels (AMM 71-11-04/201).

EFFECTIVITY

OPERATIONAL

ENGINE 1 TURBINE CASE COOLING

N75-24-00-6A

75-404-01-1 PAGE 2 OF 9 DEC 22/00

75-404-01-1

AIRLINE CARD NO.


SAS BOEING
767
TASK CARD


MECH	INSP											
		(4)	Do the activation p	rocedure	for th	ne thrust	reverse	r			
		`	7,	(AMM 78-31-00/201).	i occuui c	101 (1	ic till ust	i cvci sc	•			
EFF	ECTI	VITY —			OPERATIO	NAL	ENGINE 1	TURBINE	CASE	COOL	ING	
					N75-24-0	00-6A	75-404-0	1-1 PA	GE 3	OF	9 MAY	10/91

BOEING 767 TASK CARD

SAS

75-404-01-1 AIRLINE CARD NO.





Turbine Cooling System (Left Side) Figure 601 (Sheet 1)

EFFECTIVITY

OPERATIONAL

ENGINE 1 TURBINE CASE COOLING


N75-24-00-6A

75-404-01-1 PAGE 4 OF 9 MAY 10/95 SAS





75-404-01-1

AIRLINE CARD NO.



PWA 85986 COVERS FOR A REMOVED TVCA DUCT










ENGINES WITH BORESCOPE PLUG



ENGINES WITHOUT BORESCOPE PLUG

Turbine Cooling System (Left Side)
Figure 601 (Sheet 2)

EFFECTIVITY

OPERATIONAL

ENGINE 1 TURBINE CASE COOLING

N75-24-00-6A


75-404-01-1 PAGE 5 OF 9 MAY 10/95


SAS



75-404-01-1

AIRLINE CARD NO.





1 ENGINES WITHOUT PHASE 3

Turbine Cooling System (Right Side) Figure 602 (Sheet 1)


EFFECTIVITY		OPERATIONAL	ENGINE 1 TURB	INE CAS	E C00	LING	
		N75-24-00-6A	75-404-01-1	PAGE	6 OF	9 AUG 1	10/95
	BOEING PROPRIETARY - Copyright () - Unpublished Work -	See title page for deta	ils.			

75-404-01-1


AIRLINE CARD NO.

SAS









Turbine Cooling System (Right Side) Figure 602 (Sheet 2)

EFFECTIVITY

OPERATIONAL

ENGINE 1 TURBINE CASE COOLING

N75-24-00-6A


75-404-01-1 PAGE 7 OF 9 MAY 10/95

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

75-404-01-1

SAS

BOEING 767 TASK CARD



OPERATIONAL

N75-24-00-6A

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

ENGINE 1 TURBINE CASE COOLING

PAGE 8 OF 9 AUG 22/00

75-404-01-1

EFFECTIVITY

₹NGINES WITHOUT PHASE 3


75-404-01-1


101 01 1

SAS


767 TASK CARD

AIRLINE CARD NO.





TCC AIR SHUTOFF VALVES FULLY CLOSED POSITION



TCC AIR SHUTOFF VALVES FULLY OPEN POSITION



Turbine Cooling System (Right Side) Figure 602 (Sheet 4)

EFFECTIVITY ENGINES WITH PHASE 3

OPERATIONAL

ENGINE 1 TURBINE CASE COOLING

N75-24-00-6A

75-404-01-1 PAGE 9 OF 9 AUG 10/95

STATION
TAIL NO.
DATE

MECH INSP



BOEING CARD NO. 75-404-01-2

AIRLINE CARD NO.

WORK AREA RELATED TASK INTERVAL TASK CARD SKILL PHASE REV REVISION 005 02000 HRS DEC 22/07 ENGIN | ENGINE 2 10404 APPLICABILITY
ANF ENGINE STRUCTURAL ILLUSTRATION REFERENCE AIRPLANE **OPERATIONAL** ENGINE 2 TURBINE CASE COOLING ALL 4000 ACCESS PANELS ZONES 421

425AL 426AR 427AL 428AR

MPD ITEM NUMBER

OPERATIONALLY CHECK THE ENGINE 2 TURBINE CASE COOLING SYSTEM COOLING AIR VALVES AND CONTROL CABLE.

N75-24-00-6A N75-24-00-A

- 1. Do an Inspection of the Linkage for the Turbine Cooling System
 - A. Equipment
 - (1) Positioning bolt Standard hex head bolt No. 8-32, 1.5 inch (38.1 mm) thread of minimum length, commercially available.
 - References В.
 - (1) AMM 71-11-04/201, Fan Cowl Panels
 - (2) AMM 71-11-06/201, Core Cowl Panels
 - (3) AMM 78-31-00/201, Thrust Reverser System
 - Prepare to Do the Inspection of the Linkage
 - (1) Open the fan cowl panels (AMM 71-11-04/201).

WARNING: DO THE THRUST REVERSER DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE THRUST REVERSER. ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURY TO YOU OR DAMAGE TO EQUIPMENT.

- (2) Do this procedure: Thrust Reverser Deactivation for Ground Maintenance (AMM 78-31-00/201).
- (3) Open the core cowl panels (AMM 71-11-06/201).

EFFECTIVITY

OPERATIONAL

ENGINE 2 TURBINE CASE COOLING

N75-24-00-6A

75-404-01-2 PAGE 1 OF 9 DEC 22/07

5

75-404-01-2

AIRLINE CARD NO.

SAS BOEING 767 TASK CARD

MECH INSP

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 WHEN YOU OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.

- (4) Open the thrust reversers (AMM 78-31-00/201).
- D. Do an Inspection of the Linkage for the Turbine Cooling System (Fig. 602)

NOTE: When you do the engine shutdown, the air shutoff valves are in the fully closed position.

- (1) Install the positioning bolt in the positioning bolt hole at the rear of the actuator.
 - (a) While you install the positioning bolt, look at the linkage to make sure it moves freely and each lever arm moves off the closed stop to the open position.
 - (b) Install the positioning bolt a minimum of one inch into the actuator.
- (2) Remove the positioning bolt from the actuator.
 - (a) While you remove the positioning bolt, look at the linkage to make sure it moves freely and the lever arms go back to the fully closed position.
- (3) If the linkage does not operate correctly, repair or replace the linkage as it is necessary.
- E. Put the airplane back to its initial condition

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 WHEN YOU CLOSE THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.

- (1) Close the thrust reversers (AMM 78-31-00/201).
- (2) Close the core cowl panels (AMM 71-11-06/201).
- (3) Close the fan cowl panels (AMM 71-11-04/201).

EFFECTIVITY

OPERATIONAL

ENGINE 2 TURBINE CASE COOLING

N75-24-00-6A

75-404-01-2 PAGE 2 OF 9 DEC 22/00

75-404-01-2

AIRLINE CARD NO.

SAS FOEING
767
TASK CARD


MECH	INSP								
			(4)	Do the activation p	rocedure for t	he thrust r	reverser		
			() /	(AMM 78-31-00/201).	roccuure ror e	ne em doe i	C V C 1 O C 1		
	ECTI	vity –			1				
_ EFF	CUI	ATII			OPERATIONAL	ENGINE 2 T	TURBINE CASE	COOLING	
						,			
					N75-24-00-6A	75-404-01-	-2 PAGE 3	OF 9 M	AY 10/91


75-404-01-2

AIRLINE CARD NO.

SAS







Turbine Cooling System (Left Side) Figure 601 (Sheet 1)

EFFECTIVITY

OPERATIONAL

ENGINE 2 TURBINE CASE COOLING


N75-24-00-6A

75-404-01-2 PAGE 4 OF 9 MAY 10/95


75-404-01-2


BOEING SAS

767 TASK CARD AIRLINE CARD NO.



PWA 85986 COVERS FOR A REMOVED TVCA DUCT






LEFT TVBCA VALVE (D)



ENGINES WITH BORESCOPE PLUG



ENGINES WITHOUT BORESCOPE PLUG

Turbine Cooling System (Left Side) Figure 601 (Sheet 2)

EFFECTIVITY

OPERATIONAL

ENGINE 2 TURBINE CASE COOLING

N75-24-00-6A

75-404-01-2 PAGE 5 OF 9 MAY 10/95

767

BOEING TASK CARD


SAS


75-404-01-2

COOLING

OF 9 AUG 10/95

AIRLINE CARD NO.





1 ENGINES WITHOUT PHASE 3

Turbine Cooling System (Right Side) Figure 602 (Sheet 1)


	_			
EFFECTIVITY	OPERATIONAL	ENGINE 2 TURB	INE CAS	SE
E93	N75-24-00-6A	75-404-01-2	PAGE	6

75-404-01-2


AIRLINE CARD NO.

SAS









Turbine Cooling System (Right Side) Figure 602 (Sheet 2)

EFFECTIVITY

OPERATIONAL

ENGINE 2 TURBINE CASE COOLING

N75-24-00-6A


75-404-01-2 PAGE 7 OF 9 MAY 10/95

75-404-01-2

AIRLINE CARD NO.

SAS

BOEING 767 TASK CARD



₹NGINES WITHOUT PHASE 3

N75-24-00-6A


75-404-01-2


PAGE 8 OF 9 AUG 22/00

SAS


BOEING 767 TASK CARD

AIRLINE CARD NO.





TCC AIR SHUTOFF VALVES FULLY CLOSED POSITION



TCC AIR SHUTOFF VALVES **FULLY OPEN POSITION**



Turbine Cooling System (Right Side) Figure 602 (Sheet 4)

EFFECTIVITY ENGINES WITH PHASE 3

OPERATIONAL

ENGINE 2 TURBINE CASE COOLING

N75-24-00-6A 75-404-01-2 PAGE 9 OF 9 AUG 10/95

STA	TION									BOE	ING CARD NO.
TAII	L NO.		•			BOL	F/A	G		75-4	06-01-1
D.	ATE		S	AS			67 CARD			AIR	LINE CARD NO.
SKILL	WORK ARE	Α	REL	ATED TASK			INTERVAL		PHASE	MPD REV	TASK CARD REVISION
ENGIN	ENGINE	1				1C			11212	011	APR 22/05
TAS	К			TI	TLE			STRUCTURAL ILLUSTRATION RE	FERENCE	AF AIRPLAN	PLICABILITY E ENGINE
CHECK	/INSP	2.5	BLEED	VALVE-T	O-ACTU	ATOR LINK	AGE			AIRFLAN	E ENGINE
										ALL	4000
	ZONES							ACCESS PANELS			
411				415AL	416AR	417AL					

MECH INSP MPD ITEM NUMBER

VISUALLY CHECK THE ENGINE 1 2.5 BLEED VALVE-TO-ACTUATOR LINKAGE FOR CONDITION AND SECURITY.

N75-32-00-6A

- 1. Do the Inspection of the Compressor Bleed Control System
 - A. References
 - (1) AMM 71-11-04/201, Fan Cowl Panels
 - (2) AMM 71-11-06/201, Core Cowl Panels
 - (3) AMM 72-34-03/401, Fan Exit Liner Segment
 - (4) AMM 75-32-01/401, 2.5 Bleed Valve Actuator
 - (5) AMM 78-31-00/201, Thrust Reverser System
 - B. Prepare for the Inspection of the Compressor Bleed Control System
 - (1) Open the fan cowl panels (AMM 71-11-04/201).

WARNING: DO THE THRUST REVERSER DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE THRUST REVERSER. THE ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT.

- (2) Do this procedure: Thrust Reverser Deactivation for Ground Maintenance (AMM 78-31-00/201).
- (3) Open the core cowl panels (AMM 71-11-06/201).

CHECK/INSP 2.5 BLEED VALVE-TO-ACTUATOR LINKAGE

N75-32-00-6A 75-406-01-1 PAGE 1 OF 7 NOV 10/97

75-406-01-1

7 7-400-01-

AIRLINE CARD NO.

SAS BOEING 767 TASK CARD

MECH INSP

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00/201 WHEN YOU OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

(4) Open the thrust reversers (AMM 78-31-00/201).

C. Procedure

- (1) Do the inspection of the bleed control system (Fig. 601):
 - (a) Remove the No. 5 segment of the fan exit liner (AMM 72-34-03/401) to get access to the actuator for the 2.5 bleed valve.
 - (b) Examine the 2.5 bleed valve actuator for leakage.
 - 1) If you find leakage, replace the 2.5 bleed valve actuator (AMM 75-32-01/401).
 - (c) Visually examine the linkage assembly of the 2.5 bleed valve through the ports on the bleed exit duct found on each side of the No. 7 case strut.
 - 1) Use a fluorescent white light and mirror to examine the linkage for correct installation of the connecting pins and the condition of the linkage assembly.
 - 2) If the part has worn too much or has some damage which can cause the bleed control system to operate incorrectly, you must replace the part.
 - (d) Visually examine the bellcrank-to-bracket pivot pins for wear or damage (Reference PW SB A75-51) (see Table 601).

<u>NOTE</u>: Make sure the 2.5 bleed valve is in the fully open position.

1) Inspect for missing pivot pins (2 locations). A missing pivot pin in either of the two locations is not permitted. A missing pivot pin would cause the 2.5 bleed to stop functioning, resulting in engine operational problems. A missing pivot pin requires immediate engine removal for repair. Continue in service with a missing pivot pin is not permitted.

EFFECTIVITY

CHECK/INSP

2.5 BLEED VALVE-TO-ACTUATOR LINKAGE

N75-32-00-6A

75-406-01-1 PAGE 2 OF 7 APR 22/05

75-406-01-1

AIRLINE CARD NO.

SAS BOEING
767
TASK CARD

MECH INSP

2) Inspect for a fractured or partly missing center pivot pin. Experience shows that if this pin fractures only a portion of the pin will be missing. Some of the pin will remain and permit the 2.5 bleed to function. An engine with this condition can continue in service for up to 350 hours. If the pin is completely missing or it is obivious the bellcrank is no longer attached to the bellcrank bracket, the engine should be removed immediately for repair.

Inspection Of 2.5 Bleed Pivot Pins TABLE 601										
EXAMINE	RESULTS	DISPOSITION								
Broken pins	0.250 inch (6.350 mm) maximum amount of pin head movement permitted	Continue-in-service limitation of 350 hours. See Alert PW SB PW4ENG A75-51.								

(e) Any amount of wear on the bleed valve or bleed duct is permitted.

NOTE: If there is any sign of wear on the bleed valve or bleed duct, the wear is permitted provided the bleed valve operates normally and there are no 2.5 bleed maintenance messages.

- (f) Install the No. 5 segment of the fan exit liner (AMM 72-34-03/401).
- D. Return the Aircraft to Its Usual Condition

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00/201 WHEN YOU CLOSE THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

- (1) Close the thrust reversers (AMM 78-31-00/201).
- (2) Close the core cowl panels (AMM 71-11-06/201).
- (3) Close the fan cowl panels (AMM 71-11-04/201).

EFFECTIVITY	CHECK/INSP	2.5 BLEED	VALVE-TO-	ACTUATOR	R LINKAGE
	N75-32-00-6A	75-406-01-	1 PAGE	3 OF 7	7 APR 22/05

75-406-01-1

AIRLINE CARD NO.

SAS BOEING 767 TASK CARD


MECH INSP (4) Do the activation procedure for the thrust reversers (AMM 78-31-00/201). **EFFECTIVITY** 2.5 BLEED VALVE-TO-ACTUATOR LINKAGE CHECK/INSP N75-32-00-6A 75-406-01-1 PAGE 4 OF 7 APR 22/05


75-406-01-1

AIRLINE CARD NO.

SAS







Compressor Bleed Control System Inspection Figure 601 (Sheet 1)

EFFECTIVITY

CHECK/INSP

2.5 BLEED VALVE-TO-ACTUATOR LINKAGE

N75-32-00-6A


75-406-01-1 PAGE 5 OF 7 APR 22/05

AIRLINE CARD NO.

75-406-01-1

SAS





L-B5370 (0897)

Compressor Bleed Control System Inspection Figure 601 (Sheet 2)

CHECK/INSP 2.5 BLEED VALVE—TO—ACTUATOR LINKAGE


N75—32—00—6A 75—406—01—1 PAGE 6 OF 7 APR 22/05

BOEING 767

75-406-01-1

AIRLINE CARD NO.





CHECK/INSP

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

N75-32-00-6A

2.5 BLEED VALVE-TO-ACTUATOR LINKAGE

PAGE 7 OF 7 APR 22/05

75-406-01-1

EFFECTIVITY

STA	TION									B0E	ING CAR	D NO.
TAIL	L NO.				\bigcirc	BOE		G		75–4	06-0′	1–2
D	ATE		S	AS		767 TASK (7			AIRI	_INE CAR	D NO.
SKILL	WORK ARE	A	RELA	LATED TASK INTERVAL					PHASE	MPD REV	l	SK CARD VISION
ENGIN	ENGINE	2				1 C			11212	011	APR	22/05
TASI	K	•		TI	TLE			STRUCTURAL ILLUSTRATION R	EFERENCE		PLICABI	
CHECK	/INSP	2.5 E	BLEED	VALVE-T	O-ACTUA	TOR LINKA	GE			AIRPLAN	E	ENGINE
										ALL		4000
	ZONES						•	ACCESS PANELS				
421				425AL	426AR	427AL						

MECH INSP MPD ITEM NUMBER

VISUALLY CHECK THE ENGINE 2 2.5 BLEED VALVE-TO-ACTUATOR LINKAGE FOR CONDITION AND SECURITY.

N75-32-00-6A

- 1. Do the Inspection of the Compressor Bleed Control System
 - A. References
 - (1) AMM 71-11-04/201, Fan Cowl Panels
 - (2) AMM 71-11-06/201, Core Cowl Panels
 - (3) AMM 72-34-03/401, Fan Exit Liner Segment
 - (4) AMM 75-32-01/401, 2.5 Bleed Valve Actuator
 - (5) AMM 78-31-00/201, Thrust Reverser System
 - B. Prepare for the Inspection of the Compressor Bleed Control System
 - (1) Open the fan cowl panels (AMM 71-11-04/201).

WARNING: DO THE THRUST REVERSER DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE THRUST REVERSER. THE ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT.

- (2) Do this procedure: Thrust Reverser Deactivation for Ground Maintenance (AMM 78-31-00/201).
- (3) Open the core cowl panels (AMM 71-11-06/201).

CHECK/INSP 2.5 BLEED VALVE-TO-ACTUATOR LINKAGE

N75-32-00-6A 75-406-01-2 PAGE 1 OF 7 NOV 10/97

75-406-01-2

SAS BOEING
767
TASK CARD

AIRLINE CARD NO.

MECH INSP

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00/201 WHEN YOU OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

(4) Open the thrust reversers (AMM 78-31-00/201).

C. Procedure

- (1) Do the inspection of the bleed control system (Fig. 601):
 - (a) Remove the No. 5 segment of the fan exit liner (AMM 72-34-03/401) to get access to the actuator for the 2.5 bleed valve.
 - (b) Examine the 2.5 bleed valve actuator for leakage.
 - 1) If you find leakage, replace the 2.5 bleed valve actuator (AMM 75-32-01/401).
 - (c) Visually examine the linkage assembly of the 2.5 bleed valve through the ports on the bleed exit duct found on each side of the No. 7 case strut.
 - 1) Use a fluorescent white light and mirror to examine the linkage for correct installation of the connecting pins and the condition of the linkage assembly.
 - 2) If the part has worn too much or has some damage which can cause the bleed control system to operate incorrectly, you must replace the part.
 - (d) Visually examine the bellcrank-to-bracket pivot pins for wear or damage (Reference PW SB A75-51) (see Table 601).

<u>NOTE</u>: Make sure the 2.5 bleed valve is in the fully open position.

1) Inspect for missing pivot pins (2 locations). A missing pivot pin in either of the two locations is not permitted. A missing pivot pin would cause the 2.5 bleed to stop functioning, resulting in engine operational problems. A missing pivot pin requires immediate engine removal for repair. Continue in service with a missing pivot pin is not permitted.

EFFECTIVITY

CHECK/INSP

2.5 BLEED VALVE-TO-ACTUATOR LINKAGE

N75-32-00-6A

75-406-01-2 PAGE 2 OF 7 APR 22/05

75-406-01-2

AIRLINE CARD NO.

SAS BOEING TASK CARD

MECH	INSP

2) Inspect for a fractured or partly missing center pivot pin. Experience shows that if this pin fractures only a portion of the pin will be missing. Some of the pin will remain and permit the 2.5 bleed to function. An engine with this condition can continue in service for up to 350 hours. If the pin is completely missing or it is obivious the bellcrank is no longer attached to the bellcrank bracket, the engine should be removed immediately for repair.

	=	2.5 Bleed Pivot Pins ABLE 601
EXAMINE	RESULTS	DISPOSITION
Broken pins	0.250 inch (6.350 mm) maximum amount of pin head movement permitted	Continue-in-service limitation of 350 hours. See Alert PW SB PW4ENG A75-51.

(e) Any amount of wear on the bleed valve or bleed duct is permitted.

If there is any sign of wear on the bleed valve or bleed duct, the wear is permitted provided the bleed valve operates normally and there are no 2.5 bleed maintenance messages.

- Install the No. 5 segment of the fan exit liner (AMM 72-34-03/401).
- Return the Aircraft to Its Usual Condition

OBEY THE INSTRUCTIONS IN AMM 78-31-00/201 WHEN YOU CLOSE THE WARNING: THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

- (1) Close the thrust reversers (AMM 78-31-00/201).
- (2) Close the core cowl panels (AMM 71-11-06/201).
- (3) Close the fan cowl panels (AMM 71-11-04/201).

EFFECTIVITY	CHECK/INSP	2.5 BLEED V	/ALVE-TO-	ACTUAT	OR	LIN	CAGE
	N75-32-00-6A	75-406-01-2	PAGE	3 OF	7	APR	22/05

75-406-01-2

AIRLINE CARD NO.

SAS FOEING
767
TASK CARD


MECH	INSP						
		(4)	Do the activation pr (AMM 78-31-00/201).	ocedure for t	he thrust	reversers	
EFF	ECTI	VITY —		CHECK/INSP	2.5 BLEED	VALVE-TO-ACTUATO	OR LINKAGE
						-2 PAGE 4 OF	


75-406-01-2

AIRLINE CARD NO.

SAS







Compressor Bleed Control System Inspection Figure 601 (Sheet 1)

EFFECTIVITY

CHECK/INSP

2.5 BLEED VALVE-TO-ACTUATOR LINKAGE

N75-32-00-6A


75-406-01-2 PAGE 5 OF 7 APR 22/05

75-406-01-2

AIRLINE CARD NO.

SAS

767 TASK CARD





L-B5370 (0897)


Compressor Bleed Control System Inspection Figure 601 (Sheet 2)

EFFECTIVITY 2.5 BLEED VALVE-TO-ACTUATOR LINKAGE CHECK/INSP N75-32-00-6A 75-406-01-2 PAGE 6 OF 7 APR 22/05

BOEING 767

SAS TASK CARD 75-406-01-2

AIRLINE CARD NO.



CHECK/INSP

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

N75-32-00-6A

2.5 BLEED VALVE-TO-ACTUATOR LINKAGE

PAGE 7 OF 7 APR 22/05

75-406-01-2

EFFECTIVITY

STA	ATION											BOE	ING CARD NO.
TAI	L NO.				1		DEII	NZ	7			75–4	07-01-1
	DATE		SA	AS	X		767					AIRI	LINE CARD NO.
	PATE					TA	SK CAR	D					
SKILL	WORK AR	EA	RELA	TED TASK			INTERVA	AL.			PHASE	MPD REV	TASK CARD REVISION
ENGIN		1				01000	HRS				10202	005	DEC 22/07
TAS		FNCT	NE 4 T	TITL		N V DUCT	•	STR	UCTURAL II	LUSTRATION R	EFERENCE	AF AIRPLAN	PPLICABILITY IE ENGINE
CHECK	C/INSP	ENGI	NE I I	CA AIR S	SUPP	PLY DUCTS	5					ALL	4000
	ZONES								CESS PANEL	S			
411				415AL	416	AR 417/	AL 418A	R					
MECH INSP	,											ı	MPD ITEM NUMBER
ALOH INSP													
							VANE AN			OLING		N75-2	4-02-A
	AIR SU	IPPLY	DUCIS I	FOR GENE	ERAL	. CONDII.	ION AND	SECUR	(11Y.				
EFFFAT													
EFFECT	TATIL					I CHE	CK/INSP	EN	IGINE '	1 TCA AI	R SUPPL	Y DUC	TS

STA	TION											ING CARD NO.
TAI	L NO.					BO	EIA				75–4	07-01-2
			S	AS	XX		767				AIRI	INE CARD NO.
D	ATE		•				CARD)				
SKILL	WORK AR	EA	REL	LATED TASK			INTERVAL			PHASE	MPD REV	TASK CARD REVISION
ENGIN	ENGINE	2				01000 HR	2S			10202	005	DEC 22/07
TAS		_		TITI				STRUCTURAL	ILLUSTRATION RE			PLICABILITY
CHECK	/INSP	ENG]	INE 2 1	TCA AIR S	SUPPLY	DUCTS						
	ZONES							ACCESS PAN	IELS		ALL	4000
421				425AL	426AR	427AL	428AR					
MECH INSP											1	MPD ITEM NUMBER
MECH INSP												
								BLADE C	OOLING		N75-2	4-02-A
	AIR SU	JPPLY	DUCTS	FOR COND	OITION	I AND SEC	CURITY.					
.												
I												
FFFFCT	TVTTV •					OUE OK						

STA	TION	
TAI	L NO.	
	ATE	
	AIL	
SKILL	WORK ARI	EA



BOEING CARD NO. 75-410-01-1

AIRLINE CARD NO.

SKILL	WORK ARE	A RELATED	TASK		INTERVAL		PHASE	MPD REV	TASK CARD REVISION
ENGIN	STRUT 1			2C			12424	005	AUG 22/00
TASK		·	TITLE		STRUCTURAL ILLUSTRATION RE	REFERENCE A		PLICABILITY	
								AIRPLAN	E ENGINE

OPERATIONAL ENGINE COOLING BAROMETRIC SWITCH ALL 4000

ZONES ACCESS PANELS

431 413AL 415AL 417AL 431CT

MPD ITEM NUMBER MECH INSP

OPERATIONALLY CHECK THE ENGINE 1 EXTERNAL ACCESSORIES COOLING SYSTEM BAROMETRIC SWITCH TO CHECK FOR THE SWITCH HAVING FAILED IN THE SEA LEVEL POSITION.

N75-23-00-5A

ENGINE EXTERNAL ACCESSORIES COOLING - ADJUSTMENT/TEST

- 1. System Test Engine External Accessories Cooling
 - A. Equipment
 - (1) Vacuum gage can read an altitude up to 25,000 feet, accurate to ± 50 feet.
 - (2) Vacuum pump can supply a pressure of 10 psig (equivalent to an altitude of 25,000 feet).
 - (3) Air pressure source adjustable from 0 to 40 psi, accurate to ± 5 psi.
 - References В.
 - (1) AMM 24-22-00/201, Electrical Power Control
 - (2) AMM 71-11-04/201, Fan Cowl Panels
 - (3) AMM 71-11-06/201, Core Cowl Panels
 - (4) AMM 78-31-00/201, Thrust Reverser System
 - C. Access
 - (1) Location Zones

L Nacelle Strut 431

R Nacelle Strut

EFFECTIVITY OPERATIONAL ENGINE COOLING BAROMETRIC SWITCH N75-23-00-5A 75-410-01-1 PAGE 1 OF 5 AUG 22/00

AIRLINE CARD NO.

SAS BOEING 767 TASK CARD

MECH INSP

(2) Access Panels

431CT Forward Nacelle Strut Fairing
441CT Forward Nacelle Strut Fairing

- D. Test the Nacelle Ventilation System (Fig. 501)
 - (1) Supply electrical power (AMM 24-22-00/201).
 - (2) Make sure these circuit breakers on the overhead circuit breaker panel P11 are closed:
 - (a) 11U15, LANDING GEAR AIR/GND SYS 1
 - (b) 11U23, LANDING GEAR POSITION AIR/GND SYS 2
 - (3) Make sure the six EICAS circuit breakers are closed.
 - (4) For the left engine, make sure this circuit breaker on the overhead circuit breaker panel P11 is closed:
 - (a) 11K9, LEFT ENGINE NAC VENT VALVE
 - (5) Open the left fan cowl panel (AMM 71-11-04/201).

WARNING: DO THE THRUST REVERSER DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE THRUST REVERSER. ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURY TO YOU OR DAMAGE TO EQUIPMENT.

- (6) Do this procedure: Thrust Reverser Deactivation for Ground Maintenance (AMM 78-31-00/201).
- (7) Open the left core cowl panel (AMM 71-11-06/201).

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 WHEN YOU OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.

- (8) Open the left thrust reverser (AMM 78-31-00/201).
- (9) Open the strut access door 431CT (441CT).

EFFECTIVITY

OPERATIONAL

ENGINE COOLING BAROMETRIC SWITCH

N75-23-00-5A

75-410-01-1 PAGE 2 OF 5 AUG 22/00

AIRLINE CARD NO.

SAS BOEING 767 TASK CARD

MECH INSP

- (10) Attach the vacuum pump line to the vent port on the barometric switch.
- (11) Attach the air supply to the pneumatic line of the nacelle-zone-ventilation-shutoff valve.
- (12) Make sure the nacelle-zone-ventilation-shutoff valve is in the open position.
 - (a) Pneumatic supply and vacuum is not applied to the barometric switch.
- (13) Make sure the nacelle-zone-ventilation-shutoff valve is not manually locked in the open position.
- (14) Make sure the EICAS message, L (R) NAC VENT VAL, does not show on the bottom display.
- (15) Apply a slow and continuous vacuum, to the vent port on the barometric switch, to a maximum altitude of 25,000 feet (standard atmosphere).
 - (a) Make sure the nacelle-zone-ventilation-shutoff valve stays open.
 - (b) Make sure this EICAS message, L(R) NAC VENT VAL, shows on the bottom display.
- (16) Apply a pressure of 35 psig to the pneumatic line on the nacelle-zone-ventilation-shutoff valve.
 - (a) Make sure the nacelle-zone-ventilation-shutoff valve closes.
 - (b) Make sure this EICAS message, L(R) NAC VENT VAL, does not show on the bottom display.
- (17) Slowly and continuously decrease the vacuum to the barometic switch.
 - (a) Make sure the nacelle-zone-ventilation-shutoff valve opens between an altitude of 23,200 and 22,000 feet when you decrease the vacuum.
- (18) Increase the vacuum to an altitude of 25,000 feet.
 - (a) Make sure the nacelle-zone-ventilation-shutoff valve closes between an altitude of 23,300 and 24,500 feet when you increase the vacuum.

EFFECTIVITY

OPERATIONAL

ENGINE COOLING BAROMETRIC SWITCH

N75-23-00-5A

75-410-01-1 PAGE 3 OF 5 AUG 22/00

AIRLINE CARD NO.

SAS FOEING
767
TASK CARD

MECH INSP

- (19) Decrease the vacuum to the vent port on the barometric switch.
- (20) Remove the vacuum line from the vent port on the barometric switch.
- (21) Decrease the pneumatic pressure to zero.
- (22) Remove the air pressure line from the nacelle-zone-ventilation-shutoff valve.
- (23) Connect the pneumatic line to the nacelle-zone-ventilation-shutoff valve with the tube nut.
 - (a) Tighten the tube nut.
- E. Put the airplane back to its initial condition.

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 WHEN YOU CLOSE THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.

- (1) Close the left thrust reverser (AMM 78-31-00/201).
- (2) Close the left core cowl panel (AMM 71-11-06/201).
- (3) Close the left fan cowl panel (AMM 71-11-04/201).
- (4) Close the strut access door 431CT (441CT).
- (5) Do the activation procedure for the thrust reverser (AMM 78-31-00/201).
- (6) Remove electrical power if it is no longer necessary (AMM 24-22-00/201).

EFFECTIVITY

OPERATIONAL

ENGINE COOLING BAROMETRIC SWITCH

N75-23-00-5A


75-410-01-1 PAGE 4 OF 5 AUG 22/00

75-410-01-1

AIRLINE CARD NO.

SAS

767 TASK CARD



STA	TION	
TAI	L NO.	
D	ATE	
SKILL	WORK	AREA



BOEING CARD NO. 75-410-01-2

AIRLINE CARD NO.

TASK CARD

MPD

RELATED TASK INTERVAL PHASE REVISION REV 005 ENGIN | STRUT 2 20 DEC 22/00 12424 APPLICABILITY
ANF ENGINE STRUCTURAL ILLUSTRATION REFERENCE AIRPLANE

OPERATIONAL ENGINE COOLING BAROMETRIC SWITCH ALL 4000

ACCESS PANELS ZONES

441 423AL 425AL 427AL 441CT

MPD ITEM NUMBER MECH INSP

OPERATIONALLY CHECK THE ENGINE 2 EXTERNAL ACCESSORIES COOLING SYSTEM BAROMETRIC SWITCH TO CHECK FOR THE SWITCH HAVING FAILED IN THE SEA LEVEL POSITION.

N75-23-00-5B

ENGINE EXTERNAL ACCESSORIES COOLING - ADJUSTMENT/TEST

- 1. System Test Engine External Accessories Cooling
 - Equipment Α.
 - (1) Vacuum gage can read an altitude up to 25,000 feet, accurate to ± 50 feet.
 - (2) Vacuum pump can supply a pressure of 10 psig (equivalent to an altitude of 25,000 feet).
 - (3) Air pressure source adjustable from 0 to 40 psi, accurate to ± 5 psi.
 - References В.
 - (1) AMM 24-22-00/201, Electrical Power Control
 - (2) AMM 71-11-04/201, Fan Cowl Panels
 - (3) AMM 71-11-06/201, Core Cowl Panels
 - (4) AMM 78-31-00/201, Thrust Reverser System
 - Access
 - (1) Location Zones

L Nacelle Strut 431

R Nacelle Strut

EFFECTIVITY OPERATIONAL ENGINE COOLING BAROMETRIC SWITCH N75-23-00-5B 75-410-01-2 PAGE 1 OF 5 DEC 22/00

AIRLINE CARD NO.

SAS BOEING
767
TASK CARD

MECH INSP

(2) Access Panels

431CT Forward Nacelle Strut Fairing
441CT Forward Nacelle Strut Fairing

- D. Test the Nacelle Ventilation System (Fig. 501)
 - (1) Supply electrical power (AMM 24-22-00/201).
 - (2) Make sure these circuit breakers on the overhead circuit breaker panel P11 are closed:
 - (a) 11U15, LANDING GEAR AIR/GND SYS 1
 - (b) 11U23, LANDING GEAR POSITION AIR/GND SYS 2
 - (3) Make sure the six EICAS circuit breakers are closed.
 - (4) For the right engine, make sure this circuit breaker on the overhead circuit breaker panel P11 is closed:
 - (a) 11L35, RIGHT ENGINE NAC VENT VALVE
 - (5) Open the left fan cowl panel (AMM 71-11-04/201).

WARNING: DO THE THRUST REVERSER DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE THRUST REVERSER. ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURY TO YOU OR DAMAGE TO EQUIPMENT.

- (6) Do this procedure: Thrust Reverser Deactivation for Ground Maintenance (AMM 78-31-00/201).
- (7) Open the left core cowl panel (AMM 71-11-06/201).

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 WHEN YOU OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.

- (8) Open the left thrust reverser (AMM 78-31-00/201).
- (9) Open the strut access door 431CT (441CT).

EFFECTIVITY

OPERATIONAL

ENGINE COOLING BAROMETRIC SWITCH

N75-23-00-5B

75-410-01-2 PAGE 2 OF 5 AUG 22/00

AIRLINE CARD NO.

SAS BOEING
767
TASK CARD

MECH INSP

- (10) Attach the vacuum pump line to the vent port on the barometric switch.
- (11) Attach the air supply to the pneumatic line of the nacelle-zone-ventilation-shutoff valve.
- (12) Make sure the nacelle-zone-ventilation-shutoff valve is in the open position.
 - (a) Pneumatic supply and vacuum is not applied to the barometric switch.
- (13) Make sure the nacelle-zone-ventilation-shutoff valve is not manually locked in the open position.
- (14) Make sure the EICAS message, L (R) NAC VENT VAL, does not show on the bottom display.
- (15) Apply a slow and continuous vacuum, to the vent port on the barometric switch, to a maximum altitude of 25,000 feet (standard atmosphere).
 - (a) Make sure the nacelle-zone-ventilation-shutoff valve stays open.
 - (b) Make sure this EICAS message, L(R) NAC VENT VAL, shows on the bottom display.
- (16) Apply a pressure of 35 psig to the pneumatic line on the nacelle-zone-ventilation-shutoff valve.
 - (a) Make sure the nacelle-zone-ventilation-shutoff valve closes.
 - (b) Make sure this EICAS message, L(R) NAC VENT VAL, does not show on the bottom display.
- (17) Slowly and continuously decrease the vacuum to the barometic switch.
 - (a) Make sure the nacelle-zone-ventilation-shutoff valve opens between an altitude of 23,200 and 22,000 feet when you decrease the vacuum.
- (18) Increase the vacuum to an altitude of 25,000 feet.
 - (a) Make sure the nacelle-zone-ventilation-shutoff valve closes between an altitude of 23,300 and 24,500 feet when you increase the vacuum.

EFFECTIVITY

OPERATIONAL

ENGINE COOLING BAROMETRIC SWITCH

N75-23-00-5B

75-410-01-2 PAGE 3 OF 5 AUG 22/00

AIRLINE CARD NO.

SAS BOEING
767
TASK CARD

MECH INSP

- (19) Decrease the vacuum to the vent port on the barometric switch.
- (20) Remove the vacuum line from the vent port on the barometric switch.
- (21) Decrease the pneumatic pressure to zero.
- (22) Remove the air pressure line from the nacelle-zone-ventilation-shutoff valve.
- (23) Connect the pneumatic line to the nacelle-zone-ventilation-shutoff valve with the tube nut.
 - (a) Tighten the tube nut.
- E. Put the airplane back to its initial condition.

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 WHEN YOU CLOSE THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.

- (1) Close the left thrust reverser (AMM 78-31-00/201).
- (2) Close the left core cowl panel (AMM 71-11-06/201).
- (3) Close the left fan cowl panel (AMM 71-11-04/201).
- (4) Close the strut access door 431CT (441CT).
- (5) Do the activation procedure for the thrust reverser (AMM 78-31-00/201).
- (6) Remove electrical power if it is no longer necessary (AMM 24-22-00/201).

EFFECTIVITY

OPERATIONAL

ENGINE COOLING BAROMETRIC SWITCH

N75-23-00-5B


75-410-01-2 PAGE 4 OF 5 AUG 22/00

75-410-01-2

AIRLINE CARD NO.

SAS Z





STATION	
TAIL NO.	
DATE	\neg

SKILL

WORK AREA



BOEING CARD NO. 75-411-C1-1

AIRLINE CARD NO.

TASK CARD

ENGINE

MPD

AIRPLANE

PHASE

ENGIN ENGINE 1 01000 HRS 10202 012 DEC 22/07
TASK TITLE STRUCTURAL ILLUSTRATION REFERENCE APPLICABILITY

INTERVAL

CHECK/INSP | ENG 1 TCA AND TRC VALVE INDICATORS | ALL NOTE

ZONES ACCESS PANELS

411 415AL 416AR 417AL 418AR

RELATED TASK

MECH INSP MPD ITEM NUMBER

VISUALLY CHECK FOR EXTENSION OF THE POP-UP INDICATOR N7
ON THE ENGINE 1 TURBINE COOLING AIR (TCA) VALVE.

N75-33-00-6N75-33-00-6A N75-33-00-6B

VISUALLY CHECK FOR EXTENSION OF THE POP-UP INDICATOR N75-33-00-6

ENGINE NOTE: SB PW4ENG 75-091, 75-116, AND 75-120

ON THE ENGINE 1 THERMATIC ROTOR CONTROL (TRC) VALVE.

(PRATT AND WHITNEY). APPLICABLE TO PHASE 1 PW4000 ENGINES THAT HAVE NOT INCORPORATED SB 75-91 OR BOTH 75-116 AND 75-120. ALSO APPLICABLE TO PW4000 ENGINES CONVERTED TO PHASE 3 THAT HAVE NOT INCORPORATED

SB 75-121.

1. Do the Inspection of the HPC Secondary Flow Control Valves

A. General

(1) ENGINES WITHOUT PHASE 3 AND PRE-PW-SB 75-91; ENGINES WITHOUT PHASE 3, PRE-PW-SB 75-116 AND PRE-PW-SB 75-120; ENGINES WITHOUT PHASE 3, POST-PW-SB 72-504 AND PRE-PW-SB 75-121: This inspection examines the visual position indicators in the TCA (Turbine Cooling Air) valves and in the TRC (Thermatic Rotor Control) valves. The valves are located on the HPC case.

B. References

- (1) AMM 71-11-04/201, Fan Cowl Panels
- (2) AMM 71-11-06/201, Core Cowl Panels
- (3) AMM 75-24-01/401, Turbine Vane and Blade Cooling Air Valves
- (4) AMM 75-33-01/401, HPC Secondary Flow Control Valve
- (5) AMM 78-31-00/201, Thrust Reverser System

CHECK/INSP ENG 1 TCA AND TRC VALVE INDICATORS

N75-33-00-6A 75-411-C1-1 PAGE 1 OF 7 DEC 22/07

75-411-C1-1

AIRLINE CARD NO.

SAS BOEING 767 TASK CARD

MECH INSP

C. Access

(1) Location Zones

411 Left Engine 421 Right Engine

(2) Access Panels

415AL Fan Reverser (Left) 416AR Fan Reverser (Right) 425AL Fan Reverser (Left) 426AR Fan Reverser (Right)

D. Prepare to Do the Inspection

WARNING: DO THE DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE THRUST REVERSER. THE ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT.

- (1) Do the deactivation procedure for the thrust reverser for ground maintenance (AMM 78-31-00/201).
- (2) Open the fan cowl panels (AMM 71-11-04/201).
- (3) Open the core cowl panels (AMM 71-11-06/201).

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 TO OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

- (4) Open the thrust reversers (AMM 78-31-00/201).
- E. Do the Inspection of the Visual Position Indicators (Fig. 601)

EFFECTIVITY

CHECK/INSP

ENG 1 TCA AND TRC VALVE INDICATORS

N75-33-00-6A

75-411-C1-1 PAGE 2 OF 7 APR 22/05

75-411-C1-1

SAS BOEING
767
TASK CARD

AIRLINE CARD NO.

MECH	INSP
------	------

(1) ENGINES WITHOUT PHASE 3 AND PRE-PW-SB 75-91; ENGINES WITHOUT PHASE 3, PRE-PW-SB 75-116 AND PRE-PW-SB 75-120; ENGINES WITHOUT PHASE 3, POST-PW-SB 72-504 AND PRE-PW-SB 75-121: Examine the position of the visual position indicators in the control valves.

NOTE: Visual position indicators are in the TCA (Turbine Cooling Air) valves and the TRC (Thermatic Rotor Control) valves. The TCA valves are located at the 9:30 and 3:00 o'clock positions on the HPC case. The TRC valves are located at the 9:00 and 3:30 o'clock positions on the HPC case.

NOTE: TCA System: If the position indicator pin is not in the up position, the valve is stuck in the closed position. The valve must be replaced in ten (10) days or less.

NOTE: TRC System: If the position indicator pin is not in the up position, the valve is stuck in the closed position. The valve must be replaced in 500 hours or less.

F. Put the Airplane Back to Its Usual Condition

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 TO CLOSE THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

- (1) Close the thrust reversers (AMM 78-31-00/201).
- (2) Close the core cowl panels (AMM 71-11-06/201).
- (3) Close the fan cowl panels (AMM 71-11-04/201).
- (4) Do the activation procedure for the thrust reversers (AMM 78-31-00/201).

EFFECTIVITY

CHECK/INSP

ENG 1 TCA AND TRC VALVE INDICATORS

N75-33-00-6A


75-411-C1-1 PAGE 3 OF 7 APR 22/05

75-411-C1-1

AIRLINE CARD NO.

SAS






75-411-C1-1

AIRLINE CARD NO.

SAS

POEING 767 TASK CARD

J-411-C1-1




75-411-C1-1

AIRLINE CARD NO.

767

SAS

BOEING TASK CARD




AIRLINE CARD NO.

75-411-C1-1

SAS





STATION	
TAIL NO.	
DATE	\neg

SKILL

WORK AREA



75-411-C1-2

AIRLINE CARD NO.

AIRPLANE

PHASE

TASK CARD

ENGINE

ENGIN ENGINE 2 01000 HRS 10202 012 DEC 22/07
TASK TITLE STRUCTURAL ILLUSTRATION REFERENCE APPLICABILITY

INTERVAL

CHECK/INSP | ENG 2 TCA AND TRC VALVE INDICATORS | ALL NOTE

ZONES ACCESS PANELS

421 425AL 426AR 427AL 428AR

RELATED TASK

MECH INSP MPD ITEM NUMBER

VISUALLY CHECK FOR EXTENSION OF THE POP-UP INDICATOR N75-33-00-6N75-33-00-6A ON THE ENGINE 2 TURBINE COOLING AIR (TCA) VALVE. N75-33-00-6B

VISUALLY CHECK FOR EXTENSION OF THE POP-UP INDICATOR N75-33-00-6 ON THE ENGINE 2 THERMATIC ROTOR CONTROL (TRC) VALVE.

ENGINE NOTE: SB PW4ENG 75-091, 75-116, AND 75-120

(PRATT AND WHITNEY). APPLICABLE TO PHASE 1 PW4000 ENGINES THAT HAVE NOT INCORPORATED SB 75-91 OR BOTH 75-116 AND 75-120. ALSO APPLICABLE TO PW4000 ENGINES CONVERTED TO PHASE 3 THAT HAVE NOT INCORPORATED

SB 75-121.

1. Do the Inspection of the HPC Secondary Flow Control Valves

A. General

(1) ENGINES WITHOUT PHASE 3 AND PRE-PW-SB 75-91; ENGINES WITHOUT PHASE 3, PRE-PW-SB 75-116 AND PRE-PW-SB 75-120; ENGINES WITHOUT PHASE 3, POST-PW-SB 72-504 AND PRE-PW-SB 75-121: This inspection examines the visual position indicators in the TCA (Turbine Cooling Air) valves and in the TRC (Thermatic Rotor Control) valves. The valves are located on the HPC case.

B. References

- (1) AMM 71-11-04/201, Fan Cowl Panels
- (2) AMM 71-11-06/201, Core Cowl Panels
- (3) AMM 75-24-01/401, Turbine Vane and Blade Cooling Air Valves
- (4) AMM 75-33-01/401, HPC Secondary Flow Control Valve
- (5) AMM 78-31-00/201, Thrust Reverser System

CHECK/INSP ENG 2 TCA AND TRC VALVE INDICATORS

N75-33-00-6A 75-411-C1-2 PAGE 1 OF 7 DEC 22/07

75-411-C1-2

AIRLINE CARD NO.



MECH INSP

- C. Access
 - (1) Location Zones

411 Left Engine 421 Right Engine

(2) Access Panels

415AL Fan Reverser (Left) 416AR Fan Reverser (Right) 425AL Fan Reverser (Left) 426AR Fan Reverser (Right)

D. Prepare to Do the Inspection

WARNING: DO THE DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE THRUST REVERSER. THE ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT.

- (1) Do the deactivation procedure for the thrust reverser for ground maintenance (AMM 78-31-00/201).
- (2) Open the fan cowl panels (AMM 71-11-04/201).
- (3) Open the core cowl panels (AMM 71-11-06/201).

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 TO OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

- (4) Open the thrust reversers (AMM 78-31-00/201).
- E. Do the Inspection of the Visual Position Indicators (Fig. 601)

EFFECTIVITY

CHECK/INSP

ENG 2 TCA AND TRC VALVE INDICATORS

N75-33-00-6A

75-411-C1-2 PAGE 2 OF 7 APR 22/05

75-411-C1-2

AIRLINE CARD NO.



MECH INSP

(1) ENGINES WITHOUT PHASE 3 AND PRE-PW-SB 75-91; ENGINES WITHOUT PHASE 3, PRE-PW-SB 75-116 AND PRE-PW-SB 75-120; ENGINES WITHOUT PHASE 3, POST-PW-SB 72-504 AND PRE-PW-SB 75-121: Examine the position of the visual position indicators in the control valves.

NOTE: Visual position indicators are in the TCA (Turbine Cooling Air) valves and the TRC (Thermatic Rotor Control) valves. The TCA valves are located at the 9:30 and 3:00 o'clock positions on the HPC case. The TRC valves are located at the 9:00 and 3:30 o'clock positions on the HPC case.

NOTE: TCA System: If the position indicator pin is not in the up position, the valve is stuck in the closed position. The valve must be replaced in ten (10) days or less.

NOTE: TRC System: If the position indicator pin is not in the up position, the valve is stuck in the closed position. The valve must be replaced in 500 hours or less.

F. Put the Airplane Back to Its Usual Condition

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 TO CLOSE THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

- (1) Close the thrust reversers (AMM 78-31-00/201).
- (2) Close the core cowl panels (AMM 71-11-06/201).
- (3) Close the fan cowl panels (AMM 71-11-04/201).
- (4) Do the activation procedure for the thrust reversers (AMM 78-31-00/201).

EFFECTIVITY

CHECK/INSP

ENG 2 TCA AND TRC VALVE INDICATORS

N75-33-00-6A


75-411-C1-2 PAGE 3 OF 7 APR 22/05

75-411-C1-2

AIRLINE CARD NO.

SAS





N75-33-00-6A

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

75-411-C1-2


PAGE 4 OF 7 NOV 10/95

75-411-C1-2

AIRLINE CARD NO.

SAS

767 TASK CARD




75-411-C1-2

AIRLINE CARD NO.

SAS

767 TASK CARD




BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

75-411-C1-2

AIRLINE CARD NO.

SAS





BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

STATION	
TAIL NO.	
DATE	┑



BOEING CARD NO. 75-412-01-1

AIRLINE CARD NO.

WORK AREA RELATED TASK INTERVAL TASK CARD SKILL PHASE REV REVISION 018 AUG 22/00 ENGIN | ENGINE 1 1C 11212 APPLICABILITY
ANF ENGINE STRUCTURAL ILLUSTRATION REFERENCE AIRPLANE CHECK/INSP ENGINE 1 TCA SOLENOID VALVE ALL NOTE ACCESS PANELS ZONES 411 413AL 414AR 415AL 416AR 417AL 418AR

MECH INSP

FUNCTIONALLY CHECK THE ENGINE 1 TURBINE VANE AND BLADE COOLING AIR (TCA) SOLENOID.

N75-24-00-6B

MPD ITEM NUMBER

ENGINE NOTE: SB PW4ENG 75-091, 75-116, 75-120 AND 75-121

(PRATT AND WHITNEY). APPLICABLE TO PHASE 1 PW4000 ENGINES THAT HAVE NOT INCORPORATED SB 75-91 OR BOTH 75-116 AND 75-120. ALSO APPLICABLE TO PW4000 ENGINES CONVERTED TO PHASE 3 THAT HAVE NOT INCORPORATED SB 75-121.

- A. Equipment
 - (1) Air pressure source adjustable from 100 to 500 psi.
- B. References
 - (1) AMM 71-11-04/201, Fan Cowl Panels
 - (2) AMM 71-11-06/201, Core Cowl Panels
 - (3) AMM 78-31-00/201, Thrust Reverser System
- C. Prepare to do the Inspection of the Turbine Cooling System
 - (1) Open the fan cowl panels (AMM 71-11-04/201).

WARNING: DO THE THRUST REVERSER DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE THRUST REVERSER. ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURY TO YOU OR DAMAGE TO EQUIPMENT.

- (2) Do this procedure: Thrust Reverser Deactivation for Ground Maintenance (AMM 78-31-00/201).
- (3) Open the core cowl panels (AMM 71-11-06/201).

CHECK/INSP ENGINE 1 TCA SOLENOID VALVE

N75-24-00-6B 75-412-01-1 PAGE 1 OF 5 APR 22/99

AIRLINE CARD NO.

		TASK CARD								
MECH	INSP									
		<u>WARNING</u> :	OBEY THE INSTRUCTIONS IN AMM 78-31-00/201 WHEN YOU OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.							
		(4) Open	the thrust reversers (AMM 78-31-00/201).							
		(a)	ENGINES WITHOUT PHASE 3 AND PRE-PW-SB 75-91; ENGINES WITHOUT PHASE 3, PRE-PW-SB 75-116 AND PRE-PW-SB 75-120; ENGINES WITHOUT PHASE 3, POST-PW-SB 72-504 AND PRE-PW-SB 75-121;							
			Do the following functional test of the Turbine Vane and Blade Cooling Air (TVBCA) Valve Soleniod.							
			 The indicators on the TVBCA valves must be extended. If the indicators are not extended, the valves have failed and must be replaced before you continue with the functional inspection. 							
			2) Loosen the tube clamp on the 15th stage air supply tube (AA22) that is closest to the TVBCA valve soleniod.							
			3) Disconnect the 15th stage air supply tube (AA22) from the center connector on the TVBCA valve solenoid.							
			4) Connect a flex hose to the TVBCA valve soleniod at the 15th stage air supply port.							
			a) Use a number 7 Aero-Equip fitting.							
			5) Apply a pressure of 100 - 500 psi (689.5 - 3447.4 kPa) to pressurize the TVBCA valve soleniod.							
			NOTE: Use filtered shop air or a portable pressure bottle.							
			6) While the TVBCA valve soleniod is pressurized, examine the position indicators on the TVBCA valves and make sure they have not retracted (AMM 75-33-00/601).							


AIRLINE CARD NO.


		TASK CARD
MECH	INSP	
		7) If the position indicators are retracted (not fully extended) the TVBCA valve soleniod has failed.
		NOTE: With the TVBCA valve soleniod de-engergized, air should not flow to the TVBCA valve. The position indicators will then be in the extended (not retracted) position.
		a) Refer to PW SB 75-101 for engine disposition.
		8) Remove the flex line from the TVBCA valve soleniod.
		Connect the 15th stage air supply tube (AA22) to the center connector on the TVBCA valve solenoid.
		a) Torque the tube nut to 225 - 250 pound-inches (25.4 - 28.2 newton-meters).
		10) Tighten the tube clamp on the 15th stage air supply tube (AA22) which is closest to the TVBCA soleniod valve.
		D. Return the Aircraft to its Usual Condition
		WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00/201 WHEN YOU CLOSE THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.
		(1) Close the thrust reversers (AMM 78-31-00/201).
		(2) Close the core cowl panels (AMM 71-11-06/201).
		(3) Do the activation procedure for the thrust reverser (AMM 78-31-00/201).
		(4) Close the fan cowl panels (AMM 71-11-04/201).

AIRLINE CARD NO.

SAS







Turbine Cooling System (Left Side)
Figure 601 (Sheet 1)

EFFECTIVITY

CHECK/INSP

ENGINE 1 TCA SOLENOID VALVE


N75-24-00-6B

75-412-01-1 PAGE 4 OF 5 APR 22/99


AIRLINE CARD NO.


SAS






PWA 85986 COVERS FOR A REMOVED TVCA DUCT






LEFT TVBCA VALVE (D)



ENGINES WITH BORESCOPE PLUG



ENGINES WITHOUT BORESCOPE PLUG

Turbine Cooling System (Left Side) Figure 601 (Sheet 2)

EFFECTIVITY

CHECK/INSP

ENGINE 1 TCA SOLENOID VALVE

N75-24-00-6B

75-412-01-1 PAGE 5 OF 5 APR 22/99

STATION	
TAIL NO.	
DATE	\neg

SKILL

WORK AREA



BOEING CARD NO. 75-412-01-2

AIRLINE CARD NO.

N75-24-00-6B

PHASE

TASK CARD

ENGIN ENGINE 2

TASK

TITLE

STRUCTURAL ILLUSTRATION REFERENCE

APPLICABILITY
AIRPLANE
ENGINE

INTERVAL

CHECK/INSP | ENGINE 2 TCA SOLENOID VALVE | ALL NOTE

ZONES ACCESS PANELS

RELATED TASK

421 423AL 424AR 425AL 426AR 427AL 428AR

MECH INSP MPD ITEM NUMBER

FUNCTIONALLY CHECK THE ENGINE 2 TURBINE VANE AND BLADE COOLING AIR (TCA) SOLENOID.

ENGINE NOTE: SB PW4ENG 75-091, 75-116, 75-120 AND 75-121

(PRATT AND WHITNEY). APPLICABLE TO PHASE 1 PW4000 ENGINES THAT HAVE NOT INCORPORATED SB 75-91 OR BOTH 75-116 AND 75-120. ALSO APPLICABLE TO PW4000 ENGINES CONVERTED TO PHASE 3 THAT HAVE NOT INCORPORATED SB 75-121.

- A. Equipment
 - (1) Air pressure source adjustable from 100 to 500 psi.
- B. References
 - (1) AMM 71-11-04/201, Fan Cowl Panels
 - (2) AMM 71-11-06/201, Core Cowl Panels
 - (3) AMM 78-31-00/201, Thrust Reverser System
- C. Prepare to do the Inspection of the Turbine Cooling System
 - (1) Open the fan cowl panels (AMM 71-11-04/201).

WARNING: DO THE THRUST REVERSER DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE THRUST REVERSER. ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURY TO YOU OR DAMAGE TO EQUIPMENT.

- (2) Do this procedure: Thrust Reverser Deactivation for Ground Maintenance (AMM 78-31-00/201).
- (3) Open the core cowl panels (AMM 71-11-06/201).

CHECK/INSP ENGINE 2 TCA SOLENOID VALVE

N75-24-00-6B 75-412-01-2 PAGE 1 OF 5 APR 22/99

AIRLINE CARD NO.



MECH INSP

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00/201 WHEN YOU OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.

- (4) Open the thrust reversers (AMM 78-31-00/201).
 - (a) ENGINES WITHOUT PHASE 3 AND PRE-PW-SB 75-91; ENGINES WITHOUT PHASE 3, PRE-PW-SB 75-116 AND PRE-PW-SB 75-120; ENGINES WITHOUT PHASE 3, POST-PW-SB 72-504 AND PRE-PW-SB 75-121;

Do the following functional test of the Turbine Vane and Blade Cooling Air (TVBCA) Valve Soleniod.

- The indicators on the TVBCA valves must be extended. If the indicators are not extended, the valves have failed and must be replaced before you continue with the functional inspection.
- 2) Loosen the tube clamp on the 15th stage air supply tube (AA22) that is closest to the TVBCA valve soleniod.
- 3) Disconnect the 15th stage air supply tube (AA22) from the center connector on the TVBCA valve solenoid.
- 4) Connect a flex hose to the TVBCA valve soleniod at the 15th stage air supply port.
 - a) Use a number 7 Aero-Equip fitting.
- 5) Apply a pressure of 100 500 psi (689.5 3447.4 kPa) to pressurize the TVBCA valve soleniod.

NOTE: Use filtered shop air or a portable pressure bottle.

6) While the TVBCA valve soleniod is pressurized, examine the position indicators on the TVBCA valves and make sure they have not retracted (AMM 75-33-00/601).

EFFECTIVITY

CHECK/INSP

ENGINE 2 TCA SOLENOID VALVE

N75-24-00-6B

75-412-01-2 PAGE 2 OF 5 AUG 22/00

AIRLINE CARD NO.

SAS BOEING
767
TASK CARD

MECH INSP

7) If the position indicators are retracted (not fully extended) the TVBCA valve soleniod has failed.

NOTE: With the TVBCA valve soleniod de-engergized, air should not flow to the TVBCA valve. The position indicators will then be in the extended (not retracted) position.

- a) Refer to PW SB 75-101 for engine disposition.
- 8) Remove the flex line from the TVBCA valve soleniod.
- Connect the 15th stage air supply tube (AA22) to the center connector on the TVBCA valve solenoid.
 - a) Torque the tube nut to 225 250 pound-inches (25.4 28.2 newton-meters).
- 10) Tighten the tube clamp on the 15th stage air supply tube (AA22) which is closest to the TVBCA soleniod valve.
- D. Return the Aircraft to its Usual Condition

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00/201 WHEN YOU CLOSE THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURY TO PERSONS OR DAMAGE TO EQUIPMENT COULD OCCUR.

- (1) Close the thrust reversers (AMM 78-31-00/201).
- (2) Close the core cowl panels (AMM 71-11-06/201).
- (3) Do the activation procedure for the thrust reverser (AMM 78-31-00/201).
- (4) Close the fan cowl panels (AMM 71-11-04/201).

EFFECTIVITY

CHECK/INSP

ENGINE 2 TCA SOLENOID VALVE


N75-24-00-6B


75-412-01-2 PAGE 3 OF 5 APR 22/99

AIRLINE CARD NO.

SAS







Turbine Cooling System (Left Side)
Figure 601 (Sheet 1)

EFFECTIVITY

CHECK/INSP

ENGINE 2 TCA SOLENOID VALVE

N75-24-00-6B

75-412-01-2 PAGE 4 OF 5 APR 22/99

5


3

0


SAS




AIRLINE CARD NO.





PWA 85986 COVERS FOR A REMOVED TVCA DUCT














ENGINES WITHOUT BORESCOPE PLUG

Turbine Cooling System (Left Side)
Figure 601 (Sheet 2)

EFFECTIVITY

CHECK/INSP

ENGINE 2 TCA SOLENOID VALVE

N75-24-00-6B

75-412-01-2 PAGE 5 OF 5 APR 22/99

STATION
TAIL NO.
DATE

SKILL

WORK AREA



BOEING CARD NO. 75-414-01-1

AIRLINE CARD NO.

TASK CARD

ENGINE

MPD

PHASE

REV REVISION 01000 HRS 018 DEC 22/07 ENGIN | ENGINE 1 10202 STRUCTURAL ILLUSTRATION REFERENCE APPLICABILITY

INTERVAL

AIRPLANE CHECK/INSP ENGINE 1 TCA VALVE INDICATOR **ALL** NOTE

ZONES ACCESS PANELS

411 415AL 416AR 417AL 418AR

RELATED TASK

MPD ITEM NUMBER MECH INSP

VISUALLY CHECK FOR EXTENSION OF THE POP-UP INDICATOR ON THE ENGINE 1 TURBINE COOLING AIR (TCA) VALVES.

N75-33-00-6C

ENGINE NOTE: SB PW4ENG 75-091, 75-116, 75-120 AND 75-121

(PRATT AND WHITNEY). APPLICABLE TO ALL

ORIGINALLY CONFIGURED PHASE 3 PW4000 ENGINES. APPLICABLE TO PHASE 1 PW4000 ENGINES THAT HAVE

INCORPORATED SB 75-91 OR BOTH 75-116 AND 75-120. APPLICABLE TO PW4000 ENGINES CONVERTED TO PHASE 3 THAT HAVE INCORPORATED

SB 75-121. PHASE 3 ENGINES CAN BE

IDENTIFIED BY LOOKING FOR THE DESIGNATION PW40XX(-3) OR PW40XX(-3B) ON THE ENGINE DATA

PLATE.

Do the Inspection of the HPC Secondary Flow Control Valves

General

(1) ENGINES WITH PHASE 3;

This inspection examines the visual position indicators in the TCA (Turbine Cooling Air) valves. The valves are located on the HPC case.

References B.

- (1) AMM 71-11-04/201, Fan Cowl Panels
- (2) AMM 71-11-06/201, Core Cowl Panels
- (3) AMM 75-24-01/401, Turbine Vane and Blade Cooling Air Valves
- (4) AMM 75-24-16/401, Turbine Vane Cooling Air Valve
- (5) AMM 78-31-00/201, Thrust Reverser System

EFFECTIVITY CHECK/INSP ENGINE 1 TCA VALVE INDICATOR N75-33-00-6C 75-414-01-1 PAGE 1 OF 7 DEC 22/07

SAS BOEING TASK CARD

AIRLINE CARD NO.

MECH	INSP

- C. Access
 - (1) Location Zones

Left Engine 411 421 Right Engine

(2) Access Panels

415AL Fan Reverser (Left) 416AR Fan Reverser (Right) 425AL Fan Reverser (Left) 426AR Fan Reverser (Right)

D. Prepare to Do the Inspection

DO THE DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE <u>WARNING:</u> THRUST REVERSER. THE ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT.

- (1) Do the deactivation procedure for the thrust reverser for ground maintenance (AMM 78-31-00/201).
- (2) Open the fan cowl panels (AMM 71-11-04/201).
- (3) Open the core cowl panels (AMM 71-11-06/201).

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 TO OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

- (4) Open the thrust reversers (AMM 78-31-00/201).
- E. Do the Inspection of the Visual Position Indicators (Fig. 601)

EFFECTIVITY

CHECK/INSP

ENGINE 1 TCA VALVE INDICATOR

N75-33-00-6C

75-414-01-1 PAGE 2 OF 7 AUG 22/00

AIRLINE CARD NO.

SAS BOEING
767
TASK CARD

MECH INSP

(1) ENGINES WITH PHASE 3; Examine the position of the visual position indicators in the control valves.

NOTE: Visual position indicators are in the TCA (Turbine Cooling Air) valves located at the 9:30, 2:30, and 3:00 o'clock positions on the HPC case.

(a) If the position indicator pins are not fully extended, replace the defective control valve as it is necessary (AMM 75-24-01/401, 75-24-16/401).

NOTE: If the position indicator pin in the valve is not in the up position, the valve is stuck in the closed position. The valve must be replaced in ten (10) days or less.

F. Put the Airplane Back to Its Usual Condition

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 TO CLOSE THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

- (1) Close the thrust reversers (AMM 78-31-00/201).
- (2) Close the core cowl panels (AMM 71-11-06/201).
- (3) Close the fan cowl panels (AMM 71-11-04/201).
- (4) Do the activation procedure for the thrust reversers (AMM 78-31-00/201).

EFFECTIVITY

CHECK/INSP

ENGINE 1 TCA VALVE INDICATOR


N75-33-00-6C

75-414-01-1 PAGE 3 OF 7 APR 22/05

AIRLINE CARD NO.

SAS

767
TASK CARD



N75-33-00-6C

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.


75-414-01-1

PAGE 4 OF 7 NOV 10/95

AIRLINE CARD NO.

75-414-01-1

BOEING SAS 767 TASK CARD




75-414-01-1

AIRLINE CARD NO.

SAS

BOEING 767 TASK CARD




767 TASK CARD

SAS

75-414-01-1

AIRLINE CARD NO.



STATION
TAIL NO.
DATE

SKILL

WORK AREA



BOEING CARD NO. 75-414-01-2

AIRLINE CARD NO.

TASK CARD

MPD

PHASE

ENGIN ENGINE 2 01000 HRS 10202 018 DEC 22/07
TASK TITLE STRUCTURAL ILLUSTRATION REFERENCE APPLICABILITY

CHECK/INSP ENGINE 2 TCA VALVE INDICATOR

AIRPLANE ENGINE
ALL NOTE

ZONES ACCESS PANELS

421 425AL 426AR 427AL 428AR

MECH INSP MPD ITEM NUMBER

VISUALLY CHECK FOR EXTENSION OF THE POP-UP INDICATOR ON THE ENGINE 2 TURBINE COOLING AIR (TCA) VALVES.

N75-33-00-6C

ENGINE NOTE: SB PW4ENG 75-091, 75-116, 75-120 AND 75-121

(PRATT AND WHITNEY). APPLICABLE TO ALL

ORIGINALLY CONFIGURED PHASE 3 PW4000 ENGINES. APPLICABLE TO PHASE 1 PW4000 ENGINES THAT HAVE

INCORPORATED SB 75-91 OR BOTH 75-116 AND 75-120. APPLICABLE TO PW4000 ENGINES

CONVERTED TO PHASE 3 THAT HAVE INCORPORATED

SB 75-121. PHASE 3 ENGINES CAN BE

IDENTIFIED BY LOOKING FOR THE DESIGNATION PW40XX(-3) OR PW40XX(-3B) ON THE ENGINE DATA

PLATE.

1. Do the Inspection of the HPC Secondary Flow Control Valves

A. General

(1) ENGINES WITH PHASE 3;

This inspection examines the visual position indicators in the TCA (Turbine Cooling Air) valves. The valves are located on the HPC case.

B. References

- (1) AMM 71-11-04/201, Fan Cowl Panels
- (2) AMM 71-11-06/201, Core Cowl Panels
- (3) AMM 75-24-01/401, Turbine Vane and Blade Cooling Air Valves
- (4) AMM 75-24-16/401, Turbine Vane Cooling Air Valve
- (5) AMM 78-31-00/201, Thrust Reverser System

AIRLINE CARD NO.

SAS BOEING
767
TASK CARD

MECH INSP

C. Access

(1) Location Zones

411 Left Engine 421 Right Engine

(2) Access Panels

415AL Fan Reverser (Left) 416AR Fan Reverser (Right) 425AL Fan Reverser (Left) 426AR Fan Reverser (Right)

D. Prepare to Do the Inspection

WARNING: DO THE DEACTIVATION PROCEDURE TO PREVENT THE OPERATION OF THE THRUST REVERSER. THE ACCIDENTAL OPERATION OF THE THRUST REVERSER CAN CAUSE INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT.

- (1) Do the deactivation procedure for the thrust reverser for ground maintenance (AMM 78-31-00/201).
- (2) Open the fan cowl panels (AMM 71-11-04/201).
- (3) Open the core cowl panels (AMM 71-11-06/201).

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 TO OPEN THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

- (4) Open the thrust reversers (AMM 78-31-00/201).
- E. Do the Inspection of the Visual Position Indicators (Fig. 601)

EFFECTIVITY

CHECK/INSP

ENGINE 2 TCA VALVE INDICATOR

N75-33-00-6C

75-414-01-2 PAGE 2 OF 7 AUG 22/00

AIRLINE CARD NO.



MECH INSP

(1) ENGINES WITH PHASE 3; Examine the position of the visual position indicators in the control valves.

NOTE: Visual position indicators are in the TCA (Turbine Cooling Air) valves located at the 9:30, 2:30, and 3:00 o'clock positions on the HPC case.

(a) If the position indicator pins are not fully extended, replace the defective control valve as it is necessary (AMM 75-24-01/401, 75-24-16/401).

NOTE: If the position indicator pin in the valve is not in the up position, the valve is stuck in the closed position. The valve must be replaced in ten (10) days or less.

F. Put the Airplane Back to Its Usual Condition

WARNING: OBEY THE INSTRUCTIONS IN AMM 78-31-00 TO CLOSE THE THRUST REVERSERS. IF YOU DO NOT OBEY THE INSTRUCTIONS, INJURIES TO PERSONS OR DAMAGE TO EQUIPMENT CAN OCCUR.

- (1) Close the thrust reversers (AMM 78-31-00/201).
- (2) Close the core cowl panels (AMM 71-11-06/201).
- (3) Close the fan cowl panels (AMM 71-11-04/201).
- (4) Do the activation procedure for the thrust reversers (AMM 78-31-00/201).

EFFECTIVITY

CHECK/INSP

ENGINE 2 TCA VALVE INDICATOR


N75-33-00-6C

75-414-01-2 PAGE 3 OF 7 APR 22/05

AIRLINE CARD NO.

SAS





N75-33-00-6C

BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

75-414-01-2


PAGE 4 OF 7 NOV 10/95

75-414-01-2

AIRLINE CARD NO.

SAS






AIRLINE CARD NO.

SAS

767 TASK CARD




BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

75-414-01-2

AIRLINE CARD NO.

SAS





BOEING PROPRIETARY - Copyright (C) - Unpublished Work - See title page for details.

	STATI	ON]										BOE	ING CARD NO.	_
	TAIL	NO.					BO	FIA					75–4	15-01-1	
				SA	\S	XX		67					AIRL	INE CARD NO.	-
	DAT	E						CARD							
SKIL	.L	WORK AR	EA	RELAT	ED TASK			INTERVAL			PHA	SE	MPD REV	TASK CARD REVISION	_
		ENGINE	1				1C				112		013	NOV 10/96	,
RF	TASK PLAC	F	FNGTA	JF 1 PS		ITLE FILTERS	3		STRUCTURAL	ILLUSTRATIO	ON REFERENC		AP AIRPLAN	PLICABILITY E ENGINE	
IX.L	LAC		LINGIN	VL 1 13	J AIR	TILILIX							ALL	4000)
41	n	ZONES			416AR				ACCESS PAN	ELS					
41	U				410AK										
MECH	INSP												M	IPD ITEM NUMBER	
					4 50	7 455 0							·	7 05 4	
							YSTEM FIL F & WHITM			F		N	75 −3.	3-05-A	
						000-2-96				_					
EFF	ECTI	VITY					DEDLAS	_	ENGTHE	1 007	ATD	'I TES			_
	1						REPLACE	=	ENGINE	1 PS3	ATK F	LIER	>		
							N75-33-	-05-A	75-415	-01-1	PAGE	1 0	F 1	NOV 10/96	,

	STATI	ON									BOE	ING CARD NO.
	TAIL	NO.					BO	EIN			75-4	15-01-2
	DAT	E	-	S	SAS		7	67			AIR	LINE CARD NO.
							TASK	CARD				
SKII	LL	WORK AR	REA	RE	LATED TASK			INTERVAL		PHASE	MPD REV	TASK CARD REVISION
	TASK	ENGINE	2		TI.	TLE	1 C		STRUCTURAL ILLUSTRATION F	11212	013	NOV 10/96
			INE 2	PS3 AIR		6				AIRPLAN		
		ZONES							ACCESS PANELS		ALL	4000
42	0				426AR							
	1											MPD ITEM NUMBER
MECH	INSP										'	MPD ITEM NUMBER
EFF	ECTI	VITY					REPLACE	Ē	ENGINE 2 PS3 A	IR FILTE	RS	

N75-33-05-A 75-415-01-2 PAGE 1 OF 1 NOV 10/96