

Important

Model: GP605

GP555

Ref. No. : FF-T01-K1-000083-01

Date : April 27, 2002

GP605P

© Canon (UK) Limited

Location: Pick-up Tray PCB Assembly

Subject: Preventing Damage to the Pre-Last Original Sensor

Reason: If the slide guide lock of the ADF has been removed, the contact plate (5V) operating in conjunction with the slide guide can cause a short circuit between the pattern of sensor LED (mounted on the pickup tray PCB) and the pattern of photo elements, ultimately damaging the pre-last original sensor (S8; FG6-2782-000).

Detail: <Symptom>

The pre-last original sensor suffers damage.

<Cause>

If the slide guide lock has been removed, the contact plate operating in conjunction with the slide guide can cause a short circuit between the pattern of sensor LED (mounted on the pickup tray PCB) and the pattern of photo elements.

<Factory Measure>



The pattern of the pickup tray PCB is changed so that the contact plate will not cause it to short circuit even in the absence of the slide guide lock.

<Identifying the Pickup Tray PCB with the Measure>

Refer to the parts number silk-screened on the PCB. Keep in mind, however, that the silk-screened parts number is different from the service parts number given to the pickup tray PCB.

PCB w/o measure: on the surface, FG2-9367; on the back, FH12447

PCB w/ measure: on the back, FG3-3025, FH13481



Servicing Work:

If you have to remove the slide guide lock, be sure to replace it with a pickup tray PCB provided with the said measure.

Points to Note When Servicing:

If the pickup tray PCB is of the old type, be sure not to remove the slide guide lock.

Service Parts:

No.	Description		Part number	Q'ty	Stock	Inter-change-ability	PC.
							Stock date
1	Old	PICK-UP TRAY PCB ASSEMBLY	FG6-2783-000	1→0	C	<div> <div>↓</div> <div>No</div> </div> <div> <div>↑</div> <div>Yes</div> </div>	91
	New	PICK-UP TRAY PCB ASSEMBLY	FG6-2807-000	0→1	D		Mid of June

Affected Machines:

To be communicated as soon as identified.