

---

**Model:**

iR C6800C  
iR C6800CN

**Ref No.:**

F2-T01-0M3-10028-01

**Date:**

July 16, 2004

Issued by Canon (UK) Limited

**Revised:**

---

**Location:**

iR C6800/6800N SystemSoftwareVer6.03

**Subject:**

Release of iR C6800/6800N System Software(Ver.6.03) / Language(Ver.6.03) / Remote UI(Ver.6.02) / Dcon(Ver.8.02) / Rcon(Ver.9.02)/ BootROM (Ver.21.01)

**Reason:**To Release Dcon Software along with the production approval of iR C6800/6800N

<System CD-ROM ID No.>

FY9-4194-001

T-1

<History of Updates>

Service Info.No. / System CD-ROM ID No.	Ver.No.							Details of Changes
	System	Language	RUI	Boot ROM	Dco n	Rcon	FAX	

- / FY9-4194-0001	6.03	6.03	6.02	21.01	8.02	9.02	WLD-51-02 (120V)	<p>1)[FAX]Support of fax function (120V)</p> <p>2)[PRINT] The machine locks when the job is canceled with UFR printing</p> <p>3)[UserMode] PDL automatic selection not supported for 230V machine</p> <p>4)[PRINT] Printing trouble with NSA environment was corrected.</p> <p>5)[PRINT]Modification of the failure for "Booklet" job with "Add Cover" in D1-Controller .</p> <p>6)[PRINT] Blank in center when using Saddle Stitch function (imagePASS-C1 TR# 59)</p> <p>7)[PRINT]Modification of the failure when printed using "Booklet" function in D1-Controller</p> <p>8)[FAX] It is corrected that the error page is not printed when received data was an error.</p> <p>9)[Service Mode] Modification of failure when toner mixture execution process is executed in the mode other than Standby mode</p> <p>10)[Service Mode] Completion display of toner mixture execution process</p>
F2-T01-0M3-10021-01 / -	-	-	-	-	7.02	-	-	1)For field problem
F2-T01-0M3-10016-01 / -	-	-	-	-	-	8.01	-	1)For field problem
F2-T01-0M1-10023-01 / FY9-4194-000	5.03	5.03	1.33	21.01	6.01	21.01	-	1)FirstRelease

-Accessory Version

- Fin-R1:5.10 or later version
- Fin-R2 Stacker:5.10 or later version
- Saddle:4.07 or later version
- Punch:3.04 or later version

**Contents:**

iR C6800/6800N provides features below:

- COPY feature
- BOX feature
- PRINT feature UFR/PS/PCL
- SEND feature
- FAX feature(120V Only)

**1. Changes made by the version upgrade from System V5.03 to V6.03**

T-2

<Added Item>

No.	Items	Contents
1	[FAX]Support of fax function (120V)	From this version, only 120V devices are supported the fax function.

T-3

<Fixed Item>

No.	Items	Contents
2	[PRINT]The machine locks wen the job is canceled with UFR printing	When the cancellation of the job was executed on the machine with UFR printing, the machine locked unusually. It was corrected that the job was correctly canceled.
3	[UserMode]PDL automatic selection not supported for 230V machine.	PDL automatic selection is set to be supported for 230V machine. 'Auto' of 'Personality'is deleted the default is set to PCL. PDL automatic selection is set to be supported for 230V machine. 'Auto' of 'Personality' is deleted and the default is set to PCL.
4	[PRINT]Printing trouble with NSA enviroment was corrected.	There was a trouble that the machine locks while receiving data in the environment with NetSpotAccountant client of 30 or more. Processing was not correctly done when there were two or more accesses in the event delivery table that iRC3100 internally had at the same time. It was corrected so that it was correctly processed.
5	[PRINT]Modification of the failure for "Booklet" job with "Add Cover" in D1-Controller .	In D1-Controller , "Booklet" job with "Add Cover" is not output, but it is cancelled.This failure was corrected. *D1-Controller=imagePASS-1/ColorNetworkPrinterUnit-D1

6	[PRINT] Blank in center when using Saddle Stitch function (imagePASS-C1 TR# 59)	In the print job, when you print using Saddle Stitch setting, not using Booklet setting, Service mode of the following setting (blank in center) does not reflect correctly. This failure was corrected. -COPIER->OPTION->ACC->STPL-LMT -SORTER->OPTION->BLNK-SW
7	[PRINT]Modification of the failure when printed using "Booklet" function in D1-Controller	In D1-Controller , when using "Booklet" function, and color and black are printed on the same saide, yellow mixes on the black color. This failure was corrected. *D1-Controller=imagePASS-D1/ColorNetworkPrinterUnit-D1
8	[FAX]It is corrected that the error page is not print when receive data was an error.	Although the page that had made an error when the fax was received was printed with previous version , the error page is not printed with current version.
9	[Service Mode] Modification of failure when toner mixture execution process is executed in the mode other than Standby mode	When the toner mixture execution process (COPIER/FUNCTION/INSTALL -> TONER-S, INISET-Y/M/C/3) is executed in the mode other than Standby mode, the display is to be "NG". * This setting will be valid in the same timing as DconV8.02 upgrading.
10	[Service Mode] Completion display of toner mixture execution process	Toner mixture execution process (COPIER/FUNCTION/INSTALL -> TONER-S, INISET-Y/M/C/3) is to be completed with "OK" or "NG" display.

**1. Changes made by the version upgrade from Language V5.03 to V6.03**

T-4

No	Items	Contents
1	Upgrade versions	Language files are to be upgraded concurrently with System version upgrade.

**1. Changes made by the version upgrade from RUI V1.33 to V6.02**

T-5

<Fixed Item>

No	Items	Contents
1	[UserMode]PDL automatic selection not supported for 230V machine.	PDL automatic selection is set to be supported for 230V machine. 'Auto' of 'Personality'is deleted the default is set to PCL.

**1. Changes made by the version upgrade from Dcon V7.02 to V8.02**

T-6

&lt;Fixed Item&gt;

No	Items	Contents
1	[User Mode] Modification of failure for Saddle Stitcher Staple Repositioning operation	Saddle Stitcher Staple Repositioning function in User mode is not executed even though Start key is pressed. This failure was corrected.
2	[Service Mode] Modification of failure when toner mixture execution process is executed in the mode other than Standby mode	When the toner mixture execution process (COPIER/FUNCTION/INSTALL -> TONER-S, INISET-Y/M/C/3) is executed in the mode other than Standby mode, the display is to be "NG". * This setting will be valid in the same timing as SystemV6.03 upgrading.

**1. Changes made by the version upgrade from Rcon V8.01 to V9.02**

T-7

&lt;Fixed Item&gt;

No	Items	Contents
1	Modification of failure when using a reflection type size sensor for Inch-configuration model	In Inch-configuration model, if you perform the reflection type size sensor, LGL and LTR cannot be detected. This failure was corrected. * Reflection type size sensor = This is an individual correspondence for the claim that the scanning lamp is too bright when executing size detection using its CCD.

**When you upgrade the version of the system, please note...**

- Items to be initialized:

When the system is version-upgraded, it is overridden. The set values of the user mode and service mode are retained. As a result, no items are to be initialized. The version of service support tool used here: Version 1.63E.(Latest version is v2.03E)

- When you upgrade the version of Dcon/Rcon/G3FAX, cycling down the power of the device is required after you succeed in the upgrading.

- **Please do the upgrade to SystemV6.03 and DconV8.02 at the same time.**

**If you do not upgrade at the same time, the toner mixture execution process (COPIER/FUNCTION/INSTALL -> TONER-S, INISET-Y/M/C/3) will not be able to be executed.**

**Version Configurations:**The operating guarantee of the iR C6800 is undertaken for the following combinations:

T-8

<iRC6800Software version>

System	Language	Boot ROM	RUI	Rcon	Dcon	ALL / ALL_HDF	FAX	Finisher R1/R2	Saddle	Punch
<b>6.03</b>		21.01	<b>6.02</b> 1.33	<b>9.02</b> 8.01 7.01	<b>8.02</b> 7.02 6.01	<b>6.03</b>	WLD -51- 02	5.10	4.07	4.03 3.04

**Remarks:**

1.Specification below are deferred:

T-9

<Specification Deferred>

No.	Items	Contents
1	During copying/printing or standby,alignment behavior occurs	This is required to keep the quality of images.
2	Scan data cannot be sent after saved in BOX.	Scan data cannot be sent as color devices treat them as scan document.
3	SST's effect is not remarkable.	It cannot be more effective due to the potentiality because of being 600dpi.

2.Supported version of User Software are as below:

T-10

<User Software>

User Software	Version	
	First release	Latest version
UFR Driver	V1.21	V1.21
PS Printer Driver for Windows	V2.22	V2.22
PS Printer Driver for Macintosh(PPD)	V1.40	V1.40
PCL Printer Driver for Windows	PCL5e/5c V6.31 PCL6 V4.30	PCL5e/5c V6.31 PCL6 V4.30

FAX Driver	-	V3.50 *scheduled at the end of July
NetSpot Console	V3.00	V3.10
NetSpot Resource Downloader	V2.0	V2.0
NetSpot Device Installer	V3.00(r3.03)	V3.01(r3.04)
Address Book Coverion Utility	V1.01	V1.01
Canon LPR	V2.11	V2.11
Canon Device Status Extension	V1.20	V1.20
Color Network ScanGear	V1.30	V1.40
Canon NDPS gateway	V1.20	V1.20

**Future Release:**

The release of next version is scheduled at the end of September

**Affected Machine:**

It informs of the machine number later.

**Special Note:**

1. There is no fear of infection about the computer virus that exploits the vulnerability of Windows been disclosed by the Microsoft company because Color imageRUNNER Series uses OS different from Windows.
- 2.SEND feature has function to acquire the device information(Address Book) using the encryption module(LDAP).This encryption module has an export restriction,and is forbidden to export countries below:  
Iran,Iraq,NorthKorea,Cuba,Sudan,Syria and Libya

\*LDAP(Light weight Directory Access Protocol) operates the search and update from the client to the server.It enhances the security of the communication using the encryption process,SSL(Secure Socket Layer).SSL is a method to encryption the network path.