


Agilent Wide Range DC Current Biased Inductance Measurement

Application Note 369-8

Agilent 4284A Precision LCR Meter
Agilent 42841A Bias Current Source



Introduction

A large number of switching power supply inductors with extended high frequency characteristics have recently been developed. The reason for this is the increase in the switching frequency to reduce size of switching power supplies which are being built using electronic components which are more compact than are conventional components. However, if components which are not suitable for high frequency are used, the increase in the frequency lowers the efficiency of the switching power supply and creates electrical noise. Consequently, lower noise components and circuits for use at higher frequencies must be developed for future switching power supply designs.

Inductors are one of the easiest components to reduce in size by raising the frequency and will require the development of low-loss, low leakage cores. The development and production of such inductors requires dc current biased inductance measurements to evaluate the inductance characteristics under actual operating conditions.

This application note describes dc current biased inductance measurements that are more accurate and made over a wider frequency range than was previously possible.



Agilent Technologies

Problems concerning dc current biased inductance measurements

Dc current biased inductance measurements involve the following problems.

- Measurement preparations and procedures are time-consuming
- An external bias circuit is required
 - Setting and confirming current values are troublesome
 - Automation of measurement procedures is difficult
 - Safety problems
- Frequency range is insufficient
- Not enough bias current can be generated
- Measurement accuracy is not guaranteed

Solutions offered by the Agilent 4284A and Agilent 42841A

The 4284A precision LCR meter (with Option 4284A-002 current bias interface) in combination with the 42841A bias current source ensures simple and safe dc current biased inductance measurements. The 4284A allows for dc current biased inductance measurements with the following advantages.

- Wide 20 Hz to 1 MHz frequency range measurements
- Dc current biased inductance measurements up to 40 A using two the 42841As,
- Basic accuracy of 1%
- List sweep function for bias sweep measurements of up to 10 points
- The bias current is easily set using the 4284A's front panel keys or by using an external controller via GPIB.
- The 42842A/B bias current test fixtures which protect the operator and instrument are provided.
- Built-in memory function and a removable memory card for storing instrument setups

Measurement Preparation

Accessories required

When dc current biased inductance measurements are made using an 4284A, the accessories required depend on the maximum bias current to be used. Table 1 is a list of what accessories are required. Figures 1, 2, and 3 show the external appearance of the 42842A bias current test fixture, the 42843A bias current cable and the 16048A test leads.

Table 1. Measurement instruments

Instruments	Max. bias current	
	20 A	40 A
LCR meter	4284A (with Option 4284A-002)	4284A (with Option 4284A-002)
Bias current source	42841A	Two 42841A units
Bias current test fixture	42842A	42842B ¹
Bias current cable	Not required	42843A
Test leads	16048A	16048A




Figure 1. 42842A bias current test fixture




Figure 2. 42843A bias current cable




Figure 3. 16048A test leads

1. 42842B can be used for 20 A dc current biased measurements


Connections

The table shows which accessories are to be connected for maximum bias currents of 20 A and 40 A. The 42841A is connected to the 4284A by plugging in the provided interface cable. The 4284A uses the 16048A test leads for connection to the 42842A/B. Two 42841A units have to be connected parallel when making bias current measurement up to 40 A. (See Figure 4)


The 42842A/B are equipped with a voltage monitor terminal for connecting a digital voltmeter (DVM) to monitor the bias voltage applied to the device under test directly. Only a DVM with an input impedance of 10 M Ω or more should be connected to the voltage monitor terminal, since the output monitor has 10 k Ω resistance. The dc resistance (DCR) of the device under test can be derived from this bias voltage measurement according to the following formula.

$$DCR = \frac{V_{MON}}{I_{BIAS}} - 3 \times 10^{-3} [\Omega]$$

V_{MON} is the bias voltage measurement value (unit is V), I_{BIAS} is the bias current (unit is A) setup value and the $3 \times 10^{-3} [\Omega]$ in the formula is the residual DCR of the fixture. Refer to 'Appendix A' for information on the accuracy of DCR measurements using this method.



(a) 20 A



(b) 40 A

Figure 4. Measurement configuration

Measurement safety

Large dc current biased measurements have to be conducted with utmost care. The spike voltages caused by accidental removal of the device under test from the measurement terminals while a dc biased current is applied are particularly hazardous. If current exceeding the rating is run through a device under test (DUT), the heat generated may cause a fire or smoke. Following precautions should be taken when dc current biased measurements are being made.

- The bias current must be switched off before the DUT is disconnected.
- Make sure that the test leads between the DUT and the LCR meter are securely connected to prevent accidental disconnections.
- Check at all times that not too much current is put through the DUT to prevent abnormally high temperatures. (Check for heat or smoke.)
- The bias current must be turned off after a bias sweep operation is made with the list sweep function. (If the bias current is not turned off, the last bias current sweep value will continue to flow through the DUT.)

The 42842A is provided with the following safety features.

- Components are automatically discharged when the protective cover is opened, to ensure the safety of the operator while disconnecting a DUT.
- Transparent protective covers are used to facilitate monitoring the DUT during a measurement.
- Protective circuits are built in to prevent damage to the LCR meter from voltage spikes.
- The bias current is automatically cut off if the temperature in the fixture becomes abnormally high (i.e. 200 °C in the DUT and 70 °C at the measuring terminal.)

Compensation

Since the residual impedance caused by the 42841A is negligible, no compensation is required for normal inductance measurements. However, when measuring devices with an inductance lower than 10 μ H use the 4284A's short compensation function to reduce errors.

Measurement Results

The purpose of measuring the dc current biased inductance of inductors is to derive the current rating from the measured inductance versus dc current biased (L-IDC) characteristics. The current rating is defined as the value of the bias current when the inductance is decreased by 10% (or 30% to 50%).

The 4284A can measure L-IDC characteristics and the measurements can be easily automated by using an GPIB interface and the bias sweep function (list sweep) are used. Actual measurement examples and the information required for such measurements are given in the following paragraphs.

L-IDC characteristics measured with the list sweep function

The list sweep function of the 4284A can be used to sweep up to 10 bias current points. Figure 5 shows the rough L-IDC characteristics and the rated current. The 4284A automatically waits until the bias current has settled (settling time) at the specified current value before starting a measurement. Since the meter waits for the optimum moment to start ordinary measurements or list sweep measurements, the settling time need not be considered when the bias current is changed. Consequently, measurements are always made after the bias current has settled.

However, temporary discrepancies in the measured values result after bias current changes during measurement of the device that are slow to respond to changes in the bias current. This occurs when transient response of the device is longer than the settling time of 4284A. A suitable delay time should be set with the 4284A to compensate for this.

Always make sure to turn off the bias current to ensure that no current is flowing through the DUT after a bias sweep operation.

Measurements of L-IDC characteristics using an external controller

Since bias current values can be controlled by an external GPIB controller when the 42841A bias current source is used together with the 4284A, it is possible to perform L-IDC measurements automatically. Furthermore, the wide measurement frequency range of 4284A makes it possible to check the L-IDC characteristics per frequency as shown in Figure 6. The result shown in Figure 6 shows that there are differences in the L-IDC characteristics depending on the frequency used. The program (running on an HP 9000 series 300 computer) used to conduct these measurements is described in 'Appendix B'.

Measurements up to 40 A

Dc current biased inductance measurements up to 40 A require the use of two 42841A units. Figure 7 shows the measured L-IDC characteristics when dc current bias up to 40 A is used.

<LIST SWEEP DISPLAY>				SYS MENU
MODE : SEQ				
BIAS [A]	Ls [H]	Rs []	CMP	
100 . 00m	544 . 933u	0 . 11931		
200 . 00m	545 . 282u	0 . 11863		
500 . 00m	544 . 529u	0 . 11723		
1 . 000	538 . 915u	0 . 11503		
2 . 000	522 . 914u	0 . 11138		
5 . 000	444 . 466u	0 . 09126		
10 . 000	330 . 656u	0 . 06747		
12 . 000	296 . 950u	0 . 06206		
15 . 000	258 . 190u	0 . 05593		
20 . 000	213 . 129u	0 . 04150		

Figure 5. Measurement result using the list sweep function




Figure 6. Frequency characteristics of L-IDC

Conclusion

The 4284A equipped with the Option 4284A-002 and the 42841A bias current source will permit highly accurate and efficient dc current biased inductance measurements up to the 1 MHz frequency range. All of these combine to promote the development and production of high frequency switching power supply inductors.




Figure 7. Measurement results up to 40 A

Appendix A. Accuracy of DCR Measurements (Typical Values)

Accuracy of DCR measurements are as follows.
Here I_{BIAS} is the bias current set value.

When $I_{BIAS} \leq 1$ A

$$\pm \left\{ \left(1.2 + \frac{0.5}{I_{BIAS}} \right) \% + \frac{5}{I_{BIAS}} \text{ m}\Omega \right\}$$

When $1 \text{ A} < I_{BIAS} \leq 5 \text{ A}$

$$\pm \left\{ 2.2\% + \frac{0.5}{I_{BIAS}} \text{ m}\Omega \right\}$$

When $I_{BIAS} > 5$ A

$$\pm \left\{ 3.2\% + \frac{5}{I_{BIAS}} \text{ m}\Omega \right\}$$

Note that the input impedance of the DVM must be more than $10 \text{ M}\Omega$.

Appendix B. Sample Program List

```

1000 DIM XP ( 100, 20 ), Yp (100, 20 )           !
1010 DIM Work$ [100]                           !
1020 DIM Bias (200), Freq (20) ,A(200, 20) ,B (200, 20) !
1030 DIM Xyz (3 )                             !
1040 DIM Axis (3, 3) ,Axis$ (3) [10]          !
1050                                           !
1060 Agt4284a=717                             ! Address of 4284A
1070 ASSIGN @Work TO "WORK"                   ! Assign I/O path to store data
1080 Min_bias=0                               ! Min. bias value is 0A
1090 Max_bias=20                             ! Max. bias value is 20A
1100 Step_bias=1                             ! Step of bias sweep
1110 READ Nfreq                               ! read number of frequency
1120 FOR Ifreq=1 TO Nfreq                     !
1130     READ Freq(Ifreq)                     ! read meas. frequency
1140 NEXT Ifreq                               !
1150 Nbias=(Max_bias-Min_bias)/Step_bias+1    ! calc. number of bias points
1160 IF Nbias>200 THEN STOP                   ! check number of bias points
1170 FOR Ibias=1 TO Nbias                     !
1180     Bias(Ibias)=Min_bias+Step_bias*(Ibias-1) ! set bias value
1190 NEXT Ibias                               !
1200                                           ! << 4284A initialization>>
1210 OUTPUT Agt4284a;"TRIG:SOUR BUS"          ! Trigger mode is Bus trigger
1220 OUTPUT Agt4284a;"FUNC:IMP LSRS"         ! Meas function is Ls-Rs
1230 OUTPUT Agt4284a;"INIT:CONT ON"          !
1240 OUTPUT Agt4284a;"DISP:PAGE MEAS"        ! Display page is Meas. page
1250 OUTPUT Agt4284a;"INIT"                 ! Initialize
1260 OUTPUT Agt4284a;"BIAS:STAT ON"          ! Bias ON
1270                                           ! <<Meas. routine>>
1280 FOR Ifreq=1 TO Nfreq                     ! Freq. sweep loop <-----+
1290     OUTPUT Agt4284a;"FREQ "&VAL$(Freq(Ifreq)) !
1300     FOR Ibias=1 TO Nbias                 ! Top of bias. sweep loop <-----+
1310         OUTPUT Agt4284a;"BIAS : CURR " &VAL$ (Bias (Ibias ) ) ! Set bias
1320         OUTPUT Agt4284a;"*TRG"          ! Triggering
1330         ENTER Agt4284a;Work$           ! Enter Meas. data
1340         A(Ibias,Ifreq)=VAL(work$[1,12]) !
1350     NEXT Ibias                           ! Bottom of bias loop <-----+
1360 NEXT Ifreq                               ! Bottom of freq. loop <-----+
1370 OUTPUT Agt4284a;"BIAS:STAT OFF"          ! Bias OFF
1380 OUTPUT @work;Nfreq,Nbias                 ! Store meas. condition
1390 FOR Ifreq=1 TO Nfreq                     !
1400     FOR Ibias=1 TO Nbias                 !
1410         OUTPUT @work;A(Ibias,Ifreq)     ! Store meas. data
1420     NEXT Ibias                           !
1430 NEXT Ifreq                               !
1440                                           ! <<Graphic initialize>>
1450 CLEAR SCREEN                             ! Clear screen
1460 GOSUB Trans_init                         ! Initialize Trans subroutine
1470 WINDOW -2,2,-2,2                        ! Set graphic window
1480 GOSUB Axis                               ! Draw axes
1490 Amax=MAX(A(*))                           ! Find max. value of meas. data
1500 FOR Ifreq=1 TO Nfreq                     ! <<Calc. graphic data>>
1510     FOR Ibias=1 TO Nbias                 !
1520         Xyz(1)=LOG(Freq(Ifreq))/LOG(Freq(Nfreq)) !
1530         Xyz(2)=Bias(Ibias)/Bias(Nbias)       !
1540         Xyz(3)=A(Ibias,Ifreq)/Amax           !
1550     GOSUB Trans                           ! Make graphic data of 3D
1560     Xp (Ibias,Ifreq)=Xyz(1)               !
1570     Yp (Ibias,Ifreq)=Xyz(2)               !
1580     NEXT Ibias                           !
1590 NEXT Ifreq                               !

```

```

1600 MOVE Xp(1,1),Yp(1,1)
1610 FOR Ifreq=1 TO Nfreq
1620     FOR Ibias=1 TO Nbias
1630         DRAW Xp(Ibias,Ifreq),Yp(Ibias,Ifreq)
1640     NEXT Ibias
1650     MOVE Xp(1,Ifreq+1),Yp(1,Ifreq+1)
1660 NEXT Ifreq
1670 MOVE Xp(1,1),Yp(1,1)
1680 FOR Ibias=1 TO Nbias
1690     FOR Ifreq=1 TO Nfreq
1700         DRAW Xp(Ibias,Ifreq),Yp(Ibias,Ifreq)
1710     NEXT Ifreq
1720     MOVE Xp(Ibias+1,1),Yp(Ibias+1,1)
1730 NEXT Ibias
1740 STOP
1750
1760 Trans_init:
1770 Xd=.5
1780 Yd_1
1790 RETURN
1800
1810 Trans:
1820 Xxx=Xyz (1)
1830 Xyz (1)=Xyz (2) - Xxx*Xd
1840 Xyz (2)=Xyz (3) - Xxx*Yd
1850 RETURN
1860
1870 Axis:
1880 Axis$(1)="FREQ."
1890 Axis$(2)="BIAS"
1900 Axis$(3)="INDUCTANCE"
1910 MAT Axis= (0)
1920 FOR Iax=1 TO 3
1930     Axis(Iax,Iax)=I.2
1940 NEXT Iax
1950 MAT Xyz= (0)
1960 GOSUB Trans
1970 Xzero=Xyz(1)
1980 Yzero=Xyz(2)
1990 FOR Iax=1 TO 3
2000     MAT Xyz= Axis(Iax,*)
2010     GOSUB Trans
2020     MOVE Xzero,Yzero
2030     DRAW Xyz(1),Xyz(2)
2040     LABEL Axis$(Iax)
2050 NEXT Iax
2060 RETURN
2070
2080 DATA 17
2090 DATA 20,50,100,200,500,1E3,2E3,5E3,1E4,2E4,5E4,1E5,2E5,3E5,4E5,5E5,7E5
2100 END

```

```

! <<Draw graphic>>
! Top of freq. loop <-----+
! Top of bias loop <-----+
! Draw graph
! bottom of bias loop -----+
!
! bottom of freq. loop -----+
!
!
!
! Draw grid
!
!
!
!
! <<Init.routine for Trans>>
!
!
!
!
! <<Make 3D graph data>>
!
!
!
!
! <<Draw axes>>
! Label of Y axis
! Label of X axis
! Label of Z axis
! Init. axes data
!
!
!
! Make 3D graph data of zero
!
!
!
! Make 3D graph data of axes
!
! Draw axis
! plot label
!
!
! <<Meas. freq. data>>
! Number of data

```

Agilent Technologies' Test and Measurement Support, Services, and Assistance

Agilent Technologies aims to maximize the value you receive, while minimizing your risk and problems. We strive to ensure that you get the test and measurement capabilities you paid for and obtain the support you need. Our extensive support resources and services can help you choose the right Agilent products for your applications and apply them successfully. Every instrument and system we sell has a global warranty. Support is available for at least five years beyond the production life of the product. Two concepts underlie Agilent's overall support policy: "Our Promise" and "Your Advantage."

Our Promise

Our Promise means your Agilent test and measurement equipment will meet its advertised performance and functionality. When you are choosing new equipment, we will help you with product information, including realistic performance specifications and practical recommendations from experienced test engineers. When you use Agilent equipment, we can verify that it works properly, help with product operation, and provide basic measurement assistance for the use of specified capabilities, at no extra cost upon request. Many self-help tools are available.

Your Advantage

Your Advantage means that Agilent offers a wide range of additional expert test and measurement services, which you can purchase according to your unique technical and business needs. Solve problems efficiently and gain a competitive edge by contracting with us for calibration, extra-cost upgrades, out-of-warranty repairs, and onsite education and training, as well as design, system integration, project management, and other professional engineering services. Experienced Agilent engineers and technicians worldwide can help you maximize your productivity, optimize the return on investment of your Agilent instruments and systems, and obtain dependable measurement accuracy for the life of those products.



Agilent Email Updates

www.agilent.com/find/emailupdates

Get the latest information on the products and applications you select.

Agilent T&M Software and Connectivity

Agilent's Test and Measurement software and connectivity products, solutions and developer network allows you to take time out of connecting your instruments to your computer with tools based on PC standards, so you can focus on your tasks, not on your connections. Visit **www.agilent.com/find/connectivity** for more information.

By internet, phone, or fax, get assistance with all your test & measurement needs

Phone or Fax

United States:

(tel) 800 452 4844

Canada:

(tel) 877 894 4414

(fax) 905 282 6495

China:

(tel) 800 810 0189

(fax) 800 820 2816

Europe:

(tel) (31 20) 547 2323

(fax) (31 20) 547 2390

Japan:

(tel) (81) 426 56 7832

(fax) (81) 426 56 7840

Korea:

(tel) (82 2) 2004 5004

(fax) (82 2) 2004 5115

Latin America:

(tel) (305) 269 7500

(fax) (305) 269 7599

Taiwan:

(tel) 0800 047 866

(fax) 0800 286 331

Other Asia Pacific Countries:

(tel) (65) 6375 8100

(fax) (65) 6836 0252

Email: tm_asia@agilent.com

Online Assistance:

www.agilent.com/find/assist

Product specifications and descriptions in this document subject to change without notice.

© Agilent Technologies, Inc. 2003, 2001

Printed in USA, January 22, 2003

5950-2367



Agilent Technologies