3569A-01A

S	Е	R	V	I	С	Е	Ν	0	Т	Е
							SUPERSEDE	ES: 3569/	A-01	
356	9A Rea	al-Tim	e Freq	uency	y Analy	zer				
Seria	al Numb	ers: 0000	)A00000	/ 3405	A00292					
3569	9A firm	ware re	evision	histo	ory					
To B	e Perfor	med By:	Agilent	-Qualif	ied Perso	onnel				
	s Requir	ed:	_		_					
<b>Part</b> 0356	<b>No.</b> 9-84402			escript rmware	<b>ion</b> e Upgrad	e Kit				
New							nd in previous stallation note,			
								C	Continued	
							DATE: Decem	nber 1994	1	

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:								
MODIFICATION RECOMMENDED								
ACTION CATEGORY:	<ul> <li>IMMEDIATELY</li> <li>ON SPECIFIED FAILURE</li> <li>AGREEABLE TIME</li> </ul>	STANDARDS: Labor 0.5 Hour						
LOCATION CATEGORY:	CUSTOMER INSTALLABLE	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT						
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: December 1996						
AUTHOR: DLC	ENTITY: A100	ADDITIONAL INFORMATION: A1-9410010						

© 1994 AGILENT TECHNOLOGIES
PRINTED IN U.S.A.



## List of changes by revision:

A.00.07 (new revision)

- Corrects Leq calculation.
- Corrects computation of CDF, PDF, Ln on recalled multispectrum.
- Disables dither during short integration times.
- Band power marker now works on linear y-axis traces.
- Provides field indicators required by Sound Power standards.
- Provides correct Time and Date on Recalled Multispectrum plots.

A.00.03

- Fixed Full Octave filter shape (rolls off too fast).
- Fixed display update for a FORMAT change from CDF to PDF.
- Removed error message when saving RT Intensity Multispec after Delete All.
- Corrected divide by zero after entering 4E-3 in [Meas Dur].
- Provided ability to measure Leq instead of L(User).
- Corrected frequency inaccuracy after changing Stop F in Reverb.
- Corrected [Scale] [Integrate] graphics scaling.
- Corrected [Scale] [Integrate] with [Zoom] ON trace scaling.
- Corrected Y-axis labels with [Y-axis] [Log Mag].
- Places octave L Band Marker in A Band on screen dump.
- Made g's available in cal table.
- Corrected Trigger delay in Status Screen.
- Unlatched Overloads when not measuring.
- Unlatched overload LED.
- Provided hi-pass filters on both channels.

A.00.01

The original version shipped.

## Solution/Action:

- 1. Turn the instrument on.
- 2. Press keys [SHIFT] and [1].
- 3. Read the firmware revision number in the upper right corner of the display.

If the revision is older than A.00.07, order the firmware update kit (p/n 03569-84402 and install two new EPROM's as per kit installation note instructions.

## Warning

The EPROM installation must be performed at a static protected workstation to prevent static discharge to the EPROM's and PC assembly.

Copy all stored 3569A files to a PC, as they will be lost due to the EPROM change.