

S E R V I C E N O T E

SUPERSEDES: 3589A-01

**3589A Spectrum/Network Analyzer**

**Serial Numbers:** 3129A00100 / 3343A00626

**3589A firmware revision history**

**Parts Required:**

| Part No.    | Qty. | Description          |
|-------------|------|----------------------|
| 03589-84404 | 1    | Firmware upgrade kit |

**Situation:**

The A.00.02 firmware upgrade resolves the following defects:

- FFT state recall gives single loop LO
- Reading real time clock may hang instrument
- Source trip may cause erroneous LO UNLOCK message
- Marker function target search fails to find target at edges of screen.
- Group delay wrong on trace B when both traces are set to input group delay.

The A.00.03 firmware upgrade resolves the following defects:

- Network calibration traces can be saved via GPIB commands.
- Incorrect offset marker data displayed when switching between linear and log trace types.

*Continued*

DATE: 10 March 1994

**ADMINISTRATIVE INFORMATION**

|                               |   |   |
|-------------------------------|---|---|
| SERVICE NOTE CLASSIFICATION:  |   |   |
| <b>MODIFICATION AVAILABLE</b> |   |   |
| ACTION CATEGORY:              | <b>AGREEABLE TIME</b>   | <input checked="" type="checkbox"/> PERFORMANCE ENHANCEMENT<br><input type="checkbox"/> SERVICE/RELIABILITY ENHANCEMENT |
| LOCATION CATEGORY:            | <input checked="" type="checkbox"/> CUSTOMER INSTALLABLE<br><input type="checkbox"/> ON-SITE<br><input type="checkbox"/> SERVICE CENTER | AVAILABLE UNTIL: 15 March 1996  |
| AUTHOR: DWH                   | ENTITY: A100  | ADDITIONAL INFORMATION:   |

**Solution/Action:**

Install the firmware using the firmware update disks.

The firmware installation procedure for the 3589A is straightforward. The 3589A is equipped with reprogrammable operating firmware. Here is the procedure:

**Step 1: Determine if the instrument needs the firmware update.**

1. Set the power switch to ON.
2. After the analyzer finishes its power-up calibration routine, press the following keys:
  - [ Special Fctn ]
  - [ NON-VOL SETUP ]
  - [ VERSION ]
3. If the information block reads “Release ID: A.00.03”, you do not need to update the instruments firmware.

The information block appears on the screen for about five seconds (pressing [ VER-SION ] repeats the information).

**Step 2: Power on instrument with disk 1 in disk drive.**

1. Set the power switch to STANDBY.
2. Insert disk 1 into the internal disk drive.
3. Set the power switch to ON.
4. Wait until the instrument displays: “Remove disc and cycle power to continue.”
5. Remove disk 1 and set the power switch to STANDBY.

After the power-on tests are finished, the instrument automatically searches for a flexible disk containing the instrument firmware. When these files are located, they are loaded into memory which reprograms into the operating firmware.

**Step 3: Power on instrument with disk 2 in disk drive**

1. Insert disk 2 into the internal disk drive.
2. Set the power switch to ON.
3. Wait until the instrument displays: “Remove disc 2 and turn off instrument power.”
4. Remove disk 2 and set the power switch to STANDBY.

The “Program ROM” power-on tests may fail because the first disk only reprogrammed half of the instrument’s operating firmware. Here is the failure message you may see:

|                       |               |     |   |
|-----------------------|---------------|-----|---|
| ROM Checksum Failure. | Bad Checksum. | 04, | 0 |
| ROM Checksum Failure. | Bad Checksum. | 04, | 1 |

This message should be ignored until the firmware upgrade is complete.

**Step 4: Power on instrument and check for failures.**

1. Set the power switch to ON.
2. Check that the power-on tests finished with no failures.

If the instrument does not boot up or the power-on tests fail, check that you inserted the disks in the correct order. Repeat the installation procedure, inserting disk 1 first and disk 2 second.

If the instrument fails after repeating the installation procedure, refer to the 3589A Service Guide for service information.