S E R V I C E N O T E

SUPERSEDES: None

54600A Oscilloscope

Serial Numbers: 0000A00000 / 3106A99999

Duplicate Service Notes: 54601A-04

ROM (Firmware) upgrade required to be compatible with new interface modules

54655A, 54656A, 54657A and 54658A.

To Be Performed By: Agilent-Qualified Personnel or Customer.

Parts Required:

Parts Kit 54601-68702 Contents

P/NDescription54600-80005System 2.0 ROM5960-2485Installation Guide8710-1816Torx Driver (T-15)

Situation:

To determine the need for this firmware upgrade, check the prefix number on the rear of the oscilloscope. All oscilloscopes with serial prefix 3134A and later have the latest firmware installed. Approximately one hundred units with prefix 3106A also have the latest firmware installed. The currently installed ROM may be determined by pressing the Continued

DATE: 21 October 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:	AGREEABLE TIME	■ PERFORMANCE ENHANCEMENT □ SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	■ CUSTOMER INSTALLABLE□ ON-SITE■ SERVICE CENTER	AVAILABLE UNTIL: Product Support Life
AUTHOR: NCW	ENTITY: 0800	ADDITIONAL INFORMATION:

© 1991 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Print/Utility key after the oscilloscope has been turned on and the grid appears.

In the lower left corner of the CRT, in inverse video, will be displayed "54600A System X.Y". If "X" is the number "1", you need to install this upgrade kit. If "X" is the number "2" or later, you do not need to install this upgrade kit.

NOTE:

If the oscilloscope has ROM version 1.4 thru 1.8 no re-calibration is needed. If oscilloscope has ROM version 1.3 or below it requires re-calibration, which requires a pulse generator and takes about 10 minutes.

Solution/Action:

Replacement of ROM U42 with system ROM 2.0 (P/N 54600-80005) will allow Oscilloscopes to be compatible with new interface modules.