# S E R V I C E N O T E

SUPERSEDES: NONE

## 8164A Lightwave Measurement System

**Serial Numbers:** 42 potential units from DE38700177 to DE38700340 a detailed list is

available from OCM Customer Support 8164A

### **Power Supply**

To Be Performed By: Agilent-Qualified Personnel

#### **Parts Required:**

P/N Description Quantity
0950-2868 PWR-SPLY-375W 1

#### **Situation:**

During the month of August,1999, a quantity of 8164A mainframes were ordered and shipped without a TLS module. Due to a wrong value of a capacitor on the power supply, the current limitation may be triggered when booting the system with a TLS module installed. As a result the power supply will switch off, the system is unable to complete booting.

Continued

DATE: September 1999

### **ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS:  LABOR 1.0 Hours
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE ☐ RETURN USED ☐ RETURN PARTS: ☐ SCRAP ☐ SEE TEXT ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: March 31, 2002
AUTHOR: VE	ENTITY: B101	ADDITIONAL INFORMATION:

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note 8164A-02

#### **Solution / Action:**

Test if a "good" power supply is installed can be easily done by inserting a TLS module (model 81640A, 81680A or 81682A) and switch on the system. If the system boots the power supply is ok. In case the system is no able to boot with a TLS inserted, the power supply has to be replaced. Good parts will be available from GSL.

The service center shall return the original power supply to the factory (OCM) as of warranty claim to the vendor and add a notification stating:

model number (8164A), serial number, service center and employee who did the modification, customer name.