
# **Agilent N1011A Lightwave Verification Kit**





© Copyright
Agilent Technologies 2001
All Rights Reserved. Reproduction, adaptation, or translation without prior written permission is prohibited, except as allowed under copyright laws.

Agilent Part No. 08703-90205 Printed in USA July 2001

Agilent Technologies Lightwave Division 3910 Brickway BoulevardSanta Rosa, CA 95403, USA

#### Notice.

The information contained in this document is subject to change without notice. Companies, names, and data used in examples herein are fictitious unless otherwise noted. Agilent Technologies makes no warranty of any kind with regard to this material, including but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Agilent Technologies shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance, or use of this material.

### Restricted Rights Legend.

Use, duplication, or disclosure by the U.S. Government is subject to restrictions as set forth in subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013 for DOD agencies, and subparagraphs (c) (1) and (c) (2) of the Commercial Computer Software Restricted Rights clause at FAR 52.227-19 for other agencies.

### Warranty.

This Agilent Technologies instrument product is warranted against defects in material and workmanship for a period of one year from date of shipment. During the warranty period, Agilent Technologies will, at its option, either repair or replace products which prove to be defective. For warranty service or repair, this product must be returned to a service facility designated by Agilent Technologies. Buyer shall prepay shipping charges to Agilent Technologies and Agilent Technologies shall pay shipping charges to return the product to Buyer. However, Buyer shall pay all shipping charges, duties, and taxes for products returned to Agilent Technologies from another country.

Agilent Technologies warrants that its software and firmware designated by Agilent Technologies for use with an instrument will execute its programming instructions when properly installed on that instrument. Agilent Technologies does not warrant that the operation of the instrument, or software, or firmware will be uninterrupted or error-free.

### Limitation of Warranty.

The foregoing warranty shall not apply to defects resulting from improper or inadequate maintenance by Buyer, Buyer-supplied software or interfacing, unauthorized modification or misuse, operation outside of the environmental specifications for the product, or improper site preparation or maintenance.

No other warranty is expressed or implied. Agilent Technologies specifically disclaims the implied warranties of merchantability and fitness for a particular purpose.

### **Exclusive Remedies.**

The remedies provided herein are buyer's sole and exclusive remedies. Agilent Technologies shall not be liable for any direct, indirect, special, incidental, or consequential damages, whether based on contract, tort, or any other legal theory.

# **Safety Symbols.** CAUTION

The *caution* sign denotes a hazard. It calls attention to a procedure which, if not correctly performed or adhered to, could result in damage to or destruction of the product. Do not proceed beyond a caution sign until the indicated conditions are fully understood and met.

#### WARNING

The warning sign denotes a hazard. It calls attention to a procedure which, if not correctly performed or adhered to, could result in injury or loss of life. Do not proceed beyond a warning sign until the indicated conditions are fully understood and met.



The instruction manual symbol. The product is marked with this warning symbol when it is necessary for the user to refer to the instructions in the manual.



The laser radiation symbol. This warning symbol is marked on products which have a laser output.



The AC symbol is used to indicate the required nature of the line module input power.



The ON symbols are used to mark the positions of the instrument power line switch.



O The OFF symbols are used to mark the positions of the instrument power line switch.



The CE mark is a registered trademark of the European Community.



The CSA mark is a registered trademark of the Canadian Standards Association.



The C-Tick mark is a registered trademark of the Australian Spectrum Management Agency.

ISM1-A

This text denotes the instrument is an Industrial Scientific and Medical Group 1 Class A product.

### **Typographical Conventions.**

The following conventions are used in this book:

Key type for keys or text located on the keyboard or instrument.

*Softkey type* for key names that are displayed on the instrument's screen.

Display type for words or characters displayed on the computer's screen or instrument's display.

**User type** for words or characters that you type or enter.

Emphasis type for words or characters that emphasize some point or that are used as place holders for text that you type.

### **General Safety Considerations**

This product has been designed and tested in accordance with IEC Publication 1010, Safety Requirements for Electronic Measuring Apparatus, and has been supplied in a safe condition. The instruction documentation contains information and warnings which must be followed by the user to ensure safe operation and to maintain the product in a safe condition.

Install the instrument according to the enclosure protection provided. This instrument does not protect against the ingress of water. This instrument protects against finger access to hazardous parts within the enclosure.

# WARNING If this product is not used as specified, the protection provided by the equipment could be impaired. This product must be used in a normal condition (in which all means for protection are intact) only.

# WARNING No operator serviceable parts inside. Refer servicing to qualified service personnel. To prevent electrical shock do not remove covers.

General Safety Considerations

# **Lightwave Verification**

You can monitor the stability and repeatability of the analyzer system hardware by periodically performing the lightwave verification process. The verification test compares measurements of the current system status against factory-measured data unique to the verification kit device.

If the analyzer measures the verification device within the uncertainty limits provided on the disk, the analyzer passes the verification. If the measurement results do not fall within the uncertainty limits, perform the steps in "If the Analyzer Does Not Pass the Verification Test" on page 6 and repeat the verification procedure. If the analyzer continues to fail the test, contact your nearest Agilent Technologies office or sales representative. A list of Agilent Technologies sales and service offices is provided in "Agilent Technologies Service Offices" on page 7.

# **N1011A Verification Kit Parts**

Table 1. Kit Parts

Part Description	Part Number
20 GHz Lightwave Detector	08703-60225
Power Supply and Cable Assembly	5063-5540
RF Coax Termination	00909-60016
Optical Cable Assembly (SPC)	1005-0173
Optical Connector (FC/PC)	08154-61702
Verification Kit Manual	08703-90205

### **Lightwave Verification Procedure**

To get the best indication of instrument changes over time, print the results from the first test and archive them to compare with all subsequent tests. The verification routine sets the analyzer to the following conditions:

- Full band sweep (50 MHz to 20.05 GHz)
- 401 points
- 30 Hz IF bandwidth
- 0.5 % Smoothing
- 8 Sweep Averages

# WARNING The verification routine saves data to Memory 2, overwriting any data previously stored in Memory 2.

### **Required Equipment**


- 8703B Lightwave Component Analyzer
- Verification Kit (N1011A)
- Floppy Disk (included in verification kit)
- 1. Press System, Service Menu, Lightwave Service Menu, Verify Instrument.

The conditions set for the verification are as follows:

### **NOTE** Do not change the conditions during the verification procedure.


- 2. Press Verify ON, O/E Cal and perform an O/E Response and Match Calibration.
- 3. Press Meas, Trans: O/E, Trans: O/E (Port 1).
- 4. Press Cal, CALIBRATE MENU, RESPONSE & MATCH, REFLECTION.
- 5. Connect the open calibration standard directly to the electrical port as shown in Figure 1.

Figure 1. Forward Reflection Measurement for O/E Response and Match Calibration



- 6. Measure the calibration standard by pressing FORWARD: OPEN.
- 7. The analyzer displays "WAIT MEASURING CAL STANDARD" during the standard measurement. The softkey label is then underlined.
- 8. Repeat steps 5 through 7 to measure the short and the load calibration standards in the forward direction.
- 9. Connect the open calibration standard to the end of a cable that is connected to the electrical port as shown in Figure 2.

Figure 2. Reverse Reflection Measurement for O/E Response and Match Calibration




- 10. Measure the calibration standard by pressing **REVERSE**: **OPEN**.
- 11. The analyzer displays "WAIT MEASURING CAL STANDARD" during the standard measurement. The softkey label is then underlined.
- 12.Repeat steps 9 through 11 to measure the short and the load calibration standards in the

reverse direction.

### 13. Press **STANDARDS DONE**.


14. Connect the cables, as shown in Figure 3.

Figure 3. Transmission Measurement for O/E Response and Match Calibration




- 15.Press **TRANSMISSION**, **FWD. TRANS. THRUS**. The analyzer displays "WAIT MEASURING CAL STANDARD" during the standard measurement. The softkey label is then underlined.
- 16.Press **FWD. MATCH THRU**. The analyzer displays "WAIT MEASURING CAL STANDARD" during the standard measurement. The softkey label is then underlined.
- 17. Press STANDARDS DONE.
- 18.If you do not want the isolation calibration, press **ISOLATION**, **OMIT ISOLATION** and go to step 24.
- 19.If you want the isolation calibration, press **Avg**, **AVERAGING ON**. (For greater dynamic range use an averaging factor of 32.)
- 20. Press Cal, RESUME CAL SEQUENCE, ISOLATION.
- 21. Connect the isolation standards as shown in Figure 4.

Figure 4. Isolation Measurement for O/E Response and Match Calibration



- 22.Press **FWD ISOL'N**, **ISOL'N STD**. The O/E isolation data is measured and averaged over 16 sweeps (or the number selected). The softkey label is then underlined.
- 23. Press ISOLATION DONE, Avg, AVERAGING OFF, Cal, RESUME CAL SEQUENCE.
- 24.Press DONE: RESP & MATCH.
- 25. Insert the floppy disk that has the verification device data into the analyzer disk drive.
- 26.Press Load Disk.
- 27. Connect the verification device between the analyzer lightwave source and PORT 1.

Figure 5. Setup for Verification Device Measurement



- 28.Press **Start Verify**. This test compares the measured data with the data from the floppy disk. The message "PASS" or "FAIL" will appear on the analyzer.
- 29.Press **View Deviation** to toggle between seeing the data as a comparison or as the deviation with the limits:
  - Comparison compares the trace with the verification device data at a point-by-point basis. If one point fails in the comparison, the analyzer will fail the verification test.

The DC responsivity is not verified. The DC offset is calculated as the difference between the average value of the measured data (20 points) and the average value of the verification device data (20 points).

### If the Analyzer Does Not Pass the Verification Test

Clean all of the connectors and cable ends and repeat the verification procedure. If the analyzer continues to fail the test, contact your nearest Agilent Technologies office or sales representative. A list of Agilent Technologies sales and service offices is provided in "Agilent Technologies Service Offices" on page 7.

# **Agilent Technologies Service Offices**

Before returning an instrument for service, call the Agilent Technologies Instrument Support Center at (800) 403-0801, visit the Test and Measurement Web Sites by Country page at http://www.tm.agilent.com/tmo/country/English/index.html, or call one of the numbers listed below.

Table 2. Agilent Technologies Service Numbers

Table 2.	righthe recinologies betwee rumbers	
Austria	01/25125-7171	
Belgium	32-2-778.37.71	
Brazil	(11) 7297-8600	
China	86 10 6261 3819	
Denmark	45 99 12 88	
Finland	358-10-855-2360	
France	01.69.82.66.66	
Germany	0180/524-6330	
India	080-34 35788	
Italy	+39 02 9212 2701	
Ireland	01 615 8222	
Japan	(81)-426-56-7832	
Korea	82/2-3770-0419	
Mexico	(5) 258-4826	
Netherlands	020-547 6463	
Norway	22 73 57 59	
Russia	+7-095-797-3930	
Spain	(34/91) 631 1213	
Sweden	08-5064 8700	
Switzerland	(01) 735 7200	
United Kingdom	01 344 366666	
United States and Canada	(800) 403-0801	

Agilent Technologies Service Offices