

S E R V I C E N O T E

SUPERSEDES: None

8752A Network Analyzer**Serial Numbers:** 3214J00648 / 3214J00882**Reversed capacitor causes fuse A8F10 to blow****Parts Required:**

P/N 0180-4172, 0.47uF

Situation:

Several units have been found to have the capacitor A13C60 mounted with its polarity reversed. Over time the capacitors become leaky and cause the fuse A8F10 to blow.

Solution/Action:

When suspect units are received, the capacitor A13C60 should be checked to insure that the capacitor has been inserted correctly. If A13C60 has been inserted incorrectly replace with NEW capacitor.

Continued

DATE: October 1994

ADMINISTRATIVE INFORMATION

| | | | | | |
|---------------------------------|--|-------------------------|--|-------------|---|
| SERVICE NOTE CLASSIFICATION: | | | | | |
| MODIFICATION RECOMMENDED | | | | | |
| ACTION CATEGORY: | <input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME | STANDARDS: | Labor 0.5 Hour | | |
| LOCATION CATEGORY: | <input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER | SERVICE INVENTORY: | <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT | USED PARTS: | <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | | AGILENT RESPONSIBLE UNTIL: October 1995 | | |
| AUTHOR: EW | ENTITY: 5300 | ADDITIONAL INFORMATION: | | | |

