

MODIFICATION RECOMMENDED –
CORRECTS MANUFACTURING OR DESIGN DEFECTS

E5070A-02

S E R V I C E N O T E

Supersedes:
NONE

E5070A ENA Series Network Analyzer, 300 kHz to 3 GHz

Serial Numbers: **JP1KJ00000 / JP1KJ00223**

Firmware Update for Bug Fix

To Be Performed By: Customer

Parts Required: NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR: 0.5 Hours
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: TO	PRODUCT LINE: WN	AGILENT RESPONSIBLE UNTIL: Dec 2004	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2002
PRINTED IN U.S.A.



December 6, 2002

Situation:

The E5070A firmware revision 1.01 and below have a bug, which causes incorrect measurement results when the fixture simulator function is used. This bug has been fixed in the firmware revision 1.02 and above.

Solution/Action:

Install the latest revision 3.01 firmware (as of Dec 2002) in the E5070A. Customers can update the firmware of their own E5070A by downloading the revision 3.01 firmware from Agilent website as follows.

- 1) Access <http://www.agilent.com/find/ena>
- 2) Click “E5070A ENA Series Network Analyzer, 300kHz to 3 GHz”.
- 3) Click “Software, Firmware & Drivers”.
- 4) Click “E5070A ENA Series RF Network Analyzer, 300 kHz to 3 GHz Firmware Update”.
- 5) Follow the “Download Instructions for Firmware” to download the revision 3.01 firmware and install it into the E5070A.