E8802A-05

SERVICE NOTE

Supersedes: NONE

E8802A PNA Series RF Network Analyzers

Serial Numbers: 0000A00000/9999Z99999 [All]

Replace Inverter board (0950-3379) due to faulty component.

To Be Performed By: Agilent-qualified personnel or customer with

specific product repair knowledge - requires

instrument disassembly and component replacement.

Parts Required:

P/N Description Qty.
0950-3379 DC/AC Inverter Board 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:	X AGREEABLE TIME	PERFORMANCE ENHANCEMENT X SERVICE / RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE* X ON-SITE X SERVICE CENTER	AVAILABILTY: Support Life
AUTHOR: MF PRODUCT LINE: WN ADDITIONAL INFORMATION: *See "To Be Performed By." Written 10/17/07. Affected PNA models: E8356/7/8A, E8801/2/3A, N3381/2/3A, N5230A, E8361/2/3/4A, E8362/3/4B.		

© AGILENT TECHNOLOGIES, INC. 2007 PRINTED IN U.S.A.



Page 2 of 2 E8802A-05

Situation:

The original fuse (see photo) in the DC/AC Inverter board (p/n 0950-3379) is prone to failure in normal use.

Solution/Action:

Replace the Inverter board with a board containing the new fuse (see photo).

