								899	2A-0	2A
S	Е	R	V	Ι	С	Е	Ν	0	Т	Е
800)7 A Do	ok Dou	or An	Juzor		ç	SUPERSEDE	ES: 8992	A-02	
		ak Pow bers: See		uyzer						
Def	ective	fuse ho	older in	the A	C line f	ilter				
Dup	plicate Se	ervice No	tes:							
899	1A-03A \$	Serial Nur Serial Nur Serial Nur	mbers 36	21A008	318 / 362	1A01033				
Tol	Be Perfo	rmed By:	: Agilent	t-Qualif	fied Perso	onnel or Cu	stomer			
Par	ts Requi	red: NON	νE							
Situ	ation:									
in th conf	ne AC line figured fo	e Filter p/	/n 9135-0 0V opera	416. Th tion. Al	nis defect though th	causes the ne problem	hipped with a unit to blow f exist only in	fuses when	l	Л
									Continue	ed
						[DATE: June	1999		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:									
MODIFICATION RECOMMENDED									
ACTION CATEGORY:	 ☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME 	STANDARDS: LABOR 0.5 Hours							
LOCATION CATEGORY:	CUSTOMER INSTALLABLE ON-SITE SERVICE CENTER	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT SEE TEXT							
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: January 1999							
AUTHOR: EMC ENTITY: 5320		ADDITIONAL INFORMATION:							

© 1999 AGILENT TECHNOLOGIES
PRINTED IN U.S.A.



Solution / Action:

- 1. Set the rear panel line switch to OFF and disconnect the power cord from the line module/switch assembly.
- 2. Remove the fuse holder from the line module/switch assembly. To do this, place the blade of a small screwdriver into the slot that is near the assembly's power cord receptacle and pry the fuse holder out of the assembly(refer to Figure 2-21 in the service manual).
- 3. Check that the two middle pins on the 220-240V side of the fuse holder are removed.
- 4. If the two middle pins are present, use caution to cut and remove them.
- 5. Replace any blown fuses as needed.
- 6. Re-insert the fuse holder.
- 7. Verify that the unit operates in both 110-120V and 220-240V positions. Steps 2 thru 7 should also be performed after ordering a replacement AC line Filter p/n 9135-0416.