E8257C-08

SERVICE NOTE

Supersedes: None

E8257C PSG Analog Signal Generator

Serial Numbers: E8257C option 540 (40Ghz) only: US00000000 / US43320425 and MY00000000 / MY43321251

Procedure to resolve RF out power holes

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N	Description	Qty.		
Front panel RF o	ut -			
E8251-20035	Coupler/ RF out cable	1		
E8251-20028	Attn/ RF out cable	1		
Rear panel RF out (Option 1EM)				
E8251-20092	Coupler/ RF out cable	1		
E8251-20072	Attn/ RF out cable	1		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLA	SSIFICATION:			
MODIFICATION RECOMMENDED				
ACTION	[[]] IMMEDIATELY	STANDARDS:		
CATEGORY:	[[]] ON SPECIFIED FAILURE	LABOR: 3.0 Hours for std unit		
		13.0 Hours for 1E1 opt.	ļ	
	x AGREEABLE TIME			
LOCATION	[[]] CUSTOMER INSTALLABLE	SERVICE [[]] RETURN USED [[]] RETU	RN	
CATEGORY:	[[]] ON-SITE	INVENTORY: x SCRAP PARTS: x SCRAP		
	X SERVICE CENTER	[[]] SEE TEXT ' [[]] SEE T	EXT	
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL:		
AUTHOR: SN	PRODUCT LINE: 15			
ADDITIONAL INFOR	MATION:			

© AGILENT TECHNOLOGIES, INC. 2004 PRINTED IN U.S.A.



Page 2 of 2 E8257C-08

Situation:

The 2.4mm RF output cables E8251-20028, E8251-20035, E8251-20072 and E8251-20092 may have insufficient solder. When this occurs, power holes or spikes appear at the RF output of instrument.

Solution/Action:

If power holes or spikes appear, order a replacement RF cable. Replacement cable is dependent on Front or Rear RF out with and without attenuator. Check "Parts Required" for the correct part number. Replace the part and recalibrate the E8257C. Refer to PSG service guide for calibration. Adjustments:

- For unit without attenuator:
 - 1) Run ALC Dynamic Calibration
 - 2) Run Power Flatness Calibration
- For unit with attenuator (1E1):
 - 1) Run ALC Dynamic Calibration
 - 2) Run Power Flatness Calibration
 - 3) Perform AT1 115 Attenuator Adjustment.

Performance tests:

- For unit with or without attenuator:
 - 1) Self tests
 - 2) Run Maximum Leveled Output Power
 - 3) Power Leveled Accuracy

GTLS/SPO inventory has been purged.