E8257D-19 <u>S E R V I C E N O T E</u>

Supersedes: NONE

E8257D Analog Signal Generator

Serial Numbers: US46110761, US46461185, US46461206, US46461214, US46461221, US46461224, US46461225, MY46521457, MY46521541, MY46521542, MY46521543, MY46521558, MY46521577, MY46521664, SG46520155, SG46520171, SG46520172.

Loss of RF output power < 3.2 GHz or UNW pulse modulation performance after updating to firmware \geq C.05.01.

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required: P/N Description

Qty.

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:	Upon Failure	[[]] PERFORMANCE ENHANCEMENT x SERVICE / RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE x SERVICE CENTER	AVAILABILTY: Until EOS
AUTHOR: DMc	PRODUCT LINE: PL 15	
ADDITIONAL INFORMATION:		
© AGILENT TECHNOLOGIES, INC. 2007		
PRINTED IN U.S.A.		

December 3, 2007

Agilent Technologies

Situation:

A value entered into an array prior to firmware C.05.01 being released may result in a loss of output power \leq 3.2 GHz and/or the loose of UNW pulse performance.

Solution/Action:

Contact the sources email node, SUPPORT, SOURCES (A-Sonoma, exgen1) letting them know of the problem. Please provide: Contact information: Model and serial number: Problem statement: Lost power \leq 3.2GHz and or UNW pulse performance after updating to firmware C.0_ ._ (add firmware revision).

If possible please connect the instrument to the LAN (not behind a firewall) and provide include the IP address.

If the instrument can not be connected to the LAN you will be contacted with further instructions.