S E R V I C E N O T E

SUPERSEDES: None

8563A Portable Spectrum Analyzer

Serial Numbers: 0000A00000 / 3120A00661

Duplicate Service Notes: 8560A-16, 8561A-29, 8561B-18, 8562A-60, 8562B-58,

and 8563A-12

Preventing Negative Peak Detector Latchup

Parts Required: 1 ea. 1901-1098 diode

Situation:

An intermittent problem can occur at turn-on or at cold temperature where the displayed noise floor jumps to the top of the screen. This is caused by a latchup mechanism in the Negative Peak Detector circuitry.

Solution/Action:

The diode is added from the drain of A3Q306A to ground with the cathode of the diode connected to the transistor. Refer to the section in the Service manual on Assembly Replacement and remove the top and bottom Peak Detector shields from the A3 assembly. Keeping the leads as short as possible, install the diode on the bottom (circuit) side of the board. Solder the cathode (banded) end of the diode to pin 2 of A3Q306 and the anode end to pin 4. Lay the diode down as close as possible to the board to allow room for the shield.

DATE: 16 May 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ■ AGREEABLE TIME	STANDARDS: Labor 1.0 Hour
LOCATION CATEGORY:	■ CUSTOMER INSTALLABLE■ ON-SITE■ SERVICE CENTER	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: June 1993
AUTHOR: GPB	ENTITY: 5300	ADDITIONAL INFORMATION:

© 1991 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

