S E R V I C E N O T E

SUPERSEDES: None

8564E Portable Spectrum Analyzer

Serial Numbers:

8560A-28A: 3146A01932 / 3413A02687 8560E-06A: 0000A00000 / 3425A01033 8561E-05A: 0000A00000 / 3425A00723 8562A-68A: 3148A06894 / 3337A07664 8563A-21A: 3146A00562 / 3413A02911 8563E-07A: 0000A00000 / 3425A00476 8564E-08: 0000A00000 / 3425A00182 8565E-08: 0000A00000 / 3425A00183

Modification to improve focus reliability

Duplicate Service Notes: See Above

Parts Required:

 Part No.
 Qty.
 Description

 0160-6420
 2
 0.0047uf Capacitor

 1901-1214
 2
 Diode, 600V

Continued

DATE: August 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:	AGREEABLE TIME	☐ PERFORMANCE ENHANCEMENT ■ SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	■ CUSTOMER INSTALLABLE □ ON-SITE ■ SERVICE CENTER	AVAILABLE UNTIL: Life of Product
AUTHOR: GPB	ENTITY: 5300	ADDITIONAL INFORMATION:

© 1996 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Situation:

The breakdown voltage of two diodes used on the A17 CRT Driver assembly can be exceeded. A possibility exists that, if this voltage is exceeded, the diode may be damaged and focus will be degraded. Using diodes with a higher breakdown voltage will improve focus reliability. Changing the diodes alone, however, can cause the intensity at low levels to flicker.

Solution/Action:

Replaces A17CR10 and A17CR30 with part number 1901-1214. Also replace A17C11 and A17C30 with 0.0047uf capacitors, part number 0160-6420.