# S E R V I C E N O T E

SUPERSEDES: NONE

# 8565E Portable Spectrum Analyzer

Serial Numbers: See Below

# Reducing 300 kHz Sidebands

## **Duplicate Service Notes:**

8560E-17 Serials: 3632A02407 / 3743A03259 8562E-05 Serials: 0000A00000 / 3743A00561 8563E-17 Serials: 3645A06020 / 3743A07920 8564E-12 Serials: 3641A00611 / 3743A01005 8565E-12 Serials: 3641A00533 / 3743A00793

To Be Performed By: Agilent-Qualified Personnel

# Parts Required:

P/N Description Quanty

08564-60026 A6A2 Regulator Ay. 1 ea.

Continued

DATE: December 1997

#### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ■ AGREEABLE TIME	STANDARDS:  LABOR 0.5 Hours
LOCATION CATEGORY:	<ul><li>■ CUSTOMER INSTALLABLE</li><li>□ ON-SITE</li><li>■ SERVICE CENTER</li></ul>	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGI LENTRESPONSIBLE UNTIL: December 1999
AUTHOR: GPB	ENTITY: 5320	ADDITIONAL INFORMATION:

© 1997 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note 8565E-12

## **Situation:**

Some instruments may fail the Spurious Response spec at 300 kHz offset from a signal. This can be the result of inadequate filtering on the -5 Volt bias supply to the A8 Low Band Mixer.

#### **Solution / Action:**

Replace the older A6A2 Regulator assembly 08564-60009 with part number 08564-60026 or later. Later regulator assemblies haved added filtering on the -5 volt supply. This modification can also improve performance of instruments which already meet the Spurious Response specifications.