S E R V I C E N O T E

SUPERSEDES: None

8565 E Series Portable Spectrum Analyzers with Option 001

Serial Numbers: See below

12.4 GHz Signal on 310.7 MHz IF Output

Duplicate Service Notes:

8560E-21	Serial Numbers: 3635A02450/3643A02650
8561E-17	Serial Numbers: 3635A01064/3641A01716
8562E-09	Serial Numbers: 0000A00000/3643A00240
8563E-21	Serial Numbers: 3635A05658/3645A06169
8564E-16	Serial Numbers: 3635A00584/3643A00661
8565E-16	Serial Numbers: 3635A00511/3643A00559

To Be Performed By: Agilent-Qualified Personnel, Customer

Parts Required:

P/N	Description	Quantity
1855-0974	Transistor, FET	1

Continued

DATE: January 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: MODIFICATION AVAILABLE			
ACTION CATEGORY:	AGREEABLE TIME	☐ PERFORMANCE ENHANCEMENT ■ SERVICE/RELIABILITY ENHANCEMENT	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	AVAILABLE UNTIL: Productís support life	
AUTHOR: GPB	ENTITY: 5320	ADDITIONAL INFORMATION:	

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note 8565E-16

Situation:

Oscillations in the 310.7 MHz Second IF Stage can produce a signal at approximately 12.4 GHz at around -20 dBm on the Second IF Output. This situation does not violate any instrument specifications but it can interfere with some applications which require monitoring at the Second IF Output, such as wide band power measurement.

Solution / Action:

Change A15Q801 to the part number listed above. This is a surface mount part requiring special SMT equipment. If the equipment is not available, order the current version of the A15 RF Assembly.