8591E-01

S	Е	R	V	I	С	Ε	Ν	0	Т	Е	
							SUPERSEDE	S: NON	Ξ		
85	91E Sp	ectrum	Analy	zer							
Ser	ial Numł	oers: 000	0A00000	/ 9999	Z99999						
Inc	Increasing flatness data values improves performance										
To	To Be Performed By: Agilent-Qualified Personnel										
A4	A4 First Converter, part number 08590-60214										
Duj	Duplicate Service Notes: 8590D-01, 85910E-01										
The plet min Situ Old valu the	 Situation 1: The response has a small but abrupt resonance at about 60 MHz which cannot be completely removed by the flatness correction values at 41 MHz and 68 MHz. A 0.5 dB offset minimizes the positive and negative errors relative to the 300 MHz reference point. Situation 2: Older firmware used in the 8591E does not properly compensate for flatness correction values which are more negative than -1.3 dB in linear mode. Some clipping of the top of the signal will occur in linear mode at frequencies below 41 MHz. Analyzers with a firmware datecode newer than 27.10.92 are not affected. 										
								С	ontinued		
							DATE: Decem	ber 1994	Ļ		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICA	TION:							
INFORMATION ONLY								
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:						
PGS	5300							

© 1994 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Solution:

The Frequency Response (Flatness) correction value at 78 MHz should be increased by 0.5 dB. During the Frequency Response Adjustment Procedure found in the Service Manual, add 0.5 dB to the "Error Relative to 300 MHz" at 78 MHz only. (Column 2 of the Correction Table without Option 001. Column 5 of the Correction Table with Option 001).

Example: Error at 78 MHz relative to 300 MHz = -1.2 dBAdd 0.5 dB offset +0.5 dB

Optimum correction value at 78 MHz = -0.7dB

NOTE:

If you request and reinstall the original factory calibration values, it is not necessary to add this additional 0.5 dB offset. The original factory calibration numbers always include this offset.