S E R V I C E N O T E

SUPERSEDES: None

8591E 9kHz-1.8GHz RF Spectrum Analyzer

Serial Numbers:

3402U00938 / 3402U01000 3408U01001 / 3408U01016, 3408U01019

A16 Processor / Video Board Assembly

Incorrectly programmed PAL device may cause instrument failures

To Be Performed By: Agilent-Qualified Personnel

Duplicate Service Notes:

8590D-04

8591C-01

8591E-04

8592D-02

8593E-05

8594E-05

8595E-05

8596E-05

Parts Required:

Part No. Description 08590-80200 PAL, Programmed

Continued

DATE: 05 May 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: Labor 1.0 Hour
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: 05 May 1996
AUTHOR: DWH	ENTITY: A100	ADDITIONAL INFORMATION:

© 1994 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Situation:

The PAL, A16U114, was incorrectly programmed for the range of serial numbers described above. The parts appear to operate correctly but the longer term reliability may be degraded.

Solution/Action:

It is recommended that A16U114 (08590-80200) is replaced when any failure is reported on the range of spectrum analyzers described above. The part should be changed even for failures which appear unrelated to the PAL operation. The part will only require to be changed once because all incorrectly programmed parts have been purged from stock.

It should not be necessary to remove the A16 processor assembly from the instrument, to replace the PAL, U114. The PAL device is in a socket and is located beside the ROM, U7.