8596E-08

S	Е	R	V		С	Е	Ν	Ο	Т	Е
---	---	---	---	--	---	---	---	---	---	---

SUPERSEDES: None

8596E 9kHz-12.8GHz Microwave Spectrum Analyzer option 111, H93 or K94

Serial Numbers: 0000U00000 / 3443U00253

Group Delay Card (option card for opt. 111, H93 * K94) used with 11770A Link Measurement Personality Card Revision A.02.00 (or earlier) and 11768-80012 DRTS Measurement Personality Card Revision A.02.00 (or earlier).

Link Analyzer Self Verification Test Failure

Parts Required: P/N

11770A (latest revision)

11768-80017 (or later revision)

Description

Link Measurement Personality Card DRTS Measurement Personality Card

Situation:

There is a self test available on the 11770A and 11768-80012 Personalities. This is used to verify the performance of the group delay card in the Spectrum Analyzer. Revision A.02.00 of the 11770A and 11768-80012 Personalities do not take into account that the group delay card may use a Select On Test resistor. If the default value of this resistor was changed in the factory, the link analyzer self test will fail. The failure message implies that

Continued

DATE: February 1995

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:									
MODIFICATION RECOMMENDED									
ACTION CATEGORY:	 IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME 	STANDARDS: Labor 0.5 Hour							
LOCATION CATEGORY:	CUSTOMER INSTALLABLE	SERVICE I RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT							
AVAILABILITY:	PRODUCT'S SUPPORT LIFE AGILENT RESPONSIBLE UNTIL: February 1997								
AUTHOR: JP	ENTITY: E600	ADDITIONAL INFORMATION:							

© 1995 AGILENT TECHNOLOGIES
PRINTED IN U.S.A.



the group delay card is faulty, however the failure is caused by the personality card.

The error is seen as follows:

Select Group Delay Verification Mode, then run Verify Card as described in the Performance Verification section of the 11770A/11768-80012 Manual. The error message "Bad PLL Centre Voltage" will be displayed in the first part of the test if the failure is going to occur.

Solution/Action:

It is recommended that the 11770A or 11768-80012 be replaced with the latest revision if this failure is seen.