

MODIFICATION AVAILABLE – PERFORMANCE ENHANCEMENT
 CHARGEABLE TO CUSTOMER SERVICE / RELIABILITY
 ENHANCEMENT CHARGEABLE TO CONTRACT IF THERE IS ONE.

E4404B-13

S E R V I C E N O T E

Supersedes:
 NONE

E4404B 6.7 GHz ESA Spectrum Analyzer

Serial Numbers Malaysia Manufactured: MY41441084 / MY41441151

An incorrectly manufactured transformer used in the 2nd Converter may cause no L.O. Feedthrough or other input signals to be viewed on the display of the ESA at initial power up.

To Be Performed By: Agilent Service Centers Only unless the customer has the required equipment and PC based software to perform the ESA Adjustment and Performance tests.

P/N	Description	Qty.
5086-7958	2 nd Converter Assy.	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:	AGREEABLE TIME	<input type="checkbox"/> PERFORMANCE ENHANCEMENT <input checked="" type="checkbox"/> SERVICE / RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	AVAILABLE UNTIL: April, 2006
AUTHOR: BAD PRODUCT LINE: 12		
ADDITIONAL INFORMATION: Scrap any defectives since the 2 nd Converter is not an exchange item.		

© AGILENT TECHNOLOGIES, INC. 2004
 PRINTED IN U.S.A.



April 2, 2004

Situation:

Incorrectly manufactured transformers installed on a small printed circuit board used inside the 2nd Converter may cause no L.O. Feedthrough or no signals to be viewed on the display of the ESA at initial power up for the serial range specified above. Once the instrument warms up for a few minutes, the L.O. Feedthrough and other input signals may appear on the analyzer display.

Solution/Action:

If an instrument within the serial number range specified above is not displaying the L.O. Feedthrough signal or any other input signals, the 2nd Converter may be the root cause. Agilent recommends that the 2nd Converter should be changed. Once the 2nd Converter is changed, verify the cold start up issue with the L.O. Feedthrough and other input signals is now operating correctly. The following tests should be performed after the 2nd Converter is changed:

Performance Tests:

- Displayed Average Noise Level
- Frequency Response
- Residual FM