A MODIFICATION ONLY - DOES NOT COMMUNICATE

E4408B-10

SERVICE NOTE

Supersedes: NONE

ESA Series Spectrum Analyzers

Serial Numbers: US00000000 / US99999999

MY00000000 / MY999999999 SG00000000 / SG99999999

Input Attenuator Switching appears to be incorrect

Parts	Required:
1 al to	ixcquii cu.

P/N Description Qty.

None

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: MPM PRODUCT LINE: 12

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2005 PRINTED IN U.S.A.

Agilent Technologies

February 11, 2005

Page 2 of 2 E4408B-10

Situation:

There are different input attenuators for the various configurations that are available for these products, which require different switching logic. Because of this it is possible to have what appears to be a hardware problem that is actually caused by having the Model Number, Frequency Range, or Option UKB status set improperly. While the Processor Initialization utility in the current version of the field software will straighten out the Model Number and Frequency Range settings, it will not correct the Option UKB status. This could then make it appear that there is either a problem with the input attenuator itself or the control logic, possibly resulting in much time spent in troubleshooting a perceived hardware problem that does not exist.

Solution/Action:

There are 3 different settings on the Service menu of the instrument that can potentially cause/correct this problem. They are:

- Model Number
- Maximum Frequency
- Option UKB status

These can all be set correctly by accessing the Service Menu by pressing:

[System]{More}{More}{Service} enter passcode* {Service}{More}{Initialize Instrument**}

Where do you find the correct values for these settings?

Model Number
Maximum Frequency
Option UKB status
Front panel label just above the display
Front panel label just above the display

9KHz start frequency = UKB No
100Hz start frequency = UKB Yes

Warning: Setting these values to anything other than what is actually installed in the instrument <u>will cause problems</u>, which is why this service note is written. You cannot enable any extended functionality without having the corresponding hardware installed.

^{*} The passcode can be found in the Service Guide under "Using the Internal Service-Diagnostic Routines"

^{**} Requires firmware version A.08.00 or newer. The latest firmware can be downloaded for free from http://www.agilent.com/find/esa firmware