37724A-02

S	Е	R	V		С	Е	Ν	0	Т	Ε
							SUPERSEDE	S: None)	
377	24A SE)H Tes	t Set							
Serial Numbers: 0000U00000 / 3305U00540*										
	is Service n) firmwa					1				
Path Overhead byte programming problem fix.										
To Be Performed By: Agilent-Qualified Personnel										
Part	s Requir No. 24-60012	Desc	ription 1 Drawer			e f. Desig ear Panel				
Prob	ation: lems occu function a			progra	m path o	verhead b	ytes on instrum	ents whic	h have a	
1. V	When TU	Path AI	S is alrea	dy set.						
	When a te are trying	_	nce is alr	eady rı	unning w	hich invo	lves the path ove	erhead by	rte you	
								C	Continued	
							DATE: August	1994		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:									
MODIFICATION RECOMMENDED									
ACTION CATEGORY:	 IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME 	STANDARDS: Labor 1.0 Hour							
LOCATION CATEGORY:	 CUSTOMER INSTALLABLE ON-SITE SERVICE CENTER 	SERVICE							
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: August 1996							
AUTHOR: ER	ENTITY: 1400	ADDITIONAL INFORMATION:							

© 1994 AGILENT TECHNOLOGIES
PRINTED IN U.S.A.



The problem shows itself with a screen display of "Not Allowed - Test Function Active". The instrument path overhead becomes locked and remains that way even after you deselect the test function being run - you cannot program the path overhead bytes.

Action:

In the event of a customer complaint matching the above situation, order a replacement ROM drawer, part number 37724-60012. This will contain new firmware to fix the problem. Simply remove existing rear panel ROM drawer and replace it. Once replaced, confirm instrument operation by running Self Test (contained in Service Manual, p/n 37724-90000).