S E R V I C E N O T E

SUPERSEDES: None

8920A RF Communications Test Set

Motherboard Replacement

Parts Required:

Part No.	Qty	Description
0535-0109	2	Nut, Hex
08920-00110	1	RF Cover, Motherboard
08920-60328	1	Assembly, Motherboard
08920-61076	1	Jumper, Semi-rigid cable

Situation:

8920A Motherboard assemblies 08920-60128 and 08920-60228 are obsolete and are not available for replacement. If it becomes necessary to replace one of these assemblies, additional parts are required to retrofit the replacement Motherboard assembly 08920-60328.

Solution/Action:

Remove the original motherboard assembly and the RF cover as shown in the disassembly procedures in the 8920A Assembly Level Repair manual, part number 08920-90036. Install the replacement motherboard assembly 08920-60328 and the RF cover 08920-00110. Re-install all semi-rigid and flexible cables in their original locations. In addition, install semi-rigid jumper 08920-61076 between RF connectors J55 and J56 on the motherboard. Use hex nuts 0535-0109 to secure the jumper to the RF connectors. J54 is not used for the 8920A.

DATE: 04 March 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICA	ATION:		
INFORMATION ONLY			
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:	
LHL	1000		

© 1993 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

