

8922HR-01

HP 8922H GSM MS Test Set

0000A00000 / 9999Z99999

Y2K update information.

Product requires installation of 8922H to M upgrade kit 8922U #101, which will upgrade to 8922M functionality and have latest firmware, to be Y2K compliant to HP standards.(see situation)  
8922M firmware below B.07.07 is not Y2K compliant to HP standards.

Duplicate Service Notes:

8922H-01

To Be Performed By:

HP-Qualified Personnel

Parts Required:

HP P/N	Description	Quantity
8922U #101	8922H to M upgrade	1

Situation:

Y2K investigation has identified that the response from the BASIC function TIMEDATE is defective. This defect exists now and a TIMEDATE call would fail now if called in any BASIC application. Detection of this bug has caused all 8922 instruments below firmware B.07.07 (or C.01.03 for 8922P,R,X,Y) to be classified as Y2K non-compliant. This bug has not been reported by customers which implies that it has not used in any applications to date.

Failure to install the Y2K upgrade will not cause the HP8922H to return an incorrect date/time stamp on 1st January 2000.

Solution / Action:

8922U #101 needs be installed to turn the 8922H into a 8922M with firmware above B.07.06 to meet HP Y2K compliance standards. This fixes the TIMEDATE bug but does not affect any other date-related processes within the instrument.

The 8922H will return the correct date/time stamp on 1st January 2000, without modification. It is recommended that no upgrade is required.

Date: 24 August 1998

```

*****
*
*           MODIFICATION AVAILABLE           *
*           -----                       *
*
* REASON:           PERFORMANCE ENHANCEMENT _X *
*   -or- SERVICE/RELIABILITY ENHANCEMENT ___ *
* ACTION CATEGORY: AGREEABLE TIME           *
* LOCATION CATEGORY: CUSTOMER INSTALLABLE ___ ON-SITE ___ *
*                   HP LOCATION _X         *
* AVAILABLE UNTIL:  _END OF SUPPORT LIFE    *
* AUTHOR/ENTITY:   _AS/E600                 *
* ADDITIONAL INFO: _____               *
*
*****

```

