## 8922P-01

HP8922P GSM MS Multiband Test System comprises HP8922M #010 GSM MS Test Set and HP83220E #010 DCS/PCS MS Test Set

Serial Numbers:
0000A00000 / 9999Z99999

Y2K update information.

Product requires firmware revision C.01.03 or later to be Y2K compliant to HP standards (see situation). Firmware C.01.02 or below is not Y2K compliant to HP standards.

Duplicate Service Notes: 8922M-04, 8922MR-01

To Be Performed By: HP-Qualified Personnel.

## Parts Required:

 ${
m HP8922P/X}$  'Flash' firmware upgrade. This can be performed at either a HP Service Centre or the customer site. A suitable PC with HPIB capability and HP BASIC is required. Firmware can be downloaded from

http://hpweb.sqf.hp.com/QMD\_Mktg/prodsup/8922.htm

## Situation:

Y2K investigation has identified that the response from the BASIC function TIMEDATE is defective. This defect exists now and a TIMEDATE call would fail now if called in any BASIC application. Detection of this bug has caused all 8922 instruments below firmware B.07.07 (or C.01.03 for 8922P,R,X,Y) to be classified as Y2K non-compliant. This bug has not been reported by customers which implies that it has not used in any applications to date.

Failure to install the Y2K upgrade will not cause the HP8922P to return an incorrect date/time stamp on 1st January 2000.

## Solution / Action:

A firmware upgrade (download into flash memory) needs to be performed to install firmware C.01.03 or above to meet HP Y2K compliance standards. This fixes the TIMEDATE bug but does not affect any other date-related processes within the instrument.

The 8922P will return the correct date/time stamp on 1st January 2000, without modification. It is recommended that no upgrade is required.

Date: 24 August 1998