8922Y-02

S	Е	R	V	Ι	С	Е		Ν	0	Т	Е
							SUPEF	RSEDES	3: NON	E	
892	2 GSM	I Test S	Sets.								
Seria	al Numb	ers: 000	00A000	0 / 9999	9Z99999						
		n Distri ; failure		board	l modifi	ed to a	account	for Po	otential	Audio	
Dup	licate Se	rvice No	tes:								
	A-03										
	B-03										
8922 8922											
	G-03										
	H-02										
	M-08										
8922											
	R-02										
8922											
	X-05										
8922	Y-02										
To B	e Perfor	med By:			fied Perso	onnel					
			Custor	ner							
										Continued	d
							DATE:	Septe	mber 19	99	

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: MODIFICATION RECOMMENDED						
ACTION						
CATEGORY:	ON SPECIFIED FAILURE	LABOR 0.5 Hours				
LOCATION CATEGORY:	 ☐ CUSTOMER INSTALLABLE ☐ ON-SITE ☐ SERVICE CENTER 	SERVICE RETURN USED RETURN INVENTORY: SCRAP SCRAP SCRAP SEE TEXT SEE TEXT SEE TEXT				
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: September 2001				
AUTHOR: DO	ENTITY: E600	ADDITIONAL INFORMATION:				

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Parts Required:

P/N	Description	Quantity		
08922-69164	Refurb. Mod. Dist. Bd.	1		
Situation:				
Audio Diagnostic Test failures seen in the field				

Audio Analyser 1 - Internal Paths Test

	Lower	Upper	Actual
AC, Gain = 100, Range Det	1.553	1.898	2.271**

This test applies a 50mVpp sine wave to the Audio 1 board.Since it is a relatively low level signal (compared with the Gain =10 (0.5Vpp), Gain =1 (5Vpp)) it is susceptible to noise. The fault was diagnosed as due to a high noise contribution from U402 (TL072). Replacing with 1826-3000 (OP275GS) Low Noise Amp solved the problem. This fault does not affect the performance of the unit.

Solution / Action:

Replace the Modulation Distribution Board (A4) (08922-60164) with refurbished board (08922-69164) The replacement part is an exchange part. Old board must be returned to QMD to receive the refurbished board.