J2127A-07

SERVICE NOTE

Supersedes: None

AGILENT J2127A Transmission Test Set

Serial Numbers: GB27000487, 488, 489, 490, 491, 493, 495, 496

Possible damage tracks caused by wrongly fitted stand-off.

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

J1413-00025 Polycarbonate Tape

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	X IMMEDIATELY [] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS: LABOR: 2.0 Hours
LOCATION CATEGORY: TEXT	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER	SERVICE [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: [[]] SCRAP [[]] SEE TEXT [] SEE TEXT □ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: February 2004
AUTHOR: JH	PRODUCT LINE: PY	
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2002 PRINTED IN U.S.A.



Page 2 of 3 J2127A-07

Situation:

Due to a design problem on the Control Assembly (J1413-65001), a stand-off has been fitted the over tracks on the Processor Assembly (J1413-65002). Vibration may cause the stand-off to damage the tracks (which go to the flash card) and this may cause the instrument to fail on boot-up.

Solution/Action:

The Control Assembly should be dismantled and the affected tracks on the Processor Assembly should be protected with polycarbonate tape. Refer to Figure 1 for the location of the polycarbonate tape.

Page 3 of 3 J2127A-07




Figure 1 Location of the Polycarbonate Squares