E1420B-01

S	Е	R	V	Ι	С	Е	Ν	0	Т	Е
							SUPERSEDE	ES: NON	E	
E14	420B 7	5000 S	eries C	Univ	versal (Counter				
Inte	ermitte	nt *TST	? Self-1	fest F	ailure					
Seri	ial Numb	bers: 000	0A00000	/ 9999	A99999					
To I	To Be Performed By: Agilent-Qualified Personnel or Customer									
Pro	Problem:									
	All E1420B counters which have REV B.02.00 or REV B.02.40 firmware installed may exhibit an intermittent *TST? self-test timebase failure.									
Pro	blem Ide	entificatio	on:							
-	combina exist:	ation of tl	ne comma	and stri	ng result	s below are	e an indication	that the p	oroblem	
*ID	N?					ILENT, EI	1420B,0, OR REV B.02	40		
*TS	Т?					OR +1, Int		.40		
	G:ASS:	ALL?				JLED, AL				
DIA	G:ASS:A	A 1?				ILED, A1				
DIA	G:BLOC	C:ALL?			-> "FA	ILED, BL	OCK, TIM"			
								C	Continued	!
						ſ	DATE: 18 Sep	otember ⁻	1992	

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICA	ATION:							
INFORMATION ONLY								
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:						
AI	0200							

© 1992 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



DIAG:BLOC:COUN:ALL? DIAG:BLOC:COUN:TIM?

-> "FAILED, COUN, TIM" -> "TIMEBASE TEST: CLK10 PASSED INT MISSING EXT FAILED"

Solution:

Whenever performing the instrument self-test *TST?, or performing any timebase-related diagnostics, connect a 10MHz reference standard to the Int/Ext BNC input on the E1420B front panel.