

S E R V I C E N O T E

SUPERSEDES: NONE

E1431A 25.6 kHz 8 Channel VXI Input Module

Serial Numbers: 0000A00000 / 3425A99999

High Temperature operational failure may not be reported by diagnostics.

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

Part No.	Qty.	Description
E1431-69201	1	Exchange E1431A module

Continued

DATE: August 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR: MJL	ENTITY: A100	ADDITIONAL INFORMATION:

Situation:

The E1431A module may report an error when the customer is performing an “e1431_auto_zero_and_phase()” function in the C Interface Library. The error may also be reported for customers using the SCPI command: “INPut:PHASe:AUTO”. This error may occur only if the module temperature is greater than approximately 55C.

The following error messages will be returned when a module fails due to this problem:

“Auto zero timed out waiting for data”

and if the C Libraries are being used, they will return error number 1275. Since a customer could have the module fail at a high temperature and the Service Center not see the problem at room temperature, the Service Center needs to look for customer complaints that refer to this error message.

If the customer does not use Phase Calibration and does not use the SumBus, then they are not at risk of having a problem. The function “e1431_auto_zero()” is not affected and works correctly.

Solution/Action:

Replace the module if the customer complains about this error. Indicate on the returned module that this was the failure mode. This will aid the factory repair of the module.