

S E R V I C E N O T E

SUPERSEDES: 89430A-01

**E1431A 25.6 kHz 8 Channel VXI Input Module**

Serial Numbers: 3416A00101 / 3440A99999

- A. Firmware update to correct defects causing module lock-up.**
- B. "Unknown Revision" software message explanation**

**Parts Required:**

| Part No.    | Qty. | Description                  |
|-------------|------|------------------------------|
| E1431-19414 | 1    | Disk-SCPI Driver A.00.04     |
| E1431-19415 | 1    | Disk-Programming A.00.04     |
| E1431-19416 | 1    | DAT Tape-Programming A.00.04 |

**Equipment Required: Qty**

|                   |   |                         |
|-------------------|---|-------------------------|
| * E1431A Swe Disk | 1 | Firmware Update Utility |
| E1406A            | 1 | Command Module          |
| E1401A/B/T        | 1 | "C" size VXI Mainframe  |
| RMB Workstation   | 1 | Series 200/300          |

\*To obtain this disk, you must contact your LSID on-line support engineer currently responsible for supporting the E1431A. A disk and installation sheet will be sent to you at no charge. THIS IS ONLY AVAILABLE FOR FIELD SERVICE OFFICES. THIS UTILITY IS NOT FOR CUSTOMER USE.

*Continued*

DATE: May 1995

**ADMINISTRATIVE INFORMATION**

|                                 |   |                                     |   |
|---------------------------------|---|-------------------------------------|---|
| SERVICE NOTE CLASSIFICATION:    |   |                                     |   |
| <b>MODIFICATION RECOMMENDED</b> |   |                                     |   |
| ACTION CATEGORY:                | <input type="checkbox"/> IMMEDIATELY<br><input type="checkbox"/> ON SPECIFIED FAILURE<br><input checked="" type="checkbox"/> AGREEABLE TIME | STANDARDS:                          | Labor 1.0 Hour  |
| LOCATION CATEGORY:              | <input type="checkbox"/> CUSTOMER INSTALLABLE<br><input type="checkbox"/> ON-SITE<br><input checked="" type="checkbox"/> SERVICE CENTER     | SERVICE INVENTORY:                  | <input type="checkbox"/> RETURN<br><input type="checkbox"/> SCRAP<br><input checked="" type="checkbox"/> SEE TEXT |
| AVAILABILITY:                   | PRODUCT'S SUPPORT LIFE  | USED PARTS:                         | <input type="checkbox"/> RETURN<br><input type="checkbox"/> SCRAP<br><input checked="" type="checkbox"/> SEE TEXT |
| AUTHOR: MJL                     | ENTITY: A100  | AGILENT RESPONSIBLE UNTIL: May 1998 |   |
|                                 |   | ADDITIONAL INFORMATION:             |   |

**Situation A:**

Units with serial numbers listed above contain several firmware defects which can cause the customer's system to lock-up. These defects are:

- If local bus is used, the block size must be greater than 16.
- Block size cannot be increased using SCPI, only decreased. To increase the block size, cycle power and then select a new block size.
- The Trigger Level cannot be changed when using SCPI.
- The following setup combination cannot be used:

6.25Hz Trigger Delay 0, manual ARM and manual Trigger

**Situation B:**

If customer's application software displays the following message, it indicates that the firmware revision in their E1431A module is newer than their software libraries:

```
"!!! WARNING - E1431 at logical address xxx reports  
unknown revision, date = xxxx"
```

**Solution/Action:**

The module should be returned to a Service Center for firmware update. The service center will upload new firmware into the E1431A FLASH ROM and return the unit.

The customer's software libraries should also be updated at this time or the WARNING message listed above could occur. To do this, order the three part numbers listed at the top (-19414, -19415, -19416) and ship them back to the customer with the updated module. These libraries are revision A.00.04.

|                |
|----------------|
| <b>CAUTION</b> |
|----------------|

Note that if a customer has compiled applications from earlier versions of the software libraries, these applications may not work properly after the firmware update. If this happens, the customer will have to rebuild/compile the application using the newer libraries which were shipped back with the updated module (Revision A.00.04).