S Ε VICE R E N Т

SUPERSEDES: None

E1431A 25.6 kHz 8 Channel VXI Input module

Serial Numbers: 3416A00101 / 3445A10000

Module replacement to correct defects causing module lock-up

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N **Description** Qty. E1431-69201 Exchange E1431A

Equipment Required:

P/N **Description** Qty. E1406A Command Module "C" size VXI Mainframe E1401A/B/T

RMB Workstation Series 200/300

Continued

DATE: May 1995

ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: | | |
|------------------------------|---|---|
| MODIFICATION RECOMMENDED | | |
| ACTION CATEGORY: | ☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME | STANDARDS: Labor 0.5 Hours |
| LOCATION CATEGORY: | ☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER | SERVICE RETURN USED RETURN INVENTORY: SCRAP SEE TEXT SEE TEXT |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | AGILENT RESPONSIBLE UNTIL: May 1997 |
| AUTHOR: MJL | ENTITY: A100 | ADDITIONAL INFORMATION: |

© 1995 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Situation:

Some units, with serial numbers listed above, contain a low-temperature sensitivity which can cause the E1431A to lock-up. This failure occurs at power-up only. The failure mode is for the following front panel LEDs to stay lit after power-up.

- Failed LED
- Trigger LED
- Acquire LED

This problem is intermittent and only occurs at temperatures between 0C and 20C degrees.

Solution/Action:

If the customer complains about this failure mode, yet the module passes its *TST? diagnostic test, replace it with an exchange module with serial prefix 3518A or above. It is important to document this failure on the CSO in order for the factory to perform the proper repair on the returned module.