

## TECHNICAL MANUAL

### MAINTENANCE INSTRUCTIONS WITH ILLUSTRATED PARTS BREAKDOWN DEPOT

# RADIO FREQUENCY AMPLIFIER, AM-7224/URC, P/N 10087-0000

HARRIS CORPORATION, RF COMMUNICATIONS GROUP  
FO4606-82-D-0079  
FO9603-94-D-1349

**BASIC AND ALL CHANGES  
HAVE BEEN MERGED TO MAKE  
THIS A COMPLETE PUBLICATION**

**DISTRIBUTION STATEMENT** – Distribution authorized to U.S. Government agencies only (Administrative or Operational Use) (15 August 1991). Questions concerning technical content should be directed to WR-ALC/LYRG. Other requests for this document shall be referred to WR-ALC/LYE, Robins AFB GA 31098.

**WARNING** – This document contains technical data whose export is restricted by the Arms Export Control Act (Title 22, U.S.C., Sec. 2751 *et seq.*) or the Export Administration Act of 1979, as amended (Title 50, U.S.C., App. 2401 *et seq.*). Violations of these export laws are subject to severe criminal penalties.

**HANDLING AND DESTRUCTION NOTICE** – Comply with distribution statement and destroy by any method that will prevent disclosure of the contents or reconstruction of the document.

---

PUBLISHED UNDER AUTHORITY OF THE SECRETARY OF THE AIR FORCE

**LIST OF EFFECTIVE PAGES**

INSERT LATEST CHANGED PAGES. DESTROY SUPERSEDED PAGES.

NOTE: The portion of the text affected by the changes is indicated by a vertical line in the margins of the page. Changes to illustrations are indicated by miniature pointing hands. Changes to wiring diagrams are indicated by shaded areas

Dates of issue for original and changed pages are:

Original ..... 0..... 15 Jan 86  
 Change ..... 1..... 23 Mar 90  
 Change ..... 2..... 15 Aug 91  
 Change ..... 3..... 27 Mar 92  
 Change ..... 4..... 8 Nov 99

TOTAL NUMBER OF PAGES IN THIS PUBLICATION IS 150 CONSISTING OF THE FOLLOWING:

Page No.	*Change No.	Page No.	*Change No.	Page No.	*Change No.
<b>Title</b> .....	4	FP-4 Blank	0		
<b>A</b> .....	4	FP-5	0		
i - viii	0	FP-6 Blank	0		
6-1 - 6-26	0	FP-7	0		
<b>6-27</b>	4	FP-8	0		
6-28 - 6-35	0	FP-9	0		
6-36 Blank	0	FP-10	0		
7-1 - 7-14	0	FP-11	0		
7-15	2	FP-12 Blank	0		
7-16	0	FP-13	0		
7-17	3	FP-14 Blank	0		
7-18 - 7-22	0	FP-15	0		
7-23 Blank	0	FP-16 Blank	0		
7-24 - 7-26	0	FP-17	0		
7-27	1	FP-18 Blank	0		
7-28 - 7-46	0	FP-19	0		
7-47 Blank	0	FP-20 Blank	0		
7-48 - 7-56	0	FP-21	0		
7-57 Blank	0	FP-22 Blank	0		
7-58 - 7-70	0	FP-23	0		
7-71	1	FP-24 Blank	0		
7-72 - 7-78	0	FP-25	0		
8-1	0	FP-26 Blank	0		
8-2 Blank	0	FP-27	0		
FO-1	0	FP-28 Blank	0		
FO-2 (1 of 1)	0	FP-29	0		
FO-2 (2 of 2)	0	FP-30 Blank	0		
FO-3	0	FP-31	0		
FO-4	0	FP-32 Blank	0		
FO-5	0	FP-33	0		
FO-6	0	FP-34 Blank	0		
FO-7	0				
FO-8 (1 of 4)	0				
FO-8 (2 of 4)	0				
FO-8 (3 of 4)	0				
FO-8 (4 of 4)	0				
FO-9 (1 of 3)	0				
FO-9 (2 of 3)	0				
FO-9 (3 of 3)	0				
FO-10	0				
FO-11	0				
FP-1	0				
FP-2 Blank	0				
FP-3	0				

\*Zero in this column indicates an original page

## SAFETY SUMMARY

The following are general safety precautions that are not related to any specific procedures and therefore do not appear elsewhere in this publication. These are recommended precautions that personnel must understand and apply during many phases of operation and maintenance.

### KEEP AWAY FROM LIVE CIRCUITS

Operating personnel must at all times observe all safety regulations. Do not replace components with the power supplies turned on. Under certain conditions, dangerous potentials may exist when the power control is in the off position, due to charges retained by capacitors. To avoid casualties, always remove power and discharge circuits to ground before touching any circuit components. Remove watches and rings before performing any maintenance procedures.

### DO NOT SERVICE OR ADJUST ALONE

Under no circumstances should any person reach into or enter the enclosure for the purpose of servicing or adjusting the equipment except in the presence of someone who is capable of rendering aid.

### RESUSCITATION

Personnel working with or near high voltages should be familiar with modern methods of resuscitation.

Cardiopulmonary resuscitation procedures are outlined in T.O. 31-1-141-1, and annual refresher training requirements are outlined in AFOSH STD 127-50.

The following warnings appear in the text in this volume, and are repeated here for emphasis.

**WARNING**

Voltages dangerous to life exist in this radio equipment. Before removing the top cover, disconnect the primary power and wait 30 seconds. This allows time for all voltages to bleed off.

### HANDLING OF ELECTROSTATIC DISCHARGE SENSITIVE DEVICES (ESDS)

Electrostatic Discharge Sensitive Devices (ESDS) must be handled with certain precautions that must be followed to minimize the effect of static build-up. Consult T.O. 00-25-234, DOD Std-1686, and DOD HDBK 263. ESDS devices are identified in this technical order by the following symbol:



TABLE OF CONTENTS

Section/Para	NOTE	Page
For chapters 1-5, see the On-Equipment Manual, T.O. 31R2-2URC-121.		
CHAPTER 6. MAINTENANCE		
I	INTRODUCTION	
	6-1. Chapter Organization.....	6-1
II	ALIGNMENT PROCEDURES	
	6-2. Introduction.....	6-1
	6-3. Adjustment Procedures.....	6-2
III	DIAGNOSTIC PROCEDURES	
	6-4. Depot Maintenance Philosophy.....	6-11
	6-5. Tube Assy, A1.....	6-11
	6-6. Tank Assy, A2.....	6-12
	6-7. VSWR/XFMR PWB Assy, A3.....	6-15
	6-8. Fan Inverter PWB Assy, A4.....	6-17
	6-9. Power Control PWB Assy, A5.....	6-17
	6-10. Micro Control PWB Assy, A6.....	6-20
	6-11. Front Panel PWB Assy, A7A1.....	6-23
	6-12. Temp Sensor PWB Assy, A8.....	6-25
	6-13. Interconnect PWB Assy, A9.....	6-27
	6-14. Low Pass Filter Assy, A10.....	6-28
IV	REMOVAL/REPLACEMENT PROCEDURES	
	6-15. Removal/Replacement Procedures.....	6-29
APPENDIX	.....	6-33

CHAPTER 7. ILLUSTRATED PARTS BREAKDOWN

I	INTRODUCTION	
	7-1. Purpose.....	7-1
	7-2. Scope.....	7-1
	7-3. Chapter Organization.....	7-1
	7-4. Source, Maintenance, and Recoverability (SMR) Codes.....	7-1
	7-5. Federal Supply Codes for Manufacturers (FSCM).....	7-1
II	MAINTENANCE PARTS LIST	
III	NUMERICAL INDEX	
IV	REFERENCE DESIGNATOR INDEX	

CHAPTER 8. FOLDOUT DRAWINGS

## LIST OF ILLUSTRATIONS

Figure		Page
CHAPTER 6. MAINTENANCE		
6-1	1 KW LPA .....	6-3
6-2	VSWR/XFMR PWB Assy .....	6-5
6-3	Power Control PWB Assy .....	6-7
6-4	Temp Sensor PWB Assy .....	6-10
CHAPTER 7. ILLUSTRATED PARTS BREAKDOWN		
7-1	1 KW LPA, AM-7224/URC, Front View .....	7-14
7-2	1 KW LPA, AM-7224/URC, Exploded View .....	7-16
7-3	Installation Kit for 1 KW LPA .....	7-18
7-4	Tube Assy, A1 .....	7-20
7-5	Bias/Sample PWB Assy, A1A1 .....	7-24
7-6	Tank Assy, A2, Exploded View .....	7-26
7-7	Tank Assy, A2, Bottom View .....	7-28
7-8	Tune Capacitor No. 1 Assy, A2A1 .....	7-30
7-9	Tune Capacitor No. 2 Assy, A2A2 .....	7-32
7-10	Load Capacitor No. 1 Assy, A2A3 .....	7-34
7-11	Load Capacitor No. 2 Assy, A2A4 .....	7-36
7-12	Coil PWB Assy, A2A5 .....	7-38
7-13	Coil Drive Assy, A2A6 .....	7-40
7-14	Servo/Bandswitch Drive PWB Assy, A2A7 .....	7-42
7-15	VSWR/XFMR PWB Assy, A3 .....	7-44
7-16	Fan Inverter PWB Assy, A4 .....	7-48
7-17	Power Control PWB Assy, A5 .....	7-50
7-18	Micro Control PWB Assy, A6 .....	7-54
7-19	Front Panel PWB Assy, A7A1 .....	7-58
7-20	Temp Sensor PWB Assy, A8 .....	7-60
7-21	Interconnect PWB Assy, A9 .....	7-62
7-22	Low Pass Filter PWB Assy, A10 .....	7-64
7-23	Connector PWB Assy, A11 .....	7-66
CHAPTER 8. FOLDOUT DRAWINGS		
FO-1	Family Tree 1 KW LPA .....	FP-1
FO-2	Interconnection Diagram .....	FP-3
FO-3	Tube PWB Assy, A1A1 .....	FP-7
FO-4	Tank Assy, A2 .....	FP-9
FO-5	Servo/Bandswitch Drive PWB Assy, A2A7 .....	FP-11
FO-6	VSWR/XFMR PWB Assy, A3 .....	FP-13
FO-7	Fan Inverter PWB Assy, A4 .....	FP-15
FO-8	Power Control PWB Assy, A5 .....	FP-17
FO-9	Micro Control PWB Assy, A6 .....	FP-25
FO-10	Front Panel PWB Assy, A7A1 .....	FP-31
FO-11	Interconnect PWB Assy, A9 .....	FP-33

LIST OF TABLES

Table	CHAPTER 6. MAINTENANCE	Page
6-1	Test Equipment .....	6-2

## GLOSSARY

A	Ampere(s)
A/D	Analog-to-Digital (Converter)
AFSK	Audio frequency shift keying; a baseband modulation scheme in which two audio frequencies are used to represent binary coded data; the frequency is shifted to one frequency to represent a 1 (mark) and to the other to represent a 0 (space).
AGC	Automatic gain control
ALE	Address latch enable
AM	Amplitude modulation; a modulation scheme in which the carrier is made to vary in amplitude in accordance with the modulating signal.
AME	Amplitude modulation equivalent
ANTIVOX	Prevents false VOX operation; see VOX
BFO	Beat Frequency Oscillator, used in SSB detection circuits
BIT	Built-in Test
BIU	Bus interface unit
BW	Bandwidth
CPU	Central processing unit
CREV	Converter reverse
CW	Continuous wave; a wave that does not vary in amplitude or frequency and is turned on and off to carry intelligence, e.g., Morse Code
D/A	Digital-to-Analog (Converter)
dB	Decibel(s)
dBm	Decibel(s) relative to one milliwatt
EMI	Electromagnetic interference
EPROM	Erasable programmable read-only memory
EU	Execution unit
HF	High frequency; a radio frequency band extending from about 3 MHz to 30 MHz; in this manual, HF includes 1.6 to 30 MHz.
HV	High voltage
IF	Intermediate frequency
IM	Intermodulation (distortion)
I/O	Input/Output
KREV	Keyer reverse
LCD	Liquid crystal display
LED	Light emitting diode
LPA	Linear power amplifier
LSB	Lower sideband; a modulation scheme in which the intelligence is carried on the first sideband below the carrier frequency; see SSB
MIC	Microphone
mA	Milliampere(s)
mV	Millivolt(s)
NBSV	Narrow band secure voice
PEP	Peak envelope power
PPC	Peak power control
PWB	Printed wiring board
RAM	Random access memory
rms	Root mean square
RTC	Real time clock
RX	Receive

GLOSSARY (Continued)

S TONE	Sidetone
SSB	Single sideband; a modulation scheme in which the intelligence is carried by one of the carrier sidebands, the other sideband and the carrier center frequency being suppressed
TGC	Transmitter gain control
TX	Transmit
μA	Microampere(s)
μP	Microprocessor
USB	Upper sideband; a modulation scheme in which the intelligence is carried on the first sideband above the carrier frequency; see SSB
μV	Microvolt(s)
Vac	Volts, alternating current
VCO	Voltage controlled oscillator
Vdc	Volts, direct current
VOX	Voice operated transmission
VSWR	Voltage standing wave ratio; the ratio of the maximum to the minimum voltage of a standing wave on a radio frequency transmission line
W	Watt(s)



## INTRODUCTION

The purpose of this manual is to provide information necessary for the depot-level maintenance of Amplifier, Radio Frequency, AM-7224/URC, manufactured by the RF Communications Group of Harris Corporation, Rochester, New York. The manual is divided into three chapters. The contents of each chapter are briefly described in the following paragraphs.

### NOTE

This manual only contains three chapters, because chapters 1-5 are contained in the On-Equipment Manual, T.O. 31R2-2URC-121. For a description of the contents of these chapters, see the INTRODUCTION in T.O. 31R2-2URC-121.

Chapter 6 describes the depot-level maintenance procedures. The maintenance procedures in this chapter are based on performance testing and trouble analysis of the subassembly or PWB to locate and replace faulty parts at the lowest replaceable unit level (LRU).

Chapter 7 contains the Illustrated Parts Breakdown (IPB) information at the depot level. This includes assemblies and parts that may be replaced at the depot location.

Chapter 8 contains foldout (FO) drawings, which consist of the schematic diagrams of all the PWB assemblies. A cross reference list is also provided. The diagrams are numbered FO-1, FO-2, etc. They are printed on sheets with page-size blank aprons to permit viewing the diagram with the rest of the book closed or opened to another page.

The following specifications, standards, and publications were used in the preparation of this manual.

**APPLICABLE SPECIFICATIONS**

<b>SPECIFICATION</b>	<b>NAME</b>
MIL-M-38798B, para. 3.4	Combined Operation and Maintenance Instructions Manual (Equipment).
MIL-M-38807, Amend. 4	Preparation of Illustrated Parts Breakdown.
MIL-M-38790 and MIL-M-38784A	General Requirements for Preparation of Technical Manuals.

**APPLICABLE STANDARDS**

<b>STANDARD</b>	<b>NAME</b>
MIL-STD-12	Abbreviations for use on Drawings and in Technical Type Publications.
MIL-STD-15-1A	Graphic Symbols for Electrical Components.
MIL-STD-17-1	Mechanical Symbols.
MIL-STD-806	Graphic Symbols for Logic Diagrams.

**APPLICABLE PUBLICATIONS**

<b>PUBLICATION</b>	<b>NAME</b>
DOD 5200.20	Distribution Statements on Technical Documents.
USAS Y14.15-1966	Electrical and Electronic Diagrams.
USAS Y32.16-1968	Electrical and Electronic Reference Designations.
T.O. 31-1-141 (Series)	Technical Manual-Basic Electronic Technology and Testing Practices.

## CHAPTER 6

### MAINTENANCE

---

**WARNING**

Voltages dangerous to life exist in this radio equipment. Before removing the top cover, disconnect the primary power and wait 30 seconds. This allows time for all voltages to bleed off.

#### Section I. INTRODUCTION

**6-1. CHAPTER ORGANIZATION.** This chapter is divided into four sections. Section I tells how the chapter is organized. Section II contains alignment procedures for the replaceable modules. This information is also contained in the On-Equipment Manual, T.O. 31R2-2URC-121, and is repeated here for convenience. Section III consists of diagnostic procedures which will enable you to

troubleshoot faulty modules to the component level. These procedures are based on use of the BIT feature. For more information on BIT, as well as removal/replacement procedures and periodic maintenance procedures, see the On-Equipment Manual, T.O. 31R2-2URC-121. Section IV contains removal/replacement procedures for the internal components of the Tank Assembly.

#### Section II. ALIGNMENT PROCEDURES

**6-2. INTRODUCTION.** This section contains instructions for checking and adjusting the replaceable subassemblies in the 1KW LPA. This section also contains circuit board layouts to help you

identify the components that can be adjusted. To do the procedures described in this section, you need the test equipment listed in Table 6-1.

Table 6-1. Test Equipment

Generic Name	Military Designation	Manufacturer, Model No.	National Stock No.	Required Range
Electronic Voltmeter w/ AC Probe & T-connector		Hewlett Packard, Model 410C Model 11036A Model 11042A	6625-00-469-2258 6625-00-910-5973 5985-00-713-4356	20 to 224 V rms; 1.6 to 30 MHz (peak reading)
Digital Multimeter		Fluke, Model 8012A	6625-01-140-0221	200 mV to 250 Vac; 200 mV to 40 Vdc; 0 to 20 megohms
PROM Programmer		Data I/O, Model System 19	7045-01-115-8993	
Dummy Load		Bird, Model 8833	6625-00-225-9074	1000 W, 50 ohms
1 KW LPA	AM-7224/URC	RF Communications RF-353	5820-01-164-4871	
100 Watt Transceiver	RT 1446/URC	RF Communications RF-350K	5820-01-162-3402	
Power Supply	PP-7913/URC	RF Communications RF-354	6130-01-164-6580ZX	

NOTE: Equivalent Items Authorized

6-3. ALIGNMENT PROCEDURES

NOTE

After each of the following alignment procedures, disconnect test equipment and reconfigure equipment (module or circuit card) to normal operating condition.


- a. TUBE ASSY, A1 (figure 6-1)

R3, RF Plate Sample Adjustment

NOTE

This adjustment assumes the following initial conditions:

- The LPA has been turned off for a least 10 seconds.
- The LPA's AUTO/MANUAL BAND Switch is in the AUTO position.



353-036

Figure 6-1. 1 KW LPA

- (1) Using a Model 11042A T-connector, connect an HP-410C Voltmeter (or equivalent) between the LPA's RF output connector J5 and a dummy load.
- (2) Remove the top cover from the LPA, and pull the interlock switch all the way up to the "cheat" position.
- (3) Turn the LPA on and set the operating frequency at the transceiver to 7.0000 MHz in CW mode. After the LPA has warmed up (is in STANDBY), place LPA IN OPERATE and tune the system.
- (4) Place the LPA in Manual mode with the AUTO/MANUAL BAND Switch in the 6-8 position. Set the ANTENNA Switch to the 50 ohm position and the LOCAL KEY Switch to CN. Key the transceiver, and monitor the voltage on the RF voltmeter.
- (5) With a reading of  $223 \pm 2$  Vac on the meter, adjust R3 (accessible through a hole in the Tube Assy near the connector--see figure 6-1) so that the RF PLATE (VOLTS) position on the LPA front panel meter reads  $2100 \pm 20$ .
- (6) Return LOCAL KEY to OFF.

b. TANK ASSY, A2

No adjustments.

c. VSWR/XFMR PWB ASSY, A3 (figure 6-2)

(1) R5, Null Adjustment

**NOTE**

This adjustment assumes the following initial conditions:

- The LPA has been turned off for at least 10 seconds.
  - The LPA'S AUTO/MANUAL BAND Switch is in the AUTO position.
- (a) Connect the 1KW LPA antenna connector J5 to a dummy load.


- (b) Remove the top cover from the LPA, and pull the interlock switch all the way up to the "cheat" position.
- (c) Lower the LPA front panel to its horizontal position to gain access to the Power Control PWB Assy.
- (d) Connect a digital multimeter between test point TP2 and ground on the Power Control PWB Assy (see figure 6-3).
- (e) Turn the LPA on and set the operating frequency at the transceiver to 16.0000 MHz in CW mode. After the LPA has warmed up (is in STANDBY), place the LPA in OPERATE and tune the system.
- (f) Key the system and adjust R5 (on the VSWR/XFMR PWB Assy -- see figure 6-2) for a null (minimum voltage) on the multimeter.

(2) R8, Forward Power Sample

**NOTE**

This adjustment assumes the following initial conditions:

- The LPA has been turned off for at least 10 seconds.
  - The LPA'S AUTO/MANUAL BAND Switch is in the AUTO position.
- (a) Using a Model 11042A T-connector and a Model 11036A AC Probe, connect an HP-410C Voltmeter (or equivalent) between the LPA's RF output connector J5 and a dummy load.
  - (b) Remove the top cover from the LPA, and pull the interlock switch all the way up to the "defeat" position.
  - (c) Lower the LPA front panel to its horizontal position to gain access to the Power Control PWB Assy.



353-037A

Figure 6-2. VSWR/XFMR PWB Assy

- (d) Connect a digital multimeter between test point TP1 and ground on the A5 Power Control PWB Assy (see figure 6-3). Ensure that R34 is fully CCW and R74 is fully CW.
- (e) Turn the LPA on and set the operating frequency at the transceiver to 16.0000 MHz in CW mode. After the LPA has warmed up (is in STANDBY), place the LPA in OPERATE and tune the system.
- (f) Key the system and observe the output voltage on the HP-410C and the forward power sample voltage on the digital multimeter. The HP-410C should read  $223 \pm 2$  Vac and the multimeter should read  $7.00 \pm 0.05$  Vdc.
- (g) If both readings are within tolerance, no adjustment is required. If either reading is out of tolerance, adjust Loop Gain Potentiometer R29 on the Power Control PWB Assy so that the HP-410C reads 223 Vac. If the multimeter reading is  $7.00 \pm 0.05$  Vdc, no further adjustment is required.
- (h) If the multimeter reads less than 6.95 Vdc, adjust R29 on the Power Control PWB Assy for a reading of slightly less than 223 Vac on the HP-410C. Then adjust R8 on the VSWR/XFMR PWB Assy for a reading of 7 volts on the multimeter. Readjust R29 to increase the HP-410C reading toward 223 Vac. Continue to alternately adjust R29 toward 223 Vac and R8 toward 7 Vdc until the HP-410C reads  $223 \pm 2$  Vac and the multimeter reads  $7.00 \pm 0.05$  Vdc.
- (i) If the multimeter reads more than 7.05 Vdc, adjust R8 on VSWR/XFMR PWB Assy for a reading of slightly less than 6.95 Vdc. Then adjust R29 on the Power Control PWB Assy for 223 Vac on the HP-410C. Readjust R8 toward 7 Vdc and R29 toward 223 Vac. Continue to alternately adjust R8 and R29 until the multimeter reads 7.00

$\pm 0.05$  Vdc and the HP-410C reads  $223 \pm 2$  Vac.

### (3) R6, Reflected Sample Adjustment

#### NOTE


This adjustment assumes the following initial conditions:

- The LPA has been turned off for at least 10 seconds.
  - The LPA's AUTO/MANUAL BAND Switch is in the AUTO position.
  - R5 and R8 on the VSWR/XFMR PWB Assy are correctly adjusted.
- (a) Connect the LPA's RF output connector J5 to a dummy load.
  - (b) Remove the top cover from the LPA, and pull the interlock switch all the way up to the "cheat" position.
  - (c) Lower the LPA front panel to its horizontal position to gain access to the Power Control PWB Assy.
  - (d) Connect a digital multimeter between test points TP1 and TP2 on the A5 Power Control PWB Assy (see figure 6-3).
  - (e) Turn the LPA on and set the operating frequency at the transceiver to 16.0000 MHz in CW mode. After the LPA has warmed up (is in STANDBY), place the LPA in OPERATE and tune the system.
  - (f) Unkey the system if keyed and disconnect the dummy load from the J5 antenna connector.
  - (g) Key the system, and adjust R6 for  $0.00 \pm 0.05$  Vdc on the digital multimeter.

#### d. FAN INVERTER PWB ASSY, A4

No adjustments.





355-039A

Figure 6-3. Power Control PWB Assy

e. POWER CONTROL PWB ASSY, A5 (figure 6-3)

**(1) R29, Loop Gain Control**

**NOTE**

To adjust R29, perform the Forward Power Sample adjustment, as described in c (2) above. The two adjustments are interactive.

**(2) R34, CW/FSK Power Adjustment**

This adjustment is normally set fully counterclockwise in the 1 KW LPA. If reduced power is required in the CW or FSK mode, then the required reduced power output may be obtained by adjusting R34 in a clockwise direction during normal operation.

**(3) R73, Coupler Tune Power Adjustment**

**NOTE**

This adjustment assumes the following initial conditions:

- The LPA has been turned off for at least 10 seconds.
- The LPA's AUTO/MANUAL BAND Switch is in the AUTO position.
- R5, R6, and R8 on the VSWR/XFMR PWB Assy are correctly adjusted.

- (a) Connect the LPA's RF output connector J5 to a dummy load.
- (b) Lower the LPA front panel to its horizontal position in order to gain access to the Power Control PWB Assy.
- (c) Turn the LPA on and set the operating frequency at the transceiver to 16.0000 MHz in CW mode. After the LPA has warmed up (is in STANDBY), place the LPA in OPERATE and tune the system.

(d) Connect a ground to the J1-5 side of R121 on the Power Control PWB Assy (see figure 6-3). This will place the Power Control PWB Assy into the coupler tune mode.

(e) Set the LPA meter select switch on the front panel to the FWD PWR (WATTS) position and key the system. Adjust R73 on the Power Control PWB Assy for 200 watts on the front panel meter.

(f) Unkey the system and remove the ground from R121.

**(4) R74, Power Control Adjustment.**

This potentiometer is normally set fully clockwise. If reduced output power is required in all modes, then this is accomplished by adjusting R74 counterclockwise until the desired output power is attained.

**(5) R96, Max Plate Current Adjustment**

**NOTE**

This adjustment assumes the following initial conditions:

- The LPA has been turned off for at least 10 seconds.
- The LPA's AUTO/MANUAL BAND Switch is in the AUTO position.
- R5, R6, and R8 on the VSWR/XFMR PWB Assy are correctly adjusted.

- (a) Connect the LPA's RF output connector J5 to a dummy load.
- (b) Lower the LPA front panel to its horizontal position in order to gain access to the Power Control PWB Assy.
- (c) Turn the LPA on and set the operating frequency at the transceiver to 16.0000 MHz in CW mode. After the LPA has warmed up (is in STANDBY), set the

LPA's AUTO/MANUAL BAND Switch to the 16-24 position.

- (d) Set the TUNE PWR Switch to the ON position, and set the METER Switch to the I<sub>K</sub> (mA) position.
  - (e) Adjust R96 on the PWB Assy for 400 ±8 on the front panel meter.
- f. MICRO CONTROL PWB ASSY, A6  
No adjustments.
  - g. FRONT PANEL PWB ASSY, A7A1  
No adjustments.
  - h. TEMP SENSOR PWB ASSY, A8 (figure 6-4).

#### NOTE

This adjustment can be performed on a "cold" LPA (one that has been turned off for at least 15 minutes) or a "hot" LPA (one that has been turned on for more than 10 seconds). If you remove the JMP1 jumper (on the Power Control PWB Assy) from a cold LPA, you can begin the adjustment procedure immediately (as soon as you turn the LPA on). However, if you remove the jumper from an LPA that has been on for

more than 10 seconds, then you should allow 15 minutes for the temperature sensors to stabilize at ambient before doing the adjustment.

- (1) Lower the LPA front panel to its horizontal position to gain access to the Power Control PWB Assy.
  - (2) Remove JMP1 (PN65474-001) on the Power Control PWB Assy (see figure 6-3).
  - (3) With the LPA in warmup (for a cold LPA) or standby (for a hot LPA), connect a digital multimeter between test points TP9 and TP10 on the Power Control PWB Assy.
  - (4) If the voltage on the multimeter is  $0 \pm 2$  mV, no adjustment is necessary. If not, adjust R2 (R2 is accessible through the rear grille of the LPA--see figure 6-4) until the voltage is within the limits.
  - (5) Re-install JMP1 on the Power Control PWB Assy.
- i. INTERCONNECT PWB ASSY, A9  
No adjustments.
  - j. LOW PASS FILTER ASSY, A10  
No adjustments.




Figure 6-4. Temp Sensor PWB Assy

**MAINTENANCE**

**Section III. DIAGNOSTIC PROCEDURES**

**6-4. DEPOT MAINTENANCE PHILOSOPHY.** The maintenance procedures presented in this chapter assume that equipment problems have already been isolated to one of the replaceable subassemblies listed below. This has been accomplished in the field using the BIT (Built-In Test) troubleshooting approach. (For a detailed description of BIT, see Chapter 6 in the On-Equipment Manual for the 1 KW Linear Power Amplifier, T.O. 31R2-2URC-121). As a depot maintenance technician, your job is to take these defective subassemblies returned from the field, swap them with known good subassemblies in a properly functioning 1 KW Linear Power Amplifier (the "test bed"), and troubleshoot the defective subassemblies to the component level. Once you have identified and replaced the faulty component (resistor, capacitor, transistor, etc.), you will then perform whatever adjustment or alignment procedures are required to restore the subassembly to peak operating condition. To accomplish these tasks, you will need the procedures contained in this chapter, a complete set of schematics (in Chapter 8 of this manual), and the test equipment listed in Table 6-1. Also, refer to Appendix B for front panel meter functions and normal operating ranges. The following is a list of the subassemblies covered in Section III:

SUBASSEMBLY	PARAGRAPH
Tube Assy, A1	6-5
Tank Assy, A2	6-6
VSWR/XFMR PWB Assy, A3	6-7
Fan Inverter PWB Assy, A4	6-8
Power Control PWB Assy, A5	6-9
Micro Control PWB Assy, A6	6-10
Front Panel PWB Assy, A7A1	6-11
Temp Sensor PWB Assy, A8	6-12
Interconnect PWB Assy, A9	6-13
Low Pass Filter Assy, A10	6-14

**6-5. TUBE ASSY, A1.**

a. Preliminary Procedure.

- (1) Remove the good Tube Assy from the test-bed 1 KW Linear Power Amplifier, and replace it with the faulty Tube Assy.

- (2) Connect a dummy load to the output (J5) of the 1 KW Linear Power Amplifier (hereafter referred to as the 1 KW LPA).
- (3) Power up the 1 KW LPA from the front panel of the 100 Watt Transceiver.
- (4) After the 1 KW LPA is warmed up, run the BIT test. (For a complete description of the events that take place during the BIT test, including the causes of the various fault codes, see the Appendix at the end of this chapter.)

b. Interpreting the BIT Codes. Use the fault codes listed below as a guide in troubleshooting the Tube Assy. Refer to the section corresponding to the fault code you get. In the event that the test runs without generating a fault code, refer to the "Additional Symptoms" section following the fault code discussions. If your problem is not covered there, start at the beginning of the following procedures and work your way through to the end.

**CODE 8**

This fault code indicates that with the LPA in STANDBY, the DC plate voltage is greater than +100 Vdc.

The most probable cause of this fault code is an open R2, which prevents the DC plate sample from discharging quickly enough after the LPA is switched back to STANDBY from OPERATE.

**CODE 9**

This fault code indicates that the DC plate voltage is not between 2000 and 5000 Vdc when the 1 KW LPA is put into OPERATE.

If the Tube Assy is known to be bad and this fault code occurs, it means that there is probably an open in the Tube Assy's B+ line. With power off and all voltages discharged, remove the faulty

Tube Assy from the test bed and take resistance measurements to determine the cause of the open.

CODE 11

This fault code indicates that when the 1 KW LPA is put into OPERATE and the bias is turned on, the DC plate current is not between 20 and 150 mA.

With power off and all voltages discharged, remove the faulty Tube Assy from the test bed. Using an ohmmeter, do the following:

- (1) Check for continuity in the bias line between pins 4 and 5 of J1 and the cathode of the tube.
- (2) Check for continuity between the tube grid and ground.
- (3) Check for continuity in the filament line on both sides of the filament transformer T1.
- (4) Check for an open in the plate circuit between the tube anode and the DC plate sample circuit (R1 etc.).

If the above circuitry checks good, replace the tube.

CODE 14

This fault code indicates that although the plate voltage, bias, and RF drive from the transceiver is within tolerance, the plate current is not between 325 and 480 mA.

With power off and all voltages discharged, remove the faulty Tube Assy from the test bed. Using an ohmmeter, look for a problem in the RF input circuit between J1-9 and C1. If the RF input circuitry checks good, replace the tube.

CODE 15

This fault code indicates that although the plate current is within tolerance for the RF drive at the cathode, the microprocessor was unable to find a tune peak.

With power off and all voltages discharged, remove the faulty Tube Assy from the test bed.

Using an ohmmeter, check for a problem in the RF plate sample circuit (from C2 to J1-3). You might also check the adjustment of potentiometer R3. See the alignment procedures in Section II of this chapter.

CODE 18

This fault code indicates that the ratio of forward power to RF input power is not between 5 and 60.

With power off and all voltages discharged, remove the faulty Tube Assy from the test bed. Using an ohmmeter, do the following:

- (1) Check for a problem with the output coupling capacitor C4.
- (2) Check the continuity of the RF signal path from C4 to the output tab.
- (3) Check for a problem with load inductor L1.
- (4) If all the above components check good, replace the tube.

ADDITIONAL SYMPTOMS

High-voltage circuit breakers on the 1 KW Power Supply pop when the LPA is switched to OPERATE.

Since the Tube Assy is known to be bad, it means that there is probably a short on the Tube Assy's B+ line. With power off and all voltages discharged, remove the faulty Tube Assy from the test bed and take resistance measurements to determine the cause of the short.

6-6. TANK ASSY, A2.

a. Preliminary Procedure.

- (1) Remove the good Tank Assy from the test-bed 1 KW Linear Power Amplifier, and replace it with the faulty Tank Assy.
- (2) Connect a dummy load to the output (J5) of the 1 KW Linear Power Amplifier (hereafter referred to as the 1 KW LPA).
- (3) Power up the 1 KW LPA from the front panel of the 100 Watt Transceiver.

- (4) After the 1 KW LPA is warmed up, run the BIT test. (For a complete description of the events that take place during the BIT test, including the causes of the various fault codes, see the Appendix at the end of this chapter).
- b. Interpreting the BIT Codes. Use the fault codes listed below as a guide in troubleshooting the Tank Assy. Refer to the section corresponding to the fault code you get. In the event that the test runs without generating a fault code, start at the beginning of the following procedures and work your way through to the end.

#### CODE 4

This fault code indicates that the +13.5 Vdc, as measured at the input to the Micro Control PWB Assy, is not within the normal operating range (+10 to +16 Vdc).

Since the Tank Assy is known to be faulty, the problem is most likely a short on the Tank Assy's +13.5 V line or a short in one of the motors. Since this is a run-time fault (the FAULT light comes on whenever the +13.5 V supply is out of range for more than 3 seconds), you can easily determine whether the problem is in the supply line or in one of the motors:

- (1) If the fault occurs as soon as you turn the equipment on, the problem is in the +13.5 Vdc line.
- (2) If the fault occurs only during band selection, the problem is in the band switch drive motor.
- (3) If the fault occurs only during coil positioning, the problem is in the coil drive motor.

#### CODE 6

This fault code indicates either that the band switch did not turn or that it did not reach the specified band within 10 seconds.

The problem could be in the following areas:

- (1) The Band Switch Motor. Check it as follows:

- (a) Check to see whether the motor turns when you change bands in manual mode. If not, check TP14 on the Servo/Band Switch Drive PWB Assy for approximately +13 Vdc. If the voltage is good, check to see whether the problem is in the motor cable or the motor itself. If the voltage at TP14 is bad, check for approximately +2.5 to +5.0 Vdc at TP15. If TP15 is good, the problem must be Q10, Q11, or one of their associated components. Or there might be an open in the +13.5 V line. If TP15 is bad, the problem could be in the band selection circuitry (see paragraph 2 below), the band switch, or the connector (P1/J3).

- (b) If the motor does turn, check to see whether it turns fast enough (in other words, see if there is any mechanical binding which is slowing it down). If the motor appears to be turning freely, see if it stops within 10 seconds. If the motor does not stop within 10 seconds and does not appear to have any mechanical binding, look for a problem with the band switch or the band selection circuitry (see paragraph 2 below).

- (2) The band selection circuitry (U1 and its associated components on the Servo/Band Switch Drive PWB Assy). Check this circuitry as follows:

- (a) In manual mode, select a band other than the one you're in now.
- (b) At TP17-TP20 on the Servo/Band Switch Drive PWB Assy, check to see that the bit pattern is correct for the band you have selected. For example, if you selected Band 1 (1.6 to 1.8 MHz), you should see a high on the BDSW 1 input to U1 and lows on BDSW 2, BDSW 4, and BDSW 8.
- (c) If the input pattern to U1 is correct, check for a high on the corresponding output pin. In our example, pin 14 of U1 should be high; all other output pins (1-7, 9, 15) should be low.

- (d) If the inputs and outputs of U1 are correct, check for continuity of the lines between U1 and connector J3/P1.

CODE 7

This fault code indicates either that the coil drive motor did not turn or that the coil position is incorrect.

Check the coil drive circuitry as follows:

- (1) Check to see whether the motor turns when you move the manual TUNE switch to either MIN L or MAX L.
  - (a) If not, check TP6 (with the TUNE switch in the MAX L position) and TP10 (with the TUNE switch in the MIN L position) on the Servo/Band Switch Drive PWB Assy for approximately +12.5 Vdc with the motor running full speed. If the voltages are good, check to see whether the problem is in the motor cable or the motor itself. Also check to see whether there is any mechanical binding that might prevent the motor from turning.
  - (b) If the voltages at TP6 and TP10 are bad, check for an open in the +13.5 V line.
  - (c) If the motor turns in one direction but not the other, then check the appropriate driver transistors (Q1, Q2, and Q3 for MAX L; Q4, Q5, and Q6 for MIN L). Also check TP7 (MAX L) and TP8 (MIN L) for highs to turn the transistors on. When TP7 is high, check that Q8 (MIN L DISABLE) is turned off; when TP8 is high, check that Q7 (MAX L DISABLE) is turned off.
  - (d) Another reason why the motor might only turn in one direction is if the limit switch is stuck in one position or the other or if one of the limit switch transistors (Q13 or Q14) is shorted. Such a condition would cause the microprocessor to think that the motor had reached one of the end stops,

thus preventing any further motion in that direction.

- (2) If the coil drive motor moves freely in both directions, check to see whether the coil position is correct:
  - (a) Move the METER selector switch to COIL POS.
  - (b) Connect a voltmeter to TP1, which should read +5 Vdc.
  - (c) Using the manual TUNE switch, move the coil drive motor toward MIN L until the voltmeter reads 0 Vdc. At this point, the COIL POS meter on the LPA front panel should read 100 and the motor should stop. You should not be able to drive the motor any further in this direction.
  - (d) Connect the voltmeter to TP2, which should read +5 Vdc.
  - (e) Move the coil drive motor toward MAX L until the voltmeter reads 0 Vdc. At this point, the COIL POS meter should read 1770 and the motor should stop. You should not be able to drive the motor any further in this direction.
  - (f) If the COIL POS reading is incorrect at either end (for example, the voltage at TP1 went low when the COIL POS indicated 130; or the voltage at TP2 went low when the COIL POS indicated 1710), then you need to do an electro-mechanical realignment of the coil drive motor. See the alignment procedures in Section II of this chapter.
  - (g) If the COIL POS meter does not respond to changes in coil position or responds in a random manner, then check the twa and TWB outputs of the Encoder G1 at TP5 and TP4, respectively, with a dual-trace oscilloscope. While the motor is turning, these should both have TTL-level squarewaves (0 to +5 Vdc). If not, suspect the encoder or its inputs (+5 Vdc and ground).



- (h) If the voltages at TP1 and TP2 do not respond correctly, look for a problem with the limit switch or transistors Q13 or Q14. For example, if the voltage at TP1 goes to 0 at a coil position of 100, but the voltage at TP2 does not go to 0 at a coil position of 1770, then look for a problem with Q13. Conversely, if TP2 switches from +5 Vdc to 0 at a coil position of 1770, but TP1 does not switch at a coil position of 100, then look for a problem with Q14. If neither test point switches at its corresponding limit, then look for a problem with the limit switch.

## CODE 15

This fault code indicates that while the coil was moving from MAX L to MIN L, the microprocessor was unable to find a tune peak.

The first thing to determine is whether this fault occurs in all frequency bands or just certain ones. Therefore, you should run the BIT test in each of the frequency bands and make a note of which bands the fault occurs in.

- (1) If the fault occurs in all bands, then the problem is most likely one of the following:
  - (a) An open in the RF line. Check for continuity between the input tab and the output connector J1.
  - (b) A short on the RF line. Check for a short between the RF signal line and ground.
  - (c) A bad variable coil L1. For example, the coil might be shorted internally.
  - (d) An open in the tune capacitor switch (S1-A), the load capacitor switch (S1-B), or the fixed-coil selector switch (S1-C).
- (2) If the fault occurs in only certain bands, try to determine what these bands have in common. For example, if the fault occurs only in the three lowest bands, then you might look for a shorted tuning capacitor (C5 or C6) or a shorted load capacitor (C5 or C6). Or, if the fault only occurs in Band 1,

then you might suspect fixed coil L2 (Band 1 is the only one in which this coil is not bypassed). Another possibility is a dirty or defective switch section.

## CODE 16

This fault code indicates that when a tune peak is found, the forward tune power is not between 100 and 400 watts.

Use the same procedures as for code 15.

## CODE 18

This fault code indicates that the ratio of forward power to RF input power is not between 5 and 60.

Use the same procedures as for code 15.

## 6-7. VSWR/XFMR PWB ASSY, A3.

a. Preliminary Procedure.

- (1) Remove the good VSWR/XFMR PWB Assy from the test-bed 1 KW Linear Power Amplifier, and replace it with the faulty VSWR/XFMR PWB Assy.
- (2) Connect a dummy load to the output (J5) of the 1 KW Linear Power Amplifier (hereafter referred to as the 1 KW LPA).
- (3) Power up the 1 KW LPA from the front panel of the 100 Watt Transceiver.
- (4) After the 1 KW LPA is warmed up, run the BIT test. (For a complete description of the events that take place during the BIT test, including the causes of the various fault codes, see the Appendix at the end of this chapter.)

- b. Interpreting the BIT Codes. Use the fault codes listed below as a guide in troubleshooting the VSWR/XFMR PWB Assy. Refer to the section corresponding to the fault code you get. In the event that the test runs without generating a fault code, first check the "Additional Symptoms" section following the fault code discussions. If your problem is not covered there, start at the beginning of the following procedures and work your way through to the end.

CODE 10

This fault code indicates that when the LPA is put into OPERATE (but without bias or RF drive), the cathode current is greater than 5 mA.

This problem is most likely caused by the T/R Relay being stuck closed, which allows RF to go to the Tube Assy, causing the tube to conduct. The relay itself could be defective, or there could be a short on the T/R keyline (C10 shorted to ground, for example), causing the T/R Relay to stay energized.

CODE 14

This fault code indicates that when the LPA is keyed in OPERATE with bias and RF drive applied, the plate current is not between 325 and 480 mA.

In this case, the problem is most likely the T/R Relay's failure to energize, preventing RF drive from being applied to the tube. This could be caused by a defect in the relay itself (open or shorted coil, for example), an open +13.5 Vdc line, or an open T/R keyline.

CODE 15

This fault code indicates that when the LPA is keyed in OPERATE with bias and RF drive applied, a tune peak cannot be found.

Look for a short or open on the RF line. A possible problem could be the failure of one of the impedance-matching relays (K2-K4) to energize, which in turn could be caused by a defective relay or a fault in one of the relay driver circuits (Q1-Q3 and their associated components). Also, there could be an open in the FWD SAMPLE circuitry. Check the voltage at TP1 on the Power Control PWB Assy. If the FWD SAMPLE circuitry is working properly, this voltage should be positive (+7 Vdc indicates full forward power). If not, this voltage should be slightly negative.

CODE 16

This fault code indicates that when the LPA is keyed in OPERATE with bias and RF drive

applied, the FWD PWR is not between 100 and 400 watts.

Look for a problem in the FWD SAMPLE circuitry. Check the voltage at TP1 on the Power Control PWB Assy. If the FWD SAMPLE circuitry is working properly, this voltage should be positive (+7 Vdc indicates full forward power). If not, this voltage should be slightly negative. Also, check the adjustment of R8. See the alignment procedures in Section II of this chapter.

CODE 17

This fault code indicates that the VSWR is not less than 2.25:1.

**NOTE**

The following measurements should be taken with rf drive applied (the LPA is keyed in CW mode).

Look for a problem in the REFL SAMPLE/FWD SAMPLE circuitry by checking the voltages at TP1 and TP2 on the Power Control PWB Assy. Normally, TP1 should be close to +7 Vdc, and TP2 should be less than +1 Vdc. Also, check the adjustment of R5. See the alignment procedures in Section II of this chapter. Another possibility is an open in the RF line, which might be caused by a failure in one of the impedance-matching relays (K2-K4) or their associated driver circuits (Q1-Q3 and their surrounding components).

CODE 18

This fault code indicates that the ratio of forward power to RF input power is not between 5 and 60.

Look for a problem in the RF IN SAMPLE circuitry. (Power gain is computed by taking the ratio of the FWD SAMPLE to the RF IN SAMPLE. Since the FWD SAMPLE has been used in several other calculations prior to this one without generating a fault code, the problem is more likely in the RF IN SAMPLE circuitry.)

## ADDITIONAL SYMPTOMS

## High Forward Power

Look for a problem in FWD SAMPLE circuitry. Also, check the adjustment of R8 (see the alignment procedures in Section II of this chapter).

**6-8. FAN INVERTER PWB ASSY, A4.**a. Preliminary Procedure.

- (1) Remove the good Fan Inverter PWB Assy from the test-bed 1 KW LPA. Connect the two Fan Inverter PWB Assy cables to the faulty Fan Inverter PWB Assy. Rest the faulty Fan Inverter PWB Assy face up on top of the chassis, being careful to insulate it sufficiently.
- (2) Connect a dummy load to the output (J5) of the 1 KW Linear Power Amplifier (hereafter referred to as the 1 KW LPA).
- (3) Power up the 1 KW LPA from the front panel of the 100 Watt Transceiver.
- (4) If there is a fault in the Fan Inverter PWB Assy, the fan should not be running. Use the following procedure to isolate the problem.

b. Troubleshooting Procedure.

- (1) Check for +13.5 Vdc at pin 2 or pin 5 of T2.
- (2) Check Q1 and Q2 for collector-emitter shorts.
- (3) Check the bias circuitry (R1-R3, CR1, C3).
- (4) Check C4 and C5 for shorts.

**6-9. POWER CONTROL PWB ASSY, A5.**a. Preliminary Procedure.

- (1) Remove the good Power Control PWB Assy from the test-bed 1 KW Linear Power

Amplifier, and replace it with the faulty Power Control PWB Assy.

- (2) Connect a dummy load to the output (J5) of the 1 KW Linear Power Amplifier (hereafter referred to as the 1 KW LPA).
- (3) Power up the 1 KW LPA from the front panel of the 100 Watt Transceiver.
- (4) After the 1 KW LPA is warmed up, run the BIT test. (For a complete description of the events that take place during the BIT test, including the causes of the various fault codes, see the Appendix at the end of this chapter.)

- b. Interpreting the BIT Codes. Use the fault codes listed below as a guide in troubleshooting the Power Control PWB Assy. Refer to the section corresponding to the fault code you get. In the event that the test runs without generating a fault code, first check the "Additional Symptoms" section following the fault code discussions. If your problem is not covered there, start at the beginning of the following procedures and work your way through to the end.

## CODE 5

This fault code indicates that the XMTR FAULT line (TP11 on the Power Control PWB Assy) has gone low, indicating a temperature-related fault condition.

This fault code can be generated by any one of the following:

- (1) JMP 1 is not in place, or there is an open in the +13.5 Vdc line.
- (2) There is a fault in the LO AIR circuit (the LO AIR LED should be on if the problem is here).
- (3) There is a fault in the OVERTEMP circuit (the OVERTEMP LED should be on if the problem is here).

You should be able to isolate this problem quickly by checking the "sense" (whether the output corresponds to the inputs) of inverters U11D and U11E and of op amps U6A, U6B, and U7B.

CODE 10

This fault code indicates that when the LPA is put into OPERATE (but without bias or RF drive), the cathode current is greater than 5 mA.

- (1) Check the operation of U13A by placing the LPA into OPERATE and measuring the voltage on pin 1, which should be close to 0 (+12.5 mV or less). If it is greater than +12.5 mV, check the input at pin 3, which should be 40% of the voltage on pin 1. If the voltage on pin 3 is correct, then U13A is probably okay.
- (2) Check the voltage across R95, which should be the same as on U13-3. Normally, with the LPA in OPERATE and unkeyed, the voltage across R95 should be 0 (in other words, there should be no cathode current).
- (3) If the voltage across R95 indicates that there is cathode current, check for a problem with Q2 or Q3 (collector-emitter short) or with the keyline circuitry (U11A and Q1). With the LPA unkeyed, the output of U11A (pin 2) should be low, which keeps Q1 turned off, which in turn keeps Q2 and Q3 turned off.

CODE 11

This fault code indicates that with the LPA in OPERATE and bias applied (no RF drive), the plate current is not between 20 and 150 mA.

- (1) Key the LPA in OPERATE with no RF drive, and check the voltage at TP3. This voltage should be +5 Vdc. When you unkey the LPA, this voltage should increase to +24 Vdc. If the voltage at TP3 is incorrect, look for a problem in the bias circuit (Q2, Q3, and their associated components) or the keyline circuit (U11A, Q1, and their associated components). When the LPA is keyed, the output of U11A should be high, which turns on Q1, which then turns on Q2 and Q3.
- (2) If the voltage at TP3 is good, check the voltages at the input and output of U13A. With the LPA keyed in OPERATE (no RF drive), look for +20 to +150 mV on pin 3 and

+50 to +375 mV on pin 1. If these voltages are not correct, look for a problem in U13A or its associated components.

CODE 14

This fault code indicates that when the LPA is keyed in OPERATE with bias and RF drive applied, the plate current is not between 325 and 480 mA.

The bias, keyline, and cathode current sampling circuitry are probably okay; otherwise, code 11 would have been declared. In this case, since the fault occurs with RF drive applied, look for a problem in the TGC circuitry, which controls the amount of RF drive applied to the LPA. Check this circuitry as follows:

- (1) To see whether the TGC circuitry is indeed the cause of the problem, disconnect the cable from J1 on the AGC/TGC PWB Assy in the 100 Watt Transceiver. Run the BIT test again and see if Code 14 reappears. If it doesn't, continue with step 2 below. If it does, check the bias, keyline, and cathode current sampling circuitry as in Code 11 above.
- (2) Re-connect the cable to the AGC/TGC PWB Assy in the 100 Watt Transceiver. The first thing to do is determine whether the problem can be corrected by adjusting the potentiometers on the Power Control PWB Assy. Go the alignment procedures in Section II of this chapter and perform the entire alignment procedure. If this does not correct the problem, continue with step 3 below.
- (3) Key the LPA from the 100 Watt Transceiver in CW mode with the CW key. Measure the voltage at TP5. Normally, this voltage should be +8 Vdc. If it is greater than +8 Vdc, the output power will be lower than normal; if it is less, the output power will be greater than normal. If the voltage at TP5 is good, skip to step 8. If it is not, continue with step 4. Return the transceiver to USB mode.

**NOTE**

For all the measurements that follow, you must key the LPA from the 100 Watt Transceiver and hum into the microphone.

- (4) Observe the voltage at TP1 and TP2 with an oscilloscope. TP1 should read +7 Vdc at the peak of the waveform, and TP2 should read less than +1 Vdc (almost 0). Also, check pins 1 and 7 of U1. The voltages at these pins should be about the same as on the corresponding test points. If any of these voltages are incorrect, look for a problem in U1 and its associated components.
- (5) Check the output of U3A with an oscilloscope. Pin 1 (TP4) should be +8 Vdc at the peak. If this voltage is incorrect, look for a problem with U3A or its associated components.
- (6) Check the output (pin 1) of U9A for +8 Vdc (peak). Normally, U9A has unity gain. However, any one of several conditions can cause U8 to conduct. During CW power cutback, for example, after C10 charges, the output of U4A goes high, causing the output of U4B to go high, which in turn causes the output of U7A to go low, turning on U8 and increasing the gain of U9A. This same situation can occur if either CR29, CR10, or CR11 conducts (in response to an rf/DC protect voltage or an overtemperature or overcurrent condition), forcing the output of U4B to go high. If the voltages at U9A are not normal, do the following:

- (a) Check the anodes of CR29, CR11, CR10, and CR7 to determine if any of these is sufficiently positive to cause pin 5 of U4B to go higher than +5 Vdc, causing the output of U4B to go low. If so, you can then identify the circuit that is causing this condition:

CR29	RF/DC protect (U3B and its associated components)
CR11	Overtemperature (U6B and its associated components)
CR10	Max plate current control (U5A and its associated components)

CR7 CW power cutback (U4A and its associated components)

- (b) If none of the above circuits is responsible for changing the gain of U9A by causing the output of U4B to go low, check for a problem in U4B, U7A, U8, or their associated components.
- (7) If the voltages at U9A are normal, check the voltages at U9B. Pin 5 should normally be at +4 Vdc (peak), and pin 7 (TP5) should be at +8 Vdc (peak). If this is not the case, check for a possible problem in quad switch U10 or in U9B and one of its associated components.
- (8) Check for a possible problem in the PPC circuitry (U5B and its associated components). Measure the voltage at TP6 with an oscilloscope. Normally, this voltage should be 0 to +5 Vdc (peak). A voltage greater than this initiates the cutback condition in the transceiver (Exciter PWB Assy). Check to see whether the PPC LED illuminates (this LED should illuminate whenever the voltage at TP6 exceeds +5 Vdc, which is the threshold point for U13B). If the voltage at TP6 is consistently greater than +5 Vdc (PPC LED is on continuously), check for a problem in U5B and its associated circuitry.

**CODE 16**

This fault code indicates that when the LPA is keyed in OPERATE with bias and RF drive applied, the FWD PWR is not between 100 and 400 watts.

Use the same procedure as for Code 14.

**ADDITIONAL SYMPTOMS**

High Forward Power, Low Forward Power

Look for a problem in the TGC circuitry. Use the same procedure as for Code 14.

6-10. MICRO CONTROL PWB ASSY, A6.

a. Preliminary Procedure.

- (1) Remove the good Micro Control PWB Assy from the test-bed 1 KW Linear Power Amplifier, and replace it with the faulty Micro Control PWB Assy.
- (2) Connect a dummy load to the output (J5) of the 1 KW Linear Power Amplifier (hereafter referred to as the 1 KW LPA).
- (3) Power up the 1 KW LPA from the front panel of the 100 Watt Transceiver.
- (4) After the 1 KW LPA is warmed up, run the BIT test. (For a complete description of the events that take place during the BIT test, including the causes of the various fault codes, see the Appendix at the end of this chapter.) If you are unable to run the BIT test, either from the 100 Watt Transceiver or from the LPA, go to the "Additional Symptoms" section following the fault code discussions.

- b. Interpreting the BIT Codes. Use the fault codes listed below as a guide in troubleshooting the Micro Control PWB Assy. Refer to the section corresponding to the fault code you get. In the event that the test runs without generating a fault code, check the "Additional Symptoms" section following the fault code discussions. If the procedure there does not indicate that there is a problem, chances are that the Micro Control PWB Assy is all right.

CODE 1

This fault code indicates that when the microprocessor reads the RF PLATE SAMPLE input to the A-to-D Converter, it indicates full scale, which means that the metering is inaccurate.

The problem is most likely in either the microprocessor chip (U1) or the A-to-D Converter chip (U6). Check the clock signal (TP4) to U6 (it should be 614.4 KHz). If the signal is bad at TP4, trace the line back through U31-5 and U31-1 (4.9152 MHz), all the way back to the clock oscillator (U8, Y1, etc.). If the signal at TP4 is good, try replacing the microprocessor

first (since it's socketed), then the A-to-D Converter.

CODE 3

This fault code indicates that when the microprocessor read the PRI PWR input to the A-to-D Converter, it found it to be out of range (which is 80 to 120% of the nominal value).

Since Code 1 was not declared, the microprocessor and the A-to-D Converter are probably okay. Look for an open (R140) or a short (C140) on the PRI PWR SAMPLE input line (J1-16 to U6-4) to the A-to-D Converter (U6).

CODE 4

This fault code indicates that when the microprocessor read the +13.5 VDC SAMPLE input to the A-to-D Converter, it found it to be out of range (which is +10 to +16 Vdc).

Since Code 1 was not declared, the microprocessor and the A-to-D Converter are probably okay. Look for an open (R16) or a short (C22, VR2) on the +13.5 VDC SAMPLE input line (J1-47, -48 to U6-3) to the A-to-D Converter (U6). Check also the voltage divider formed by R16 and R17. Another possibility is that VR2 is breaking down at a lower potential than it is rated at (5.1 Vdc).

CODE 6

This fault code indicates that the band switch, when commanded to move to a different band, did not reach the selected band within 10 seconds.

- (1) With the LPA in manual mode, select a different operating band from the one you're in now. Then check the BDSW output signal lines to the Tank Assy for the correct binary code. In other words, if you switch from the 1.6 to 1.8 MHz band (Band 1) to the 4 to 6 MHz band (Band 5), you should see highs on pins 5 and 9 of Output Latch U13 and lows on pins 2 and 6. Check for the signals on the output sides of their resistors (R120-R123) also. If the code is correct, try switching to Band 2 (U13-6 should be high; pins 2, 5, and 9 should be

low) and then to Band 8 (U13-2 should be high; pins 5, 6, and 9 should be low), checking the code at both bands. If the codes are correct in all cases, proceed to step 2.

- (2) If the Output Latch U13 and the BDSW signal lines are functioning properly, check the BDSW ON line and the Input Latch U28. After making a band change in manual mode, check to see whether pin 13 of U17 goes high and then low again after a few seconds. Check for the opposite on pin 12 of U17 and pin 14 of U28. If U17 appears to be working properly, suspect U28.

#### CODE 7

*This fault code indicates that when the coil drive motor was commanded to move first to MIN L and then to MAX L, it either did not move or its position counter was found to be inaccurate (the coil's position at MIN L or MAX L did not agree with stored values).*

- (1) Check the MIN L and MAX L signal lines on both sides of U11. When the BIT test is run, U11-3 should be low normally and then go high momentarily. The opposite should happen at U11- 14. After U11-3 returns low, U11-2 should go high momentarily and then return low again. The opposite should occur at U11- 15. If the signals are good at U11, check at the output sides of the respective resistors (R125, R126). If the signals are good there, proceed to step 2.
- (2) Check the MIN L LIMIT and MAX L LIMIT signal lines coming into the board. When the BIT test is run, the MIN L LIMIT signal line (U28-13) should go low and then high again. After the MIN L LIMIT signal line returns high, the MAX L LIMIT signal line (U28-8) should go low and then remain there for a few seconds until the tuning portion of the BIT test, when it should go high again. If these signals are incorrect, look for a problem in the input resistors (R130, R131) or the pullup resistor pack (R20).
- (3) Check the TWA and TWB signal lines (U17-9, U17-11). When the tuning coil is in motion, these signals should be TTL (0 to

+5 Vdc) square waves of opposite polarity. Check these signals on both the inputs and outputs of U17. Also, check the edge detector circuit: pins 4 and 5 of U26 should be high pulses when the coil drive motor starts to move and continue to be high pulses until the motor stops. Pin 1 of U26 should be the opposite. If this is not the case, look for a problem in U17, U26, or one of their associated components (R5, C24, C29, CR1,

#### CODE 8

This fault code indicates that with the LPA in STANDBY, the DC plate voltage is greater than 100.

- (1) Look for a problem in U25 or U20. Place the LPA in STANDBY and check the signal level at U25-12. It should be low. Then command the LPA to OPERATE, and see whether this pin goes high. If it does, check for the opposite reactions at U20-14 and the output side of R107.
- (2) If the signal at U25-12 is not correct, check the inputs to U25: +5 Vdc at pins 15 and 16; GND at pin 8; the clock signal (TP2) at pin 3 and the SERIAL DATA signal (TP3) at pin 2 (also check the pullup lines through R8); and the strobe signal at pin 1. If the inputs to U25 appear to be good, replace U25.

#### CODE 9

This fault code indicates that with the LPA in OPERATE, the DC plate voltage is not between 2000 and 5000.

Check for an open (R141) or a short (C141) on the DC PLATE SAMPLE line (J1-38 to U6-5). With the LPA in OPERATE, this line should read approximately +1.8 to +4.5 Vdc, which corresponds to a plate voltage of +2000 to +5000 Vdc.

#### CODE 11

This fault code indicates that when the LPA is keyed in OPERATE without RF drive, the plate current is not between 20 and 150 mA.

Check for an open (R138) or a short (C138) on the I SAMPLE line (J1-42 to U6-1).

#### CODE 12

This fault code indicates that when the RF MUTE command was sent to the 100 Watt Transceiver, the RF input level to the LPA did not drop below 6 W in 200 ms.

- (1) Look for a problem in U19 or U30. Run the BIT test and see whether U30-11, which should normally be high, goes low momentarily and then high again. If not, check for the reverse situation at U30-6.
- (2) If the signal is good at U30-6, suspect U30 itself or look for a short (CR8 or C111) or open (R111) on the RF MUTE signal line.
- (3) If the signal at U30-6 is not good, suspect U19. Before replacing it, check for +5 Vdc at pins 15 and 16 and for GND at pin 8. If these inputs are good, replace U19.

#### CODE 13

This fault code indicates that when the TPR (Tune Power Request) and TGC TPR signals were sent to the transceiver, the RF input signal level did not rise above 5 W in 20 seconds.

- (1) Check for an open (R137) or a short (C137) in the RF IN SAMPLE signal line (J1-12 to U6-28).
- (2) Another possibility is a fault in the DATA lines (J1-8, 9 to U1-10, 11). With the LPA in AUTO mode, change frequency bands on the transceiver and then key the system. You should see a series of pulses on the DATA+ line. Trace these pulses from U1-11 through U10, Q2, U4-1, and out to J1-9. You should also see these pulses at U4-4, U3, and back at U1-10.

#### CODE 15

This fault code indicates that when the LPA is keyed in OPERATE with RF drive, a tune peak cannot be found as the coil is moved from MAX L to MIN L.

- (1) Look for an open (R136) or a short (C136) in the FWD SAMPLE line (J1-39 to U6-27).

- (2) Check that the PA TUNE line (output side of R102) goes low while the microprocessor is attempting to find a tune peak during the BIT test. If not, check for an open R102 or a problem in U20 or U25 (these two chips should be okay; otherwise, a Code 8 would have been declared).

#### CODE 21

This fault code indicates that data sent from pin 11 of the microprocessor (U1) was not received (echoed back) at pin 10. Normally, this code indicates a problem in the communications link between the LPA and the transceiver; but in this case, since we know that the Micro Control PWB Assy is faulty, the problem has to be in the on-board DATA lines (J1-8, 9 to U1-10, 11). With the LPA in AUTO mode, change frequency bands on the transceiver and then key the system. You should see a series of pulses on the DATA+ line. Trace these pulses from U1-11 through U10, Q2, U4-1, and out to J1-9. You should also see these pulses at U4-4, U3, and back at U1-10.

#### ADDITIONAL SYMPTOMS

##### Microprocessor Fault

Microprocessor-related faults are generally characterized by an abnormal or random display and a loss of transceiver control functions (i.e., there is no LPA status displayed on the transceiver or the status is always MANUAL). In this case, running the BIT test is of no avail. Therefore, if you think you have a microprocessor-related fault and you cannot run the BIT test, use the following procedure:

#### NOTE

The Micro Control PWB Assy contains the Intel 8031 microprocessor, which controls all the functions of the LPA, including the BIT test. A failure in the microprocessor, EPROM, RAM, decoder, etc. will probably disable the BIT circuitry and most of the other LPA functions as well. Unless you are thoroughly familiar with the



circuitry of this board and with the operation of microprocessors, it will be very difficult for you to isolate a faulty chip or discrete component using standard test equipment and troubleshooting techniques. The following procedures, therefore, are intended to check only the most obvious and fundamental aspects of the board's operation. If these do not enable you to identify the problem, then you will need more advanced test equipment and test procedures, which are beyond the scope of this manual.

- (1) Check the supply voltage (+5 Vdc) to the microprocessor at U1-40. Also check for 0 Vdc at pins 20 and 31.
- (2) Check the reset pin (U1-9). Normally, this pin should be low all the time. If the microprocessor is not working properly, it will be pulsing high at a 9.375 Hz rate. If this is the case, then the clock oscillator (Y1, U8, and their associated components), counters U31 and U32, and buffers U17 and U3 are probably okay. If the reset line is continually high, look for a failure in U3 or U17.
- (3) Check the clock inputs to the microprocessor: U1-19 (4.9152 MHz), U1-15 (153.6 KHz), and U1-12 (300 Hz). If any of these inputs is bad, trace the signal line(s) back to the counters (U31, U32) and/or the oscillator (U8, Y1, etc.).
- (4) Check U1-30 (TP1) to see if it's pulsing high and low; it should not be stuck high or low. Do the same for U1-16, U1-17, and all the address lines.
- (5) If all the above checks are good, try replacing the microprocessor U1. This chip is socketed for easy replacement.
- (6) If the problem persists, replace the EPROM U2. This chip is also socketed.
- (7) If the problem still persists, check the supply voltages and ground connections to all the other chips, beginning with the RAM (U29) and the address decoder (U27).

## 6-11. FRONT PANEL PWB ASSY, A7A1.

### a. Preliminary Procedure.

- (1) Disconnect the cable from the good Front Panel PWB Assy in the test-bed 1 KW Linear Power Amplifier, and connect it to the faulty Front Panel PWB Assy. It is not necessary to mount the faulty Front Panel PWB Assy in the test bed.
- (2) Connect a dummy load to the output (J5) of the 1 KW Linear Power Amplifier (hereafter referred to as the 1 KW LPA).
- (3) Power up the 1 KW LPA from the front panel of the 100 Watt Transceiver.
- (4) Look at the display on the front panels of both the 1 KW LPA and the 100 Watt Transceiver. If you notice anything abnormal, either when you first power up the LPA or after the LPA is warmed up and you try to operate it, refer to the appropriate section below.

### b. Troubleshooting Procedures.

Problems with the 1 KW LPA can be grouped under the following general symptoms:

#### LPA does not power up.

The first thing you should do in this situation is determine whether the Front Panel PWB Assy has +5 V applied when you command the LPA to turn on from the 100 Watt Transceiver. Normally, this is indicated by the POWER ENABLE LED being on steady and the STANDBY LED blinking. If neither LED is on, look for a failure in the POWER ENABLE switch S8. If the STANDBY LED is blinking but the POWER ENABLE LED is off, look for a failure in the POWER ENABLE LED.

#### LPA status at 100 Watt Transceiver is missing or incorrect.

- (1) If there is no LPA status at the transceiver (the AMP:STBY indicator is not visible on the transceiver's display), the problem could be anywhere on the output side of the data line (U17-U20, U11F, or the FP IN EN, SER CK, or SER DATA signal lines).

- (a) Every 50 ms, you should see a series of 200 KHz clock pulses on the SER CK line (pin 10 of U17-U20). During this time, the FP IN EN line (pin 9 of U17-U20 and pin 15 of U11) should go low, which allows the serial data to be clocked out from U17-U20 through U11F. Check pin 13 of U11 for a series of data pulses every 50 ms.
  - (b) If the data pulses are not present, but the SER CK and FP IN EN signals are good, trace the data pulses back through U11-14 and the inputs (pin 11) and the outputs (pin 3) of U17-U20. Check for the presence of the operating voltages (+5 Vdc, GND) at each of these chips.
- (2) If you do have LPA status at the transceiver (AMP:STBY indicator is on) but the status is incorrect (e.g., the LPA MAN indicator on the transceiver is on when the LPA's AUTO/MANUAL BAND switch is in the AUTO position), look for a problem with switch S1 or shift registers U17 or U18 and their associated components.
- (a) Rotate AUTO/MANUAL BAND switch S1 through each of its positions. At each position, check the bit pattern on pins 1, 4-7, and 13-15 of U17 and on pins 5-7 of U18. Only one of these pins should be low for a given setting of S1, and it should be different for each setting.
  - (b) If the bit pattern at the parallel inputs to U17 and U18 is correct for each position of S1, then check the serial outputs (pin 3) of both U17 and U18. Using a dual-trace oscilloscope, sync on the negative transition of the FP IN EN signal and look for a series of data pulses at U17-3 and U18-3. Try changing the setting of S1 and look for a corresponding change in the data pattern.
  - (c) If the data signal at U17-3 and/or U18-3 is incorrect, check the operating voltages (+5 Vdc and GND) for U17 and/or U18. If the operating voltages are good, replace the appropriate chip

(U17 if the data signal at U17-3 was bad; U18 if the data signal at U17-3 was good).

#### Meter failures.

Look for a problem with METER switch S2 or with one of the resistor packs (R17, R18). Rotate S2 through each of its positions. At each position, check the bit pattern on the control lines to U17 (pins 1, 4, 13-15) and U18 (pins 4-7, 13, 14). For each switch setting, only one of these control lines should be low; all others should be high. Presumably, the shift registers (U17-U18), the output buffer (U11F), the SER CK line, and the FP IN EN line are good; otherwise, you would probably have missing or incorrect LPA status at the transceiver.

#### Manual control failures.

If one of the manual control switches (TUNE PWR, LOCAL KEY, TUNE, ANTENNA, and SELF TEST) does not appear to be functioning properly, check its operation by monitoring the logic level at its control line. For example, when you activate the TUNE PWR switch, pin 15 of U19 should go low. It should remain low until you flip the TUNE PWR switch off. For multiple switch failures, including failures at selected positions of the AUTO/MANUAL BAND and METER switches, look for a problem in one of the resistor packs (R16-R19).

#### LCD failures.

Typical failure modes for the LCD (DS1) are (1) the loss of an individual segment, (2) a completely blank display, or (3) a display in which the outline of the previous character persists after a new character appears.

- (1) A good way to check whether a particular segment is defective is to run the BIT test. During the BIT test, all LCD segments are supposed to be lit. If a segment is not lit, check for a high at its corresponding control line on U28 (a high at the output of U28 turns the segment on). For example, if the center segment of the third character is not illuminated during BIT, check to see whether U28-15 is high during BIT. If it is, replace DS1. If it isn't, replace U28.

- (2) If the display is completely blank, do the following:
- Check for the presence of the operating voltages (+5 Vdc, GND) at U28 and DS1. If these voltages are good, run the BIT test and check for highs on all the outputs of U28 (pins 3-29, 32, 33, 37-39). If the outputs of U28 are high, replace DS1.
  - If the outputs of U28 are not high, check for a series of 200 KHz clock pulses at U28-40 every 50 ms, along with a series of data pulses at U28-34. If the inputs to U28 are good, replace U34.
  - If the clock signal is bad at U28-40, check it at U11-2. Also, check for a low on the LCD OUT EN line (U11-1) while the SER CK line and the SER DATA lines are pulsing. (The LCD OUT EN line allows the SER CK pulses to be buffered through U11A to U28-40.) If the inputs to U11 (including the +5 Vdc and GND operating voltages) are good, replace U11.
- (3) If the outline of a previous character persists after a new character appears, the 75 Hz LCD CLK signal is probably bad. Check it at pins 1 and 28 of DS1 and at pin 31 of U28.

#### LED Failures.

If you suspect that one of the front panel LEDs is defective, run the BIT test. All of the LEDs should be on during the test.

- If one LED fails to light, check its driver circuit. The four LEDs are controlled by U26, pins 4-7. A high on one of these pins is applied to the base of its driver transistor, thus turning it and its associated LED on. For example, if the FAULT LED fails to come on during the BIT test, check for a high on U26-4. If U26-4 is low, replace U26. If U26-4 is high, the problem is either in Q1, R6, or DS2.
- (2) If two or more LEDs fail to function properly, do the following:
- If none of the LEDs comes on, check the supply voltages (+5 Vdc and GND) to U26: pins 15 and 16 should be at +5 Vdc, and pin 8 should be at 0 Vdc. Also, check for a series of 200 KHz clock pulses every 50 ms at pin 3 and a corresponding series of data pulses at pin 2. At the same time, pin 1 should pulse high whenever there is a change in the LED status, such as when the LPA is switched from STANDBY to OPERATE. When the clock and data lines are inactive, pin 1 should be low. If all the inputs to U26 are good, replace U26. If not, trace out the defective signal line.
  - If at least one of the LEDs comes on, replace U26.

#### 6-12. TEMP SENSOR PWB ASSY, A8.

##### a. Preliminary Procedure.

- Remove the good Temp Sensor PWB Assy from the test-bed 1 KW Linear Power Amplifier, and replace it with the faulty Temp Sensor PWB Assy.
- Connect a dummy load to the output (J5) of the 1 KW Linear Power Amplifier (hereafter referred to as the 1 KW LPA).
- Power up the 1 KW LPA from the front panel of the 100 Watt Transceiver.
- After the 1 KW LPA is warmed up, run the BIT test. (For a complete description of the events that take place during the BIT test, including the causes of the various fault codes, see the Appendix at the end of this chapter.)

- b. Interpreting the BIT Codes. Use the fault code listed below as a guide in troubleshooting the Temp Sensor PWB Assy. In the event that the test runs without generating a fault code, check the "Additional Symptoms" section following the discussion of the fault code.

CODE 5

This fault code indicates that the XMTR FAULT line (TP11 on the Power Control PWB Assy) went low, which could have been caused by any of the following:

Low air flow

High ambient temperature

JMP1 on the Power Control PWB Assy not being installed

Since we know that the problem is in the Temp Sensor PWB Assy, we can eliminate the last cause. To determine whether the fault code is generated by low air flow or by high ambient temperature, check whether the LO AIR LED (DS4) or the OVERTEMP LED (DS5) on the Power Control PWB Assy comes on when the fault is declared.

- (1) The LOW AIR LED indicates that the temperature sensed by U2 on the Temp Sensor PWB Assy (as measured by the voltage at TP9 on the Power Control PWB Assy) is at least 15° C to 21° C greater than the temperature sensed at U2 (as measured by the voltage at TP10). This could be caused by either a failure in the fan (which in this case we know is okay) or in one of the temperature sensing circuits (U1, U2, or their associated components). Do the following:

NOTE

This procedure can be performed on a "cold" LPA (one that has been turned off for at least 15 minutes) or a "hot" LPA (one that has been turned on for more than 10 seconds). If you remove the JMP1 jumper (on the Power Control PWB Assy) from a cold LPA, you can begin the procedure immediately (as soon as you turn the LPA on). However, if you remove the jumper from an LPA that has been on for more than 10 seconds, then you should allow 15 minutes for the temperature sensors to stabilize at ambient before doing the procedure.

- (a) Remove JMP1 on the Power Control PWB Assy. With the LPA in STANDBY, measure the voltages at TP9 and TP10 on the Power Control PWB Assy. At a room temperature of 21° C (70° F), both test points should read approximately +2.94 Vdc. (For each °C up or down, the voltage at the test points should increase or decrease by 10 mV.) If TP9 is off by more than a few tenths of a volt, replace U1. If TP10 is off, try adjusting potentiometer R2 on the Temp Sensor PWB Assy to make the voltage at TP10 match that at TP9. If adjusting R2 is ineffectual, replace U2.

- (b) If the above procedure does not isolate the problem, install JMP1 and measure the voltages at TP9 and TP10 again. TP10 should read the same as before, but TP9 should indicate an increase of approximately 70 mV (in other words, with the fan running, the heat generated by the conduction of R1 should increase the temperature of U1 by approximately 7° C).

- (c) If the results of the above tests are still inconclusive, try transmitting for awhile into the dummy load until the LPA reaches its normal operating temperature (110° C). Measure the voltages at TP9 and TP10 again. TP10 should read approximately +3.68 Vdc, with TP9 approximately 70 mV higher (+3.75 Vdc).

- (2) The OVERTEMP LED indicates that the ambient temperature of the LPA, as measured by U2 on the Temp Sensor PWB Assy, is greater than 150° C (302° F). The problem has to be in the U2 temperature sensing circuit. Try adjusting R2 first (see the alignment procedures in Section II of this chapter). If adjusting R2 fails to correct the problem, replace U2.

ADDITIONAL SYMPTOMS

Low forward power.

This could indicate a faulty U2 or a misadjusted R2. In other words, the output voltage of U2 is high enough to initiate power cutback, but not

high enough to generate an OVERTEMP fault. First try adjusting R2 (see the alignment procedures in Section II of this chapter). If this fails to correct the problem, replace U2.

### 6-13. INTERCONNECT PWB ASSY, A9.

#### a. Preliminary Procedure.

- (1) Remove the good Interconnect PWB Assy from the test-bed 1 KW Linear Power Amplifier, and replace it with the faulty Interconnect PWB Assy.
- (2) Connect a dummy load to the output (J5) of the 1 KW Linear Power Amplifier (hereafter referred to as the 1 KW LPA).
- (3) Power up the 1 KW LPA from the front panel of the 100 Watt Transceiver.
- (4) After the 1 KW LPA is warmed up, run the BIT test. (For a complete description of the events that take place during the BIT test, including the causes of the various fault codes, see the Appendix at the end of this chapter.) If you are unable to run the BIT test, either from the 100 Watt Transceiver or from the LPA, go to the "Additional Symptoms" section following the fault code discussions.

- b. Interpreting the BIT Codes. Use the fault codes listed below as a guide in troubleshooting the Interconnect PWB Assy. Refer to the section corresponding to the fault code you get. In the event that the test runs without generating a fault code, refer to the "Additional Symptoms" section following the fault code discussions. If your problem is not covered there, start at the beginning of the following procedures and work your way through to the end.

#### CODE 3

This fault code indicates that when the microprocessor read the PRI PWR SAMPLE input to the A-to-D Converter, it found it to be out of range (which is 80 to 120% of the nominal value).

The PRI PWR SAMPLE input to the A-to-D Converter is obtained from a precision volt-

age divider (R1, R2) in series with the +13.5 Vdc from the 1 KW Power Supply. With a nominal input voltage (+13.5 Vdc), there should be approximately +3 Vdc at the junction of R1 and R2. Measure the voltage across R1 and R2. The voltage across R1 should be 3.46 times greater than the voltage across R2. If the input voltage (+13.5 Vdc) is marginally high or low, a slight change in the ratio of these two resistors can generate a Code 3 fault.

#### CODE 8

This fault code indicates that with the LPA in STANDBY, the DC plate voltage is greater than 100.

Look for a fault in the HV ON circuit, specifically a shorted Q1 or Q2, which is keeping the high voltage relay (K1 in the 1 KW Power Supply) energized in STANDBY.

#### CODE 9

This fault code indicates that with the LPA in OPERATE, the DC plate voltage is not between 2000 and 5000.

The most obvious cause of this fault is an open Q1 or Q2 (or a fault in one of their associated components), which is preventing the high voltage relay (K1 in the 1 KW Power Supply) from energizing in OPERATE.

#### ADDITIONAL SYMPTOMS

LPA does not power up.

Look for a problem in the POWER ON SW line: either an open or a short (C1 or CR1, for example).

No LPA status at the transceiver.

Since the Interconnect PWB Assy is the distribution center for the +13.5 Vdc to many of the other circuit boards, including the Micro Control PWB Assy which in turn supplies the Front Panel PWB Assy, an open in one of the +13.5 Vdc distribution lines could disrupt LPA transceiver communications. Check especially for continuity in the connectors, J1 and J2.

**6-14. LOW PASS FILTER ASSY, A110.** If this assembly is defective, the problem is most likely a shorted capacitor or an open inductor. You should be able to isolate the faulty component

very quickly by taking resistance measurements from the RF Me to ground and from one end of the RF line (J4) to the other (J5).

## Section IV. REMOVAL/REPLACEMENT PROCEDURES

**6-15. REMOVAL/REPLACEMENT PROCEDURES.** The following removal/replacement procedures are for the internal components of the A2 Tank Assy only. Removal/replacement procedures for the Tank Assy itself and for the other major subassemblies of the 1 KW LPA are contained in the On-Equipment Manual, T.O. 31R2-2URC-121.

### NOTES

When replacing switches, apply a thin film of Dow Corning No. 200 silicone lubricant to the wiping surface of the switch contacts.

Some of the screws in the following procedures are secured with Loctite No. 222 (purple). Apply a new coating of Loctite 222 when reinstalling these screws.

#### (1) Wafer Switches

##### (a) Band Select Switch

### CAUTION

Due to the shape of the shaft that runs through the center of the Band Select Switch, it is possible to install the switch correctly or 180° out of phase. Therefore, before removing the switch, make sure that the switch is set for band 1 (1.6-1.8 MHz), in which case the open position of the switch should be oriented toward the driven pulley. When installing a new switch, make sure that its orientation is the same as that of the one you took out.

- i. Loosen the two setscrews holding the black plastic Geneva drive gear to the switch shaft.

### NOTE

Before removing the Geneva drive gear from the shaft, place an identifying mark on the gear and the flat of the shaft. This is so you will be able to re-install the gear in

the same position it was when you took it off.

- ii. Remove the Geneva drive gear from the shaft.
  - iii. Remove the two Phillips screws holding the Band Select Switch to the chassis.
  - iv. Unsolder the flexible cable wires from the old switch and solder them to the new switch, being careful to orient the flexible cable correctly.
  - v. Mount the new switch to the chassis, making sure that its orientation is the same as for the old switch.
  - vi. Mount the Geneva drive gear to the shaft.
- (b) Selector Switch Assy for the Tune Capacitors, Load Capacitors, and Inductors

### NOTES

This switch assembly (S1-A, -B, and -C) must be replaced as a unit. If one of the sections is defective, do not attempt to repair it. Instead, replace the entire switch assembly.

Before starting the following procedure, select band 1 (1.6-1.8 MHz). Note the orientation of the three movable switch contacts on each section of the switch assembly. The contacts on the new switch assembly must be oriented the same way. Due to the shape of the switch shaft, it is possible to mount the switch in only one of two ways: correctly or 180° out of phase.

- i. Loosen the setscrew holding the black plastic Geneva drive gear to the switch shaft.

- ii. Remove the Geneva drive gear from the shaft.
- iii. Loosen six Phillips screws and remove the top cover (to which the circuit board is mounted).
- iv. Unsolder the Coil Assy leads at the switch. Also, unsolder the connecting strap to the variable coil. Disconnect the ground wire to the chassis by removing the Phillips mounting screw.
- v. Remove the four Phillips screws and remove the Coil Assy.
- vi. After placing identifying marks on the two Load Capacitor Assemblies, remove them from the chassis by removing their two Phillips mounting screws.
- vii. Do the same for the two Tune Capacitor Assemblies.
- viii. Unsolder the remaining strap to the variable coil.
- ix. On the bottom of the Tank Assy, remove the three mounting nuts for the switch assembly.
- x. Remove the switch assembly.
- xi. Unsolder any remaining leads or jumpers from the old switch assembly and transfer them to the new switch assembly.
- xii. Unsolder coil L6 from the old switch assembly. Remove the two plastic mounting screws, and remove the coil. Transfer this coil to the new switch assembly.
- xiii. Mount the new switch assembly to the Tank Assy chassis. Use the chassis ground strap as a guide in orienting the new switch assembly correctly. Make sure that the orientation of the movable switch contacts is the same as it was on the old switch assembly. Install and tighten the three mounting nuts on the bottom of the Tank Assy.
- xiv. Solder the leads from the variable coil to the new switch assembly.
- xv. Install the Tune Capacitor Assemblies and the Load Capacitor Assemblies, making sure that the assemblies are correctly installed per your identifying marks. Check that all the contacts on these assemblies engage the switch tabs.
- xvi. Install the Coil Assy, and make all solder connections between it and the switch assembly.
- xvii. Install the top cover and tighten the six Phillips screws.
- xviii. Install the Geneva drive gear.
- xix. Check the shaft alignment as follows:

With the drive pin completely disengaged from the Geneva drive gear, check that the three movable switch contacts in each section are centered on their corresponding fixed contacts. Manually rotate the band switch drive through all the frequency bands, checking the alignment of the movable switch contacts in each band.
- xx. To align the shaft:

Remove the two Phillips screws and the Geneva drive gear. Twist the shaft manually until the contacts are centered. Position the Geneva drive gear onto the adjustable disk so that the mounting holes in the drive gear align with the holes in the disk. Install and tighten the Phillips screws. Rotate the drive 360° and check whether the contact alignment is still correct. You may



have to go back and forth a couple of times to optimize the alignment for the entire range of bands.

(2) S3, Overtravel Limit Switch

**NOTE**

This switch is located on the bottom of the Tank Assy.

- (a) Manually rotate the band switch drive pulley until the switch actuator is in the middle of the cam. The switch should be actuated at this point.
- (b) Note the orientation of the flexible cable, and unsolder the flexible cable wires from the switch.
- (c) Remove the two Phillips mounting screws from the standoffs, and remove the switch.
- (d) Mount the new switch to the standoffs with the two Phillips screws.
- (e) Resolder the flexible cable wires, making sure that the cable orientation is correct.
- (f) Before tightening the screws, make sure that the switch is actuated but not bottomed out. In other words, the switch actuator should not be at the limit of its travel.

(3) Band Switch Drive Motor

- (a) Unsolder the motor leads at the bottom of the chassis where they are connected to the flexible cable. Mark the flexible cable wires appropriately.
- (b) Slip the drive belt off the drive pulley.
- (c) Loosen the setscrew and remove the drive pulley from the motor shaft.
- (d) Remove the three Phillips screws holding the motor to the chassis.
- (e) Remove the motor.

- (f) Install the new motor, reversing the order of the above steps.

(4) Coil Drive Motor

- (a) Unsolder the flexible cable leads from the coil drive motor and mark them.
- (b) Remove the four Phillips screws holding the Coil Drive Assy to the chassis.
- (c) Pull the Coil Drive Assy straight out, disengaging the Coil Drive Assy coupling from the coil shaft coupling (the couplings are mated together with a phenolic key which will fall out when the Coil Drive Assy is removed).
- (d) Slip the drive belt off the coil drive pulley.
- (e) Loosen the setscrew and remove the pulley from the motor shaft.
- (f) Remove the three screws holding the motor to the Coil Drive Assy mounting plate.
- (g) Remove the motor.
- (h) Install the new motor, reversing the order of the above steps and being careful not to disturb the position of the gears.

(5) Motion Sensor Assy

- (a) Loosen the two slotted setscrews on the Motion Sensor side of the white plastic coupling.
- (b) Unsolder the four Motion Sensor flexible cable wires, being careful to mark their positions.
- (c) Remove the two Phillips mounting screws and remove the Motion Sensor Assy.
- (d) Remove the nut and remove the Motion Sensor from its mounting plate.

- (e) To install the new Motion Sensor, reverse the order of the above steps.
- (6) Limit Switch
- (a) Manually position the tuning coil so that it is at least a third of the way from either end stop.
  - (b) Remove the two Phillips screws holding the Limit Switch Assy.
  - (c) Remove the nut and remove the Limit Switch from its mounting plate.
  - (d) Unsolder the Limit Switch from its flexible cable, and note the cable's orientation.
  - (e) To install a new Limit Switch, reverse the order of the above steps.
- (7) Tuning Coil
- (a) Manually position the tuning coil to its rear end stop.
  - (b) Remove the Coil Drive Assy, but do not unsolder any wires (see paragraph 4 above).
  - (c) Remove the two nuts, and disconnect the three straps at the front of the coil.
  - (d) Grasping the coil with one hand, remove the two Phillips screws holding the tuning coil assembly to the side of the chassis.
  - (e) Remove the tuning coil assembly, and remove its coupling half.
  - (f) Assemble the coupling half to the shaft of the new coil assembly using the two setscrews. Manually position the new tuning coil assembly so that it is in the same position as the old one (with the coil at its rear end stop).
  - (g) Fasten the new tuning coil assembly to the side of the chassis with the two Phillips screws. Do not tighten the screws.
  - (h) Connect the straps at the front of the coil.
  - (i) Install the Coil Drive Assy, mating the coil drive coupling to the coil shaft coupling with the phenolic key. If the two couplings do not line up, rotate the coil shaft until they do. DO NOT ROTATE THE COIL DRIVE COUPLING.
  - (j) Tighten the Coil Drive Assy mounting screws.

## APPENDIX A

CHECKS PERFORMED DURING THE AUTOMATIC BIT ROUTINE FOR THE 1 KW LPA

## NOTE

If BIT is initiated during WARMUP, only the tests up to and including the Band Switch/Servo Coil Test are performed.

1. Front Panel Test. At the start of the test, the front panel is disabled and remains so for the remainder of the test. Also at the start of the test, all front panel LCD segments and LED indicators are turned on. They stay on for the remainder of the test with the exception of the condition when tune power is requested from the 100 Watt Transceiver (see "Keying Test").

2. Micro Control Test. The microprocessor is checked. If its operation is determined to be incorrect, FAULT 2-01 is declared.

3. Primary Power Test. The primary power level is sampled. If it is not between 80 and 120% of the nominal value, FAULT 2-03 is declared.

4. Low Voltage Supply Test. The 13.5 V supply is sampled. If it is not between 10 and 16 Vdc, FAULT 2-04 is declared.

5. Transmitter Fault Test. If the XMTR-FAULT signal line (temperature sensor) is active, FAULT 2-05 is declared.

6. Band Switch/Servo Coil Test. For this test, a band other than the current operating band is selected for the band switch. Once this position is reached, the switch returns to the current operating band position. If the switch does not turn, or if it takes over 10 seconds to reach the selected band, FAULT 2-06 is declared. The coil is moved to MIN L and then to MAX L, and the coil position counter is checked at both limits. If the coil does not move, or if the position counter is inaccurate, FAULT 2-07 is declared. If the 1 KW LPA is in WARMUP, no further testing is done.

7. High Voltage Test. With the 1 KW LPA in STANDBY, FAULT 2-08 is declared if the DC plate voltage is greater than 100 volts. The 1 KW LPA is put into OPERATE. If the DC plate voltage is not between 2000 and 5000 volts, FAULT 2-09 is

declared. If the plate current is greater than 5 mA, FAULT 2-10 is declared.

8. Bias Test. The power amplifier bias is turned on (the LPA is keyed without RF drive). If the plate current is not between 20 and 150 mA, FAULT 2-11 is declared.

9. Keying Test. An RF MUTE message is sent to the 100 Watt Transceiver. If the RF input signal level is not below 6 watts in 200 milliseconds, FAULT 2-12 is declared. If the RF input falls below 6 watts, the T/R relay is keyed and the RF MUTE signal is removed. Tune Power Request (TPR) and Transmit Gain Control Tune Power Request (TGC TPR) messages are sent to the 100 Watt Transceiver. The message "rF" is sent to the METER LCD display to let the operator know that RF input power is required to complete the test. This message remains until the RF input signal level is greater than 5 watts. If the RF input signal is not greater than 5 watts in 20 seconds, FAULT 2-13 is declared. If the RF input signal level is sufficient, the power amplifier plate current is checked. If the power amplifier plate current is not between 325 mA and 480 mA, FAULT 2-14 is declared. The DC plate voltage is checked again at this point; and if it is not within the previously specified limits for the OPERATE mode (2000 to 5000 Vdc), FAULT 2-09 is declared.

10. Tuning Test. A TGC Lock command is sent to the 100 Watt Transceiver. Using the auto-tuning software, the coil is moved toward MIN L while searching for a tune peak. If no tune peak is found, FAULT 2-15 is declared. When the tune peak is found, forward power is checked. If the forward power is not between 100 watts and 400 watts, FAULT 2-16 is declared. If the forward power is normal, the VSWR is checked. If the VSWR is not less than 2.25:1, FAULT 2-17 is declared. If the VSWR is normal, the ratio of forward power to RF input power is checked. This ratio must be between 5

and 60. If not, FAULT 2-18 is declared. Tune Power Request Off, TGC Tune Power Request Off, and TGC Lock Off commands are sent to the 100 Watt Transceiver when this part of the test is completed.

11. Transceiver Serial Link Test. As in normal operation, certain failures in the serial link to the transceiver during the BIT test cause FAULT 2-21 to be declared.

12. Test Completion.

- (a) The BIT tests described in the above paragraphs are continued until a fault is encountered. When a fault is flagged, all further testing is aborted.
- (1) If the BIT test was initiated from the 100 Watt Transceiver, the fault code is displayed on the transceiver LCD display. The fault code will also appear on the LPA's LCD display if the METER selector switch is placed in the STATUS/FAULT position. The fault code may be cleared by commanding the LPA to OPERATE from the 100 Watt Transceiver or by moving the METER selector switch out of the STATUS/FAULT position.
- (2) If the BIT test was initiated from the LPA, the fault code is displayed on the LPA's front panel meter. The fault code will also

appear on the transceiver's LCD display if "2ND," "TEST" is pressed. To remove the LPA from the test mode, the METER selector switch must be moved out of the STATUS/FAULT position. The fault code may be cleared by commanding the LPA to OPERATE from the 100 Watt Transceiver (if the LPA is placed back in AUTO) or by moving the METER selector switch to the STATUS/FAULT position and then out again.

- (b) If no fault is encountered during any of the tests, the following occurs:
  - (1) If the BIT test was initiated from the 100 Watt Transceiver, the message "PASSEd" is displayed on the transceiver front panel for 5 seconds; and the LPA front panel returns immediately to its normal operating mode.
  - (2) If the BIT test was initiated from the LPA, the message "PASS" is displayed on the meter. The message will remain there as long as the METER selector switch is in the STATUS/FAULT position. When the selector switch is moved out of the STATUS/FAULT position, the message disappears and the LPA front panel returns to its normal operating mode.

## APPENDIX B

## Meter Functions and Normal Operating Ranges

Position	Function	Range/Units	Normal (Stby/Warmup)	Normal (Operate, Keyed in CW)
PRI PWR (%)	Displays the average primary power input as a percentage of the nominal value	0% to 166%	90 to 110	90 to 110
13.5 VDC	Displays the average output of the low voltage power supply	0 to +22 Vdc	11 to 16	11 to 16
DC PLATE (VOLTS)	Displays the average plate voltage of the power amplifier tube	0 to +5000 Vdc	0	2400 to 3200 <sup>(1)</sup>
I <sub>K</sub>	Displays the average cathode (plate) current of the power amplifier tube	0 to 2000 mA	0	700 to 1100 <sup>(1)</sup>
RF IN (WATTS)	Displays the peak RF input power from the 100 Watt Transceiver	0 to 250 W	0 to 100 <sup>(2)</sup>	40 to 100 <sup>(1)</sup>
RF PLATE (VOLTS)	Displays the peak RF voltage at the plate of the power amplifier tube (with respect to the average DC voltage)	0 to 5000 Vdc	0	1800 to 2400 <sup>(1)</sup>
FWD PWR (WATTS)	Displays the peak forward power at the RF output	0 to 1500 W	0	900 to 1100
REFL PWR (WATTS)	Displays the peak reflected power at the RF output	0 to 1500 W	0	0 to 100, depending on load <sup>(1)</sup>
ANT VSWR	Displays the peak ratio of the mismatch between the 1 KW LPA and its load, be it antenna, antenna coupler, or dummy load	1:1 to 999:1	0	1:1 to 2:1 <sup>(1)</sup>
COIL POS	Displays the servo coil position	100 to 1770	See Figure 3-1	See Figure 3-1
STATUS/FAULT	Displays a fault code. If the FAULT light is lit and the meter is switched to the STATUS/FAULT position, a fault code will be displayed. When the selector switch is moved out of the STATUS/FAULT position, the fault code will be cleared and the FAULT light will be turned off.	Fault codes		

(1) With a power output of 1 KW, as indicated on the FWD PWR meter.

(2) With the transceiver keyed; otherwise, the reading will be 0 W.



## CHAPTER 7

### ILLUSTRATED PARTS BREAKDOWN

#### Section 1. INTRODUCTION

**7-1. PURPOSE.** This chapter lists, illustrates, and describes the detail parts for the 1 KW LPA. Its purpose is for the identification, requisitioning, and issuance of parts at the depot level.

**7-2. SCOPE.** Bulk electrical items, such as terminals, wire, heat shrink tubing, etc., are not listed in this manual. Common hardware items, such as screws, washers, nuts, etc., when used to attach structural components that are not normally removed or disassembled, are also not listed. In general, the parts installed at the time the 1 KW LPA was manufactured are listed and identified in this chapter. When a part (including vendor items), which is different from the original, was installed during the manufacture of later items, series, or blocks, all parts are listed (and "Usable-On" coded). However, when the original part does not have continued application (no spares of the original were procured or such spares are no longer authorized for replacement), only the preferred part is listed. Also, when a part was installed during modification, and the original does not have continued application, only the preferred item is listed. Interchangeable and substitute parts, subsequently authorized by the Government, are not listed in this chapter; such items are identified by information available through the Interchangeable and Substitute (I & S) Data Systems. Refer to T.O. 00-25-184. When a standard size part can be replaced with an oversize or undersize part, the latter parts, showing sizes, are also listed. Repair Parts Kits

and Quick Change Units are listed when they are available for replacement.

**7-3. CHAPTER ORGANIZATION.** This chapter is divided into two sections. Section I, INTRODUCTION, explains the purpose, scope, and organization of the chapter. Section II, MAINTENANCE PARTS LIST, consists of illustrations, in which the detail parts of the 1 KW LP are identified by numbers (called index numbers), followed by lists which contain parts numbers, descriptions, and other relevant data for the items identified on the illustrations. Section II also contains two other lists: A numerical index, which lists the parts in alphanumerical sequence; and a reference designator index, which lists the electrical parts in alphabetical sequence by their reference designators.

**7-4. SOURCE, MAINTENANCE, AND RECOVERABILITY (SMR) CODES.** This chapter contains Air Force Peculiar In-Being Source and Repair Codes only. Definitions of these SMR codes, as well as detailed coding criteria and transposition matrices for each coding method, may be obtained from T.O. 00-25-195. Refer to page 7-13.

**7.5. FEDERAL SUPPLY CODES FOR MANUFACTURERS (FSCM).** The codes used in this chapter are as follows. The first list is in numerical order by FSCM; the second is in alphabetical order by manufacturer name.

**T.O. 31R2-2URC-123**

<b>FSCM</b>	<b>NAME AND ADDRESS</b>				
		02660	Bunker Ramo-Eltra Corporation Amphenol Division 2801 S. 25th Avenue Broadview, IL 60153	06980	Varian Associates, Inc. EIMAC Division 301 Industrial Way San Carlos, CA 94070
00000	Ordnance Corps The Defense Logistics Services Center	02735	RCA Corporation Solid State Division Route 202 Somerville, NJ 08876	07263	Fairchild Camera and Instrument Corporation Semiconductor Division Subsidiary of Schlumberger LTD North American Sales Mail Stop 14-1053 401 Ellis Street P.O. Drawer 7284 Mountain View, CA 94042
00141	PIC Design Corporation Division of Wells-Berrous Corporation Benson Road P.O. Box 1004 Middlebury, CT 06762	02768	Illinois Tool Works, Inc. Fastex Division 195 Algonquin Road Des Plaines, IL 60016		
00159	Acme Electric Corporation Cuba, NY	03508	General Electric Company Semi-Conductor Products Department W. Genesee Street Auburn, NY 13021	07707	USM Corporation Subsidiary of Emhart Industries, Inc. USM Fastener Division 510 River Road Shelton, CT 06484
00213	Nytronics Components Group, Inc. Subsidiary of Nytronics Inc. Orange Street Darlington, SC 29532	03888	Pyrofilm Division Division of KDI Electronics Inc. 60 S. Jefferson Road Whippany, NJ 07981	07858	Arrow Hart Canada LTD Scarborough, Ontario Canada M8Z 2R4
00348	Microtran Co., Inc. 145 E. Mineola Avenue P.O. Box 236 Valley Stream, NY 11582	04009	Crouse-Hinds Arrow Hart Inc. Arrow Hart Division 103 Hawthorn Street Hartford, CT 06105	08289	Blinn Delbert Company, Inc. The 1678 E. Mission Blvd. P.O. Box 2007 Pomona, CA 91769 5065
00493	Sargent Art Division of Mead Corporation Hazleton, PA	04222	AVX Ceramics Division of AVX Corporation 19th Avenue South P.O. Box 867 Myrtle Beach, SC 29577	08484	Breeze-Eastern Corporation Subsidiary of Transtechnology Corporation 700 Liberty Avenue Union, NJ 07083
00752	Eaton Corporation All Division Long Island Plants Commack Road Deer Park, L.I., NY 11729	04386	Litton Industries, Inc. Litton Systems Inc. Triad-Utrad Division 305 N. Briant Street Huntington, IN 46750	08544	United Shoe Machinery Corporation Cincinnati, OH
00758	Neilsen Products Company Lake Elmo, MN	04426	Licon Division of Illinois Tool Works, Inc. 6615 W. Irving Park Road Chicago, IL 60634	08779	Signal Transformer Company, Inc. 500 Bayview Avenue Inwood, NY 11696
00779	AMP, Inc. 2800 Fulling Mill P.O. Box 3608 Harrisburg, PA 17105	04713	Motorola, Inc. Semiconductor Products Sector 5005 E. McDowell Road Phoenix, AZ 85008	09023	Cornell-Dubilier Electronics 118 E. Jones Street Fuquay-Varina, NC 27526
00853	Sangamo Weston, Inc. Sangamo Capacitor Division Subsidiary of Schlumberger LTD Sangamo Road P.O. Box 128 Pickens, SC 29671	05326	General Electric Company Aviation Service Operation/CINTI 333 W. Seymour Avenue Cincinnati, OH 45216	09166	Stone City Products, Inc. 1206 7th Street P.O. Box 369 Bedford, IN 47421
01009	Alden Products Company 117 N. Main Street P.O. Box 860 Brockton, MA 02403	05828	General Instrument Corporation Government Systems Division 600 W. John Street Hicksville, NY 11802	09214	General Electric Company Semi-Conductor Products Department Power Components Operation W. Genesee Street Auburn, NY 13021
01295	Texas Instruments Inc. Semiconductor Group 13500 N. Central Expressway P.O. Box 225012 M/S 49 Dallas, TX 75265	06090	Raychem Corporation 300 Constitution Drive Menlo Park, CA 94025	09353	C and K Components, Inc. 15 Riverdale Avenue Newton, MA 02158
01961	Varian Associates, Inc. Pulse Engineering Subsidiary 7250 Convoy CT P.O. Box 12235 San Diego, CA 92112	06383	Panduit Corporation 17301 Ridgeland Tinley Park, IL 60477	10026	CSI Capacitors A Division of CSI Technologies, Inc. Del Dios Highway P.O. Box 2052 Escondido, CA 92025
02111	Spectrol Electronics Corporation Subsidiary of Carrier Corporation 17070 E. Gale Avenue P.O. Box 1220 City of Industry, CA 91749	06402	E-T-A Circuit Breakers 7400 N. Croname Road Chicago, IL 60648	10054	Marson Corp 130 Crescent Avenue Chelsea, MA 02150
02114	Amperex Electronic Corporation Ferroxcube Division 5083 Kings HWY Saugerties, NY 12477	06540	Mite Corporation Amatom Electronic Hardware Division 446 Blake Street New Haven, CT 06515	11195	Magna Division Vermont American Corporation 1001 West Park Road Elizabethtown, KY 42701
02289	Hi-G Company Subsidiary of Nytronics Inc. 101 Locust Street Hartford, CT 06114			11236	CTS of Berne, Inc. 406 Parr Road Berne, IN 46711



11897	Plastiglide Manufacturing Corporation 2701 W. El Segundo Blvd. Hawthorne, CA 90250	16546	Centralab, Inc. A North American Philips Company 4561 Colorado Los Angeles, CA 90039	21340	ITT Telecom Products Corporation Network Systems Division HWY 137 Suncrest Drive P.O. Box N Carroll Reece Station Johnson City, TN 37601
12040	National Semiconductor Corporation Commerce Drive P.O. Box 443 Danbury, CT 06810	16733	Cablewave Systems, Inc. 60 Dodge Avenue North Haven, CT 06473	22526	Du Pont E I De Nemours and Company, Inc. Photo Products Department Berg Electronics Division Route 83 New Cumberland, PA 17070
12909	Cardion Electronics Division of General Signal Controls, Inc. A Unit of General Signal Corporation Long Island Expressway Woodbury, NY 11797	16741	Triad Transformer Corporation Huntington, IN	22701	Bestran Corporation Dilectron Division 2669 So. Myrtle Avenue Monrovia, CA 91016
12969	Unitrode Corporation 580 Pleasant Street Watertown, MA 02172	17117	Electronic Molding Corporation 96 Mill Street Woonsocket, RI 02895	22903	Singer Company The Link Flight Simulation Division Advanced Products Operation 1077 E. Arques Avenue P.O. Box 3484 Sunnyvale, CA 94088
13103	Thermalloy Company, Inc. 2021 W. Valley View Lane P.O. Box 340839 Dallas, TX 75234	17856	Siliconix, Inc. 2201 Laurelwood Road Santa Clara, CA 95054	24446	General Electric Company 3135 Easton Turnpike Fairfield, CT 06431
13499	Rockwell International Corporation Collins Telecommunications Products Division Defense Electronics Operations 855 NE 35th Street Cedar Rapids, IA 52498	18212	American Trans-Coil Corporation 124-06 101st Avenue Richmond Hill, NY 11419	24546	Corning Glass Works 550 High Street Bradford, PA 16701
13764	Micro Plastics, Inc. HWY 178 N. Flippin, AR 72634	18324	Signetics Corporation Military Products Division 4130 S. Market Court Sacramento, CA 95834	25330	General Connector Corporation Subsidiary of the Union Corporation 80 Bridge Street Newton, MA 02158
14304	Harris Corporation RF Communications Division 1680 University Avenue Rochester, NY 14610	18722	RCA Corporation Solid State Division Crestwood Road Mountaintop, PA 18707	25403	Amperex Electronic Corporation Semiconductor Solid State and Active Devices-Electro Optical Devices Providence Pike Slatersville, RI 02876
14519	Designatronics, Inc. 55 S. Denton Avenue New Hyde Park, NY 11040	18796	Murato Erie Technological Products State College Operations 1900 W. College Avenue State College, PA 16801	26066	Minnesota Mining and Manufacturing Company Industrial Tape Division 3M Center St Paul, MN 55101
14655	Cornell-Dubilier Electronics Division of Federal Pacific Electric Company Government Contracts Department 150 Ave L Newark, NJ 07101	18876	Department of Army U.S. Army Missile Command Redstone Arsenal, AL 35809	26344	Mite Corporation 466 Blake Street New Haven, CT 06515
14674	Corning Glass Works Houghton Park Corning, NY 14830	18915	Birtcher Corporation The Industrial Division 4501 N. Arden Drive P.O. Box 4399 El Monte, CA 91734	26667	Litton Industries, Inc. Triad Distributor Division Huntington, IN
14933	Defense Electronics Supply Center Dayton, OH 45401	19200	U.S. Army Armament Research and Development Command Dover, NJ 07801	27014	National Semiconductor Corporation 2900 Semiconductor Drive Santa Clara, CA 95051
15542	Mini-Circuits Laboratory Division of Scientific Components Corporation 2625 E. 14th Street Brooklyn, NY 11235	19207	U.S. Army Tank Automotive Command Warren, MI 48090	27264	Molex, Inc. 2222 Wellington Court Lisle, IL 60532
15801	Fenwal Electronics Division of Kidde Walter and Company, Inc. 63 Fountain Street Framingham, MA 01701	19396	Illinois Tool Works, Inc. Paktron Division 900 Follin Lane S.E. Vienna, VA 22180	27777	Varo, Inc. Electron Devices Division 2203 Walnut Street P.O. Box 401146 Garland, TX 75040
15912	T and B/Ansley Corporation Subsidiary of Thomas and Betts Corporation 4371 Valley Blvd. Los Angeles, CA 90031	19647	Caddock Electronics, Inc. 1717 Chicago Avenue Riverside, CA 92507	28124	Minnesota Mining and Manufacturing Company Industrial Coated Abrasives Division 3M Center St. Paul, MN 55101
15969	Dixie Chemical Company 3635 W. Dallas Street Houston, TX 77019	19701	Mepco/Electra, Inc. A North American Philips Company P.O. Box 760 Mineral Wells, TX 76067		
		21052	High Energy Corporation Subsidiary of Inductotherm Corporation Lower Valley Road Parkesburg, PA 19365		
		21317	Electronic Applications Company 4918 Santa Anita Avenue El Monte, CA 91734		

**T.O. 31R2-2URC-123**

28480	Hewlett-Packard Company Corporate HQ 3000 Hanover Street Palo Alto, CA 94304	34649	Intel Corporation 3065 Bowers Avenue Santa Clara, CA 95051	54254	Minnesota Mining and Manufacturing Company Data Recording Products Division 350 S. Lewis Road Camarillo, CA 93010
28482	Electronic Laboratory Supply Company 7208 Germantown Avenue Philadelphia, PA 19119	34899	Fair-Rite Products Corporation 1 Commercial Row Walkill, NY 12589	54473	Matsushita Electric Corporation of America One Panasonic Way P.O. Box 1501 Secaucus, NJ 07094
28520	Heyco Molded Products 1750 Blvd. P.O. Box 160 Kenilworth, NJ 07033	37695	Magnavox Government and Industrial Electronics Co. 1313 Production Road Fort Wayne, IN 46808	54904	Eltra Corporation Subsidiary of Allied Chemical Company Medwec Division 105 Skyport Drive P.O. Box 417 Scottsbluff, NE 69361
29964	Allied Devices Corporation 2365 Milburn Avenue P.O. Drawer E. Baldwin, NY 11510	44122	LXD 24500 High Point Road Cleveland, OH 44122	55002	Power Conversion, Inc. 495 Boulevard Elmwood Park, NJ 07407
30142	Minnesota Mining and Manufacturing Company Energy Systems 3M Center Bldg. 551 St. Paul, MN 55101	44655	Ohmite Manufacturing Company 3601 W. Howard Street Skokie, IL 60076	55285	The Bergquist Company, Inc. 5300 Edina Industrial Blvd. Minneapolis, MN 55435
31433	Union Carbide Corporation Electronics Division HWY 276 SE P.O. Box 5928 Greenville, SC 29606	46384	Penn Engineering and Manufacturing Corporation Old Easton Road P.O. Box 1000 Danboro, PA 18916	55322	Samtec, Inc. 810 Progress Blvd. P.O. Box 1147 New Albany, IN 47150
31922	Leeds and Northrup Company A Unit of General Signal Corporation Sumneytown Pike North Wales, PA 19454	49671	RCA Corporation 30 Rockefeller Plaza New York, NY 10020	55566	R A F Electronic Hardware, Inc. 95 Silvermine Road Seymour, CT 06483
32039	Zeus Industrial Products, Inc. Ft. Thompson Street Raritan, NJ 08869	50157	Midwest Components, Inc. 1981 Port City Blvd. P.O. Box 787 Muskegon, MI 49443	56289	Sprague Electric Company 87 Marshall Street North Adams, MA 01247
32097	PCC Pertec Division Pertec Computer Corporation 9600 Irondale Avenue Chatsworth, CA 91311	50173	Curt Straub Enterprises 444 W. Ocean Blvd. Suite 1106 Long Beach, CA 90802	56637	RCD Components, Inc. 330 Bedford Street Manchester, NH 03101
32284	Rotron Controls Division Rotron, Inc. Woodstock, NY	50434	Hewlett-Packard Company Optoelectronics Division 640 Page Hill Road Palo Alto, CA 94304	56699	Mepco/Electra, Inc. 6071 St. Andrews Road Columbia, SC 29210
32293	Intersil Inc. Subsidiary of General Electric Company 10710 N. Tantau Avenue Cupertino, CA 95014	51144	IDI Electric Canada LTD 33 Fuller Road Box 159 Ajax, Ontario Canada L1S 2E1	57074	Alberox Corporation New Bedford, MA
32848	Thompson Industries Division of W M F Container Corporation 2501 E. Magnolia Street Phoenix, AZ 85036	51984	NEC America, Inc. 2741 Prosperity Avenue Fairfax, VA 22031	57285	Millen Division Electronic Instrument and Specialty Corporation 42 Pleasant Street Stoneham, MA 02180
32890	Luminescent Systems Inc. Etna Road Grafton County Lebanon, NH 03766	52458	Magnum Electric Corporation 6385 Dixie HWY Erie, MI 48133	57771	Stimpson Company, Inc. 900 Sylvan Avenue Bayport, NY 11705
32997	Bourns, Inc. Triopot Division 1200 Columbia Avenue Riverside, CA 92507	52559	Metraplex Corporation Berkshire Industrial Park Bldg. 3 Bethel, CT 06801	57921	Bourns, Inc. Precisions/Controls Division 1200 Columbia Avenue Riverside, CA 92507
34335	Advanced Micro Devices 901 Thompson Place Sunnyvale, CA 94086	52760	Minnesota Mining and Manufacturing Company Electro Products Division 341 Factory Road Addison, IL 60101	57922	Bourns, Inc. Precisions/Controls Division 1200 Columbia Avenue Riverside, CA 92507
34553	Amperex Electronic Corporation Component Division Hauppauge, NY	53373	Midland-Ross Corporation Cambion Division Barnstead Road Pittsfield, NH 03263	57924	Bourns, Inc. Networks Division 12155 Magnolia Avenue Riverside, CA 92503
		53894	Aham, Inc. 27901 Front Street Rancho California, CA 92390	58167	Palco Connector, Inc. 75 Center Street Bristol, CT 06010