



8371 Release Notes Version 1.1 Apr 99

Version 1.1 Release Notes Apr 1999

© Copyright International Business Machines Corporation 1999. All rights reserved.

US Government Users Restricted Rights – Use duplication or disclosure restricted by GSA ADP Schedule Contract with IBM Corp.

8371 and 8265-L3S Release Notes Version 1.1 - April 1999

Latest Release Notes Are On the Web

Go to www.networking.ibm.com/support for the latest version of these Release Notes.

These Release Notes apply to the IBM 8371-A16 and to the 8265-L3S (hereafter referred to as the 8371 Blade).

Safety Notice

Danger: Double-pole/neutral fusing in the power supply. Power might present in the product unless the power cord is unplugged.

Cuidado: Fusível bipolar/neutro na fonte de alimentação. Pode haver energia presente no produto, a menos que o cabo de alimentação esteja desconectado.

Waarschuwing:

Dubbelpool/neutraal zekering in de voedingseenheid. Er kan spanning in het product aanwezig zijn zolang de stekker in het stopcontact zit.

Pas på!

Strømforsyningssenheden; er sikret til brug ved 110 og 220 volt. Der kan være; spænding; i produktet, medmindre netledningen er trukket ud.

VAARA: Virtalähde on varustettu kaksinapaisella sulakkeella, jossa on myös maanapa. Tuotteessa voi olla jännite, jos verkkokohtoa ei ole irrotettu.

ATTENTION : L'un des deux fusibles est sur le neutre. L'alimentation est protégée par fusibles sur les deux pôles (phase et neutre). Préservez le courant possible sauf si le cordon d'alimentation est débranché.

Achtung: Zweipolige bzw. Neutralleiter-Sicherung im Netzteil. Netzstecker ziehen, um sicherzustellen, daß keine Spannung am Gerät anliegt.

Attenzione: L'alimentatore contiene fusibili su fasi/neutro. Può essere presente tensione nell'apparecchiatura se il cavo di alimentazione è collegato.

Advarsel: Topolet/nøytral; sikring i strømforsyningssenheten.; Det kan være; strø.m; i maskinen hvis ikke nettkabelen er dratt ut .

Cuidado:

Protecção (por fusíveis) bipolar com neutro na fonte de alimentação. A menos que o cabo de alimentação esteja desligado, o produto pode estar sob tensão.

Precaución: Hay una fusión de doble polo/neutro en la fuente de alimentación. El producto podría estar cargado eléctricamente a menos que el cable de alimentación esté desconectado.

VARNING: Nötaggregatet är dubbelpoligt avsökrat. Det kan finnas ström i produkten såvida inte nätkabeln är urkopplad.

تحذير: القطب الثنائي أحايي الانصهار في مصدر الطاقة .
يمكن أن تكون الكهرباء موجودة في المنتج ما لم يتم فصل سلك الكهرباء.

Предупреждение: Дублирано - фаза/нула свързване в енергийното захранване. Възможно е наличие на ел.енергия в уреда, докато захранващият кабел не е изваден от контакта.

Opasnost: Energetski izvor opremljen je osiguračima na faznom i nultom priključku. Uredaj može ostati pod naponom sve dok se priključni kabel ne odvoji od utičnice.

注意: 电源中装有双柱式/中性保险丝。除非未插入电源线，否则产品带电。

注意：電源供應器內含雙極/中性熔絲 (Double-pole/neutral fusing)。
未將電源線自插座拔掉前，本產品內部可能有電存在。

Pozor: V napájecím zdroji je dvoupólové jištění (pojistka ve středním vodiči). Dokud není napájecí šňůra odpojená od sítě, může být zařízení pod napětím.

Προσοχή: Ασφάλεια δύο πόλων/ουδέτερου στην πηγή ρεύματος. Ενδέχεται να υπάρχει ηλεκτρική ισχύς στο προϊόν εάν δεν έχει αποσυνδεθεί το καλώδιο ρεύματος.

זהירות : נתיק דו-קוטבי/נייטרלי באספקת הכוח.
יש לנתק את כבל הכוח כדי למנוע זרם חשמל
במוחץ .

Figyelem: A tápegységen kívül a biztosíték található.
A termék kikapcsolt állapotban is feszültség alatt állhat,
kivéve, ha a tápkábel ki van húzva.

注意 :
この電源は、2極／中性線にヒューズを使用しています。
電源コードを抜いていない状態では電圧がかかっています。

주의: 전원 공급 장치에 양극/중성의 퓨즈가 있습니다.
전원 코드가 연결되지 않아도 제품 내에 전원이 잔류할
수 있습니다.

Uzmanību: Divpolu/neitrālā apvienotā strāvas apgāde.
Iespējams, ka produktā ir elektriskā strāva, ja strāvas vada
kontaktdakša nav izrauta no ligzdas.

Dēmesio: Čienginyje yra atvirų dvigubų kontaktų su
įtampa. Jeigu įrenginys neišjungtas, kai kurios dalys
gali būti su įtampa.

Опасност: Во единицата за напојување има двополен осигурувач. Доколку
кабелот за напојување не е исклучен, во производот може да биде присутна
електрична енергија.

Uwaga: W zasilaczu zamontowany jest bezpiecznik.
Dopóki kabel zasilający nie zostanie odłączony w
urządzeniu może występować napięcie.

Pericol: O siguranță neutră/două capete este în sursa de alimentare.
Tensiunea poate să fie prezentă în produs dacă nu este scos din priză
cablul de alimentare.

Осторожно: Источник питания с двухполюсным
предохранителем. Устройство может быть под
напряжением, пока вы не выдернете шнур из розетки.

Опасност: Извор напајања је опремљен осигурачима на фазном и нултом прикључку. У уређају може бити присутан напон осим ако је прикључни кабл одвојен од утичнице.

Výstraha: Poistky sú na oboch póloch napájacieho zdroja. Pokiaľ nie je odpojená šnúra zo siete, zariadenie môže byť pod napäťom.

Nevarnost: Pri napajalniku je zagotovljeno varovanje polov in nevtralnega vodnika. Napetost je lahko prisotna na izdelku, če priključnega kabla ne potegnemo iz vtičnice.

Dikkat: Güç kaynağı çift kutuplu, topraklı sigorta içerir. Güç kablosu przinden çekilmekçe ürününde elektrik bulunabilir.

Loading the 8371 and the 8371 Blade Operational Code

ATTENTION: This device is shipped with a downlevel version of the operational code. To download the latest operational code for the 8371, or to see Tech Tips, customer forums, or to register for information updates, go to:

[www.networking.ibm.com/support/products.nsf/techsupport/\(8371\)?OpenDocument](http://www.networking.ibm.com/support/products.nsf/techsupport/(8371)?OpenDocument)

Loading the 8371 Blade Control-Point Switch Code

You need to download a Control Point Switch code from the Web for 8371 Blade from

[www.networking.ibm.com/support/products.nsf/techsupport/\(8265\)?OpenDocument](http://www.networking.ibm.com/support/products.nsf/techsupport/(8265)?OpenDocument)

The microcode level should be **PNNI Version 4.1.2** or higher.

Using the MPOA Client Function on the 8371

If you use the MPOA Client function on the 8371 with the MPOA Server function on the MSS Server, the MSS Server must run microcode Version 2.1 PTF 5 (or higher) or microcode Version 2.2 PTF 3 (or higher). The latest software is available from www.networking.ibm.com/support/8210. Ensure that you read the MSS upgrade instructions.

Note: The MSS Server needs to have 64MB of memory installed.

8210 MPOA Server PTF Requirement

A known problem with the MPOA Server function on the 8210 MSS Server supporting the MPOA Client function on the 8371 has been corrected in MSS Server microcode Version 2.2 PTF 3 (or higher) or Version 2.1 PTF 5 (or higher). If you use the MPOA Server function on the 8210 MSS Server to support the MPOA Client function on the 8371, the 8210 MSS Server may run out of memory after several days of sustained cache imposition activities. The 8210 will stop with an indication of "no mem" and traffic using the route including the 8210 and the 8371 will stop. The 8210 must be rebooted to re-establish the routed path.

If you are experiencing this problem, the PTF with the fix is required to overcome the problem. You may perform the following steps on the 8210 to verify that you have the memory leak problem:

1. Allow the 8210 to reach steady state. This may take several hours.
2. Use the following example from t 5 to display the imposition cache for the MPS.

```
+ protocol mpoa
MPOA> mps
MPS> imposition-cache list
```
3. Repeat the **imposition-cache list** command several times to verify that the number of MPOA imposition cache entries is not fluctuating.
4. Return to the OPCON prompt (+) and use the **memory** command several times over a period of several hours to determine a trend in memory usage. It is normal to have an increase in memory usage with an increase in traffic. However, memory usage should reach a steady state.

```
+ memory

Physical installed memory: 64 MB
Total routing (heap) memory: 31 MB
Routing memory in use: 23 %

      Total    Reserve    Never    Perm    Temp    Prev
      Alloc    Alloc    Alloc    Alloc
Heap memory 32190464 1297656 24455700 5926172 1631384 177208

Number of global buffers: Total = 400, Free = 389, Fair = 17, Low = 80
Global buff size: Data = 9234, Hdr = 64, Wrap = 74, Trail = 32, Total = 9408
```

If the **routing memory in use** and the **Never Alloc** entries show an upward trend in usage after the device has reached steady state, you may have a memory leak.

Network Interfaces Automatically Configured

Table 1. Network Interfaces Automatically Configured

Device Types	Slot	Ports	Interface Net Number
10/100 Ethernet (fixed ports on base switch)	0	1 - 16	0 - 15
10/100 Ethernet	1	1 - 8	16 - 23
10/100 Ethernet*	2	1 - 8	24 - 31
Reserved	3	1 - 4	32 - 35
ATM*	1	1-2	36 - 37

Table 1. Network Interfaces Automatically Configured (continued)

Device Types	Slot	Ports	Interface Net Number
ATM	2	1	38
ATM*	2	1	39
Ethernet LAN Emulation Client	3	5 - 29	40 - 63

Note: *Not available on 8371 Blades

SNMP Agent Capabilities

SNMP agent capabilities are documented in readme files at the FTP site. The external site directory is: <ftp://ftp.networking.ibm.com/pub/netmgmt/8371/>

Hot-Swapping Feature Cards

Prior to hot-swapping an 8371 feature card, you must disable the feature card ports. Use the **+ disable slot n** (where *n* is the slot number) command from t 5 to disable all ports on the slot. After replacing the feature card, use the **+ enable slot n** command from t 5 to test all the ports.

Performance Considerations

Performance Monitor and event logging activities might impact performance.

Do Not Use the 8371 Blades in 8265 Base Slots 2, 4, or 6

An 8371 Blade fills two slots in the 8265 (the first slot occupied is the base slot). Do not insert an 8371 Blade in base slots 2, 4, or 6. You can insert an 8371 Blade in all other slots. This slot restriction exists only through June 30, 1999. Prior to this date, we will publish a list of exact serial numbers affected by this restriction. After this date, there will be no restriction.

Default IP Host Address

For management purposes, the 8371 (box or blade) default configuration has an IP host address of 10.1.2.4 with a mask of 255.255.255.0.

OC12 ATM Uplink on 8371 Blades

The 8371 Blade OC12 ATM uplink is used for in-band communication with the 8265. In-band communication can be disabled from the console or configuration command prompts using the **disable slot 2** or **disable interface 38** commands and enabled using the **enable slot 2** or **enable interface 38** commands. While this interface is disabled, the 8265 will no longer communicate with the 8371.

TFTP Does Not Support Long File Names

Some DOS or Windows TFTP clients only support file names that comply with the *filename.ext* syntax, where *filename* can be up to 8 characters long and *ext* can be up to 3 characters long. When executing a **tftp get** to retrieve a configuration or load image, these clients will send the same file, /usr/os.Id, for each of the following file requests:

- /usr/os.Id
- /usr/os.Id.new

Ports Need to be Marked as Forwarding

A port does not begin to forward traffic as soon as an ATM or Ethernet port is cabled to it. Although a valid link indication, signalling a good connection, is given immediately, there can be a delay of up to two minutes before traffic forwarding begins. To verify that a port is in forwarding state, issue the following commands from the **console** prompt.

```
+ protocol asrt  
ASRT> list spanning-tree-protocol state active  
802.1d Spanning Tree State  
Designated root (prio/add): 32768/00-04-AC-C4-D3-D1  
Root cost: 0  
Root port: Self  
Current (root) maximum age: 20 seconds  
Current (root) hello time: 2 seconds  
Current (root) Forward delay: 15 seconds  
Topology change detected: FALSE  
Topology change: FALSE  
  
Port Interface State  
2 Eth/1 Forwarding
```

Some Applications Fail when Spanning Tree is Enabled

Some applications and hosts, such as RIPL, BootP, and POS Terminals, fail at start-up time (never at re-try) when directly connected to a switch because the application attempts to connect before the Spanning Tree Protocol recognizes that the switch port is in forwarding state. Rebooting will not solve this problem.

You should disable Spanning Tree Protocol at the configuration prompt to allow these applications to come up.

```
Config> protocol asrt  
ASRT Config> disable stp
```

Note: You should ensure that your bridged network is configured properly. Disabling Spanning Tree Protocol may cause problems if a bridged network is improperly configured.

BPDUs are not Forwarded when Spanning Tree is Disabled

If Spanning Tree is globally disabled, the 8371 will not forward BPDUs on any ports. While other multicast traffic is forwarded on all ports when the traffic is received, the 8371 drops all BPDUs that it receives.

EIA 232 Service Port Pin Assignments

Pin assignments for the EIA 232 service ports are shown on page 1-4 of the *8371 Networking Multilayer Ethernet Switch Installation and Planning Guide*.

Terminal May Not be Attached to the Ethernet Port

On page 1-2 of the *8371 Networking Multilayer Ethernet Switch Installation and Planning Guide*, remove "or an Ethernet port." from bullet two. The terminal may not be attached to the Ethernet port.

Web Browser Support

The Web interface supports Netscape Navigator 4.07 or higher.