

Field Feature Bill of Material (FFBM)

PN 80G2807

Replace TRP Processor (FC 5600) with TRP2 (FC 5622) in IBM 3746 Models 9X0

Written by: J. Michaut Checked by: J. Combes Approved by: A. Badino Reviewed by: B. Smith

3746 PN 80G2808 EC D55787 EC E63480 1 of 10 06SEP94 19AUG96

© Copyright IBM Corp. 1996

3746 PN 80G2808 FFBM 2 of 10

08

EC D55787 EC E63480 06SEP94 19AUG96

Before Installation (Steps 1-8)

Net Priced Feature -

All parts removed from this machine are IBM property and must be returned to IBM.

1.0 Machines Affected

3746 Models 900 or 950.

2.0 Related BMs and ECs

2.1 Prerequisites

(Must be installed prior to this installation)

 EC microcode D22510K minimum level or higher.

Checkpoint: Check that the basic level packaging unit EC level is D22512-062 or higher (Refer to SPIM, Chapter 3, 'Displaying the EC Level of Code Installed on the Hard Disk).

2.2 Concurrent

(Must be installed together) None.

2.3 Companion

(May be installed separately) None.

3.0 BMs to be Used

FFBM Title

80G2807 Replace TRP Processor (FC 5600)

with TRP2 (FC 5622)

4.0 Preparation

1. See the *HONE configuration/plugging sheet* and the following figures to determine the cassette positions.

Figure 1. Basic Enclosure

Q	Р	М	К	Н	F	D	В
Dummy	TRP / ESCP / CLP	CSCE					

Figure 2. 1st or 2nd Expansion Enclosure.

- 2. Familiarize yourself with the purpose and details of the installation instruction before negotiating machine time with the customer.
- 3. Check all items listed on the BM(s) to determine that all parts have been received.

3746	PN 80G2808	EC D55787	EC E63480		
FFBM	3 of 10	06SEP94	19AUG96		



5.0 Programming

5.1 Diagnostic Programs

None.

6.0 Purpose and Description

6.1 Purpose

Convert TRP (FC 5600) to TRP2 (FC 5622)

6.2 Description

Exchange of a cassette processor.

7.0 Installation Time

FFBM	Machine Hours	System Hours	Nbr. CE
80G2807	0.5	0.0	1

8.0 Tools/Materials Required

ESD kit (PN 6428316).

EC D55787	EC E63480		
06SEP94	19AUG96		



Installation (Steps 9-11)

9.0 Safety

Review the **Safety Notices** and the **Safety Inspection Procedures** located at the beginning of the *IBM 3745 Communication Controller All Models*, *IBM 3746 Expansion Unit Model 900*, *IBM 3746 Nways Multinetwork Controller Model 950 Safety Information*, GA33-0400

10.0 Details of the Installation

		Before the exchange, ask the customer:
		1. For the maintenance password.
		2. To logoff the Service Processor (SP), if not already done.
10 1	37/6-Qv() Power Mode
10.1	31 4 0-3X	If the 3746-9x0 is in Power Mode 1 (remote):
		Set the Power Control indicator of the 3746-9x0 control panel to 3 (local) then Press the Validate key.
10.2	Log the	SP ON
	9	1. On MOSS-E View window, click on Program.
		2. Click on LOG ON MOSS-E.
		3. Enter the maintenance password, press Enter .
	_	
10.3	Process	or Cassette Exchange
		1. Double click on the 3746-9x0 icon.
		2. On 3746-9x0 Menu window, click on Problem Management option
		3. Double click on Perform Maintenance option.
		4. On the Resource Options Selection for maintenance window, Click on Via the Active CDF-E option, then click on OK.
		5. On the Resource Selector window, select (click on) the TRP you want to replace.
		6. Once the resource is set to concurrent mode, the Maintenance Options window is displayed.
		7. Click on Replace the Resource option, then click on OK.
		8. On Confirmation window, click on OK .
3746 FFBM	PN 80G2808 5 of 10	EC D55787 EC E63480 06SEP94 19AUG96

5

9.	On the 3746-9x0 machine, open the front cover.					
10.	Exchange the TRP cassette by the TRP2.					
	Warning —					
	Use the ESD kit and procedures.					
	a. Locate the TRP cassette to be removed.					
	b. If there is a cable plug in the front of the cassette:					
	Remove the bracket.Unplug the cable.					
	c. Remove the TRP cassette (Follow the instruction label affix close to the enclosure).					
	d. Insert the TRP2 cassette into the enclosure and slide it firmly until it clicks (Locks in).					
	 e. If there was a cable in front of the TRP, plug it on the TRP2 and secure it with the bracket previously removed. 					
11.	Wait until the Alarm xxxx FRU Unplugged , and Alarm xxxx FRU Plugged messages are displayed on the Service Processor screen, then continue.					
12.	On the Confirmation window, click on OK .					
13.	Return to the Maintenance Options window.					
14.	Click on Perform Diagnostics on the resource option, then click on OK.					
15.	A ${f Diagnostics}$ window is displayed. Check that the ${f Specific}$ adapter and ${f No}$ wrap options are selected, then click on ${f Start}$.					
16.	A Specific Adapter window is displayed, select (click on) the TRP2 just installed, then click on \mathbf{OK}					
17.	The Diagnostics window is displayed again and the Elapsed time is incremented during the test.					
	At the end of the test, the number of errors is indicated by an arrow.					
	a. If there is an error: Call support for assistance					
	b. Otherwise, click on Cancel to return to the Maintenance Options window, then continue on next step.					
18.	Click on Initialize the Resource option to reinitialize the TRP2.					
19.	follow the instruction of the $\boldsymbol{Warning}$ window, then click on \boldsymbol{OK} when prompted.					
20.	The Maintenance Options window is displayed					
21.	Click on Remove the Resource from the Concurrent Mode $\operatorname{option},$ then click on OK					
22.	On the Warning window, click on OK					
23.	On the Resource Selector window, click on Cancel					
C D5578	7 EC E63480					

3746 FFBM 6 of 10

PN 80G2808

E



24. Return to the 3746-9x0 Menu window

10.4 EEPROM Upgrade

- 1. On the 3746-9x0 Menu window click on Change Management.
- 2. Double click on the Upgrade/Downgrade EEPROM Code Level. A window is displayed with a message box saying that the service processor is searching the 3746-9x0 configuration.

On **EEPROM Upgrade** window, the processors subject to upgrade or downgrade are highlighted according to the preselected status of the options "Upgrade" or "Downgrade" on the top of the window (see Figure 3).




Figure 3. Example of An EEPROM Upgrade Window

- 1 Gives the list of the 3746-9x0 processors in CDF-E with their status (available/disconnected/active).
- 2 Gives the current and new EEPROM level: PN/EC/Level of each processor.
- **3** Gives the status after the activation of the function.
- 3. According to the action that you want to do, click on "Upgrade" or "Downgrade" option on the top of the screen, then click on OK An "EEPROM Upgrade" window informs you that the EEPROM upgrade or downgrade is in progress with its time duration.
- At the end, a status is displayed for each processor.
- 4. Check the result of your EEPROM upgrade/downgrade operation with the following table and take the appropriate action:

3746	PN 80G2808	EC D55787	EC E63480		
FFBM	7 of 10	06SEP94	19AUG96		

EEPROM Status	Action
Complete	Upgrade done without error continue with the next step.
Start failed	Call your support
Failed	Call your support
Completion failed	Call your support

	<u> </u>	5. Return to the 3746-9x0 Menu, then click on Operation Management.				
	_	 Double click on the Perform General IML with Diagnostics. A Normal IML must be terminated by 00000000 displayed on the 3746-9x0 control panel. 				
10.5	3746-9x0 Power Mode					
	_	On the 3746-9x0 control panel, set the Power Control indicator to its original value.				
		Press the Validate key.				
10.6	Log the SP C					
	_	1. On the 3746-9x0 Menu window, click on Function, then, click on Exit.				

___ 2. On the MOSS-E View window, click on Program.

__ 3. Click on LOG OFF MOSS-E.

11.0 Test Procedures

No Test Required.

3746	PN 80G2808	EC D55787	EC E63480		
FFBM	8 of 10	06SEP94	19AUG96		



After Installation (steps 12-15)

12.0 Field Updating

None.

13.0 Publications Update

None.

14.0 Parts Disposition

All replaced/removed parts become the property of IBM. You MUST RETURN these parts following the instructions given on the Returned Material Equipment Report (RMER) provided with this FFBM.

15.0 Machine Records

- Record in the MACHINE HISTORY the new EC D55787 installed.
- Report installation and quality to existing procedures.

*** End of instructions ***

PN 80G2808 3746 FFBM 10 of 10

EC D55787 06SEP94 EC E63480 19AUG96