

Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts PAGE 1 (17)

Approved 1.0

Confidential

SQX 00443-en MWy 22.05.2002



# Service Manual Nokia 3510

# NHM-8 Service Level 2

Copyright <sup>©</sup> Nokia Corporation. This material, including documentation and any related computer programs, is protected by copyright controlled by Nokia Mobile Phones. All rights are reserved. Copying, including reproducing, storing, adapting or translating, any or all of this material requires the prior written consent of Nokia Mobile Phones. This material also contains confidential information, which may not be disclosed to others without the prior written consent of Nokia Mobile Phones.



Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts PAGE 2 (17)

Approved 1.0

Confidential

SQX 00443-en MWy 22.05.2002

#### Introduction

The purpose of this document is to give Nokia service level 2 workshops aids to carry out service for 3510. The use of this Service Manual is only for Nokia authorized service partners additionally to other service documentation like Service Bulletins.

While every endeavor has been made to ensure the accuracy of this document, some errors may exist. If you find any errors or if you have further suggestions, Nokia should be notified. Please keep in mind also that this documentation is continuously being updated and modified, so watch always out for the newest version.

## Warnings and Cautions

Please refer to the phone's user guide for instructions relating to operation, care and maintenance including important safety information. Note also the following:

#### Warnings:

1. CARE MUST BE TAKEN ON INSTALLATION IN VEHICLES FITTED WITH ELECTRONIC ENGINE MANAGEMENT

SYSTEMS AND ANTI-SKID BRAKING SYSTEMS. UNDER CERTAIN FAULT CONDITIONS, EMITTED RF ENERGY CAN AFFECT THEIR OPERATION. IF NECESSARY, CONSULT THE VEHICLE DEALER/MANUFACTURER TO DETERMINE THE IMMUNITY OF VEHICLE ELECTRONIC SYSTEMS TO RF ENERGY.

2. THE HANDPORTABLE TELEPHONE MUST NOT BE OPERATED IN AREAS LIKELY TO CONTAIN POTENTIALLY EXPLOSIVE ATMOSPHERES EG PETROL STATIONS (SERVICE STATIONS), BLASTING AREAS ETC.

3. OPERATION OF ANY RADIO TRANSMITTING EQUIPMENT, INCLUDING CELLULAR TELEPHONES, MAY INTERFERE WITH THE FUNCTIONALITY OF INADEQUATELY PROTECTED MEDICAL DEVICES. CONSULT A PHYSICIAN OR THE MANUFACTURER OF THE MEDICAL DEVICE IF YOU HAVE ANY QUESTIONS. OTHER ELECTRONIC EQUIPMENT MAY ALSO BE SUBJECT TO INTERFERENCE.

#### **Cautions:**

1. Servicing and alignment must be undertaken by qualified personnel only.

2. Ensure all work is carried out at an anti-static workstation and that an anti-static wrist strap is worn.

3. Ensure solder, wire, or foreign matter does not enter the telephone as damage may result.

4. Use only approved components as specified in the parts list.

5. Ensure all components, modules screws and insulators are correctly re-fitted after servicing and alignment. Ensure all cables and wires are repositioned correctly.

6. All PC's used with NMP Service Software for this produce must be bios and operating system "Year 2000 Compliant".



Approved 1.0

Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts

Confidential

SQX 00443-en MWy 22.05.2002

# Table of content

1.	EXPLODED VIEW
2.	BILL OF REPAIR
3.	SW-UPDATE
4.	GENERAL REPAIR INFORMATION
5.	DISASSEMBLY INSTRUCTIONS
6.	QUICK TROUBLE SHOOTER PART1 13
7.	QUICK TROUBLE SHOOTER PART2 14
8.	ESD PROTECTION REQUIREMENTS15
9.	SERVICE NOTES16
10.	GONOGO TESTER17
11.	BATTERYTESTER



PAGE 4 (17)

Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts

Confidential

SQX 00443-en MWy 22.05.2002

#### Change History

Originator	Status	Version No.	Date	Comments
MWy	Draft	0.1	04.04.2002	Initial draft
MWy	Approved	1.0	22.05.2002	approval

Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts PAGE 5 (17)

Approved 1.0

Confidential

SQX 00443-en MWy 22.05.2002

## **1. EXPLODED VIEW**



Description: See corresponding ITEM/CIRCUIT REF of the BOR (Bill Of Repair)

Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts PAGE 6 (17)

Confidential

SQX 00443-en MWy 22.05.2002

## 2. BILL OF REPAIR

ITEM/ CIRCUIT REF.	ΟΤΥ	PART NO	PART NAME
1003	6	6290107	SCREW 1.8X7.0 FE T6+
1004	1	4850247	DISPLAY ASSEMBLY
A901	1	9517120	BB SHIELD LID
l019	1	9517121	METAL FRAME ASSY
l018	1	5140067	SPEAKER+SPRING 103+-3DB 32R D13.2 (EARPIECE)
1006	1	5140243	SALT SPEAKER
1007	1	5409159	BOTTOM CONNECTOR (WITHOUT MICROPHONE)
1021	1	5140201	MICROPHONE -42dB +-3dB
1008	1	6800053	VIBRA MOT ASSY 1.3V 115MA 9500RPM
1009	1	9517122	SIM CARD SUPPORT
l010	1	5400253	BATTERY CONNECTOR
l014	1	9510854	RELEASE SPRING CLOSED
F100	1	5119019	SM FUSE F 1.5A 32V 0603 1.5A
S300	1	5209001	SM SW TACT SPST 12V 50MA SIDE KEY
V301	1	4860401	LED LNJ322W830NK 575NM 90DEG TBSF
V302	1	4860401	LED LNJ322W830NK 575NM 90DEG TBSF
V308	1	4860401	LED LNJ322W830NK 575NM 90DEG TBSF
V309	1	4860401	LED LNJ322W830NK 575NM 90DEG TBSF

#### **VARIANT PARTS**

ITEM/ CIRCUIT REF.	QTY	PART NO	PART NAME
1001	1	9490588	A-COVER Assembly DARK BLUE
1001	1	9490590	A-COVER Assembly BURGUNDY
1001	1	9490589	A-COVER Assembly WHITE
1002	1	9794055	KEYMAT LATIN
1002	1	9794104	KEYMAT ARABIC
1002	1	9794107	KEYMAT CYRILIC
1002	1	9794105	KEYMAT GREEK
1002	1	9794106	KEYMAT HEBREW
l011	1	9790514	POWER KEY LIME GREEN
l017	1	9490585	B-COVER ASSEMBLY LIGHT BLUE
1017	1	9490587	B-COVER ASSEMBLY BURGUNDY
l017	1	9490586	B-COVER ASSEMBLY GREEN

Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts PAGE 7 (17)

Confidential

SQX 00443-en MWy 22.05.2002

#### SWAP UNITS

ΟΤΥ	PART NO	PART NAME
	0074112	NHM-8NX N3510 SWAP ENGINE EUROPE
	0074113	NHM-8NX N3510 SWAP ENGINE RUSSIA
	0074114	NHM-8NX N3510 SWAP ENGINE TURKEY
	0074115	NHM-8NX N3510 SWAP ENGINE CS-SK
	0074116	NHM-8NX N3510 SWAP ENGINE FRANCE
	0074117	NHM-8NX N3510 SWAP ENGINE POLAND

#### SERVICE TOOLS

TYPE	QTY	PART NO	PART NAME
		0670403	BLC-2 BATTERY PACK
		0271582	DCV-10 DESKTOP STAND
		0272169	AC TRAVEL CHARGER ACP-8E (Euro)
		0272172	AC TRAVEL CHARGER ACP-8X (UK)
		0271467	HDC-5 HEADSET
		0775304	FLA-23 POS FLASH LOADING ADAPTER
		0730218	XCS-1 SERVICE CABLE
		0080541	FLS-4S POS FLASH DONGLE
		0775311	SERVICE SOFTWARE PHOENIX
		0770431	SRT-6 OPENING TOOL

Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts

Confidential

PAGE 8 (17)

SQX 00443-en MWy 22.05.2002

#### 3. SW-UPDATE

NOKIA

To use FLS-4S Flash Dongle you have to follow the user guide inside the sales package. Please check always the latest version of flash software, which is available on Partner Website. **Flash Concept – (Point of Sales)** 

#### Note that ACF-8 charger is inside FLS-4S sales pack and cannot be ordered separately.

<complex-block>

Description: See corresponding ITEM/CIRCUIT REF of the BOR (Bill Of Repair)

Approved 1.0

Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts PAGE 9 (17)

Approved 1.0

Confidential

SQX 00443-en MWy 22.05.2002

## 4. GENERAL REPAIR INFORMATION

In this section you will get some general hints how to carry out repairs:

- $\circ\,$  Before starting the repair you must take care of ESD precautions like being in your ESD-area and connecting your wristband.
- $\circ\,$  Use gloves to avoid corrosion and fingerprints.
- $\circ$  Protect windows and displays with a foil to avoid dust and scratches.
- When cleaning the pads you have to use a soft cloth and isopropanol. It is not allowed to use a glass fiber pencil because it scratches the surface and will lead later on to corrosion.
- Mechanical parts, which didn't repair the failure, can be reused, if they are not soldered.
- Use always original Nokia parts or accessories.
- Meet the torque requirements when assembling the unit (see also the document "torques for transceiver assembly" on Partner Websites).
- Always use your own equipment for testing where you are sure that it works. E.g. if the customer complains about charger function, please test the phone with your own charger to be sure if phone or charger causes the malfunction.

#### Following General Service Bulletins have to be followed:

- SB-055 Common notice for good ventilation
- SB-089: Don't try to repair prototypes (indicated on Typelabel).
- SB-107: Be sure that you have minimum hardware requirements in place.
- SB-115: Handling of liquid damages.
- SB-121: If one of your service tools cause malfunction, return the defective part.
- SB-122: Soldering with **manual hot air gun** is totally forbidden because of the very sensitive  $\mu$ BGA components and  $\mu$ Via technology.
- SB-124 Service Policy for packaging serviced products
- SB-131: Check these guidelines when refurbishing products.
- SB-132: You need a **Golden Phone** for inspecting your measuring equipment.

Please check Partner Websites (PWS) for latest news and files on a regular basis.

#### Legend for Quick Trouble Shooter:

This legend is valid for all parts of the Quick Trouble Shooter

Follow the steps until the problem is solved. If this doesn't help, you are not authorized to go forward. Only underlined components (e.g. <u>1007</u>) can be changed.

Follow the arrows step by step			
or contacts: Check optical and mechanical condition as well as corrosion.			
if necessary.			
ure component for electrical functionality and change, if needed.			
ore action possible, send product to the			
priate service partner with higher service level.			
script numbers are for additional comments or instructions			

Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts


#### PAGE 10 (17)

Approved 1.0

Confidential

SQX 00443-en MWy 22.05.2002


#### 5. DISASSEMBLY INSTRUCTIONS




Release the A-Cover from the bottom side of the unit.



Also, protect the inner part of the window with a foil. The Keymat is loose inside the A-Cover.




When releasing the side clips of the D-Cover you can use the SRT-6.



Take away the Display Assembly (UI module) and avoid touching the pads with your fingers.




Take away the A-Cover.



Open the six screws in the predefined order with a Torx 6 driver. When re-assembling, the reverse order has to be taken with a torque of 28 Ncm.



This is the second clip.



There are two snaps on each side of the Metal Frame.

Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts PAGE 11 (17)


Approved 1.0

Confidential

SQX 00443-en MWy 22.05.2002



Remove the Metal Frame.




The next step is to take away the Radio Module BF4A.



Remove the Power Key.



The Microphone can be changed separately. To remove it from the connector housing, you have to push it with e.g. Torx Driver.




If you hold the UI module upside down, the Speaker drops out of its hollow.



Lift up the Battery Connector with your fingers.



To loosen the System Connector you can use SRT-6 opening tool. Take care not to scratch the D-Cover or the connector housing.



When re-assembling the Microphone remember the right direction. The hole of the Microphone has to point to the hole of the connector housing.

Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts




Approved 1.0

Confidential

SQX 00443-en MWy 22.05.2002



The SALT Speaker is taped to the D-Cover and can be removed with a straight bladed screwdriver.



Remove the SIM Card Support using this way.




After releasing the two hooks, you can remove the Release Spring easily.

When assembling the phone, screws must be tightened with a torque of 28 Ncm! The GoNoGo test verifies that the electrical specifications will be fulfilled.



If you need to change the Vibra Motor, strong tweezers or pliers can be taken.




The Release Spring is locked on two sides. Use a screwdriver to unlock the two snaps.




#### 6. QUICK TROUBLE SHOOTER PART1

Quick Trouble Shooter 3510 BF4A



#### 7. QUICK TROUBLE SHOOTER PART2



Service Manual 3510 Level 2

Copyright 2002 © Nokia Corporation

Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts PAGE 15 (17)

Approved 1.0

Confidential

SQX 00443-en MWy 22.05.2002

#### 8. ESD PROTECTION REQUIREMENTS



Electrostatic discharge can easily damage the sensitive components of electronic products. Therefore every Service Partner has to take care of at least some precautions like ESD restricted area, floor, table, covering, chair(s), shoes or arm wrist.

#### Please refer to the Partner Website document **ESD protection requirements for NMP Service Level 1/2 Service Suppliers**



#### PAGE 16 (17)

Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts

Confidential

SQX 00443-en MWy 22.05.2002

#### 9. SERVICE NOTES

NOKIA

We recommend using Service Notes when shipping phones to other Service Partners. It prevents the product from scratches, it is ESD-neutral and has the possibility to give valuable feedback of the fault symptom through a structured form. Please refer to the document **Service Notes for faulty NMP transceiver** on Partner Website to get further information.

Handled by Serial n.o.: 444333/- Yes X Warranty Case R X Repair RO Refurbishment only A Analysis 24h 24 h Service	No Inst Instar RR Repair and Ref SW Software upda C Claim	
A) EXISTENCE OF FAU	LT	
1. X Continuous fault	2. 🗌 Intermittent fault	3.
4. By shock or vibratio	on 5. 🗆 No clear fault	6. Only as portable
7. 🗆 Only in a car	8. 🗌 Only in desktop	
B) SYMPTOM OF THE	FAULT ON CMT-PART - S	
1. 🗆 Totally dead	2. 🗆 Selftest failure	3. SIM Fail
4. 🗙 No service	5. 🗆 No calls in	6. 🗆 No calls out
7. 🗆 Keypad failure	8. 🗆 Display failure	9. Audio failure
10. 🗆 Doesn't charge	11. 🗆 Overcharging	12. Hand-free failure
13. 🗆 Burns fuses	14. 🗆 Accessory fail, which	ch
15. 🗆 Switches off	16. 🗌 Other	A CONTRACTOR OF THE OWNER
C) OBSERVED OR MEAS	SURED FAULT	
1. 🗙 TX Power	NO	CLA NOBLE PHONES LTD.
2. 🗆 TX Phase error	MADE	N GERMANY
3. 🗆 Bit Error Rate	CE CE	0168 X
4. 🗆 Burst Template		
5. 🗆 Ramping spectra		19333/20/975406/2
6. 🗆 RX Quality	1	DE DIQUEIR IN IN TANK
7. 🗆 RSSI	0	ode: 0503831
8. 🗆 Other		Wher: R&D Bochum
D) SYMPTOM OF THE	the second se	TTA
ON PDA-PART -	TAULI	
Symptom Code		1000
1.  PDA doesn't start		
2. Internal error	1 Standard Barrier	AAA Include
3. C Keypad failure	and the second s	
4. Display failure	A DECEMBER OF STREET	

PAGE 17 (17)

Approved 1.0

Nokia Mobile Phones Customer Care E&A Technical Services, Repair Concepts

Confidential

SQX 00443-en MWy 22.05.2002

#### **10. GONOGO TESTER**

The Acterna/Wavetek GoNoGo Tester has to be used to carry out the final test after your service action to guarantee the functionality of the phone.

Please refer to the actual information in the Nokia Care Point Extranet within the Partner Website.



#### **11. BATTERYTESTER**

The Astratec battery tester lets you test the capacity of Nokia batteries. Please refer to the actual information in the Nokia Care Point Extranet within the Partner Website.

