

# Service & repair hints of NOKIA 5110 / 6110

Service & Analysis Center Europe

DT40 - C715  
C700 - C702  
C700 - C702  
L700 - L702  
N700 - N710  
S700 - S710  
T700 - T702

## Change history

Originator	Approved	Status	Version	Date	Comment
Ralf Heptner		Draft	0.1	11.08.99	
Ralf Heptner		Draft	0.2	25.08.99	Flowcharts updated
Ralf Heptner		Draft	0.3	27.09.99	SIM lock lists updated, some minor changes
Ralf Heptner		Draft	0.4	01.10.99	Forword changed
Jose Marquez		Draft	0.5	08.10.99	Forword changed
Ralf Heptner		Approved	1.0	19.10.99	Forword changed

## Introduction

### IMPORTANT:

**This document is intended for use by authorized NOKIA service centers only.**

The purpose of this document is to provide some further service information for NOKIA 6110, 5110 phones.

It contains a lot of collected tips and hints, to find failures and repair solutions easily.

I will also give support to the inexperienced technicians.

Saving process time and improving the repair quality is the aim of using this document.

We have built it up based on fault symptoms (listed in "Contents") followed by detailed description for further analysis.

It is to be used additionally to the service manual and other service information like Service Bulletins, for that reason it doesn't contain any circuit descriptions or schematics.

### **All measurements are made with using of following equipment:**

Nokia repair SW	: Wintesla Version 6.10
DLL version	: NSEKM-13 version 2.41.03
Nokia Module Jig	: JBS-19
Digital multimeter	: Fluke 73
Oscilloscope	: Hitachi V-1565; Fluke PM 3380A
Spectrum Analyzer	: Advantest R3361C with an analogue probe
RF-Generator /	: Rohde & Schwarz CMD 53
GSM Tester	

While every endeavour has been made to ensure the accuracy of this document, some errors may exist. If any errors are found by the reader, NOKIA should be notified in writing, using following procedure:

#### **Please state:**

Title of the Document + Issue Number/Date of publication

Page(s) and/or Figure(s) in error

#### **Please send to:**


Nokia GmbH  
Service & Analysis Center Europe  
Meesmannstr.103  
D-44807 Bochum / Germany  
Email: [ams.sace-training@nokia.com](mailto:ams.sace-training@nokia.com)

## Contents

<b><u>CHANGE HISTORY .....</u></b>	<b><u>2</u></b>
<b><u>INTRODUCTION.....</u></b>	<b><u>3</u></b>
PHONE DOESN'T SWITCH ON .....	5
PHONE SWITCHES ITSELF OFF .....	8
SWITCH ITSELF OFF- CONTACT SERVICE APPEARS ON THE DISPLAY .....	9
CONTACT SERVICE – COBBA PARALLEL BUS FAILED.....	10
CONTACT SERVICE – COBBA SERIAL BUS FAILED.....	11
CONTACT SERVICE – EEPROM TUNE CHECKSUM FAIL .....	12
CONTACT SERVICE – PPM VALIDITY .....	13
CLOCK TIME OR USER SETTING PROBLEMS .....	14
THE PHONE HANGS UP, AFTER ENTERING THE PIN-CODE.....	16
NOT CHARGING .....	17
LOW STAND BY TIME .....	21
BUZZER FAILURES .....	22
INTERNAL AUDIO FAILURES.....	23
EXTERNAL AUDIO FAILURES.....	24
ACCESSORY DETECTION FAILURE (HEADSET / CAR KIT ACTIVE).....	25
DISPLAY FAILURE.....	27
KEYPAD FAILURE.....	29
INSERT SIM CARD .....	30
SIM CARD NOT ACCEPTED, SIM LOCK FAILURE.....	31
LOW RECEIVER SIGNAL STRENGTH INDICATOR.....	35
NO SERVICE .....	35
NO RX (NO RX CALIBRATION...RSSI READING FIXED VALUE).....	36
NO RX (NO RX CALIBRATION...RSSI READING HIGH DIFFERENCE) .....	36
NO RX (NO RX CALIBRATION...RSSI READING HIGHEST VALUE).....	36
NO RX (NO RX CALIBRATION...RSSI READING HIGHEST VALUE).....	37
CALL BREAKS / NO SERVICE.....	38
NO CALL / SERVICE O.K.....	38
NO OR TO LOW TX – POWER .....	38

Phone doesn't switch on

Figure 1: Flow chart of phone doesn't switch on



**N100 faulty/ poor solderings**

- Check if voltage on Pin 29 drops of 700 mV during pressing the Power on button
- Check if there is a 32.768 KHz square wave on Pin 48
- Check if PURX Pin 54 goes up to 2.8 V DC
- Check if VXO Pin 28 goes up to 2.8 V DC

**B100 faulty 32,768KHz**

- Check 32.768 KHz ; 1 Vpp clock signal on B100

**G600 faulty 13 MHz**

- Check VXO 2,8V DC on J522
- Check 13 MHz; 1 Vpp on output

**S001 User Interface**

- Check if voltage on Pin 29 drops of 700 mV during pressing the Power on button

**X300 UI Connector bent**

- Check if voltage on Pin 29 drops of 700 mV during pressing the Power on button

**R118 missing/ poor soldering**

- Check if voltage on Pin 29 drops of 700 mV during pressing the Power on button

**D200 MAD faulty/ poor soldering**

- Check 32.768 kHz square wave on Pin 124 (comes from CCONT Pin 48)
- Check 13 MHz On Pin 93 (comes from G600)
- Check VBB 2.8 V DC
- Check PURX 2.8 V DC on Pin 122 (comes from CCONT Pin 54)
- Check SLEEPX 2.8 V DC On Pin 113
- Resolder MAD complete

**D210 FLASH faulty/ poor soldering/ empty**

- Check VBB 2.8 V DC on Pin 47
- If power consumption is around 20mA try to flash the phone
- Resolder FLASH completely

L103 faulty/ poor soldering

- Check VB on J232

X101 / X102 contacts bent/ dirty

- Check if VBATT and Gnd are connected


N550 short circuit

- If there is a short circuit on VBATT, lift L550 and check again
- If the PCB is burnt, swap the phone


C610; C611; C612 burnt/ short circuit

- Lift the capacitor and check again
- If the PCB is burnt, scrap the phone

Figure 2: Block diagram of switching on routine



Phone switches itself off






### C131 10 $\mu$ F/10V

- Check that the handset work probably with 3V SIM-cards
- Check the 5V supply voltage at C131 (about 4,8V-5,2V, Maximum noise 350mVpp overlap)

Figure 3: diagram of normal noise on C131




Maximum noise on C131 with 5V SIM-card

### Switch itself off- contact service appears on the display


#### D200 MAD faulty / poor soldering

- Check the amplitude of the 32,768KHz square wave on pin 124 (comes from CCONT pin 48)
- Check the amplitude of the 13MHz clock frequency pin 93 (from G600)
- Check VBB 2,8V DC
- Resolder MAD
- Internal error of MAD

**Contact service – COBBA parallel bus failed**



## Contact service – COBBA serial bus failed




### N250 COBBA faulty / poor soldering

- Check VBB 2,8V DC on pin 27, 53 from COBBA
- Check VCOBBA 2,8V DC on pin 7,12,21,25, from COBBA
- Check COBBACKL 13MHz 3,2Vpp pin 45 from COBBA
- Resolder COBBA
- Internal error of COBBA

Note! Rewrite SIMLOCK and IMEI entries with use of the Nokia security SW (SSSW) and make a SW-update or send this phones to the SACE, if this procedure is not permitted to you

**Contact service – Eeprom tune checksum fail**




**D240 Eeprom faulty**

- Check via wintesla if IMEI or product data are corrupted
- Don't use the "Full factory set" via wintesla, otherwise the IMEI will Change to question marks
- Change the Eeprom if it's permitted for you and write all ID data (IMEI, product code...) back
- If aren't allowed to change the Eeprom and the IMEI is missing, write a note with a little Comment, and send it together with the phone to the SACE

Note! Rewrite SIMLOCK and IMEI entries with use of the Nokia security SW (SSSW) and make a SW-update or send this phones to the SACE, if this procedure is not permitted to you


Contact service – PPM validity



SW / D210 Flash faulty / poor soldering


- Check if the fault disappear after update the handset
- Resolder D210 Flash
- Internal error of Flash

**Clock time or user setting problems**




**Clock time / ringing tone is to fast or to slowly**

- Check that the sleepclk is 32.768KHz square wave on pin 48 CCONT
- Check the crystal B100, R154, C101, C102, N100



**G100, Loose of clock time, if the battery is empty or removed for few minutes**


- G100 Back up battery faulty / disconnected
- Check the voltage 2,8V-3,3V over the back up battery connected to the PCB in the service modus
- Check the spring contacts
- Clean the back up battery contacts on the board




N100, Clock will freeze after switching on

- CCONTINT short circuit / break
- Check the CCONTINT impulse on pin 52 CCONT or pin 123 MAD (see the diagram below)
- Check pin 52 CCONT pin 123 MAD short circuit or break

Figure 4: CCONT INT impulse on CCONT pin 52



The phone hangs up, after entering the PIN-code






**D200 MAD faulty / poor soldering**

- Check the amplitude of the 32,768KHz square wave on pin 124 (comes from CCONT pin 48)
- Check the amplitude of the 13MHz clock frequency pin 93 (from G600)
- Check VBB 2,8V DC
- Resolder MAD
- Internal error of MAD



Not charging





#### F101 faulty

- Check resistance of F101 (0Ω)

#### V100 faulty

- Check resistance of V100 (50KΩ in circuit)

#### L104 faulty Vcharge

- Check resistance of L104 (0Ω)

#### L105 faulty Charge ground

- Check resistance of L105 (0Ω)

#### C103 faulty short circuit on Vcharge

- Check resistance of C103 (50KΩ in circuit)

#### N101 faulty/ poor soldering

- Check PWMOUT on Pin 7 (1 Hz standard / 32Hz fast)
- Check if CHARLIM on Pin 9 is 2.8V DC

#### N100 faulty/ poor soldering

- Change if any A/D value is out of limit but the DC voltages are ok.
- If DC voltages are wrong, check corresponding voltage dividers
- Check PWMOUT on Pin 56 (1 Hz standard / 32 Hz fast)

#### X100 faulty/ poor soldering

- Check connection of Vcharge; charge ground; charge control

#### X101 BSI; X102 BTEMP

- Check connection if battery size or battery temp A/D are out of limit


#### V102 faulty

- Check if there is a short circuit in charge control line


#### Energy management Calibration

- If charging stops too early
- If message "not charging" appears on LCD"
- If any part in charging circuit has changed
- If any A/D value is out of limit, check the corresponding DC Voltages on CCONT

Figure 5: Block diagram of charging concept



Low Stand by time



N550 / N100 / N101 / D200 / Battery calibration – faulty

- Check the current consumption in different operation modes


Figure 6: current consumption values

Function mode	Minimum current in mA	Maximum current in mA
Off state	0	1
Sleep mode	1	5
Call mode, Pover level 5	200	550

- Disconnect the PA N550, lift L560 and check the current again
- Check, if the current consumption comes from the first or second side of CCONT, lift L103
- Check C105, C142 or N101
- Check soldering of the MAD
- Change MAD
- calibrate Battery and charging values, if charging stops to early or battery get hot during charging (see also chapter "Not charging")

**Note! The Stand by time depends very much on the network side and handling of the phone**

## Buzzer failures



### B001 / UI-module

- Check buzzer signal about 1Vpp pulses (use WINTESLA / testing / audio Level 1, 1000Hz)
- Change component if signal is ok

### X300, board to board connector

- Check soldering
- Check contact springs, change component if bent


### D200, MAD

- Check buzzer signal on Pin 97 (200mV pulses) use WINTESLA / testing / audio Level 1, 1000Hz

### B100, 32.768KHz crystal

- Change component if ringing tone speed is to low or high if a call comes in. If you pick a ringing tone from the menu, the speed is normal.
- In this case, also the clock is running wrong if the phone is switched off.

## Internal Audio Failures



### Speaker

- No / quiet / distorted receiving audio signal
- Check the mechanic of speaker, contacts, membrane, soiling
- Check resistance of speaker (about 30Ω)

### Microphone

- No / quiet / distorted transmitting audio signal
- Check contacts of microphone
- Check resistance of microphone (about 800Ω)

### X300

- Check soldering
- Check contacts (change connector if bent)

### X100

- Check microphone spring contacts
- Check soldering


### V103

- Check resistance from MIC N or MIC P to ground (about 1KΩ and 2KΩ)  
change component if resistance is 0Ω

### C266

- Check MIC BIAS voltage 2.8V DC if audio is active (use WINTESLA / testing / audio)

External Audio Failures



L106

- Check resistance of coil (0Ω), if there is no XMIC

L107


- Check resistance of coil (0Ω), if there is no XEAR

X100

- Check soldering
- Check contacts (soiling)



Accessory detection failure (headset / car kit active)



## V102

- Check resistance of XMIC to ground if headset is detected
- Check resistance of XEAR to ground if car kit is detected
- Change component if resistance is low

## R259 / R260

- Check soldering and resistance of components if car kit is detected (45KΩ / 22KΩ inside PCB)


## R256 / R257 / R261

- Check soldering and resistance of components if headset is detected (2,2KΩ, 45KΩ, 22KΩ inside PCB)


## Liquid damage

- Check if there is a liquid damage around X100, V101, V102 and L105)

Figure 7: Block diagram of audio switching concept




Display Failure



## Elastomer

- Change Elastomer if contrast disappears, missing segments

Figure 8: different types of elastomer




## LCD

- Change LCD if elastomer change doesn't help

Figure 9: different types of LCD's

### Philips LCD



NO capacitors inside

### Seiko LCD



capacitors inside

## X300

- Check soldering
- Check contacts (change connector if bent)


## D200

- If there are wrong signs on LCD and the filled LCD during start up is missing, check LCD reset on JBS-19 Test Pin 25 or D200/ 36 during start up

## UI-module

- Check LCD contact Pads, clean if soiled
- Change if elastomer and LCD change doesn't help
- UE4S\_05 (NSE-1), UE4\_13 (NSE-3) makes a better contact between elastomer and PCB

**Keypad failure**



**X300**

- Check soldering
- Check contacts (change connector if bent)


**D200**

- Check ROW and COL lines

**UI-module**

- Check keys on UI, change UI-module if any keydome is damaged

## Insert SIM card



### X302, SIM card reader

- Check soldering
- Check contacts (change connector if bent)

### X101, battery connector

- Check BSI connection to D200 / 95 CardDetX

### D200, MAD

- Check SIM card -DATA (Pin120), -Clock 3,25MHz (Pin 126), -Reset (Pin 127), -IOC (Pin 128) and -Power (Pin 129)


### N100, CCONT

- SIM card -DATA (Pin 43), -Clock 3,25MHz (Pin 38), -Reset (Pin 42) and VSIM 3V/5V DC (Pin 36) depends on SIM card

### V104

- Change component if SIM -DATA, -Clock, -Reset or VSIM is short circuited to ground

SIM card not accepted, SIM LOCK failure



- If message "SIM Card not accepted" appears on LCD after entering PIN code, a SIM LOCK is activated in this phone.
- Initialize phone into normal mode and activate Quick/ RF-info (WINTESLA) compare the SIM LOCK entries with the below listed references
- If MCC+MNC or status doesn't match to the listed entries, correct the SIMLOCK entries with use of the Nokia security SW (SSSW) or send this phones to the SACE if it is not permitted to you

## N100, CCONT

- Refer to insert SIM Card procedure

## N250, COBBA

- Change COBBA if all SIM LOCK entries and SIM card signals from CCONT are ok

Note! Rewrite SIMLOCK and IMEI entries with use of the Nokia security SW (SSSW) and make a SW-update or send this phones to the SACE, if this procedure is not permitted to you

Figure 10: No SIMLOCK set to the phone

```

Phone Mode:
  NORMAL
Phone Version:
  V 5.31 19-02-99 MSE-3 (c) NMP.
Serial Number:
  490518/10/020919/4
SIM Lock Settings:
  SimLock  Status  Type      Counter  Data
  L1       Open   Factory   0        Mcc+Mnc 00101
  L2       Open   Factory   0        Gid1     0000
  L3       Open   Factory   0        Gid2     0000
  L4       Open   Factory   0        Msin     0000000001
  
```

Figure 11: SIMLOCK is set to operator OLA France

```

Phone Mode:
  NORMAL
Phone Version:
  V 5.11 19-02-99 MSE-1 (c) NMP.
Serial Number:
  490520/20/083049/9
SIM Lock Settings:
  SimLock  Status  Type      Counter  Data
  L1       Closed  User      0        Mcc+Mnc 20801
  L2       Closed  User      0        Gid1     0000
  L3       Open   Factory   0        Gid2     0000
  L4       Open   Factory   0        Msin     0000000000
  
```



Table 1: List of current SIM LOCK phones NSE-1

Code NSE-1	Country	Operator	IMSI MCC+MNC
501639	Spain	Movistar	214070
501640	Spain	Airtel	214010
501641	Poland	Polkomtel	260010
501901	Austria	Max.Mobil	232030
502054	Hungary	Westel	216300
502055	Hungary	Pannon	216010
502056	Poland	Era	260020
502057	South Africa	Vodacom	655010
502058	Greece	TeleStet	2021099????????
502059	Greece	Panafon	2020590????????
502060	Spain	Airtel	214018:????????
502061	Spain	Movistar (Activa)	214070?61??????
502063	France	OLA	208010
502092	Ireland	Eircell	272010
502094	Portugal	TMN	26803????????
502299	France	OLA	208010
502394	South Africa	MTN	655100000000000
502413	Portugal	Optimus	26803????????
502510	Romania	Dialog	22610????????
502561	Portugal	Optimus	26803????????
502562	Poland	Polkomtel	260010
502638	Turkey	Turkcell	28601????????
502639	Turkey	Telsim	28602????????
502834	Ireland	Digifone	27202????????
502975	Spain	Movistar	2140;????????
502976	Spain	Movistar	2140;????????
502986	Sweden	Comviq	24007????????
503020	Austria	Mobilkom	23201????????
503021	Austria	Mobilkom	23201????????
503137	Portugal	Telecel	26801????????
503141	Portugal	TMN	26806????????
503393	France	OLA	208010
503503	UK	Vodafone	26806????????
503574	Rumania	Connex	22601????????

**Table 2: List of current SIM LOCK phones NSE-3**

Code	Country	Operator	IMSI MCC+MNC
501561		Plus	
501562	Spain	Airtel	214010
501563	Spain	Movistar	214070
501791	Hungary	Westel blue	216300
501792	Hungary	Westel green	216300
501875	Poland	ERA green	260020
501876	Poland	ERA blue	260020
501878	Spain	Movistar Activa	21407?61???????
501880	Spain	Airtel blue	214010
502053	Austria	Max Mobil blue	232030
502113	Spain	Airtel Continua	214018:?????????
502147	Hungary	Pannon blue	216010
502148	Hungary	Pannon green	216010
502149	France	SFR blue	20810?????????
502162	Austria	Max Mobil blue WLL	232030
502163	Austria	Max Mobile Green WLL	232030
502164	Spain	Airtel blue WLL	214010
502165	Spain	Movistar blue WLL	214070
502166	Spain	Airtel green WLL	214010
502167	Spain	Movistar green WLL	214070
502430	France	SFR blue	20810?????????
?	Poland	Polkomtel	2600100
502599	Dubai	(Dubai)	655100
502636	Turkey	Turkcell	28601???????????
502637	Turkey	Telsim	28602???????????
502972	Spain	Movistar	2140;???????????
502973	Spain	Movistar green WLL	2140;???????????
502974	Spain	Movistar blue WLL	2140;???????????
503143	Greece	Panafon	2020590

## Low receiver signal strength indicator

Antenna faulty / wrong - Tuning

- Check the code of the antenna label (see below)
- Check the receiver signal indicator with a new antenna
- Retune the handset

NMP CODE	DESCRIPTION	TYPE CODE (Stamped in helix antenna)	NOTE
0660178	ANTENNA FXD 890-960/1710-1880 MHz	DGPxxxxx	NSM-1*
0660160	ANTENNA FIXED HELIX 890-960 MHz	SGSxxxxx	NSE-1/3*
0660145	HELIX 1710-1880 MHz PCN	SPNxxxxx	NSK-1/3*

## No service

13MHz VCTCXO G600 out of range

- Check the 13MHz reference frequency pin 21 N620 (PLUSSA) or pin 2 from G600, set first the module in service mode, a frequency error of +-50Hz can create deviation of the IF frequencies


X560 Antenna connector / switch mechanical faulty

- Check the handset with the external antenna
- Check the resistance "00hm" from the internal antenna pad to the "in" pin of X560

## B100 32,768KHz crystal

- Check the amplitude of the 32,768KHz square wave on pin 48 of CCONT

Figure 12: diagram of N100 pin 48 32,768KHz square wave



Sleepclk signal measurable on pin 48 from CCONT in Local mode

## No RX (no Rx calibration...RSSI reading fixed value)

### D200, MAD / N250, COBBA faulty

- Check if the 13MHz IF frequency on pin 22,23 COBBA change the amplitude, if the generator frequency level has changed
- Check if the RXC impulse on pin 53 N620 (PLUSSA) change the amplitude, if the generator frequency level has changed
- Change MAD
- Change COBBA

Note! Rewrite SIMLOCK and IMEI entries with use of the Nokia security SW (SSSW) and make a SW-update or send this phones to the SACE, if this procedure is not permitted to you

## No RX (no Rx calibration...RSSI reading high difference)

### Z550 Duplexer faulty / poor soldering

- Check the rx signal on the ANT pin and on the output
- Check that the attenuation between duplexer "in" and "out" is about 2dbm
- Resolder the duplexer or change it

## No RX (no Rx calibration...RSSI reading highest value)

### Z621 / Z620 faulty / poor soldering

- Check the 71MHz IF frequency on Z621
- Check the components C505, C507, L500, L503 if the signal amplitude is different between the two lines
- check the soldering of Z621 or change it
- check the 13MHz IF frequency on Z620, about 3dbm attenuation between signal-in and signal-out
- check the soldering of Z620 or change it

## No RX (no Rx calibration...RSSI reading highest value)

### N620 PLUSA faulty / poor soldering

- check the UHF- and VHF oscillator frequency
- check the control-lines for the PLL, pin 54, 55, 56 of N620 (see the diagrams below)
- check the UHF-VC on pin 27 N620 1,9V-3.2V depending of the channel
- check the VHF-VC on pin 18 N620 2,6V
- check the 5V VCP supply voltage drop over R640 (normal 0,2V)
- change the N620 PLUSA

Figure 13: diagram of SCLK




Figure 14: diagram of SDATA





Figure 15: diagram of SENA1



## Call breaks / No service

### G550 UHF Oscillator out of range or high spurious emission

- check the UHF frequency on G530 for high spurious or deviation
- check the UHF-VC on pin 27 N620 1,9V-3.2V depending on the channel
- check the 5V VCP supply voltage on pin 17, 28 of N620 PLUSA or pin 32 of CCONT
- check R533 47Kohm, C535 1,5nF

## No Call / service O.K.

### N100 CCONT faulty

- check if the "Insert SIM-card" message appear sometime on the display
- check if it's possible to read the saved phone numbers of the SIM-card
- Resolder CCONT
- Change CCONT

## No or to low TX – Power

### N550 / X 560 faulty

- Check the power supply Vbat N550 pin 2, 4, 6, 12, 13, 14
- Check the input power on pin 8 N550 (nominal 0dbm)
- Check the output power on pin 12, 13, 14 of N550
- Check the TX-Power control on pin 9 of N550 (1Vpp-1, 5Vpp / 0,4..V - 0,9..V DC depend of the power-level)  
(see the diagram below)
- Change the PA if no or to low gain comes out
- Check the TX-Power on the antenna IN/OUT pads from X 560
- Check the attenuation of the connector

Figure 16: Diagram of TX-control

