

CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 1 (29) Repairhints Version 1.0 Approved

# Repairhints


6210/6250 NPE-3/NHM-3 HDa13/S 893





CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 2 (29) Repairhints Version 1.0 Approved

# **GENERAL**



# -How to use this document

Put the QUICK REPAIR layouts behind this manual.

Now you are able to follow these specifications with graphical layouts and it is easier for you to find the components and measuring points.

# -Component characteristics:

Some components contain important data.

Several described steps are only practicable if you are able to reflash/ realign the phone and/or rewrite IMEI/SIMlock in certain cases. Please pay attention to separate notes.

# -Underfills, broken balls, µBGA

It is not possible to change underfilled components. The trial will damage PCB surely. All replaceable µBGA-components must be renewed after removing. Reflow is not allowed.

Check soldering points, remove oxidated solderings (broken balls) carefully by enclosing few new solder before placing new components.

μBGA must be soldered only with NMP approved μBGA-rework machines (e.g. Zevac/OK International). Use only recommended Fluxtype and an appropriate amount of it.

# -PCB handling

Only use appropriate cleaning materials, don't use scratching or rubbing tools. Clean PCB carefully after every rework and take great pains over the keyboard area. Don't make any loose wiring connections anywhere.

If it is necessary to change any item located under the metal shields, remove the shield first, don't cut partially or bend it. **Take care: Corners of the lids are sharp, insuries are possible!** Shields and screws must be renewed after removal.

# -Realign after repair

Characteristics of replacement parts are different.

To prevent additional faults after repair (eg. low standby time, loosing network etc...) it is necessary to retune phone values after repair.



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07

Repairhints
Version 1.0 Approved

3 (29)

# INTRODUCTION

# IMPORTANT:

This document is intended for use by authorized NOKIA service centers only.

The purpose of this document is to provide some further service information for NOKIA 6210/6250 phones.

It contains a lot of collected tips and hints to find failures and repair solutions easily.

It also will give support to the inexperienced technicians.

Saving process time and improving the repair quality is the aim of using this document.

We have build it up based on fault symptoms (listed in "Contents") followed by detailed description for further analysis.

It is to be used additionally to the service manual and other service information like Service Bulletins, for that reason it doesn't contain any circuit descriptions or schematics.

# All measurements are made using following equipment:

Nokia repair SW : WinTesla Version 6.43

DLL version : 311.03.00

Nokia Module Jig : JBT-13 / MJS-23

Digital multimeter : Fluke 73

Oscilloscope : Hitachi V-1565; Fluke PM 3380A/B

Spectrum Analyzer : Advantest R3162 with an analogue probe

RF-Generator / : Rohde & Schwarz CMU 200

**GSM** Tester

While every endeavour has been made to ensure the accuracy of this document, some errors may exist. If any errors are found by the reader, NOKIA should be notified in writing, using following procedure:

#### Please state:

Title of the Document + Issue Number/Date of publication. Page(s) and/or Figure(s) in error.

Please send to: Nokia GmbH

Service & Analysis Center Europe

Meesmannstr.103

D-44807 Bochum / Germany

Email: training.sace@nokia.com



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 4 (29) Repairhints Version 1.0 Approved

# **Contents**

GENERAL	2
INTRODUCTION	3
GENERAL TUNING INFORMATION	5
USER INTERFACE FAILURES	11
SIMCARD FAILURES	13
CHARGING PROBLEMS	14
CONTACT SERVICE	15
PHONE DOES NOT SWITCH ON	17
LOW STANDBY/OPERATION MODE TIME	18
FLASH UPDATE NOT POSSIBLE	18
NO SERVICE PROBLEMS	19
SIGNAL CHARTS	25
FREQUENCY LIST	26
SPECIAL INFORMATION FOR NHM-3	27
CHANGE HISTORY	29



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 5 (29) Repairhints Version 1.0 Approved


# GENERAL TUNING INFORMATION - DIFFERENCES TO EARLIER PHONES

# **Energy management calibration information**

If it is necessary to realign, it is imperative to follow the instructions displayed in the pop-up windows! As soon as you take an other order as given from WinTesla, the alignment will be failed or will stop and you must begin once

Follow these instructions as shown in pictures and your energy management calibration will work.

# First step: (Charge current)



# Second step: (Charge current)



If all of the measurements are OK, the values are now adjusted.

If one or more values failed, see charging problems on page #14.



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 6 (29) Repairhints Version 1.0 Approved

# TX tuning

Has to be tuned in both bands, but only on middle channels: CH38 – 897,6 MHz for EGSM and CH700 – 1747,8 MHz for PCN. TX I/Q tuning has to be done for both bands.

Reference are always target- values given from WINTESLA.

# **RX** calibration


# RSSI (Radio / Received Signal Strength Indicator)

The "RX calibration" is used to determine gain at different gain-settings for front-end and Hagar and needs to be done in both bands, but the calibration only has to be started once, it will automatically proceed to the PCN band after EGSM.

**Note:** If the frequency in your Wintesla is different from 946.2671 MHz ,you will have to close Wintesla and add or edit these lines in your tesla.ini file:

[NPE-3\_TUNING] RXChannelGSM = 56 TXChannelGSM = 38


Restart Wintesla and redo RX Calibration.




**Note if the low level in your Wintesla is different from –85dBm**, you will have to close Wintesla and add these lines in your tesla.ini file:

[NPE-3LEVELS] RSSILow =-85 RSSIHigh =-55

Restart Wintesla and redo RX Calibration





Note: Check if AGC-values are in ascending order (10dBm/step, exception: In PCN mode gainstep 2 to 3 is only ~5dBm)



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 7 (29) Repairhints Version 1.0 Approved

# AM suppression tuning


Tune's four Hagar internal resistors of RX demodulator.


Purpose is to minimize the effect of any kind of AM interference to RX performance.

Tuning is automatic but it needs AM-modulated signal to phones` antenna input and has to be done for both bands.

#### NOTE:

Set the generator to the level or frequency shown in your wintesla window!





# NOTE: WINTESLA WILL USE CH.56/700+10MHz INSTEAD OF ALL MANUAL SETTINGS IN TESLA.INI!


# Use these settings:

EGSM PCN


Fmod=1kHz Fmod=1kHz
Mod depth=83% Mod depth=83%

P=-23dBm P=-26dBm

F=956.2MHz F=1852.800MHz



AM supression results should be in a range for: EGSM –86dBm to –130dBm, PCN -95dBm to –130dBm



RX filter calibration results for AD values should be in a range between 0 and 1023.



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07

Repairhints Version 1.0 Approved

8 (29)

# **Description of Signals & Voltages**

The cause of this list are some new named signals/voltages in opposite to former names which are used in this document (where to measure) & for a better understanding in addition to the service manual.

# Startup sequence/CCONT section

PWRON/WDDISX (J102/R401) Always high level, only pulled down as long as powerkey is pressed.

PURX (J101) Power-Up-Reset signal from CCONT. When the voltages are stable, this line is on high level

allowing the MAD to run (Masterreset).

CCONTCSX (J100) Chip select for the CCONT. Used when the MAD wants to access the CCONT on the serial

bus (the serial bus is shared with the display) GENSIO-bus.

**CCONTINT** Interrupt from the CCONT to the MAD; for example: from the Real Time Clock, when a

charger is connected or when an intelligent battery powers the phone up

Output to the charger, when using 3-wire charging. The duty cycle of this 32Hz signal CHARG\_CTRL (J114/C171)

switches the output current of the ACP-9 charger.

RFC (J601) Reference Frequency Clock. High stability clock signal for the digital circuits inBaseband

(13MHz)

SLEEPCLK (J112/C113) 32kHz clock generated in CCONT RTC. Used by MAD during sleepmode SYNTHPWR (J317) Control line from MAD to CCONT. Turns on/off 3 voltage regulators for RF

VCXOPWR/SLEEPX (J331/J333/R305) Control line from MAD to CCONT. Controls the sleep-mode by turning on/off regulators

needed during normal/sleep

Battery voltage VB (J103/C105)

VCORE (C155) Digital baseband supply for the MAD core, 1.7 –1.9V

VBB (J108/C147) Digital baseband supply, 2.7V

Analog baseband supply, 2.7V (used for audio) VCOBBA (J109/C254)

Battery voltage for supplying IRDA, VIBRA and BUZZER VBATTIR (L121)

Battery voltage for the Power amplifiers (RF) VBATTRF (L122)

Battery voltage for supplying LED's VBATTUI (L120)

VREF (J117/C143) 1.5V reference voltage (+-1,5%) generated by CCONT VREF\_RX (R510) Reference voltage for HAGAR, generated by COBBA

VSYN\_1 (J106/C130) Supply voltage for SHF VCO

VSYN\_2 (C133) Supply voltage for digital and analog circuits in HAGAR (VLO, VPRE, VBB, VF\_RX)

VRX (J104/C136) Supply voltage for HAGAR part of the RX chain VTX (J107/C142) Supply voltage for the TX chain in HAGAR

VXO (J105/C141) Supply voltage for the VCTCXO and VDIG in HAGAR VCP (J110/C157) 4,9V supply voltage for PLL charge pump HAGAR

Charger input V\_IN (F101)

VPP (C349) 12V input for fast flashing. In normal use, this line of the Flash is used for write protecting

the flash, and is then controlled by MAD with a possible overrule from a voltage detection circuit. So if the battery is removed, the voltage detector disabled writing to the flash

**VIRDA** (C139) Regulator (2.7V), that turns the Infrared device and buffers on/off

RAM\_BCK (C135) Backup-supply to SRAM. When the phone is turned off, the SRAM gets power from the

RTC-battery, so that data is not lost

BATTIO (V120) Signal used for turning ON an intelligent battery from the phone

Checked by: CC Training Group © 2001 NMP Approved by: SACE



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07

Repairhints
Version 1.0 Approved

9 (29)

# RF part

AFC (R604) Automatic Frequency Control - analog control signal for 26 MHz VCTCXO fine tuning COBBACLK (J200) 13MHz clock from MAD to COBBA - used for syncronized serial communication between

COBBA and MAD

HAGARRESET (J500/N501) Reset signal from MAD to HAGAR

DET (V800) Detector signal between powerdetector and HAGAR SCLK (J502/J506) Clock for HAGAR serial programming (26 MHz) SDATA (J503/J507) Data for HAGAR serial programming

SLE (J501/J505) Serial Latch Enable for HAGAR serial programming (formerly titled as SENA)

RXI, RXQ (R509) The RX baseband signals (after downconversion)

GSM\_RX (Z700) EGSM RX signal between RX/TX switch and 1<sup>st</sup> EGSM SAW GSM TX (L800) EGSM TX signal between dual-coupler and RX/TX switch

TXP (R512) Transmitter power enable - used for timing of the power loop, Enables the operation

amplifier in HAGAR

TXC (R518) Transmitter power control signal, that controls the level of the output power and the shape

of the burst

VPCTRL\_G (V803) Control line for PA output power

TXVDET (C531) Supply voltage for the RF power detector circuit

TXBUF\_G (C807) Supply voltage for EGSM TX buffer TXBUF\_P (C829) Supply voltage for PCN TX buffer

LNA\_G (C706) EGSM LNA supply voltage, front-end gain on/off LNA\_P (C700) PCN LNA supply voltage, front-end gain on/off LNAB\_G (R708) BIAS for both LNA's, front-end gain on/off

TXI\_0, TXI\_180 (R513) Differential In-phase TX signals to the IQ-modulator

TXQ\_0, TXQ\_180 (R516) Differential quadrature-phase TX signals to the IQ-modulator

TXVGSM (R910/N800) Selects GSM Tx mode in PA and RX/TX Switch TXVPCN (R911/N800) Selects PCN Tx mode in PA and RX/TX Switch

OUTM\_G\_TX (L802)

Balanced EGSM TX signal between HAGAR and EGSM TX balun

OUTP\_G\_TX (L802)

Balanced EGSM TX signal between HAGAR and EGSM TX balun

OUTM\_P\_TX (L804)

Balanced PCN TX signal between HAGAR and PCN TX balun

OUTP\_P\_TX (L804)

Balanced PCN TX signal between HAGAR and PCN TX balun

Balanced PCN TX signal between HAGAR and PCN TX balun

INM\_GSM\_RX (L704) Balanced EGSM RX signal between EGSM RX balun and RF input of HAGAR INP\_GSM\_RX (L704) Balanced EGSM RX signal between EGSM RX balun and RF input of HAGAR

INM\_LO (T600)

Balanced VCO signal between VCO balun and VCO input of HAGAR
INP\_LO (T600)

Balanced VCO signal between VCO balun and VCO input of HAGAR
INP\_PCN\_RX (L703)

Balanced VCO signal between PCN RX balun and RF input of HAGAR
INM\_PCN\_RX (L703)

Balanced PCN RX signal between PCN RX balun and RF input of HAGAR
Balanced PCN RX signal between PCN RX balun and RF input of HAGAR

OSC\_DIV/TOUT (C614) Reference divider output (13 MHz) -- RFClock OSC\_IN (G602) Reference frequency input from ref oscillator

OUT\_CP (C605) Output of the PLL charge pump

PCS\_RX (Z701) PCN RX signal between RX/TX switch and 1<sup>st</sup> PCN SAW PCS\_TX (L800) PCN TX signal between dual-coupler and RX/TX switch

© 2001 NMP Checked by: Approved by: CC Training Group SACE



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07

Repairhints
Version 1.0 Approved

10 (29)

# Digital/programming part

MBUS (J113/R172) Bidirectional serial bus between MAD and accessory - during flashing, clock signal is

received on this line

MBUS1 (V170) Same as above, but on the "dirty" side of the filter

FBUS(1:0) (V171) FastBus. Consisting of FBUS\_RX and FBUS\_TX signals. Used for IRDA and accessory

communication. During flashing, the data is transferred on these lines

FBUS\_RX(J332/R306) Receive line from the MAD's point of view FBUS\_TX(J331/R305) Transmit line from the MAD's point of view

# User Interface part

XEAR (L201)

Audio output when using carkit or headset

XMIC (L201)

Audio input when using carkit or headset

MICN (L200) Negative side of the microphone MICP (L200) Positive side of the microphone

PD2 (R201) Signal for muting microphone in headset, controlled by MAD

BUZZER (R410) PWM-signal from MAD, controls the buzzer

LCDCD (J328) Signal for controlling if the display is to receive data or control information on the serial

bus

LCDEN (J451) Chip enable signal to the display, informing that data on the serial bus is to the display

driver

LCDRSTX(R430) Reset signal from MAD to display driver

LIGHT (R427) Signal from MAD, that turns on the LED's for keyboard and backlight

ROW(4:0) (V450) Keyboard matrix scan lines COL(4:0) (V450) Keyboard matrix scan lines

CARDDET (C127) Used for detecting removal of the battery. When the battery is removed, this signal goes

high before the power is lost, giving the MAD time to power down the SIM-card

SIMIF(4:0) (J300) Serial bus for transferring SIM-data between MAD and CCONT

HEADDET (C211) Used for detection of which accessory has been connected to the system connector by

measuring the voltage on XMIC. Connected to A/D-converter in CCONT, and I/O-pin on MAD. Data can also be transferred, for example - between MAD and DLR3-cable

HOOKDET (C212) For detecting when the push-button on the headset is pressed

DLR3 (V221) When the DLR3-cable is detected, this signal controls a switch, which gives power to the

cable

SGND (L201) Return line for microphone and earpice when a headset is connected to the phone. When

the DLR3-cable is connected, it changes to a power supply line to the cable, supplying 2.7V



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 11 (29) Repairhints Version 1.0 Approved

# **USER INTERFACE FAILURES**

# Display failure

Check mechanical appearance of H400 and C451.

Check contact pads on PCB – clean also if necessary

Check VBB 2,7V at C452

Check if Vout 3,6V / 70mVpp at C451 (noise < 100mV), if much higher, C451 may be broken.

Change LCD unit if failure persists - probably MAD D301 faulty.

If the LCD shows too much contrast and / or LCD flickers, check if C451 is broken.

If there are vertical or horizontal lines missing, LCD unit electrical defect.

# **Keypad malfunktion**

Check if domesheet contacts are dirty, clean PCB (keypads) if necessary

Check mechanical appearance of domesheet (LCD unit) itself.

Check resistance of ROW and COL lines between the keys (0 Ohm)

Change LCD unit.

If keypad is still malfunctioned - probably MAD D301 faulty.

If keypad crackles when pressing keys, change keypad.

# Backlight failure

First check mechanical condition and position of baseband shield, check for shorts, etc.

Check VBATTUI 3,6V at L120

Check VBATTUI 3,6V at R424

Check voltage at V430 (LCD lights) 3,6V and at LED's V420 - V423

Check voltage at V431 (Key lights) 3,6V and at LED's V424 - V429

Check voltage at R427 (LIGHT line) – if this fails, MAD D301 or PCB faulty

Note: Different LEDs for LCD (brighter) and keypad backlight.

# Clock time problems.

Clock time has to be corrected in short periods.

Check amplitude and frequency of sleepclock oscillator at J112 / C113 should be 3,2Vpp squarewave at 32,768kHz.


If not ok change B110 and check parts around oscillator: (R110, R111, R112, R113, C110, C111, C112, C113).

# Clock time is lost after removing battery.


First try to charge RTC battery, by connecting battery to the phone for app. 10 minutes.


If fault remains, check contact springs of battery or change RTC battery (LCD unit). Check VBACK 3.2V at RTC battery **G100** If fault persists, probably CCONT **N102** or CHAPS **N100** faulty.

# 32 kHz before and after C113












CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 12 (29) Repairhints Version 1.0 Approved

# Vibra failure


Check mechanical appearance of M400
Check VBATTIR 3,6V at L121
Check VBATTIR 3,6V at V440
Check vibra signal at L401. If not ok check VIBRA signal at R444
If signal is ok at R444 change V441, if signal fails,

MAD D301 is probably faulty, or a disconnection between MAD and R444 in VIBRA line is the reason



# Buzzer failure

Check mechanical condition of buzzer **B400**Check VBATTIR 3,6V at **L121**Check buzzer signal at **R410**Check buzzer signal in and out at **V410**Change buzzer **B400** if all of the above works



 Name Date
 = Active Channel 1 Date

 Date
 = 19.12 cV

 207:22 27
 27

 Y Scale
 = 100
 mV/Div

 X Scale
 = 0.00
 mV

 X Scale
 = 200
 μs/Div

 X Size
 = 349
 (512)

 Maximum
 = 21.88
 mV

 Minimum
 = 240,50
 mV



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 13 (29) Repairhints Version 1.0 Approved

# SIMcard failures

# SIMcard not accepted

Use Wintesla to open normal mode/quick/RF info window - compare shown SIMlock data with the listed entries of the respective productcode (see SIMlock list).

If shown SIMlock data is the same as in the list – Status is ok und must be set so! Probably MSIN data field is closed to special IMSI number range, it only can be opened by operator (refer to general Service Bulletin 065).

If SIMlock data is not the same as in SIMlock list or somehow corrupted, SIMlock-data must be rewritten with the Nokia-security password.

If SIMlock is corrected or inactive but fault remains - **N240** is faulty, or there are probably broken solderings under COBBA - change **N240** - realign RX / TX values and rewrite SIMlock data and flash the phone after this again.

# "Insert SIMcard" appears in Display

Check X160, if bent or soiled - change if necessary

Check BSI A/D values (ok range 340-350)


Check V160: pin1 – DATA\_0, pin3 - VSIM, pin4 - SIMCLK, pin5 – SIMRST\_0

Check also R160, C160, C161, C162

Check resistance of SIMlines to GND - change V160, C163, C164 if necessary, probably broken solderings under CCONT N102 Change CCONT N102 and run energy management calibration, if fault persists - probably MAD D301 or PCB faulty.

# SIMcard Signals

# SIMCLK DATA\_0





CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 14 (29) Repairhints Version 1.0 Approved

# CHARGING PROBLEMS

At first try an energy management calibration; either to define the defective area, or the phone works well after calibration. (See page #5)

# "NOT CHARGING" appears on display

If calibration failed – check possible failure message:

Battery temperature failed: Check X120, X121, R122 / R123, R124, V120, change N102 if necessary.

Battery size failed: Check X121, X120, R120 / R121, change N102 if necessary.

Battery voltage failed: Check L123 / R105 / C104 / C105, change N102 if necessary

Charge current failed: Check R106, change N100 and / or N102.

Charge voltage failed: Check VCHARGE at voltage devider R102 / R103, if ok – change N102,

if not ok - check X001, R101, F101, L101, change N100 if necessary.

# X120 / X121 battery connector, X001 system connector.

Check mechanical condition of connectors – change if necessary.

# V\_IN line short-circuited to GND

Check resistance of V\_IN line at F101 to GND (50 kOhm), if resistance is not ok - remove L101 and check again. If resistance is ok now - C101 / C102 or N100 should be the reason, if resistance is still not ok - R101 faulty.

# CCONT / N102 faulty

Change CCONT N102 if any A/D (calibration) value, is out of limit and DC voltage is ok.

If DC voltages are not ok, check corresponding voltage dividers and battery connectors **X120** / **X121**, always realign RX/TX and AD values after changing CCONT **N102**.

# Nothing happens if charger is connected

F101 faulty

Check resistance of F101 (0 Ohm).

Check voltage at R103 > 0.4V if charger is connected. If not ok (<0.4V) – check / change X120,X121,F101,R101,R102/R103, if ok - change N100 and / or N102.

# Energy management calibration.

Calibration has to be done always if any part in charging circuit has been replaced.

Try calibration, if charging process stops too early or doesn't start and if message "NOT CHARGING" appears on Display.


( Also see "General tuning informations" )

Service & Analysis Center Europe

CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 15 (29) Repairhints Version 1.0 Approved

# **CONTACT SERVICE**

SACE CC Training Group





CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 16 (29) Repairhints Version 1.0 Approved

# CONTACT SERVICE PROBLEMS

This fault means that the phone software is able to run and thus the watchdog of CCONT N102 can be served. Selftest functions run when power is switched on and program is executed from FLASH If any selftest fails, - "CONTACT SERVICE" appears in Display.

Note: Always try SW-update to solve the problem or locate the error - in most of the cases phones are ok after update.

Possible failures:

#### MCU ROM Checksum failed:

Try to flash the phone. If not ok after flashing – change FLASH D311 if you are authorized to rewrite IMEI and SIMlock data, if failure persists after changing D311, MAD D301 defect which is not changeable.

# **CCONT Interface failed:**

Probably broken solderings under CCONT N102


If not ok after rework of CCONT, probably MAD **D301** or PCB faulty. Run energy management calibration after changing CCONT! NOTE: For Energy management calibration see also **general tuning information** page!

# COBBA parallel/serial failed

Check VBB 2,7V at C147, VCOBBA 2,7V at C254 & COBBACLK at J200

If all ok - change COBBA N240

If the failure persists after changing COBBA – probably MAD D301 or PCB faulty.



#### DSP Alive failed

In most of all DSP alive selftest failures MAD D301 is faulty, which is not changeable.

# EEPROM tune checksum / security checksum failed

Use Wintesla to check if phonedata like IMEI, product data or PSN are corrupted.

If phone data is ok, try to reset the phone. If phone data is not ok or fault remains after reset, FLASH D311 is faulty.

# **RTC Battery failed**

First try to charge RTC battery by switching on the phone for app. 10 minutes If fault remains, check contact springs of battery. In some cases it is necessary to change CCONT **N102**.



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 17 (29) Repairhints Version 1.0 Approved

# PHONE DOES NOT SWITCH ON

First check always current consumption: off state 0-2,3mA, sleep mode 2,3-4mA. If too high – see section "low standby / operation mode time".

Disable watchdog if phone switches off after 2 or 3 seconds.

Check connectors X001/X120/X121 - change if bent or soiled.

Check VB 3,6V at J103/C105 - if not ok, check/change L123.

Check if PWRON at R401/J102 drops to OV while pressing powerswitch, if not ok - check/change S402, R401.

Check 32,768kHz at **J112/C113**, 3Vpp squarewave – (if it is difficult to measure squarewave, because of Basebandshield, check 32,768 kHz at the other side of C113, 900mVpp sinewave).

If not ok, check/change components around **B110**, **(R110-R113 & C110-C113)** and/or change CCONT **N102** if necessary. Check VCORE at **C155** – 1,7V – if not ok, change CCONT **N102**.

Check VBB 2,7V at J108/C147, VXO 2,7V at J105/C141, VREF 1,5V (+-1,5%) at J117/C144 –if not ok, check resistance of lines to GND and/or change CCONT N102 if necessary.

Check SLEEPX/VCXOPWR 2,7V at J333/J331 - if not ok, MAD is faulty in all probability - swap the phone, because MAD D301 is not changeable.

Check PURX 2,7V at J101 after pressing powerswitch - if not ok, change CCONT N102.


Check 13MHz Clk frequency (RFC) at C613, if not ok, check values around 26MHz oscillator G602 / V600 Change HAGAR N500 if necessary.


Try to flash the phone - if not ok, see section "FLASH update not possible".


#### Note:

It is nessesary to realign all RX/TX values after changing HAGAR **N500 and** run energy management calibration after changing CCONT **N102**.

For Energy managemant calibration see also **general tuning information page!** 32,687 kHz before and after C613.









CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 18 (29) Repairhints Version 1.0 Approved

# LOW STANDBY / OPERATION MODE TIME

# Off state current > 0-2,3mA.

lift L122 (VBATTRF) - check current consumption, if ok - N800 faulty in all probability,

if current is still too high after changing N800. check / change C814, C815, C817.

Lift L123 (VB) - check current consumption - if too high,

# **VB** line faulty

In most cases is CCONT **N102** the reason. If fault persists after changing CCONT, it is also possible, that capacitor(s) in VB line is/are faulty (C105, C122, C123, ...). Check all these components lifting one after the other, with repeated current testing. If fault persists, probably one of the  $\mu$ BGA / CSP's and / or PCB should be the reason.

# Sleep mode current > 2,3-4mA

Check resistance of all voltage output lines of CCONT N102 to GND

Check component(s) in corresponding line(s) if resistance is not ok

If resistance of voltage lines (from CCONT N102) are ok, but sleep mode current is still too high – change CCONT N102.

Check charging circuit, run energy management calibration.

If calibration fails - continue with section "Not charging"

Align RX / TX values. If calibration fails - continue with section "RX / TX faults".

#### Note

Standby time also depends on network side and users handling, like lights on/off, VIBRA- / WAP activities, games etc.

# FLASH UPDATE NOT POSSIBLE

Check if fault code from prommer is one of the following:

# MCU boot failure, serial clock/data line failure:

Connect "watchdog disable" WDDISX R401 to GND.

Check VBB 2,7V at J108/C147 and VXO 2,7V at J105 / C141, if not ok - continue with section "PHONE DOES NOT SWITCH ON" Check SLEEPX 2,7V at J333 - if not ok - MAD D301 faulty in all probability

Check PURX 2,7V at J101 - if not ok change CCONT N102

Check 13MHz Clk frequency at **C613**, approximately 800mVpp, if not ok, check values around 26MHz oscillator **G602** / **V600**, change HAGAR **N500** if necessary

Check resistance of MBUS / FBUS lines (J113 / J331 / J332) to GND, also check R172, V170, V171,R305, R306 and check X001

If update still not possible – swap the phone, MAD **D301** or PCB should be the reason.

# Algorithm code fail, alias ID missing:

Update FPS4 box with the latest flash device list and try to update again, if fault remains, check values at MAD **D301**. If ok, change FLASH **D311** 

# **External RAM failure:**

Check values at MAD **D301**, if ok - SRAM **D310** faulty and/or change FLASH **D311** if necessary. See chapter "PHONE DOES NOT SWITCH ON"

#### Note:

It is necessary to run energy management calibration after changing CCONT N102! For Energy management calibration see also general tuning information page (#5).



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 19 (29) Repairhints Version 1.0 Approved

# NO SERVICE PROBLEMS

#### No RX EGSM

Use Wintesla to set phone in following mode: Initialise / Local mode / Testing / RF Controls / Gain step value >2 / active unit RX-burstmode / Channel 56 (946,2MHz). Set Generator to same frequency, -40dBm.

Check 26MHz reference oscillator frequency at G602, 800mVpp/frequency deviation < 100Hz

Check 946,2MHz at **C912**, if not ok, check/ change **Z900**, **X900**.

Check 946,2MHz at L700, if not ok, check/change Z700.

Check 946,2MHz at **V700** in & out, if not ok, check LNA values: VLNAB\_G 2,7V at **V700**, pin 8 and LNA\_G 0,7V at pin4, change HAGAR **N500** if necessary.

Check 946,2 MHz at L704 - if not ok, check/change Z703, R702, T700.

Check RXIQ signals at **R509**, if not ok, check supply values at HAGAR **N500**: 2,7V at **C513** (VXO), **C501** (VRX), **C503**(VSYN\_2) and **N501** input 4.9V (VCP). If one or more of these fails, change **N102**.

Check SDATA at J503/J507, SCLK at J502/J506 and SLE at J501/J505, if not ok MAD D301 faulty

Check VREF (1,5V) at **R514** / VREF RX (1,2V) at **R510**, if not ok, change **N102**.

Check frequency of SHF oscillator **G600** if possible – refer to EGSM frequencies list.

If all values are ok but no RXIQ signals measurable at **R509**, HAGAR faulty, or there are probably broken solderings under **N500**. If signals at **R509** ok, but still no RX calibration possible, check values at COBBA **N240**:

VBB at C256 (2,7V) and VCOBBA at R245 (2,7V), also check COBBACLK at J200.

If values ok – N240 faulty, or there are probably broken solderings under COBBA.

#### No RX PCN

Use Wintesla to set phone in following mode: Initialise / Local mode / Testing / RF Controls / Gain step value >2 / active unit RX burst / Channel 700 (1842,8MHz). Set Generator to same frequency, -40dBm.

Check 26MHz reference oscillator frequency at G602, 800mVpp/frequency deviation < 100Hz

Check 1842,8MHz at X900 and ANT pad of Z900 - change X900 if necessary.

Check 1842,8MHz at C913, if not ok, check solderings of Z900, change if necessary .

Check 1842,8MHz (PCS\_RX) at C702 - if not ok, check/change Z701.

Check 1842,8MHz at C712 - if not ok check values of LNA: VLNAB\_G = 2,7V at V701, pin 8 (VC) and LNA\_P = 0,7V at pin 4 (VCC) Change V701 if necessary.

Check 1842,8MHz at L703, If not ok, check/change Z702, T701

Check RXIQ signal at R509 - if not ok, check values at HAGAR N500: 2,7V at C513 (VXO), C501 (VRX), C503 (VSYN\_2) and N501 input 4.9V (VCP).

If one or more of these fails - change N102

Check SDATA at J503/J507, SCLK at J502/J506 and SLE at J501/J505, if not ok MAD D301 faulty.

Check VREF (1,5V) at **R514** / VREF\_RX (1,2V) at **R510**, if not ok, change **N102**.

Check frequency of SHF oscillator **G600** if possible – refer to EGSM frequencies list.

If there is no possibility to check frequency - check if oscillator works by measuring VCC at **C601** (2,7V) and VC at **C603**, which varies between 0,7V and 3,8V (see EGSM list).

If VC is 4,8V, the oscillator doesn't work in all probability, also check **T600** and **R608**.

If all values are ok but no RXIQ signal is measurable at **R509**, **N500** is faulty, or there are probably broken solderings under HAGAR.

If signal at **R509** ok but still no RX calibration possible, check values at COBBA **N240**: VBB 2,7V at **C256** and VCOBBA 2,7V at **R245**, also check COBBACLK at **J200**.

If values are ok, N240 faulty, or there are probably broken solderings under COBBA.

Note: After changing COBBA, HAGAR and/or CCONT it is necessary to realign all RX,TX -and AD values, and rewrite IMEI and SIMlock data (COBBACHANGE)

© 2001 NMP Checked by: Approved by: CC Training Group SACE



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 20 (29) Repairhints Version 1.0 Approved

# NO SERVICE PROBLEMS EGSM/PCN no RX

First check 26 MHz at G602 (700mVpp,+/-100Hz) Check SHF (list) and/or VC/VCC 2.7V (C601) No service No service (GSM900) (GSM 1800) Check 946,2MHz at Z900 (antennapad) Check 1842,8 MHz at Check/change X900 OK OK Check 946,2MHz at C912 Check 1842,8MHz at C913 Check/change Z900 Check 946,2MHz at Check 1842,8MHz at C702 Change Z700 Change Z701 Check
LNAB\_G at V700/701, VC (2.7)
at pin8, 2,7V at pin4.
LNA\_G = 0.7V
LNA\_P = 0.7V Check 946,2MHz at Check 1842,8MHz at V700 OK OK Change N500 Check/change Z703, R702, T700 Check 1842,8MHz at Check 946,2MHz at Check/change Z702 T701 Change N500 ΟK Check supply voltages at N500: C513 (VXO); C501 (VRX); C503 (VSYN\_L) At N501: (VCP) 4.8V Check RX IQ at R509 Check RX I/Q at R509 Check SDATA J503 SLE J501 SCLK J502 Change N240 Swap PCB Check VBB 2.7V at C256, R245. VCOBBA (2,7V) and COBBACLK at J200



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07

21 (29) Repairhints Version 1.0 Approved

# NO SERVICE PROBLEMS / TX POWER

First of all: Try to calibrate RX / TX values to define the fault area, or phone works well after calibration

# No or low TX power EGSM

Use Wintesla to set phone in following mode: Initialise / Local mode / Testing /RF Controls / active unit TX / **Channel 38** (897,6MHz).

Check 26MHz reference oscillator frequency at G602 (800mVpp, frequency deviation < 100Hz)

CheckTXBUF\_G at C807 - 2,7Vpp squarewave - see signal page #27

Check TXIQ signals at C525 / C526, refer to signals shown on page #27.

If not ok, check values at COBBA N240 (see COBBA N240 chapter page #24).

Check 897,6 MHz at T800 pin 4 and 6. If not ok, check signals at HAGAR N500 (see HAGAR N500 chapter)

Check 897,6 MHz at N800 pin 8. If not ok,check / change parts like T800,V801, Z802, Z800.

Check 897,6 MHz at L800 pin 1. If not ok, check values at N800.

Check 897,6 MHz at X902 (Antenna pad). If not ok, check / change X900.

Check **L800** in & out, check also signal at **Z900** in & out and TXVGSM: 2,7Vpp squarewave at **C910** (sets **Z900** into TX-mode).

#### No or low Tx power PCN

Use Wintesla to set phone in following mode: Initialise / Local mode / Testing /RF Controls / active unit TX / **Channel 700** (1747,8MHz).

Check 26MHz reference oscillator frequency at G602 (800mVpp, frequency deviation < 100Hz).

Check TXBUF\_P at C829 - 2,7V squarewave - see signal page #27

Check TXIQ signals at C525 / C526, refer to signals shown on page #27.

If not ok check values at COBBA N240 (see COBBA N240 chapter, page #24)

Check 1747,8MHz at T840 pin 4 and 6. If not ok check signals at HAGAR N500 (see HAGAR N500 chapter).

Check 1747,8MHz at N800 pin 8. If not ok check / change parts like T840,V802, Z800.

Check 1747,8MHz at L800 pin 2. If not ok, check values at N800.


Check 1747,8MHz at X902 (Antenna pad). If not ok, check / change X900.

Check **L800** in & out, check also signal at **Z900** in & out and TXVPCN: 2,7Vpp squarewave at **C911** (sets **Z900** into TX-mode).

© 2001 NMP Checked by: Approved by: CC Training Group SACE

CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 22 (29) Repairhints Version 1.0 Approved

NO TX





CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 23 (29) Repairhints Version 1.0 Approved


# SHF OSCILLATOR PROBLEMS

This causes problems in EGSM and PCN mode (RX/TX).


If the phone has no service because of too low TX power (eg. approximately 5dBm in the highest powerlevels) and / or there are strange A/D values in the RSSI measurements – check (if possible) the SHF frequency with a spectrum analyzer and /or the RX calibration A/D values (also see pictures below) if there might be something unusual like a cutted SHF oscillator frequency amplitude and / or the gain readings in RX calibration are lower as normal, - approximately about values of 10 to 20.


If this is the case, check the periphery – capacitors of SHF Oscillator **G602** in VC circuit (**C603**, **C604**, **C605**) Check their resistance to GND (approximately 3MOhm at **R612** to GND in normal case / otherwise the value should be in lower kOhm range (around 10k):

Left picture shows a normal SHF frequency amplitude – right side in defect case



Left picture shows normal gain readings – right picture in defect case (RX Calibration):








CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 24 (29) Repairhints Version 1.0 Approved

Approved by: SACE

# COBBA / N240 faulty

Check VBB 2,7V at **C256** and VCOBBA 2,7V at **R245**Check 13MHz COBBACLK at **J200**, probably broken solderings under COBBA / **N240**.
Realign Rx / Tx values after rework of COBBA **N240**.



# HAGAR / N500 faulty

Check voltages at HAGAR:

**VXO** 2,7V at **C533** 

**VCP** 4,7V at **N501** (output)

VSYN\_2 2,7V at C503 VRX 2,7V at C501 VREF 1,5V at C143

Check 26MHz reference oscillator frequency at G602:

800mVpp – frequency deviation < 100Hz.

Check TXIQ signals at R513/C525 (TXI 0/180) and R516 / C526 (TXQ 0/180)

Check SDATA at J503/J507, SCLK at J502/J506 and SLE (SENA) at J501/J505 (refer to signals shown on page #27)

Check TXC at C529 (diagram on page #25)

Check TXP at R512, 3Vpp squarewave/ 217Hz

Check frequency of SHF oscillator / G600 - refer to EGSM frequency list

If all values are ok but no TX - signal is measurable at **T800**, there are probably broken solderings under HAGAR, or **N500** is faulty.


Note: After changing COBBA, HAGAR and/or CCONT it is necessary to realign all RX,TX -and AD values, and rewrite IMEI and SIMlock data (COBBACHANGE)




CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 25 (29) Repairhints Version 1.0 Approved

# SIGNAL CHARTS

# Serial data (RX Burst mode)




# Serial clock (RX Burst mode)




Name = Active Channel 1
Date = 11.12.00
Time = 08.40.12
Y Scale = 500 mV/Div
Y At 50% = 1.323 V
X Scale = 2 µs/Div
X At 0% = -2,04 µs
X Size = 512 (512)
Maximum = 2,805 V
Minimum = -97.23 mV

# Serial Latch enable (RX Burst mode)




# TX power control TXC




Name = Active Channel 1
Date = 11.1.2.00
Time = 07:54:20
Y Scale = 500 mV/Div
Y At 50% = 407.50 mV
X Scale = 1 mer/Div
X At 0% = -160 µs
X Size = 512 [512]
Maximum = 1,506 V
Minimum = -398,91 mV

# TX power enable TXP



# TX\_IN phase /Quadrature phase (0/180°)



Name = Active Channel 1
Date = 11.12.00
Time = 08:03:34

Y Scale = 500 mV/Div
Y At 50% = -360.00 mV
X Scale = 100 μs/Div
X At 0% = -60 μs
X Size = 512 (512)
Meximum = 1,452 V
Minimum = -22.50 mV



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 26 (29) Repairhints Version 1.0 Approved

# FREQUENCY LIST

Channel	TX	RX	VCO - TX	VCO	VCO - RX	VCO
	NALI-z	N /ILI-z	NALI-z	VC at C603 VOLT	N ALI -	VC at C603 VOLT
1	MHz	MHz	MHz		MHz	
38	890,2 897,6	935,2 942,6	3560,8	1,7	3740,8	2,81
60	902	942,6	3608	2,01	3788	3
124	914,8	959,8	3659,2	2,34	3839,2	3,2
512	1710,2	1805,2	3420,4	0,84	3610,4	2,03
700	1710,2	1842,8	3495,6	1,3	3685,6	2,36
885	1747,8	1879,8	3569,6	1,77	3759,6	2,66
000	1704,0	1077,0	3307,0	1,77	3737,0	2,00
975	880,2	925,2	3520,8	1,46	3700,8	2,66
976	880,4	925,4	3521,6	1,70	3700,6	2,00
977	880,6	925,6	3522,4		3702,4	
978	8,088	925,8	3523,2		3703,2	
979	881	926	3524		3704	
980	881,2	926,2	3524,8		3704,8	
981	881,4	926,4	3525,6		3705,6	
982	881,6	926,6	3526,4		3706,4	
983	881,8	926,8	3527,2		3707,2	
984	882	927	3528		3707,2	
985	882,2	927,2	3528,8	1,51	3708,8	2,69
986	882,4	927,4	3529,6	1,51	3709,6	2,07
987	882,6	927,6	3530,4		3710,4	
988	882,8	927,8	3531,2		3711,2	
989	883	928	3532		3712	
990	883,2	928,2	3532,8		3712,8	
991	883,4	928,4	3533,6		3713,6	
992	883,6	928,6	3534,4		3714,4	
993	883,8	928,8	3535,2		3715,2	
994	884	929	3536		3716	
995	884,2	929,2	3536,8	1,56	3716,8	2,72
996	884,4	929,4	3537,6	·	3717,6	·
997	884,6	929,6	3538,4		3718,4	
998	884,8	929,8	3539,2		3719,2	
999	885	930	3540		3720	
1000	885,2	930,2	3540,8		3720,8	
1001	885,4	930,4	3541,6		3721,6	
1002	885,6	930,6	3542,4		3722,4	
1003	885,8	930,8	3543,2		3723,2	
1004	886	931	3544		3724	
1005	886,2	931,2	3544,8	1,61	3724,8	2,75
1006	886,4	931,4	3545,6		3725,6	
1007	886,6		3546,4		3726,4	
1008	886,8	931,8	3547,2		3727,2	
1009	887	932	3548		3728	
1010	887,2	932,2	3548,8		3728,8	
1011	887,4	932,4	3549,6		3729,6	
1012	887,6	932,6	3550,4		3730,4	
1013	887,8	932,8	3551,2		3731,2	
1014	888	933	3552		3732	
1015	888,2	933,2	3552,8	1,66	3732,8	2,78
1016	888,4	933,4	3553,6		3733,6	
1017	888,6	933,6	3554,4		3734,4	
1018	8,888	933,8	3555,2		3735,2	
1019	889	934	3556		3736	
1020	889,2	934,2	3556,8		3736,8	
1021	889,4	934,4	3557,6		3737,6	
1022	889,6	934,6	3558,4		3738,4	
1023	889,8	934,8	3559,2	1,7	3739,2	2,81
0	890	935	3560		3740	



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 27 (29) Repairhints Version 1.0 Approved

# Special information for NHM-3

This phone is build so that it can withstand a fall of 3 metres height without harmful effects – what certainly does not mean that you should test this feature on purpose.

Further more the phone endures drops into water of 0.5metres depth up to 1minute at a water temperature of not more than 50°C. Therefore the speaker, buzzer and microphone are sealed. Take care not to destroy these seals if you have to change one of the above mentioned item, don't even touch the seals!


To ensure water resistance, covers with gaskets must not be used more than three times after tightening the screws. Check always appearance of gasket around systemconnector and battery cover, change parts in case of doubt! It is absolutly necessary to use always new screws to assemble the phone, because gaskets around screws are surely damaged after tightening them! Order / torque of tightening screws: middle screws at 12Ncm, top screws at 25Ncm and then bottom screws at a torque of 25Ncm.

Note that accessories do not fulfill the same tough specifications as the phone is made for. Do not connect any electrical item (eg. charger, carkit) to the phone if it is still damp!

# The usage of NPE-3 Repair-Hints for NHM-3 phones is possible without any problems.

Schematics of both phones differ only in few points (eg. varistors in Xmic-line, some more components around LNA...), and almost all itemcodes are the same.

Because of different systemmodul-forms you have to use MJS-23 Jig with XRC-3 Rf-cable for testing and adjustment. If you have to make energy management calibration (eg. after changing Ccont or any part of the charging circuit), be sure that you are using dll 311.04.00 or later, else the tuning of battery size won't work and you will get the following failure message:



One of the most conspicuous differences between NPE-3 and NHM-3 is the systemconnector, which is connected via flexfoil to Pcb. Further more a batteryconnector similar to the one in NSM-2/3 is used. The Simcard-holder is combined with the shielding of the baseband as well as the antenna is one part with the shielding of the poweramplifier. The RF-connector is constructed flexible, so that a fall does not result in torn off traces.

If it is necessary to change any item with help of a soldering machine ( eg  $\mu$ BGA-components, shieldings, poweramplifier...), you have to remove the display assy first, which is connected to PCB with a flexfoil. This can be done easily with help of a Metcal Soldering Station MX500 equipped with a soldering tip SMTC 162.

Hot air should not be used to desolder anything ever since using Pcb with microvias, which will crack rapidly if exposed to too high temperature!









CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 28 (29) Repairhints Version 1.0 Approved

To remove the flexfoil release clips of display assy first and turn it around, so that you have access to the soldering points of the foil. Now you can desolder the flexfoil easily.



Before soldering a new display (do not use the old one!) clean careful the soldering points. Add few new solder to the pads and enclose only a little bit of flux.

Bend the flexfoil a little bit at the perforation, so that it is easier to hold the display in correct position. Do not touch the contacts of the flexfoil with bare fingers!



Heat up the soldering points for approximately 10 seconds. Check connection visually (especially at the top of the flex for shorts to ground) and clip display on Pcb. Never bend the flexfoil for more than 90°!



CONFIDENTIAL HDa-13/S 893 Introduction Date 2001-02-07 29 (29) Repairhints Version 1.0 Approved

# **CHANGE HISTORY**

Originator	Status	Version	Date	Comment
CC-Training- Group	Draft	0.1	24.01.2001	First draft version for the repair group
CC-Training- Group	Approved	1.0	06.02.2001	First approved version