NOKIA	CONFIDENTIAL		1(5)
Service & Analysis Center Europe	RF Quick Repair Layout	Version 1.0) Approved
SACE CC Training Group	NPE-3		
©NMP 2001 Only for Training and Service Purposes	06.02.2001		

No TX EGSM


- 1. Check 26MHz reference oscillator at G602: 800mVpp/frequency deviation < 100Hz, if not ok, change G602.
- 2. Check TXIQ signals at R513/R516.
- 3. Check VBB 2,7V at C256 and VCOBBA at C254 check COBBACLK at J200, N240 faulty, or there are probably broken solderings under COBBA if ok, goto 7.
- 4. Check VTX (2,7V) at C142 and VBATTRF 3,6V at L122 if not ok, change N102.
- 5. Check supply voltages (2,7V) for HAGAR at a:C513(VXO), b:C501(VRX), c:C503 (VSYN_2), d:N501 input 4,8V (VCP) if one or more of these fails change N102.
- 6. Check SDATA at a: J503/J507, SCLK atb: J502/J506 and SLE at c: J501/J505 if not ok MAD D301 faulty.
- 7. Check TXC at C529, check TXP at R512, change N240 for TXC- and N102 for TXP fault.
- 8. Check frequency of SHF oscillator G600 if possible refer to EGSM frequency list.
- If there is no possibility to check frequency check if oscillator works by measuring VCC at C601 (2,7V) and VC at C603, which varies between 0,7V and 3,8V (see EGSM list). If VC is 4,8V the oscillator doesn't work in all probability.
- If values are ok but no TX signal at T800 measurable N500 faulty, or there are probably broken solderings under HAGAR.
- 9. Check 897,6 MHz (CH56) at N800, pin 8 if not ok, check T800, Z802, Z800, V801.
- 10. Check 897,6 MHz (CH56) at L800, pin 1 if not ok, check VBATTRF at N800,pin 3 & 6.
- 11. Check also TXVGSM (2,7Vpp squarewave) at N800, pin 2 and Vapc 1-1,6Vpp squarewave, (depends on TX powerlevel) at N800, pin 7.
- 12. Check 897,6 MHz (CH56) at X902 (antenna pad) and at X900 (antenna connector) if not ok, check L800 in & out also check Z900 in & out and TXVGSM at R910. No BX EGSM
- 1. Check 26 MHz reference oscillator at G602, 800mVpp/frequency deviation < 100Hz, if not ok, change G602.
- 2. Check 942,6 MHz (CH56) at C912 if not ok, check solderings of Z900, change Diplexer if necessary.
- 3. Check 942,6 MHz (CH56) at L800 if not ok, check/change Z800.
- 4. Check 942,6 MHz (CH56) at V800 in £t out if not ok, check LNA values: VLNAB_G 2,7V at V800, pin 8 and LNA_G 0,7V at pin4, change HAGAR N500 if necessary.
- 5. Check 942,6 MHz (CH56) at L704 if not ok, check/change Z703, R702, T800
- 6. Check RXIQ signals at R509 if not ok, check supply values at HAGAR N500: supply voltages are 2,7V at C513 (VXO), C501 (VRX), C503(VSYN_2) and N501 input 4,8V (VCP). If one or more of these fails - change N102
- 7. Check SDATA at a: J503/J507, SCLK at b: J502/J506 and SLE at c: J501/J505. If not ok MAD D301 faulty.
- 8. Check VREF (1,5V) at R514 / VREF RX (1,2V) at R510 if not ok, change N102
- 9. Check frequency of SHF oscillator G600 if possible refer to EGSM frequencies list
- 10. If there is no possibility to check frequency check if oscillator works by measuring VCC at C601 (2,7V) and VC at C603, which varies between 0,7V and 3,8V (see EGSM list) If VC is 4.8V the oscillator doesn't work in all probability!


If all values are ok but no RXIQ signals measurable at R509 HAGAR faulty, or there are probably broken solderings under N500. If signals at R509 ok but still no RX calibration possible - check values at COBBA N240:


- 11. Check VBB at a:C256 (2,7V) and VCOBBA at b:R245 (2,7V), also check COBBACLK at J200. If values ok N240 faulty, or there are probably broken solderings under COBBA. No TX PCN
- 1. Check 26 MHz reference oscillator at G602, 800mVpp/frequency deviation < 100Hz, if not ok, change G602.
- 2. Check TXIQ signals at R513/R516.
- 3. Check VBB 2,7V at C256 and VCOBBA 2,7Vat R245, check COBBACLK at J200.
- -. N240 faulty, or there are probably broken solderings under COBBA. If OK, goto 8.
- 4. Check VTX (2,7V) at C142 and VBATTRF 3,6V at L122 if not ok, change N102.
- 5. Check 1747,8 MHz at T840 pin 4 and 6.
- 6. Check supply voltages (2,7V) for HAGAR at a:C513 (VX0), b:C501 (VRX),c:C503 (VSYN_2) and d:N501 input 4,8V (VCP), if one or more of these fails change N102.
- 7. Check SDATA at a: J503/J507, SCLK at b: J502/J506 and SLE at c: J501/J505, if not ok MAD D301 faulty.
- 8. Check TXC at C529, check TXP at C524 if not ok, change N240 for TXC- and N102 for TXP fault.
- 9. Check frequency of SHF oscillator G600 if possible refer to EGSM frequencies list. If there is no possibility to check frequency - check if oscillator works by measuring VCC at C601 (2,7V) and VC at C603, which varies between 0,7V and 3,8V (see EGSM list) -If VC is 4,8V - the oscillator doesn't work in all probability! If values are ok but no TX signal at T840 measurable - N500 faulty, or there are probably broken solderings under HAGAR.
- 10. Check 1747,8MHz (CH 700) at N800 pin 8 if not ok, check parts like T840, Z800 or V801.
- 11. Check 1747,8MHz (CH 700) at L800 pin 2 if not ok, check VBATTRF at N800,pin 3 & 6.
- Also check TXVPCN 2,8Vpp squarewave at N800,pin 1 and Vapc 1-1,6Vpp squarewave (depends on TX powerlevel) at N800,pin 7.

12. Check 1747,8MHz (CH 700) at X902 (antenna pad) - If not ok, check L800 in & out, also check Z900 in & out X900 (antenna connector) and TXVPCN at R911. No RX PCN

- 1. Check 26MHz reference oscillator at G602, 800mVpp/frequency deviation < 100Hz, if not ok, change G602.
- 2. Check 1842,8MHz (CH 700) at X900 and ANT pad of Z900 if not ok, change X900.
- 3. Check 1842,8MHz (CH 700)at C913 if not ok, check solderings of Z900, change if necessary.
- 4. Check 1842,8MHz (PCS_RX) at C702 if not ok, check/change Z701.
- 5. Check 1842,8MHz (CH 700) at C712 if not ok check values of LNA like VLNAB_G = 2,7V at V701, pin 8 (VC) and LNA_P = 0,7V at pin 4 (VCC), change V701 if necessary.
- 6. Check 1842,8MHz (CH 700) at L703 if not ok, check/change Z702, T701.
- 7. Check RXIQ signal at R509 if not ok, check values at HAGAR N500:
- 8. Supply voltages are 2,7V at a:C513 (VXO), b:C501 (VRX), c:C503 (VSYN_2) and d:N501 input 4,8V (VCP).
- If one or more of these fails change N102.
- 9. Check SDATA at a: J503/J507, SCLK at b: J502/J506 and SLE at c: J501/J505, if not ok MAD D301 faulty.
- 10. Check VREF (1,5V) at R514 / VREF_RX (1,2V) at R510 if not ok, change N102.
- 11. Check frequency of SHF oscillator G600 if possilble refer to EGSM frequencies list.
- If there is no possibility to check frequency check if oscillator works by measuring.
- VCC at C601 (2,7V) and VC at C603, which varies between 0,7V and 3,8V (see EGSM list).
- If VC is 4,8V the oscillator doesn't work in all probability.
- If all values are ok but no RXIQ signal is measurable at R509 N500 faulty, or there are probably broken solderings under HAGAR. If signal at R509 ok but still no RX calibration possible check values at COBBA N240.
- 12. Check VBB 2,7V at C256 and VCOBBA 2,7V at R245, also check COBBACLK at J200.
- If values are ok, N240 faulty, or there are probably broken solderings under COBBA.









NOKIA	CONFIDENTIAL		2(5)
Service & Analysis Center Europe	Baseband Quick Repair Layout	Version 1.0) Approved
SACE CC Training Group	NPE-3		
©NMP 2001 Only for Training and Service Purposes	06.02.2001		

Phone does not switch on

- First check current consumption: off state 0-2.35 mA / sleep mode 2.35-4 mA. If too high continue with section "low standby / operation mode time"
- 1. Check connectors X001 / X120 / X121 if bent or soiled.
- 2. Check VB 3,6V at J103 / C105 if not ok, check L123.
- 3. Check if PWRON at R401 / J102 drops to 0V while pressing powerswitch, if not ok check/change S402, R401.
- 4. Check 32,768kHz at J112 / C113, 3,2Vpp squarewave ok goto 7.
- 5. Check/change B110, R110, R111, R112, R113, C110, C111, C112, C113.
- Change CCONT N102 if necessary
- Check VBB 2,7V at J108 / C147 if not ok, check resistance of line to GND or change CCONT N102
 Check VXO 2,7V at J105 / C141 if not ok, check resistance of line to GND or change CCONT N102
- Check VXO 2,7V at 5105 / C141 11 Not ok, check resistance of line to GND of change CCONT N102
 Check VREF 1.5V (+-1.5%) at J117 / C144 if not ok, check resistance of line to GND or change CCONT N102
- Check SLEEPX 2,7V at J333 if not ok MAD is faulty in all probability swap the phone, because MAD D301 is not changeable
- 10. Check PURX 2,7V at J101 after pressing powerswitch if not ok, change CCONT N102
- 11. Check 13MHz Clk frequency (RFC) at C613, approximately 800mVpp -
- if not ok, check values around G602 / V600 change HAGAR N500 if necessary try to flash the phone - if not ok - continue with section "FLASH update not possible"
- Note: it is necessary to run energy management calibration after changing CCONT N102!
- NOTE: for Energy managemant calibration see also general tuning information page!
- FLASH update not possible
- Check if fault code from prommer is one of the following :
- MCU boot failure, serial clock/data line failure: yes goto 3
- Algorithm code fail, alias ID missing: goto 2.
- External RAM failure:
- 1. Check values at MAD D301, if ok SRAM D310 faulty / change FLASH D311 if necessary
- 2. Update FPS4 box with the latest flash device list and try to update again
- If fault remains, check values at MAD D301 if ok, change FLASH D311
- 3. Connect "watchdog disable" WDDISX R401 to GND.
- 4. Check VBB 2,7V at J108/C147 and VXO 2,7V at J105 / C141, if not ok continue with section "Phone does not switch on"
- 5. Check SLEEPX 2,7V at J333 if not ok MAD D301 faulty in all probability, swap the phone, because MAD is not changeable
- 6. Check PURX 2,7V at J101 if not ok change CCONT N102
- 7. Check 13MHz Clk frequency at C613, approximately 800mVpp, if not ok, check values around G602 / V600 change HAGAR N500 if necessary
- 8. Check resistance of MBUS / FBUS lines (J113 / J331 / J332) to GND, also check R172, V170, V171,R305, R306 and check X001 If update is still not possible swap the phone, MAD D301 or PCB should be the reason.
- Note: it is necessary to run energy management calibration after changing CCONT N102! NOTE: for Energy managemant calibration see also general tuning information page!

Low standby / operation mode time

- Check power consumption: off state current = 0-2.35 mA. If ok, goto 5
- 1. lift L122 (VBATTRF) check current consumption. If ok, goto 3
- 2. lift L123 (VB) check current consumption. If ok, goto 4
- 3. N800 faulty in all probability if current is still too high after changing N800, check / change C814, C815, C817.
- 4. VB line faulty in most cases is CCONT N102 the reason. If fault persists after changing CCONT, it is also possible, that capacitor(s) in VB line is/are faulty (C105, C122, C123, ...) check all these components lifting one after the other, with repeated current testing, probably one of the μBGA CSP's and / or ultimately the PCB should be the reason
- Check current in sleep mode: 2.35-4 mA. If ok, goto 6 Check resistance of all voltage output lines of CCONT N102 to GND Change component(s) in corresponding line(s) if resistance is not ok
- 6. If resistance of voltage lines (from CCONT N102) are ok, but sleep mode current is still too high change CCONT N102 Note: it is necessary to run energy management calibration after changing CCONT N102! NOTE: for Energy managemant calibration see also general tuning information page! Check charging circuit, run energy management calibration. If calibration fails - continue with section "Not charging"
- Align RX / TX values. If calibration fails continue with section "RX / TX faults"

Note: Standby time also depends on network side and users handling, like lights on/off, VIBRA- / WAP activities, games etc.. Contact Service

MCU ROM Checksum failed:

Try to flash the phone. If not ok - change FLASH D311. If failure still persists after rework of FLASH, MAD D301 or PCB should be the reason CCONT Interface failed:

N102 faulty and/or probably broken solderings under CCONT. If not ok after rework of CCONT, probably MAD D301 or PCB faulty Note: it is necessary to run energy management calibration after changing CCONT N102!

- NOTE: for Energy managemant calibration see also general tuning information page!
- COBBA parallel / serial failed:
- 1. Check VBB 2,7V at J108 / C147 and VCOBBA 2,7V at J109 / C254
- 2. Check COBBACLK at J200 probably faulty COBBA N240, or broken solderings under COBBA
- If fault still remains after rework of N240 swap probably MAD D301 or PCB faulty
- DSP alive test failed

In most of all DSP alive selftest failures - MAD D301 faulty, which is not changeable!


- EEPROM tune checksum / EEPROM security checksum failed
- Use Wintesla to check if phonedata like IMEI-, product- or PSN- data are corruped / missing

If phone data is ok try to reset the phone. If phone data is not ok, or fault remains after rewriting phone data - change FLASH D311

RTC Battery failed

First try to charge RTC battery, by connecting battery to the phone for app. 10 minutes.

If fault remains after disconnecting/connecting battery - check contact springs of battery and Pads on PCB (if dirty etc.) - change LCD unit and/or CCONT N102, CHAPS N100 if necessary







NOKIA	CONFIDENTIAL		3(5)
Service & Analysis Center Europe	Baseband Quick Repair Layout	Version 1.0) Approved
SACE CC Training Group	NPE-3		
©NMP 2001 Only for Training and Service Purposes	06.02.2001		

	Internal audio faults
	No audio from speaker
1.	Check resistance of speaker B200 (300hm), change speaker if bent (especially membrane) or soiled.
2.	Check connection between speakerpads on PCB to a)C248/C249 and to b)C246/C247. If not ok, check R247 to GND, resistance of both lines should be > 1 Mohm
	If fault persists change COBBA N240.
	Note: Realign Rx/Tx values and rewrite SIMlock data after changing COBBA!
	Microphone does not work
	Check impedance of microphone (0,5-1k0hm), change if necessary.
	Check mechanical condition of connector X001 and MIC itself for dirt etc
	Check MicBias at L200, 2,4V on active microphone.If not ok, check - values around V231.
4.	Check connection between L200- C263 (470 Ohm),-C237 (0 Ohm),-C238 (0 Ohm) if fault remains, change Cobba N240. Note: Realign RX / TX values and rewrite SIMlock data after changing COBBA!
	Clock time problems
	Clock time has to be corrected in short periods
1	Check amplitude and frequency of sleepclock oscillator at C113/J112, should be 3,2Vpp squarewave at 32,768kHz.
	If not ok, change B110 and check parts around oscillator (R110, R111, R112, R113, C110, C111, C112, C113).
2.	Clock time is lost after removing battery
	First try to charge RTC battery, by connecting battery to the phone for app. 10 minutes.
	If fault remains, check contact springs of battery, change RTC battery (LCD unit).
	If fault persists, probably CCONT N102 or CHAPS N100 faulty.
	Note: It is necessary to run energy management calibration after changing CCONT N102!
	For Energy managemant calibration also see general tuning information page!
	Phone intermittend switches off
1.	Check mechanical appearance of connector X120 / X121 - change if necessary .
	Check amplitude of 32,768kHz at J112 / C113, 3,2Vpp squarewave, change B110 if necessary.
2.	If not ok, check parts around (R110, R111, R112, R113, C110, C111, C112, C113), probably broken solderings under CCONT N102 change if necessary.
	the same problem may cause HAGAR N500, because the reference oscillator G602 is divided to 13MHz system clock by HAGAR N500.
	If you suppose broken solderings under HAGAR - rework as described above.
	Note: it is necessary to run energy management calibration after changing CCONT N102!
	NOTE: for Energy managemant calibration see also general tuning information page!
	Not charging
1	Nothing happens if charger is connected.
	Check mechanical appearance of connector X120 / X121. Check resistance of fuse F101.
2.	Check resistance of charge line (V_IN) to GND - value should be app. 50kOhm, if not ok, check/change R101, L101, C101, C102 and voltage devider R102 / R103.
3	Change N100 and/or N102 if necessary.
	"Not charging"
	Run energy management calibration. If it works without failuremessage, try to charge again after calibration. If a failure message appears, check the following:
	Battery temperature failed:
1.	Check X120, R122/123 or change CCONT N102.
	Battery size failed:
2.	Check X121, R120, R121 or change CCONT N102.
	Battery voltage failed:
3.	Check X120, C120, C121, L123, C122, C123 or change CCONT N102.
	Charge current failed:
4.	Check / change R106, R105, C104, or change CHAPS N100 and/or CCONT N102.
-	Charge voltage failed:
5.	Check VCHARGE at voltage divider R102 / R103 - if ok change CCONT N102, if not ok, check parts like X001, X120, X121, F101, R101, L101, C101, C102 and/or change CHAPS N100 if necessary.
	NOTE: for Energy managemant calibration see also General tuning information page!
	Note: to the gy managemant canotation see also deneral tuning motimation page:
1	Check X160, if bent or soiled - change if necessary.
	Check V160: pin1 – DATAO, pin3 – VSIM, pin4 – SIMCLK, pin5 SIMresetO. (See signal-page).
3.	Also check R160, C160, C161, C162.
	Check resistance of simlines to GND - change V160, C163, C164 if necessary, probably broken solderings under CCONT N102.
	Change CCONT N102 and run energy management calibration, if fault persists - probably MAD D301 or PCB faulty
	Vibra failure
1.	Check mechanical appearance of M400 change if necessary
2.	Check VBATTIR 3,6V at L121
	Check VBATTIR 3,6V at V440
4.	Check VIBRA signal at L401 If not ok, check VIBRA signal at R444
	If signal is ok at R444, change V441, if signal fails, MAD D301 probably faulty, or a disconnection between MAD D301 and R444 in VIBRA line
	Display failure
-	If line segments missing or no display function at all
	Check mechanical appearance of H400 and check Elastomer - change LCD unit if necessary
	Check contacts on PCB if dirty clean pads if necessary Check VBB 2,7V at C452 if not ok, probably MAD D301 or PCB faulty, check C451 if bent
7.	Backlight failure
Q	Check VBATTUI 3,6V at L120
	Check VBATTUI 3,6V at R424
	. Check voltage at V430 (LCD lights) 3.6V, check voltage at LED's V420 – V423
	Check voltage at V43 (Key lights) 3.6V, check voltage at LED's V424 - V429
	Check voltage at R427 (LIGHT line) if it fails, MAD D301 probably faulty
	Buzzer failure
13.	Check mechanical condition (if dirty etc.) of B400 change if necessary
14.	Check VBATTIR 3,6V at L121

- 14. Check VBATTIR 3,6V at L121 15. Check VBATTIR 3,6V at V410
- 16. Check BUZZER signal at V411 if signal fails, probably MAD D301 or PCB faulty






NOKIA	CONFIDENTIAL		4(5)
Service & Analysis Center Europe	Measurement Points	Version 1.0) Approved
SACE CC Training Group	NPE-3/ NHM-3		
©NMP 2001 Only for Training and Service Purposes	06.02.2001		



· · · · · · · · · · · · · · · · · · ·	~		~			~
VSA((speer of)) Name *Adde Name Name *Adde Name Name Name Name Name Name Name Name Name Name	200 0000000000000000000000000000000000	54,00 Fold (253) 54,00 Hard - Adding Owned 1 44,00 Hard - Adding Owned 1 24,00 Hard - Adding Owned 1 74,950 - 8,00 Hord - Adding Owned 1 750,00 Hord - Adding Owned 1	D0 4 CSS Here -Acia Coned 1 1,89	Sour # 4500000 283	3303 Six1a #50507 2330 Image: state sta	31 4 4.06.050
1) VSIM	2) COBBACLK	3) TX I/Q	4) TX I/Q	5) SCLK	6) SDATA	7) SLE
2,200 12,201Hot ef c113 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,000 1,407 V 1,000 1,407 V	80.00 RK 0 #558/jl 90.00 Image: 10.200 90.00 Image: 10.200	Bit Gild #259 (p) 8000 Max 8000 Max 4000 Max 2000 Max 2000 Max 4000 Max 2000 Max 4000 Max <td>134 Adv Dessel 138 </td> <td>SetLOOM d (150 4000 1000 2000 1000 2000 1000 V000 1000 V000 1000 1000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000</td> <td>346X1A.4.2151 2355 235 235 235 235 235 235 235 235 235 235 235 235 236 237 238 239</td> <td>Actine Channel 1-2</td>	134 Adv Dessel 138	SetLOOM d (150 4000 1000 2000 1000 2000 1000 V000 1000 V000 1000 1000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000 2000 1000	346X1A.4.2151 2355 235 235 235 235 235 235 235 235 235 235 235 235 236 237 238 239	Actine Channel 1-2
9) 32 kHz SLEEPCLK	10) RX I	11) RX Q	12) LNA B_G	13) SIMCLK	14) SIMDATA	15) SIM_RESET
Name - Adds-Durrel 2.330	H404496551 el 200034	67,7084r # CS14 and CS15 2000 The stand of	TMGSH/ TMCPU al 1980; pri 1/2 2.800 1.000 1.000 1.000 V 0.000 V V V V V V V V V V V V	VCTD2, S v1000 / doerd an powered level g EGM Heel S 2000 2000 1000 1000 V 5004 ± 000 V 5004 ± 000 0000 V 5004 ± 000 V 5004 ± 0000 V 5004 ±	DET av800 E6501 EP01 djorde on poerleveljene og E6501 ev93 2.000 1.000 1.000 1.000 V 9.000 1.000	67.2004- 47.57 av(5)8 80.00 40.00 10 10 10 10 10 10 10 10 10
17) TXP	18) HAGAR_RESET	19) 67.708 kHz	20) TXVGSM/TXVPCN	21) VPCTRL	22) DET	23) 67.708kHz (



800,00

Measuring Points NHM-3 (6250)

ANTENNA TXVPQN

GSMTX

Z900

TXVGSM

GSMRX

NOKIA	CONFIDENTIAL		5(5)
Service & Analysis Center Europe	Colored Component Finder	Version 1.0) Approved
SACE CC Training Group	NPE-3/NHM-3		
©NMP 2001 Only for Training and Service Purposes	06.02.2001		

