

CCS Technical Documentation
RH-34 Series Transceivers

Troubleshooting - Antennas

Contents

	Page No
Troubleshooting - Antennas	3
Failures and Corrective Measures	3
Appearance of phone	3
Missing internal antenna or antenna radiator	3
Missing GPS antenna	4
RF feed pin/ground pin, IHF speaker pins in C-cover missing or damaged	5
Damaged GPS feed or ground pin	5
Wrong internal antenna installed	5
Obstructed RF feed and ground pads, GPS feed and ground pads, IHF speaker pads ..	6
CDMA or GPS RF connector failure	6
RH-34 Display Assembly	8
Missing or damaged baseband shield	10

Troubleshooting - Antennas

This troubleshooting guide addresses potential failures that will affect the antenna performance of the RH-34 phone, and discusses methods for correction of these failures.

Failures and Corrective Measures

Appearance of phone



Figure 1: Front and back views of the RH-34 (6585) phone

Missing internal antenna or antenna radiator



Figure 2: RH-34 (6585) phone with and without antenna cap




Figure 3: RH-34 (6585) antenna cap with and without radiator

If the antenna cap is missing or there is a cap but it has no radiator, install a new antenna cap with radiator. If the radiator looks obviously damaged (dents, corrosion) or the slot in the radiator has a significantly different shape, then install a new antenna cap with correct radiator.

If no antenna or no radiator is installed, the antenna gain will be degraded by more than 25 dB.

Missing GPS antenna




Figure 4: Back view of RH-34 (6585) C-cover with GPS antenna assembled

If GPS antenna is missing, install a new GPS antenna. If the GPS antenna looks obviously damaged, replace the antenna with a new one.

RF feed pin/ground pin, IHF speaker pins in C-cover missing or damaged




Figure 5: Inside view of the C-cover

Two pogo pins are inserted in the C-cover. One end of the pogo pin (in Figure 4) touches the antenna, the other end (in Figure 5) touches the pad on the PWB. If either of the pogo pins is missing, or either of the pogo pins is obviously damaged (stuck in the C-cover plastic tube, lose the inside spring force), the antenna will lose the contact to the PWB. Replace the whole C-cover assembly with a correct new one.

If the RF feed doesn't touch the PWB, then the antenna gain will degrade by more than 25 dB. If the ground pin doesn't touch the PWB then the antenna gain may degrade about 5 to 10 dB.

If either of the IHF speaker pins is damaged or missing, the speaker will not connect to PWB. Antenna PCS gain will drop 2 dB. The C-cover assembly should be replaced.

Damaged GPS feed or ground pin

As shown in Figure 5, if either the GPS antenna feed or the ground leg is broken, or bent such that either pin will not touch the PWB, then the GPS antenna should be replaced with a new one.

Wrong internal antenna installed



Figure 6: Top view of RH-34 (6585) antenna vs. Jacqueline antenna

The RH-34 (6585) antenna and the Jacqueline antenna caps are similar in appearance. The radiators are totally different.

If the wrong antenna is installed, install the correct one.

Obstructed RF feed and ground pads, GPS feed and ground pads, IHF speaker pads




Figure 7: PWB layout of RF feed/ground pads, GPS feed/ground pads, and IHF speaker pads

If the RF feed pad is obstructed, removed, or covered, then the internal antenna feed pogo pin will not touch the PWB and then the antenna gain will degrade by more than 25 dB. If the ground pad is obstructed, removed, or covered, then the ground pogo pin will not touch the PWB and the antenna gain will degrade more than 5dB. If corrosion is present or the pad is missing, then most likely the PWB and phone needs to be replaced. If either pad is obstructed or covered, the pad should be cleared and/or cleaned.

If the GPS feed pad is obstructed, removed, or covered, then the GPS antenna feed leg will not touch the PWB. If the ground pad is obstructed, removed, or covered, then the ground spring clip will not touch the PWB.

If the Internal Hands Free (IHF) speaker pads are obstructed, removed, or covered, then the IHF speaker will not produce sound. The antenna PCS gain will be degraded by about 2 dB. If corrosion is present or the pad is missing, then most likely the PWB and phone needs to be replaced. If either pad is obstructed or covered, the pad should be cleared and/or cleaned.

CDMA or GPS RF connector failure

CDMA and GPS use the same type of RF connector. The RF connector could fail by not connecting the RF input to the RF output of the RF connector. If this happens to the CDMA RF connector, then the antenna gain will degrade by about 25 dB. If this happens to GPS RF connector, the GPS antenna gain will degrade by about 20 dB. This can be checked by testing for DC conductivity between the RF input and RF output of the RF connector. Note the DC conductivity test must be done without any cable attached to

the RF connector. Since the RF connector is also a switch, the RF output will be disconnected from the RF input when a cable is inserted into the RF connector. When a cable is not inserted, the RF input is connected to the RF connector. The locations of both RF connectors are shown in Figure 7.

- CDMA RF input – connects to duplexor
- CDMA RF output – connects to antenna pad through vias
- GPS RF input – connects to GPS ceramic filter output
- GPS RF output – connects to GPS antenna-matching circuits
- RF connector – connects to coaxial cable

If the RF input is not connected properly to the RF output, then the RF connector must be replaced.

RH-34 Display Assembly

Grounding of the display shield and frame




Figure 8: RH-34 phone display assembly




Figure 9: Side view of RH-34 display assembly

The display shield is connected to the display frame plated area (screw boss area) and then to the PWB through the two top screws. The grounding of the display shield and frame will impact the radiation performance of the phone. If the screws are loose, then tighten them. If the screw bosses are stripped, then the chassis will need to be replaced. If the screws are missing, install new ones.

If the display frame plated area is cracked or the metal plating has peeled off, then the grounding of the display shield and frame will not be guaranteed. Replace the frame.

Wrong display assembly installed




Figure 10: Side view of RH-34 and RH-27 display assembly




Figure 11: Back view of RH-34 and RH-27 display assembly

Display assemblies of RH-34 (6585) and RH-27 (6225) are very similar. However, the RH-27 display shield is different on the side from the RH-34 shield, as shown in Figure 10 inside the blue dashed line. Second, the metal plating at the top area of the RH-27 frame is different from the top of the RH-34 frame, as shown in Figure 11 inside the blue dashed line. For RH-34 frame, the screw boss area is plated but isolated from the rest of the frame, and also there is no plating in the area inside the green dashed line in Figure 11. For the RH-27 frame, the whole top area is fully plated.

If the wrong display shield or frame is installed, replace it with a correct one.

Missing or damaged baseband shield




Figure 12: RH-34 baseband shield assembly

Baseband shield is part of the display assembly. If the baseband shield is missing or obviously damaged, the radiated phone performance will be impacted. Install a new baseband shield.