




**PACE PM 200 Process Monitor**  
**PACE PART NUMBER 8007-0464-P1**  
**Operation and Maintenance Instructions**  
**MANUAL NUMBER 5050-0562**

**Parts Identification**



- |                                  |  |
|----------------------------------|--|
| 1. Temperature Sensor.           | 7. Test /Ground Switch.                      |
| 2. External K-Type Thermocouple. | 8. Power Cord / Power Inlet.                 |
| 3. C / F Switch                  | 9. Male to Female Power Cord / Power Outlet. |
| 4. Sensor Tension Control.       | 10. Function Control.                        |
| 5. Grounding Cable with Clip.    | 11. Power Switch.                            |
| 6. LCD Display.                  | 12. Conduction Plate.                        |

**Specification**

Item	Temperature Tester	
Measuring Range	Temperature	0-600 °C / 32-1200 °F
	Voltage	0-90mV (AC)
	Resistance	0-90 Ω
Resolution	Temperature	1 °C / 1 °F
	Voltage	0.1mV
	Resistance	0.1 Ω
Accuracy	Temperature	± 3 °C ± 6 °F
	Voltage	± (3%±2 digit)
	Resistance	± (1%±2 digit)
Temperature Sensor	K Type Thermocouple	
Display	Liquid Crystal Display	3.50Digits
	Display of Over-range	-1,1
Voltage Measurement	Conform to MIL-STD-2000	
Power Consumption	1W	
Dimension	150mm (W) X 55mm (H) X 150mm (D)	
Weight	Approximately 910 grams (2 lb)	
Operational Environment	0-40 °C /32-104 °F 0-80RH%	

## Maintenance

1. Periodically remove flux splatter from unit using an alcohol-moistened cloth.
2. Repeated measurement will cause sensor to wear out. A properly installed sensor is critical to the accuracy of this device.
3. Handle the temperature sensor carefully. The temperature sensor is extremely thin and may break if handled incorrectly.
4. Before measuring, coat the soldering tip with fresh solder. This is necessary to ensure proper contact between the tip and temperature sensor or tip and conduction plate.
5. When performing test, never let the soldering tip touch the stainless steel housing below the measuring point. An error in measurement will occur.
6. Insure the power source is properly ground before operating this device.
7. If tests are preformed using the PACE TD-100 handpiece, make sure the Tip Heater Cartridge is seated firmly in handle.
8. When operating the PS-90 or SX80 handpiece, make sure inside surfaces of the heater assembly and setscrew are clean and free of oxidation. Insure the setscrew is tight before continuing with test.


## Sensor Installation

1. To install a new sensor (P/N 1285-0046-P1), adjust the tension control slide to the down position.
2. Slip sensor loops onto the three posts making sure to match positive and negative end to corresponding post.

**Note**  
Open sensor error will be displayed as "1". Check sensor post connections. If necessary, replace sensor.

Tension control

Sensor posts



## Measuring Tip Temperature

1. Connect power cord to PM200.
2. Connect your PACE soldering station power supply with handpiece and tip to the PM200 using the supplied male to female power cable.
3. Turn both the PM200 and soldering station power switch to the ON position.
4. Select Celsius or Fahrenheit using the °F / °C Conversion Switch on left side of unit.
5. Turn the dial control switch to "TEMP" position.
6. Clean and re-tin the handpiece tip with fresh solder.
7. Hold tip of handpiece to temperature sensor and heat the solder until display stabilizes. Add solder to tip until sensor is immersed in solder.
8. Record displayed temperature value.




## Measuring the Difference In Potential Between Tip and Ground

1. Connect power cord to PM200.
2. Connect your PACE soldering station power supply with handpiece to the PM200 using the supplied male to female power cable.
3. Turn both the PM200 and soldering station power switch to the ON position.
4. Set power supply temperature to the highest setting possible. (900 °F for Sodr-Tek units / 850 °F for THC models).
5. Turn the dial control switch to “mV” position.
6. Using the ground clip cable, connect the ground terminal (GRD) on the left side of the PM200 to the conduction plate. **DO NOT** touch handpiece tip to the conduction plate during this step.

### Note

Holding the test / ground switch while recording displayed values will produce the same internal grounding condition as the ground clip cable.

7. Record the value displayed on the LCD display as **V1**.
8. Disconnect the ground clip from the conduction plate.
9. Clean and re-tin the handpiece tip with fresh solder.
10. Using the soldering handpiece, place a small bead of soldering the center of the conduction plate and heat the solder until it has become completely melted.
11. When the LCD display has stabilized, record the value as **V2**.
12. Subtract **V1** from **V2** to derive the difference in potential between the tip and ground.



Example: **V1** (00.1) – **V2** (00.9) = 0.8mV

## Measuring the Resistance Between Tip and Ground

1. With PM200, soldering station, and handpiece connected, power on both units.
2. Set tip temperature to the highest setting possible. (900°F for Sodr-Tek units / 850 °F for THC models).
3. Turn the dial control switch to “OHM” position.
4. Using the ground clip cable, connect the ground terminal (GRD) on the side of the PM200 to the conduction plate.
5. Record the value displayed on the LCD display as **R1**.
6. Disconnect the ground clip from the conduction plate.
7. Clean and re-tin the handpiece tip with fresh solder.
8. Using the soldering handpiece, place a small bead of soldering the center of the conduction plate and heat the solder until it has become completely melted.
9. When the LCD display has stabilized, record the value as **R2**.
10. Subtract **R1** from **R2** to derive the resistance from tip to ground.

Example: **R1** (00.1) - **R2** (00.4) = 0.3Ω



**PACE Incorporated**  
9030 Junction Drive  
Annapolis Junction,  
MD 20701  
Tel: (301) 490-9860  
Fax: (301) 498-3252

**PACE Europe Limited**  
13 Tanners Drive  
Blakelands  
Milton Keynes  
Tel: (44) 1908-277666  
Fax: (44) 1908-277777